

Aircraft Details

Use the query results with caution

Over time registration numbers are assigned to different aircraft and diverse data stores with inconsistent data are being joined

[Back to Query Entry](#)

N Number: 7982A

Last Action Date	2019-02-27		
Airworthiness Date	2005-03-12	Expiration Date	2022-07-31
Manufacturer_Name	WILSON LEE	Model Name	RV9-A
Registrant Name	WILSON LEE	Street	507 HWY 110 S
Registrant City	WHITEHOUSE	Registrant State	TX
Registrant Zip Code	75791	Country	UNITED STATES
Region	Southwestern	Registrant Type	Individual
Fract Owner		Certificate Issue Date	2008-02-09
Status	First Notice for Registration Renewal		
Serial Number	90292	Aircraft Type	Fixed wing single engine
Mode S Code	52554134	Year Mfr	2005
Aircraft Category	Land	Builder Certification	Not Type Certificated
Number Engines	1	Number Seats	2
Aircraft Weight	CLASS 1	Aircraft Cruising Speed	0
Airworthiness Classification	Experimental	Approved Operation Codes	Amateur Built
Engine Manufacturer	AMA/EXPR		
Engine Model Name	UNKNOWN ENG	Engine Type	Reciprocating
Engine Horsepower/Thrust	0	Fuel Consumed	0.00

----- History 1 -----

Last Action Date	2016-02-16		
Registrant Name	WILSON LEE	Street	507 HWY 110 S
Registrant City	WHITEHOUSE	Registrant State	TX
Registrant Zip Code	75791	Country	UNITED STATES
Region	Southwestern	Registrant Type	Individual
Fract Owner		Certificate Issue Date	2008-02-09

Status First Notice for Registration Renewal

----- History 2 -----

Last Action Date 2013-07-19
Registrant Name WILSON LEE Street 507 HWY 110 S
Registrant City WHITEHOUSE Registrant State TX
Registrant Zip Code 75791 Country UNITED STATES
Region Southwestern Registrant Type Individual
Fract Owner Certificate Issue Date 2008-02-09
Status First Notice for Registration Renewal

----- History 3 -----

Last Action Date 2008-02-09
Registrant Name WILSON LEE Street 507 HWY 110 S
Registrant City WHITEHOUSE Registrant State TX
Registrant Zip Code 75791 Country UNITED STATES
Region Southwestern Registrant Type Individual
Fract Owner Certificate Issue Date 2008-02-09
Status First Notice for Re- Registration/Renewal

----- History 4 -----

Last Action Date 2007-12-07
Registrant Name SALE REPORTED Street 507 HWY 110 S
Registrant City WHITEHOUSE Registrant State TX
Registrant Zip Code 75791 Country UNITED STATES
Region Southwestern Registrant Type Individual
Fract Owner Certificate Issue Date
Status Sale reported

----- History 5 -----

Last Action Date 2007-03-27
Registrant Name HOLLOWAY FRED Street 3110 BELMEAD LN
Registrant City TYLER Registrant State TX
Registrant Zip Code 75701-7838 Country UNITED STATES
Region Southwestern Registrant Type Co-Owned
Fract Owner Certificate Issue Date 2007-03-27
Status N-Number Assigned and Registered

----- History 6 -----

Last Action Date 2004-08-17

Registrant Name	WILSON LEE	Street	18160 COUNTY ROAD 26
Registrant City	TYLER	Registrant State	TX
Registrant Zip Code	75707-2926	Country	UNITED STATES
Region	Southwestern	Registrant Type	Individual
Fract Owner		Certificate Issue Date	2004-08-17
Status	N-Number Assigned and Registered		

***** No Deregistered Data Found *****

----- Reserved Aircraft 1 -----

Registrant	WILSON LEE	Street 1	18160 CT RD 26
Street 2		City	TYLER
State	TX	Zip Code	75707
Reserved Date	2004-08-04	Reservation Type	Fee paid
Experation Notice Date	2005-06-04	Changed N Number	

----- FAA Accident/Incident 1 -----

Occurrence Date	2007-10-10	Aircraft Make	AMTR
Aircraft Model	RV9A	Damage	MINOR
Document Last Modified	2012-10-31		
Narrative	(-23) NOSE WHEEL FAIRING INTERFERED WITH MAIN WHEEL BRAKE CAUSING WHEEL TO LOCK UP ON LANDING AND PULL THE AIRPLANE OFF THE RUNWAY.		

***** No NTBS Accidents Found *****

----- NTBS Pre 1982 Accident 1 -----

Qccurrence Date	1968-06-29	Aircraft Make	BEECH
Aircraft Model	A45	Aircraft Serial Number	
Damage	DESTROYED	Accident Location	GREENSBORO,NC
Occurrences	ENGINE FAILURE OR MALFUNCTION WHEELS-UP	Phase of Flight	IN FLIGHT - NORMAL CRUISE LANDING - LEVEL OFF/TOUCHDOWN
Causes	INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING FUEL CONTAMINATION- EXCLUSIVE OF	Narrative	LINT AND WATER FOUND IN FUEL PUMP AND CARBURETOR.UNABLE LAND ON ARPT DUE TO CONGESTED RNWY.

WATER IN FUEL
FOREIGN
MATERIAL
AFFECTING
NORMAL
OPERATIONS
WATER IN FUEL
WET,SOFT
GROUND

***** No SDR's Found *****

[Custom Reports](#)

Copyright 2001 - 2022 AviationDB.com Corp. All Rights Reserved

[Legal](#)

[Contact Us](#)