

Aircraft Details

Use the query results with caution

Over time registration numbers are assigned to different aircraft and diverse data stores with inconsistent data are being joined

Back to Query Entry

Last Action Date

Registrant Name

N Number: 993ES						
Last Action Date	2020-03-10					
Airworthiness Date	1969-08-05	Expiration Date	2023-03-31			
Manufacturer_Name	ВЕЕСН	Model Name	D55			
Registrant Name	ALEXANDER DAVID	Street	96 VIA OREADA			
Registrant City	CORRALES	Registrant State	NM			
Registrant Zip Code	870487433	Country	UNITED STATES			
Region	Southwestern	Registrant Type	Individual			
Fract Owner		Certificate Issue Date	2020-03-10			
Status	N-Number Assigned an	d Registered				
Serial Number	TE-748	Aircraft Type	Fixed wing multi engine			
Mode S Code	53357075	Year Mfr	1969			
Aircraft Category	Land	Builder Certification	Type Certificated			
Number Engines	2	Number Seats	6			
Aircraft Weight	CLASS 1	Aircraft Cruising Speed	165			
Airworthiness Classification	Standard	Approved Operation Codes	Normal			
Engine Manufacturer	CONT MOTOR					
Engine Model Name	IO 520 SERIES	Engine Type	Reciprocating			
Engine Horsepower/Thrust	0	Fuel Consumed	0.00			

----- History 1 -----

Street

518 BIRDSALL ST #

В

2018-03-09

LAWRENCE D

TIMTE

Registrant City	HOUSTON	Registrant State	TX		
Registrant Zip Code	770077104	Country	UNITED STATES		
Region	Southwestern	Registrant Type	Individual		
Fract Owner		Certificate Issue Date	1996-10-03		
Status	N-Number Assigned and Registered				
	Histo	ory 2			
Last Action Date	2015-12-05				
Registrant Name	TIMTE LAWRENCE D	Street	518 BIRDSALL ST # B		
Registrant City	HOUSTON	Registrant State	TX		
Registrant Zip Code	770077104	Country	UNITED STATES		
Region	Southwestern	Registrant Type	Individual		
Fract Owner		Certificate Issue Date	1996-10-03		
Status	First Notice for Registration Renewal				
	Histo	ory 3			
Last Action Date	2015-03-17				
Registrant Name	TIMTE LAWRENCE D	Street	1530 MORITZ DR		
Registrant City	HOUSTON	Registrant State	TX		
Registrant Zip Code	770553261	Country	UNITED STATES		
Region	Southwestern	Registrant Type	Individual		
Fract Owner		Certificate Issue Date	1996-10-03		
Status	N-Number Assigned and Registered				
History 4					
Last Action Date	2012-11-05				
Registrant Name	TIMTE LAWRENCE D	Street	1530 MORITZ DR		
Registrant City	HOUSTON	Registrant State	TX		
Registrant Zip Code	770553261	Country	UNITED STATES		
Region	Southwestern	Registrant Type	Individual		
Fract Owner		Certificate Issue Date	1996-10-03		
Status	First Notice for Registra	ation Renewal			
**** / #					
History 5					
Last Action Date	2012-08-07	G	015 111 DED 10703		
Registrant Name	TIMTE	Street	915 HUNTINGTON		

	LAWRENCE D		CV		
Registrant City	HOUSTON	Registrant State	TX		
Registrant Zip Code	770631525	Country	UNITED STATES		
Region	Southwestern	Registrant Type	Individual		
Fract Owner		Certificate Issue Date	1996-10-03		
Status	N-Number Assigned an	d Registered			
	Histo	ory 6			
Last Action Date	2010-05-18				
Registrant Name	TIMTE LAWRENCE D	Street	915 HUNTINGTON CV		
Registrant City	HOUSTON	Registrant State	TX		
Registrant Zip Code	770631525	Country	UNITED STATES		
Region	Southwestern	Registrant Type	Individual		
Fract Owner		Certificate Issue Date	1996-10-03		
Status	Status First Notice for Re- Registration/Renewal				
History 7					
Last Action Date	2007-05-15	a.	045111111111111111111111111111111111111		
Registrant Name	TIMTE LAWRENCE D	Street	915 HUNTINGTON CV		
Registrant City	HOUSTON	Registrant State	TX		
Registrant Zip Code	77063-1525	Country	UNITED STATES		
Region	Southwestern	Registrant Type	Individual		
Fract Owner		Certificate Issue Date	1996-10-03		
Status	The Triennial Aircraft Registration form was mailed and has not been returned by the Post Office				
History 8					
Last Action Date	2004-05-18				
Registrant Name	TIMTE LAWRENCE D	Street	915 HUNTINGTON CV		
Registrant City	HOUSTON	Registrant State	TX		

Registrant Zip Code UNITED STATES 77063-1525 **Country** Region Southwestern **Registrant Type** Individual 1996-10-03 **Fract Owner Certificate Issue Date**

The Triennial Aircraft Registration form was mailed and has not been **Status**

returned by the Post Office

----- History 9 -----

Last Action Date 2001-05-15

Registrant Name TIMTE Street 915 HUNTINGTON

LAWRENCE D CV

Registrant City HOUSTON Registrant State TX

Registrant Zip Code 77063-1525 Country UNITED STATES

Region Southwestern Registrant Type Individual

Fract Owner Certificate Issue Date 1996-10-03

Status The Triennial Aircraft Registration form was mailed and has not been

returned by the Post Office

----- History 10 -----

Last Action Date 1998-05-21

Registrant Name TIMTE Street 915 HUNTINGTON

LAWRENCE D CV

Registrant City HOUSTON Registrant State TX

Registrant Zip Code 77063-1525 **Country** UNITED STATES

Region Southwestern Registrant Type Individual

Fract Owner Certificate Issue Date 1996-10-03

Status N-Number assigned

***** No Deregistered Data Found *****

***** No Reserved Data Found *****

----- FAA Accident/Incident 1 -----

Occurrence Date 1995-05-13 Aircraft Make BEECH

Aircraft Model D55 Damage SUBSTANTIAL

Document Last Modified 2012-08-08

Narrative STUDENT BELEIVED RETRACTED GEAR ON TAKEOFF. POOR

CLIMB. ABORTED. LANDED GEAR UP. FLAPS WERE FULL DOWN.

----- NTBS Accident 1 -----

Event Date 1995-05-13 **Aircraft Make** BEECH **Aircraft Model** D55 **Aircraft Serial Number** TE-748

Damage SUBS

Probably Cause THE PILOT'S INADVERTENT RETRACTION OF THE LANDING

GEAR, RESULTING IN A GEAR UP LANDING.

Prelimenary Narrative On May 13, 1995, at 1036 central daylight time, a Beech D55, N993ES, was

substantially damaged during landing near Norman, Oklahoma. The private pilot was not injured. Visual meteorological conditions prevailed for the 14 CFR Part 91 local instructional flight and no flight plan was filed. During an interview, conducted by the Federal Aviation Administration (FAA) inspector, the pilot stated that he was endorsed for solo flight in the multiengine airplane. The purpose of the flight was a series of touch and goes ending with a full stop. During the third touch and go, the pilot stated that he added "full power"; however, during the initial climb "the plane did not seem to fly." He further stated that he reduced the power and landed on runway 35. Examination of the airplane an FAA inspector revealed the flaps were fully extended and the gear retracted. During discussions with the pilot, he stated that he "would normally retract the flaps and that he thought the flaps were up and the gear down."

Final Narrative

DURING A SERIES OF TOUCH AND GO LANDINGS THE PILOT LANDED THE AIRCRAFT WITH THE LANDING GEAR RETRACTED. THE PILOT STATED THAT FOLLOWING THE LAST TOUCH AND GO HE FELT THAT THE AIRCRAFT WAS NOT CLIMBING SO HE REDUCED POWER TO ABORT THE TAKEOFF. HE ALSO REPORTED THAT HE NORMALLY RETRACTS THE FLAPS AND LEAVES THE GEAR DOWN AFTER HE LIFTS OFF.

***** No NTBS Pre 1982 Accidents Found *****

***** No SDR's Found *****

Custom Reports Copyright 2001 - 2022 AviationDB.com Corp. All Rights Reserved Legal Contact Us