

# N2175F

## 1979 Piper PA-28RT-201

---

# Airworthiness Directives

**Aircraft S/N: 28R-7918012**



**RidgeAire**  
WORLDWIDE  
aviation specialists

*Prepared by the worldwide aviation specialists at RidgeAire, Inc.*

**Triton Aviation Data Corp.**  
**The AD Resource System**  
 DataBases updated July 24, 2019: As of Biweekly 2019-15-16

N2175F

Display Reports in MS-Word

[Return to Search Selections](#)

Search within the listed ADs for: search

Manufacturer: Piper Aircraft Inc. TC No.: 2A13  
 Airworthiness Directives for Model: PA-28RT-201  
 Rec (Yes): Indicates a Recurring AD.

Number of ADs: 18

AD Number	PDF	Rec	Subject	Effective
62-19-03	PDF	No	Propeller attach bolts	08/28/62
64-06-06	PDF	Yes	Control wheels	04/06/64
67-20-04	PDF	No	Main landing gear torque link	09/27/67
67-26-02	PDF	No	Fuel selector valve	05/22/68
79-13-03	PDF	Yes	Fire hazard prevention	06/08/79
79-22-02	PDF	No	Fuel leakage	10/26/79
80-14-03	PDF	No	Bendix, King or Narco transmitters	07/01/80
80-19-01	PDF	No	Carbon monoxide in cabin	09/12/80
80-24-03	PDF	No	Superseded by 86-17-01	11/28/80
81-11-02 R1	PDF	No	Oil drain valves	10/02/81
82-06-11 R1	PDF	No	NLG, inspect, rig, modify	06/16/82
86-17-01	PDF	No	Ammeter replacement	08/21/86
94-14-14	PDF	No	Nose landing gear modification	08/19/94
96-10-03	PDF	No	Flap lever assembly	06/14/96
2010-15-10	PDF	No	Control wheel shaft - both pilot and copilot	08/31/10
2013-02-13	PDF	Yes	Horizontal stabilator control system	03/11/13
2018-02-05	PDF	No	Superseded by 2018-07-03	02/07/18
2018-07-03	PDF	No	Fuel tank selector cover - left & right fuel tank selector placards	04/20/18

Ac  
 DC

The Following ADs apply to Accessories that could be installed on the PA-28RT-201 (See Explanation) No. of ADs: 7

AD Number	PDF	Rec	Subject	Effective
79-26-05	PDF	No	Oil and fuel system hoses P/N 762506	01/03/80
85-23-07	PDF	No	Undetected trim malfunctions	01/27/86
98-21-21 R1	PDF	No	Overheating: electric door seal inflation systems	05/01/00
2001-23-17	PDF	No	GNS 430 Circuitry changes - deviation & flag outputs	12/28/01
2005-01-19	PDF	No	Garmin GTX 33, GTX 33D, GTX 330, GTX 330D Mode S Transponders	02/23/05
2006-03-08	PDF	No	Aero Advantage ADV211CC & ADV212CW Vacuum Pumps; pump chamber failure	03/10/06
2019-01-02	PDF	No	Disable Automatic Dependent Surveillance-Broadcast due to repeat resetting, AFM change	02/07/19

ADs that address non-Type Certificate holders (Garmin, Bendix, etc.) can be found in the [Appliance/Accessory Index](#).  
 Use your Browser's "Print Page" function to print this Summary,  
 and/or use "Save As" to save it to disk. Change the file name before clicking on "Save".