

# N790AL

## 1985 Cessna Citation SII

---

# CAMPS Report

**Aircraft S/N: S550-0024**



**RidgeAire**  
WORLDWIDE  
aviation specialists

*Prepared by the worldwide aviation specialists at RidgeAire, Inc.*



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
5-12-06	PHASE 6	CRQ		DAYS 29-Jun-2022 HRS 8957.7 LDG 7478		14		13-Jul-2022	5 d
051015B	INSPECT LIFE VEST RECERTIFICATION UNK			MTH 15-Nov-2021 HRS 8949.5 LDG 7477		12		30-Nov-2022	4 m 22 d
051220 LEFT	INSPECT LEFT ADDU CAL UNK			MTH 25-Mar-2021 HRS 8923.2 LDG 7461		24		31-Mar-2023	8 m 23 d
051220 RIGHT	INSPECT RIGHT ADDU CAL UNK			MTH 25-Mar-2021 HRS 8923.2 LDG 7461		24		31-Mar-2023	8 m 23 d
051233	INSPECT (CONCORDE) CRQ			MTH 10-Mar-2022 HRS 8957.7 LDG 7478		4 200		10-Jul-2022 9157.7	2 d 200
052501	INSPECT ELT 91.207 INSP. UNK			MTH 15-Nov-2021 HRS 8949.5 LDG 7477		12		30-Nov-2022	4 m 22 d
053401	INSPECT AVIONICS INSPECTION CRQ			MTH 10-Mar-2022 HRS 8957.7 LDG 7478		12		31-Mar-2023	8 m 23 d
055601 RIGHT	INSPECT COCKPIT SIDE WINDOW INSPECTION UNK			MTH 25-Jan-2021 HRS 8921.5 LDG 7459		24 300		31-Jan-2023 9221.5	6 m 23 d 263.8
5-12-01 051201	PHASE 1 UNK			MTH 25-Jan-2021 HRS 8921.5 LDG 7459		24 300		31-Jan-2023 9221.5	6 m 23 d 263.8
5-12-02 051202	PHASE 2 UNK			MTH 25-Jan-2021 HRS 8921.5 LDG 7459		24 300		31-Jan-2023 9221.5	6 m 23 d 263.8
5-12-03 051203	PHASE 3 UNK			MTH 25-Jan-2021 HRS 8921.5 LDG 7459		24 300		31-Jan-2023 9221.5	6 m 23 d 263.8
5-12-04 051204	PHASE 4 UNK			MTH 25-Jan-2021 HRS 8921.5 LDG 7459		24 300		31-Jan-2023 9221.5	6 m 23 d 263.8
5-12-05 051205	PHASE 5 UNK			MTH 01-Aug-2019 HRS 8912.2 LDG 7452		36 1200		31-Aug-2022 10112.2	1 m 23 d 1154.5
5-12-08	PHASE 8 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES) UNK			MTH 10-Mar-2022 HRS 8957.7 LDG 7478		6			
A262003 AFT 051208 : A	INSPECT/WEIGH PORTABLE FIRE EXTINGUISHER : PHASE 8 CRQ		PN-UNKNOWN Y-620253	MTH 10-Mar-2022		6		30-Sep-2022	2 m 22 d
A262003 FORWARD 051208 : F	INSPECT/WEIGH PORTABLE FIRE EXTINGUISHER : PHASE 8 CRQ		PN-UNKNOWN B-74102062	MTH 10-Mar-2022		6		30-Sep-2022	2 m 22 d
5-12-0B 051200B	PHASE B UNK			MTH 01-Oct-2018 HRS 8902.1 LDG 7446		150		9052.1	94.4
5-12-11	PHASE 11 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES) UNK			MTH 10-Mar-2022 HRS 8957.7 LDG 7478		6			
B342004 051211	INSPECT/OPERATIONAL TEST STANDBY GYRO POWER SUPPLY LEAD ACID PS835 BATTERY PACK: PHASE 11 CRQ		501-1228-04 5550	MTH 10-Mar-2022 HRS 8957.7 LDG 7478		6		30-Sep-2022	2 m 22 d



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
5-12-12	PHASE 12			MTH HRS					
						3600		11902.38	2944.68
5-12-13 051213	PHASE 13	SAO		MTH 20-Jun-1997 HRS 5020		5000		10020	1062.3
5-12-14 051214	PHASE 14			MTH 22-Feb-1985 HRS 0		10000		10000	1042.3
5-12-15 051215	PHASE 15			MTH 22-Feb-1985 HRS 0		10000		10000	1042.3
5-12-16 051216	PHASE 16			MTH 22-Feb-1985 HRS 0		10000		10000	1042.3
5-12-17 051217	PHASE 17			MTH 22-Feb-1985 HRS 0	-315	10000		10000	1042.3
5-12-18 051218	PHASE 18	UNK		MTH 15-Nov-2021 HRS 8949.5 LDG 7477		12		30-Nov-2022	4 m 22 d
5-12-20	PHASE 20 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	UNK		MTH 25-Mar-2021 HRS 8923.2 LDG 7461		24			
B341003 LEFT 051220 : L-ALT	AUTOMATIC PRESSURE ALTITUDE REPORTING SYSTEM, AIR DATA COMPUTER AND ALTIMETER - PERFORM CALIBRATION TEST: PHASE 20	UNK	4016341-905 80031395	MTH 25-Mar-2021		24		31-Mar-2023	8 m 23 d
B341003 NO. 1 051220 : ADC	AUTOMATIC PRESSURE ALTITUDE REPORTING SYSTEM, AIR DATA COMPUTER AND ALTIMETER - PERFORM CALIBRATION TEST: PHASE 20	UNK	4013241-931 84062728	MTH 25-Mar-2021		24		31-Mar-2023	8 m 23 d
B341003 NO. 2 051220 : ADC#2	AUTOMATIC PRESSURE ALTITUDE REPORTING SYSTEM, AIR DATA COMPUTER AND ALTIMETER - PERFORM CALIBRATION TEST: PHASE 20	UNK	PN SN-UNKNOWN	MTH 25-Mar-2021		24		31-Mar-2023	8 m 23 d
B341003 RIGHT 051220 : R-ALT	AUTOMATIC PRESSURE ALTITUDE REPORTING SYSTEM, AIR DATA COMPUTER AND ALTIMETER - PERFORM CALIBRATION TEST: PHASE 20	UNK	C661072-0101 W8020H	MTH 25-Mar-2021		24		31-Mar-2023	8 m 23 d
B341003 STANDBY	AUTOMATIC PRESSURE ALTITUDE REPORTING SYSTEM, AIR DATA COMPUTER AND ALTIMETER - PERFORM CALIBRATION TEST: PHASE 20	UNK	C661072-0101 W002011	MTH 25-Mar-2021		24		31-Mar-2023	8 m 23 d
B341004 LEFT 051220 : L-ALT	BAROMETRIC ALTIMETER - PERFORM CALIBRATION TEST: PHASE 20	UNK	4016341-905 80031395	MTH 25-Mar-2021		24		31-Mar-2023	8 m 23 d
B341004 RIGHT 051220 : R-ALT	BAROMETRIC ALTIMETER - PERFORM CALIBRATION TEST: PHASE 20	UNK	C661072-0101 W8020H	MTH 25-Mar-2021		24		31-Mar-2023	8 m 23 d
B341004 STANDBY	BAROMETRIC ALTIMETER - PERFORM CALIBRATION TEST: PHASE 20	UNK	C661072-0101 W002011	MTH 25-Mar-2021		24		31-Mar-2023	8 m 23 d
B341005 LEFT 051220 : L	LEAK TEST STATIC SYSTEM: PHASE 20	UNK		MTH 25-Mar-2021 HRS 8923.2 LDG 7461		24		31-Mar-2023	8 m 23 d
B341005 RIGHT 051220 : R	LEAK TEST STATIC SYSTEM: PHASE 20	UNK		MTH 25-Mar-2021 HRS 8923.2 LDG 7461		24		31-Mar-2023	8 m 23 d
B341107 LEFT 051220 : L-ALT	CHECK ALTIMETER (AIRPLANES CERTIFIED FOR RVSM): PHASE 20	UNK	4016341-905 80031395	MTH 25-Mar-2021		24		31-Mar-2023	8 m 23 d
B341107 NO. 1 051220 : ADC	CHECK AIR DATA COMPUTER (AIRPLANES CERTIFIED FOR RVSM) : PHASE 20	UNK	4013241-931 84062728	MTH 25-Mar-2021		24		31-Mar-2023	8 m 23 d
B341107 NO. 2 051220 : ADC#2	CHECK AIR DATA COMPUTER (AIRPLANES CERTIFIED FOR RVSM): PHASE 20	UNK	PN SN-UNKNOWN	MTH 25-Mar-2021		24		31-Mar-2023	8 m 23 d



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
B341107 RIGHT <i>051220 : R-ALT</i>	CHECK ALTIMETER (AIRPLANES CERTIFIED FOR RVSM): PHASE 20	UNK	C661072-0101 W8020H	MTH 25-Mar-2021		24		31-Mar-2023	8 m 23 d
B341107 STANDBY	BAROMETRIC ALTIMETER - PERFORM CALIBRATION TEST: PHASE 20	UNK	C661072-0101 W002011	MTH 25-Mar-2021		24		31-Mar-2023	8 m 23 d
5-12-21	PHASE 21 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)			MTH 25-Mar-2021 HRS LDG		24			
A237003 <i>051221 : CVR</i>	INSPECT COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON : PHASE 21	UNK	DK120 SD63942	MTH 25-Jan-2021 HRS 8921.5 LDG 7459		24		31-Jan-2023	6 m 23 d
B237004 <i>051221 : CVR</i>	OPERATIONAL TEST COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON : PHASE 21	UNK	DK120 SD63942	MTH 25-Jan-2021 HRS 8921.5 LDG 7459		24		31-Jan-2023	6 m 23 d
B345001 LEFT <i>051221</i>	CALIBRATION TEST TRANSPONDER TRANSPONDER SYSTEM: PHASE 21		010-00230-21 84305571	MTH 25-Mar-2021		24		31-Mar-2023	8 m 23 d
B345001 RIGHT <i>051221 : R</i>	CALIBRATION TEST TRANSPONDER TRANSPONDER SYSTEM: PHASE 21		622-1270-001 24746	MTH 25-Mar-2021		24		31-Mar-2023	8 m 23 d
5-12-22	PHASE 22 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	UNK		MTH 01-Oct-2018 HRS 8902.1 LDG 7446		36			
B326003 <i>051222 : GEAR</i>	HYDROSTATIC TEST EMERGENCY GEAR AIR BOTTLE : PHASE 22		9912103-3 6507	MTH 01-Jul-2020		36		31-Jul-2023	12 m 23 d
5-12-23	PHASE 23 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	UNK		MTH 20-Jan-2020 HRS 8916.6 LDG 7455		60			
B262002 AFT <i>051223 : ATR</i>	HYDROSTATIC TEST ENGINE FIRE EXTINGUISHER : PHASE 23	UNK	9912048-3 58198EJ	MTH 20-Jan-2020		60		31-Jan-2025	30 m 23 d
B262002 FORWARD <i>051223 : FTR</i>	HYDROSTATIC TEST ENGINE FIRE EXTINGUISHER : PHASE 23	UNK	9912048-3 58190EJ	MTH 20-Jan-2020		60		31-Jan-2025	30 m 23 d
5-12-26 <i>051226</i>	PHASE 26	UNK		MTH 25-Jan-2021 HRS 8921.5 LDG 7459		24 3000		31-Jan-2023 11921.5	6 m 23 d 2963.8
5-12-30 <i>051230 : ACM</i>	PHASE 30	UNK		MTH 01-Aug-2019 HRS 8912.2 LDG 7452		600		9512.2	554.5
5-12-32 <i>051232</i>	PHASE 32			MTH 22-Feb-1985 LDG 0		15000		15000	7522
5-12-33 <i>051233</i>	PHASE 33			MTH 22-Feb-1985 LDG 0		15000		15000	7522
5-12-40 <i>051240</i>	PHASE 40 NOT USED	*CF		MTH 22-Feb-1985		A/R			
5-12-43 <i>051243</i>	PHASE 43 NOT USED	*CF		MTH 22-Feb-1985		A/R			
5-12-47	PHASE 47 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)			MTH 22-Feb-1985		144			



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
B262003 AFT <i>051247 : A</i>	HYDROSTATIC TEST PORTABLE FIRE EXTINGUISHER : PHASE 47	UNK	PN-UNKNOWN Y-620253	MTH 01-Sep-2017		144		30-Sep-2029	86 m 22 d
CALIBRATION, TEST, OVERHAUL, OR EXPIRATION DATE OF INSTALLED COMPONENT UNKNOWN. PLEASE NOTIFY CESCOM OF APPROPRIATE DATE.									
B262003 FORWARD <i>051247 : F</i>	HYDROSTATIC TEST PORTABLE FIRE EXTINGUISHER : PHASE 47	UNK	PN-UNKNOWN B-74102062	MTH 01-Sep-2017		144		30-Sep-2029	86 m 22 d
5-12-48	PHASE 48 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	UNK		MTH 01-Oct-2018 HRS 8902.1 LDG 7446		72			
B262004 AFT <i>051248 : A</i>	INSPECT PORTABLE FIRE EXTINGUISHER FIRE EXTINGUISHERS-EMPTY, FOR DAMAGE AND RECHARGE: PHASE 48	UNK	PN-UNKNOWN Y-620253	MTH 01-Sep-2017		72		30-Sep-2023	14 m 22 d
CALIBRATION, TEST, OVERHAUL, OR EXPIRATION DATE OF INSTALLED COMPONENT UNKNOWN. PLEASE NOTIFY CESCOM OF APPROPRIATE DATE.									
B262004 FORWARD <i>051248 : F</i>	INSPECT PORTABLE FIRE EXTINGUISHER FIRE EXTINGUISHERS-EMPTY, FOR DAMAGE AND RECHARGE: PHASE 48	UNK	PN-UNKNOWN B-74102062	MTH 01-Sep-2017		72		30-Sep-2023	14 m 22 d
5-12-49 <i>051249</i>	PHASE 49	UNK		MTH 01-Aug-2019 HRS 8912.2 LDG 7452		36 1200		31-Aug-2022 10112.2	1 m 23 d 1154.5
5-12-52 <i>051252</i>	PHASE 52	UNK		MTH 15-Nov-2021 HRS 8949.5 LDG 7477		12		30-Nov-2022	4 m 22 d
5-12-53 <i>051253</i>	PHASE 53	CRQ		MTH 10-Mar-2022 HRS 8957.7 LDG 7478		72 2400		31-Mar-2028 11357.7	68 m 23 d 2400
5-12-54	PHASE 54			MTH 22-Feb-1985 HRS 0		13200		13200	4242.3
5-12-55	PHASE 55			MTH 22-Feb-1985 HRS 0		15600		15600	6642.3
5-12-56	PHASE 56			MTH 22-Feb-1985 HRS 0		15600		15600	6642.3
5-12-57	PHASE 57			MTH HRS		10000		10000	1042.3
5-12-58	PHASE 58			MTH HRS		300		10807.03	1849.33
5-12-59	PHASE 59			MTH ACH		500		2077.1	2077.1
5-12-MA	PHASE MA			MTH HRS		300		9631.43	673.73
5-12-MB	PHASE MB			MTH 22-Feb-1985 LDG 0		10000		10000	2522
057110 E1	MINOR INSPECTION	CRQ		MTH 10-Mar-2022 HRS 8957.7 LDG 7478		24 300		31-Mar-2024 (12892)9257.7	20 m 23 d 300
057110 E2	MINOR INSPECTION	CRQ		MTH 10-Mar-2022 HRS 8957.7 LDG 7478		24 300		31-Mar-2024 (12892)9257.7	20 m 23 d 300
215012	REPLACE COMPRESSOR DRIVE MOTOR BRUSHES (COMPRESSOR MOTORS 1134104-1, -5 ORFWA1134104-1, -5 ONLY)		PN SN-UNKNOWN	MTH		N/A			
262003 AFT LEFT	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)	UNK	AE873364 017	MTH 01-Oct-2018 HRS 8902.1 LDG 7446		N/A			



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Maintenance Inspections

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
262003 AFT RIGHT	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE) UNK	AE873364 016	MTH 01-Oct-2018 HRS 8902.1 LDG 7446		N/A			
262003 FORWARD LEFT	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE) UNK	AE873364 013	MTH 01-Oct-2018 HRS 8902.1 LDG 7446		N/A			
262003 FORWARD RIGHT	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE) UNK	AE873364 009	MTH 01-Oct-2018 HRS 8902.1 LDG 7446		N/A			
B350004 051222 : OXY	HYDROSTATIC TEST OXYGEN CYLINDER ASSEMBLY DOT 3HT 1850 OR DOT 3FC1850 OR MANUFACTURED UNDER DOT-SP-8162. UNK	176176-64 L400070	MTH 08-Jan-2021		36		31-Jan-2024	18 m 23 d
710000 E1	TURBINE WASH UNK		MTH 25-Jan-2021 HRS 8921.5 LDG 7459		A/R			
710000 E2	TURBINE WASH UNK		MTH 25-Jan-2021 HRS 8921.5 LDG 7459		A/R			
710010 E1	OVERHAUL		MTH 20-Jun-2001 HRS 6057.7		3500		(13192)9557.7	600
710010 E2	OVERHAUL		MTH 20-Jun-2001 HRS 6057.7		3500		(13192)9557.7	600
710020 E1	HOT SECTION INSPECTION		MTH 24-Sep-2013 HRS 8594.7 LDG 7344		1800		(14029)10394.7	1437
710020 E2	HOT SECTION INSPECTION		MTH 24-Sep-2013 HRS 8547.7 LDG 7344		1800		(13982)10347.7	1390
710030 E1	INSPECT INTERMEDIATE CASE FOR CORROSION		MTH		A/R			
710030 E2	INSPECT INTERMEDIATE CASE FOR CORROSION		MTH		A/R			
720010 E1	OIL ANALYSIS		MTH 13-Mar-1986		A/R			
720010 E2	OIL ANALYSIS		MTH 13-Mar-1986		A/R			
731025 E1	VISUALLY INSPECT FUEL-OIL COOLER	UA530768-4 3107	MTH 13-Mar-1986 HRS -3634.3		A/R		(13192)9557.7	600
731025 E2	VISUALLY INSPECT FUEL-OIL COOLER	UA530768-4 3301	MTH 13-Mar-1986 HRS -3634.3		A/R		(13192)9557.7	600
731035 E1	VISUALLY INSPECT MOTIVE FLOW VALVE	2524995 A90562	MTH 13-Mar-1986 HRS -3634.3		1800		(13192)9557.7	600
731035 E2	VISUALLY INSPECT MOTIVE FLOW VALVE	2524995-1 A90618	MTH 13-Jun-2008 HRS 7686.6 LDG 6932		1800		(13120.9)9486.6	528.9



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
731090 E1	VISUALLY INSPECT FLOW DIVIDER VALVE			25607-2 3288	MTH 13-Mar-1986 HRS -3634.3		1800		(13192)9557.7	600
731090 E2	VISUALLY INSPECT FLOW DIVIDER VALVE			25607-2 3294	MTH 13-Mar-1986 HRS -3634.3		1800		(13192)9557.7	600
741030 E1 LOWER	VISUAL INSPECT IGNITION EXCITER CRQ			NB01201 K6421	MTH 10-Mar-2022 HRS 8957.7 LDG 7478		24 300		31-Mar-2024 (12892)9257.7	20 m 23 d 300
741030 E1 UPPER	VISUAL INSPECT IGNITION EXCITER CRQ			NB01201 K6679	MTH 10-Mar-2022 HRS 8957.7 LDG 7478		24 300		31-Mar-2024 (12892)9257.7	20 m 23 d 300
741030 E2 LOWER	VISUAL INSPECT IGNITION EXCITER CRQ			NB01201 K8934	MTH 10-Mar-2022 HRS 8957.7 LDG 7478		24 300		31-Mar-2024 (12892)9257.7	20 m 23 d 300
741030 E2 UPPER	VISUAL INSPECT IGNITION EXCITER CRQ			NB01201 1239	MTH 10-Mar-2022 HRS 8957.7 LDG 7478		24 300		31-Mar-2024 (12892)9257.7	20 m 23 d 300
770010 E1	INSPECT T1 PROBE THERMOCOUPLE HARNESS FOR DAMAGE OR PROBES TOUCHING EACH OTHER				MTH 13-Mar-1986 HRS -3634.3		24 300		31-Mar-2024 (12892)9257.7	20 m 23 d 300
770010 E2	INSPECT T1 PROBE THERMOCOUPLE HARNESS FOR DAMAGE OR PROBES TOUCHING EACH OTHER				MTH 13-Mar-1986 HRS -3634.3		24 300		31-Mar-2024 (12892)9257.7	20 m 23 d 300
792010 E1	CHANGE OIL				MTH 04-Nov-2015 HRS 8873.5 LDG 7465		O/C			
792010 E2	CHANGE OIL				MTH 04-Nov-2015 HRS 8873.5 LDG 7465		O/C			
792020 E1	INSPECT/CLEAN OR REPLACE OIL FILTER ELEMENT UNK				MTH 01-Aug-2019 HRS 8912.2		200		(12746.5)9112.2	154.5
792020 E2	INSPECT/CLEAN OR REPLACE OIL FILTER ELEMENT UNK				MTH 01-Aug-2019 HRS 8912.2		200		(12746.5)9112.2	154.5



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
211002	EMERGENCY PRESSURIZATION VALVE LGB			27441482-06 3AP19	MTH 14-Aug-1998 HRS 5424		O/C	0		
212003	BLOWER 9912070-1	SNA		19A2338 1024	MTH 18-Nov-2003 HRS 6968		O/C	0		
212004	CABIN OVERHEAD FAN UNK			BC61A-901 B2312A	MTH 04-Nov-2015 HRS 8873.5 LDG 7436		1000	0 0	9873.5	915.8
212005	CABIN DIVIDER BLOWER LEFT 5515129-4	*CF		WS2107F30 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
212005	CABIN DIVIDER BLOWER RIGHT 5515129-4	*CF		WS2107F30 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
212006	CABIN UNDERFLOOR BLOWER 1433			5703-4 1433	MTH 14-Jan-2010 HRS 8006.9 LDG 7020		O/C	0 0 0		
212009	CABIN UNDERFLOOR ACTUATOR *CF			NYLC50466 594	MTH 22-Feb-1985		O/C			
212010	DOOR ACTUATOR MOTOR ASSY 9910059-3	*CF		5A3032 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
212027 212006	DEFOG FAN UNK			PN-UNKNOWN SN-UNKNOWN	MTH 01-Oct-2018 HRS 8902.1 LDG 7446		3500	36	12366.1	3408.4
213001	CABIN PRESS INDICATOR 3001J14	*CF		C668511-0102 17889	MTH 22-Feb-1985		O/C			
213002	OUTFLOW VALVE CONTROLLER SAO			130356-15 481050	MTH 28-Sep-1997 HRS 5154		O/C	0		
213003	CABIN RATE OF CLIMB INDICATOR 35060-1128	*CF		C668513-0101 W10059H	MTH 22-Feb-1985		O/C			
213007 LEFT	OUTFLOW VALVE SAO			103576-36 141419	MTH 08-Feb-1996 HRS 4071		O/C	0		
213007 RIGHT	OUTFLOW VALVE SAO			103576-36 341473	MTH 24-Mar-1995 HRS 3411		O/C	0		
213009 LEFT	BLEED AIR FLOW CONTROL VALVE SAO			81085-3 107	MTH 12-Mar-1997 HRS 4865		O/C	0		
213009 RIGHT	BLEED AIR FLOW CONTROL VALVE SAO			81085-3 183	MTH 15-Jun-1998 HRS 5403		O/C	0		
213013	PNEUMATIC RELAY UNK			PN-UNKNOWN SN-UNKNOWN	MTH 01-Aug-2019 HRS 8912.2 LDG 7452		O/C	0 0 0		
215001	REFRIGERATION PACKAGE 9912069-25	*CF		782343-1 840724	MTH 22-Feb-1985		O/C			
215004	AIR CYCLE MACHINE 9912069-1	MCO		738384-26 LB1038	MTH 12-Jun-2010 HRS 8073.7 LDG 7063		5000	0	13073.7	4116
RECOMMENDED ECONOMIC OVERHAUL PERIOD DEFINED BY HAMILTON STANDARD.										
215005	BYPASS VALVE 9912069-1	*CF		754751-2 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
215007	GND OPERATION VALVE -- 9912294-1			BYLB50907 274	MTH 06-Aug-2012 HRS 8405.2 LDG 7247		O/C	1 0 0		





# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
215013	SWITCH-A/C --	GJT		1250232-4 SN-UNKNOWN	MTH HRS		20-Sep-2000 6026	O/C 0		
215014	AIR COND MOTOR --	GJT		1134104-1 SN-UNKNOWN	MTH HRS		20-Sep-2000 6026	O/C 0		
215015	COMPRESSOR DRIVE MOTOR			PN SN-UNKNOWN	MTH		22-Feb-1985	O/C	0	
215016	COMPRESSOR --	GJT		1134160-BSC SN-UNKNOWN	MTH HRS		20-Sep-2000 6026	O/C 0		
215017	CONDENSOR --	GJT		1134400-9 SN-UNKNOWN	MTH HRS		20-Sep-2000 6026	O/C 0		
215019	A/C CONTROL UNIT --	GJT		C35020A SN-UNKNOWN	MTH HRS		20-Sep-2000 6026	O/C 0		
215022	AIRCONDITION EVAPORATOR AFT	GJT		1250240-3 SN-UNKNOWN	MTH HRS		20-Sep-2000 6026	O/C 0		
215023	AIRCONDITION EVAPORATOR FORWARD	GJT		1250240-1 SN-UNKNOWN	MTH HRS		20-Sep-2000 6026	O/C 0		
216002	TEMP CONTROL UNIT 9912069-22	LGB		754661-5 79D3679	MTH HRS		14-Aug-1998 5424	O/C 0		
216003	DUCT TEMP SENSOR 9912069-14	*CF		754691-1 SN-UNKNOWN	MTH		22-Feb-1985	O/C		
216004	CABIN TEMP SENSOR	SAO		754661-1 8405551	MTH HRS		01-Apr-1996 4165	O/C 0		
216005	CENTRIFUGAL BLOWER *CF			3A1003-10 SN-UNKNOWN	MTH		22-Feb-1985	O/C		
221008	AUTOPILOT COMPUTER SP-200	UVA		4008519-945 88044235	MTH HRS		18-Sep-2007 7836	O/C 5500		
221009	AUTOPILOT CONTROLLER PC-500	SAO		4018639-909 89123238	MTH HRS		28-Feb-1997 4823	O/C 2264		
221010	AILERON AUTOPILOT SERVO SM-200	SAO		4006719-906 86052626	MTH HRS		12-Dec-1995 3966	O/C 0		
221010	ELEVATOR AUTOPILOT SERVO SM-200	ILG		4006719-914 82038665	MTH HRS		01-Apr-2005 7427	O/C 0		
221010	RUDDER AUTOPILOT SERVO SM-200	*CF		4006719-906 84061028	MTH		22-Feb-1985	O/C		
230010	COCKPIT VOICE RECORDER GA-100	SAO		GA100-0000 2295	MTH HRS		15-Jun-1998 5403	O/C 0		
230017	COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON 266-E0305-00	UNK		DK120 SD63942	MTH		01-Oct-2018	O/C		
231003	HF RECEIVER/EXCITER KTR-953	SAO		064-1015-00 3903	MTH HRS		24-Mar-1997 4886	O/C 1475		
231004	HF ANTENNA COUPLER KAC-952	SAO		064-1017-01 10559	MTH HRS		24-Mar-1997 4886	O/C 4886		



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
231005	HF CONTROL HEAD KCU-951	SAO		064-1016-03 6057	MTH 25-Oct-1996 HRS 4576		O/C	1165		
232002 NO. 2	COMM ANTENNA	*CF		VFS10-108-1 1325	MTH 22-Feb-1985		O/C			
232003 NO. 1	COMM ANTENNA	SAO		VFS10-90-5 3328	MTH 15-May-1997 HRS 4971		O/C	0		
232004	AIRBIRNE COMMUNICATION TRANSCEIVER	GJT		900002-1 600372	MTH 17-Aug-2000 HRS 6026		O/C	0		
232005 CABIN	CONTROL PHONE	GJT		500-10036-003 SN-UNKNOWN	MTH 17-Aug-2000 HRS 6026		O/C	0		
232006 CKPT	CONTROL-COCKPIT --	GJT		500-10036-003 SN-UNKNOWN	MTH 17-Aug-2000 HRS 6026		O/C	0		
232007 NO. 1	AIRBORNE COMMUNICATION ANTENNA --	GJT		CI-120-500 SN-UNKNOWN	MTH 17-Aug-2000 HRS 6026		O/C	0		
232007 NO. 2	AIRBORNE COMMUNICATION ANTENNA --	GJT		CI-120-500 SN-UNKNOWN	MTH 17-Aug-2000 HRS 6026		O/C	0		
232010 BOTTOM	NO.2 COMM TRANSCEIVER	SNA		622-6152-011 32077	MTH 19-Sep-2002 HRS 6661		O/C	0		
232010 TOP	NO.1 COMM TRANSCEIVER VHF-22A	SAO		622-6152-001 20767	MTH 30-Aug-1997 HRS 5106		O/C	3014		
232011 LEFT	COMM CONTROL CTL-22	GJT		622-6520-005 10635	MTH 20-Sep-2000 HRS 6026		O/C	2687		
232011 RIGHT	COMM CONTROL CTL-22	GJT		622-6520-005 11258	MTH 20-Sep-2000 HRS 6026		O/C	0		
235001 LEFT	AUDIO AMPLIFIER	SAO		5630-1 232	MTH 12-Mar-1996 HRS 4126		O/C	0		
235001 RIGHT	AUDIO AMPLIFIER	VNY	B	5630-1 207	MTH 25-Feb-2005 HRS 7384		O/C	4111		
237010B	ULB (CVR) BATTERY	UNK		810-2007/K SN-UNKNOWN	MTH 01-Oct-2018		72	16	30-Jun-2023	11 m 22 d
242001 BOTTOM	NO.2 AC INVERTER	MRC		SPC38B 2022	MTH 02-Oct-2006 HRS 7709		O/C	0		
242001 TOP	NO.1 AC INVERTER	SNA		SPC38B 1787	MTH 22-Mar-2004 HRS 7103		O/C	0		
243001 LEFT	STARTER/GENERATOR 9912125-4			23085-004 401	MTH 13-Jul-2015 HRS 8859.1 LDG 7431		1000	21 0 0	9859.1	901.4
243001 RIGHT	STARTER/GENERATOR 9912125-3			23085-004-1 96131	MTH 06-Aug-2012 HRS 8405.2 LDG 7247		1000	3 0 0	9405.2	447.5
243003 LEFT	GENERATOR CONTROL UNIT			9912039-6 99534	MTH 05-Nov-2014 HRS 8764.6 LDG 7398		O/C	0 0 0		



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
243003 RIGHT	GENERATOR CONTROL UNIT			9912039-6 7310AB	MTH 15-Oct-2014 HRS 8757.2 LDG 7398		O/C	4 0 0		
243004 LEFT	AMMETER	*CF		C662501-0104 36	MTH 22-Feb-1985		O/C			
243004 RIGHT	AMMETER	*CF		C662501-0104 64	MTH 22-Feb-1985		O/C			
243005	VOLTMETER	*CF		C662502-0101 1338	MTH 22-Feb-1985		O/C			
243007	BATTERY	UNK		RG-380E/44 70011952	MTH 25-Jan-2021 HRS 8921.5 LDG 7459		O/C	0 0 0		
243008	BATTERY TEMPERATURE MODULE	*CF		1529-1 1341	MTH 22-Feb-1985		O/C			
243009	BATTERY TEMPERATURE GAGE	SNA		1229-1 697	MTH 19-May-2000 HRS 5969		O/C	0		
243011	CURRENT VOLTAGE CONTROLLER	SAO		1301-1 1796	MTH 25-May-1995 HRS 3537		O/C	299		
243012	CURRENT SENSOR	IND		1302-1 243A	MTH 06-Oct-2008 HRS 7925		O/C	0		
243013	BATT DISCONNECT K69 RELAY	JAC		A876K CM88693	MTH 07-Aug-2002 HRS 6627		O/C	0		
243014 243010	BATTERY TEMPERATURE SENSOR	SAO		1166-1 9688	MTH 09-Oct-1989 HRS 1112		O/C	0		
243015 243010 : G	TEMPERATURE SENSOR GAGE	*CF		1166-1 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
245001 CENTER	5 VOLT LIGHT DIMMER	SAO		1505-1 4098	MTH 30-Oct-1997 HRS 5226		O/C	2598		
245001 LEFT	5 VOLT LIGHT DIMMER	SAO		1505-1 1985	MTH 28-Mar-1996 HRS 4158		O/C	1411		
245001 RIGHT	5 VOLT LIGHT DIMMER	SAO		273-1 3026	MTH 02-Jan-1995 HRS 3386		O/C	0		
245003 LEFT	START K7 RELAY	*CF		A703C SN-UNKNOWN	MTH 22-Feb-1985		O/C			
245003 RIGHT	START K8 RELAY	IND		A703C CG97324	MTH 20-Jun-2008 HRS 7909		O/C	0		
245004 LEFT	POWER K13 RELAY	*CF		A703P SN-UNKNOWN	MTH 22-Feb-1985		O/C			
245004 RIGHT	POWER K12 RELAY	*CF		A703P SN-UNKNOWN	MTH 22-Feb-1985		O/C			
256002	LOCATOR BEACON TRANSMITTER	SNA		3000-11 332050	MTH 29-Jul-2003 HRS 6827		O/C	0		
256003	REPLACE LOCATOR BEACON TRANSMITTER BATTERY			C406-2 452-0133 SN-UNKNOWN	MTH 20-Oct-2020 HRS 8918.5 LDG 7456		DUE DUE DUE DUE	0	31-Aug-2024	25 m 23 d
256004 LEFT	LOCATOR BEACON ANTENNA	*CF		ELT10-177-1 628	MTH 22-Feb-1985		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
256004 RIGHT	LOCATOR BEACON ANTENNA *CF			ELT10-177-2 618	MTH 22-Feb-1985		O/C			
256010 NO. 10	LIFE PRESERVER			RSS-301T 1-2027599	MTH 15-Jul-2014 HRS 8670.8 LDG 7367		120	0 0 0	31-Jul-2024	24 m 23 d
256010 NO. 1	LIFE PRESERVER			RSS-301T 1-2027606	MTH 15-Jul-2014 HRS 8670.8 LDG 7367		120	0 0 0	31-Jul-2024	24 m 23 d
256010 NO. 2	LIFE PRESERVER			RSS-301T 1-2027582	MTH 15-Jul-2014 HRS 8670.8 LDG 7367		120	0 0 0	31-Jul-2024	24 m 23 d
256010 NO. 3	LIFE PRESERVER			RSS-301T 1-2027586	MTH 15-Jul-2014 HRS 8670.8 LDG 7367		120	0 0 0	31-Jul-2024	24 m 23 d
256010 NO. 4	LIFE PRESERVER			RSS-301T 1-2027645	MTH 15-Jul-2014 HRS 8670.8 LDG 7367		120	0 0 0	31-Jul-2024	24 m 23 d
256010 NO. 5	LIFE PRESERVER			RSS-301T 1-2027651	MTH 15-Jul-2014 HRS 8670.8 LDG 7367		120	0 0 0	31-Jul-2024	24 m 23 d
256010 NO. 6	LIFE PRESERVER			RSS-301T 1-2027657	MTH 15-Jul-2014 HRS 8670.8 LDG 7367		120	0 0 0	31-Jul-2024	24 m 23 d
256010 NO. 7	LIFE PRESERVER			RSS-301T 1-2027695	MTH 15-Jul-2014 HRS 8670.8 LDG 7367		120	0 0 0	31-Jul-2024	24 m 23 d
256010 NO. 8	LIFE PRESERVER			RSS-301T 1-2027701	MTH 15-Jul-2014 HRS 8670.8 LDG 7367		120	0 0 0	31-Jul-2024	24 m 23 d
256010 NO. 9	LIFE PRESERVER			RSS-301T 1-2027576	MTH 15-Jul-2014 HRS 8670.8 LDG 7367		120	0 0 0	31-Jul-2024	24 m 23 d
261001 LEFT	ENGINE FIRE DETECTOR SENSOR 9912036-3 *CF			244-18882 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
261001 RIGHT	ENGINE FIRE DETECTOR SENSOR 9912036-3 *CF			244-18882 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
261002 LEFT	FIRE DETECTION CONTROL UNIT 9912036-2 *CF			377-02808 8433006	MTH 22-Feb-1985		O/C			
261002 RIGHT	FIRE DETECTION CONTROL UNIT 9912036-2 *CF			377-02808 8433013	MTH 22-Feb-1985		O/C			
262001 AFT	ENGINE FIRE EXTINGUISHER			9912048-3 58198EJ	MTH 15-Jul-2014 HRS 8670.8 LDG 7367		O/C	1 0 0		
262001 FORWARD	ENGINE FIRE EXTINGUISHER			9912048-3 58190EJ	MTH 15-Jul-2014 HRS 8670.8 LDG 7367		O/C	1 0 0		
262002 AFT	PORTABLE FIRE EXTINGUISHER UNK			PN-UNKNOWN Y-620253	MTH 20-Oct-2020 HRS 8918.5 LDG 7456		O/C			
262002 FORWARD	PORTABLE FIRE EXTINGUISHER UNK			PN-UNKNOWN B-74102062	MTH 20-Oct-2020 HRS 8918.5 LDG 7456		O/C			
262101 AFT LEFT 262003 : AL	FIRE EXTINGUISHER CARTRIDGE UNK			AE873364 017	MTH 01-Oct-2018 HRS 8902.1 LDG 7446		120	0 0	31-Oct-2027	63 m 23 d

Manufacture Date: 01-Oct-2017



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
262101 AFT RIGHT 262003 : AR Manufacture Date: 01-Oct-2017	FIRE EXTINGUISHER CARTRIDGE UNK			AE873364 016	MTH 01-Oct-2018 HRS 8902.1 LDG 7446		120	0 0	31-Oct-2027	63 m 23 d
262101 FORWARD LEFT 262003 : FL Manufacture Date: 01-Oct-2017	FIRE EXTINGUISHER CARTRIDGE UNK			AE873364 013	MTH 01-Oct-2018 HRS 8902.1 LDG 7446		120	0 0	31-Oct-2027	63 m 23 d
262101 FORWARD RIGHT 262003 : FR Manufacture Date: 01-Oct-2017	FIRE EXTINGUISHER CARTRIDGE UNK			AE873364 009	MTH 01-Oct-2018 HRS 8902.1 LDG 7446		120	0 0	31-Oct-2027	63 m 23 d
271001	AILERON TRIM TAB ACTUATOR 5565450-51 *CF			5565450-72 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
272001	RUDDER TRIM TAB ACTUATOR 5565450-71 *CF			5565450-71 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
273002	ELECTRIC ELEVATOR TRIM ACTUATOR			1U662-001 T353	MTH 12-Sep-2014 HRS 8727.5 LDG 7388		O/C	17 0 0		
273003 LEFT	ELEVATOR TRIM TAB ACTUATOR *CF			5565450-79 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
273003 RIGHT	ELEVATOR TRIM TAB ACTUATOR 5565450-80 *CF			5565450-80 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
275003 LEFT	FLAP ACTUATOR *CF 9912007-1			55800-1 157	MTH 22-Feb-1985		O/C			
275003 RIGHT	FLAP ACTUATOR *CF 9912007-1			55800-1 143	MTH 22-Feb-1985		O/C			
275004 LEFT WING LEFT INBOARD	-AFT FLAP ROLLER SAO			CC50380 SN-UNKNOWN	MTH 15-Jun-1998 HRS 5403 LDG 5105		5000	0	10105	2627
275004 LEFT WING LEFT OUTBOARD	-AFT FLAP ROLLER SAO			CC50380 SN-UNKNOWN	MTH 15-Jun-1998 HRS 5403 LDG 5105		5000	0	10105	2627
275004 LEFT WING RIGHT INBOARD	-AFT FLAP ROLLER SAO			CC50380 SN-UNKNOWN	MTH 22-Dec-1997 HRS 5301 LDG 5018		5000	0	10018	2540
275004 LEFT WING RIGHT OUTBOARD	-AFT FLAP ROLLER SAO			CC50380 SN-UNKNOWN	MTH 22-Dec-1997 HRS 5301 LDG 5018		5000	0	10018	2540
275004 RIGHT WING LEFT INBOARD	-AFT FLAP ROLLER SAO			CC50380 SN-UNKNOWN	MTH 15-Jun-1998 HRS 5403 LDG 5105		5000	0	10105	2627
275004 RIGHT WING LEFT OUTBOARD	-AFT FLAP ROLLER SAO			CC50380 SN-UNKNOWN	MTH 15-Jun-1998 HRS 5403 LDG 5105		5000	0	10105	2627
275004 RIGHT WING RIGHT INBOARD	-AFT FLAP ROLLER SAO			CC50380 SN-UNKNOWN	MTH 22-Dec-1997 HRS 5301 LDG 5018		5000	0	10018	2540
275004 RIGHT WING RIGHT OUTBOARD	-AFT FLAP ROLLER SAO			CC50380 SN-UNKNOWN	MTH 22-Dec-1997 HRS 5301 LDG 5018		5000	0	10018	2540
276001 LEFT	SPEED BRAKES ACTUATOR 5527230-1 *CF			5527230-1 10	MTH 22-Feb-1985		O/C			
276001 RIGHT	SPEED BRAKES ACTUATOR 5527230-1 *CF			5527230-1 86	MTH 22-Feb-1985		O/C			



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
282001 LEFT	MOTOR DRIVEN FUEL PUMP 9912017-2	UNK		1C7-12 11BP7	MTH 01-Oct-2018 HRS 8902.1 LDG 7446		O/C	0 0 0		
282001 RIGHT	MOTOR DRIVEN FUEL PUMP 9912017-2	IND		1C7-12 9BD7	MTH 16-Mar-2009 HRS 7930		O/C	0		
284001 LEFT	LOW LEVEL FUEL SWITCH SAO			L15H-3 4920	MTH 12-Mar-1997 HRS 4865		O/C	0		
284001 RIGHT	LOW LEVEL FUEL SWITCH *CF			L15H-3 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
284002 LEFT	FUEL QUANTITY COMPENSATOR 9912019-4	*CF		300047-13001 14859R	MTH 22-Feb-1985		O/C			
284002 RIGHT	FUEL QUANTITY COMPENSATOR 9912019-4	*CF		300047-13001 14843R	MTH 22-Feb-1985		O/C			
284007	FUEL QUANTITY INDICATOR 9912147-12	SAO		VSDL-OC403D 360	MTH 02-Aug-1994 HRS 3014		O/C	32		
291001	HYDRAULIC RESERVOIR ASSEMBLY 9912052-12	LGB		7140-7 627	MTH 06-Feb-2000 HRS 5879		O/C	0		
291002 LEFT	ENGINE HYDRAULIC PUMP 9912062-4	SAO		24195-LAA 1269	MTH 06-Mar-1996 HRS 4111		O/C	0		
291002 RIGHT	ENGINE HYDRAULIC PUMP 9912062-3	SAO		4120-004000 199	MTH 22-Jan-1997 HRS 4739		O/C	0		
291005 LEFT	HYDRAULIC W/FLOW DETECTOR CHECK VALVE 9912194-3	*CF		3520020100-4 1901	MTH 22-Feb-1985		O/C			
291005 RIGHT	HYDRAULIC W/FLOW DETECTOR CHECK VALVE 9912194-3	*CF		3520020100-4 1963	MTH 22-Feb-1985		O/C			
291007 LEFT	HYDRAULIC FIREWALL SHUTOFF VALVE *CF			149145 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
291007 RIGHT	HYDRAULIC FIREWALL SHUTOFF VALVE *CF			149145 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
291012	HYDRAULIC BY-PASS VALVE - SAO			2710971 539	MTH 01-Nov-1997 HRS 5226		O/C	0		
301001 AFT	ANTI-ICE PUMP *CF			XA9511A004 T12248	MTH 22-Feb-1985		O/C			
301001 FORWARD	ANTI-ICE PUMP			XA9511C005 T1711-84	MTH 06-Aug-2012 HRS 8405.2 LDG 7247		O/C	1 0 0		
301002 LEFT	LOW PRESSURE SWITCH *CF			PO67B078 T79184	MTH 22-Feb-1985		O/C			
301002 RIGHT	LOW PRESSURE SWITCH *CF			PO67B078 T79484	MTH 22-Feb-1985		O/C			
301003	ANTI-ICE TANK ASSY *CF			6514007-5 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
301004	ANTI-ICE FLUID INDICATOR *CF			19-435-02 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
301005 LEFT	SURF SOLENOID VALVE *CF			FV137 SN-UNKNOWN	MTH 22-Feb-1985		O/C			



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
301005 RIGHT	SURF SOLENOID VALVE *CF			FV137 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
301005	SOLENOID VALVE *CF			FV137 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
301006 LEFT INBOARD	HORIZONTAL STABILIZER PANEL *CF			D3717 M1784	MTH 22-Feb-1985		O/C			
301006 LEFT OUTBOARD	HORIZONTAL STABILIZER PANEL *CF			D3715 M1584	MTH 22-Feb-1985		O/C			
301006 RIGHT INBOARD	HORIZONTAL STABILIZER PANEL *CF			D3718 M1884	MTH 22-Feb-1985		O/C			
301006 RIGHT OUTBOARD	HORIZONTAL STABILIZER PANEL *CF			D3716 M1684	MTH 22-Feb-1985		O/C			
301007 LEFT NO.1	WING PANEL *CF			D3709 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
301007 LEFT NO.2	WING PANEL *CF			D3731 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
301007 LEFT NO.3	WING PANEL *CF			D3729 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
301007 LEFT NO.4	WING PANEL *CF			D3703 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
301007 LEFT NO.5	WING PANEL *CF			D3701 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
301007 RIGHT NO.1	WING PANEL *CF			D3710 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
301007 RIGHT NO.2	WING PANEL *CF			D3732 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
301007 RIGHT NO.3	WING PANEL *CF			D3730 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
301007 RIGHT NO.4	WING PANEL *CF			D3704 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
301007 RIGHT NO.5	WING PANEL *CF			D3702 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
301008 LEFT	FAIRING PANEL *CF			D3714 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
301008 RIGHT	FAIRING PANEL *CF			D3713 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
301009 LEFT	SURF PROPORTIONER *CF			PU306DW38 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
301009 RIGHT	SURF PROPORTIONER *CF			PU306DW38 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
301010	ENGINE PROPORTIONER *CF			PU306DC39 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
301011	HOR/STB PROPORTIONER *CF			PU306DT41 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
301012	ICE DETECTOR SAO			871DN1 116	MTH 17-Jun-1989 HRS 1048		O/C		0	
301013 <i>301016</i>	SURF PUMP CHECK VALVE *CF			FV121 T45684	MTH 22-Feb-1985		O/C			
301014 LEFT	FAIRING PANEL PRESSURE SWITCH *CF			PO67L025 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
301014 LEFT INBOARD	FAIRING PANEL PRESSURE SWITCH *CF			PO67L015 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
301014 RIGHT	FAIRING PANEL PRESSURE SWITCH *CF			PO67L025 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
301014 RIGHT INBOARD	FAIRING PANEL PRESSURE SWITCH *CF			PO67L015 SN-UNKNOWN	MTH 22-Feb-1985		O/C			



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
301016 LEFT	WING PANEL PRESSURE SWITCH *CF			PO67LC050 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
301016 RIGHT	WING PANEL PRESSURE SWITCH *CF			PO67LC050 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
301017 LEFT INBOARD	HORIZONTAL STABILIZER PRESSURE SWITCH *CF			PO67L025 M20384	MTH 22-Feb-1985		O/C			
301017 LEFT OUTBOARD	HORIZONTAL STABILIZER PRESSURE SWITCH *CF			PO67L025 M18884	MTH 22-Feb-1985		O/C			
301017 RIGHT INBOARD	HORIZONTAL STABILIZER PRESSURE SWITCH *CF			PO67L025 M18784	MTH 22-Feb-1985		O/C			
301017 RIGHT OUTBOARD	HORIZONTAL STABILIZER PRESSURE SWITCH *CF			PO67L025 M19284	MTH 22-Feb-1985		O/C			
301018 <i>301015 : PUMP</i>	ENGINE PUMP CHECK VALVE *CF			FV147 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
301019 LEFT	SURF TEE CHECK VALVE *CF			FV147 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
301019 RIGHT	SURF TEE CHECK VALVE *CF			FV147 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
301020	SURF INBD CHECK VALVE *CF			FV147 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
301021	SURF TO ENGINE CHECK VALVE *CF			FV147 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
301022 INBOARD <i>301020 : INBD</i>	SURF CHECK VALVE *CF			FV147 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
302003 LEFT	ENGINE BLEED AIR VALVE 9912086-3	IND		229715-1 1273	MTH 30-Apr-2008 HRS 7898		O/C		5095	
302003 RIGHT	ENGINE BLEED AIR VALVE 9912086-3	GJT		229715 SN-UNKNOWN	MTH 20-Sep-2000 HRS 6026		O/C		0	
302004 LEFT	ANTI ICE TEMP SWITCH *CF			21548-2-19-6 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
302004 RIGHT	ANTI ICE TEMP SWITCH *CF			21548-2-19-6 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
303001 LEFT	PITOT TUBE *CF			2-7442-3 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
303001 RIGHT	PITOT TUBE *CF			PH502 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
303002 LEFT	PILOT STATIC PORT *CF			CM2933-7 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
303002 RIGHT <i>303003 : RT</i>	CO-PILOT STATIC PORT *CF			CM2933-7 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
303003 LEFT	CO-PILOT STATIC PORT LGB			CM2933-7 SN-UNKNOWN	MTH 14-Aug-1998 HRS 5424		O/C		0	
303003 RIGHT <i>303002 : RB</i>	PILOT STATIC PORT *CF			CM2933-7 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
304001	HOT AIR TEMPERATURE MONITOR- 5514120	*CF		1169-1 1420	MTH 22-Feb-1985		O/C			
304002	HEAT EXCHANGER 9912041-4	*CF		10663A SN-UNKNOWN	MTH 22-Feb-1985		O/C			





# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
304005	TEMPERATURE CONTROL VALVE 9912085-1	*CF		27241287 6M0042	MTH 22-Feb-1985		O/C			
304006	TEMPERATURE CONTROLLER 9912085-2	SAO		27231272 1AG7	MTH 22-Dec-1997 HRS 5301		O/C	0		
304009	WINDSHIELD BLEED AIR VALVE 9912086-4	SNA		67410-2 2128ABCDEG	MTH 27-Dec-2000 HRS 6144		O/C	0		
312001 RIGHT	CLOCK	GJT		811B 35075	MTH 20-Sep-2000 HRS 6026		O/C	0		
312002 LEFT	CLOCK BATTERY	GJT		811-BATT-1 SN-UNKNOWN	MTH 20-Sep-2000 HRS 6026		O/C	0		
313001	FLIGHT HOURMETER 15136	LGB		C664503-0102 SN-UNKNOWN	MTH 14-Aug-1998 HRS 5424		O/C	0		
313003	ACCELEROMETER	SAO		7000922 5122	MTH 01-Feb-1993 HRS 2307		O/C	0		
321001 LEFT	MAIN LANDING GEAR ASSY 6641000	*CF		6641000-3 18	MTH 22-Feb-1985 LDG 0		25800	0	25800	18322
321002 RIGHT	MAIN LANDING GEAR ASSY 6641000	*CF		6641000-4 17	MTH 22-Feb-1985 LDG 0		25800	0	25800	18322
321003 LEFT MAIN LANDING GEAR	TORQUE LINK BOLT			5541220-2 NA	MTH 06-Aug-2012 HRS 8405.2 LDG 7247		21500	0	28747	21269
321003 RIGHT MAIN LANDING GEAR	TORQUE LINK BOLT	*CF		5541220-2 SN-UNKNOWN	MTH 22-Feb-1985 LDG 0	1374	21500	1374	21500	14022
322001	NOSE LANDING GEAR ASSY 6642000-2	*CF		6642000-2 2	MTH 22-Feb-1985 LDG 0		23900	0	23900	16422
322002	NOSE GEAR SHIMMY DAMPER 430558			5543001-11 430558	MTH 20-Feb-2014 HRS 8645.7 LDG 7355		O/C	0 0 0		
322004	NOSE LANDING GEAR FORK *CF			5542300-2 SN-UNKNOWN	MTH 22-Feb-1985 LDG 0		13800	0	13800	6322
322005	NOSE GEAR ACTUATOR FITTING *CF			5511169-1 SN-UNKNOWN	MTH 22-Feb-1985 LDG 0		23900	0	23900	16422
322006 LEFT	NOSE GEAR TRUNNION SUPPORT ASSEMBLY 5513056-5	*CF		6613056-1 SN-UNKNOWN	MTH 22-Feb-1985 LDG 0		11600	0	11600	4122
322006 RIGHT	NOSE GEAR TRUNNION SUPPORT ASSEMBLY 5513056-5	*CF		6613056-2 SN-UNKNOWN	MTH 22-Feb-1985 LDG 0		11600	0	11600	4122
322007	NOSE GEAR TRUNNION *CF			5542301-9 SN-UNKNOWN	MTH 22-Feb-1985 LDG 0		23900	0	23900	16422
322008	NOSE LANDING GEAR PISTON WELD ASSEMBLY *CF			6642100-2 SN-UNKNOWN	MTH 22-Feb-1985 LDG 0		13800	0	13800	6322
323001 LEFT MAIN LANDING GEAR	SIDE BRACE ACTUATOR			9912111-1 35	MTH 15-Jul-2014 HRS 8670.8 LDG 7367		25800	0	33167	25689
323002 RIGHT MAIN LANDING GEAR	SIDE BRACE ACTUATOR 9912111-2	ILG		2-7442-4 SN-UNKNOWN	MTH 07-Jun-2005 HRS 7474 LDG 6632		28500	0	35132	27654
323003 NOSE LANDING GEAR	ACTUATOR			9912120-4 1387B	MTH 06-Aug-2012 HRS 8405.2 LDG 7247			6 0	39847	32369

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
323004 LEFT	LANDING GEAR UPLOCK ACTUATOR 5527500 *CF	5527504-2 WMP479	MTH 22-Feb-1985		O/C			
323004 NOSE	LANDING GEAR UPLOCK ACTUATOR 5527500-2 *CF	5527504-2 WMP463	MTH 22-Feb-1985		O/C			
323004 RIGHT	LANDING GEAR UPLOCK ACTUATOR 5517000 *CF	5527504-2 WMP444	MTH 22-Feb-1985		O/C			
323006	EMERGENCY GEAR AIR BOTTLE	9912103-3 6507	MTH 15-Oct-2020 HRS 8918 LDG 7455		288	144 15.9 9	31-Oct-2032	123 m 23 d
PLEASE NOTIFY CESCOM OF MANUFACTURE DATE, TIME ON COMPONENT, OR SERIAL NUMBER.								
323007	GEAR CONTROL VALVE SAO	66710 119	MTH 17-May-1995 HRS 3518 LDG 3396		O/C		0	
323008	DUMP VALVE *CF	AS19400-1 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
323019	EMERGENCY AIR BOTTLE GAGE *CF	2341128 SN-UNKNOWN	MTH 22-Feb-1985		O/C	0		
324001 LEFT	MAIN WHEEL ASSEMBLY UNK	PN-UNKNOWN SN-UNKNOWN	MTH 01-Aug-2019 HRS 8912.2 LDG 7452		O/C			
324001 RIGHT	MAIN WHEEL ASSEMBLY UNK	PN-UNKNOWN SN-UNKNOWN	MTH 01-Aug-2019 HRS 8912.2 LDG 7452		O/C			
324002	NOSE WHEEL ASSEMBLY UNK	PN-UNKNOWN SN-UNKNOWN	MTH 01-Aug-2019 HRS 8912.2 LDG 7452		O/C			
324003 LEFT	BRAKE ASSEMBLY	5005494-3EX JAN85-51	MTH 22-Oct-2013 HRS 8559.9 LDG 7321		O/C	0 0 0		
324004 RIGHT	BRAKE ASSEMBLY	5005494-3EX APR83-85	MTH 22-Oct-2013 HRS 8559.9 LDG 7321		O/C	0 0 0		
324005 LEFT	MAIN TIRE UNK	220K08-3 83172745	MTH 01-Aug-2019 HRS 8912.2 LDG 7452		O/C	0 0 0		
324005 RIGHT	MAIN TIRE UNK	220K08-3 83172739	MTH 01-Aug-2019 HRS 8912.2 LDG 7452		O/C	0 0 0		
324006	NOSE TIRE UNK	184F10-2 91022654	MTH 01-Aug-2019 HRS 8912.2 LDG 7452		O/C	0 0 0		
324011 LEFT	(PILOT SIDE) MASTER BRAKE CYLINDER 9912050-11 *CF	12A085-11 2746	MTH 22-Feb-1985		O/C			
324011 RIGHT	(PILOT SIDE) MASTER BRAKE CYLINDER 9912050-11 *CF	12A085-11 2743	MTH 22-Feb-1985		O/C			
324012 LEFT	(COPILOT SIDE) MASTER BRAKE CYLINDER 9912050-12 *CF	12A085-12 2820	MTH 22-Feb-1985		O/C			



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
324012 RIGHT	(COPILOT SIDE) MASTER BRAKE CYLINDER 9912050-12	*CF		12A085-12 2680	MTH 22-Feb-1985		O/C			
324014	EMERGENCY AIR BRAKE VALVE 9912105-1	*CF		53640 641A	MTH 22-Feb-1985		O/C			
324019	BRAKE PRESSURE PUMP ASSY 9912166-2	*CF		634343 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
324020	BRAKE CONTROL BOX 9912305-6	IND		42-707-1 241	MTH 30-Apr-2008 HRS 7898		O/C	0		
324021	POWER BRAKE ANTI-SKID VALVE 9912305-7	SAO		38-707-1 159	MTH 02-Jun-1985 HRS 78		O/C	0		
324023	ACCUMULATOR	*CF		57C57652 63	MTH 22-Feb-1985		O/C			
324024 LEFT	WHEEL TRANSDUCER 9912305-2	SNA		40-955 3876	MTH 08-Apr-2002 HRS 6533		O/C	0		
324024 RIGHT	WHEEL TRANSDUCER 9912305-2	UVA		40-955 3932	MTH 18-Sep-2007 HRS 7836		O/C	0		
324025	PRESSURE SWITCH 9912163-1	IND		1206P25 2001	MTH 30-Apr-2008 HRS 7898 LDG 6952		O/C	0		
324026	POWER BRAKE ASSEMBLY MOTOR SDL			MP50B1 1920	MTH 17-Jul-2001 HRS 6343		O/C	0		
324101	PARKING BRAKE VALVE *CF			AS20800-6 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
325001	BUNGEE ASSEMBLY	SNA		5565624-20 SN-UNKNOWN	MTH 14-Mar-2001 HRS 6237 LDG 5681		O/C	0		
326002 LEFT	M/G UP & LOCKED SWITCH *CF			65430087 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
326002 RIGHT	M/G UP & LOCKED SWITCH *CF			65430087 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
326003 LEFT	M/G DOWN & LOCK SWITCH SNA			602EN16-6B SN-UNKNOWN	MTH 23-Jul-1999 HRS 5642 LDG 5262		O/C	0		
326003 RIGHT	M/G DOWN & LOCK SWITCH SNA			602EN16-6B SN-UNKNOWN	MTH 23-Jul-1999 HRS 5642 LDG 5262		O/C	0		
326004	N/G DOWN & LOCK SWITCH *CF			602EN16-6B SN-UNKNOWN	MTH 22-Feb-1985		O/C			
326005	N/G UP&LOCKED SWITCH *CF			CM3597-1 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
331001	ANNUNCIATOR PANEL -- 9912119-8	IND		465-1-8 036	MTH 20-Jun-2008 HRS 7909		O/C	0		
331011	EL PANEL-115V INVERTER *CF			EM2044-1 509	MTH 22-Feb-1985		O/C			
332002 AFT	INDIRECT LIGHTING INVERTER CRQ			18.996-1 7371	MTH 23-Dec-1999 HRS 5821		O/C	0		



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
332002 FORWARD	INDIRECT LIGHTING INVERTER SAO			18.994C 4453	MTH 16-Nov-1993 HRS 2431		O/C	0		
334002	VERT FIN ANTI-COLLISION LIGHT ASSEMBLY IND			40-0100-15 2372	MTH 05-Dec-2007 HRS 7851		O/C	0		
334003 LEFT	STROBE LIGHT POWER SUPPLY 9910368-2 SAO			60-2799-1 14289	MTH 25-Oct-1996 HRS 4576		O/C	0		
334003 RIGHT	STROBE LIGHT POWER SUPPLY 9910368-2 IND			60-2799-1 17203	MTH 08-Aug-2008 HRS 7919		O/C	3621		
334004 RIGHT	STROBE LITE TUBE APS-25423			31-3172-11 31-3172-11	MTH 10-Mar-2010 HRS 8032 LDG 7035		O/C	1 0 0		
335001	EMERGENCY BATTERY PACK SAO			6568109-7 SN-UNKNOWN	MTH 23-Jul-1996 HRS 4432		O/C	0		
341001 LEFT	AIR SPEED INDICATOR AW2837AB05 SNA			C661063-0104 SN-UNKNOWN	MTH 12-Apr-2001 HRS 6255		O/C	0		
341001 RIGHT	AIR SPEED INDICATOR AW2837AB05 GJT			C661063-0104 127ABC	MTH 09-Aug-2001 HRS 6352		O/C	97		
341002 STANDBY	ALTIMETER UNK			C661072-0101 W002011	MTH 25-Mar-2021 HRS 8923.2 LDG 7461		O/C			
341004	OAT GAUGE 162BL507D *CF			C668510-0401 2070	MTH 22-Feb-1985		O/C			
341005	OVERSPEED WARNING SWITCH 9912076-12 GSO			D2RA45C-24 330	MTH 28-Jun-2006 HRS 7661		O/C	0		
341010	AOA INDICATOR *CF			SLZ9987 CR1060C	MTH 22-Feb-1985		O/C			
341012	AOA POTENTIOMETER 5518132-1 *CF			MOD202-5K SN-UNKNOWN	MTH 22-Feb-1985		O/C			
341013	AOA TRANSMITTER *CF			SLZ7672 DY1028	MTH 22-Feb-1985		O/C			
341014	AOA TRANSMITTER INDEXER *CF			SLZ9374 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
341019 LEFT	ALTIMETER BA-141			4016341-905 80031395	MTH 20-Mar-1997 HRS 4884		O/C	2109		
341019 RIGHT <i>341002 : R</i>	RIGHT ALTIMETER 10450-11110			C661072-0101 W8020H	MTH 06-Dec-2002 HRS 6689		O/C	0		
341020	V-NAV COMPUTER CONTROL VN-212 SNA			4020571-904 90082344	MTH 23-Dec-2003 HRS 6999		O/C	4273		
342001	MAGNETIC COMPASS C2400-L4V2W-5B			C660501-0301 SN-UNKNOWN	MTH 04-Feb-2010 HRS 8016 LDG 7027		O/C	0 0 0		
342002	TURN AND BANK INDICATOR SNA			C661004-0101 95345H	MTH 17-Nov-2003 HRS 6968		O/C	0		



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
342003 RIGHT	HORIZON GYRO 1U149-002-2	VNY		C661056-0202 TH2039H	MTH 25-Feb-2005 HRS 7384		O/C	0		
342021 LEFT	VERTICAL SPEED INDICATOR *CF			C661006-0101 W10821H	MTH 22-Feb-1985		O/C			
342021 RIGHT	VERTICAL SPEED INDICATOR *CF			C661006-0101 W10822H	MTH 22-Feb-1985		O/C			
342041	FLIGHT DIRECTOR COMPUTER FZ-500	SNA		4018369-905 93096889	MTH 23-Jul-1999 HRS 5642		O/C	968		
342042 RIGHT	AP/FD MODE SELECTOR MS-205	SAO		4020570-903 86081532	MTH 03-Oct-1997 HRS 5158		O/C	0		
342043 LEFT	VERTICAL GYRO VG-14A	SAO		7000622-901 92117220	MTH 15-Jun-1998 HRS 5403		O/C	594		
342044 LEFT	RATE GYRO RG-204	SAO		7007453-903 96104155	MTH 15-Jun-1998 HRS 5403		O/C	0		
342046 NO. 1	AIR DATA COMPUTER AZ-241			4013241-931 84062728	MTH 14-Aug-1998 HRS 5424		O/C	2026		
342048 LEFT <i>342048L : L</i>	ADDU INDICATOR	UNK		9D-80130-16 26841	MTH 25-Mar-2021 HRS 8923.2 LDG 7461		O/C			
342048 RIGHT <i>342048R : R</i>	ADDU INDICATOR	UNK		9D-80130-16 26297	MTH 25-Mar-2021 HRS 8923.2 LDG 7461		O/C			
342048 STANDBY	ADC/ALTIMETER --	GJT		90004-00348111038 94977	MTH 20-Sep-2000 HRS 6026		O/C	608		
342049 LEFT	DIR GYRO SYN COMPASS C-14D	IND		4020577-3 83113251	MTH 30-Apr-2008 HRS 7898		O/C	39		
342049 RIGHT	DIR GYRO SYN COMPASS C-14D	SAO		4020577-3 82042641	MTH 06-Jan-1997 HRS 4712		O/C	0		
342050 LEFT	FLUX VALVE FX-220	SAO		2594484 82080700	MTH 23-Apr-1996 HRS 4231		O/C	0		
342050 RIGHT	FLUX VALVE FX-220	SAO		2594484 85118763	MTH 23-May-1996 HRS 4296		O/C	0		
342052	REMOTE COMPENSATOR CS-412	*CF		2593379-1 84067728	MTH 22-Feb-1985		O/C			
342053 RIGHT	HSI INDICATOR RD-450	SAO		7002493-903 84080406	MTH 26-Jan-1993 HRS 2302		O/C	2302		
342064	STANDBY GYRO POWER SUPPLY PS-835	UNK		501-1228-04 5550	MTH 01-Aug-2019 HRS 8912.2 LDG 7452		O/C	0 0 0		
342065	STAND-BY GYRO AI-804	IND		501-1197-05 2475	MTH 16-Mar-2009 HRS 7930		O/C	0		
342066 LEFT BOTTOM	EFIS HSI DISPLAY ED-800	SAO		7003430-901 86120802	MTH 29-Dec-1997 HRS 5314		O/C	428		



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
342066 LEFT TOP	EFIS HSI DISPLAY ED-800	*CF		7003430-901 84060333	MTH 22-Feb-1985		O/C			
342067	SELECT CONTROLLER SENSOR SC-800	LGB		7004123-213 88050974	MTH 14-Aug-1998 HRS 5424		O/C	0		
342068 LEFT	EFIS CONTROLLER DC-800	GRR		7003420-945 85050515	MTH 07-Jul-1998 HRS 5418		O/C	0		
342070 LEFT	EFIS SYMBOL GENERATOR SG-601	SAO		7003400-912 84110458	MTH 15-Jun-1998 HRS 5403		O/C	3677		
342072	JET STATIC CONVERTER *CF			501-1318-01 1840	MTH 22-Feb-1985		O/C			
344002	RADAR INDICATOR DI-2007			MI585277 3558	MTH 11-Mar-2015 HRS 8805.1 LDG 7415		O/C	4046.1		
344019	RADAR-RCVR/XMTR --			MI585222-1 3316	MTH 11-Mar-2015 HRS 8805.1 LDG 7415		O/C	6246.1		
344020 -	RADAR ANTENNA --		8	MI585224-2 3101	MTH 11-Mar-2015 HRS 8805.1 LDG 7415		O/C	4700.1		
344021 LEFT	TAWS/RMI INDICATOR RMI-30	CRQ		622-4938-004 5784	MTH 18-Nov-1999 HRS 5771		O/C	0		
344021 RIGHT	TAWS/RMI INDICATOR RMI-30	LGB		622-4938-004 7179	MTH 15-Jun-2004 HRS 7216		O/C	4239		
344022	RADIO ALTIMETER TRANSCEIVER RT-300	*CF		7001840-905 84031180	MTH 22-Feb-1985		O/C			
344023 AFT	RADIO ALTM ANTENNA AT-224	*CF		4010504 83062032	MTH 22-Feb-1985		O/C			
344023 FORWARD	RADIO ALTM ANTENNA AT-224	*CF		4010504 83041982	MTH 22-Feb-1985		O/C			
345004 LEFT	TRANSPONDER ANTENNA *CF			DMN150-2 25706	MTH 22-Feb-1985		O/C			
345004 RIGHT	TRANSPONDER ANTENNA *CF			DMN150-2 25710	MTH 22-Feb-1985		O/C			
345007 LEFT	DME ANTENNA *CF			DMN150-2 25674	MTH 22-Feb-1985		O/C			
345011 LEFT	ADF RECEIVER ADF-60A	SAO		622-2362-001 20515	MTH 13-Aug-1996 HRS 4474		O/C	1129		
345011 RIGHT	ADF RECEIVER ADF-60A	SAO		622-2362-001 2755	MTH 27-Jan-1998 HRS 5352		O/C	1341		
345014 LEFT	ADF LOOP ANTENNA APA-80	GSO		622-2363-001 28PYH	MTH 20-Jul-2006 HRS 7677		O/C	0		
345014 RIGHT	ADF LOOP ANTENNA APA-80	LGB		622-2363-001 1GM4K	MTH 23-Jun-2004 HRS 7233		O/C	0		
345017	MARKER BEACON ANTENNA SNA			CI164 SN-UNKNOWN	MTH 11-May-1999 HRS 5548		O/C	0		
345018	GLIDESCOPE ANTENNA *CF			RGS1048 9272	MTH 22-Feb-1985		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
345021 NO. 1	RVSM ANALOG INTERFACE UNIT UVA			9B-81040-26 26841	MTH HRS		22-Sep-2004 7276	O/C 0		
345032 BOTTOM	NO.2 NAVIGATION TRANSCEIVER VIR-32	GSO		622-6137-001 5369	MTH HRS		24-Jan-2007 7772	O/C 0		
345032 TOP	NO.1 NAVIGATION TRANSCEIVER VIR-32	SAI		622-6137-001 3959	MTH HRS		30-Jun-1994 2927	O/C 0		
345033 BOTTOM	NAVIGATION NO. 2 CONTROL UNIT CTL-32	SAO		622-6521-013 2648	MTH HRS		15-Jun-1998 5403	O/C 2268		
345033 TOP	NAVIGATION NO. 1 CONTROL UNIT CTL-32	*CF		622-6521-013 2131	MTH		22-Feb-1985	O/C		
345034 LEFT	TRANSPONDER GTX-330			010-00230-21 84305571	MTH HRS		19-Jun-2013 8548.8	O/C 8548.8		
345034 RIGHT	TRANSPONDER TDR-90			622-1270-001 24746	MTH HRS		19-Jun-2013 8548.8	O/C		
345035 LEFT	DME INDICATOR IND-42A	SNA		622-6524-001 557	MTH HRS		24-Aug-2001 6362	O/C 6352		
345036 LEFT	DME INTERROGATOR DME-42	IND		622-6263-003 15286	MTH HRS		20-Jun-2008 7909	O/C 0		
345039	CONTROL TRANSPONDER ADAPTER CAD-62	SAO		622-6590-001 12996	MTH HRS		04-Dec-1995 3942	O/C 0		
345040	TRANSPONDER CONTROL CTL-92	SAO		622-6523-005 1886	MTH HRS		24-Sep-1997 5140	O/C 0		
345053	VLF ANTENNA	*CF		11455-2 1238	MTH		22-Feb-1985	O/C		
345054	VLF CONTROL DISPLAY	SAO		11600-2 382	MTH HRS		25-Oct-1996 4576	O/C 1813		
345056	VLF RECEIVER/COMPUTER	SAO		10050-3-3B1 4290	MTH HRS		11-Nov-1996 4600	O/C 1005		
345057 -	VLF OPT EQUIPMT UNIT -- SAO			10600-2-202 3513	MTH HRS		11-Nov-1996 4600	O/C 1802		
345080 NO. 1	CONTROL DISPLAY UNIT -- IND			1117-11 279	MTH HRS		18-Jul-2008 7919	O/C 0		
345081 NO. 1	CONFIGURATION MODULE -- GRR			11926 636	MTH HRS		07-Jul-1998 5418	O/C 0		
345084	NCU --			1116-40-1116 149	MTH HRS LDG		17-Aug-2012 8410 7249	O/C 940		
346093	GPS ANTENNA	ILG		401-420 5070725	MTH		15-Aug-2005	O/C		
346098	GPS RECEIVER			069-01034-0101 1255	MTH HRS		01-Apr-2001 6254	O/C 0		
351001	OXYGEN PRESSURE GAUGE MD-97	*CF		C668512-0101 6211	MTH		22-Feb-1985	O/C 0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
351004 LEFT	CREW OXYGEN MASK 9914067-41	CRQ		MC10-16-101 92605	MTH 29-Jun-2022 HRS 8957.7 LDG 7478		72	0	30-Jun-2028	71 m 22 d
Manufacture Date: 01-Jun-2022										
351004 RIGHT	CREW OXYGEN MASK ZC369-64	CRQ		174260-63 07444	MTH 29-Jun-2022 HRS 8957.7 LDG 7478		72	0	30-Jun-2028	71 m 22 d
Manufacture Date: 13-Jun-2022										
351005	OXYGEN REGULATOR *CF			ZR807 165	MTH 22-Feb-1985		O/C	0		
351006	OXYGEN CYLINDER ASSEMBLY ZC369-64	UNK		176176-64 L400070	MTH 25-Jan-2021 HRS 8921.5 LDG 7459		288	292	01-Sep-2033	133 m 24 d
361003	PNEUMATIC REGULATOR 9912043-2	*CF		38E85-5C RF1324	MTH 22-Feb-1985		O/C			
361005 RIGHT	GYRO PRESSURE GAGE *CF	*CF		C668515-0101 6153	MTH 22-Feb-1985		O/C			
361006 BOTTOM	FORWARD INST BA PRESS REGULATOR LGB			3H64-7 4AY3	MTH 15-Jun-2004 HRS 7216		O/C	0		
361006 TOP	FORWARD INST BA PRESS REGULATOR *CF	*CF		3H64-4 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
361007	PRESSURE DOOR SEAL HOSE *CF			CM2939-4-15 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
383002	TOILET PUMP			17000-102 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
521001	CABIN DOOR SEAL 9912075-4	SNA		S15501-4 SN-UNKNOWN	MTH 21-Nov-2003 HRS 6968		O/C	0		
526001	CABIN DOOR STEP 6519009	*CF		6519009-44 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
561001 LEFT	MAIN WINDSHIELD ASSY, (LH) UNK	UNK		PAS9912064-15 21811	MTH 04-Nov-2015 HRS 8873.5 LDG 7436		O/C	0 0 0		
561002 RIGHT	MAIN WINDSHIELD ASSY, (LH) 9912064-16	UNK		P00042-1 7000	MTH 04-Nov-2015 HRS 8873.5 LDG 7436		O/C	0 0 0		
561003	FOUL WEATHER WINDOW GJT			5511275-202 2439	MTH 27-Sep-1999 HRS 5714		O/C	0		
561005 LEFT INBOARD	FLIGHT COMPARTMENT WINDOW GJT			5511285-5 0158	MTH 31-Oct-2001 HRS 6415		O/C	0		
561005 LEFT OUTBOARD	FLIGHT COMPARTMENT WINDOW GJT			5511285-3 0143	MTH 31-Oct-2001 HRS 6415		O/C	0		
561005 RIGHT INBOARD	FLIGHT COMPARTMENT WINDOW GJT			5511285-6 0167	MTH 31-Oct-2001 HRS 6415		O/C	0		
561005 RIGHT OUTBOARD	FLIGHT COMPARTMENT WINDOW GJT			5511285-4 0187	MTH 31-Oct-2001 HRS 6415		O/C	0		
562001 LEFT NO. 1	CABIN WINDOW *CF	*CF		5591005-6 SN-UNKNOWN	MTH 22-Feb-1985		O/C			





# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
562001 LEFT NO. 2	CABIN WINDOW			PAS9912207-8 9911	MTH 30-Sep-2009 HRS 7930 LDG 6975		O/C	6 0 0		
562001 LEFT NO. 3	CABIN WINDOW	*CF		5591005-5 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
562001 LEFT NO. 4	CABIN WINDOW	*CF		5591005-5 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
562001 LEFT NO. 5	CABIN WINDOW			PAS9912207-8 9912	MTH 30-Sep-2009 HRS 7930 LDG 6975		O/C	6 0 0		
562001 LEFT NO. 6	CABIN WINDOW	*CF		5591005-5 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
562001 RIGHT NO. 1	CABIN EMERGENCY DOOR WINDOW	*CF		5591005-5 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
562001 RIGHT NO. 2	CABIN WINDOW	*CF		5591005-5 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
562001 RIGHT NO. 3	CABIN WINDOW	*CF		5591005-5 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
562001 RIGHT NO. 4	CABIN WINDOW	*CF		5591005-5 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
562001 RIGHT NO. 5	CABIN WINDOW	*CF		5591005-5 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
562001 RIGHT NO. 6	CABIN WINDOW			PAS9912207-8 9910	MTH 30-Sep-2009 HRS 7930 LDG 6975		O/C	6 0 0		
576002 LEFT	AILERON --	IND		6524113-805 173C	MTH 20-Jun-2008 HRS 7909		O/C	0		
712001 LEFT	AFT ENGINE ISOLATOR		ILG	LM420SA23 SN-UNKNOWN	MTH 06-Jun-2005 HRS 7474		3500	0	10974	2016.3
712001 RIGHT	AFT ENGINE ISOLATOR		UNK	PN-UNKNOWN SN-UNKNOWN	MTH 01-Aug-2019 HRS 8912.2 LDG 7452		3500	9692	13192	4234.3
712002 LEFT BOTTOM	FWD ENGINE ISOLATOR		ILG	LM420SA31 SN-UNKNOWN	MTH 06-Jun-2005 HRS 7474		3500	0	10974	2016.3
712002 LEFT TOP	FWD ENGINE ISOLATOR		ILG	LM420SA30 SN-UNKNOWN	MTH 06-Jun-2005 HRS 7474		3500	0	10974	2016.3
712002 RIGHT BOTTOM	FWD ENGINE ISOLATOR		UNK	PN-UNKNOWN SN-UNKNOWN	MTH 01-Aug-2019 HRS 8912.2 LDG 7452		3500	9692	13192	4234.3
712002 RIGHT TOP	FWD ENGINE ISOLATOR		UNK	PN-UNKNOWN SN-UNKNOWN	MTH 01-Aug-2019 HRS 8912.2 LDG 7452		3500	9692	13192	4234.3
71EN1 NO. 1 <i>710001 : E1**L</i>	ENGINE	KTMB		JT15D-4B PCE-102184	MTH 22-Oct-2013 HRS 8559.9 LDG 7351		E/C	12194.2		
71EN2 NO. 2 <i>710001 : E2**R</i>	ENGINE	KTMB		JT15D-4B PCE-102210	MTH 22-Oct-2013 HRS 8559.9 LDG 7351		E/C	12194.2		
722001 E1	OIL PUMP	FXE		3104268-01 HIA9123	MTH 22-Nov-2008 HRS 7718.7		O/C	0		



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
722001 E2	OIL PUMP			3104268-01 PWC89D5158	MTH 13-Jun-2008 HRS 7686.6 LDG 6932		O/C	0 0 0		
723001 E1	ENGINE FAN --	SAT		3018020 SN-UNKNOWN	MTH 20-Jun-2001 HRS 6057.7		O/C	0		
723001 E2	ENGINE FAN --	SAT		3018020 SN-UNKNOWN	MTH 20-Jun-2001 HRS 6057.7		O/C	0		
723010 E1	CENTRIFUGAL IMPELLER	SAT		3040937 A000K10L	MTH 20-Jun-2001 HRS 6057.7 LDG 6140 ACCC YC		12000	0	(10662)10662	10662
723010 E2	CENTRIFUGAL IMPELLER	SAT		3040937 A000FR1M	MTH 20-Jun-2001 HRS 6057.7 LDG 6140 ACCC YC		12000	0	(10662)10662	10662
723020 E1	LOW PRESSURE BOOST COMPRESSOR HUB	SAT		3021112 7P760	MTH 20-Jun-2001 HRS 6057.7 LDG 6140 ACCC YC		14000	9054 9054	(3608)3608	3608
723020 E2	LOW PRESSURE BOOST COMPRESSOR HUB	SAT		3021112 2R114	MTH 20-Jun-2001 HRS 6057.7 LDG 6140 ACCC YC		14000	9054 9054	(3608)3608	3608
723030 E1	LOW PRESSURE COMPRESSOR HUB	SAT		3018018 1R148	MTH 20-Jun-2001 HRS 6057.7 LDG 6140 ACCC YC		27500	9054 18108	(6716)3358	6716
723030 E2	LOW PRESSURE COMPRESSOR HUB	SAT		3018018 3R894	MTH 20-Jun-2001 HRS 6057.7 LDG 6140 ACCC YC		27500	9054 18108	(6716)3358	6716
725010 E1	HIGH PRESSURE TURBINE ROTOR DISK	SAT		3023411 23A034	MTH 20-Jun-2001 HRS 6057.7 LDG 6140 ACCC YC		14000	0	(12662)12662	12662
725010 E2	HIGH PRESSURE TURBINE ROTOR DISK	SAT		3023411 2W631	MTH 20-Jun-2001 HRS 6057.7 LDG 6140 ACCC YC		14000	9054 9054	(3608)3608	3608
725020 E1	SECOND STAGE LOW PRESSURE TURBINE ROTOR DISK	SAT		3022212 2R909	MTH 20-Jun-2001 HRS 6057.7 LDG 6140 ACCC YC		14000	9054 9054	(3608)3608	3608
725020 E2	SECOND STAGE LOW PRESSURE TURBINE ROTOR DISK			3022212 4L809	MTH 13-Jun-2008 HRS 7686.6 LDG 6932 ACCC YC		14000	11320.9 9817	(3608)3608	3608



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
725030 E1	THIRD STAGE LOW PRESSURE TURBINE ROTOR DISK SAT		3021213 3R032	MTH 20-Jun-2001 HRS 6057.7 LDG 6140 ACCC YC		14000	9054 9054	(3608)3608	3608
725030 E2	THIRD STAGE LOW PRESSURE TURBINE ROTOR DISK SAT		3036113 5T257	MTH 20-Jun-2001 HRS 6057.7 LDG 6140 ACCC YC		14000	9054 9054	(3608)3608	3608
725071 E1	COMBUSTION LINER SAT		3105143-01 8C493	MTH 20-Jun-2001 HRS 6057.7		O/C	0		
725071 E2	COMBUSTION LINER SAT		3105143-01 9C978	MTH 20-Jun-2001 HRS 6057.7		O/C	0		
725101 E1 NO. 1	REPLACE HIGH TURBINE BLADES SAT			MTH 20-Jun-2001 HRS 6057.7		O/C			
725101 E2 NO. 1	REPLACE HIGH TURBINE BLADES SAT			MTH 20-Jun-2001 HRS 6057.7		O/C			
731004 LEFT	LOW FUEL PRESSURE SWITCH 9912033-1 *CF		1103P92 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
731004 RIGHT	LOW FUEL PRESSURE SWITCH 9912033-1 *CF		1103P92 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
732002	ENGINE SYNC CONTROL 5560001 SAO		213787 22428404	MTH 14-Jul-1997 HRS 5036		O/C	0		
732003	ENGINE SYNC ACTUATOR *CF		5485-066 1759775D	MTH 22-Feb-1985		O/C			
733002	FUEL FLOW INDICATOR 9912147-16 GJT		VSDL-OC208E 282CA	MTH 27-Sep-1999 HRS 5714		O/C	0		
731010 E1	FUEL PUMP		025493-402 2190	MTH 20-Feb-2014 HRS 8645.7 LDG 7385		O/C	954.1		
731010 E2	FUEL PUMP 3032203 SAT		398601-2 536	MTH 20-Jun-2001 HRS 6057.7		O/C	0		
731020 E1	FUEL-OIL COOLER 3015303 SAT		UA530768-4 3107	MTH 20-Jun-2001 HRS 6057.7		O/C	0		
731020 E2	FUEL-OIL COOLER 3015303 SAT		UA530768-4 3301	MTH 20-Jun-2001 HRS 6057.7		O/C	0		
731030 E1	MOTIVE FLOW VALVE 3017930 SAT		2524995 A90562	MTH 20-Jun-2001 HRS 6057.7		O/C	0		
731030 E2	MOTIVE FLOW VALVE 3017930		2524995-1 A90618	MTH 13-Jun-2008 HRS 7686.6 LDG 6932		O/C			
731040 E1	FLOW DIVIDER VALVE 3024476 SAT		25607-2 3288	MTH 20-Jun-2001 HRS 6057.7		O/C	0		
731040 E2	FLOW DIVIDER VALVE 3024476 SAT		25607-2 3294	MTH 20-Jun-2001 HRS 6057.7		O/C	0		



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
732004 E1	SOLENOID FUEL VALVE 3029591	SAT		3244758-1 C18177	MTH 20-Jun-2001 HRS 6057.7		O/C	0		
732004 E2	SOLENOID FUEL VALVE 3029591	SAT		3244758-1 C18158	MTH 20-Jun-2001 HRS 6057.7		O/C	0		
732010 E1	FUEL CONTROL UNIT 3030251			3244759-3 A58671	MTH 20-Feb-2014 HRS 8645.7 LDG 7355		O/C	1608.9		
732010 E2	FUEL CONTROL UNIT 3030251	SAT		3244759-3 A92547	MTH 20-Jun-2001 HRS 6057.7		O/C	0		
733010 E1	FUEL FLOW TRANSMITTER 9912031-6			3268014-0201 1130D	MTH 27-Aug-2010 HRS 8109 LDG 7087		O/C			
733010 E2	FUEL FLOW TRANSMITTER 9912031-6			3268014-0201 995B	MTH 23-Jan-1996 HRS 2883.7		O/C	0	0	
741010 E1 LOWER	IGNITION EXCITER	SAT		NB01201 K6421	MTH 20-Jun-2001 HRS 6057.7		O/C	0		
741010 E2 LOWER	IGNITION EXCITER	SAT		NB01201 K8934	MTH 20-Jun-2001 HRS 6057.7		O/C	0		
741015 E1 UPPER	IGNITION EXCITER	SAT		NB01201 K6679	MTH 20-Jun-2001 HRS 6057.7		O/C	0		
741015 E2 UPPER	IGNITION EXCITER	SAT		NB01201 1239	MTH 20-Jun-2001 HRS 6057.7		O/C	0		
742010 E1 OUTBOARD	IGNITER PLUG	UNK		FHE246-4 SN-UNKNOWN	MTH 01-Aug-2019 HRS 8912.2		O/C	0	0	
742010 E2 OUTBOARD	IGNITER PLUG	UNK		FHE246-4 SN-UNKNOWN	MTH 01-Aug-2019 HRS 8912.2		O/C	0	0	
742020 E1 INBOARD	IGNITER PLUG	UNK		FHE246-4 SN-UNKNOWN	MTH 01-Aug-2019 HRS 8912.2		O/C	0	0	
742020 E2 INBOARD	IGNITER PLUG	UNK		FHE246-4 SN-UNKNOWN	MTH 01-Aug-2019 HRS 8912.2		O/C	0	0	
742030 E1 SHORT	IGNITER LEAD	UNK		53067-21 SN-UNKNOWN	MTH 01-Oct-2018 HRS 8902.1 LDG 7446		O/C			
742030 E2 SHORT	IGNITER LEAD	SAT		10-395428-1 SN-UNKNOWN	MTH 20-Jun-2001 HRS 6057.7		O/C	0		
742040 E1 LONG	IGNITER LEAD	UNK		53067-38.5 SN-UNKNOWN	MTH 01-Aug-2019 HRS 8912.2		O/C	0	0	
742040 E2 LONG	IGNITER LEAD	SAT		53067-38.5 SN-UNKNOWN	MTH 20-Jun-2001 HRS 6057.7		O/C	0		



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
750010 E1	LOW PRESSURE COMPRESSOR ANTI-ICING SOLENOID VALVE 3018531	SAT		KW15632 3568	MTH 20-Jun-2001 HRS 6057.7		O/C	0		
750010 E2	LOW PRESSURE COMPRESSOR ANTI-ICING SOLENOID VALVE 3018531	SAT		KW15632 3281	MTH 20-Jun-2001 HRS 6057.7		O/C	0		
761005	SOLENOID ASSEMBLY 9912110-1	*CF		U-183238-001 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
771001 LEFT BOTTOM	TACH N2 GENERATOR 9912034-1	*CF		22A623 6994	MTH 22-Feb-1985		O/C			
771001 LEFT TOP	TACH N1 GENERATOR 9912034-1	GJT		22A623 7033	MTH 25-Aug-1999 HRS 5686		O/C	721		
771001 RIGHT BOTTOM	TACH N2 GENERATOR 9912034-1	SAO		22A623 7222	MTH 10-Oct-1996 HRS 4576		O/C	0		
771001 RIGHT TOP	TACH N1 GENERATOR 9912034-1	GJT		22A623 7774	MTH 25-Aug-1999 HRS 5686		O/C	372		
771002	N2 TURBINE RPM INDICATOR 9912147-24	IND		9912147-24 83	MTH 18-Mar-2011 HRS 8205.2 LDG 7152		O/C			
771003	N1 FAN RPM INDICATOR 9912147-24	IND		VSDL-OC410AD 85	MTH 08-Aug-2008 HRS 7919		O/C	0		
772003 772001	ITT INDICATOR 9912147-34	IND		VSDL-OC419L 141	MTH 08-Aug-2008 HRS 7919		O/C	5113		
781001 LEFT	EXHAUST NOZZLE CONE 9912110-6-S6	*CF		9912110-6-S6 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
781001 RIGHT	EXHAUST NOZZLE CONE 9912110-7-S7	*CF		9912110-7-S7 SN-UNKNOWN	MTH 22-Feb-1985		O/C			
783001 LEFT	THRUST REVERSER ASSEMBLY 202-0100-501	LGB		202-0100-501 RC1538	MTH 18-Aug-1998 HRS 5424 LDG 5114		O/C	5114		
783001 RIGHT	THRUST REVERSER ASSEMBLY 202-0100-503			202-0100-503 RC1507	MTH 18-Mar-2011 HRS 8205.2 LDG 7152		O/C			
783002 LEFT	CONTROL VALVE 65680	*CF		65680 801	MTH 22-Feb-1985		O/C			
783002 RIGHT	CONTROL VALVE 65680	*CF		65680 794	MTH 22-Feb-1985		O/C			
783003 LEFT	THREE WAY VALVE 13027-4	*CF		13027-4 1526	MTH 22-Feb-1985		O/C			
783003 RIGHT	THREE WAY VALVE 13027-4	*CF		13027-4 1513	MTH 22-Feb-1985		O/C			
783005 LEFT	THRUST REVERSER DOOR 202-0001-1	*CF		202-0001-1 1538	MTH 22-Feb-1985		O/C			
783005 RIGHT	THRUST REVERSER DOOR 202-0001-2	*CF		202-0001-2 1533	MTH 22-Feb-1985		O/C			
783006 LEFT	THRUST REVERSER DOOR 202-0002-1	*CF		202-0002-1 1538	MTH 22-Feb-1985		O/C			
783006 RIGHT	THRUST REVERSER DOOR 202-0002-2	*CF		202-0002-2 1533	MTH 22-Feb-1985		O/C			



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
783007 LEFT	THRUST REVERSER MECH ASSEMBLY 9912110-1	*CF		202-0004-1 1538	MTH 22-Feb-1985		O/C			
783007 RIGHT	THRUST REVERSER MECH ASSEMBLY 9912110-1	*CF		202-0004-1 1535	MTH 22-Feb-1985		O/C			
783008 LEFT	THRUST REVERSER MECH ASSEMBLY 9912110-1	*CF		202-0004-3 1538	MTH 22-Feb-1985		O/C			
783008 RIGHT	THRUST REVERSER MECH ASSEMBLY 9912110-1	*CF		202-0004-5 1535	MTH 22-Feb-1985		O/C			
783009 LEFT	THRUST REVERSER FAN DUCT 9912110-1	*CF		202-0012-1 1538	MTH 22-Feb-1985		O/C			
783009 RIGHT	THRUST REVERSER FAN DUCT 9912110-1	*CF		202-0012-1 1535	MTH 22-Feb-1985		O/C			
783010 LEFT INBOARD	THRUST REVERSER ACTUATOR 9912110-1	*CF		62270 1480	MTH 22-Feb-1985		O/C			
783010 LEFT OUTBOARD	THRUST REVERSER ACTUATOR 9912110-1	*CF		62270 1496	MTH 22-Feb-1985		O/C			
783010 RIGHT INBOARD	THRUST REVERSER ACTUATOR 9912110-1	*CF		62270 1555	MTH 22-Feb-1985		O/C			
783010 RIGHT OUTBOARD	THRUST REVERSER ACTUATOR 9912110-1	*CF		62270 1554	MTH 22-Feb-1985		O/C			
793001	OIL TEMPERATURE INDICATOR			9912147-11 220A	MTH 18-Mar-2011 HRS 8205.2 LDG 7152		O/C			
793002 LEFT	OIL TEMPERATURE TRANSMITTER SAO			MS28034-3 92627	MTH 21-Jul-1994 HRS 2974		O/C	0		
793002 RIGHT	OIL TEMPERATURE TRANSMITTER SAO			MS28034-3 91319	MTH 27-Sep-1989 HRS 1108		O/C	0		
793003	OIL PRESSURE INDICATOR 9912147-10	SNA		VSDL-OC204H 195A	MTH 07-Apr-1999 HRS 5525		O/C	5525		
793004 LEFT	OIL PRESSURE TRANSMITTER 9912164-1	SAO		123479 49894	MTH 15-Nov-1995 HRS 3895		O/C	0		
793004 RIGHT	OIL PRESSURE TRANSMITTER 9912164-1	SAO		123479 47909	MTH 15-Jun-1998 HRS 5403		O/C	0		
793006 RIGHT	SW-LOW OIL PRESSURE -- SAO			1103P89-1 797	MTH 10-Oct-1996 HRS 4576		O/C	0		
792003 E1	OIL FILTER	SAT		3015330 SN-UNKNOWN	MTH 20-Jun-2001 HRS 6057.7		O/C	0		
792003 E2	OIL FILTER			3111843-01 NSN	MTH 13-Jun-2008 HRS 7686.6 LDG 6932		O/C	0 0 0		
832001 E1	MAIN GEAR BOX ASSY -- SAT			3018390 SN-UNKNOWN	MTH 20-Jun-2001 HRS 6057.7		O/C	0		
832001 E2	MAIN GEAR BOX ASSY -- SAT			3018390 SN-UNKNOWN	MTH 20-Jun-2001 HRS 6057.7		O/C	0		



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-03-01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC)		INFORMATIONAL			-			
	<b>MOC :</b>								
SL CIL-99-03 R01	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)		RECOMMENDED			-			
	<b>MOC :</b>								
SL CIL-99-03	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) (SUPERSEDED BY CIL-99-03 R01)		RECOMMENDED MTH			-			
	<b>MOC :</b>								
SL S550-03-02 R01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC) (THIS SL IS REPLACED BY CIL-03-01, DATED JUNE 3, 2013)		INFORMATIONAL			-			
	<b>MOC :</b>								
SL S550-99-04 R07	CESCOM PRICES (THIS SL IS CANCELS SLS550-99-04 R6 AND PREVIOUS)		INFORMATIONAL			-			
	<b>MOC :</b>								
SL S550-99-07	MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS		INFORMATIONAL			A/R			
	<b>MOC :</b>								
SL S550-99-08	MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION		INFORMATIONAL			A/R			
	<b>MOC :</b>								
SL CIL-99-04	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW		INFORMATIONAL			-			
	<b>MOC :</b>								
SB S550-11-01 11SB-01	GROSS WEIGHT INCREASE (SUPERSEDED BY S550-11-01 R01)	SAO	RECOMMENDED	MTH 30-Oct-1988 HRS 921		A/R			Complete
	<b>MOC :</b> COMPLIED WITH								
SB S550-11-03 R01 11SB-03 : S55R1	SEAT PLACARD INSTALLATIONS AND EMERGENCY EXIT HANDLE GUARD DECAL REPLACEMENT	SAO	MANDATORY	MTH 20-Nov-1991 HRS 1480		A/R			Complete
	<b>MOC :</b> COMPLIED WITH								
SB S550-11-03 11SB-03	SEAT PLACARD INSTALLATIONS AND EMERGENCY EXIT HANDLE GUARD DECAL REPLACEMENT (SUPERSEDED BY S550-11-03 R01)	SAO	MANDATORY	MTH 20-Nov-1991 HRS 1480		A/R			Complete
	<b>MOC :</b> COMPLIED WITH								
SB S550-11-04 11SB-04	AIRSPPEED LIMITATIONS PLACARD REPLACEMENT	SAO	MANDATORY	MTH 11-Jul-1989 HRS 1070		A/R			Complete
	<b>MOC :</b> COMPLIED WITH								
SB S550-11-05 11SB-05	FLAP NO STEP PLACARD INSTALLATION	UNK	RECOMMENDED	MTH 01-Aug-2019 HRS 8912.2 LDG 7452		A/R			Complete
	<b>MOC :</b> COMPLIED WITH								
SB S550-11-06 11SB-06	FIRE EXTINGUISHER PLACARD INSTALLATION		OPTIONAL	MTH		A/R			
	<b>MOC :</b>								
SL S550-11-01 11SL-01	DATA PLATE RELOCATION	SAO	OPTIONAL	MTH		A/R			
	<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME								



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-99-01 R01	USE OF CORROSION INHIBITING COMPOUNDS (SUPERSEDED BY CIL-99-01 R02)			INFORMATIONAL			-			
	<b>MOC :</b>									
SL CIL-99-01 R02	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL			-			
	<b>MOC :</b>									
SL CIL-99-01	USE OF CORROSION INHIBITING COMPOUNDS (SUPERSEDED BY CIL-99-01 R01)			INFORMATIONAL			-			
	<b>MOC :</b>									
SL CIL-99-02	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			MTH RECOMMENDED			-			
	<b>MOC :</b>									
SL CIL-20-01 R02	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			-			
	<b>MOC :</b>									
SL CIL-20-01	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY CIL-20-01 R01)			INFORMATIONAL			-			
	<b>MOC :</b>									
SL S550-20-01 R27	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SLS550-20-01 R28)			INFORMATIONAL			A/R			
	<b>MOC :</b>									
SL S550-20-04	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL			INFORMATIONAL			-			
	<b>MOC :</b>									
SL CIL-21-01	COMPRESSOR MOTOR BRUSH LIFE LIMIT			INFORMATIONAL			-			
	<b>MOC :</b>									
SL CIL-21-02 R01	ENVIRONMENTAL HOUR METER INSTALLATION			MANDATORY	MTH 01-Aug-2019 HRS 8912.2 LDG 7452		-			Complete
	<b>MOC :</b> COMPLIED WITH									
SL CIL-21-02	ENVIRONMENTAL HOUR METER INSTALLATION (SUPERSEDED BY CIL-21-02 R01)			OPTIONAL			-			
	<b>MOC :</b>									
SB S550-21-03 R01 <i>21SB-03 : S55R1</i>	FREON AIR CONDITIONING SYSTEM INSTALLATION - CANCELLED			CANCELLED	MTH		A/R			
	<b>MOC :</b>									
SB S550-21-04 <i>21SB-04</i>	CABIN VENTILATION MOTOR REPLACEMENT (SUPERSEDED BY S550-21-04 R01)	SAO		OPTIONAL	MTH 21-Nov-1986 HRS 498		A/R			Complete
	<b>MOC :</b> COMPLIED WITH									
SB S550-21-05 <i>21SB-05</i>	SUPPLEMENTAL COCKPIT AIR DISTRIBUTION SYSTEM			OPTIONAL	MTH		A/R			
	<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB S550-21-06 R01 <i>21SB-06 : S55R1</i>	FRESH AIR DUCT INSTALLATION	SAO		MANDATORY	MTH 30-Aug-1997 HRS 5106		A/R			Complete
	<b>MOC :</b> COMPLIED WITH									





# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB S550-21-08 21SB-08	TAILCONE RAM AIR INLET PRESSURIZATION VALVE INSTALLATION			OPTIONAL MTH			A/R			
<b>MOC :</b>										
SB S550-21-09 R02 21SB-09 : S55R2	TAILCONE FRESH AIR DUCT MODIFICATION (SUPERSEDED BY S550-21-09 R03)	SAO		OPTIONAL MTH			A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB S550-21-10 21SB-10	AIR DUCT RETENTION IMPROVEMENT (SUPERSEDED BY S550-21-10 R01)			RECOMMENDED			A/R			
<b>MOC :</b>										
SB S550-21-11 21SB-11	ACM BLEED AIR DUCT SUPPORT CLAMP INSTALLATION			OPTIONAL MTH			A/R			
<b>MOC :</b>										
SB S550-21-12 21SB-12	TAILCONE PRESSURE VALVE ACTUATOR WIRING MODIFICATION			OPTIONAL MTH			A/R			
<b>MOC :</b>										
SB S550-21-14 21SB-14	ADDITIONAL OUTFLOW VALVE REPLACEMENTS	SAO		MANDATORY HRS	29-May-1995 3609		A/R			Complete
<b>MOC :</b> COMPLIED WITH - NOT APPLICABLE BY COMPONENT SERIAL NUMBER.										
SB S550-21-15 21SB-15	AIR CONDITIONING - COCKPIT SIDE WINDOW DEFOG SYSTEM MODIFICATION			OPTIONAL MTH			A/R			
<b>MOC :</b>										
SB S550-21-16 21SB-16	CABIN FAN AND DEFOG BLOWER WIRING IMPROVEMENT			DISCRETIONARY MTH			A/R			
<b>MOC :</b>										
SB S550-21-17	AIR CONDITIONING - TEMPERATURE CONTROLLER IMPROVEMENT			OPTIONAL			A/R			
<b>MOC :</b>										
SL S550-21-02 21SL-02	TAILCONE FRESH AIR DUCT ROUTING INSPECTION			RECOMMENDED			A/R			
<b>MOC :</b>										
SL S550-21-05 21SL-05	AIR CONDITIONING - TRANSMITTAL OF FORT WORTH AIRWORKS, INC. SERVICE BULLETIN 99-101, EVAPORATOR MODULE INSTALLATION 1250240 AND 1134240 SERIES.			RECOMMENDED			A/R			
<b>MOC :</b>										
SB S550-23-01 R01 23SB-01 : S55R1	STATIC DISCHARGE IMPROVEMENT (SUPERSEDED BY S550-23-01 R02)	SAO		OPTIONAL MTH	26-Mar-1987 581		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SB S550-23-04 23SB-04	COCKPIT VOICE RECORDER INSTALLATION (FAIRCHILD GA100)	SAO		OPTIONAL MTH	15-Jun-1998 5403		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SB S550-23-06 R01 23SB-06 : S55R1	HONEYWELL EFIS SYMBOL GENERATOR INTERPOSER FILTER INSTALLATION			OPTIONAL MTH			A/R			
<b>MOC :</b>										
SB S550-23-07 23SB-07	STATIC WICK REPLACEMENT			OPTIONAL MTH			A/R			
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB S550-23-08 R01 <i>23SB-08 : S55R1</i>	COLLINS 8.33 KHZ COMMUNICATION RADIO INSTALLATION			OPTIONAL	MTH		A/R			
<b>MOC :</b>										
SB S550-23-09 <i>23SB-09</i>	VLF NOISE FILTER CAPACITOR REMOVAL/REPLACEMENT (SUPERSEDED BY S550-23-09 R01)	CRQ		MANDATORY	MTH 01-Dec-1999 HRS 5792		A/R			Complete
<b>MOC :</b> COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
SL S550-23-01 <i>23SL-01</i>	MICROPHONE REPLACEMENT PROGRAM	SAO		RECOMMENDED	MTH HRS		0			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
<b>MOC :</b>										
SL S550-23-02 <i>23SL-02</i>	STATIC DISCHARGE WICK MODIFICATION	SAO		OPTIONAL	MTH 26-Jul-1989 HRS 1078		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SL S550-23-14 <i>23SL-14</i>	COMMUNICATIONS - AIRSHOW RELIABILITY IMPROVEMENTS AND SERVICE PACK SOFTWARE UPGRADE			RECOMMENDED			A/R			
<b>MOC :</b>										
SB S550-24-02 <i>24SB-02</i>	RIGHT WING INSPECTION LIGHT CIRCUIT BREAKER REWIRING	SAO		RECOMMENDED	MTH 18-Sep-1985 HRS 167		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SB S550-24-04 <i>24SB-04</i>	LEFT CIRCUIT BREAKER PANEL BUSSING MODIFICATION (SUPERSEDED BY S550-24-04 R01)	SAO		MANDATORY	MTH 30-Oct-1986 HRS 484		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SB S550-24-06 <i>24SB-06</i>	TKS FLUID PUMP SEPARATE CIRCUIT BREAKER INSTALLATION (SUPERSEDED BY S550-24-06 R01)	SAO		OPTIONAL	MTH 02-Oct-1987 HRS 665		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SB S550-24-07 R01 <i>24SB-07 : S55R1</i>	CIRCUIT BREAKER PANEL SUPPORT BRACKET AND COVER REPLACEMENT	SAO		MANDATORY	MTH 30-Sep-1987 HRS 664		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SB S550-24-08 <i>24SB-08</i>	LH AND RH PITOT STATIC CIRCUIT BREAKER REPLACEMENT AND CABIN FAN POWER BUS BAR CHANGE	SAO		MANDATORY	MTH 16-Feb-1987 HRS 547		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SB S550-24-11 <i>24SB-11</i>	RIGHT PYLON WIRE BUNDLE PROTECTION	SAO		MANDATORY	MTH 19-Nov-1991 HRS 1480		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SB S550-24-12 <i>24SB-12</i>	CONTROL WHEEL ELECTRICAL CABLE REPLACEMENT (SUPERSEDED BY S550-24-12 R01)			OPTIONAL	MTH		A/R			
<b>MOC :</b>										
SB S550-24-14 R01 <i>24SB-14 : S55R1</i>	MAIN LANDING GEAR AXLE ANTISKID WIRE BUNDLE PROTECTION			RECOMMENDED			A/R			
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB S550-24-14 24SB-14	MAIN LANDING GEAR AXLE ANTISKID WIRE BUNDLE PROTECTION (SUPERSEDED BY S550-24-14 R01)	SAO	RECOMMENDED	MTH 30-Nov-1991 HRS 1494		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SB S550-24-15 24SB-15	WING WIRE BUNDLE ROUTING MODIFICATION		RECOMMENDED			A/R			
<b>MOC :</b>									
SB S550-24-17 24SB-17	AVIONICS POWER RELAYS REPLACEMENT	*CF	OPTIONAL	MTH		A/R			
<b>MOC :</b>									
SB S550-24-18 24SB-18	WING TIP WIRE BUNDLE PROTECTIVE COVER INSTALLATION	*CF	RECOMMENDED			A/R			
<b>MOC :</b>									
SB S550-24-19 R01 24SB-19 : S55R1	ELECTRICAL CABLE CHAFING PROTECTION INSTALLATION W.S. 44.0 AND W.S. 54.07		RECOMMENDED			A/R			
<b>MOC :</b>									
SB S550-24-19 24SB-19	ELECTRICAL CABLE CHAFING PROTECTION INSTALLATION W.S. 44.0 AND W.S. 54.07 (SUPERSEDED BY S550-24-19 R01)		RECOMMENDED			A/R			
<b>MOC :</b>									
SB S550-24-21 R01 24SB-21 : S55R1	OVERVOLTAGE MONITOR SYSTEM INSTALLATION		OPTIONAL	MTH		A/R			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>									
SB S550-24-22 24SB-22	BATTERY DISCONNECT RELAY ACCESS IMPROVEMENT		OPTIONAL	MTH		A/R			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>									
SB S550-24-23 R01 24SB-23 : S55R1	MAIN POWER WIRE ANCHOR IMPROVEMENT		RECOMMENDED	MTH HRS		300			
SERVICE BULLETIN ON HOLD.									
<b>MOC :</b>									
SB S550-24-24	ELECTRICAL POWER - MAGNETIC CIRCUIT BREAKER REPLACEMENT		OPTIONAL			A/R			
<b>MOC :</b>									
SL S550-24-01 R01 24SL-01 : S55R1	TAILCONE WIRE BUNDLE REROUTING AND CLAMPING	SAO	RECOMMENDED	MTH 21-Nov-1991 HRS 1482		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SL S550-24-01 24SL-01	TAILCONE WIRE BUNDLE REROUTING AND CLAMPING	SAO	RECOMMENDED	MTH 21-Nov-1991 HRS 1482		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SL S550-24-06 24SL-06	500 HOUR MID-LIFE BEARING CHANGE FOR 9912125-1 (23085-004 AND 23085-004 MOD A) STARTER GENERATORS		RECOMMENDED			A/R			
<b>MOC :</b>									
SL S550-24-07 24SL-07	COCKPIT CIRCUIT BREAKER INSPECTION/REPLACEMENT	SAO	RECOMMENDED	MTH 14-Oct-1997 HRS 5192		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SL S550-24-08 24SL-08	DELETE THE 500 HOUR MID-LIFE BEARING CHANGE REQUIREMENT FOR THE 9912125-1 (23085-004 MOD A) STARTER/GENERATOR		RECOMMENDED			A/R			
<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL S550-24-10 <i>24SL-10</i>	ANTI-ICE RELAY BASE ORIENTATION INSPECTION/MODIFICATION (SUPERSEDED BY SLS550-24-10 R01)			RECOMMENDED			A/R			
<b>MOC :</b>										
ASB S550-25-03A <i>25SB-03</i>	CABIN DISPLAY MODIFICATION	SAO		MANDATORY	MTH 31-Jul-1985 HRS 120		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SB S550-25-05 <i>25SB-05</i>	SEAT CUSHION REPLACEMENT			OPTIONAL	MTH		A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB S550-25-08 <i>25SB-08</i>	CABIN DISPLAY UNIT REPLACEMENT AND SIGN INSTALLATION	SAO		MANDATORY	MTH 02-Apr-1987 HRS 581		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SB S550-25-09 <i>25SB-09</i>	CREW SEAT BACK MODIFICATION			OPTIONAL	MTH		A/R			
<b>MOC :</b>										
SB S550-25-10 <i>25SB-10</i>	THREE BOOK JEPP CASE INSTALLATION	SAO		OPTIONAL	MTH 21-Sep-1986 HRS 449		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SB S550-25-11 <i>25SB-11</i>	LOCATOR BEACON RESET CIRCUIT VOLTAGE LIMIT RESISTOR REMOVAL	SAO		MANDATORY	MTH 13-Oct-1986 HRS 472		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SB S550-25-12 <i>25SB-12</i>	TAILCONE ACCESS DOOR STRAP INSTALLATION	SAO		OPTIONAL	MTH 21-Sep-1986 HRS 449		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
ASB S550-25-16A <i>25SBA16</i>	INTERIOR CABINERY ELECTRICAL POWER SOURCE DISABLEMENT	SAO		MANDATORY	MTH 20-Apr-1987 HRS 581		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SB S550-25-18 <i>25SB-18</i>	PASSENGER SEAT ARMREST RELEASE LEVER REPLACEMENT			OPTIONAL	MTH		A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB S550-25-20 <i>25SB-20</i>	FORWARD REFRESHMENT CENTER OVERBOARD DRAIN RELOCATION (SUPERSEDED BY S550-25-20 R01)			RECOMMENDED			A/R			
<b>MOC :</b>										
SB S550-25-21 <i>25SB-21</i>	CREW SEAT PAN REPLACEMENT			OPTIONAL	MTH		A/R			
<b>MOC :</b>										
SB S550-25-29 R02 <i>25SB-29 : S55R2</i>	ARTEX C406-2 THREE-FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT) (SUPERSEDED BY S550-25-29 R03)			OPTIONAL			A/R			
<b>MOC :</b> - SERVICE BULLETIN ON HOLD.										
SB S550-25-29 R03 <i>25SB-29 : S55R2</i>	ARTEX C406-2 THREE-FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT)			OPTIONAL			A/R			
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB S550-25-30 R01 <i>25SB-30 : S55R1</i>	GLARESHIELD LEATHER STRIP INSTALLATION		MTH OPTIONAL			A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SL S550-25-02 R03 <i>25SL-02 : S55R3</i>	INTERIOR CABINETY WIRING AND ELECTRICAL COMPONENT INSPECTION AND MODIFICATION (SUPERSEDED BY SLS550-25-02 R04)	SAO	MANDATORY	MTH 20-Apr-1987 HRS 581		A/R			Complete
<b>MOC :</b> COMPLIED WITH									
SL S550-25-02 R04 <i>25SL-02 : S55R4</i>	INTERIOR CABINETY WIRING AND ELECTRICAL COMPONENT INSPECTION AND MODIFICATION	SAO	MANDATORY	MTH 15-Dec-1989 HRS 1152		A/R			Complete
<b>MOC :</b> COMPLIED WITH									
SL S550-25-04 <i>25SL-04</i>	SWITLIK INFLATABLE LIFE PRESERVER INSPECTION	SAO	INFORMATIONAL	MTH 30-Sep-1988 HRS 898		A/R			Complete
<b>MOC :</b> COMPLIED WITH									
SL S550-25-07 <i>25SL-07</i>	TRANSMITTAL OF EASTERN AERO MARINE SERVICE BULLETIN SBV-25-2, EQUIPMENT/FURNISHINGS - LIFE PRESERVERS AND INDIVIDUAL FLOTATION DEVICES REPLACEMENT OF CO2 INFLATOR - MANDATORY	SAO	MANDATORY	MTH 14-Oct-1997		A/R			Complete
<b>MOC :</b> COMPLIED WITH									
SL S550-25-08 <i>25SL-08</i>	EQUIPMENT/FURNISHINGS - GLARESHIELD ATTACHMENT SCREW(S) INSPECTION/REPLACEMENT		RECOMMENDED			A/R			
<b>MOC :</b>									
SB 26-36 REV E	INSULATION RESISTANCE TESTING OF THERMISTOR DETECTORS					-			
<b>MOC :</b>									
SL CIL-26-01 R01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING		MANDATORY	MTH		-			
<b>MOC :</b>									
SL CIL-26-01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING (SUPERSEDED BY CIL-26-01 R01)		MANDATORY	MTH		-			
<b>MOC :</b>									
SB S550-26-02 <i>26SB-02</i>	FIRE BOTTLE WIRE IDENTIFICATION SLEEVE INSTALLATION	ILG	MANDATORY	MTH 12-Dec-2005 HRS 7574		A/R			Complete
<b>MOC :</b> COMPLIED WITH									
ASL SLS550-26-01A <i>26ASL01</i>	TRANSMITTAL OF MEGGITT SAFETY SYSTEMS SERVICE BULLETIN 26-36 -THERMISTORS DETECTORS	UNK	MANDATORY	MTH 01-Aug-2019 HRS 8912.2 LDG 7452		A/R			N/A
<b>MOC :</b> NOT APPLICABLE - BY AFFECTED MODEL NOT INSTALLED									
SB S550-27-01 <i>27SB-01</i>	ELEVATOR TRIM T.O. MARKER	SAO	MANDATORY	MTH 20-Nov-1991 HRS 1480		A/R			Complete
<b>MOC :</b> COMPLIED WITH									
SB S550-27-02 R03 <i>27SB-02 : S55R3</i>	HIGH ALTITUDE TAKEOFF CAPABILITIES - 7-DEGREE FLAPS		OPTIONAL	MTH		A/R			
<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB S550-27-02 27SB-02	HIGH ALTITUDE TAKEOFF CAPABILITIES - 7-DEGREE FLAPS (SUPERSEDED BY S550-27-02 R01)			OPTIONAL	MTH		A/R			
<b>MOC :</b>										
SB S550-27-05 27SB-05	RUDDER TRIM WHEEL BEARING INSPECTION/REPLACEMENT (SUPERSEDED BY S550-27-05 R01)			RECOMMENDED			A/R			
<b>MOC :</b>										
SB S550-27-06 27SB-06	EXTENDED PEDESTAL AILERON PULLEY BRACKET MODIFICATION (SUPERSEDED BY S550-27-06 R01)	SAO		RECOMMENDED	MTH 04-Oct-1993 HRS 2429		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB S550-27-07 R01 27SB-07 : S55R1	AILERON CONTROL QUADRANT BOLT INSPECTION/REPLACEMENT (SUPERSEDED BY S550-27-07 R02)	SAO		MANDATORY	MTH 30-Aug-1997 HRS 5106		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB S550-27-08 27SB-08	AILERON/RUDDER INTERCONNECT CLAMP MODIFICATION	LGB		RECOMMENDED	MTH 14-Aug-1998 HRS 5424		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB S550-27-09 27SB-09	FLIGHT CONTROLS - TRIM TAB ACTUATOR GREASE FITTING INSTALLATION			OPTIONAL	MTH		A/R			
<b>MOC :</b>										
SL S550-27-01 27SL-01	ELEVATOR CONTROL PUSH ROD ASSEMBLY INSPECTION/RIVET REPLACEMENT	SAO		RECOMMENDED	MTH 31-Mar-1987 HRS 581		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SL S550-27-05 27SL-05	FLAP/ELEVATOR TRIM MIXER ACTUATOR ASSEMBLY INSPECTION/REPLACEMENT	SAO		RECOMMENDED	MTH 25-Nov-1991 HRS 1486		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SL S550-27-07 R01 27SL-07 : S55R1	RUDDER/AILERON INTERCONNECT BOLT INSPECTION	SAO		MANDATORY	MTH 15-Jun-1998 HRS 5403		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SL S550-27-07 27SL-07	RUDDER/AILERON INTERCONNECT BOLT INSPECTION (SUPERSEDED BY SLS550-27-07 R01)	SAO		SUPERSEDED	MTH 02-Oct-1997 HRS 5157		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SL S550-27-08 27SL-08	RUDDER PEDAL SUPPORT INSPECTION			RECOMMENDED			A/R			
<b>MOC :</b>										
SB S550-28-03 28SB-03	WING LEADING EDGE RIB FLAPPER VALVES INSTALLATION			OPTIONAL	MTH		A/R			
<b>MOC :</b>										
SB S550-28-04 28SB-04	MOTIVE FLOW FUEL LINE INSPECTION AND SUPPORT INSTALLATION	SAO		RECOMMENDED	MTH 21-Jun-1994 HRS 2888		A/R			Complete
<b>MOC : COMPLIED WITH</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB S550-28-05 28SB-05	FUEL SYSTEM PLUMBING CLAMP ADDITIONS	SAO	RECOMMENDED	MTH 25-Oct-1996 HRS 4576		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SB S550-28-06 28SB-06	IMPROVED FUEL CROSSFEED SELECT KNOB AVAILABILITY		OPTIONAL	MTH		A/R			
<b>MOC :</b>									
SB S550-28-07 28SB-07	FUEL LINE SUPPORT INSTALLATION		RECOMMENDED	MTH HRS		3500		9048	90.3
<b>MOC :</b>									
SB S550-28-08 28SB-08	WING FUEL BOOST PUMP WIRE ROUTING IMPROVEMENT	LGB	MANDATORY	MTH 15-Jun-2004 HRS 7216		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SB S550-28-09 R01 28SL-01 : S55R3	FUEL - FUEL CHECK VALVE MODIFICATION	UNK	RECOMMENDED	MTH 01-Oct-2018 HRS 8902.1 LDG 7446		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SB S550-28-09 28SB-09	FUEL CHECK VALVE MODIFICATION (SUPERSEDED BY S550-28-09 R01)		RECOMMENDED	MTH 05-Aug-2012 HRS 8405.2 LDG 7247		A/R			Complete
OPERATOR CHOOSES TO PERFORM AT NEXT PHASE 5.									
<b>MOC : COMPLIED WITH</b>									
SL S550-28-01 R03 28SL-01 : S55R3	FUEL QUANTITY COMPENSATOR INSTALLATION ATTACHMENT INSPECTION	SAO	RECOMMENDED	MTH 04-Oct-1993 HRS 2429		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
ASL SLS550-28-03A 28SLA03	TRANSMITTAL OF PARKER HANNIFIN CORPORATION -AIRBORNE AIR & FUEL PRODUCTS SERVICE LETTER NO. 41, RAPCO FLEET SUPPORT INC. OVERHAUL OF AIRBORNE FUEL PUMPS (SUPERSEDED BY SLS550-28-03A R01)	SAO	MANDATORY	MTH 26-Oct-1996 HRS 4576		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SB S550-29-01 29SB-01	ECOLOGY (OVERFLOW) BOTTLE INSTALLATION		OPTIONAL	MTH		A/R			
<b>MOC :</b>									
SL S550-29-02 29SL-02	HYDRAULIC LINE INSPECTION (SUPERSEDED BY SLS550-29-02 R01)	SAO	RECOMMENDED	MTH 21-Aug-1990 HRS 1284		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SL CIL-30-01 R01 30SLA05 : S55R2	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES		INFORMATIONAL			-			
<b>MOC :</b>									
ASL S550-30-05 R02 30SLA05 : S55R2	TKS ANTI-ICE SYSTEM PROPORTIONING UNIT CONNECTIONS	SAO	MANDATORY	MTH 16-Jan-1986 HRS 255		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SB S550-30-06 30SB-06	ANTI-ICE PUMP ISOLATOR INSTALLATION	SAO	RECOMMENDED	MTH 29-Feb-1988 HRS 775		A/R			Complete
<b>MOC : COMPLIED WITH</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB S550-30-08 30SB-08	ANTI-ICE PUMP WIRING CIRCUIT MODIFICATION	SAO	RECOMMENDED	MTH 30-Apr-1987 HRS 581		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SB S550-30-11 30SB-11	ICE DETECTOR REPLACEMENT (SUPERSEDED BY S550-30-11 R01)	SAO	RECOMMENDED	MTH 17-Jun-1989 HRS 1048		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SB S550-30-14 30SB-14	FLUID ANTI-ICE SYSTEM WING CUFF AND FAIRING PANELS INSPECTION AND PURGE CYCLE MODIFICATION (SUPERSEDED BY S550-30-14 R01)	SAO	MANDATORY	MTH 26-Oct-1996 HRS 4576		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SB S550-30-15 30SB-15	ANTI-ICE SYSTEM IMPROVEMENT		RECOMMENDED			A/R			
<b>MOC :</b>									
SB S550-30-16 30SB-16	ICE DETECTOR TEST CYCLE TIME DELAY MODIFICATION (SUPERSEDED BY S550-30-16 R01)		RECOMMENDED			A/R			
<b>MOC :</b>									
SB S550-30-17 30SB-17	WINDSHIELD BLEED AIR ORIFICE INSPECTION/REMOVAL (SUPERSEDED BY S550-30-17 R01)	SAO	MANDATORY	MTH 10-Jul-1991 HRS 1420		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SL S550-30-03 30SL-03	AIRFOIL ANTI-ICE LEADING EDGE ATTACH SCREW HEAD AND COUNTERSINK FILLING	SAO	RECOMMENDED	MTH 30-Jul-1986 HRS 416		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
ASL SLS550-30-04A 30SLA04	TKS PROPORTIONING UNIT INSPECTION/REPLACEMENT	SAO	MANDATORY	MTH 18-Dec-1985 HRS 229		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
ASL SLS550-30-05A 30SLA05	ICE & RAIN PROTECTION - TKS ANTI-ICE SYSTEM PROPORTIONING UNIT CONNECTIONS	SAO	MANDATORY	MTH 16-Jan-1986 HRS 255		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SL S550-30-07 30SL-07	ICE DETECT PROBE - MAINTENANCE CAUTION	SAO	INFORMATIONAL	MTH 10-Jun-1987 HRS 591		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SL CIL-31-01	INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION		INFORMATIONAL			-			
<b>MOC :</b>									
SL CIL-32-01	LANDING GEAR - IMPROVED NOSE WHEEL GREASE SEAL		INFORMATIONAL			-			
<b>MOC :</b>									
SL CIL-32-03	NLG UPLOCK ROLLER BRACKET INSPECTION		RECOMMENDED	MTH HRS		300		10972.9	2015.2
<b>MOC :</b>									
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION		INFORMATIONAL			-			
<b>MOC :</b>									





# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl	Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-32-06	LANDING GEAR - WIRELESS TIRE PRESSURE SENSOR FILL VALVE TORQUE VERIFICATION									
	INFORMATIONAL									
	<b>MOC :</b>									
SB S550-32-01 R02 32SB-01 : S55R2	LANDING GEAR - INSTALLATION OF CLEVELAND WHEELS AND BRAKES	SAO	OPTIONAL		MTH		A/R			
	<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB S550-32-01 32SB-01	LANDING GEAR - INSTALLATION OF CLEVELAND WHEELS AND BRAKES (SUPERSEDED BY S550-32-01 R01)	SAO	OPTIONAL		MTH		A/R			
	<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB S550-32-02 R02 32SB-02 : S55R2	ANTI-SKID WIRE BUNDLE ROUTING IMPROVEMENT (SUPERSEDED BY S550-32-02 R03)	SAO	RECOMMENDED		MTH 27-Mar-1989 HRS 1000		A/R			Complete
	<b>MOC :</b> COMPLIED WITH									
SB S550-32-02 32SB-02	ANTI-SKID WIRE BUNDLE ROUTING IMPROVEMENT (SUPERSEDED BY S550-32-02 R01)	SAO	RECOMMENDED		MTH 18-Jun-1987 HRS 593		A/R			Complete
	<b>MOC :</b> COMPLIED WITH									
SB S550-32-04 32SB-04	MAIN LANDING GEAR DOORS REPLACEMENT (IMPROVED SLUSH AND SNOW OPERATION) (SUPERSEDED BY S550-32-04 R01)	SAO	OPTIONAL		MTH		A/R			
	<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB S550-32-05 R01 32SB-05 : S55R1	MAIN LANDING GEAR TORQUE LINK MODIFICATION (SUPERSEDED BY S550-32-05 R02)	SAO	MANDATORY		MTH 27-Mar-1989 HRS 1000		A/R			Complete
	<b>MOC :</b> COMPLIED WITH									
SB S550-32-05 32SB-05	MAIN LANDING GEAR TORQUE LINK MODIFICATION (SUPERSEDED BY S550-32-05 R01)	SAO	MANDATORY		MTH 21-Dec-1988 HRS 932		A/R			Complete
	<b>MOC :</b> COMPLIED WITH									
SB S550-32-06 32SB-06	NOSE GEAR STEERING BUNGEE SPRING REPLACEMENT		RECOMMENDED				A/R			
	<b>MOC :</b>									
SB S550-32-07 32SB-07	BF GOODRICH BRAKES AND WHEELS INSTALLATION (SUPERSEDED BY S550-32-07 R01)	SAO	OPTIONAL		MTH		A/R			
	<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB S550-32-08 32SB-08	INCREASED MAXIMUM GEAR EXTEND SPEED		OPTIONAL		MTH		A/R			
	<b>MOC :</b>									
SB S550-32-11 32SB-11	BF GOODRICH BRAKE BLEEDER BLOCK INSTALLATION AND HOSE REPLACEMENT (SUPERSEDED BY S550-32-11 R01)		OPTIONAL		MTH		A/R			
	<b>MOC :</b>									
SB S550-32-12 32SB-12	MAIN LANDING GEAR WHEEL WELL AFT SPAR BOX HYDRAULIC/PNEUMATIC LINES GROMMET REPLACEMENT	SAO	RECOMMENDED		MTH 04-Oct-1993 HRS 2429		A/R			Complete
	<b>MOC :</b> COMPLIED WITH									



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB S550-32-13 32SB-13	ANTISKID DRIVE CLIP REPLACEMENT			RECOMMENDED			A/R			
<b>MOC :</b>										
SB S550-32-15 32SB-15	POWER BRAKE HYDRAULIC PUMP SCREW REPLACEMENT			RECOMMENDED	MTH		A/R			
<b>MOC :</b>										
SB S550-32-16 32SB-16	ANTISKID SYSTEM DIODE REMOVAL			RECOMMENDED			A/R			
<b>MOC :</b>										
SB S550-32-18 R02 32SB-18 : S55R2	R02 LANDING GEAR ON GROUND OPERATION MODIFICATION			RECOMMENDED			A/R			
<b>MOC :</b>										
SB S550-32-19 R01 32SB-19 : S55R1	R01 LANDING GEAR - PARKING BRAKE CABLE REPLACEMENT			OPTIONAL	MTH		A/R			
<b>MOC :</b>										
SB S550-32-21 R01	REPLACEMENT OF BLEEDER SCREWS AND FITTINGS WITH BLEEDER PLUGS	UNK		RECOMMENDED	MTH 01-Oct-2018 HRS 8902.1 LDG 7446		-			Complete
<b>MOC :</b> COMPLIED WITH										
SB S550-32-21	REPLACEMENT OF BLEEDER SCREWS AND FITTINGS WITH BLEEDER PLUGS (SUPERSEDED BY S550-32-21 R01)			RECOMMENDED			-			
<b>MOC :</b>										
SB S550-32-22	LANDING GEAR - LANDING GEAR WARNING HORN REPLACEMENT			OPTIONAL			-			
<b>MOC :</b>										
SL S550-32-01 32SL-01	HYDRAULIC BRAKE HOSE INSPECTION	SAO		RECOMMENDED	MTH 04-Nov-1985 HRS 196		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SL S550-32-02 32SL-02	MAIN LANDING GEAR WHEEL-HALF SEALS FOR COLD WEATHER OPERATION			OPTIONAL	MTH		A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
ASL SLS550-32-03A 32SLA03	INSPECTION OF MAIN LANDING GEAR TORQUE LINK CONNECTING HARDWARE	SAO		MANDATORY	MTH 15-Jan-1986 HRS 251		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SL S550-32-05 32SL-05	NOSE GEAR STEERING LOWER JOINT BEARING INSPECTION	SAO		RECOMMENDED	MTH 23-Feb-1990 HRS 1182		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SL S550-32-06 32SL-06	CLEVELAND BRAKE INSPECTION	SAO			MTH 31-Mar-1988 HRS 800		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
ASL SLS550-32-10A 32SLA10	INSPECTION OF MAIN LANDING GEAR UPPER AND LOWER TORQUE LINK CONNECTING HARDWARE			MANDATORY	MTH 27-Mar-1989 HRS 1000		DAILY DAILY DAILY			Complete
<b>MOC :</b> COMPLIED WITH										



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL S550-32-11 32SL-11	UPLOCK ACTUATOR HYDRAULIC LINE INSPECTION	SAO	RECOMMENDED	MTH 04-Oct-1993 HRS 2429		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SL S550-32-13 32SL-13	MAIN LANDING GEAR AXLE INTERNAL CORROSION INSPECTION		RECOMMENDED			A/R			
<b>MOC :</b>									
SL S550-32-17 32SL-17	LANDING GEAR EMERGENCY EXTENSION CONTROL ASSEMBLY PIN INSPECTION	SAO	RECOMMENDED	MTH 21-Aug-1990 HRS 1284		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SL S550-32-21 32SL-21	STRUT EXTENSION INSPECTION AND PISTON UPPER BEARING RETENTION IMPROVEMENT (SUPERSEDED BY SLS550-32-21 R01)	SAO	RECOMMENDED	MTH 02-Jun-1991 HRS 1413		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SL S550-32-22 32SL-22	EMERGENCY LANDING GEAR BLOWDOWN BOTTLE LEVER SAFETY WIRE INSPECTION/REPLACEMENT		RECOMMENDED			A/R			
<b>MOC :</b>									
SL S550-32-24 32SL-24	MAIN LANDING GEAR DRAG BRACE ATTACH NUT REPLACEMENT		RECOMMENDED			A/R			
<b>MOC :</b>									
SL S550-32-26 32SL-26	NOSE AND MAIN LANDING GEAR UPLOCK SPRING INSPECTION/REPLACEMENT (SUPERSEDED BY SLS550-32-26 R01)	SAO	RECOMMENDED	MTH 19-Mar-1991 HRS 1401		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SL S550-32-27 32SL-27	ANTI-SKID SYSTEM CONTROL UNIT CALIBRATION VERIFICATION		RECOMMENDED			A/R			
<b>MOC :</b>									
SL S550-32-29 32SL-29	NOSE LANDING GEAR UPLOCK LINE INSPECTION	SAO	RECOMMENDED	MTH 28-Jun-1991 HRS 1413		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SL S550-32-30 32SL-30	LANDING GEAR HANDLE LOCKING SOLENOID RIGGING INSPECTION	SAO	RECOMMENDED	MTH 04-Oct-1991 HRS 1464		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SL S550-32-34 32SL-34	NOSE GEAR TRUNNION FINISH INSPECTION/REFINISH		RECOMMENDED			A/R			
<b>MOC :</b>									
SL S550-32-37 32SL-37	BRAKE AND SPOILER/SPEEDBRAKE EXTENDED HYDRAULIC LINE(S) ROUTING INSTPECTION/MODIFICATION		RECOMMENDED			A/R			
<b>MOC :</b>									
SL S550-32-41 R01 32SL-41 : S55R1	TEIJIN SEIKI MAIN AND NOSE LANDING GEAR ACTUATOR DOWN AND LOCKED SWITCH INSPECTION/ REPLACEMENT (SUPERSEDED BY SLS550-32-41 R02)		RECOMMENDED			A/R			
<b>MOC :</b>									
SL S550-32-45 32SL-45	NOSE LANDING GEAR WHEEL AND TIRE ASSEMBLY AND WIDE DOOR ATTACH HARDWARE INSPECTION / REPLACEMENT *KAT UPDATED		RECOMMENDED			A/R			
<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL S550-32-46 R01 32SL-46 : S55R1	MAIN LANDING GEAR EXTEND PNEUMATIC LINE CLEARANCE INSPECTION	SAO		RECOMMENDED	MTH 25-Oct-1996 HRS 4576		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SL S550-32-52 R01 32SL-52 : S55R1	NOSE LANDING GEAR ICE PROTECTION BOOT INSTALLATION			OPTIONAL	MTH 30-Sep-2009 HRS 7930 LDG 6975		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SL S550-32-54 32SL-54	EMERGENCY GEAR RELEASE INSPECTION	UNK		MANDATORY	MTH 01-Aug-2019 HRS 8912.2 LDG 7452		24 400			Complete
<b>MOC : COMPLIED WITH</b>										
SL CIL-33-01	LIGHTS - TRANSMITTAL OF RADIANT POWER CORP. SB-RPC-001, PROCEDURE TO REPLACE OBSOLETE CONNECTOR ASSEMBLY FOR CBS28 EMERGENCY BATTERY			INFORMATIONAL			-			
<b>MOC :</b>										
SB S550-33-01 33SB-01	LANDING LIGHT RELOCATION (SUPERSEDED BY S550-33-01 R01)	SAO		OPTIONAL	MTH		A/R			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>										
SB S550-33-02 33SB-02	RUDDER MOUNTED OSCILLATING BEACON REPLACEMENT (SUPERSEDED BY S550-33-02 R01)	SAO		OPTIONAL	MTH 30-May-1990 HRS 1254		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB S550-33-04 R02 33SB-04 : S55R2	AFT CABIN PSU LIGHT WIRE REPLACEMENT	SAO		MANDATORY	MTH 22-Dec-1997 HRS 5301		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB S550-33-06 33SB-06	AFT CABIN PSU LIGHT POWER SUPPLY REPLACEMENT	SAO		RECOMMENDED	MTH 30-Aug-1997 HRS 5106		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB S550-33-07 33SB-07	LANDING LIGHT ELECTRICAL CIRCUIT MODIFICATION (SUPERSEDED BY S550-33-07 R01)			OPTIONAL	MTH		A/R			
<b>MOC :</b>										
SB S550-33-08 33SB-08	INDIRECT LIGHTING CONNECTOR CONTACT INSPECTION/REPLACEMENT	SAO		RECOMMENDED	MTH 21-Aug-1990 HRS 1284		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB S550-33-09 R01 33SB-09 : S55R1	LANDING LIGHT BULB PROTECTION (SUPERSEDED BY S550-33-09 R02)	SAO		OPTIONAL	MTH		A/R			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>										
SB S550-33-11 R01 33SB-11 : S55R1	WING TIP NAV/COLLISION LIGHT MODIFICATION	*CF		OPTIONAL	MTH		A/R			
<b>MOC :</b>										
SB S550-33-12 R03 33SB-12 : S55R3	WING TIP MOUNTED LANDING LIGHT INSTALLATION	*CF		OPTIONAL	MTH		A/R			
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB S550-33-13 33SB-13	LANDING LIGHT CIRCUIT SWITCH MODULE INSTALLATION OPTIONAL			MTH			A/R			
<b>MOC :</b>										
SB S550-33-14 33SB-14	INDIRECT LIGHTING LAMP AND CONNECTOR UPGRADE SAO			MTH HRS 5301	22-Dec-1997		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SB S550-33-15 R01 33SB-15 : S55R1	R01 LIGHTS - EMERGENCY LIGHTING BATTERY PACK UPGRADE OPTIONAL			MTH			A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB S550-33-16 33SB-16	LED TAIL POSITION LIGHT INSTALLATION OPTIONAL			MTH			A/R			
<b>MOC :</b> - SERVICE BULLETIN ON HOLD.										
SL S550-33-03 R01 33SL-03 : S55R1	CABIN INDIRECT LIGHTING SYSTEM INSPECTION (SUPERSEDED BY SLS550-33-03 R02) SAO			RECOMMENDED MTH HRS 4303	31-May-1996		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SL S550-33-03 R02 33SL-03 : S55R2	CABIN INDIRECT LIGHTING SYSTEM INSPECTION RECOMMENDED						A/R			
<b>MOC :</b>										
SL S550-33-06 R01 33SL-06 : S55R1	LANDING LIGHT SWITCH INSPECTION/REPLACEMENT SAO			MANDATORY MTH HRS 4576	25-Oct-1996		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SL S550-33-06 33SL-06	LANDING LIGHT SWITCH INSPECTION/REPLACEMENT (SUPERSEDED BY SLS550-33-06 R01) SAO			MANDATORY MTH HRS 2888	21-Jun-1994		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SB S550-34-06 34SB-06	STATIC LINE REROUTE SAO			MANDATORY MTH HRS 498	21-Nov-1986		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SB S550-34-07 34SB-07	VLF H-FIELD ANTENNA AND COUPLER PROTECTION OPTIONAL			MTH			A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB S550-34-08 34SB-08	COLLINS PROLINE II CTL DISPLAY MANUAL DIMMING MODIFICATION SAO			OPTIONAL MTH HRS 416	30-Jul-1986		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SB S550-34-17 R01 34SB-17 : S55R1	STATIC PORT DOUBLER INSTALLATION RECOMMENDED						A/R			
<b>MOC :</b>										
SB S550-34-25 R01 34SB-25 : S55R1	STARTER-GENERATOR AND GCU FILTER INSTALLATION RECOMMENDED						A/R			
<b>MOC :</b>										
ASB S550-34-26 R01 34SBA26 : S55R1	VG14A VERTICAL GYRO INSPECTION SAO			MANDATORY MTH HRS 1181	30-Jan-1990		A/R			Complete
<b>MOC :</b> COMPLIED WITH										



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB S550-34-27 34SB-27	VN-212 SIGNAL GROUND WIRING MODIFICATION OPTIONAL			MTH			A/R			
<b>MOC :</b>										
SB S550-34-35 34SB-35	COPILOT ALTIMETER INSTALLATION - KOLLSMAN OPTIONAL			MTH			A/R			
<b>MOC :</b>										
SB S550-34-36 R02 34SB-36 : S55R2	NAVIGATION - REDUCED VERTICAL SEPARATION MINIMUM (RVSM) OPERATION MODIFICATION OPTIONAL			MTH			A/R			
<b>MOC :</b>										
SB S550-34-37 34SB-37	TRAFFIC COLLISION AVOIDANCE SYSTEM (TCAS) II AND MST-67A TRANSPONDER UPGRADE FOR ELEMENTARY SURVEILLANCE OPTIONAL			MTH			A/R			
<b>MOC :</b>										
SB S550-34-38 34SB-38	SANDEL ST3400 TAWS INSTALLATION OPTIONAL			MTH			A/R			
<b>MOC :</b>										
SB S550-34-39 34SB-39	SIGMA-TEK CONTROL PANEL INSTALLATION OPTIONAL			MTH			A/R			
<b>MOC :</b>										
SB S550-34-40	NAVIGATION - HONEYWELL TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM II (TCAS II) VERSION 7.1 SOFTWARE UPDATE OPTIONAL						-			
<b>MOC :</b>										
SL S550-34-01 34SL-01	COLLINS VIR-32 NAVIGATION RECEIVER SERVICE BULLETIN 14 RECOMMENDED						A/R			
<b>MOC :</b>										
SL S550-34-06 34SL-06	DORNE AND MARGOLIN DMN4-17-4 NAV ANTENNA COUPLER INSPECTION SAO			RECOMMENDED	MTH	21-Aug-1990 HRS 1284		A/R		Complete
<b>MOC :</b> COMPLIED WITH										
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001 UNK			MANDATORY	DAYS	01-Aug-2019 HRS 8912.2 LDG 7452		-		N/A
<b>MOC :</b> NOT APPLICABLE - BY AFFECTED MODEL NOT INSTALLED										
SB S550-35-01 35SB-01	TAILCONE MOUNTED OXYGEN BOTTLE INSTALLATION (SUPERSEDED BY S550-35-01 R01) OPTIONAL			MTH			A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB S550-35-03 R01 35SB-03 : S55R1	EROS OXYGEN MASK INSTALLATION OPTIONAL			MTH			A/R			
<b>MOC :</b>										
SB S550-35-04 35SB-04	CHAFING PROTECTION INSTALLATION OF TAILCONE LINES AND WIRE BUNDLES (SUPERSEDED BY S550-35-04 R01) SAO			RECOMMENDED	MTH	26-Oct-1996 HRS 4576		A/R		Complete
<b>MOC :</b> COMPLIED WITH - NOT APPLICABLE										
SL S550-35-03	OXYGEN BOTTLE INSPECTION INFORMATIONAL			MTH	26-Jul-2011 HRS 8236 LDG 7173		A/R			Complete
<b>MOC :</b> COMPLIED WITH										



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL S550-35-04 R01	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240	UNK	MANDATORY	MTH 01-Aug-2019 HRS 8912.2 LDG 7452		-			N/A
<b>MOC : NOT APPLICABLE - AFFECTED MODEL NOT INSTALLED</b>									
SL S550-35-04	TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 (SUPERSEDED BY SLS550-35-04 R01)		MANDATORY			-			
<b>MOC :</b>									
SB S550-36-01 36SB-01	BLEED AIR CHECK VALVE INSPECTION/REPLACEMENT (SUPERSEDED BY S550-36-01 R01)	SAO	MANDATORY	MTH 30-Aug-1986 HRS 431		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SB S550-36-02 36SB-02	DOOR SEAL PLUMBING INSPECTION AND MODIFICATION		RECOMMENDED			A/R			
<b>MOC :</b>									
SB S550-36-04 R01 36SB-04 : S55R1	ENGINE BLEED AIR CONNECTOR IMPROVEMENT		OPTIONAL	MTH		A/R			
<b>MOC :</b>									
SB S550-36-05 36SB-05	DOOR SEAL VALVE REPLACEMENT		OPTIONAL	MTH		A/R			
<b>MOC :</b>									
ASL S550-52-03	DOORS - EMERGENCY EXIT INSPECTION	UNK	MANDATORY	DAYS 01-Aug-2019 HRS 8912.2 LDG 7452		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SB S550-52-02 52SB-02	ENTRY STEP ASSEMBLY IMPROVEMENT (SUPERSEDED BY S550-52-02 R01)	SAO	RECOMMENDED	MTH 21-Sep-1986 HRS 449		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SB S550-52-04 52SB-04	TAILCONE BAGGAGE DOOR RESTRAINT CABLE INSTALLATION	SAO	OPTIONAL	MTH		A/R			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>									
SB S550-52-05 52SB-05	BAGGAGE DOOR POSITIVE SAFETY LOCK INSTALLATION (SUPERSEDED BY S550-52-05 R01)	SAO	RECOMMENDED	MTH 25-Oct-1996 HRS 4576		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SB S550-52-06 52SB-06	WIDE DOOR INSTALLATION (SUPERSEDED BY S550-52-06 R01)	SAO	OPTIONAL	MTH		A/R			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>									
SB S550-52-08 52SB-08	WIDE DOOR RETRACT CABLE MODIFICATION (SUPERSEDED BY S550-52-08 R01)		OPTIONAL	MTH		A/R			
<b>MOC :</b>									
SB S550-52-09 52SB-09	ENTRY DOOR STEP CATCH COVER INSTALLATION (WITH STANDARD DOOR AND STEP)	SAO	RECOMMENDED	MTH 24-Mar-1995 HRS 3411		A/R			Complete
<b>MOC : COMPLIED WITH</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL S550-52-01 52SL-01	NOSE AND TAILCONE BAGGAGE DOOR INSPECTION	SAO	RECOMMENDED	MTH 17-Mar-1989		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SL S550-52-02 52SL-02	EMERGENCY EXIT INNER HANDLE ATTACH SCREW INSPECTION/REPLACEMENT	SAO	MANDATORY	MTH 04-Oct-1993 HRS 2429		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SB S550-53-01 53SB-01	TAILCONE BALLAST INSTALLATION (SUPERSEDED BY S550-53-01 R01)		OPTIONAL	MTH		A/R			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>									
SB S550-53-02 53SB-02	CABIN FLOORBOARD ACCESS IMPROVEMENT		RECOMMENDED			A/R			
<b>MOC :</b>									
SB S550-53-03 53SB-03	TAILCONE BAGGAGE COMPARTMENT ACCESS DOOR REPLACEMENT (SUPERSEDED BY S550-53-03 R01)	SAO	MANDATORY	MTH 25-Oct-1996 HRS 4576		A/R			Complete
<b>MOC : COMPLIED WITH - NOT APPLICABLE</b>									
SB S550-53-05 R01 53SB-05 : S55R1	TAILCONE BAGGAGE COMPARTMENT GUSSET INSPECTION/INSTALLATION (SUPERSEDED BY S550-53-05 R02)		RECOMMENDED			A/R			
<b>MOC :</b>									
SB S550-53-08 53SB-08	FRAME BRACE INSPECTION/INSTALLATION (SUPERSEDED BY S550-53-08 R01)	SAO	RECOMMENDED	MTH 24-Mar-1995 HRS 3411		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SB S550-53-09 53SB-09	CABIN INTERIOR ATTACH/CONTACT POINT CORROSION PROTECTION (SUPERSEDED BY S550-53-09 R01)	SAO	RECOMMENDED	MTH 04-Oct-1993 HRS 2429		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SB S550-53-10 53SB-10	FLIGHT CREW SEAT RAIL AND BEAM RIVETS INSPECTION/INSTALLATION	SAO	RECOMMENDED	MTH 24-Mar-1995 HRS 3411		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SB S550-53-11 53SB-11	DORSAL FIN INSTALLATION AND MATERIAL IMPROVEMENT		OPTIONAL	MTH		A/R			
<b>MOC :</b>									
SB S550-53-12 53SB-12	MAP COMPARTMENT ASSEMBLY INSPECTION/REPLACEMENT	SAO	RECOMMENDED	MTH 18-Oct-1995 HRS 3832		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SB S550-53-14 53SB-14	AN3-5A BOLT INSPECTION/REPLACEMENT	SAO	RECOMMENDED	MTH 30-Aug-1997 HRS 5106		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SB S550-53-15 53SB-15	FUSELAGE MOISTURE DRAIN INSTALLATION		OPTIONAL	MTH		A/R			
<b>MOC :</b>									
SB S550-53-16 53SB-16	FUSELAGE - MAIN CARRY-THRU LUG INSPECTION		RECOMMENDED			A/R			
<b>MOC :</b>									





# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB S550-53-17 53SB-17	WHEEL WELL BOX/SKIN GAP IMPROVEMENT			OPTIONAL	MTH		A/R			
<b>MOC :</b>										
SL S550-53-01 53SL-01	NOSE BAGGAGE AND TAILCONE ACCESS DOOR LATCH INSPECTION	SAO		RECOMMENDED	MTH 04-Oct-1987 HRS 665		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SL S550-53-03 53SL-03	DORSAL FIN VANE INSPECTION			RECOMMENDED			A/R			
<b>MOC :</b>										
SL S550-53-04 R01 53SL-04 : S55R1	INTERCOSTAL DRAINAGE PATH INSPECTION			RECOMMENDED			A/R			
<b>MOC :</b>										
SB S550-54-01 54SB-01	PYLON FAIRING DRAIN HOLE INSTALLATION	SAO		MANDATORY	MTH 26-Feb-1986 HRS 296		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SL S550-55-01 R01 55SL-01 : S55R1	RUDDER TORQUE TUBE INTERNAL CORROSION INSPECTION	SAO		RECOMMENDED	MTH 21-Nov-1990 HRS 1352		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SL S550-55-01 55SL-01	RUDDER TORQUE TUBE INTERNAL CORROSION INSPECTION (SUPERSEDED BY SLS550-55-01 R1)	SAO		RECOMMENDED	MTH 21-Nov-1990 HRS 1352		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SB S550-57-01 57SB-01	RIGHT WING ACCESS PANEL INSTALLATION	SAO		OPTIONAL	MTH 11-Jan-1988 HRS 749		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SB S550-57-02 57SB-02	VORTEX GENERATOR REMOVAL (SUPERSEDED BY S550-57-02 R01)			OPTIONAL	MTH		A/R			
<b>MOC :</b>										
SB S550-57-03 R02 57SB-03 : S55R2	FLAP ACTUATOR UPPER BELLCRANK BRACKET REPLACEMENT	SAO		RECOMMENDED	MTH 15-Jun-1998 HRS 5403		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SB S550-57-06 R01 57SB-06 : S55R1	STUB WING DOUBLER INSTALLATION	SAO		OPTIONAL	MTH		A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB S550-57-06 57SB-06	STUB WING DOUBLER INSTALLATION (SUPERSEDED BY S550-57-06 R01)	SAO		OPTIONAL	MTH		A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB S550-57-09 57SB-09	FLAP VENT HOLES INSTALLATION	SAO		RECOMMENDED	MTH 25-Oct-1996 HRS 4576		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
ASL SLS550-57-01A 57SLA01	FLAP DRAIN HOLE INSPECTION	SAO		MANDATORY	MTH 31-May-1988 HRS 827		A/R			Complete
<b>MOC :</b> COMPLIED WITH										



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL S550-57-02 57SL-02	AILERON EXTERNAL BALANCE WEIGHT INSPECTION		RECOMMENDED			A/R			
<b>MOC :</b>									
SL S550-71-01 71SL-01	JT15D-4B MINIMUM FUEL FLOW ADJUSTMENT	SAO	RECOMMENDED	MTH 04-Oct-1987 HRS 665		A/R			Complete
<b>MOC :</b> COMPLIED WITH									
SL S550-71-02 71SL-02	ENGINE BREATHER TUBE EXTENSION		OPTIONAL	MTH		A/R			
<b>MOC :</b>									
SL S550-72-02 72SL-02	BORESCOPE INSPECTION JT15D-4B ADDED TO PHASE 4 INSPECTION (SUPERSEDED BY SLS550-72-02 R01)	SAO	RECOMMENDED	MTH 26-Feb-1986 HRS 296		A/R			Complete
<b>MOC :</b> COMPLIED WITH									
SL S550-72-04 72SL-04	IMPROVED RETENTION OF P3 AIR-TO-FUEL CONTROL BOSS	SAO	RECOMMENDED	MTH 10-Jul-1987 HRS 604		A/R			Complete
<b>MOC :</b> COMPLIED WITH									
SL S550-72-05 72SL-05	JT15D FAN BLADE INSPECTION	SAO	RECOMMENDED	MTH 14-May-1987 HRS 581		A/R			Complete
<b>MOC :</b> COMPLIED WITH									
SL S550-72-06 R01 72SL-06 : S55R1	LOW COMPRESSOR CASE INSPECTION (SUPERSEDED BY SLS550-72-06 R02)	SAO	RECOMMENDED	MTH 31-May-1988 HRS 827		A/R			Complete
<b>MOC :</b> COMPLIED WITH									
SL S550-72-06 R02 72SL-06 : S55R2	LOW COMPRESSOR CASE INSPECTION (SUPERSEDED BY SLS550-72-06 R03)	SAO	RECOMMENDED	MTH 27-May-1988		A/R			Complete
<b>MOC :</b> COMPLIED WITH									
SL S550-72-06 72SL-06	LOW COMPRESSOR CASE INSPECTION (SUPERSEDED BY SLS550-72-06 R01)	SAO	RECOMMENDED	MTH 14-Jan-1988 HRS 749		A/R			Complete
<b>MOC :</b> COMPLIED WITH									
SL S550-72-07 72SL-07	LOW COMPRESSOR CASE DAMPENING RING INSTALLATION (SUPERSEDED BY SLS550-72-07 R01)	SAO	RECOMMENDED	MTH 27-May-1989 HRS 1038		A/R			Complete
<b>MOC :</b> COMPLIED WITH									
ASL SLS550-72-09A LEFT ENGINE 72SLA09 : S550L	JT15D-4B HIGH TURBINE BLADE SHAFT (CANCELLED)	SAO	CANCELLED	MTH 04-Nov-1988 HRS 921		A/R			Complete
<b>MOC :</b> COMPLIED WITH									
ASL SLS550-72-09A RIGHT ENGINE 72SLA09 : S550R	JT15D-4B HIGH TURBINE BLADE SHAFT (CANCELLED)	SAO	CANCELLED	MTH 04-Nov-1988 HRS 921		A/R			Complete
<b>MOC :</b> COMPLIED WITH									
SL S550-72-11 R01 72SL-11 : S55R1	JT15D-4B HIGH TURBINE BLADE SHIFT		RECOMMENDED			A/R			
<b>MOC :</b>									
SL S550-72-19 72SL-19	TRANSMITTAL OF P&WC SERVICE LETTER JT15D-023 REPLACEMENT OF OIL PUMP PLUG		RECOMMENDED			A/R			
<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl Part Serial No		C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB JT15D-72-7001 R25 E1	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS (SUPERSEDED BY SB 72-7001 R26) RECOMMENDED				-			
	<b>MOC :</b>							
SB JT15D-72-7001 R25 E2	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS (SUPERSEDED BY SB 72-7001 R26) RECOMMENDED				-			
	<b>MOC :</b>							
SB JT15D-72-7001 R26 E1	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS (SUPERSEDED BY SB 72-7001 R27) RECOMMENDED				-			
	<b>MOC :</b>							
SB JT15D-72-7001 R26 E2	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS (SUPERSEDED BY SB 72-7001 R27) RECOMMENDED				-			
	<b>MOC :</b>							
SB JT15D-72-7001 R27 E1	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS RECOMMENDED				-			
	<b>MOC :</b>							
SB JT15D-72-7001 R27 E2	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS RECOMMENDED				-			
	<b>MOC :</b>							
SB JT15D-72-7002 R42 E1	SERVICE LIVES - ROTOR COMPONENTS (SUPERSEDED BY SB 72-7002 R43) CATEGORY 3					A/R		
	<b>MOC :</b>							
SB JT15D-72-7002 R42 E2	SERVICE LIVES - ROTOR COMPONENTS (SUPERSEDED BY SB 72-7002 R43) CATEGORY 3					A/R		
	<b>MOC :</b>							
SB JT15D-72-7002 R44 E1	SERVICE LIVES ROTOR COMPONENTS CATEGORY 3				-			
	<b>MOC :</b>							
SB JT15D-72-7002 R44 E2	SERVICE LIVES ROTOR COMPONENTS CATEGORY 3				-			
	<b>MOC :</b>							
SB JT15D-72-7002 R45 E1	ROTOR COMPONENTS - SERVICE LIVES CATEGORY 3				-			
	<b>MOC :</b>							
SB JT15D-72-7002 R45 E2	ROTOR COMPONENTS - SERVICE LIVES CATEGORY 3				-			
	<b>MOC :</b>							
SB JT15D-72-7003 R35 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY SB 72-7003 R36) -				-			
	<b>MOC :</b>							
SB JT15D-72-7003 R35 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY SB 72-7003 R36) -				-			
	<b>MOC :</b>							



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB JT15D-72-7003 R36 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY SB 72-7003 R37)								
	<b>MOC :</b>								
SB JT15D-72-7003 R36 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY SB 72-7003 R37)								
	<b>MOC :</b>								
SB JT15D-72-7003 R37 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY SB 72-7003 R38)								
	<b>MOC :</b>								
SB JT15D-72-7003 R37 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY SB 72-7003 R38)								
	<b>MOC :</b>								
SB JT15D-72-7003 R38 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY SB 72-7003 R39)								
	<b>MOC :</b>								
SB JT15D-72-7003 R38 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY SB 72-7003 R39)								
	<b>MOC :</b>								
SB JT15D-72-7003 R39 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY SB 72-7003 R40)		RECOMMENDED						
	<b>MOC :</b>								
SB JT15D-72-7003 R39 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY SB 72-7003 R40)		RECOMMENDED						
	<b>MOC :</b>								
SB JT15D-72-7003 R40 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY		RECOMMENDED						
	<b>MOC :</b>								
SB JT15D-72-7003 R40 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY		RECOMMENDED						
	<b>MOC :</b>								
SB JT15D-72-7003 R41 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY		RECOMMENDED			A/R			
	<b>MOC :</b>								
SB JT15D-72-7003 R41 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY		RECOMMENDED			A/R			
	<b>MOC :</b>								
SB JT15D-72-7144 R20 E1	ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING								
	<b>MOC :</b>								
SB JT15D-72-7144 R20 E2	ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING								
	<b>MOC :</b>								



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB JT15D-72-7144 R21 E1	ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING			RECOMMENDED			-			
<b>MOC :</b>										
SB JT15D-72-7144 R21 E2	ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING			RECOMMENDED			-			
<b>MOC :</b>										
SB JT15D-72-7244 R05 E1	LOW TURBINE DISK AND TURBINE SHAFT ASSEMBLY - IMPROVED DURABILITY			CATEGORY 5			-			
<b>MOC :</b>										
SB JT15D-72-7244 R05 E2	LOW TURBINE DISK AND TURBINE SHAFT ASSEMBLY - IMPROVED DURABILITY			CATEGORY 5			-			
<b>MOC :</b>										
SB JT15D-72-7288 R04 E1	REPLACEMENT OF OVERSPEED CONTROL WIRE ROPE			CATEGORY 5			-			
<b>MOC :</b>										
SB JT15D-72-7288 R04 E2	REPLACEMENT OF OVERSPEED CONTROL WIRE ROPE			CATEGORY 5			-			
<b>MOC :</b>										
SB JT15D-72-7292 R01 E1	INTRODUCTION OF IMPROVED FUEL MANIFOLD TRANSFER TUBE LOCKING BRACKETS			CATEGORY 4			-			
<b>MOC :</b>										
SB JT15D-72-7292 R01 E2	INTRODUCTION OF IMPROVED FUEL MANIFOLD TRANSFER TUBE LOCKING BRACKETS			CATEGORY 4			-			
<b>MOC :</b>										
SB JT15D-72-7293 R10 E1	INTRODUCTION OF IMPROVED HIGH TURBINE ROTOR BLADE (DIRECTIONALLY SOLIDIFIED)			CATEGORY 4			-			
<b>MOC :</b>										
SB JT15D-72-7293 R10 E2	INTRODUCTION OF IMPROVED HIGH TURBINE ROTOR BLADE (DIRECTIONALLY SOLIDIFIED)			CATEGORY 4			-			
<b>MOC :</b>										
SB JT15D-72-7364 R03 E1	CONVERSION OF JT15D-4 ENGINE TO JT15D-4B CONFIGURATION			CATEGORY 8			-			
<b>MOC :</b>										
SB JT15D-72-7364 R03 E2	CONVERSION OF JT15D-4 ENGINE TO JT15D-4B CONFIGURATION			CATEGORY 8			-			
<b>MOC :</b>										
SB JT15D-72-7459 R01 E1	REPLACEMENT OF IGNITER (SUPERSEDED BY SB 72-7459 R02)			CATEGORY 8			A/R			
<b>MOC :</b>										
SB JT15D-72-7459 R01 E2	REPLACEMENT OF IGNITER (SUPERSEDED BY SB 72-7459 R02)			CATEGORY 8			A/R			
<b>MOC :</b>										
SB JT15D-72-7459 R02 E1	REPLACEMENT OF IGNITER			CATEGORY 8			-			
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB JT15D-72-7459 R02 E2	REPLACEMENT OF IGNITER			CATEGORY 8			-			
<b>MOC :</b>										
SB JT15D-72-7522 R06 E1	MODIFICATION OF GAS GENERATOR CASE (SUPERSEDED BY SB 72-7522 R07)			CATEGORY 5			-			
<b>MOC :</b>										
SB JT15D-72-7522 R06 E2	MODIFICATION OF GAS GENERATOR CASE (SUPERSEDED BY SB 72-7522 R07)			CATEGORY 5			-			
<b>MOC :</b>										
SB JT15D-72-7522 R07 E1	MODIFICATION OF GAS GENERATOR CASE			CATEGORY 5			-			
<b>MOC :</b>										
SB JT15D-72-7522 R07 E2	MODIFICATION OF GAS GENERATOR CASE			CATEGORY 5			-			
<b>MOC :</b>										
SB JT15D-72-7565 R01 E1	REPLACEMENT OF UPPER TOWER SHAFT DUPLEX BEARING			CATEGORY 5			-			
<b>MOC :</b>										
SB JT15D-72-7565 R01 E2	REPLACEMENT OF UPPER TOWER SHAFT DUPLEX BEARING			CATEGORY 5			-			
<b>MOC :</b>										
SB JT15D-72-7588 R02 E1	REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX INPUT DRIVE GEAR			CATEGORY 8			-			
<b>MOC :</b>										
SB JT15D-72-7588 R02 E2	REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX INPUT DRIVE GEAR			CATEGORY 8			-			
<b>MOC :</b>										
SB JT15D-72-7589 R01 E1	HIGH TURBINE DISC BALANCING ASSEMBLY - REPLACEMENT OF			CATEGORY 8			-			
<b>MOC :</b>										
SB JT15D-72-7589 R01 E2	HIGH TURBINE DISC BALANCING ASSEMBLY - REPLACEMENT OF			CATEGORY 8			-			
<b>MOC :</b>										
SB JT15D-72-7618 R02 E1	REPLACEMENT / MODIFICATION OF NO. 4 BEARING SLEEVE, HOUSING ASSEMBLY AND ROTOR AIR SEAL			CATEGORY 6			-			
<b>MOC :</b>										
SB JT15D-72-7618 R02 E2	REPLACEMENT / MODIFICATION OF NO. 4 BEARING SLEEVE, HOUSING ASSEMBLY AND ROTOR AIR SEAL			CATEGORY 6			-			
<b>MOC :</b>										
SB JT15D-72-7618 R03 E1	REPLACEMENT/MODIFICATION OF NO. 4 BEARING SLEEVE, HOUSING ASSEMBLY AND ROTOR AIR SEAL			CATEGORY 6			-			
<b>MOC :</b>										
SB JT15D-72-7618 R03 E2	REPLACEMENT/MODIFICATION OF NO. 4 BEARING SLEEVE, HOUSING ASSEMBLY AND ROTOR AIR SEAL			CATEGORY 6			-			
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB JT15D-72-7621 R01 E1	REPLACEMENT OF OIL FILTER ELEMENT			CATEGORY 7						
	<b>MOC :</b>									
SB JT15D-72-7621 R01 E2	REPLACEMENT OF OIL FILTER ELEMENT			CATEGORY 7						
	<b>MOC :</b>									
SB JT15D-72-7625 R01 E1	REPLACEMENT OF GASKET			CATEGORY 6			A/R			
	<b>MOC :</b>									
SB JT15D-72-7625 R01 E2	REPLACEMENT OF GASKET			CATEGORY 6			A/R			
	<b>MOC :</b>									
SB JT15D-72-7625 E1	REPLACEMENT OF GASKET (SUPERSEDED BY SB 72-7625 R01)			CATEGORY 6			A/R			
	<b>MOC :</b>									
SB JT15D-72-7625 E2	REPLACEMENT OF GASKET (SUPERSEDED BY SB 72-7625 R01)			CATEGORY 6			A/R			
	<b>MOC :</b>									
SB JT15D-72-7627 E1	LOW PRESSURE TURBINE INTERSTAGE ROTOR AIR SEAL AND ROTOR AIR SEAL -REPLACEMENT OF			CATEGORY 6						
	<b>MOC :</b>									
SB JT15D-72-7627 E2	LOW PRESSURE TURBINE INTERSTAGE ROTOR AIR SEAL AND ROTOR AIR SEAL -REPLACEMENT OF			CATEGORY 6						
	<b>MOC :</b>									
SB JT15D-72-7633 E1	ALTERNATE SOURCE RETAINING RING			CATEGORY 7						
	<b>MOC :</b>									
SB JT15D-72-7633 E2	ALTERNATE SOURCE RETAINING RING			CATEGORY 7						
	<b>MOC :</b>									
SB JT15D-72-7634 E1	REPLACEMENT OF SHIPPING CAPS FOR SHIPPING CONTAINERS			CATEGORY 3						
	<b>MOC :</b>									
SB JT15D-72-7634 E2	REPLACEMENT OF SHIPPING CAPS FOR SHIPPING CONTAINERS			CATEGORY 3						
	<b>MOC :</b>									
SB JT15D-72-7636 R01 E1	REPLACEMENT OF CADMIUM PLATED BOLTS			CATEGORY 7						
	<b>MOC :</b>									
SB JT15D-72-7636 R01 E2	REPLACEMENT OF CADMIUM PLATED BOLTS			CATEGORY 7						
	<b>MOC :</b>									
SB JT15D-72-7636 E1	REPLACEMENT OF CADMIUM PLATED BOLTS			CATEGORY 7						
	<b>MOC :</b>									
SB JT15D-72-7636 E2	REPLACEMENT OF CADMIUM PLATED BOLTS			CATEGORY 7						
	<b>MOC :</b>									
SB JT15D-72-7639 R02 E1	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY			CATEGORY 3						
	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB JT15D-72-7639 R02 E2	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY									
				CATEGORY 3			-			
	<b>MOC :</b>									
SB JT15D-72-7639 R03 E1	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY									
				CATEGORY 7			-			
	<b>MOC :</b>									
SB JT15D-72-7639 R03 E2	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY									
				CATEGORY 7			-			
	<b>MOC :</b>									
SB JT15D-72-7639 R04 E1	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY									
				CATEGORY 7			-			
	<b>MOC :</b>									
SB JT15D-72-7639 R04 E2	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY									
				CATEGORY 7			-			
	<b>MOC :</b>									
SB JT15D-72-7639 E1	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY (SUPERSEDED BY JT15D-72-7639 R01)									
				CATEGORY 4			-			
	<b>MOC :</b>									
SB JT15D-72-7639 E2	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY (SUPERSEDED BY JT15D-72-7639 R01)									
				CATEGORY 4			-			
	<b>MOC :</b>									
SB JT15D-72-7640 E1	REPLACEMENT OF SHIPPING PLUG									
				CATEGORY 7			-			
	<b>MOC :</b>									
SB JT15D-72-7640 E2	REPLACEMENT OF SHIPPING PLUG									
				CATEGORY 7			-			
	<b>MOC :</b>									
SB JT15D-72-7642 R01 E1	TRANSFER OF MANUFACTURING RIGHTS FOR VARIOUS PARTS									
				CATEGORY 10			-			
	<b>MOC :</b>									
SB JT15D-72-7642 R01 E2	TRANSFER OF MANUFACTURING RIGHTS FOR VARIOUS PARTS									
				CATEGORY 10			-			
	<b>MOC :</b>									
SB JT15D-72-7642 E1	TRANSFER OF MANUFACTURING RIGHTS FOR VARIOUS PARTS									
				CATEGORY 9			-			
	<b>MOC :</b>									
SB JT15D-72-7642 E2	TRANSFER OF MANUFACTURING RIGHTS FOR VARIOUS PARTS									
				CATEGORY 9			-			
	<b>MOC :</b>									
SB JT15D-72-7644 E1	REPLACEMENT OF T1 THERMOCOUPLE HARNESS									
				CATEGORY 7			-			
	<b>MOC :</b>									
SB JT15D-72-7644 E2	REPLACEMENT OF T1 THERMOCOUPLE HARNESS									
				CATEGORY 7			-			
	<b>MOC :</b>									
SB JT15D-72-7655 E1	INSPECTION OF IMPELLER REAR FACE									
				CATEGORY 3			-			
	<b>MOC :</b>									





# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB JT15D-72-7655 E2	INSPECTION OF IMPELLER REAR FACE			CATEGORY 3			-			
	<b>MOC :</b>									
ASB S550-73-01A R03 73SBA01 : S55R3	9912031-6 FUEL FLOW TRANSMITTER INSPECTION	SAO		MTH HRS	25-Oct-1996 4576		N/A			Complete
	<b>MOC :</b> COMPLIED WITH									
ASB S550-73-01A 73SBA01	9912031-6 FUEL FLOW TRANSMITTER INSPECTION (SUPERSEDED BY S550-73-01A R01)	SAO		MANDATORY	MTH HRS		28-Jun-1991 1413	A/R		Complete
	<b>MOC :</b> COMPLIED WITH									
SB S550-73-02 R01 73SB-02 : S55R1	9912031-6 FUEL FLOW TRANSMITTER THREAD INSPECTION	SAO		MANDATORY	MTH HRS		25-Oct-1996 4576	A/R		Complete
	<b>MOC :</b> COMPLIED WITH									
SL CIL-74-01 R01	INSPECTION OF IGNITION CABLE AND THROTTLE LINKAGE	UNK		MANDATORY	DAYS HRS LDG		01-Oct-2018 8902.1 7446	-		Complete
	<b>MOC :</b> COMPLIED WITH									
SL CIL-74-01	INSPECTION OF IGNITION CABLE AND THROTTLE LINKAGE (SUPERSEDED BY CIL-74-01 R01)			MANDATORY	DAYS			-		
	<b>MOC :</b>									
SL S550-74-02 74SL-02	IGNITION - TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN 7567R1 TURBOFAN ENGINE IGNITER BOX GROUNDING STRAP - INTRODUCTION OF			RECOMMENDED				A/R		
	<b>MOC :</b>									
SB S550-78-04 78SB-04	EXHAUST - THRUST REVERSER THROTTLE LOAD LIMITER MODIFICATION (SUPERSEDED BY S550-78-04 R01)	SAO		RECOMMENDED	MTH HRS		04-Oct-1993 2429	A/R		Complete
	<b>MOC :</b> COMPLIED WITH									
SB S550-78-05 78SB-05	EXHAUST - THRUST REVERSER THROTTLE STOP SOLENOID GROUND IMPROVEMENT			OPTIONAL	MTH			A/R		
	<b>MOC :</b>									
SL S550-78-01 78SL-01	INSPECTION OF AND REPLACEMENT OF PLUMBING ASSEMBLY IF AND AS REQUIRED	SAO		RECOMMENDED	MTH HRS		21-Mar-1986 296	A/R		Complete
	<b>MOC :</b> COMPLIED WITH									
SL S550-78-02 78SL-02	THRUST REVERSER JUNCTION BOX MODIFICATION (SUPERSEDED BY SLS550-78-02 R01)	SAO		RECOMMENDED	MTH HRS		04-Jul-1987 600	A/R		Complete
	<b>MOC :</b> COMPLIED WITH									
SL S550-78-04 R02 78SL-04 : S55R2	THRUST REVERSER DOOR MODIFICATION			RECOMMENDED				A/R		
	<b>MOC :</b>									
SL S550-78-04 78SL-04	THRUST REVERSER DOOR MODIFICATION (SUPERSEDED BY SLS550-78-04 R01)			SUPERSEDED				-		
	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL S550-78-05 R03 78SL-05 : S55R3	THRUST REVERSER SYSTEM OPERATIONAL TEST	SAO		MTH RECOMMENDED	25-Oct-1996 4576		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SL S550-78-05 78SL-05	THRUST REVERSER SYSTEM OPERATIONAL TEST (SUPERSEDED BY SLS550-78-05 R01)	SAO		MTH RECOMMENDED	10-Jul-1991 1420		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SL S550-78-08 78SL-08	THRUST REVERSER STANG FAIRING SUPPORT FORMER REPLACEMENT	SAO		MTH RECOMMENDED	09-Aug-1994 3029		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SL S550-78-10 R01 78SL-10 : S55R1	TRANSMITTAL OF NORDAM SERVICE BULLETIN CITSII 78-12 R1, EXHAUST - THRUST REVERSER - REPLACEMENT OF THRUST REVERSER STANG FAIRING SUPPORT FORMER			RECOMMENDED			A/R			
<b>MOC :</b>										
SIL GEN-153 R09 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
<b>MOC :</b>										
SIL GEN-153 R09 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
<b>MOC :</b>										
SB S550-80-01 80SB-01	STARTING - REPLACEMENT OF SUPPRESSION DIODE WITH TRANSZORB			OPTIONAL MTH			A/R			
<b>MOC :</b>										
SL CIL-99-01 R03	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS			CANCELLED			-			
<b>MOC :</b>										
SL CIL-99-02 R01	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			CANCELLED			-			
<b>MOC :</b>										
SL CIL-99-03 R02	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			CANCELLED			-			
<b>MOC :</b>										
SL CIL-99-04 R01	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			CANCELLED			-			
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 1990-07-10 <i>21AD-01</i>	TO PREVENT FAILURE OF THE ELEVATOR OR RUDDER CONTROL CABLES	SAO		SUPERSEDED	MTH 08-Feb-1991 HRS 1400		-			Complete
<b>MOC : COMPLIED WITH</b>										
FAA 1993-05-15 <i>78AD-01</i>	MODIFY THE THRUST REVERSER THROTTLE LOAD LIMITER	SAO		MANDATORY	MTH 18-Oct-1995 HRS 3832		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
FAA 2013-09-11 PARA (G)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION FOR PART NUMBER (P/N)	UNK		MANDATORY	DAYS 01-Aug-2019 HRS 8912.2 LDG 7452		-			N/A
<b>MOC : NOT APPLICABLE - BY AFFECTED MODEL NOT INSTALLED</b>										
FAA 2013-09-11 PARA (H)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION A/C COMPRESSOR HOUR METER AND MAINTENANCE RECORDS	UNK		MANDATORY	DAYS 01-Aug-2019 HRS 8912.2 LDG 7452		-			N/A
<b>MOC : NOT APPLICABLE - BY AFFECTED MODEL NOT INSTALLED</b>										
FAA 2013-09-11 PARA (I) & (J)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REPLACEMENT OF A/C COMPRESSOR MOTOR BRUSHES AND RELATED MAINTENANCE MANUAL INFORMATION	UNK		MANDATORY	MTH 01-Aug-2019 HRS 8912.2 LDG 7452		-			N/A
<b>MOC : NOT APPLICABLE - BY AFFECTED MODEL NOT INSTALLED</b>										
FAA 2013-09-11 PARA (K)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM DEACTIVATION OF A/C SYSTEM	UNK		MANDATORY	MTH 01-Aug-2019 HRS 8912.2 LDG 7452		A/R			N/A
<b>MOC : NOT APPLICABLE - BY AFFECTED MODEL NOT INSTALLED</b>										
FAA 2013-09-11 PARA (L)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REACTIVATION OF A/C SYSTEM	UNK		MANDATORY	MTH 01-Aug-2019 HRS 8912.2 LDG 7452		A/R			N/A
<b>MOC : NOT APPLICABLE - BY AFFECTED MODEL NOT INSTALLED</b>										
FAA 2013-09-11 PARA (M)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM PARTS RETURN AND REPORTING REQUIREMENTS	UNK		MANDATORY	MTH 01-Aug-2019 HRS 8912.2 LDG 7452		-			N/A
<b>MOC : NOT APPLICABLE - BY AFFECTED MODEL NOT INSTALLED</b>										
FAA 2013-09-11	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM	UNK		MANDATORY	MTH 01-Aug-2019 HRS 8912.2 LDG 7452		-			N/A
<b>MOC : NOT APPLICABLE - BY AFFECTED MODEL NOT INSTALLED</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-17-12 PARA (G)	INSPECT THE A/C COMPRESSOR MOTOR TO DETERMINE WHETHER P/N FWA1134104-1 OR P/N FWA1134104-5 IS INSTALLED	UNK		MANDATORY	DAYS 01-Aug-2019 HRS 8912.2 LDG 7452		-			N/A
<b>MOC : NOT APPLICABLE - AFFECTED MODEL NOT INSTALLED</b>										
FAA 2015-17-12 PARA (H)	DETERMINE THE HOUR READING ON THE A/C COMPRESSOR HOUR METER (IF, DURING THE INSPECTION REQUIRED BY PARA (G) OF THIS AD, ANY A/C COMPRESSOR MOTOR HAVING P/N FWA1134104-1 OR P/N FWA1134104-5 IS FOUND	UNK		MANDATORY	DAYS 01-Aug-2019 HRS 8912.2 LDG 7452		-			N/A
<b>MOC : NOT APPLICABLE - AFFECTED MODEL NOT INSTALLED</b>										
FAA 2015-17-12 PARA (I)	REPLACE THE A/C COMPRESSOR MOTOR BRUSHES WITH NEW BRUSHES (USING THE HOUR READING ON THE A/C COMPRESSOR HOUR METER DETERMINED IN PARA (H) OF THIS AD)	UNK		MANDATORY	MTH 01-Aug-2019 HRS 8912.2 LDG 7452		-			N/A
<b>MOC : NOT APPLICABLE - AFFECTED MODEL NOT INSTALLED</b>										
FAA 2015-17-12 PARA (K)	DEACTIVATE THE A/C SYSTEM (IN LIEU OF REPLACING THE A/C COMPRESSOR MOTOR BRUSHES AS REQUIRED BY THIS AD)	UNK		MANDATORY	MTH 01-Aug-2019 HRS 8912.2 LDG 7452		-			N/A
<b>MOC : NOT APPLICABLE - AFFECTED MODEL NOT INSTALLED</b>										
FAA 2015-17-12 PARA (L)	IF THE A/C SYSTEM IS DEACTIVATED, AS SPECIFIED IN PARA (K), PRIOR TO THE A/C SYSTEM BEING REACTIVATED: PERFORM THE INSPECTION SPECIFIED IN PARA (H), AND DO THE REPLACEMENTS SPECIFIED IN PARA (I), AT THE TIMES SPECIFIED IN PARA (I). RETURN THE A/C SYSTEM TO SERVICE	UNK		MANDATORY	MTH 01-Aug-2019 HRS 8912.2 LDG 7452		-			N/A
<b>MOC : NOT APPLICABLE - AFFECTED MODEL NOT INSTALLED</b>										
FAA 2015-17-12 PARA (M)	SEND THE REMOVED BRUSHES TO CESSNA AIRCRAFT COMPANY	UNK		MANDATORY	DAYS 01-Aug-2019 HRS 8912.2 LDG 7452		-			N/A
<b>MOC : NOT APPLICABLE - AFFECTED MODEL NOT INSTALLED</b>										
FAA 2015-17-12	AIR CONDITIONING - INSPECTIONS TO DETERMINE IF CERTAIN A/C COMPRESSOR MOTORS ARE INSTALLED AND TO DETERMINE THE ACCUMULATED HOURS ON CERTAIN A/C COMPRESSOR MOTOR ASSEMBLIES; AND REPETITIVE REPLACEMENT OF THE BRUSHES IN THE A/C COMPRESSOR MOTOR ASSEMBLY, OR, AS AN OPTION TO THE BRUSH REPLACEMENT, DEACTIVATION OF THE A/C SYSTEM AND PLACARD INSTALLATION; AND RETURN OF REPLACED BRUSHES TO CESSNA	UNK		MANDATORY	MTH 01-Aug-2019 HRS 8912.2 LDG 7452		-			N/A
<b>MOC : NOT APPLICABLE - AFFECTED MODEL NOT INSTALLED</b>										
FAA 1988-06-02	ELECTRICAL POWER			MANDATORY			-			
<b>MOC :</b>										
FAA 1987-03-15 25AD-01	SUPERSEDED BY AD 1988-24-16 SAO			SUPERSEDED	MTH 20-Apr-1987 HRS 581		-			Complete
<b>MOC : COMPLIED WITH</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 1988-24-16 25AD-03	TO PRECLUDE WIRING FAILURE, WHICH CAN RESULT IN CABIN SMOKE AND/OR FIRE	SAO		MANDATORY	MTH 15-Dec-1989 HRS 1152		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
FAA 1989-06-01 25AD-04	APPLIANCE AD - TO PREVENT THE IMPROPER FUNCTIONING OF THE CO2 INFLATORS	SAO		MANDATORY	MTH 26-Jul-1989 HRS 1078		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
FAA 1998-25-10 25AD-07	APPLIANCE AD - TO PREVENT FAILURE OF THE SEAT RESTRAINT SYSTEM	SNA		MANDATORY	MTH 14-Jan-1999 HRS 5479		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
FAA 2015-10-02 PARA (G)	GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2			MANDATORY	MTH		-			
<b>MOC :</b>										
FAA 2015-10-02 PARA (H)	CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK			MANDATORY			-			
<b>MOC :</b>										
FAA 2015-10-02 PARA (I)	REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS			MANDATORY			-			
<b>MOC :</b>										
FAA 2015-10-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT			MANDATORY	MTH		-			
<b>MOC :</b>										
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS	UNK		MANDATORY	MTH 15-Nov-2021 HRS 8949.5 LDG 7477		12		15-Nov-2022	4 m 7 d Complete
<b>MOC : COMPLIED WITH</b>										
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT			MANDATORY			-			
<b>MOC :</b>										
FAA 2017-16-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS			MANDATORY			-			
<b>MOC :</b>										
FAA 2021-07-13 PARA (E)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE			MANDATORY	MTH		-			
<b>MOC :</b>										
FAA 2021-07-13 PARA (E)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE			MANDATORY	MTH		-			
<b>MOC :</b>										
FAA 2021-07-13 PARA (E)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER			MANDATORY			-			
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2021-07-13	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT			MANDATORY			-			
	<b>MOC :</b>									
AD 26-05	KIDDE AEROSPACE HAND HELD BTL	SNA			MTH 30-Jan-2004 HRS 7048		-			Complete
	<b>MOC :</b> COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED									
FAA 2001-22-14 26AD-01	APPLIANCE AD - TO PREVENT DAMAGE TO FIRE EXTINGUISHING SYSTEM COMPONENTS CAUSED BY A FIRE EXTINGUISHING SYSTEM BOTTLE CARTRIDGE ACTIVATING WITH EXCESSIVE ENERGETIC	SNA		MANDATORY	MTH 27-Dec-2001 HRS 6469		A/R			Complete
	<b>MOC :</b> COMPLIED WITH - NOT APPLICABLE									
FAA 2006-04-10 26AD-02	SUPERSEDED BY 2007-11-17	TOL		SUPERSEDED	MTH 17-Jun-2006 HRS 7648		-			Complete
	<b>MOC :</b> COMPLIED WITH - INTENT ACCOMPLISHED DURING PREVIOUS MAINTENANCE OR THROUGH ALTERNATE METHOD OF COMPLIANCE.									
FAA 2007-11-17 26AD-06	ENSURE FIRE EXTINGUISHING BOTTLES ARE ACTIVATED IN THE EVENT OF AN ENGINE OR APU FIRE			MANDATORY	DAYS 30-Sep-2009 HRS 7930 LDG 6975		A/R			Complete
	<b>MOC :</b> COMPLIED WITH									
FAA 2010-04-16 PARA (G) 26AD-07	REPLACE TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI WITH SERVICABLE UNIT			MANDATORY	DAYS 28-Apr-2010 HRS 8032 LDG 7040		A/R			N/A
	<b>MOC :</b> NOT APPLICABLE - DOSE NOT APPLY NOT INSTALLED									
FAA 2010-04-16 PARA (H)	RETURN TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI THE AFFECTED FIRE EXTINGUISHER TO MANUFACTURER			MANDATORY	DAYS 28-Apr-2010 HRS 8032 LDG 7040		A/R			N/A
	<b>MOC :</b> NOT APPLICABLE - DOSE NOT APPLY NOT INSTALLED									
FAA 2010-04-16	APPLIANCE AD - TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI			MANDATORY	MTH 28-Apr-2010 HRS 8032 LDG 7040		A/R			N/A
	<b>MOC :</b> NOT APPLICABLE - DOSE NOT APPLY NOT INSTALLED									
FAA 2006-06-03 28AD-02	PREVENT FUEL VAPOR IGNITION			MANDATORY	MTH 30-Sep-2009 HRS 7930 LDG 6975		A/R			Complete
	<b>MOC :</b> COMPLIED WITH									
FAA 1985-24-04 30AD-01	TO PREVENT HAZARDOUS ACCUMULATION OF ICE ON THE INBOARD WING LEADING EDGE DURING FLIGHT IN ICING CONDITIONS	SAO		MANDATORY	MTH 18-Dec-1985 HRS 229		A/R			Complete
	<b>MOC :</b> COMPLIED WITH									
FAA 1985-25-10 30AD-02	TO PREVENT HAZARDOUS ACCUMULATION OF ICE ON THE WING LEADING EDGE AND HORIZONTAL STABILIZER DURING FLIGHT IN ICING CONDITIONS	SAO		MANDATORY	MTH 16-Jan-1986 HRS 255		A/R			Complete
	<b>MOC :</b> COMPLIED WITH									



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2021-23-12	APPLIANCE AD - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS	CRQ		MANDATORY	MTH 10-Mar-2022 HRS 8957.7 LDG 7478		-			Complete
<b>MOC : COMPLIED WITH - COMPLIED WITH AD2021-23-12</b>										
FAA 1986-01-02 32AD-01	SUPERSEDED BY 1988-13-03	SAO		SUPERSEDED	MTH 15-Jan-1986 HRS 251		-			Complete
<b>MOC : COMPLIED WITH</b>										
FAA 1988-13-03 R01 32AD-02 : S55R1	TO PREVENT LOSS OF CONTROL OF THE AIRPLANE DURING LANDING OR TAKEOFF DUE TO FAILURE OF THE COTTER PINS SECURING THE MAIN LANDING GEAR TORQUE LINK CONNECTIONS	SAO		MANDATORY	MTH 30-May-1990 HRS 1254		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
FAA 1988-13-03 32AD-02	TO PREVENT LOSS OF CONTROL OF THE AIRPLANE DURING LANDING OR TAKEOFF DUE TO FAILURE OF THE COTTER PINS SECURING THE MAIN LANDING GEAR TORQUE LINK CONNECTIONS (SUPERSEDED BY 1988-13-03 R01)	SAO		SUPERSEDED	MTH 30-May-1990 HRS 1254		-			Complete
<b>MOC : COMPLIED WITH</b>										
FAA 1990-07-08 33AD-02	APPLIANCE AD - SUPERSEDED BY AD 1990-07-08 R1	SAO		SUPERSEDED	MTH 13-Feb-1991 HRS 1401		-			Complete
<b>MOC : COMPLIED WITH</b>										
FAA 1990-14-06 33AD-03	APPLIANCE AD - SUPERSEDED BY AD 1995-22-01	SAO		SUPERSEDED	MTH 13-Feb-1991 HRS 1401		-			Complete
<b>MOC : COMPLIED WITH</b>										
FAA 1995-22-01 33AD-04	APPLIANCE AD - TO PREVENT SMOKE, FIRE, ELECTRICAL SHOCK AND POSSIBLE ELECTROMAGNETIC INTERFERENCE CAUSED BY HIGH VOLTAGE ARCING	SAO		MANDATORY	MTH 22-Dec-1997 HRS 5301		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
AD 34-07	ALLIED SIGNAL NAV	CRQ			MTH 15-Jul-1999 HRS 5631		-			Complete
<b>MOC : COMPLIED WITH</b>										
AD 34-08	MODE C TRANSPONDER CHECKS	CRQ			MTH 12-Jan-2000 HRS 5846		-			Complete
<b>MOC : COMPLIED WITH</b>										
FAA 1990-03-02 34AD-01	APPLIANCE AD - SUPERSEDED BY AD 1990-06-13	SAO		SUPERSEDED	MTH 01-May-1993 HRS 2424		-			Complete
<b>MOC : COMPLIED WITH</b>										
FAA 1990-06-13 34AD-02	APPLIANCE AD - TO PREVENT ERRONEOUS ATTITUDE DISPLAY	SAO		MANDATORY	MTH 01-May-1993 HRS 2424		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
FAA 1998-25-02 34AD-06	APPLIANCE AD - TO PREVENT THE DISPLAY OF TARGET INDICATORS ON THE WRONG SIDE OF THE AIRCRAFT CAUSED BY AN INTERNAL COMPONENT FAILURE IN THE SKY497 INSTALLATIONS	SNA		MANDATORY	MTH 14-Jan-1999 HRS 5479		A/R			Complete
<b>MOC : COMPLIED WITH</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2001-23-17 <i>34AD-26</i>	APPLIANCE AD - TO PREVENT INACCURATE COURSE DEVIATION DISPLAYS IN THE GNS 430 UNIT	SNA	MANDATORY	MTH 27-Dec-2001 HRS 6469		A/R			Complete
<b>MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED</b>									
FAA 2003-13-08 <i>34AD-13</i>	APPLIANCE AD - TERRAIN AWARENESS WARNING SYSTEMS (TAWS)	SNA	MANDATORY	MTH 30-Jan-2004 HRS 7048		A/R			Complete
<b>MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED</b>									
FAA 2004-08-15 <i>34AD-14</i>	APPLIANCE AD - CORRECTION: GOODRICH AVIONICS SYSTEMS, INC TAWS8000 TERRAIN AWARENESS WARNING SYSTEM	ILG	MANDATORY	MTH 12-Dec-2005 HRS 7574		A/R			N/A
<b>MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED</b>									
FAA 2006-16-18 R01 <i>34AD-34 : S55R1</i>	APPLIANCE AD - TO PREVENT A BEARING ERROR			DAYS 04-Jan-2010 HRS 7930 LDG 6975		14			N/A
<b>MOC : NOT APPLICABLE - TO THIS AIRCRAFT.THERE IS NO SANDEL ST3400 INSTALLED.NO FURTHER ACTION NECESSARY</b>									
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION		MANDATORY	MTH		-			
<b>MOC :</b>									
FAA 2015-10-51-E	APPLIANCE/EMERGENCY AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.		MANDATORY	MTH		-			
<b>MOC :</b>									
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS		MANDATORY			-			
<b>MOC :</b>									
FAA 1994-19-06 <i>35AD-01</i>	APPLIANCE AD - TO PREVENT THE FLIGHT CREW FROM EXPERIENCING DIFFICULTY IN EXHALING	SAO	MANDATORY	MTH 18-Aug-1995 HRS 3694		A/R			Complete
<b>MOC : COMPLIED WITH - NOT APPLICABLE</b>									
FAA 1999-08-21 <i>35AD-02</i>	APPLIANCE AD - TO PREVENT REDUCED OXYGEN CONSUMPTION WHEN PASSENGERS ARE REQUIRED TO USE DEFECTIVE OXYGEN MASKS	LGB	MANDATORY	MTH 04-Jun-1999 HRS 5576		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011	UNK	MANDATORY	MTH 01-Aug-2019 HRS 8912.2 LDG 7452		-			N/A
<b>MOC : NOT APPLICABLE - PN AFFECTED NOT INSTALLED</b>									
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PAPERGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSES	UNK	MANDATORY	MTH 01-Aug-2019 HRS 8912.2 LDG 7452		-			N/A
<b>MOC : NOT APPLICABLE - PN AFFECTED NOT INSTALLED</b>									





# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-08-07	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSSES	UNK	MANDATORY	MTH 01-Aug-2019 HRS 8912.2 LDG 7452		-			N/A
<b>MOC : NOT APPLICABLE - PN AFFECTED NOT INSTALLED</b>									
FAA 2015-23-09 PARA (G)	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER	UNK	MANDATORY	DAYS 01-Aug-2019 HRS 8912.2 LDG 7452		-			N/A
<b>MOC : NOT APPLICABLE - BY AFFECTED MODEL NOT INSTALLED</b>									
FAA 2015-23-09 PARA (H.1)	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).	UNK	MANDATORY	DAYS 01-Aug-2019 HRS 8912.2 LDG 7452		-			N/A
<b>MOC : NOT APPLICABLE - BY AFFECTED MODEL NOT INSTALLED</b>									
FAA 2015-23-09 PARA (H.2.1)	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1	UNK	MANDATORY	DAYS 01-Aug-2019 HRS 8912.2 LDG 7452		-			N/A
<b>MOC : NOT APPLICABLE - BY AFFECTED MODEL NOT INSTALLED</b>									
FAA 2015-23-09 PARA (H.2.II)	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."	UNK	MANDATORY	DAYS 01-Aug-2019 HRS 8912.2 LDG 7452		-			N/A
<b>MOC : NOT APPLICABLE - BY AFFECTED MODEL NOT INSTALLED</b>									
FAA 2015-23-09 PARA (I)	REGULATOR REPLACEMENT	UNK	MANDATORY	MTH 01-Aug-2019 HRS 8912.2 LDG 7452		-			N/A
<b>MOC : NOT APPLICABLE - BY AFFECTED MODEL NOT INSTALLED</b>									
FAA 2015-23-09	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS	UNK	MANDATORY	MTH 01-Aug-2019 HRS 8912.2 LDG 7452		-			N/A
<b>MOC : NOT APPLICABLE - BY AFFECTED MODEL NOT INSTALLED</b>									
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAAAD 2017-18-12		MANDATORY	MTH		-			
<b>MOC :</b>									
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12		MANDATORY			-			
<b>MOC :</b>									
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAAAD 2017-18-12		MANDATORY	MTH		-			
<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAAAD 2017-18-12		MANDATORY			-			
<b>MOC :</b>									
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	UNK	MANDATORY	MTH 01-Aug-2019 HRS 8912.2 LDG 7452		-			N/A
<b>MOC :</b> NOT APPLICABLE - NOT EQUIPPED WITH PBE									
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	UNK	MANDATORY	MTH 01-Aug-2019 HRS 8912.2 LDG 7452		-			N/A
<b>MOC :</b> NOT APPLICABLE - NOT EQUIPPED WITH PBE									
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.	UNK	MANDATORY	MTH 01-Aug-2019 HRS 8912.2 LDG 7452		-			N/A
<b>MOC :</b> NOT APPLICABLE - NOT EQUIPPED WITH PBE									
FAA 2017-18-12	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES	UNK	MANDATORY	MTH 01-Aug-2019 HRS 8912.2 LDG 7452		-			N/A
<b>MOC :</b> NOT APPLICABLE - NOT EQUIPPED WITH PBE									
FAA 1988-11-07 57AD-01	TO PREVENT LOSS OF A FLAP PANEL	SAO	MANDATORY	MTH 31-May-1988 HRS 827		A/R			Complete
<b>MOC :</b> COMPLIED WITH									
AD 72-01	JT15D FAN BLADE INSP	SAO		MTH 14-May-1987 HRS 581		-			Complete
<b>MOC :</b> COMPLIED WITH									
AD 72-03	HP TURB. BLADE SHIFT	SAO		MTH 20-Sep-1995 HRS 3770		-			Complete
<b>MOC :</b> COMPLIED WITH									
AD 72-04	GAS GEN CASE INSP	SAO		MTH 20-Sep-1995 HRS 3770		-			Complete
<b>MOC :</b> COMPLIED WITH									
FAA 1988-22-03 E1	HT BLADE SHIFT INSP	AZO	SUPERSEDED	MTH 07-Nov-1988 HRS -3251.3		-			Complete
<b>MOC :</b> COMPLIED WITH									
FAA 1988-22-03 E2	HT BLADE SHIFT INSP	AZO	SUPERSEDED	MTH 07-Nov-1988 HRS -3251.3		-			Complete
<b>MOC :</b> COMPLIED WITH									
FAA 1993-18-08 E1	PREVENT A HIGH PRESSURE TURBINE (HPT) ASSEMBLY FAILURE. AMENDMENT 39-8693	CMH	MANDATORY	MTH 14-Jan-1994 HRS 849.7		-			Complete
<b>MOC :</b> COMPLIED WITH									



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
FAA 1993-18-08 E2	PREVENT A HIGH PRESSURE TURBINE (HPT) ASSEMBLY FAILURE. AMENDMENT 39-8693 CMH	MANDATORY	MTH 14-Jan-1994 HRS 849.7							Complete

**MOC : COMPLIED WITH**



# CESCOM 10 - Aircraft Status Report

Owner: **PREMIER AIR CHARTER, LLC**  
 Aircraft Model: **S550 - CITATION SII**  
 Aircraft Serial: **S550-0024**  
 Unit: **0024** Reg No: **N790AL**  
 Airworthiness: **22-Feb-1985**  
 Print Date: **08-Jul-2022 10:39AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>8957.7</b>	<b>7478</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 1</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>
<b>ENG 2</b>	<b>12592</b>	<b>10392</b>	<b>29-Jun-2022</b>	<b>.9</b>

## Factory Installed

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
24FO-01B <i>24FO-01 : 550/B</i>	BATTERY & MONITOR FOR 20 CELL FACTORY OPTION	*CF		12B FO	MTH 22-Feb-1985		-			
25FO-08	SEATING OPTION 1 FACTORY OPTION	*CF		110 FO	MTH 22-Feb-1985		-			
27FO-01A <i>27FO-01 : 550/A</i>	ELECTRIC TRIM SWITCH COPILOT FACTORY OPTION	*CF		33A FO	MTH 22-Feb-1985		-			
28FO-01	FUEL CAP LOCKING FACTORY OPTION	*CF		36 FO	MTH 22-Feb-1985		-			
32FO-03M <i>32FO-03 : 550/M</i>	GRAVEL RUNWAY KIT FACTORY OPTION	*CF		187M FO	MTH 22-Feb-1985		-			
33FO-02B <i>33FO-02 : 550/B</i>	LIGHT-RECOGNITION WING-TIP MOUNTED FACTORY OPTION	*CF		49B FO	MTH 22-Feb-1985		-			
34FO-01C <i>34FO-01 : 550/C</i>	ALTIMETER MILLIBAR R H EXCH FACTORY OPTION	*CF		01C FO	MTH 22-Feb-1985		-			
34FO-03	HORIZON GYRO ELECTRIC STANDBY FACTORY OPTION	*CF		142 FO	MTH 22-Feb-1985		-			
34FO-04	LOCATOR BEACON EMERGENCY FACTORY OPTION	*CF		175 FO	MTH 22-Feb-1985		-			
34FO-07D <i>34FO-07 : 550/D</i>	2ND TRANSPONDER- COLLINS TDR-90 FACTORY OPTION	*CF		623D FO	MTH 22-Feb-1985		-			
34FO-12S <i>34FO-12 : 550/S</i>	2ND ADF COLLINS ADF60 WO/HF COMM AFT FACTORY OPTION	*CF		658S FO	MTH 22-Feb-1985		-			
34FO-13A <i>34FO-13 : 550/A</i>	COLLIN ELECTRONIC CONTROL-CTL W/DUAL ADF FACTORY OPTION	*CF		659A FO	MTH 22-Feb-1985		-			
34FO-20X <i>34FO-20 : 550/X</i>	VLF NAV GLOBAL GNS500A SER 3 AFT FACTORY OPTION	*CF		693X FO	MTH 22-Feb-1985		-			
34FO-94F <i>34FO-94 : 550/F</i>	RADIO ALTIMETER SPERRY AA-300 FACTORY OPTION	*CF		673F FO	MTH 22-Feb-1985		-			
35FO-02B <i>35FO-02 : 550/B</i>	OXYGEN SYSTEM 64 CUBIC FEET FACTORY OPTION	*CF		66B FO	MTH 22-Feb-1985		-			
73FO-01C <i>73FO-01 : 550/C</i>	ENGINE SYNCHRONIZING INSTRUMENT W/TH REV FACTORY OPTION	*CF		76C FO	MTH 22-Feb-1985		-			
78FO-01	THRUST REVERSERS FACTORY OPTION	*CF		193 FO	MTH 22-Feb-1985		-			