



## Status Report

HAWKER 800XP

S/N 258300 N950PC

OWNER: ASAP JET CHARTERS INC  
ADDRESS: 12025 NW 62ND STREET  
CORAL SPRINGS FL 33076-1906  
OFFICE:  
FAX: 1-954-827-0885

OPERATOR: KLM AVIATION, INC.  
ADDRESS: 1525 NW 56 STREET  
FT. LAUDERDALE FL 33309  
OFFICE: 1-954-608-8138  
FAX: 1-954-827-0885

OPERATOR: KLM AVIATION, INC.  
ADDRESS: 12025 NW 62ND CT  
CORAL SPRINGS FL 33076  
OFFICE: 1-954-501-6842  
FAX: 1-954-827-0885

ANALYST: CHRISTOPHER CUTLER  
EMAIL: CCUTLER@CAMPSYSTEMS.COM

1-866-581-2267 (OFFICE)  
316-462-2442 (FAX)  
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)  
631-980-4222 (EFAX-CARDS)

PLEASE REACH OUT TO YOUR ANALYST TO  
RECORD CHANGES TO ADDRESS, LAST ACTUALS  
(IF ANY).

FILTER CRITERIA : Spl. Reqs:INCLUDE;PN/SN-UNKNOWN Components:INCLUDE;Task Type:PACKAGE, COMPONENT, SERVICE

|                                                                         |                                      |                                                                                                                                                |                                               |
|-------------------------------------------------------------------------|--------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------|
| AIRCRAFT                                                                | SERIAL / REGNO: 258300/N950PC        | MODEL: HAWKER 800XP                                                                                                                            | MANUFACTURER: TEXTRON AVIATION INC.           |
| CERTIFICATION DATE: 30-MAY-1996                                         |                                      | LAST ACTUALS:<br>6528.3 A/C HRS as of 29-JAN-2023<br>3929 AFL as of 29-JAN-2023<br>3349.13 APH as of 25-NOV-2022<br>6302 APS as of 25-NOV-2022 |                                               |
| APU                                                                     | SERIAL / PART: SP-E965277/165101-200 | MODEL: T-62T-40C8D1                                                                                                                            | MANUFACTURER: HAMILTON SUNDSTRAND CORPORATION |
| INSTALLED ON: 11-SEP-1996<br>9 APU HRS 0 A/C HRS<br>47 APUS             |                                      | LAST ACTUALS:<br>3349.13 APU HRS as of 25-NOV-2022<br>6302 APUS as of 25-NOV-2022                                                              |                                               |
| ENGINE NO. 1                                                            | SERIAL / PART: P-107171/3075160-3    | MODEL: TFE731-5BR-1H                                                                                                                           | MANUFACTURER: HONEYWELL                       |
| INSTALLED ON: 09-MAR-2004<br>2632.6 ENG. HRS 2632.6 A/C HRS<br>1434 ENC |                                      | LAST ACTUALS:<br>6531.5 ENG. HRS as of 29-JAN-2023<br>3932 ENC as of 29-JAN-2023                                                               |                                               |
| ENGINE NO. 2                                                            | SERIAL / PART: P-107151/3075160-3    | MODEL: TFE731-5BR-1H                                                                                                                           | MANUFACTURER: HONEYWELL                       |
| INSTALLED ON: 18-JAN-2002<br>2057 ENG. HRS 2137 A/C HRS<br>1144 ENC     |                                      | LAST ACTUALS:<br>6447.2 ENG. HRS as of 29-JAN-2023<br>3884 ENC as of 29-JAN-2023                                                               |                                               |



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                 | Unit                                                                                           | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition              |
|-----------------------------------------|------------------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|--------------------------|
| ATA 00 - INFORMATION                    |                                                                                                |           |          |          |                           |           |           |                          |
| 121000 <sup>U</sup>                     | AIRCRAFT REGISTRATION                                                                          |           |          |          |                           |           |           | Service ATA:00           |
|                                         | MOS                                                                                            | 23-Nov-22 | 36       |          | 31-Oct-25 (M)             |           | 1004 d    |                          |
|                                         | HRS                                                                                            | 6482.7    |          |          |                           |           |           |                          |
|                                         | AFL                                                                                            | 3897      |          |          |                           |           |           |                          |
| 121003 <sup>U</sup>                     | AIRCRAFT RADIO STATION LICENSE                                                                 |           |          |          |                           |           |           | Service ATA:00           |
|                                         | MOS                                                                                            | 23-Nov-22 | 120      |          | 28-Jan-30 (M)             |           | 2554 d    |                          |
|                                         | HRS                                                                                            | 6482.7    |          |          |                           |           |           |                          |
|                                         | AFL                                                                                            | 3897      |          |          |                           |           |           |                          |
| 121004 <sup>U</sup>                     | AIRWORTHINESS CERTIFICATE                                                                      |           |          |          |                           |           |           | Service ATA:00           |
|                                         | MOS/MSC                                                                                        | 23-Nov-22 | O/C      |          |                           |           |           |                          |
|                                         | HRS                                                                                            | 6482.7    |          |          |                           |           |           |                          |
|                                         | AFL                                                                                            | 3897      |          |          |                           |           |           |                          |
| 151000 <sup>U</sup>                     | FLIGHT MANUAL CURRENCY REVIEW                                                                  |           |          |          |                           |           |           | Service ATA:00           |
|                                         | MOS                                                                                            | 10-Dec-22 | 12       |          | 10-Dec-23                 |           | 313 d     |                          |
|                                         | HRS                                                                                            | 6488.1    |          |          |                           |           |           |                          |
|                                         | AFL                                                                                            | 3901      |          |          |                           |           |           |                          |
| BCXP-160901                             | REVIEW HAWKER 750/800XP/850XP/900XP AFMS REVISION 32 DATED SEP.16 REVISION SUMMARY CHANGE FORM |           |          |          |                           |           |           | Service ATA:00           |
|                                         | MOS/MSC                                                                                        | 22-Jul-21 | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                                         | HRS                                                                                            | 6077.4    |          |          |                           |           |           |                          |
|                                         | AFL                                                                                            | 3596      |          |          |                           |           |           |                          |
| PROC. REF: RCF BCXP                     |                                                                                                |           |          |          |                           |           |           |                          |
| ATA 02 - RESERVED FOR AIRLINE USE       |                                                                                                |           |          |          |                           |           |           |                          |
| 020001 <sup>U</sup>                     | MANAGEMENT AGREEMENT                                                                           |           |          |          |                           |           |           | Service ATA:02           |
|                                         | MOS                                                                                            | 22-Dec-22 | 24       |          | 02-Jan-25 (M)             |           | 702 d     |                          |
|                                         | HRS                                                                                            | 6495.5    |          |          |                           |           |           |                          |
|                                         | AFL                                                                                            | 3906      |          |          |                           |           |           |                          |
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS |                                                                                                |           |          |          |                           |           |           |                          |
| 050001                                  | INSPECTION PRE-FLIGHT                                                                          |           |          |          |                           |           |           | Service ATA:05           |
|                                         | MOS/MSC                                                                                        | 06-Jan-23 | A/R      |          |                           |           |           |                          |
|                                         | HRS                                                                                            | 6519.5    |          |          |                           |           |           |                          |
| WC#: 05.T01                             | AFL                                                                                            | 3923      |          |          |                           |           |           |                          |
| PROC. REF: AFMS 05-00-00                |                                                                                                |           |          |          |                           |           |           |                          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                                                 | Unit                                                | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|-----------------------------------------------------------------------------------------|-----------------------------------------------------|-----------|---------------|----------|---------------------------|-----------|-----------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS                                                 |                                                     |           |               |          |                           |           |           |                |
| 050005                                                                                  | INSPECTION POST FLIGHT                              |           |               |          |                           |           |           | Service ATA:05 |
|                                                                                         | MOS/MSC                                             | 06-Jan-23 | A/R           |          |                           |           |           |                |
|                                                                                         | HRS                                                 | 6519.5    |               |          |                           |           |           |                |
| WC#: 05.T02                                                                             | AFL                                                 | 3923      |               |          |                           |           |           |                |
| PROC. REF: AFMS 05-00-00                                                                |                                                     |           |               |          |                           |           |           |                |
| 050010 <sup>U</sup>                                                                     | KLM AVIATION- EMERGENCY EQUIPMENT VISUAL INSPECTION |           |               |          |                           |           |           | Package ATA:05 |
|                                                                                         | DAYS                                                | 22-Dec-22 | 60            |          | 21-Feb-23 (M)             |           | 21 d      |                |
|                                                                                         | HRS                                                 | 6495.5    |               |          |                           |           |           |                |
|                                                                                         | AFL                                                 | 3906      |               |          |                           |           |           |                |
| PKG:68                                                                                  |                                                     |           |               |          |                           |           |           |                |
| 050110                                                                                  | INSPECTION B1-B12 COMPLETE                          |           |               |          |                           |           |           | Package ATA:05 |
|                                                                                         | MOS                                                 | 15-Oct-19 |               |          |                           |           |           |                |
|                                                                                         | HRS                                                 | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)  |                |
|                                                                                         | AFL                                                 | 3397      |               |          |                           |           |           |                |
| PKG:2<br>WO#: N950PC B & C CHECK                                                        |                                                     |           |               |          |                           |           |           |                |
| 050141                                                                                  | INSPECT AREA F1-800 HOURS                           |           |               |          |                           |           |           | Service ATA:05 |
|                                                                                         | MOS                                                 | 15-Oct-19 |               |          |                           |           |           |                |
|                                                                                         | HRS                                                 | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)  |                |
| WC#: 05.203                                                                             | AFL                                                 | 3397      |               |          |                           |           |           |                |
| PROC. REF: AFMS INTRODUCTION, AFMS INSPECTION B3<br>PKG:2,10<br>WO#: N950PC B & C CHECK |                                                     |           |               |          |                           |           |           |                |
| 050171                                                                                  | INSPECT AREA F3 ABOVE FLOOR-800 HOURS               |           |               |          |                           |           |           | Service ATA:05 |
|                                                                                         | MOS                                                 | 15-Oct-19 |               |          |                           |           |           |                |
|                                                                                         | HRS                                                 | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)  |                |
| WC#: 05.206                                                                             | AFL                                                 | 3397      |               |          |                           |           |           |                |
| PROC. REF: AFMS INTRODUCTION, AFMS INSPECTION B6<br>PKG:2,13<br>WO#: N950PC B & C CHECK |                                                     |           |               |          |                           |           |           |                |
| 050181                                                                                  | INSPECT AREA F4-800 HOURS                           |           |               |          |                           |           |           | Service ATA:05 |
|                                                                                         | MOS                                                 | 15-Oct-19 |               |          |                           |           |           |                |
|                                                                                         | HRS                                                 | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)  |                |
| WC#: 05.207                                                                             | AFL                                                 | 3397      |               |          |                           |           |           |                |
| PROC. REF: AFMS INTRODUCTION, AFMS INSPECTION B7<br>PKG:2,14<br>WO#: N950PC B & C CHECK |                                                     |           |               |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                           | Unit                         | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition                         |
|---------------------------------------------------|------------------------------|-----------|----------------|----------|---------------------------|-----------|-------------|-------------------------------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS           |                              |           |                |          |                           |           |             |                                     |
| 050191                                            | INSPECT AREA T1-800 HOURS    |           |                |          |                           |           |             | Service ATA:05                      |
|                                                   | MOS                          | 15-Oct-19 |                |          |                           |           |             |                                     |
|                                                   | HRS                          | 5795.3    | 800 (+40/-10)  |          | 6595.3                    | 6635.3    | 67 (+40)    |                                     |
| WC#: 05.208                                       | AFL                          | 3397      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INTRODUCTION, AFMS INSPECTION B8  |                              |           |                |          |                           |           |             | PKG:2,15<br>WO#: N950PC B & C CHECK |
| 050201                                            | INSPECT AREA W1-800 HOURS    |           |                |          |                           |           |             | Service ATA:05                      |
|                                                   | MOS                          | 15-Oct-19 |                |          |                           |           |             |                                     |
|                                                   | HRS                          | 5795.3    | 800 (+40/-10)  |          | 6595.3                    | 6635.3    | 67 (+40)    |                                     |
| WC#: 05.209                                       | AFL                          | 3397      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INTRODUCTION, AFMS INSPECTION B9  |                              |           |                |          |                           |           |             | PKG:2,16<br>WO#: N950PC B & C CHECK |
| 050211                                            | INSPECT AREA W2-800 HOURS    |           |                |          |                           |           |             | Service ATA:05                      |
|                                                   | MOS                          | 15-Oct-19 |                |          |                           |           |             |                                     |
|                                                   | HRS                          | 5795.3    | 800 (+40/-10)  |          | 6595.3                    | 6635.3    | 67 (+40)    |                                     |
| WC#: 05.210                                       | AFL                          | 3397      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INTRODUCTION, AFMS INSPECTION B10 |                              |           |                |          |                           |           |             | PKG:2,17<br>WO#: N950PC B & C CHECK |
| 050221                                            | INSPECT AREA M1/M2-800 HOURS |           |                |          |                           |           |             | Service ATA:05                      |
|                                                   | MOS                          | 15-Oct-19 |                |          |                           |           |             |                                     |
|                                                   | HRS                          | 5795.3    | 800 (+40/-10)  |          | 6595.3                    | 6635.3    | 67 (+40)    |                                     |
| WC#: 05.211                                       | AFL                          | 3397      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INTRODUCTION, AFMS INSPECTION B11 |                              |           |                |          |                           |           |             | PKG:2,18<br>WO#: N950PC B & C CHECK |
| 050231                                            | INSPECT AREA G-800 HOURS     |           |                |          |                           |           |             | Service ATA:05                      |
|                                                   | MOS                          | 15-Oct-19 |                |          |                           |           |             |                                     |
|                                                   | HRS                          | 5795.3    | 800 (+40/-10)  |          | 6595.3                    | 6635.3    | 67 (+40)    |                                     |
| WC#: 05.212                                       | AFL                          | 3397      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INTRODUCTION, AFMS INSPECTION B12 |                              |           |                |          |                           |           |             | PKG:2,19<br>WO#: N950PC B & C CHECK |
| 050240                                            | INSPECTION C1-C12 COMPLETE   |           |                |          |                           |           |             | Package ATA:05                      |
|                                                   | MOS                          | 06-May-15 |                |          |                           |           |             |                                     |
|                                                   | HRS                          | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
|                                                   | AFL                          | 2873      |                |          |                           |           |             |                                     |
|                                                   |                              |           |                |          |                           |           |             | PKG:3<br>WO#: N950PC B & C CHECK    |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                          | Unit                                    | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition                         |
|--------------------------------------------------|-----------------------------------------|-----------|----------------|----------|---------------------------|-----------|-------------|-------------------------------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS          |                                         |           |                |          |                           |           |             |                                     |
| 050271                                           | INSPECT AREA F1-1600 HOURS              |           |                |          |                           |           |             | Service ATA:05                      |
|                                                  | MOS                                     | 06-May-15 |                |          |                           |           |             |                                     |
|                                                  | HRS                                     | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 05.303                                      | AFL                                     | 2873      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INTRODUCTION, AFMS INSPECTION C3 |                                         |           |                |          |                           |           |             | PKG:3,22<br>WO#: N950PC B & C CHECK |
| 050281                                           | INSPECT AREA F2-1600 HOURS              |           |                |          |                           |           |             | Service ATA:05                      |
|                                                  | MOS                                     | 06-May-15 |                |          |                           |           |             |                                     |
|                                                  | HRS                                     | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 05.304                                      | AFL                                     | 2873      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INTRODUCTION, AFMS INSPECTION C4 |                                         |           |                |          |                           |           |             | PKG:3,23<br>WO#: N950PC B & C CHECK |
| 050291                                           | INSPECT AREA F3 UNDERFLOOR-1600 HOURS   |           |                |          |                           |           |             | Service ATA:05                      |
|                                                  | MOS                                     | 06-May-15 |                |          |                           |           |             |                                     |
|                                                  | HRS                                     | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 05.305                                      | AFL                                     | 2873      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INTRODUCTION, AFMS INSPECTION C5 |                                         |           |                |          |                           |           |             | PKG:3,24<br>WO#: N950PC B & C CHECK |
| 050301                                           | INSPECT AREA F3- ABOVE FLOOR-1600 HOURS |           |                |          |                           |           |             | Service ATA:05                      |
|                                                  | MOS                                     | 06-May-15 |                |          |                           |           |             |                                     |
|                                                  | HRS                                     | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 05.306                                      | AFL                                     | 2873      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INTRODUCTION, AFMS INSPECTION C6 |                                         |           |                |          |                           |           |             | PKG:3,25<br>WO#: N950PC B & C CHECK |
| 050311                                           | INSPECT AREA F4-1600 HOURS              |           |                |          |                           |           |             | Service ATA:05                      |
|                                                  | MOS                                     | 06-May-15 |                |          |                           |           |             |                                     |
|                                                  | HRS                                     | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 05.307                                      | AFL                                     | 2873      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INSPECTION C7, AFMS INTRODUCTION |                                         |           |                |          |                           |           |             | PKG:3,26<br>WO#: N950PC B & C CHECK |
| 050321                                           | INSPECT AREA T1-1600 HOURS              |           |                |          |                           |           |             | Service ATA:05                      |
|                                                  | MOS                                     | 06-May-15 |                |          |                           |           |             |                                     |
|                                                  | HRS                                     | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 05.308                                      | AFL                                     | 2873      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INSPECTION C8                    |                                         |           |                |          |                           |           |             | PKG:3,27<br>WO#: N950PC B & C CHECK |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                           | Unit                          | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition                         |
|---------------------------------------------------|-------------------------------|-----------|-----------------|----------|---------------------------|-----------|---------------|-------------------------------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS           |                               |           |                 |          |                           |           |               |                                     |
| 050331                                            | INSPECT AREA W1-1600 HOURS    |           |                 |          |                           |           |               | Service ATA:05                      |
|                                                   | MOS                           | 06-May-15 |                 |          |                           |           |               |                                     |
|                                                   | HRS                           | 5125.6    | 1600 (+50/-50)  |          | 6725.6                    | 6775.6    | 197.3 (+50)   |                                     |
| WC#: 05.309                                       | AFL                           | 2873      |                 |          |                           |           |               |                                     |
| PROC. REF: AFMS INTRODUCTION, AFMS INSPECTION C9  |                               |           |                 |          |                           |           |               | PKG:3,28<br>WO#: N950PC B & C CHECK |
| 050341                                            | INSPECT AREA W2-1600 HOURS    |           |                 |          |                           |           |               | Service ATA:05                      |
|                                                   | MOS                           | 06-May-15 |                 |          |                           |           |               |                                     |
|                                                   | HRS                           | 5125.6    | 1600 (+50/-50)  |          | 6725.6                    | 6775.6    | 197.3 (+50)   |                                     |
| WC#: 05.310                                       | AFL                           | 2873      |                 |          |                           |           |               |                                     |
| PROC. REF: AFMS INTRODUCTION, AFMS INSPECTION C10 |                               |           |                 |          |                           |           |               | PKG:3,29<br>WO#: N950PC B & C CHECK |
| 050351                                            | INSPECT AREA M1/M2-1600 HOURS |           |                 |          |                           |           |               | Service ATA:05                      |
|                                                   | MOS                           | 06-May-15 |                 |          |                           |           |               |                                     |
|                                                   | HRS                           | 5125.6    | 1600 (+50/-50)  |          | 6725.6                    | 6775.6    | 197.3 (+50)   |                                     |
| WC#: 05.311                                       | AFL                           | 2873      |                 |          |                           |           |               |                                     |
| PROC. REF: AFMS INTRODUCTION, AFMS INSPECTION C11 |                               |           |                 |          |                           |           |               | PKG:3,30<br>WO#: N950PC B & C CHECK |
| 050361                                            | INSPECT AREA G-1600 HOURS     |           |                 |          |                           |           |               | Service ATA:05                      |
|                                                   | MOS                           | 06-May-15 |                 |          |                           |           |               |                                     |
|                                                   | HRS                           | 5125.6    | 1600 (+50/-50)  |          | 6725.6                    | 6775.6    | 197.3 (+50)   |                                     |
| WC#: 05.312                                       | AFL                           | 2873      |                 |          |                           |           |               |                                     |
| PROC. REF: AFMS INTRODUCTION, AFMS INSPECTION C12 |                               |           |                 |          |                           |           |               | PKG:3,31<br>WO#: N950PC B & C CHECK |
| 050370                                            | INSPECTION D1-D12 COMPLETE    |           |                 |          |                           |           |               | Package ATA:05                      |
|                                                   | MOS                           | 18-Aug-17 |                 |          |                           |           |               |                                     |
|                                                   | HRS                           | 5554.6    | 3200 (+150/-50) |          | 8754.6                    | 8904.6    | 2226.3 (+150) |                                     |
|                                                   | AFL                           | 3197      |                 |          |                           |           |               |                                     |
|                                                   |                               |           |                 |          |                           |           |               | PKG:4                               |
| 050411                                            | INSPECT AREA F2-3200 HOURS    |           |                 |          |                           |           |               | Service ATA:05                      |
|                                                   | MOS                           | 18-Aug-17 |                 |          |                           |           |               |                                     |
|                                                   | HRS                           | 5554.6    | 3200 (+150/-50) |          | 8754.6                    | 8904.6    | 2226.3 (+150) |                                     |
| WC#: 05.404                                       | AFL                           | 3197      |                 |          |                           |           |               |                                     |
| PROC. REF: AFMS INTRODUCTION, AFMS INSPECTION D4  |                               |           |                 |          |                           |           |               | PKG:4,35                            |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                           | Unit                                   | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                             | Disposition    |
|---------------------------------------------------|----------------------------------------|-----------|-----------------|----------|---------------------------|-----------|---------------------------------------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS           |                                        |           |                 |          |                           |           |                                       |                |
| 050431                                            | INSPECT AREA F3 ABOVE FLOOR-3200 HOURS |           |                 |          |                           |           |                                       | Service ATA:05 |
|                                                   | MOS                                    | 18-Aug-17 |                 |          |                           |           |                                       |                |
|                                                   | HRS                                    | 5554.6    | 3200 (+150/-50) |          | 8754.6                    | 8904.6    | 2226.3 (+150)                         |                |
| WC#: 05.406                                       | AFL                                    | 3197      |                 |          |                           |           |                                       |                |
| PROC. REF: AFMS INTRODUCTION, AFMS INSPECTION D6  |                                        |           |                 |          |                           |           | PKG:4,37                              |                |
| 050441                                            | INSPECT AREA F4-3200 HOURS             |           |                 |          |                           |           |                                       | Service ATA:05 |
|                                                   | MOS                                    | 18-Aug-17 |                 |          |                           |           |                                       |                |
|                                                   | HRS                                    | 5554.6    | 3200 (+150/-50) |          | 8754.6                    | 8904.6    | 2226.3 (+150)                         |                |
| WC#: 05.407                                       | AFL                                    | 3197      |                 |          |                           |           |                                       |                |
| PROC. REF: AFMS INTRODUCTION, AFMS INSPECTION D7  |                                        |           |                 |          |                           |           | PKG:4,38                              |                |
| 050491                                            | INSPECT AREA G-3200 HOURS              |           |                 |          |                           |           |                                       | Service ATA:05 |
|                                                   | MOS                                    | 18-Aug-17 |                 |          |                           |           |                                       |                |
|                                                   | HRS                                    | 5554.6    | 3200 (+150/-50) |          | 8754.6                    | 8904.6    | 2226.3 (+150)                         |                |
| WC#: 05.412                                       | AFL                                    | 3197      |                 |          |                           |           |                                       |                |
| PROC. REF: AFMS INTRODUCTION, AFMS INSPECTION D12 |                                        |           |                 |          |                           |           | PKG:4,43                              |                |
| 050500                                            | INSPECTION E1-E12 COMPLETE             |           |                 |          |                           |           |                                       | Package ATA:05 |
|                                                   | MOS                                    | 11-Oct-22 | 12 (+1m/-1m)    |          | 11-Oct-23                 | 11-Nov-23 | 253 d (+31)                           |                |
|                                                   | HRS                                    | 6446.4    |                 |          |                           |           |                                       |                |
|                                                   | AFL                                    | 3873      |                 |          |                           |           |                                       |                |
|                                                   |                                        |           |                 |          |                           |           | PKG:5<br>WO#: N950PC 48 MONTH INSP    |                |
| 050571                                            | INSPECT AREA F4-12 MONTHS              |           |                 |          |                           |           |                                       | Service ATA:05 |
|                                                   | MOS                                    | 11-Oct-22 | 12 (+1m/-1m)    |          | 11-Oct-23                 | 11-Nov-23 | 253 d (+31)                           |                |
|                                                   | HRS                                    | 6446.4    |                 |          |                           |           |                                       |                |
| WC#: 05.506                                       | AFL                                    | 3873      |                 |          |                           |           |                                       |                |
| PROC. REF: AFMS INTRODUCTION, AFMS INSPECTION E7  |                                        |           |                 |          |                           |           | PKG:5,50<br>WO#: N950PC 48 MONTH INSP |                |
| 050630                                            | INSPECTION F1-F12 COMPLETE             |           |                 |          |                           |           |                                       | Package ATA:05 |
|                                                   | MOS                                    | 11-Oct-22 | 24 (+2m/-2m)    |          | 11-Oct-24                 | 11-Dec-24 | 619 d (+61)                           |                |
|                                                   | HRS                                    | 6446.4    |                 |          |                           |           |                                       |                |
|                                                   | AFL                                    | 3873      |                 |          |                           |           |                                       |                |
|                                                   |                                        |           |                 |          |                           |           | PKG:6<br>WO#: N950PC 48 MONTH INSP    |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                           | Unit                      | C/W       | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                             | Disposition    |
|---------------------------------------------------|---------------------------|-----------|--------------|----------|---------------------------|-----------|---------------------------------------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS           |                           |           |              |          |                           |           |                                       |                |
| 050661                                            | INSPECT AREA F1-24 MONTHS |           |              |          |                           |           |                                       | Service ATA:05 |
|                                                   | MOS                       | 11-Oct-22 | 24 (+2m/-2m) |          | 11-Oct-24                 | 11-Dec-24 | 619 d (+61)                           |                |
|                                                   | HRS                       | 6446.4    |              |          |                           |           |                                       |                |
| WC#: 05.603                                       | AFL                       | 3873      |              |          |                           |           |                                       |                |
| PROC. REF: AFMS INTRODUCTION, AFMS INSPECTION F3  |                           |           |              |          |                           |           | PKG:6,58<br>WO#: N950PC 48 MONTH INSP |                |
| 050671                                            | INSPECT AREA F2-24 MONTHS |           |              |          |                           |           |                                       | Service ATA:05 |
|                                                   | MOS                       | 11-Oct-22 | 24 (+2m/-2m) |          | 11-Oct-24                 | 11-Dec-24 | 619 d (+61)                           |                |
|                                                   | HRS                       | 6446.4    |              |          |                           |           |                                       |                |
| WC#: 05.604                                       | AFL                       | 3873      |              |          |                           |           |                                       |                |
| PROC. REF: AFMS INTRODUCTION, AFMS INSPECTION F4  |                           |           |              |          |                           |           | PKG:6,59<br>WO#: N950PC 48 MONTH INSP |                |
| 050691                                            | INSPECT AREA F3-24 MONTHS |           |              |          |                           |           |                                       | Service ATA:05 |
|                                                   | MOS                       | 11-Oct-22 | 24 (+2m/-2m) |          | 11-Oct-24                 | 11-Dec-24 | 619 d (+61)                           |                |
|                                                   | HRS                       | 6446.4    |              |          |                           |           |                                       |                |
| WC#: 05.606                                       | AFL                       | 3873      |              |          |                           |           |                                       |                |
| PROC. REF: AFMS INTRODUCTION, AFMS INSPECTION F6  |                           |           |              |          |                           |           | PKG:6,61<br>WO#: N950PC 48 MONTH INSP |                |
| 050701                                            | INSPECT AREA F4-24 MONTHS |           |              |          |                           |           |                                       | Service ATA:05 |
|                                                   | MOS                       | 11-Oct-22 | 24 (+2m/-2m) |          | 11-Oct-24                 | 11-Dec-24 | 619 d (+61)                           |                |
|                                                   | HRS                       | 6446.4    |              |          |                           |           |                                       |                |
| WC#: 05.607                                       | AFL                       | 3873      |              |          |                           |           |                                       |                |
| PROC. REF: AFMS INTRODUCTION, AFMS INSPECTION F7  |                           |           |              |          |                           |           | PKG:6,62<br>WO#: N950PC 48 MONTH INSP |                |
| 050721                                            | INSPECT AREA W1-24 MONTHS |           |              |          |                           |           |                                       | Service ATA:05 |
|                                                   | MOS                       | 11-Oct-22 | 24 (+2m/-2m) |          | 11-Oct-24                 | 11-Dec-24 | 619 d (+61)                           |                |
|                                                   | HRS                       | 6446.4    |              |          |                           |           |                                       |                |
| WC#: 05.609                                       | AFL                       | 3873      |              |          |                           |           |                                       |                |
| PROC. REF: AFMS INTRODUCTION, AFMS INSPECTION F9  |                           |           |              |          |                           |           | PKG:6,64<br>WO#: N950PC 48 MONTH INSP |                |
| 050731                                            | INSPECT AREA W2-24 MONTHS |           |              |          |                           |           |                                       | Service ATA:05 |
|                                                   | MOS                       | 11-Oct-22 | 24 (+2m/-2m) |          | 11-Oct-24                 | 11-Dec-24 | 619 d (+61)                           |                |
|                                                   | HRS                       | 6446.4    |              |          |                           |           |                                       |                |
| WC#: 05.610                                       | AFL                       | 3873      |              |          |                           |           |                                       |                |
| PROC. REF: AFMS INTRODUCTION, AFMS INSPECTION F10 |                           |           |              |          |                           |           | PKG:6,65<br>WO#: N950PC 48 MONTH INSP |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                           | Unit                      | C/W       | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                             | Disposition    |
|---------------------------------------------------|---------------------------|-----------|--------------|----------|---------------------------|-----------|---------------------------------------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS           |                           |           |              |          |                           |           |                                       |                |
| 050751                                            | INSPECT AREA G-24 MONTHS  |           |              |          |                           |           |                                       | Service ATA:05 |
|                                                   | MOS                       | 11-Oct-22 | 24 (+2m/-2m) |          | 11-Oct-24                 | 11-Dec-24 | 619 d (+61)                           |                |
|                                                   | HRS                       | 6446.4    |              |          |                           |           |                                       |                |
| WC#: 05.612                                       | AFL                       | 3873      |              |          |                           |           |                                       |                |
| PROC. REF: AFMS INTRODUCTION, AFMS INSPECTION F12 |                           |           |              |          |                           |           | PKG:6,67<br>WO#: N950PC 48 MONTH INSP |                |
| 050760                                            | INSPECTION G COMPLETE     |           |              |          |                           |           |                                       | Package ATA:05 |
|                                                   | MOS                       | 15-Oct-19 | 48 (+2m/-2m) |          | 15-Oct-23                 | 15-Dec-23 | 257 d (+61)                           |                |
|                                                   | HRS                       | 5795.3    |              |          |                           |           |                                       |                |
|                                                   | AFL                       | 3397      |              |          |                           |           |                                       |                |
|                                                   |                           |           |              |          |                           |           | PKG:7<br>WO#: N950PC 48 MONTH INSP    |                |
| 050761                                            | INSPECT AREA F1-48 MONTHS |           |              |          |                           |           |                                       | Service ATA:05 |
|                                                   | MOS                       | 15-Oct-19 | 48 (+2m/-2m) |          | 15-Oct-23                 | 15-Dec-23 | 257 d (+61)                           |                |
|                                                   | HRS                       | 5795.3    |              |          |                           |           |                                       |                |
| WC#: 05.703                                       | AFL                       | 3397      |              |          |                           |           |                                       |                |
| PROC. REF: AFMS INTRODUCTION, AFMS INSPECTION G   |                           |           |              |          |                           |           | PKG:7<br>WO#: N950PC 48 MONTH INSP    |                |
| 050762                                            | INSPECT AREA F2-48 MONTHS |           |              |          |                           |           |                                       | Service ATA:05 |
|                                                   | MOS                       | 15-Oct-19 | 48 (+2m/-2m) |          | 15-Oct-23                 | 15-Dec-23 | 257 d (+61)                           |                |
|                                                   | HRS                       | 5795.3    |              |          |                           |           |                                       |                |
| WC#: 05.704                                       | AFL                       | 3397      |              |          |                           |           |                                       |                |
| PROC. REF: AFMS INTRODUCTION, AFMS INSPECTION G   |                           |           |              |          |                           |           | PKG:7<br>WO#: N950PC 48 MONTH INSP    |                |
| 050763                                            | INSPECT AREA F3-48 MONTHS |           |              |          |                           |           |                                       | Service ATA:05 |
|                                                   | MOS                       | 15-Oct-19 | 48 (+2m/-2m) |          | 15-Oct-23                 | 15-Dec-23 | 257 d (+61)                           |                |
|                                                   | HRS                       | 5795.3    |              |          |                           |           |                                       |                |
| WC#: 05.705                                       | AFL                       | 3397      |              |          |                           |           |                                       |                |
| PROC. REF: AFMS INTRODUCTION, AFMS INSPECTION G   |                           |           |              |          |                           |           | PKG:7<br>WO#: N950PC 48 MONTH INSP    |                |
| 050764                                            | INSPECT AREA F4-48 MONTHS |           |              |          |                           |           |                                       | Service ATA:05 |
|                                                   | MOS                       | 15-Oct-19 | 48 (+2m/-2m) |          | 15-Oct-23                 | 15-Dec-23 | 257 d (+61)                           |                |
|                                                   | HRS                       | 5795.3    |              |          |                           |           |                                       |                |
| WC#: 05.707                                       | AFL                       | 3397      |              |          |                           |           |                                       |                |
| PROC. REF: AFMS INTRODUCTION, AFMS INSPECTION G   |                           |           |              |          |                           |           | PKG:7<br>WO#: N950PC 48 MONTH INSP    |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                               | Unit                                                        | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                          | Disposition    |
|-----------------------------------------------------------------------|-------------------------------------------------------------|-----------|---------------|----------|---------------------------|-----------|------------------------------------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS                               |                                                             |           |               |          |                           |           |                                    |                |
| 050765                                                                | INSPECT AREA T1-48 MONTHS                                   |           |               |          |                           |           |                                    | Service ATA:05 |
|                                                                       | MOS                                                         | 15-Oct-19 | 48 (+2m/-2m)  |          | 15-Oct-23                 | 15-Dec-23 | 257 d (+61)                        |                |
|                                                                       | HRS                                                         | 5795.3    |               |          |                           |           |                                    |                |
| WC#: 05.708                                                           | AFL                                                         | 3397      |               |          |                           |           |                                    |                |
| PROC. REF: AFMS INTRODUCTION, AFMS INSPECTION G                       |                                                             |           |               |          |                           |           | PKG:7<br>WO#: N950PC 48 MONTH INSP |                |
| 050766                                                                | INSPECT AREA W1/W2-48 MONTHS                                |           |               |          |                           |           |                                    | Service ATA:05 |
|                                                                       | MOS                                                         | 15-Oct-19 | 48 (+2m/-2m)  |          | 15-Oct-23                 | 15-Dec-23 | 257 d (+61)                        |                |
|                                                                       | HRS                                                         | 5795.3    |               |          |                           |           |                                    |                |
| WC#: 05.709                                                           | AFL                                                         | 3397      |               |          |                           |           |                                    |                |
| PROC. REF: AFMS INTRODUCTION, AFMS INSPECTION G                       |                                                             |           |               |          |                           |           | PKG:7<br>WO#: N950PC 48 MONTH INSP |                |
| 050771                                                                | INSPECTION 400 HOUR DETAILED WALK-AROUND                    |           |               |          |                           |           |                                    | Service ATA:05 |
|                                                                       | MOS                                                         | 11-Oct-22 |               |          |                           |           |                                    |                |
|                                                                       | HRS                                                         | 6446.4    | 400 (+40/-10) |          | 6846.4                    | 6886.4    | 318.1 (+40)                        |                |
| WC#: 05.100                                                           | AFL                                                         | 3873      |               |          |                           |           |                                    |                |
| PROC. REF: MMA 400 HR, AFMS 400 HR DETAILED WALK-AROUND, AMM 05-00-00 |                                                             |           |               |          |                           |           |                                    |                |
| 055005                                                                | ACCOMPLISH INSPECTIONS AFTER AN OVERWEIGHT OR HEAVY LANDING |           |               |          |                           |           |                                    | Service ATA:05 |
|                                                                       | MOS/MSC                                                     | 30-May-96 | A/R           |          |                           |           |                                    |                |
|                                                                       | HRS                                                         | 0         |               |          |                           |           |                                    |                |
| WC#: 05.710                                                           | AFL                                                         | 0         |               |          |                           |           |                                    |                |
| PROC. REF: AFMS HEAVY LANDING INSPECTION                              |                                                             |           |               |          |                           |           |                                    |                |
| 055010                                                                | ACCOMPLISH INSPECTIONS AFTER FLIGHT IN HEAVY TURBULENCE     |           |               |          |                           |           |                                    | Service ATA:05 |
|                                                                       | MOS/MSC                                                     | 30-May-96 | A/R           |          |                           |           |                                    |                |
|                                                                       | HRS                                                         | 0         |               |          |                           |           |                                    |                |
| WC#: 05.711                                                           | AFL                                                         | 0         |               |          |                           |           |                                    |                |
| PROC. REF: AFMS TURBULENCE                                            |                                                             |           |               |          |                           |           |                                    |                |
| 055015                                                                | ACCOMPLISH INSPECTIONS AFTER A LIGHTNING STRIKE             |           |               |          |                           |           |                                    | Service ATA:05 |
|                                                                       | MOS/MSC                                                     | 30-May-96 | A/R           |          |                           |           |                                    |                |
|                                                                       | HRS                                                         | 0         |               |          |                           |           |                                    |                |
| WC#: 05.712                                                           | AFL                                                         | 0         |               |          |                           |           |                                    |                |
| PROC. REF: AFMS LIGHTNING STRIKE INSPECTION                           |                                                             |           |               |          |                           |           |                                    |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                   | Unit                                                                                          | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|-------------------------------------------|-----------------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS   |                                                                                               |           |          |          |                           |           |           |                |
| 055035                                    | ACCOMPLISH INSPECTIONS AFTER A COLD SOAK BELOW -40 DEGREE C                                   |           |          |          |                           |           |           | Service ATA:05 |
|                                           | MOS/MSC                                                                                       | 30-May-96 | A/R      |          |                           |           |           |                |
|                                           | HRS                                                                                           | 0         |          |          |                           |           |           |                |
| WC#: 05.713                               | AFL                                                                                           | 0         |          |          |                           |           |           |                |
| 055040                                    | ACCOMPLISH INSPECTIONS AFTER MISUSE OF REVERSE THRUST                                         |           |          |          |                           |           |           | Service ATA:05 |
|                                           | MOS/MSC                                                                                       | 30-May-96 | A/R      |          |                           |           |           |                |
|                                           | HRS                                                                                           | 0         |          |          |                           |           |           |                |
| WC#: 05.714                               | AFL                                                                                           | 0         |          |          |                           |           |           |                |
| PROC. REF: AFMS REVERSE THRUST INSPECTION |                                                                                               |           |          |          |                           |           |           |                |
| 055045                                    | ACCOMPLISH INSPECTIONS AFTER LANDING GEAR VIBRATION                                           |           |          |          |                           |           |           | Service ATA:05 |
|                                           | MOS/MSC                                                                                       | 30-May-96 | A/R      |          |                           |           |           |                |
|                                           | HRS                                                                                           | 0         |          |          |                           |           |           |                |
| WC#: 05.715                               | AFL                                                                                           | 0         |          |          |                           |           |           |                |
| PROC. REF: AFMS VIBRATION INSP.           |                                                                                               |           |          |          |                           |           |           |                |
| 055050                                    | ACCOMPLISH INSPECTIONS AFTER LANDING OR ABORTED TAKE-OFF IN DEEP WATER PUDDLES, SLUSH OR SNOW |           |          |          |                           |           |           | Service ATA:05 |
|                                           | MOS/MSC                                                                                       | 30-May-96 | A/R      |          |                           |           |           |                |
|                                           | HRS                                                                                           | 0         |          |          |                           |           |           |                |
| WC#: 05.716                               | AFL                                                                                           | 0         |          |          |                           |           |           |                |
| PROC. REF: AFMS SLUSHY RUNWAY INSPECTION  |                                                                                               |           |          |          |                           |           |           |                |
| 055060                                    | ACCOMPLISH INSPECTIONS AFTER AN EMERGENCY STOP                                                |           |          |          |                           |           |           | Service ATA:05 |
|                                           | MOS/MSC                                                                                       | 30-May-96 | A/R      |          |                           |           |           |                |
|                                           | HRS                                                                                           | 0         |          |          |                           |           |           |                |
| WC#: 05.717                               | AFL                                                                                           | 0         |          |          |                           |           |           |                |
| PROC. REF: AFMS EMERGENCY STOP INSPECTION |                                                                                               |           |          |          |                           |           |           |                |
| 055065                                    | ACCOMPLISH INSPECTIONS AFTER ABNORMAL APU CONDITIONS                                          |           |          |          |                           |           |           | Service ATA:05 |
|                                           | MOS/MSC                                                                                       | 30-May-96 | A/R      |          |                           |           |           |                |
|                                           | HRS                                                                                           | 0         |          |          |                           |           |           |                |
| WC#: 05.718                               | AFL                                                                                           | 0         |          |          |                           |           |           |                |
| PROC. REF: AFMS ABNORMAL APU INSPECTION   |                                                                                               |           |          |          |                           |           |           |                |
| 055070                                    | ACCOMPLISH INSPECTIONS AFTER FLAP OVERSPEED                                                   |           |          |          |                           |           |           | Service ATA:05 |
|                                           | MOS/MSC                                                                                       | 30-May-96 | A/R      |          |                           |           |           |                |
|                                           | HRS                                                                                           | 0         |          |          |                           |           |           |                |
| WC#: 05.719                               | AFL                                                                                           | 0         |          |          |                           |           |           |                |
| PROC. REF: AFMS FLAP OVERSPEED            |                                                                                               |           |          |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                 | Unit                                                                               | C/W       | Interval   | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                                              | Disposition    |
|-----------------------------------------|------------------------------------------------------------------------------------|-----------|------------|----------|---------------------------|-----------|--------------------------------------------------------|----------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS |                                                                                    |           |            |          |                           |           |                                                        |                |
| 055075                                  | ACCOMPLISH INSPECTIONS AFTER EXPOSURE TO VOLCANIC ASH                              |           |            |          |                           |           |                                                        | Service ATA:05 |
|                                         | MOS/MSC                                                                            | 30-May-96 | A/R        |          |                           |           |                                                        |                |
|                                         | HRS                                                                                | 0         |            |          |                           |           |                                                        |                |
| WC#: 05.720                             | AFL                                                                                | 0         |            |          |                           |           |                                                        |                |
| PROC. REF: AFMS VOLCANIC ASH            |                                                                                    |           |            |          |                           |           |                                                        |                |
| 055080                                  | ACCOMPLISH INSPECTIONS FOR HYDRAULIC CONTAMINATION OF THE CABIN VENTILATION SYSTEM |           |            |          |                           |           |                                                        | Service ATA:05 |
|                                         | MOS/MSC                                                                            | 30-May-96 | A/R        |          |                           |           |                                                        |                |
|                                         | HRS                                                                                | 0         |            |          |                           |           |                                                        |                |
|                                         | AFL                                                                                | 0         |            |          |                           |           |                                                        |                |
| 055090                                  | ACCOMPLISH AIRCRAFT STORAGE                                                        |           |            |          |                           |           |                                                        | Service ATA:05 |
|                                         | MOS/MSC                                                                            | 30-May-96 | A/R        |          |                           |           |                                                        |                |
|                                         | HRS                                                                                | 0         |            |          |                           |           |                                                        |                |
|                                         | AFL                                                                                | 0         |            |          |                           |           |                                                        |                |
| 057110                                  | NO. 1 ENGINE - 150 TO 250 HOUR INSPECTION                                          |           |            |          |                           |           |                                                        | Package ATA:05 |
|                                         | MOS                                                                                | 11-Oct-22 |            |          |                           |           |                                                        |                |
|                                         | HRS                                                                                | 6450.1    | 150 (+100) |          | (6600.1)<br>6596.9        | 6700.1    | 68.6 (+100)                                            |                |
|                                         | ENC                                                                                | 3876      |            |          |                           |           |                                                        |                |
| PROC. REF: LMM 72-00-00                 |                                                                                    |           |            |          |                           |           |                                                        |                |
|                                         |                                                                                    |           |            |          |                           |           | PKG:1<br>WO#: N950PC B & C CHECK,N950PC LH ENG MPI     |                |
| 057110                                  | NO. 2 ENGINE - 150 TO 250 HOUR INSPECTION                                          |           |            |          |                           |           |                                                        | Package ATA:05 |
|                                         | MOS                                                                                | 11-Oct-22 |            |          |                           |           |                                                        |                |
|                                         | HRS                                                                                | 6365.3    | 150 (+100) |          | (6515.3)<br>6596.4        | 6615.3    | 68.1 (+100)                                            |                |
|                                         | ENC                                                                                | 3828      |            |          |                           |           |                                                        |                |
| PROC. REF: LMM 72-00-00                 |                                                                                    |           |            |          |                           |           |                                                        |                |
|                                         |                                                                                    |           |            |          |                           |           | PKG:1<br>WO#: N950PC B & C CHECK,N950PC RH ENG MPI/CZI |                |
| 057120                                  | NO. 1 ENGINE - 300 TO 400 HOUR INSPECTION                                          |           |            |          |                           |           |                                                        | Package ATA:05 |
|                                         | MOS                                                                                | 11-Oct-22 |            |          |                           |           |                                                        |                |
|                                         | HRS                                                                                | 6450.1    | 300 (+100) |          | (6750.1)<br>6746.9        | 6850.1    | 218.6 (+100)                                           |                |
|                                         | ENC                                                                                | 3876      |            |          |                           |           |                                                        |                |
| PROC. REF: LMM 72-00-00                 |                                                                                    |           |            |          |                           |           |                                                        |                |
|                                         |                                                                                    |           |            |          |                           |           | PKG:2<br>WO#: N950PC LH ENG MPI                        |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                 | Unit                                        | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition                         |
|-----------------------------------------|---------------------------------------------|-----------|-------------|----------|---------------------------|-----------|--------------|-------------------------------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS |                                             |           |             |          |                           |           |              |                                     |
| 057120                                  | NO. 2 ENGINE - 300 TO 400 HOUR INSPECTION   |           |             |          |                           |           |              | Package ATA:05                      |
|                                         | MOS                                         | 11-Oct-22 |             |          |                           |           |              |                                     |
|                                         | HRS                                         | 6365.3    | 300 (+100)  |          | (6665.3)<br>6746.4        | 6765.3    | 218.1 (+100) |                                     |
|                                         | ENC                                         | 3828      |             |          |                           |           |              |                                     |
| PROC. REF: LMM 72-00-00                 |                                             |           |             |          |                           |           |              | PKG:2<br>WO#: N950PC RH ENG MPI/CZI |
| 057140                                  | NO. 1 ENGINE - 500 TO 850 HOUR INSPECTION   |           |             |          |                           |           |              | Package ATA:05                      |
|                                         | MOS                                         | 11-Oct-22 |             |          |                           |           |              |                                     |
|                                         | HRS                                         | 6450.1    | 800 (+50)   |          | (7250.1)<br>7246.9        | 7300.1    | 718.6 (+50)  |                                     |
|                                         | ENC                                         | 3876      |             |          |                           |           |              |                                     |
| PROC. REF: LMM 72-00-00, LMM 72-00-00   |                                             |           |             |          |                           |           |              | PKG:4<br>WO#: N950PC LH ENG MPI     |
| 057140                                  | NO. 2 ENGINE - 500 TO 850 HOUR INSPECTION   |           |             |          |                           |           |              | Package ATA:05                      |
|                                         | MOS                                         | 11-Oct-22 |             |          |                           |           |              |                                     |
|                                         | HRS                                         | 6365.3    | 800 (+50)   |          | (7165.3)<br>7246.4        | 7215.3    | 718.1 (+50)  |                                     |
|                                         | ENC                                         | 3828      |             |          |                           |           |              |                                     |
| PROC. REF: LMM 72-00-00, LMM 72-00-00   |                                             |           |             |          |                           |           |              | PKG:4<br>WO#: N950PC RH ENG MPI/CZI |
| 057160                                  | NO. 1 ENGINE - 1000 TO 1400 HOUR INSPECTION |           |             |          |                           |           |              | Package ATA:05                      |
|                                         | MOS                                         | 25-Nov-19 |             |          |                           |           |              |                                     |
|                                         | HRS                                         | 5714      | 1200 (+200) |          | (6914)<br>6910.8          | 7114      | 382.5 (+200) |                                     |
|                                         | ENC                                         |           |             |          |                           |           |              |                                     |
| PROC. REF: LMM 72-00-00, LMM 72-00-00   |                                             |           |             |          |                           |           |              | WO#: N950PC LH ENG MPI              |
| 057160                                  | NO. 2 ENGINE - 1000 TO 1400 HOUR INSPECTION |           |             |          |                           |           |              | Package ATA:05                      |
|                                         | MOS                                         | 05-Nov-19 |             |          |                           |           |              |                                     |
|                                         | HRS                                         | 5714.4    | 1200 (+200) |          | (6914.4)<br>6995.5        | 7114.4    | 467.2 (+200) |                                     |
|                                         | ENC                                         |           |             |          |                           |           |              |                                     |
| PROC. REF: LMM 72-00-00, LMM 72-00-00   |                                             |           |             |          |                           |           |              | WO#: N950PC RH ENG MPI/CZI          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                 | Unit                                        | C/W       | Interval   | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition                         |
|-----------------------------------------|---------------------------------------------|-----------|------------|----------|---------------------------|-----------|-------------|-------------------------------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS |                                             |           |            |          |                           |           |             |                                     |
| 057170                                  | NO. 1 ENGINE - 1200 TO 1650 HOUR INSPECTION |           |            |          |                           |           |             | Package ATA:05                      |
|                                         | MOS                                         | 04-May-15 |            |          |                           |           |             |                                     |
|                                         | HRS                                         | 5125      | 1600 (+50) |          | (6725)<br>6721.8          | 6775      | 193.5 (+50) |                                     |
|                                         | ENC                                         | 2873      |            |          |                           |           |             |                                     |
| PROC. REF: LMM 72-00-00, LMM 72-00-00   |                                             |           |            |          |                           |           |             | PKG:5<br>WO#: N950PC LH ENG MPI     |
| 057170                                  | NO. 2 ENGINE - 1200 TO 1650 HOUR INSPECTION |           |            |          |                           |           |             | Package ATA:05                      |
|                                         | MOS                                         | 04-May-15 |            |          |                           |           |             |                                     |
|                                         | HRS                                         | 5125.6    | 1600 (+50) |          | (6725.6)<br>6806.7        | 6775.6    | 278.4 (+50) |                                     |
|                                         | ENC                                         | 2873      |            |          |                           |           |             |                                     |
| PROC. REF: LMM 72-00-00, LMM 72-00-00   |                                             |           |            |          |                           |           |             | PKG:5<br>WO#: N950PC RH ENG MPI/CZI |
| T05T03 <sup>U</sup>                     | INSPECTION CRITERIA/STRUCTURAL INSPECTIONS  |           |            |          |                           |           |             | Service ATA:05                      |
|                                         | MOS/MSC                                     | 22-Jul-21 | O/C        |          |                           |           |             |                                     |
|                                         | HRS                                         | 6077.4    |            |          |                           |           |             |                                     |
| WC#: 05.T03                             | AFL                                         | 3596      |            |          |                           |           |             |                                     |
| PROC. REF: AFMS INTRODUCTION            |                                             |           |            |          |                           |           |             |                                     |
| ATA 06 - DIMENSIONS AND AREAS           |                                             |           |            |          |                           |           |             |                                     |
| T06T01 <sup>U</sup>                     | GENERAL INSPECTION PANEL LOCATION CHARTS    |           |            |          |                           |           |             | Service ATA:06                      |
|                                         | MOS/MSC                                     | 22-Jul-21 | O/C        |          |                           |           |             |                                     |
|                                         | HRS                                         | 6077.4    |            |          |                           |           |             |                                     |
| WC#: 06.T01                             | AFL                                         | 3596      |            |          |                           |           |             |                                     |
| PROC. REF: AFMS PANEL LOCATION          |                                             |           |            |          |                           |           |             |                                     |
| ATA 08 - LEVELING AND WEIGHING          |                                             |           |            |          |                           |           |             |                                     |
| 080001 <sup>U</sup>                     | AIRCRAFT REWEIGHT                           |           |            |          |                           |           |             | Service ATA:08                      |
|                                         | MOS                                         | 19-Aug-21 | 36         |          | 31-Aug-24                 |           | 578 d       |                                     |
|                                         | HRS                                         | 6108.8    |            |          |                           |           |             |                                     |
|                                         | AFL                                         | 3621      |            |          |                           |           |             |                                     |
| 080002 <sup>U</sup>                     | UPDATE BOW                                  |           |            |          |                           |           |             | Service ATA:08                      |
|                                         | MOS/MSC                                     | 24-Dec-21 | A/R        |          |                           |           |             |                                     |
|                                         | HRS                                         | 6264.3    |            |          |                           |           |             |                                     |
|                                         | AFL                                         | 3743      |            |          |                           |           |             |                                     |
| PROC. REF: AMM 34-09-111                |                                             |           |            |          |                           |           |             |                                     |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                          | Unit                                                          | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition    |
|--------------------------------------------------|---------------------------------------------------------------|-----------|---------------|----------|---------------------------|-----------|-------------|----------------|
| ATA 10 - PARKING, MOORING, STORE AND RET TO SERV |                                                               |           |               |          |                           |           |             |                |
| 100002                                           | ACCOMPLISH AIRPLANE "FLIGHT READY" STORAGE 2 WEEK INSPECTION  |           |               |          |                           |           |             | Service ATA:10 |
|                                                  | MOS/MSC                                                       | 30-May-96 | N/R           |          |                           |           |             |                |
|                                                  | HRS                                                           | 0         |               |          |                           |           |             |                |
| WC#: 10.010                                      | AFL                                                           | 0         |               |          |                           |           |             |                |
| 100004                                           | ACCOMPLISH AIRPLANE "FLIGHT READY" STORAGE 4 WEEK INSPECTION  |           |               |          |                           |           |             | Service ATA:10 |
|                                                  | MOS/MSC                                                       | 30-May-96 | N/R           |          |                           |           |             |                |
|                                                  | HRS                                                           | 0         |               |          |                           |           |             |                |
| WC#: 10.020                                      | AFL                                                           | 0         |               |          |                           |           |             |                |
| 100006                                           | ACCOMPLISH AIRPLANE "FLIGHT READY" STORAGE 6 MONTH INSPECTION |           |               |          |                           |           |             | Service ATA:10 |
|                                                  | MOS/MSC                                                       | 30-May-96 | N/R           |          |                           |           |             |                |
|                                                  | HRS                                                           | 0         |               |          |                           |           |             |                |
| WC#: 10.030                                      | AFL                                                           | 0         |               |          |                           |           |             |                |
| 101002                                           | ACCOMPLISH AIRPLANE "FLIGHT READY" STORAGE 2 WEEK INSPECTION  |           |               |          |                           |           |             | Service ATA:10 |
|                                                  | MOS/MSC                                                       | 30-May-96 | N/R           |          |                           |           |             |                |
|                                                  | HRS                                                           | 0         |               |          |                           |           |             |                |
|                                                  | AFL                                                           | 0         |               |          |                           |           |             |                |
| 101004                                           | ACCOMPLISH AIRPLANE "FLIGHT READY" STORAGE 4 WEEK INSPECTION  |           |               |          |                           |           |             | Service ATA:10 |
|                                                  | MOS/MSC                                                       | 30-May-96 | N/R           |          |                           |           |             |                |
|                                                  | HRS                                                           | 0         |               |          |                           |           |             |                |
|                                                  | AFL                                                           | 0         |               |          |                           |           |             |                |
| 101006                                           | ACCOMPLISH AIRPLANE "FLIGHT READY" STORAGE 6 MONTH INSPECTION |           |               |          |                           |           |             | Service ATA:10 |
|                                                  | MOS/MSC                                                       | 30-May-96 | N/R           |          |                           |           |             |                |
|                                                  | HRS                                                           | 0         |               |          |                           |           |             |                |
|                                                  | AFL                                                           | 0         |               |          |                           |           |             |                |
| ATA 12 - SERVICING                               |                                                               |           |               |          |                           |           |             |                |
| 120001                                           | LUBRICATE AREA G-200 HOURS                                    |           |               |          |                           |           |             | Service ATA:12 |
|                                                  | MOS                                                           | 11-Oct-22 |               |          |                           |           |             |                |
|                                                  | HRS                                                           | 6446.4    | 200 (+40/-10) |          | 6646.4                    | 6686.4    | 118.1 (+40) |                |
| WC#: 12.001                                      | AFL                                                           | 3873      |               |          |                           |           |             |                |
| PROC. REF: AFMS LUBRICATION, AFMS LUBRICATION    |                                                               |           |               |          |                           |           |             |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                       | Unit                                      | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition                         |
|-----------------------------------------------|-------------------------------------------|-----------|---------------|----------|---------------------------|-----------|-------------|-------------------------------------|
| ATA 12 - SERVICING                            |                                           |           |               |          |                           |           |             |                                     |
| 120003                                        | LUBRICATE AREA F1-400 HOURS               |           |               |          |                           |           |             | Service ATA:12                      |
|                                               | MOS                                       | 11-Oct-22 |               |          |                           |           |             |                                     |
|                                               | HRS                                       | 6446.4    | 400 (+40/-10) |          | 6846.4                    | 6886.4    | 318.1 (+40) |                                     |
| WC#: 12.003                                   | AFL                                       | 3873      |               |          |                           |           |             |                                     |
| PROC. REF: AFMS LUBRICATION                   |                                           |           |               |          |                           |           |             |                                     |
| 120004                                        | LUBRICATE AREA T1-400 HOURS               |           |               |          |                           |           |             | Service ATA:12                      |
|                                               | MOS                                       | 11-Oct-22 |               |          |                           |           |             |                                     |
|                                               | HRS                                       | 6446.4    | 400 (+40/-10) |          | 6846.4                    | 6886.4    | 318.1 (+40) |                                     |
| WC#: 12.004                                   | AFL                                       | 3873      |               |          |                           |           |             |                                     |
| PROC. REF: AFMS LUBRICATION, AFMS LUBRICATION |                                           |           |               |          |                           |           |             |                                     |
| 120007                                        | LUBRICATE AREA W1/W2-400 HOURS            |           |               |          |                           |           |             | Service ATA:12                      |
|                                               | MOS                                       | 11-Oct-22 |               |          |                           |           |             |                                     |
|                                               | HRS                                       | 6446.4    | 400 (+40/-10) |          | 6846.4                    | 6886.4    | 318.1 (+40) |                                     |
| WC#: 12.007                                   | AFL                                       | 3873      |               |          |                           |           |             |                                     |
| PROC. REF: AFMS LUBRICATION, AFMS LUBRICATION |                                           |           |               |          |                           |           |             |                                     |
| 120012                                        | LUBRICATE AREA F3 (ABOVE FLOOR)-800 HOURS |           |               |          |                           |           |             | Service ATA:12                      |
|                                               | MOS                                       | 15-Oct-19 |               |          |                           |           |             |                                     |
|                                               | HRS                                       | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)    |                                     |
| WC#: 12.012                                   | AFL                                       | 3397      |               |          |                           |           |             |                                     |
| PROC. REF: AFMS LUBRICATION                   |                                           |           |               |          |                           |           |             |                                     |
|                                               |                                           |           |               |          |                           |           |             | PKG:2,13<br>WO#: N950PC B & C CHECK |
| 120013                                        | LUBRICATE AREA F4-800 HOURS               |           |               |          |                           |           |             | Service ATA:12                      |
|                                               | MOS                                       | 15-Oct-19 |               |          |                           |           |             |                                     |
|                                               | HRS                                       | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)    |                                     |
| WC#: 12.009                                   | AFL                                       | 3397      |               |          |                           |           |             |                                     |
| PROC. REF: AFMS LUBRICATION                   |                                           |           |               |          |                           |           |             |                                     |
|                                               |                                           |           |               |          |                           |           |             | PKG:2,14<br>WO#: N950PC B & C CHECK |
| 120015                                        | LUBRICATE AREA W1-800 HOURS               |           |               |          |                           |           |             | Service ATA:12                      |
|                                               | MOS                                       | 15-Oct-19 |               |          |                           |           |             |                                     |
|                                               | HRS                                       | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)    |                                     |
| WC#: 12.015                                   | AFL                                       | 3397      |               |          |                           |           |             |                                     |
| PROC. REF: AFMS LUBRICATION, AFMS LUBRICATION |                                           |           |               |          |                           |           |             |                                     |
|                                               |                                           |           |               |          |                           |           |             | PKG:2,16<br>WO#: N950PC B & C CHECK |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                       | Unit                                      | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition                         |
|-----------------------------------------------|-------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-------------|-------------------------------------|
| ATA 12 - SERVICING                            |                                           |           |                |          |                           |           |             |                                     |
| 120016                                        | LUBRICATE AREA W2-800 HOURS               |           |                |          |                           |           |             | Service ATA:12                      |
|                                               | MOS                                       | 15-Oct-19 |                |          |                           |           |             |                                     |
|                                               | HRS                                       | 5795.3    | 800 (+40/-10)  |          | 6595.3                    | 6635.3    | 67 (+40)    |                                     |
| WC#: 12.016                                   | AFL                                       | 3397      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS LUBRICATION, AFMS LUBRICATION |                                           |           |                |          |                           |           |             | PKG:2,17<br>WO#: N950PC B & C CHECK |
| 120018                                        | LUBRICATE AREA G-800 HOURS                |           |                |          |                           |           |             | Service ATA:12                      |
|                                               | MOS                                       | 15-Oct-19 |                |          |                           |           |             |                                     |
|                                               | HRS                                       | 5795.3    | 800 (+40/-10)  |          | 6595.3                    | 6635.3    | 67 (+40)    |                                     |
| WC#: 12.018                                   | AFL                                       | 3397      |                |          |                           |           |             |                                     |
|                                               |                                           |           |                |          |                           |           |             | PKG:2,19<br>WO#: N950PC B & C CHECK |
| 120019                                        | LUBRICATE AREA F1-1600 HOURS              |           |                |          |                           |           |             | Service ATA:12                      |
|                                               | MOS                                       | 06-May-15 |                |          |                           |           |             |                                     |
|                                               | HRS                                       | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 12.013                                   | AFL                                       | 2873      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS LUBRICATION                   |                                           |           |                |          |                           |           |             | PKG:3,22<br>WO#: N950PC B & C CHECK |
| 120020                                        | LUBRICATE AREA F2-1600 HOURS              |           |                |          |                           |           |             | Service ATA:12                      |
|                                               | MOS                                       | 06-May-15 |                |          |                           |           |             |                                     |
|                                               | HRS                                       | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 12.020                                   | AFL                                       | 2873      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS LUBRICATION                   |                                           |           |                |          |                           |           |             | PKG:3,23<br>WO#: N950PC B & C CHECK |
| 120021                                        | LUBRICATE AREA F3 (UNDERFLOOR)-1600 HOURS |           |                |          |                           |           |             | Service ATA:12                      |
|                                               | MOS                                       | 06-May-15 |                |          |                           |           |             |                                     |
|                                               | HRS                                       | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 12.021                                   | AFL                                       | 2873      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS LUBRICATION                   |                                           |           |                |          |                           |           |             | PKG:3,24<br>WO#: N950PC B & C CHECK |
| 120022                                        | LUBRICATE AREA F3-1600 HOURS              |           |                |          |                           |           |             | Service ATA:12                      |
|                                               | MOS                                       | 06-May-15 |                |          |                           |           |             |                                     |
|                                               | HRS                                       | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 12.022                                   | AFL                                       | 2873      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS LUBRICATION                   |                                           |           |                |          |                           |           |             | PKG:3,25<br>WO#: N950PC B & C CHECK |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                     | Unit                         | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition                           |
|-----------------------------|------------------------------|-----------|-----------------|----------|---------------------------|-----------|---------------|---------------------------------------|
| ATA 12 - SERVICING          |                              |           |                 |          |                           |           |               |                                       |
| 120023                      | LUBRICATE AREA F4-1600 HOURS |           |                 |          |                           |           |               | Service ATA:12                        |
|                             | MOS                          | 06-May-15 |                 |          |                           |           |               |                                       |
|                             | HRS                          | 5125.6    | 1600 (+50/-50)  |          | 6725.6                    | 6775.6    | 197.3 (+50)   |                                       |
| WC#: 12.023                 | AFL                          | 2873      |                 |          |                           |           |               |                                       |
| PROC. REF: AFMS LUBRICATION |                              |           |                 |          |                           |           |               | PKG:3,26<br>WO#: N950PC B & C CHECK   |
| 120024                      | LUBRICATE AREA T1-1600 HOURS |           |                 |          |                           |           |               | Service ATA:12                        |
|                             | MOS                          | 06-May-15 |                 |          |                           |           |               |                                       |
|                             | HRS                          | 5125.6    | 1600 (+50/-50)  |          | 6725.6                    | 6775.6    | 197.3 (+50)   |                                       |
| WC#: 12.024                 | AFL                          | 2873      |                 |          |                           |           |               |                                       |
| PROC. REF: AFMS LUBRICATION |                              |           |                 |          |                           |           |               | PKG:3,27<br>WO#: N950PC B & C CHECK   |
| 120025                      | LUBRICATE AREA W1-1600 HOURS |           |                 |          |                           |           |               | Service ATA:12                        |
|                             | MOS                          | 06-May-15 |                 |          |                           |           |               |                                       |
|                             | HRS                          | 5125.6    | 1600 (+50/-50)  |          | 6725.6                    | 6775.6    | 197.3 (+50)   |                                       |
| WC#: 12.025                 | AFL                          | 2873      |                 |          |                           |           |               |                                       |
| PROC. REF: AFMS LUBRICATION |                              |           |                 |          |                           |           |               | PKG:3,28<br>WO#: N950PC B & C CHECK   |
| 120026                      | LUBRICATE AREA W2-1600 HOURS |           |                 |          |                           |           |               | Service ATA:12                        |
|                             | MOS                          | 06-May-15 |                 |          |                           |           |               |                                       |
|                             | HRS                          | 5125.6    | 1600 (+50/-50)  |          | 6725.6                    | 6775.6    | 197.3 (+50)   |                                       |
| WC#: 12.026                 | AFL                          | 2873      |                 |          |                           |           |               |                                       |
| PROC. REF: AFMS LUBRICATION |                              |           |                 |          |                           |           |               | PKG:3,29<br>WO#: N950PC B & C CHECK   |
| 120030                      | LUBRICATE AREA F2-3200 HOURS |           |                 |          |                           |           |               | Service ATA:12                        |
|                             | MOS                          | 18-Aug-17 |                 |          |                           |           |               |                                       |
|                             | HRS                          | 5554.6    | 3200 (+150/-50) |          | 8754.6                    | 8904.6    | 2226.3 (+150) |                                       |
| WC#: 12.030                 | AFL                          | 3197      |                 |          |                           |           |               |                                       |
| PROC. REF: AFMS LUBRICATION |                              |           |                 |          |                           |           |               | PKG:4,35                              |
| 120049                      | LUBRICATE AREA F1-24 MONTHS  |           |                 |          |                           |           |               | Service ATA:12                        |
|                             | MOS                          | 11-Oct-22 | 24 (+2m/-2m)    |          | 11-Oct-24                 | 11-Dec-24 | 619 d (+61)   |                                       |
|                             | HRS                          | 6446.4    |                 |          |                           |           |               |                                       |
| WC#: 12.049                 | AFL                          | 3873      |                 |          |                           |           |               |                                       |
| PROC. REF: AFMS LUBRICATION |                              |           |                 |          |                           |           |               | PKG:6,58<br>WO#: N950PC 48 MONTH INSP |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                     | Unit                                  | C/W       | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                             | Disposition    |
|-----------------------------|---------------------------------------|-----------|--------------|----------|---------------------------|-----------|---------------------------------------|----------------|
| ATA 12 - SERVICING          |                                       |           |              |          |                           |           |                                       |                |
| 120050                      | LUBRICATE AREA F2-24 MONTHS           |           |              |          |                           |           |                                       | Service ATA:12 |
|                             | MOS                                   | 11-Oct-22 | 24 (+2m/-2m) |          | 11-Oct-24                 | 11-Dec-24 | 619 d (+61)                           |                |
|                             | HRS                                   | 6446.4    |              |          |                           |           |                                       |                |
| WC#: 12.050                 | AFL                                   | 3873      |              |          |                           |           |                                       |                |
| PROC. REF: AFMS LUBRICATION |                                       |           |              |          |                           |           | PKG:6,59<br>WO#: N950PC 48 MONTH INSP |                |
| 121001 <sup>U</sup>         | CAE VENDOR TRAINING AUDIT- DALLAS     |           |              |          |                           |           |                                       | Service ATA:12 |
|                             | MOS                                   | 20-Oct-22 | 24           |          | 20-Oct-24                 |           | 628 d                                 |                |
|                             | HRS                                   | 6453.1    |              |          |                           |           |                                       |                |
|                             | AFL                                   | 3876      |              |          |                           |           |                                       |                |
| 121002 <sup>U</sup>         | CAE VENDOR TRAINING AUDIT- MORRISTOWN |           |              |          |                           |           |                                       | Service ATA:12 |
|                             | MOS                                   | 24-Oct-21 | 24           |          | 24-Oct-23                 |           | 266 d                                 |                |
|                             | HRS                                   | 6169      |              |          |                           |           |                                       |                |
|                             | AFL                                   | 3664      |              |          |                           |           |                                       |                |
| 122400 <sup>U</sup>         | AIRCRAFT WASH                         |           |              |          |                           |           |                                       | Service ATA:12 |
|                             | MOS/MSC                               | 07-Dec-22 | A/R          |          |                           |           |                                       |                |
|                             | HRS                                   | 6488.1    |              |          |                           |           |                                       |                |
|                             | AFL                                   | 3901      |              |          |                           |           |                                       |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                    | Unit                                                | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition                        |
|--------------------------------------------|-----------------------------------------------------|-----------|---------------|----------|---------------------------|-----------|-------------|------------------------------------|
| ATA 20 - STANDARD PRACTICES - AIRFRAME     |                                                     |           |               |          |                           |           |             |                                    |
| 200001                                     | BONDING CHECK CONTROL SURFACES                      |           |               |          |                           |           |             | Service ATA:20                     |
|                                            | MOS                                                 | 15-Oct-19 |               |          |                           |           |             |                                    |
|                                            | HRS                                                 | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)    |                                    |
| WC#: 20.010                                | AFL                                                 | 3397      |               |          |                           |           |             |                                    |
| PROC. REF: AFMS INSPECTION B1              |                                                     |           |               |          |                           |           |             | PKG:2,8<br>WO#: N950PC B & C CHECK |
| 200002                                     | FUNCTIONAL TEST REFUEL POINT EARTHING STUDS (3 OFF) |           |               |          |                           |           |             | Service ATA:20                     |
|                                            | MOS                                                 | 25-Jun-20 |               |          |                           |           |             |                                    |
|                                            | HRS                                                 | 5801      | 800 (+40/-10) |          | 6601                      | 6641      | 72.7 (+40)  |                                    |
| WC#: 20.020                                | AFL                                                 | 3399      |               |          |                           |           |             |                                    |
| PROC. REF: AFMS INSPECTION B1              |                                                     |           |               |          |                           |           |             | PKG:2,8<br>WO#: N950PC B & C CHECK |
| 200003                                     | CHECK RADIO RACKING, ELECTRICAL-BONDING             |           |               |          |                           |           |             | Service ATA:20                     |
|                                            | MOS                                                 | 15-Oct-19 | 48 (+2m/-2m)  |          | 15-Oct-23                 | 15-Dec-23 | 257 d (+61) |                                    |
|                                            | HRS                                                 | 5795.3    |               |          |                           |           |             |                                    |
| WC#: 20.030                                | AFL                                                 | 3397      |               |          |                           |           |             |                                    |
| PROC. REF: AMM 24-01-00, AFMS INSPECTION G |                                                     |           |               |          |                           |           |             | PKG:7<br>WO#: N950PC 48 MONTH INSP |
| ATA 21 - AIR CONDITIONING                  |                                                     |           |               |          |                           |           |             |                                    |
| 210002                                     | CHECK/TEST RAM AIR VALVE/DUMP VALVE/VENT VALVE      |           |               |          |                           |           |             | Service ATA:21                     |
|                                            | MOS                                                 | 15-Oct-19 |               |          |                           |           |             |                                    |
|                                            | HRS                                                 | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)    |                                    |
| WC#: 21.075                                | AFL                                                 | 3397      |               |          |                           |           |             |                                    |
| PROC. REF: AFMS INSPECTION B1              |                                                     |           |               |          |                           |           |             | PKG:2,8<br>WO#: N950PC B & C CHECK |
| 210003                                     | BENCH CHECK ENVIRONMENTAL CONTROL SYSTEM            |           |               |          |                           |           |             | Service ATA:21                     |
|                                            | MOS                                                 | 15-Oct-19 |               |          |                           |           |             |                                    |
|                                            | HRS                                                 | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)    |                                    |
| WC#: 21.110                                | AFL                                                 | 3397      |               |          |                           |           |             |                                    |
| PROC. REF: AFMS INSPECTION B1              |                                                     |           |               |          |                           |           |             | PKG:2,8<br>WO#: N950PC B & C CHECK |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                | Unit                                                                                                                                                           | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                           | Disposition    |
|--------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-------------------------------------|----------------|
| ATA 21 - AIR CONDITIONING                              |                                                                                                                                                                |           |                |          |                           |           |                                     |                |
| 210004                                                 | CHECK MANUAL CABIN ALTITUDE CONTROL VALVE                                                                                                                      |           |                |          |                           |           |                                     | Service ATA:21 |
|                                                        | MOS                                                                                                                                                            | 15-Oct-19 |                |          |                           |           |                                     |                |
|                                                        | HRS                                                                                                                                                            | 5795.3    | 800 (+40/-10)  |          | 6595.3                    | 6635.3    | 67 (+40)                            |                |
| WC#: 21.270                                            | AFL                                                                                                                                                            | 3397      |                |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION B4                          |                                                                                                                                                                |           |                |          |                           |           | PKG:2,11<br>WO#: N950PC B & C CHECK |                |
| 210005                                                 | CHECK COOLING TURBINE EXHAUST DUCT DRAIN                                                                                                                       |           |                |          |                           |           |                                     | Service ATA:21 |
|                                                        | MOS                                                                                                                                                            | 15-Oct-19 |                |          |                           |           |                                     |                |
|                                                        | HRS                                                                                                                                                            | 5795.3    | 800 (+40/-10)  |          | 6595.3                    | 6635.3    | 67 (+40)                            |                |
| WC#: 21.260                                            | AFL                                                                                                                                                            | 3397      |                |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION B7                          |                                                                                                                                                                |           |                |          |                           |           | PKG:2,14<br>WO#: N950PC B & C CHECK |                |
| 210006                                                 | INSPECT WATER SEPARATOR FOR SATISFACTORY CONDITION                                                                                                             |           |                |          |                           |           |                                     | Service ATA:21 |
|                                                        | MOS                                                                                                                                                            | 11-Oct-22 |                |          |                           |           |                                     |                |
|                                                        | HRS                                                                                                                                                            | 6446.4    | 400 (+10%)     |          | 6846.4                    | 6886.4    | 318.1 (+40)                         |                |
| WC#: 21.221                                            | AFL                                                                                                                                                            | 3873      |                |          |                           |           |                                     |                |
| PROC. REF: AFMS OUT OF PHASE INSPECTIONS, AMM 21-10-95 |                                                                                                                                                                |           |                |          |                           |           |                                     |                |
| 210007                                                 | INSPECT WATER SEPARATOR WATER DRAIN, WATER DRAIN PIPELINE, HP LINE TO WATER INJECTOR NOZZLE AND WATER INJECTOR NOZZLE ARE FREE FROM BLOCKAGES AND OBSTRUCTIONS |           |                |          |                           |           |                                     | Service ATA:21 |
|                                                        | MOS                                                                                                                                                            | 11-Oct-22 |                |          |                           |           |                                     |                |
|                                                        | HRS                                                                                                                                                            | 6446.4    | 400 (+10%)     |          | 6846.4                    | 6886.4    | 318.1 (+40)                         |                |
| WC#: 21.280                                            | AFL                                                                                                                                                            | 3873      |                |          |                           |           |                                     |                |
| PROC. REF: AFMS OUT OF PHASE INSPECTIONS, AMM 21-10-95 |                                                                                                                                                                |           |                |          |                           |           |                                     |                |
| 210008                                                 | VISUALLY INSPECT CABIN PRESSURE OUTFLOW/SAFETY VALVE CONTROLLER                                                                                                |           |                |          |                           |           |                                     | Service ATA:21 |
|                                                        | MOS                                                                                                                                                            | 06-May-15 |                |          |                           |           |                                     |                |
|                                                        | HRS                                                                                                                                                            | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50)                         |                |
| WC#: 21.118                                            | AFL                                                                                                                                                            | 2873      |                |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION C4                          |                                                                                                                                                                |           |                |          |                           |           | PKG:3,23<br>WO#: N950PC B & C CHECK |                |
| 210009                                                 | CHECK PRESSURIZATION CONTROL VENTURI SCREEN                                                                                                                    |           |                |          |                           |           |                                     | Service ATA:21 |
|                                                        | MOS                                                                                                                                                            | 06-May-15 |                |          |                           |           |                                     |                |
|                                                        | HRS                                                                                                                                                            | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50)                         |                |
| WC#: 21.275                                            | AFL                                                                                                                                                            | 2873      |                |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION C6                          |                                                                                                                                                                |           |                |          |                           |           | PKG:3,25<br>WO#: N950PC B & C CHECK |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                     | Unit                                              | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                           | Disposition    |
|---------------------------------------------|---------------------------------------------------|-----------|-----------------|----------|---------------------------|-----------|-------------------------------------|----------------|
| ATA 21 - AIR CONDITIONING                   |                                                   |           |                 |          |                           |           |                                     |                |
| 210010                                      | CLEAN PRESSURE REGULATOR FILTER SCREENS           |           |                 |          |                           |           |                                     | Service ATA:21 |
|                                             | MOS                                               | 15-Oct-19 | 48 (+2m/-2m)    |          | 15-Oct-23                 | 15-Dec-23 | 257 d (+61)                         |                |
|                                             | HRS                                               | 5795.3    |                 |          |                           |           |                                     |                |
| WC#: 21.155                                 | AFL                                               | 3397      |                 |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION G, AMM 21-30-55  |                                                   |           |                 |          |                           |           | PKG:7<br>WO#: N950PC 48 MONTH INSP  |                |
| 210011                                      | CLEAN/FUNCTIONAL TEST OUTFLOW/SAFETY VALVES       |           |                 |          |                           |           |                                     | Service ATA:21 |
|                                             | MOS                                               | 15-Oct-19 | 48 (+2m/-2m)    |          | 15-Oct-23                 | 15-Dec-23 | 257 d (+61)                         |                |
|                                             | HRS                                               | 5795.3    |                 |          |                           |           |                                     |                |
| WC#: 21.120                                 | AFL                                               | 3397      |                 |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION G, AMM 21-30-25  |                                                   |           |                 |          |                           |           | PKG:7<br>WO#: N950PC 48 MONTH INSP  |                |
| 210012                                      | INSPECT AIR CONDITIONING DUCTS                    |           |                 |          |                           |           |                                     | Service ATA:21 |
|                                             | MOS                                               | 06-May-15 |                 |          |                           |           |                                     |                |
|                                             | HRS                                               | 5125.6    | 1600 (+50/-50)  |          | 6725.6                    | 6775.6    | 197.3 (+50)                         |                |
| WC#: 21.250                                 | AFL                                               | 2873      |                 |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION C7, AMM 21-10-15 |                                                   |           |                 |          |                           |           | PKG:3,26<br>WO#: N950PC B & C CHECK |                |
| 210013                                      | INSPECT RAM AIR DUCT                              |           |                 |          |                           |           |                                     | Service ATA:21 |
|                                             | MOS                                               | 06-May-15 |                 |          |                           |           |                                     |                |
|                                             | HRS                                               | 5125.6    | 1600 (+50/-50)  |          | 6725.6                    | 6775.6    | 197.3 (+50)                         |                |
| WC#: 21.255                                 | AFL                                               | 2873      |                 |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION C7               |                                                   |           |                 |          |                           |           | PKG:3,26<br>WO#: N950PC B & C CHECK |                |
| 210014                                      | INSPECT CABIN AIR FILTERS (PRESSURIZATION SYSTEM) |           |                 |          |                           |           |                                     | Service ATA:21 |
|                                             | MOS                                               | 15-Oct-19 | 48 (+2m/-2m)    |          | 15-Oct-23                 | 15-Dec-23 | 257 d (+61)                         |                |
|                                             | HRS                                               | 5795.3    |                 |          |                           |           |                                     |                |
| WC#: 21.310                                 | AFL                                               | 3397      |                 |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION G                |                                                   |           |                 |          |                           |           | PKG:7<br>WO#: N950PC 48 MONTH INSP  |                |
| 210015                                      | INSPECT SILENCER DUCT/SOUNDPROOFING               |           |                 |          |                           |           |                                     | Service ATA:21 |
|                                             | MOS                                               | 18-Aug-17 |                 |          |                           |           |                                     |                |
|                                             | HRS                                               | 5554.6    | 3200 (+150/-50) |          | 8754.6                    | 8904.6    | 2226.3 (+150)                       |                |
| WC#: 21.015                                 | AFL                                               | 3197      |                 |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION D7, AMM 21-10-15 |                                                   |           |                 |          |                           |           | PKG:4,38                            |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                      | Unit                                                                                                                                       | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                           | Disposition    |
|----------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------|-----------|-----------------|----------|---------------------------|-----------|-------------------------------------|----------------|
| ATA 21 - AIR CONDITIONING                    |                                                                                                                                            |           |                 |          |                           |           |                                     |                |
| 210016                                       | BENCH CHECK SYSTEM OVERHEAT TEMPERATURE SWITCH                                                                                             |           |                 |          |                           |           |                                     | Service ATA:21 |
|                                              | MOS                                                                                                                                        | 18-Aug-17 |                 |          |                           |           |                                     |                |
|                                              | HRS                                                                                                                                        | 5554.6    | 3200 (+150/-50) |          | 8754.6                    | 8904.6    | 2226.3 (+150)                       |                |
| WC#: 21.195                                  | AFL                                                                                                                                        | 3197      |                 |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION D7, AMM 21-60-85  |                                                                                                                                            |           |                 |          |                           |           | PKG:4,38                            |                |
| 210017                                       | CHECK BAGGAGE PANNIER HEATING SYSTEM INLET AND OUTLET VALVE (IF FITTED) OREXTERNAL BAGGAGE UNIT (EBU) INLET VALVE<br>(750 AIRPLANES ONLY). |           |                 |          |                           |           |                                     | Service ATA:21 |
|                                              | MOS/MSC                                                                                                                                    |           | N/R             |          |                           |           |                                     |                |
|                                              | HRS                                                                                                                                        | 0         |                 |          |                           |           |                                     |                |
| WC#: 21.285                                  | AFL                                                                                                                                        |           |                 |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION D7                |                                                                                                                                            |           |                 |          |                           |           |                                     |                |
| 210018                                       | FUNCTIONAL TEST ALTITUDE SWITCH, CABIN DEPRESSURIZATION WARNING                                                                            |           |                 |          |                           |           |                                     | Service ATA:21 |
|                                              | MOS                                                                                                                                        | 15-Oct-19 | 48 (+2m/-2m)    |          | 15-Oct-23                 | 15-Dec-23 | 257 d (+61)                         |                |
|                                              | HRS                                                                                                                                        | 5795.3    |                 |          |                           |           |                                     |                |
| WC#: 21.135                                  | AFL                                                                                                                                        | 3397      |                 |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION G, AMM 21-30-70   |                                                                                                                                            |           |                 |          |                           |           | PKG:7                               |                |
| 210019                                       | INSPECT CABIN SUPPLY NON-RETURN VALVE                                                                                                      |           |                 |          |                           |           |                                     | Service ATA:21 |
|                                              | MOS                                                                                                                                        | 18-Aug-17 |                 |          |                           |           |                                     |                |
|                                              | HRS                                                                                                                                        | 5554.6    | 3200 (+150/-50) |          | 8754.6                    | 8904.6    | 2226.3 (+150)                       |                |
| WC#: 21.065                                  | AFL                                                                                                                                        | 3197      |                 |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION D7, AMM 21-10-107 |                                                                                                                                            |           |                 |          |                           |           | PKG:4,38                            |                |
| 210020                                       | FUNCTIONAL TEST ELECTRICALLY ACTUATED AUXILIARY HEATING VALVE                                                                              |           |                 |          |                           |           |                                     | Service ATA:21 |
|                                              | MOS                                                                                                                                        | 06-May-15 |                 |          |                           |           |                                     |                |
|                                              | HRS                                                                                                                                        | 5125.6    | 1600 (+50/-50)  |          | 6725.6                    | 6775.6    | 197.3 (+50)                         |                |
| WC#: 21.180                                  | AFL                                                                                                                                        | 2873      |                 |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION C1, AMM 21-60-105 |                                                                                                                                            |           |                 |          |                           |           | PKG:3,20<br>WO#: N950PC B & C CHECK |                |
| 210021                                       | INSPECT/CHECK APU SUPPLY, AUXILIARY SUPPLY, RAM AIR SUPPLY AND MAIN ENGINE SUPPLY CHECK/NON-RETURN VALVES                                  |           |                 |          |                           |           |                                     | Service ATA:21 |
|                                              | MOS                                                                                                                                        | 18-Aug-17 |                 |          |                           |           |                                     |                |
|                                              | HRS                                                                                                                                        | 5554.6    | 3200 (+150/-50) |          | 8754.6                    | 8904.6    | 2226.3 (+150)                       |                |
| WC#: 21.030                                  | AFL                                                                                                                                        | 3197      |                 |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION D7, AMM 21-10-165 |                                                                                                                                            |           |                 |          |                           |           | PKG:4,38                            |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                                            | Unit                                                     | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition                         |
|------------------------------------------------------------------------------------|----------------------------------------------------------|-----------|---------------|----------|---------------------------|-----------|-------------|-------------------------------------|
| ATA 21 - AIR CONDITIONING                                                          |                                                          |           |               |          |                           |           |             |                                     |
| 210022                                                                             | CHECK TORQUE AIR CONDITIONING DUCTS                      |           |               |          |                           |           |             | Service ATA:21                      |
|                                                                                    | MOS/MSC                                                  | 10-Oct-22 | O/C           |          |                           |           |             |                                     |
|                                                                                    | HRS                                                      | 6446.4    |               |          |                           |           |             |                                     |
| WC#: 21.010                                                                        | AFL                                                      | 3873      |               |          |                           |           |             |                                     |
| PROC. REF: AFMS OUT OF PHASE INSPECTIONS, AMM 21-10-15, AMM 21-10-87, AMM 21-10-95 |                                                          |           |               |          |                           |           |             |                                     |
| 210024                                                                             | CLEAN/REPLACE LOW LIMIT TEMPERATURE CONTROL VALVE FILTER |           |               |          |                           |           |             | Service ATA:21                      |
|                                                                                    | MOS                                                      | 22-Jul-21 |               |          |                           |           |             |                                     |
|                                                                                    | HRS                                                      | 6077.4    | 800 (+40/-10) |          | 6877.4                    | 6917.4    | 349.1 (+40) |                                     |
| WC#: 21.290                                                                        | AFL                                                      | 3596      |               |          |                           |           |             |                                     |
| PROC. REF: AFMS INSPECTION B7                                                      |                                                          |           |               |          |                           |           |             |                                     |
|                                                                                    |                                                          |           |               |          |                           |           |             | PKG:2,14<br>WO#: N950PC B & C CHECK |
| 211013                                                                             | LEFT SWITCHES BLEED AIR OVER TEMPERATURE TEST            |           |               |          |                           |           |             | Service ATA:21                      |
|                                                                                    | MOS                                                      | 08-Jan-21 | 60            |          | 08-Jan-26                 |           | 1073 d      |                                     |
|                                                                                    | HRS                                                      | 5937.6    |               |          |                           |           |             |                                     |
| WC#: 21.265                                                                        | AFL                                                      | 3502      |               |          |                           |           |             |                                     |
|                                                                                    |                                                          |           |               |          |                           |           |             | WO#: N950PC 48 MONTH INSP           |
| 211014                                                                             | RIGHT SWITCHES BLEED AIR OVER TEMPERATURE TEST           |           |               |          |                           |           |             | Service ATA:21                      |
|                                                                                    | MOS                                                      | 08-Jan-21 | 60            |          | 08-Jan-26                 |           | 1073 d      |                                     |
|                                                                                    | HRS                                                      | 5937.6    |               |          |                           |           |             |                                     |
| WC#: 21.265                                                                        | AFL                                                      | 3502      |               |          |                           |           |             |                                     |
|                                                                                    |                                                          |           |               |          |                           |           |             | WO#: N950PC 48 MONTH INSP           |
| 211019                                                                             | APU SHUTOFF VALVE                                        |           |               |          |                           |           |             | Component ATA:21                    |
| PN:321292-1                                                                        | MOS/MSC                                                  | 30-May-96 | O/C           |          |                           |           |             |                                     |
| SN:UNKNOWN                                                                         | HRS                                                      | 0         |               | TSN 0    |                           |           |             |                                     |
| WC#: 21.020                                                                        | AFL                                                      | 0         |               |          |                           |           |             |                                     |
| PROC. REF: AMM 21-10-195                                                           |                                                          |           |               |          |                           |           |             |                                     |
| 211031                                                                             | APU BLEED AIR NON-RETURN VALVE                           |           |               |          |                           |           |             | Component ATA:21                    |
| PN:123190-1-1                                                                      | MOS/MSC                                                  | 30-May-96 | O/C           |          |                           |           |             |                                     |
| SN:UNKNOWN                                                                         | HRS                                                      | 0         |               | TSN 0    |                           |           |             |                                     |
| WC#: 21.025                                                                        | AFL                                                      | 0         |               |          |                           |           |             |                                     |
| 211088                                                                             | NO. 1 AIR DISTRIBUTION ACTUATOR                          |           |               |          |                           |           |             | Component ATA:21                    |
| PN:PN                                                                              | MOS/MSC                                                  | 30-May-96 | O/C           | TSN 0    |                           |           |             |                                     |
| SN:UNKNOWN                                                                         | HRS                                                      | 0         |               | TSN 0    |                           |           |             |                                     |
| WC#: 21.108                                                                        | AFL                                                      | 0         |               | TSN 0    |                           |           |             |                                     |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-----------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 21 - AIR CONDITIONING |                                         |           |          |          |                           |           |           |                  |
| 211089                    | NO. 2 AIR DISTRIBUTION ACTUATOR         |           |          |          |                           |           |           | Component ATA:21 |
| PN:PN                     | MOS/MSC                                 | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.108               | AFL                                     | 0         |          | TSN 0    |                           |           |           |                  |
| 211090                    | NO. 3 AIR DISTRIBUTION ACTUATOR         |           |          |          |                           |           |           | Component ATA:21 |
| PN:PN                     | MOS/MSC                                 | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.108               | AFL                                     | 0         |          | TSN 0    |                           |           |           |                  |
| 211091                    | NO. 4 AIR DISTRIBUTION ACTUATOR         |           |          |          |                           |           |           | Component ATA:21 |
| PN:PN                     | MOS/MSC                                 | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.108               | AFL                                     | 0         |          | TSN 0    |                           |           |           |                  |
| 211092                    | NO. 5 AIR DISTRIBUTION ACTUATOR         |           |          |          |                           |           |           | Component ATA:21 |
| PN:PN                     | MOS/MSC                                 | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.108               | AFL                                     | 0         |          | TSN 0    |                           |           |           |                  |
| 212001                    | LEFT MAIN AIR VALVE                     |           |          |          |                           |           |           | Component ATA:21 |
| PN:321292-1               | MOS/MSC                                 | 30-Aug-96 | O/C      |          |                           |           |           |                  |
| SN:2570                   | HRS                                     | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 21.040               | AFL                                     | 9         |          |          |                           |           |           |                  |
| PROC. REF: AMM 21-10-25   |                                         |           |          |          |                           |           |           |                  |
| 212002                    | RIGHT MAIN AIR VALVE                    |           |          |          |                           |           |           | Component ATA:21 |
| PN:HTE250072              | MOS/MSC                                 | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:MM831999               | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.045               | AFL                                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 21-10-24   |                                         |           |          |          |                           |           |           |                  |
| 212008                    | PRESSURE REGULATOR VALVE                |           |          |          |                           |           |           | Component ATA:21 |
| PN:PN                     | MOS/MSC                                 | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.295               | AFL                                     | 0         |          | TSN 0    |                           |           |           |                  |
| 212026                    | NO. 1 ENGINE BLEED AIR NON-RETURN VALVE |           |          |          |                           |           |           | Component ATA:21 |
| PN:HTE4168                | MOS/MSC                                 | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:M217VNR1295            | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.050               | AFL                                     | 0         |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                                         | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|----------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 21 - AIR CONDITIONING |                                              |           |          |          |                           |           |           |                  |
| 212027                    | NO. 2 ENGINE BLEED AIR NON-RETURN VALVE      |           |          |          |                           |           |           | Component ATA:21 |
| PN:HTE4168                | MOS/MSC                                      | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:M304VNR296             | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.050               | AFL                                          | 0         |          |          |                           |           |           |                  |
| 212050                    | AUXILIARY HEATING BLEED AIR NON-RETURN VALVE |           |          |          |                           |           |           | Component ATA:21 |
| PN:123190-1-1             | MOS/MSC                                      | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.055               | AFL                                          | 0         |          |          |                           |           |           |                  |
| 212062                    | LEFT (HP/LP) MIXING VALVE                    |           |          |          |                           |           |           | Component ATA:21 |
| PN:3213788-1-1            | MOS/MSC                                      | 14-Nov-96 | O/C      |          |                           |           |           |                  |
| SN:1433                   | HRS                                          | 24        |          |          |                           |           |           |                  |
| WC#: 21.060               | AFL                                          | 12        |          |          |                           |           |           |                  |
| PROC. REF: AMM 21-10-35   |                                              |           |          |          |                           |           |           |                  |
| 212063                    | RIGHT (HP/LP) MIXING VALVE                   |           |          |          |                           |           |           | Component ATA:21 |
| PN:3213788-1-1            | MOS/MSC                                      | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:1346                   | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.060               | AFL                                          | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 21-10-35   |                                              |           |          |          |                           |           |           |                  |
| 212074                    | MAIN SUPPLY NON-RETURN VALVE                 |           |          |          |                           |           |           | Component ATA:21 |
| PN:AWE124-51-2            | MOS                                          | 30-May-96 |          |          |                           |           |           | OVERHAUL         |
| SN:UNKNOWN                | HRS                                          | 0         | 12000    | TSN 0    | 12000                     |           | 5471.7    |                  |
| WC#: 21.245               | AFL                                          | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 21-10-107  |                                              |           |          |          |                           |           |           |                  |
| 212082                    | BLEED AIR CHECK VALVE                        |           |          |          |                           |           |           | Component ATA:21 |
| PN:HTE4405                | MOS/MSC                                      | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:BWF643                 | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.070               | AFL                                          |           |          |          |                           |           |           |                  |
| 212086                    | RAM AIR NON-RETURN VALVE                     |           |          |          |                           |           |           | Component ATA:21 |
| PN:321262-1               | MOS/MSC                                      | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:1074                   | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.075               | AFL                                          | 0         |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                                               | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|----------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 21 - AIR CONDITIONING |                                                    |           |          |          |                           |           |           |                  |
| 212098                    | RAM AIR SUPPLY NON-RETURN VALVE                    |           |          |          |                           |           |           | Component ATA:21 |
| PN:123190-1               | MOS/MSC                                            | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:5560                   | HRS                                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.080               | AFL                                                | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 21-10-165  |                                                    |           |          |          |                           |           |           |                  |
| 212103                    | TEMPERATURE DUCT SWITCH                            |           |          |          |                           |           |           | Component ATA:21 |
| PN:25-6MC-415             | MOS/MSC                                            | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.085               | AFL                                                | 0         |          |          |                           |           |           |                  |
| 212122                    | UPPER CHECK VALVE                                  |           |          |          |                           |           |           | Component ATA:21 |
| PN:130156-1               | MOS/MSC                                            | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:105-2070               | HRS                                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.095               | AFL                                                | 0         |          |          |                           |           |           |                  |
| 212123                    | LOWER CHECK VALVE                                  |           |          |          |                           |           |           | Component ATA:21 |
| PN:130156-1               | MOS/MSC                                            | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:105-2040               | HRS                                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.095               | AFL                                                | 0         |          |          |                           |           |           |                  |
| 212146                    | CABIN RECIRCULATING FAN                            |           |          |          |                           |           |           | Component ATA:21 |
| PN:45L3-111               | MOS/MSC                                            | 30-Aug-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:0176                   | HRS                                                | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 21.100               | AFL                                                | 9         |          |          |                           |           |           |                  |
| 213001                    | NO. 1 ENGINE HIGH PRESSURE BLEED AIR SHUTOFF VALVE |           |          |          |                           |           |           | Component ATA:21 |
| PN:B01A214128A            | MOS/MSC                                            | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:RP226                  | HRS                                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.105               | AFL                                                | 0         |          |          |                           |           |           |                  |
| 213002                    | NO. 2 ENGINE HIGH PRESSURE BLEED AIR SHUTOFF VALVE |           |          |          |                           |           |           | Component ATA:21 |
| PN:B01A214128A            | MOS/MSC                                            | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:RP228                  | HRS                                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.105               | AFL                                                | 0         |          |          |                           |           |           |                  |
| 213019                    | OUTFLOW/SAFETY VALVE CONTROLLER                    |           |          |          |                           |           |           | Component ATA:21 |
| PN:130530-4               | MOS/MSC                                            | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:94-A0083               | HRS                                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.115               | AFL                                                | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 21-30-16   |                                                    |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                         | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 21 - AIR CONDITIONING |                              |           |          |          |                           |           |           |                  |
| 213020                    | CABIN PRESSURE CONTROLLER    |           |          |          |                           |           |           | Component ATA:21 |
| PN:PN                     | MOS/MSC                      | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.321               | AFL                          | 0         |          | TSN 0    |                           |           |           |                  |
| 213031                    | LEFT OUTFLOW VALVE           |           |          |          |                           |           |           | Component ATA:21 |
| PN:103278-13              | MOS/MSC                      | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:35-742                 | HRS                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.120               | AFL                          | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 21-30-25   |                              |           |          |          |                           |           |           |                  |
| 213032                    | RIGHT OUTFLOW VALVE          |           |          |          |                           |           |           | Component ATA:21 |
| PN:103278-13              | MOS/MSC                      | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:35-760                 | HRS                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.120               | AFL                          | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 21-30-25   |                              |           |          |          |                           |           |           |                  |
| 213035                    | 2" BUTTERFLY VALVE           |           |          |          |                           |           |           | Component ATA:21 |
| PN:PN                     | MOS/MSC                      | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.320               | AFL                          | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                              |           |          |          |                           |           |           |                  |
| 213067                    | CABIN ALTITUDE CONTROL VALVE |           |          |          |                           |           |           | Component ATA:21 |
| PN:131004-2               | MOS/MSC                      | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:43-4971                | HRS                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.125               | AFL                          | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 21-30-95   |                              |           |          |          |                           |           |           |                  |
| 213073                    | MECHANICAL DUMP VALVE        |           |          |          |                           |           |           | Component ATA:21 |
| PN:25-8VF43-35A           | MOS/MSC                      | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:NH442                  | HRS                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.130               | AFL                          | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 21-30-136  |                              |           |          |          |                           |           |           |                  |
| 213097                    | ALTIMETER PRESSURE SWITCH    |           |          |          |                           |           |           | Component ATA:21 |
| PN:214C40-2-57            | MOS/MSC                      | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:T31152                 | HRS                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.135               | AFL                          |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                            | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|---------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 21 - AIR CONDITIONING |                                 |           |          |          |                           |           |           |                  |
| 213098                    | ALTIMETER PRESSURE SWITCH       |           |          |          |                           |           |           | Component ATA:21 |
| PN:PN                     | MOS/MSC                         | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.300               | AFL                             | 0         |          | TSN 0    |                           |           |           |                  |
| 213109                    | VENTURI                         |           |          |          |                           |           |           | Component ATA:21 |
| PN:131052-1               | MOS/MSC                         | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:105-3760               | HRS                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.140               | AFL                             | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 21-30-105  |                                 |           |          |          |                           |           |           |                  |
| 213115                    | FAN OPERATED VENTURI            |           |          |          |                           |           |           | Component ATA:21 |
| PN:132322-3-1             | MOS/MSC                         | 10-Jun-11 | O/C      |          |                           |           |           |                  |
| SN:117-1559               | HRS                             | 4444.1    |          |          |                           |           |           |                  |
| WC#: 21.145               | AFL                             | 2480      |          |          |                           |           |           |                  |
| PROC. REF: AMM 21-30-65   |                                 |           |          |          |                           |           |           |                  |
| 213121                    | LEFT PNEUMATIC VALVE            |           |          |          |                           |           |           | Component ATA:21 |
| PN:107312-4-1             | MOS/MSC                         | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:55-11765               | HRS                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.150               | AFL                             | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 21-30-35   |                                 |           |          |          |                           |           |           |                  |
| 213122                    | RIGHT PNEUMATIC VALVE           |           |          |          |                           |           |           | Component ATA:21 |
| PN:107312-4-1             | MOS/MSC                         | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:55-11770               | HRS                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.150               | AFL                             | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 21-30-35   |                                 |           |          |          |                           |           |           |                  |
| 213133                    | LEFT ABSOLUTE PRESSURE CONTROL  |           |          |          |                           |           |           | Component ATA:21 |
| PN:102466-5               | MOS/MSC                         | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:95-1913                | HRS                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.155               | AFL                             | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 21-30-55   |                                 |           |          |          |                           |           |           |                  |
| 213134                    | RIGHT ABSOLUTE PRESSURE CONTROL |           |          |          |                           |           |           | Component ATA:21 |
| PN:102466-5               | MOS/MSC                         | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:95-1915                | HRS                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.155               | AFL                             | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 21-30-55   |                                 |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                                                                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 21 - AIR CONDITIONING |                                                                         |           |          |          |                           |           |           |                  |
| 213157                    | JET PUMP                                                                |           |          |          |                           |           |           | Component ATA:21 |
| PN:131150-1-1             | MOS/MSC                                                                 | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:15-2770                | HRS                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.160               | AFL                                                                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 21-30-45   |                                                                         |           |          |          |                           |           |           |                  |
| 213169                    | CABIN DIFFERENTIAL PRESSURE INDICATOR                                   |           |          |          |                           |           |           | Component ATA:21 |
| PN:51010-1113             | MOS/MSC                                                                 | 30-Aug-96 | O/C      |          |                           |           |           |                  |
| SN:504171                 | HRS                                                                     | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 21.165               | AFL                                                                     | 9         |          |          |                           |           |           |                  |
| 213181                    | GROUND PRESSURE CONNECTOR                                               |           |          |          |                           |           |           | Component ATA:21 |
| PN:WGE133-2A              | MOS/MSC                                                                 | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:RP831                  | HRS                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.170               | AFL                                                                     | 0         |          |          |                           |           |           |                  |
| 216001                    | CABIN TEMPERATURE CONTROL VALVE                                         |           |          |          |                           |           |           | Component ATA:21 |
| PN:104968                 | MOS/MSC                                                                 | 10-Jan-02 | O/C      | TSO 6    |                           |           |           |                  |
| SN:973                    | HRS                                                                     | 2125      |          | TSO 0    |                           |           |           |                  |
| WC#: 21.175               | AFL                                                                     | 1175      |          | TSO 0    |                           |           |           |                  |
| PROC. REF: AMM 21-60-57   |                                                                         |           |          |          |                           |           |           |                  |
| 216006                    | AIR CONDITIONING DUCT, SILENCER TO REAR PRESSURE BULKHEAD SHUTOFF VALVE |           |          |          |                           |           |           | Component ATA:21 |
| PN:PN                     | MOS/MSC                                                                 | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.326               | AFL                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                         |           |          |          |                           |           |           |                  |
| 216025                    | AUXILIARY HEATING VALVE                                                 |           |          |          |                           |           |           | Component ATA:21 |
| PN:104568                 | MOS/MSC                                                                 | 14-Nov-96 | O/C      |          |                           |           |           |                  |
| SN:13033                  | HRS                                                                     | 24        |          | TSN 0    |                           |           |           |                  |
| WC#: 21.180               | AFL                                                                     | 12        |          |          |                           |           |           |                  |
| PROC. REF: AMM 21-60-105  |                                                                         |           |          |          |                           |           |           |                  |
| 216055                    | CABIN TEMPERATURE (CONTROLLER) SENSOR                                   |           |          |          |                           |           |           | Component ATA:21 |
| PN:607148-1-1             | MOS/MSC                                                                 | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:055C-8358              | HRS                                                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.185               | AFL                                                                     | 0         |          |          |                           |           |           |                  |
| PROC. REF: MMA 21-60-05   |                                                                         |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                         | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 21 - AIR CONDITIONING |                              |           |          |          |                           |           |           |                  |
| 216073                    | CABIN TEMPERATURE CONTROLLER |           |          |          |                           |           |           | Component ATA:21 |
| PN:617452-4               | MOS/MSC                      | 18-May-00 | O/C      |          |                           |           |           |                  |
| SN:114C-379               | HRS                          | 1408      |          |          |                           |           |           |                  |
| WC#: 21.190               | AFL                          | 724       |          |          |                           |           |           |                  |
| PROC. REF: AMM 21-60-67   |                              |           |          |          |                           |           |           |                  |
| 216097                    | TEMPERATURE DUCT SELECTOR    |           |          |          |                           |           |           | Component ATA:21 |
| PN:25-6MC-415             | MOS/MSC                      | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.195               | AFL                          | 0         |          |          |                           |           |           |                  |
| 216115                    | COLD AIR UNIT PACK           |           |          |          |                           |           |           | Component ATA:21 |
| PN:2214070-5              | MOS/MSC                      | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:16235                  | HRS                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.200               | AFL                          |           |          |          |                           |           |           |                  |
| 216121                    | MODULATING VALVE             |           |          |          |                           |           |           | Component ATA:21 |
| PN:978836-5-1             | MOS/MSC                      | 22-Nov-10 | O/C      |          |                           |           |           |                  |
| SN:248                    | HRS                          | 4317.1    |          |          |                           |           |           |                  |
| WC#: 21.210               | AFL                          | 2410      |          |          |                           |           |           |                  |
| 216127                    | CONTROL SENSOR               |           |          |          |                           |           |           | Component ATA:21 |
| PN:1150642-3              | MOS/MSC                      | 26-Oct-10 | O/C      |          |                           |           |           |                  |
| SN:081C-11218             | HRS                          | 4288.8    |          |          |                           |           |           |                  |
| WC#: 21.215               | AFL                          | 2396      |          |          |                           |           |           |                  |
| PROC. REF: AMM 21-60-60   |                              |           |          |          |                           |           |           |                  |
| 216135                    | TOTAL TEMPERATURE SENSOR     |           |          |          |                           |           |           | Component ATA:21 |
| PN:PN                     | MOS/MSC                      | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.305               | AFL                          | 0         |          | TSN 0    |                           |           |           |                  |
| 217001                    | WATER SEPARATOR              |           |          |          |                           |           |           | Component ATA:21 |
| PN:25-8VF1351-131         | MOS/MSC                      | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:75-1128                | HRS                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.220               | AFL                          | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 21-10-95   |                              |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                 | Unit                               | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------------------------------|------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 21 - AIR CONDITIONING               |                                    |           |          |          |                           |           |           |                  |
| 217014                                  | CABIN TRIPLE INDICATOR             |           |          |          |                           |           |           | Component ATA:21 |
| PN:720-15900-913                        | MOS/MSC                            | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                              | HRS                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.225                             | AFL                                | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 21-30-90                 |                                    |           |          |          |                           |           |           |                  |
| 217023                                  | PRESSURE SWITCH                    |           |          |          |                           |           |           | Component ATA:21 |
| PN:690090                               | MOS/MSC                            | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:FRTR014AS                            | HRS                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 21.235                             | AFL                                | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 21-10-39                 |                                    |           |          |          |                           |           |           |                  |
| ATA 22 - AUTO FLIGHT                    |                                    |           |          |          |                           |           |           |                  |
| 221001                                  | AFCS CONTROL PANEL                 |           |          |          |                           |           |           | Component ATA:22 |
| PN:7011702-915                          | MOS/MSC                            | 16-Nov-10 | O/C      |          |                           |           |           |                  |
| SN:88060134                             | HRS                                | 4294.3    |          |          |                           |           |           |                  |
| WC#: 22.010                             | AFL                                | 2398      |          |          |                           |           |           |                  |
| 221007                                  | NO. 1 FLIGHT GUIDANCE COMPUTER     |           |          |          |                           |           |           | Component ATA:22 |
| PN:7003974-713                          | MOS/MSC                            | 25-Jan-19 | O/C      | TSR 3    |                           |           |           |                  |
| SN:88041185                             | HRS                                |           |          | TSR 0    |                           |           |           |                  |
| WC#: 22.015                             | AFL                                |           |          | TSR 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF, AMM 34-22-05 |                                    |           |          |          |                           |           |           |                  |
| 221008                                  | NO. 2 FLIGHT GUIDANCE COMPUTER     |           |          |          |                           |           |           | Component ATA:22 |
| PN:7003974-713                          | MOS/MSC                            | 28-Oct-05 | O/C      |          |                           |           |           |                  |
| SN:90112631                             | HRS                                | 3001.7    |          |          |                           |           |           |                  |
| WC#: 22.015                             | AFL                                | 1673      |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF, AMM 34-22-05 |                                    |           |          |          |                           |           |           |                  |
| 221010                                  | NO. 1 AUTO PILOT MODE SELECT PANEL |           |          |          |                           |           |           | Component ATA:22 |
| PN:PN                                   | MOS/MSC                            | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                              | HRS                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.040                             | AFL                                | 0         |          | TSN 0    |                           |           |           |                  |
| 221011                                  | NO. 2 AUTO PILOT MODE SELECT PANEL |           |          |          |                           |           |           | Component ATA:22 |
| PN:PN                                   | MOS/MSC                            | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                              | HRS                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 22.040                             | AFL                                | 0         |          | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                               | Unit                               | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------------------|------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 22 - AUTO FLIGHT                  |                                    |           |          |          |                           |           |           |                  |
| 221037                                | AUTOPILOT ELEVATOR SERVO           |           |          |          |                           |           |           | Component ATA:22 |
| PN:4006719-910                        | MOS/MSC                            | 30-Aug-96 | O/C      |          |                           |           |           |                  |
| SN:96028411                           | HRS                                | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 22.020                           | AFL                                | 9         |          |          |                           |           |           |                  |
| 221039                                | ELEVATOR SERVO MOUNT               |           |          |          |                           |           |           | Component ATA:22 |
| PN:4005842                            | MOS/MSC                            | 19-Nov-96 | O/C      |          |                           |           |           |                  |
| SN:96037132                           | HRS                                | 27        |          | TSN 0    |                           |           |           |                  |
| WC#: 22.050                           | AFL                                | 16        |          | TSN 0    |                           |           |           |                  |
| 221043                                | AUTOPILOT RUDDER SERVO             |           |          |          |                           |           |           | Component ATA:22 |
| PN:4006719-913                        | MOS/MSC                            | 30-Aug-96 | O/C      |          |                           |           |           |                  |
| SN:95118164                           | HRS                                | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 22.020                           | AFL                                | 9         |          |          |                           |           |           |                  |
| 221045                                | RUDDER SERVO MOUNT                 |           |          |          |                           |           |           | Component ATA:22 |
| PN:4005842                            | MOS/MSC                            | 19-Nov-97 | O/C      |          |                           |           |           |                  |
| SN:96037188                           | HRS                                | 27        |          | TSN 0    |                           |           |           |                  |
| WC#: 22.050                           | AFL                                | 16        |          | TSN 0    |                           |           |           |                  |
| 221049                                | AUTOPILOT AILERON SERVO            |           |          |          |                           |           |           | Component ATA:22 |
| PN:4006719-906                        | MOS/MSC                            | 30-Aug-96 | O/C      |          |                           |           |           |                  |
| SN:96038449                           | HRS                                | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 22.020                           | AFL                                | 9         |          |          |                           |           |           |                  |
| 221052                                | AILERON SERVO MOUNT                |           |          |          |                           |           |           | Component ATA:22 |
| PN:4005842                            | MOS/MSC                            | 19-Nov-97 | O/C      |          |                           |           |           |                  |
| SN:96037191                           | HRS                                | 27        |          | TSN 0    |                           |           |           |                  |
| WC#: 22.050                           | AFL                                | 16        |          | TSN 0    |                           |           |           |                  |
| ATA 23 - COMMUNICATIONS               |                                    |           |          |          |                           |           |           |                  |
| 231001                                | NO. 1 HF COMMUNICATIONS CONTROLLER |           |          |          |                           |           |           | Component ATA:23 |
| PN:071-1274-02                        | MOS/MSC                            | 12-Nov-96 | O/C      |          |                           |           |           |                  |
| SN:3285                               | HRS                                | 19        |          |          |                           |           |           |                  |
| WC#: 23.015                           | AFL                                | 11        |          |          |                           |           |           |                  |
| PROC. REF: MMA 23-10-05, MMA 23-10-15 |                                    |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-----------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 23 - COMMUNICATIONS   |                                         |           |          |          |                           |           |           |                  |
| 231002                    | NO. 2 HF COMMUNICATIONS CONTROLLER      |           |          |          |                           |           |           | Component ATA:23 |
| PN:PN                     | MOS/MSC                                 | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 23.015               | AFL                                     | 0         |          | TSN 0    |                           |           |           |                  |
| 231004                    | NO. 1 HF CONTROLLER ADAPTER             |           |          |          |                           |           |           | Component ATA:23 |
| PN:071-1268-0001          | MOS/MSC                                 | 30-Aug-96 | O/C      |          |                           |           |           |                  |
| SN:2749                   | HRS                                     | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 23.020               | AFL                                     | 9         |          |          |                           |           |           |                  |
| 231006                    | NO. 2 HF CONTROLLER ADAPTER             |           |          |          |                           |           |           | Component ATA:23 |
| PN:PN                     | MOS/MSC                                 | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 23.020               | AFL                                     | 0         |          | TSN 0    |                           |           |           |                  |
| 231011                    | NO. 1 HF COMMUNICATIONS POWER AMPLIFIER |           |          |          |                           |           |           | Component ATA:23 |
| PN:064-1017-0002          | MOS/MSC                                 | 30-Aug-96 | O/C      |          |                           |           |           |                  |
| SN:14313                  | HRS                                     | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 23.025               | AFL                                     | 9         |          |          |                           |           |           |                  |
| 231012                    | NO. 2 HF COMMUNICATIONS POWER AMPLIFIER |           |          |          |                           |           |           | Component ATA:23 |
| PN:PN                     | MOS/MSC                                 | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 23.025               | AFL                                     | 0         |          | TSN 0    |                           |           |           |                  |
| 231015                    | COLLINS HG 9041 HF ANTENNA              |           |          |          |                           |           |           | Component ATA:23 |
| PN:PN                     | MOS/MSC                                 | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 23.130               | AFL                                     | 0         |          | TSN 0    |                           |           |           |                  |
| 231016                    | COLLINS HF 9031A RECEIVER/TRANSMITTER   |           |          |          |                           |           |           | Component ATA:23 |
| PN:PN                     | MOS/MSC                                 | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 23.135               | AFL                                     | 0         |          | TSN 0    |                           |           |           |                  |
| 231025                    | NO. 1 HF RECEIVER EXCITER               |           |          |          |                           |           |           | Component ATA:23 |
| PN:064-1015-01            | MOS/MSC                                 | 30-Aug-96 | O/C      |          |                           |           |           |                  |
| SN:30221                  | HRS                                     | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 23.030               | AFL                                     | 9         |          |          |                           |           |           |                  |
| WO#: N950PC 48 MONTH INSP |                                         |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                           | Unit                                 | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                 | Disposition      |
|-------------------------------------------------------------------|--------------------------------------|-----------|----------|----------|---------------------------|-----------|---------------------------|------------------|
| ATA 23 - COMMUNICATIONS                                           |                                      |           |          |          |                           |           |                           |                  |
| 231026                                                            | NO. 2 HF RECEIVER EXCITER            |           |          |          |                           |           |                           | Component ATA:23 |
| PN:064-1015-01                                                    | MOS/MSC                              | 30-May-96 | O/C      | TSN 0    |                           |           |                           |                  |
| SN:29407                                                          | HRS                                  | 0         |          | TSN 0    |                           |           |                           |                  |
| WC#: 23.030                                                       | AFL                                  | 0         |          | TSN 0    |                           |           |                           |                  |
|                                                                   |                                      |           |          |          |                           |           | WO#: N950PC 48 MONTH INSP |                  |
| 231027                                                            | NO. 1 HF BRIDGING AMPLIFIER          |           |          |          |                           |           |                           | Component ATA:23 |
| PN:071-0019-00                                                    | MOS/MSC                              | 30-May-96 | O/C      |          |                           |           |                           |                  |
| SN:UNKNOWN                                                        | HRS                                  | 0         |          | TSN 0    |                           |           |                           |                  |
| WC#: 23.035                                                       | AFL                                  | 0         |          |          |                           |           |                           |                  |
| 231028                                                            | NO. 2 HF BRIDGING AMPLIFIER          |           |          |          |                           |           |                           | Component ATA:23 |
| PN:PN                                                             | MOS/MSC                              | 30-May-96 | O/C      | TSN 0    |                           |           |                           |                  |
| SN:UNKNOWN                                                        | HRS                                  | 0         |          | TSN 0    |                           |           |                           |                  |
| WC#: 23.035                                                       | AFL                                  | 0         |          | TSN 0    |                           |           |                           |                  |
| 231029                                                            | DUAL HF CAPACITOR                    |           |          |          |                           |           |                           | Component ATA:23 |
| PN:071-1271-0001                                                  | MOS/MSC                              | 30-Aug-96 | O/C      |          |                           |           |                           |                  |
| SN:1849                                                           | HRS                                  | 16        |          | TSN 0    |                           |           |                           |                  |
| WC#: 23.040                                                       | AFL                                  | 9         |          |          |                           |           |                           |                  |
| 231043                                                            | NO. 1 VHF COMMUNICATIONS TRANSCEIVER |           |          |          |                           |           |                           | Component ATA:23 |
| PN:7510733-676                                                    | MOS/MSC                              | 21-Feb-20 | O/C      |          |                           |           |                           |                  |
| SN:92030809                                                       | HRS                                  | 5797.9    |          |          |                           |           |                           |                  |
| WC#: 23.045                                                       | AFL                                  | 3397      |          |          |                           |           |                           |                  |
| PROC. REF: AMM 25-11-05, MMA 23-20-79, MMA 23-20-80, MMA 23-20-81 |                                      |           |          |          |                           |           | WO#: N950PC 48 MONTH INSP |                  |
| 231049                                                            | NO. 2 VHF COMMUNICATIONS TRANSCEIVER |           |          |          |                           |           |                           | Component ATA:23 |
| PN:7510733-676                                                    | MOS/MSC                              | 21-Feb-20 | O/C      |          |                           |           |                           |                  |
| SN:92030812                                                       | HRS                                  | 5797.9    |          |          |                           |           |                           |                  |
| WC#: 23.045                                                       | AFL                                  | 3397      |          |          |                           |           |                           |                  |
| PROC. REF: AMM 25-11-05, MMA 23-20-79, MMA 23-20-80, MMA 23-20-81 |                                      |           |          |          |                           |           | WO#: N950PC 48 MONTH INSP |                  |
| 231050                                                            | ATC UPPER ANTENNA                    |           |          |          |                           |           |                           | Component ATA:23 |
| PN:S65-5366-7L                                                    | MOS/MSC                              | 21-Feb-20 | O/C      |          |                           |           |                           |                  |
| SN:261-134320                                                     | HRS                                  | 5797.9    |          |          |                           |           |                           |                  |
| WC#: 23.050                                                       | AFL                                  | 3397      |          |          |                           |           |                           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                               | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 23 - COMMUNICATIONS   |                                    |           |          |          |                           |           |           |                  |
| 231055                    | NO. 1 VHF AERIAL                   |           |          |          |                           |           |           | Component ATA:23 |
| PN:16-21-1T               | MOS/MSC                            | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 23.055               | AFL                                | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 23-20-1626 |                                    |           |          |          |                           |           |           |                  |
| 231056                    | NO. 2 VHF AERIAL                   |           |          |          |                           |           |           | Component ATA:23 |
| PN:16-21-1T               | MOS/MSC                            | 03-Jan-12 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                | 4572.3    |          |          |                           |           |           |                  |
| WC#: 23.055               | AFL                                | 2562      |          |          |                           |           |           |                  |
| PROC. REF: AMM 23-20-1626 |                                    |           |          |          |                           |           |           |                  |
| 231058                    | AUDIO TONE GENERATOR               |           |          |          |                           |           |           | Component ATA:23 |
| PN:M1285AC                | MOS/MSC                            | 30-Aug-96 | O/C      |          |                           |           |           |                  |
| SN:9604334                | HRS                                | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 23.060               | AFL                                | 9         |          |          |                           |           |           |                  |
| PROC. REF: MMA 23-50-67   |                                    |           |          |          |                           |           |           |                  |
| 231061                    | NO. 1 RADIO MANAGEMENT UNIT        |           |          |          |                           |           |           | Component ATA:23 |
| PN:7013270-983            | MOS/MSC                            | 21-Feb-20 | O/C      |          |                           |           |           |                  |
| SN:10027683               | HRS                                | 5797.9    |          |          |                           |           |           |                  |
| WC#: 23.065               | AFL                                | 3397      |          |          |                           |           |           |                  |
| PROC. REF: AMM 23-80-05   |                                    |           |          |          |                           |           |           |                  |
| 231062                    | NO. 2 RADIO MANAGEMENT UNIT        |           |          |          |                           |           |           | Component ATA:23 |
| PN:7013270-983            | MOS/MSC                            | 21-Feb-20 | O/C      |          |                           |           |           |                  |
| SN:11037691               | HRS                                | 5797.9    |          |          |                           |           |           |                  |
| WC#: 23.065               | AFL                                | 3397      |          |          |                           |           |           |                  |
| PROC. REF: AMM 23-80-05   |                                    |           |          |          |                           |           |           |                  |
| 231064                    | CLEARANCE DELIVERY CONTROL         |           |          |          |                           |           |           | Component ATA:23 |
| PN:7513000-835            | MOS/MSC                            | 09-Mar-04 | O/C      | TSN 0    |                           |           |           |                  |
| SN:03112586               | HRS                                | 2632.6    |          | TSN 0    |                           |           |           |                  |
| WC#: 23.070               | AFL                                | 1434      |          | TSN 0    |                           |           |           |                  |
| 234001                    | MOBILE RADIO/TELEPHONE TRANSCEIVER |           |          |          |                           |           |           | Component ATA:23 |
| PN:724855-802             | MOS/MSC                            | 02-Dec-22 | O/C      |          |                           |           |           |                  |
| SN:MSA-5702               | HRS                                | 6488.1    |          |          |                           |           |           |                  |
| WC#: 23.075               | AFL                                | 3901      |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                             | Unit                                   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------------------------------------------|----------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 23 - COMMUNICATIONS                             |                                        |           |          |          |                           |           |           |                  |
| 234007                                              | MOBILE RADIO ANTENNA                   |           |          |          |                           |           |           | Component ATA:23 |
| PN:902131-1                                         | MOS/MSC                                | 30-Aug-96 | O/C      |          |                           |           |           |                  |
| SN:00355                                            | HRS                                    | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 23.080                                         | AFL                                    | 9         |          |          |                           |           |           |                  |
| 234013                                              | COCKPIT MOBILE RADIO TELEPHONE HANDSET |           |          |          |                           |           |           | Component ATA:23 |
| PN:724866-808                                       | MOS/MSC                                | 30-Aug-96 | O/C      |          |                           |           |           |                  |
| SN:MX23012                                          | HRS                                    | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 23.085                                         | AFL                                    | 9         |          |          |                           |           |           |                  |
| PROC. REF: MMA 23-16-05, MMA 23-16-10, AMM 23-17-05 |                                        |           |          |          |                           |           |           |                  |
| 234019                                              | CABIN MOBILE RADIO TELEPHONE HANDSET   |           |          |          |                           |           |           | Component ATA:23 |
| PN:724866-809                                       | MOS/MSC                                | 30-Aug-96 | O/C      |          |                           |           |           |                  |
| SN:MX22925                                          | HRS                                    | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 23.085                                         | AFL                                    | 9         |          |          |                           |           |           |                  |
| PROC. REF: MMA 23-16-05, MMA 23-16-10, AMM 23-17-05 |                                        |           |          |          |                           |           |           |                  |
| 234041                                              | FLITEPHONE AUXILIARY BELL              |           |          |          |                           |           |           | Component ATA:23 |
| PN:300-2070-000                                     | MOS/MSC                                | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                                          | HRS                                    | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 23.090                                         | AFL                                    | 0         |          |          |                           |           |           |                  |
| 235001                                              | NO. 1 AUDIO CONTROLLER                 |           |          |          |                           |           |           | Component ATA:23 |
| PN:7511001-909                                      | MOS/MSC                                | 30-Aug-96 | O/C      |          |                           |           |           |                  |
| SN:96021751                                         | HRS                                    | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 23.095                                         | AFL                                    | 9         |          |          |                           |           |           |                  |
| PROC. REF: MMA 23-50-67                             |                                        |           |          |          |                           |           |           |                  |
| 235002                                              | NO. 2 AUDIO CONTROLLER                 |           |          |          |                           |           |           | Component ATA:23 |
| PN:7511001-909                                      | MOS/MSC                                | 30-Aug-96 | O/C      |          |                           |           |           |                  |
| SN:96021770                                         | HRS                                    | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 23.095                                         | AFL                                    | 9         |          |          |                           |           |           |                  |
| PROC. REF: MMA 23-50-67                             |                                        |           |          |          |                           |           |           |                  |
| 235017                                              | NO. 1 HANDHELD AUDIO MICROPHONE        |           |          |          |                           |           |           | Component ATA:23 |
| PN:488T                                             | MOS/MSC                                | 19-Nov-96 | O/C      |          |                           |           |           |                  |
| SN:76091                                            | HRS                                    | 28        |          |          |                           |           |           |                  |
| WC#: 23.100                                         | AFL                                    | 16        |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                           | Unit                                                        | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                 | Disposition      |
|-------------------------------------------------------------------|-------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|---------------------------|------------------|
| ATA 23 - COMMUNICATIONS                                           |                                                             |           |          |          |                           |           |                           |                  |
| 235019                                                            | NO. 2 HANDHELD AUDIO MICROPHONE                             |           |          |          |                           |           |                           | Component ATA:23 |
| PN:488T                                                           | MOS/MSC                                                     | 19-Nov-96 | O/C      |          |                           |           |                           |                  |
| SN:76160                                                          | HRS                                                         | 28        |          |          |                           |           |                           |                  |
| WC#: 23.100                                                       | AFL                                                         | 16        |          |          |                           |           |                           |                  |
| 237001                                                            | COCKPIT VOICE RECORDER                                      |           |          |          |                           |           |                           | Component ATA:23 |
| PN:1602-01-03                                                     | MOS/MSC                                                     | 25-Jun-20 | O/C      |          |                           |           |                           |                  |
| SN:481                                                            | HRS                                                         | 5801      |          | TSN 5785 |                           |           |                           |                  |
| WC#: 23.105                                                       | AFL                                                         | 3399      |          |          |                           |           |                           |                  |
| PROC. REF: MMA 23-70-05, MMA 23-70-35, AMM 23-70-15, AMM 23-70-25 |                                                             |           |          |          |                           |           | WO#: N950PC 48 MONTH INSP |                  |
| 237004                                                            | COCKPIT VOICE RECORDER NO.1 MICROPHONE                      |           |          |          |                           |           |                           | Component ATA:23 |
| PN:16101-02                                                       | MOS/MSC                                                     | 30-Aug-96 | O/C      |          |                           |           |                           |                  |
| SN:1446                                                           | HRS                                                         | 16        |          | TSN 0    |                           |           |                           |                  |
| WC#: 23.110                                                       | AFL                                                         | 9         |          |          |                           |           |                           |                  |
| 237005                                                            | COCKPIT VOICE RECORDER NO.2 MICROPHONE                      |           |          |          |                           |           |                           | Component ATA:23 |
| PN:16101-02                                                       | MOS/MSC                                                     | 30-Aug-96 | O/C      |          |                           |           |                           |                  |
| SN:1447                                                           | HRS                                                         | 16        |          | TSN 0    |                           |           |                           |                  |
| WC#: 23.110                                                       | AFL                                                         | 9         |          |          |                           |           |                           |                  |
| 237014                                                            | COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON            |           |          |          |                           |           |                           | Component ATA:23 |
| PN:DK/120/90                                                      | MOS                                                         | 27-Feb-20 | 72       | TSN 8    | 27-Jun-25                 |           | 878 d                     | OVERHAUL         |
| SN:AT139306                                                       | HRS                                                         | 5801      |          | TSN 0    |                           |           |                           |                  |
| WC#: 23.105                                                       | AFL                                                         | 3399      |          | TSN 0    |                           |           |                           |                  |
| PROC. REF: MMA 23-70-35, AMM 23-70-15, AMM 23-70-25               |                                                             |           |          |          |                           |           | WO#: N950PC 48 MONTH INSP |                  |
| 237015                                                            | TEST COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON       |           |          |          |                           |           |                           | Service ATA:23   |
|                                                                   | MOS                                                         | 10-Feb-22 | 24       |          | 10-Feb-24                 |           | 375 d                     |                  |
|                                                                   | HRS                                                         |           |          |          |                           |           |                           |                  |
| WC#: 23.105                                                       | AFL                                                         |           |          |          |                           |           |                           |                  |
| PROC. REF: MMA 23-70-35, AMM 23-70-15, AMM 23-70-25               |                                                             |           |          |          |                           |           | WO#: N950PC 48 MONTH INSP |                  |
| 237016                                                            | CLEAN/TEST COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON |           |          |          |                           |           |                           | Service ATA:23   |
|                                                                   | MOS                                                         | 11-Feb-22 | 24       |          | 11-Feb-24                 |           | 376 d                     |                  |
|                                                                   | HRS                                                         | 6264.3    |          |          |                           |           |                           |                  |
| WC#: 23.105                                                       | AFL                                                         | 3756      |          |          |                           |           |                           |                  |
| PROC. REF: MMA 23-70-35, AMM 23-70-15, AMM 23-70-25               |                                                             |           |          |          |                           |           | WO#: N950PC 48 MONTH INSP |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                               | Unit                                                             | C/W       | Interval   | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|---------------------------------------|------------------------------------------------------------------|-----------|------------|----------|---------------------------|-----------|--------------|------------------|
| ATA 23 - COMMUNICATIONS               |                                                                  |           |            |          |                           |           |              |                  |
| 237017                                | REPLACE COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON BATTERY |           |            |          |                           |           |              | Service ATA:23   |
|                                       | MOS/MSC                                                          | 27-Feb-20 | DUE        |          | 01-Jul-26 (M)             |           | 1247 d       |                  |
|                                       | HRS                                                              |           |            |          |                           |           |              |                  |
| WC#: 23.105                           | AFL                                                              |           |            |          |                           |           |              |                  |
| 237019                                | LEFT COCKPIT VOICE RECORDER CONTROL                              |           |            |          |                           |           |              | Component ATA:23 |
| PN:1614-01                            | MOS/MSC                                                          | 30-Aug-96 | O/C        |          |                           |           |              |                  |
| SN:216                                | HRS                                                              | 16        |            | TSN 0    |                           |           |              |                  |
| WC#: 23.125                           | AFL                                                              | 9         |            |          |                           |           |              |                  |
| 237020                                | RIGHT COCKPIT VOICE RECORDER CONTROL                             |           |            |          |                           |           |              | Component ATA:23 |
| PN:93-A151-20                         | MOS/MSC                                                          | 30-May-96 | O/C        |          |                           |           |              |                  |
| SN:UNKNOWN                            | HRS                                                              | 0         |            | TSN 0    |                           |           |              |                  |
| WC#: 23.125                           | AFL                                                              | 0         |            |          |                           |           |              |                  |
| 237021                                | VOICE RECORDER INERTIA SWITCH                                    |           |            |          |                           |           |              | Component ATA:23 |
| PN:3L0-453/2                          | MOS/MSC                                                          | 30-Aug-96 | O/C        |          |                           |           |              |                  |
| SN:5413                               | HRS                                                              | 16        |            | TSN 0    |                           |           |              |                  |
| WC#: 23.115                           | AFL                                                              | 9         |            |          |                           |           |              |                  |
| 237022                                | COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON BATTERY         |           |            |          |                           |           |              | Component ATA:23 |
| PN:43530                              | MOS/MSC                                                          | 06-Jan-14 | O/C        | TSN 0    |                           |           |              |                  |
| SN:UNKNOWN                            | HRS                                                              | 5056.7    |            | TSN 0    |                           |           |              |                  |
|                                       | AFL                                                              | 2830      |            | TSN 0    |                           |           |              |                  |
| 238015                                | SELCAL DECODER UNIT                                              |           |            |          |                           |           |              | Component ATA:23 |
| PN:1200008-001                        | MOS/MSC                                                          | 30-Aug-96 | O/C        |          |                           |           |              |                  |
| SN:157                                | HRS                                                              | 16        |            | TSN 0    |                           |           |              |                  |
| WC#: 23.120                           | AFL                                                              | 9         |            |          |                           |           |              |                  |
| PROC. REF: MMA 23-20-05, AMM 23-20-10 |                                                                  |           |            |          |                           |           |              |                  |
| 238018 <sup>U</sup>                   | SELCAL CODE CALL SIGN                                            |           |            |          |                           |           |              | Service ATA:23   |
|                                       | MOS/MSC                                                          |           | DUE        |          |                           |           |              |                  |
|                                       | HRS                                                              |           |            |          |                           |           |              |                  |
|                                       | AFL                                                              |           |            |          |                           |           |              |                  |
| ATA 24 - ELECTRICAL POWER             |                                                                  |           |            |          |                           |           |              |                  |
| 240001                                | INSPECT/CHECK NO. 1 ENGINE STARTER/GENERATOR                     |           |            |          |                           |           |              | Service ATA:24   |
| PN:23080-064                          | MOS                                                              | 11-Oct-22 |            |          |                           |           |              |                  |
| SN:6568                               | HRS                                                              | 6446.4    | 200 (+200) |          | 6646.4                    | 6846.4    | 118.1 (+200) |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                                                      | C/W       | Interval                                               | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition                         |
|---------------------------|-----------------------------------------------------------|-----------|--------------------------------------------------------|----------|---------------------------|-----------|---------------|-------------------------------------|
| ATA 24 - ELECTRICAL POWER |                                                           |           |                                                        |          |                           |           |               |                                     |
| WC#: 24.045               | AFL                                                       | 3873      | PROC. REF: AFMS OUT OF PHASE INSPECTIONS, AMM 24-30-21 |          |                           |           |               |                                     |
| 240001                    | INSPECT/CHECK NO. 2 ENGINE STARTER/GENERATOR              |           |                                                        |          |                           |           |               | Service ATA:24                      |
| PN:23080-064              | MOS                                                       | 11-Oct-22 |                                                        |          |                           |           |               |                                     |
| SN:3161                   | HRS                                                       | 6446.4    | 200 (+200)                                             |          | 6646.4                    | 6846.4    | 118.1 (+200)  |                                     |
| WC#: 24.045               | AFL                                                       | 3873      | PROC. REF: AFMS OUT OF PHASE INSPECTIONS, AMM 24-30-21 |          |                           |           |               |                                     |
| 240002                    | OPERATE NO.1 AND NO.2 MAIN STATIC INVERTERS               |           |                                                        |          |                           |           |               | Service ATA:24                      |
|                           | MOS                                                       | 15-Oct-19 |                                                        |          |                           |           |               |                                     |
|                           | HRS                                                       | 5795.3    | 800 (+40/-10)                                          |          | 6595.3                    | 6635.3    | 67 (+40)      |                                     |
| WC#: 24.010               | AFL                                                       | 3397      | PROC. REF: AFMS INSPECTION B1                          |          |                           |           |               |                                     |
|                           |                                                           |           |                                                        |          |                           |           |               | PKG:2,8<br>WO#: N950PC B & C CHECK  |
| 240003                    | FUNCTION TEST FREQUENCY WILD A.C. SYSTEM                  |           |                                                        |          |                           |           |               | Service ATA:24                      |
|                           | MOS                                                       | 18-Aug-17 |                                                        |          |                           |           |               |                                     |
|                           | HRS                                                       | 5554.6    | 3200 (+150/-50)                                        |          | 8754.6                    | 8904.6    | 2226.3 (+150) |                                     |
| WC#: 24.030               | AFL                                                       | 3197      | PROC. REF: AFMS INSPECTION D1, AMM 24-22-02            |          |                           |           |               |                                     |
|                           |                                                           |           |                                                        |          |                           |           |               | PKG:4,32                            |
| 240004                    | CHECK BUSBAR CONTACTOR CONTROL                            |           |                                                        |          |                           |           |               | Service ATA:24                      |
|                           | MOS                                                       | 06-May-15 |                                                        |          |                           |           |               |                                     |
|                           | HRS                                                       | 5125.6    | 1600 (+50/-50)                                         |          | 6725.6                    | 6775.6    | 197.3 (+50)   |                                     |
| WC#: 24.145               | AFL                                                       | 2873      | PROC. REF: AFMS INSPECTION C1                          |          |                           |           |               |                                     |
|                           |                                                           |           |                                                        |          |                           |           |               | PKG:3,20<br>WO#: N950PC B & C CHECK |
| 240005                    | FUNCTIONAL TEST APU GENERATOR OVERHEAT INDICATION CIRCUIT |           |                                                        |          |                           |           |               | Service ATA:24                      |
|                           | MOS                                                       | 18-Aug-17 |                                                        |          |                           |           |               |                                     |
|                           | HRS                                                       | 5554.6    | 3200 (+150/-50)                                        |          | 8754.6                    | 8904.6    | 2226.3 (+150) |                                     |
| WC#: 24.180               | AFL                                                       | 3197      | PROC. REF: AFMS INSPECTION D1, AMM 24-36-03            |          |                           |           |               |                                     |
|                           |                                                           |           |                                                        |          |                           |           |               | PKG:4,32                            |
| 240006                    | CHECK D.C. BUSBAR PROTECTION/VOLTAGE SENSING UNIT         |           |                                                        |          |                           |           |               | Service ATA:24                      |
|                           | MOS                                                       | 18-Aug-17 |                                                        |          |                           |           |               |                                     |
|                           | HRS                                                       | 5554.6    | 3200 (+150/-50)                                        |          | 8754.6                    | 8904.6    | 2226.3 (+150) |                                     |
| WC#: 24.070               | AFL                                                       | 3197      | PROC. REF: AFMS INSPECTION D6, AMM 24-30-142           |          |                           |           |               |                                     |
|                           |                                                           |           |                                                        |          |                           |           |               | PKG:4,37                            |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                      | Unit                                                        | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                           | Disposition    |
|----------------------------------------------|-------------------------------------------------------------|-----------|-----------------|----------|---------------------------|-----------|-------------------------------------|----------------|
| ATA 24 - ELECTRICAL POWER                    |                                                             |           |                 |          |                           |           |                                     |                |
| 240007 <sup>S</sup>                          | BENCH CHECK GROUND POWER OVERVOLTAGE SENSOR (IF FITTED).    |           |                 |          |                           |           |                                     | Service ATA:24 |
|                                              | MOS                                                         | 18-Aug-17 |                 |          |                           |           |                                     |                |
|                                              | HRS                                                         | 5554.6    | 3200 (+150/-50) |          |                           |           |                                     |                |
| WC#: 24.110                                  | AFL                                                         | 3197      |                 |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION D7, AMM 24-30-146 |                                                             |           |                 |          |                           |           | PKG:4,38                            |                |
| 240009                                       | FUNCTIONAL TEST D.C. GENERATING SYSTEM                      |           |                 |          |                           |           |                                     | Service ATA:24 |
|                                              | MOS                                                         | 15-Oct-19 |                 |          |                           |           |                                     |                |
|                                              | HRS                                                         | 5795.3    | 800 (+40/-10)   |          | 6595.3                    | 6635.3    | 67 (+40)                            |                |
| WC#: 24.065                                  | AFL                                                         | 3397      |                 |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION B1, AMM 24-30-01  |                                                             |           |                 |          |                           |           | PKG:2,8<br>WO#: N950PC B & C CHECK  |                |
| 240010                                       | INSPECT PE, PS1 AND PS2 BUSBAR FEEDER CABLES BELOW PANEL DA |           |                 |          |                           |           |                                     | Service ATA:24 |
|                                              | MOS                                                         | 06-May-15 |                 |          |                           |           |                                     |                |
|                                              | HRS                                                         | 5125.6    | 1600 (+50/-50)  |          | 6725.6                    | 6775.6    | 197.3 (+50)                         |                |
| WC#: 24.160                                  | AFL                                                         | 2873      |                 |          |                           |           |                                     |                |
| PROC. REF: AMM 24-01-00, AFMS INSPECTION C6  |                                                             |           |                 |          |                           |           | PKG:3,25<br>WO#: N950PC B & C CHECK |                |
| 240011                                       | FUNCTIONAL TEST OF THE BUSBAR PE, PS1 AND PS2 FEEDER FUSES  |           |                 |          |                           |           |                                     | Service ATA:24 |
|                                              | MOS                                                         | 06-May-15 |                 |          |                           |           |                                     |                |
|                                              | HRS                                                         | 5125.6    | 1600 (+50/-50)  |          | 6725.6                    | 6775.6    | 197.3 (+50)                         |                |
| WC#: 24.150                                  | AFL                                                         | 2873      |                 |          |                           |           |                                     |                |
| PROC. REF: AMM 24-01-00, AFMS INSPECTION C7  |                                                             |           |                 |          |                           |           | PKG:3,26<br>WO#: N950PC B & C CHECK |                |
| 240012 <sup>U</sup>                          | INSPECT BUSBAR PE, PS1 AND PS2 FEEDER SYSTEM CONNECTIONS    |           |                 |          |                           |           |                                     | Service ATA:24 |
|                                              | MOS                                                         | 06-May-15 |                 |          |                           |           |                                     |                |
|                                              | HRS                                                         | 5125.6    | 1600 (+50/-50)  |          | 6725.6                    | 6775.6    | 197.3 (+50)                         |                |
| WC#: 24.165                                  | AFL                                                         | 2873      |                 |          |                           |           |                                     |                |
| PROC. REF: AMM 24-01-00, AFMS INSPECTION C7  |                                                             |           |                 |          |                           |           | PKG:3,26<br>WO#: N950PC B & C CHECK |                |
| 240013                                       | FUNCTION TEST ALL CIRCUIT BREAKERS                          |           |                 |          |                           |           |                                     | Service ATA:24 |
|                                              | MOS                                                         | 18-Aug-17 |                 |          |                           |           |                                     |                |
|                                              | HRS                                                         | 5554.6    | 3200 (+150/-50) |          | 8754.6                    | 8904.6    | 2226.3 (+150)                       |                |
| WC#: 24.005                                  | AFL                                                         | 3197      |                 |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION D1                |                                                             |           |                 |          |                           |           | PKG:4,32                            |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                                               | Unit                                                                       | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                          | Disposition    |
|---------------------------------------------------------------------------------------|----------------------------------------------------------------------------|-----------|-----------------|----------|---------------------------|-----------|------------------------------------|----------------|
| ATA 24 - ELECTRICAL POWER                                                             |                                                                            |           |                 |          |                           |           |                                    |                |
| 240014                                                                                | FUNCTION TEST MAIN GENERATOR CONTROL UNIT (GCU)                            |           |                 |          |                           |           |                                    | Service ATA:24 |
|                                                                                       | MOS                                                                        | 18-Aug-17 |                 |          |                           |           |                                    |                |
|                                                                                       | HRS                                                                        | 5554.6    | 3200 (+150/-50) |          | 8754.6                    | 8904.6    | 2226.3 (+150)                      |                |
| WC#: 24.040                                                                           | AFL                                                                        | 3197      |                 |          |                           |           |                                    |                |
| PROC. REF: AFMS INSPECTION D1, AMM 24-30-07                                           |                                                                            |           |                 |          |                           |           | PKG:4,32                           |                |
| 240015                                                                                | FUNCTION TEST APU GENERATOR CONTROL UNIT (GCU)                             |           |                 |          |                           |           |                                    | Service ATA:24 |
|                                                                                       | MOS                                                                        | 18-Aug-17 |                 |          |                           |           |                                    |                |
|                                                                                       | HRS                                                                        | 5554.6    | 3200 (+150/-50) |          | 8754.6                    | 8904.6    | 2226.3 (+150)                      |                |
| WC#: 24.040                                                                           | AFL                                                                        | 3197      |                 |          |                           |           |                                    |                |
| PROC. REF: AFMS INSPECTION D1, AMM 24-36-03                                           |                                                                            |           |                 |          |                           |           | PKG:4,32                           |                |
| 240016                                                                                | INSPECT ELECTRICAL CABLE PRESSURE BUNGS (IN THE FORWARD PRESSURE BULKHEAD) |           |                 |          |                           |           |                                    | Service ATA:24 |
|                                                                                       | MOS                                                                        | 18-Aug-17 |                 |          |                           |           |                                    |                |
|                                                                                       | HRS                                                                        | 5554.6    | 3200 (+150/-50) |          | 8754.6                    | 8904.6    | 2226.3 (+150)                      |                |
| WC#: 24.235                                                                           | AFL                                                                        | 3197      |                 |          |                           |           |                                    |                |
| PROC. REF: AMM 24-01-00, AFMS INSPECTION D3                                           |                                                                            |           |                 |          |                           |           | PKG:4,34                           |                |
| 240017                                                                                | INSPECT/CHECK EARTH STATIONS *16, *17, *18, AND *19                        |           |                 |          |                           |           |                                    | Service ATA:24 |
|                                                                                       | MOS                                                                        | 15-Oct-19 | 48 (+2m/-2m)    |          | 15-Oct-23                 | 15-Dec-23 | 257 d (+61)                        |                |
|                                                                                       | HRS                                                                        | 5795.3    |                 |          |                           |           |                                    |                |
| WC#: 24.155                                                                           | AFL                                                                        | 3397      |                 |          |                           |           |                                    |                |
| PROC. REF: AMM 24-01-00, AFMS INSPECTION G                                            |                                                                            |           |                 |          |                           |           | PKG:7<br>WO#: N950PC 48 MONTH INSP |                |
| 240018                                                                                | INSPECT ELECTRICAL CABLE PRESSURE BUNGS (IN THE REAR PRESSURE-BULKHEAD)    |           |                 |          |                           |           |                                    | Service ATA:24 |
|                                                                                       | MOS                                                                        | 18-Aug-17 |                 |          |                           |           |                                    |                |
|                                                                                       | HRS                                                                        | 5554.6    | 3200 (+150/-50) |          | 8754.6                    | 8904.6    | 2226.3 (+150)                      |                |
| WC#: 24.235                                                                           | AFL                                                                        | 3197      |                 |          |                           |           |                                    |                |
| PROC. REF: AMM 24-01-00, AFMS INSPECTION D7                                           |                                                                            |           |                 |          |                           |           | PKG:4,38                           |                |
| 240024                                                                                | INSPECT/CHECK APU STARTER/GENERATOR                                        |           |                 |          |                           |           |                                    | Service ATA:24 |
| PN:23080-005                                                                          | MOS                                                                        | 15-Oct-19 |                 |          |                           |           |                                    |                |
| SN:2175                                                                               | HRS                                                                        | 5795.3    |                 |          |                           |           |                                    |                |
| WC#: 24.085                                                                           | AFL                                                                        | 3397      |                 |          |                           |           |                                    |                |
|                                                                                       | APH                                                                        | 2963.42   | 500             |          | 3463.42                   |           | 114.3                              |                |
| PROC. REF: AFMS OUT OF PHASE INSPECTIONS, AFMS OUT OF PHASE INSPECTIONS, AMM 24-30-21 |                                                                            |           |                 |          |                           |           |                                    |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                     | Unit                                                                                                               | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                             | Disposition    |
|-------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------|-----------|-----------------|----------|---------------------------|-----------|---------------------------------------|----------------|
| ATA 24 - ELECTRICAL POWER                                   |                                                                                                                    |           |                 |          |                           |           |                                       |                |
| 240025                                                      | INSPECT ELECTRICAL CABLE PRESSURE BUNGS (IN THE FUSELAGE KEEL AT THE FRONT SPAR)                                   |           |                 |          |                           |           |                                       | Service ATA:24 |
|                                                             | MOS                                                                                                                | 18-Aug-17 |                 |          |                           |           |                                       |                |
|                                                             | HRS                                                                                                                | 5554.6    | 3200 (+150/-50) |          | 8754.6                    | 8904.6    | 2226.3 (+150)                         |                |
| WC#: 24.245                                                 | AFL                                                                                                                | 3197      |                 |          |                           |           |                                       |                |
| PROC. REF: AMM 24-01-00, AFMS INSPECTION D5                 |                                                                                                                    |           |                 |          |                           |           | PKG:4,36                              |                |
| 240026                                                      | INSPECT ELECTRICAL CABLE PRESSURE BUNGS (IN THE FORWARD PRESSURE BULKHEAD)                                         |           |                 |          |                           |           |                                       | Service ATA:24 |
|                                                             | MOS                                                                                                                | 18-Aug-17 |                 |          |                           |           |                                       |                |
|                                                             | HRS                                                                                                                | 5554.6    | 3200 (+150/-50) |          | 8754.6                    | 8904.6    | 2226.3 (+150)                         |                |
| WC#: 24.240                                                 | AFL                                                                                                                | 3197      |                 |          |                           |           |                                       |                |
| PROC. REF: AMM 24-01-00, AFMS INSPECTION D4                 |                                                                                                                    |           |                 |          |                           |           | PKG:4,35                              |                |
| 240027                                                      | CHECK MAIN BATTERIES                                                                                               |           |                 |          |                           |           |                                       | Service ATA:24 |
|                                                             | MOS                                                                                                                | 18-Aug-17 |                 |          |                           |           |                                       |                |
|                                                             | HRS                                                                                                                | 5554.6    | 3200 (+150/-50) |          | 8754.6                    | 8904.6    | 2226.3 (+150)                         |                |
| WC#: 24.250                                                 | AFL                                                                                                                | 3197      |                 |          |                           |           |                                       |                |
| PROC. REF: AFMS INSPECTION D7, AMM 24-30-104, AMM 24-30-151 |                                                                                                                    |           |                 |          |                           |           | PKG:4,38                              |                |
| 240028                                                      | VISUAL INSPECTION PANEL GG AND TERMINAL BLOCK M                                                                    |           |                 |          |                           |           |                                       | Service ATA:24 |
|                                                             | MOS                                                                                                                | 11-Feb-22 |                 |          |                           |           |                                       |                |
|                                                             | HRS                                                                                                                | 6264.3    | 400 (+10%)      |          | 6664.3                    | 6704.3    | 136 (+40)                             |                |
| WC#: 24.095                                                 | AFL                                                                                                                | 3756      |                 |          |                           |           |                                       |                |
| PROC. REF: AMM 24-01-00, AFMS OUT OF PHASE INSPECTIONS      |                                                                                                                    |           |                 |          |                           |           |                                       |                |
| 240029                                                      | VISUAL INSPECTION FOR DISCOLORATION AND SIGNS OF HEAT DISTRESS, INSPECT DA-PANEL FOR PROPER MOUNTING OF COMPONENTS |           |                 |          |                           |           |                                       | Service ATA:24 |
|                                                             | MOS                                                                                                                | 11-Oct-22 | 12 (+1m/-1m)    |          | 11-Oct-23                 | 11-Nov-23 | 253 d (+31)                           |                |
|                                                             | HRS                                                                                                                | 6446.4    |                 |          |                           |           |                                       |                |
| WC#: 24.260                                                 | AFL                                                                                                                | 3873      |                 |          |                           |           |                                       |                |
| PROC. REF: AFMS INSPECTION E6                               |                                                                                                                    |           |                 |          |                           |           | PKG:5,49<br>WO#: N950PC 48 MONTH INSP |                |
| 240030                                                      | FUNCTION TEST CABIN INVERTER (115 VAC) SYSTEM (IF INSTALLED)                                                       |           |                 |          |                           |           |                                       | Service ATA:24 |
|                                                             | MOS                                                                                                                | 11-Oct-22 |                 |          |                           |           |                                       |                |
|                                                             | HRS                                                                                                                | 6446.4    | 200 (+10%/-10%) |          | 6646.4                    | 6666.4    | 118.1 (+20)                           |                |
| WC#: 24.255                                                 | AFL                                                                                                                | 3873      |                 |          |                           |           |                                       |                |
| PROC. REF: AFMS OUT OF PHASE INSPECTIONS                    |                                                                                                                    |           |                 |          |                           |           |                                       |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                      | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition            |
|---------------------------|---------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------------|
| ATA 24 - ELECTRICAL POWER |                           |           |          |          |                           |           |           |                        |
| 240050 <sup>U</sup>       | BATTERY- SECURE LANE      |           |          |          |                           |           |           | Component ATA:24       |
| PN:500-05                 | MOS/MSC                   | 15-Apr-21 | A/R      |          |                           |           |           |                        |
| SN:0119                   | HRS                       |           |          |          |                           |           |           |                        |
|                           | AFL                       |           |          |          |                           |           |           |                        |
| 242001                    | NO. 1 (MAIN) INVERTER     |           |          |          |                           |           |           | Component ATA:24       |
| PN:ASH664-5               | MOS/MSC                   | 25-Jun-20 | O/C      |          |                           |           |           |                        |
| SN:TP1024                 | HRS                       | 5801      |          |          |                           |           |           |                        |
| WC#: 24.015               | AFL                       | 3399      |          |          |                           |           |           |                        |
| PROC. REF: AMM 24-21-102  |                           |           |          |          |                           |           |           |                        |
| 242002                    | NO. 2 (MAIN) INVERTER     |           |          |          |                           |           |           | Component ATA:24       |
| PN:ASH-664-5              | MOS/MSC                   | 10-Oct-01 | O/C      |          |                           |           |           |                        |
| SN:LG1291                 | HRS                       | 2057      |          |          |                           |           |           |                        |
| WC#: 24.015               | AFL                       | 1144      |          |          |                           |           |           |                        |
| PROC. REF: AMM 24-21-102  |                           |           |          |          |                           |           |           |                        |
| 242013                    | NO. 3 (STANDBY) INVERTER  |           |          |          |                           |           |           | Component ATA:24       |
| PN:PC250                  | MOS/MSC                   | 21-Jun-11 | O/C      |          |                           |           |           |                        |
| SN:6146                   | HRS                       | 4454.6    |          | TSO 1451 |                           |           |           |                        |
| WC#: 24.015               | AFL                       | 2487      |          |          |                           |           |           |                        |
| PROC. REF: AMM 24-21-105  |                           |           |          |          |                           |           |           |                        |
| 242031                    | NO. 1 INVERTER CONTACTOR  |           |          |          |                           |           |           | Component ATA:24       |
| PN:LDA200818C             | MOS                       | 06-May-13 |          | TSO 0    |                           |           |           | OVERHAUL               |
| SN:X2825                  | HRS                       | 4942.5    | 5000     | TSO 0    | 9942.5                    |           | 3414.2    |                        |
| WC#: 24.020               | AFL                       | 2767      |          | TSO 0    |                           |           |           |                        |
| 242032                    | NO. 2 INVERTER CONTACTOR  |           |          |          |                           |           |           | Component ATA:24       |
| PN:LDA200818C             | MOS                       | 06-May-13 |          | TSO 0    |                           |           |           | OVERHAUL               |
| SN:W4141                  | HRS                       | 4942.5    | 5000     | TSO 0    | 9942.5                    |           | 3414.2    |                        |
| WC#: 24.020               | AFL                       | 2767      |          | TSO 0    |                           |           |           |                        |
| 242073                    | NO. 1 ENGINE AC GENERATOR |           |          |          |                           |           |           | Component ATA:24       |
| PN:BA02801-1              | MOS                       | 27-Feb-20 | 96       | TSO 1    | 27-Jan-28                 |           | 1822 d    | OVERHAUL               |
| SN:2617                   | HRS                       | 5801      | 3000     | TSO 0    | 8801                      |           | 2272.7    |                        |
| WC#: 24.025               | AFL                       | 3399      |          | TSO 0    |                           |           |           |                        |
| PROC. REF: AMM 24-22-21   |                           |           |          |          |                           |           |           | WO#: N950PC LH ENG MPI |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                            | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                                    | Disposition      |
|---------------------------|---------------------------------|-----------|----------|----------|---------------------------|-----------|----------------------------------------------|------------------|
| ATA 24 - ELECTRICAL POWER |                                 |           |          |          |                           |           |                                              |                  |
| 242074                    | NO. 2 ENGINE AC GENERATOR       |           |          |          |                           |           |                                              | Component ATA:24 |
| PN:BA02801-1              | MOS                             | 27-Feb-20 | 96       | TSO 3    | 27-Nov-27                 |           | 1761 d                                       | OVERHAUL         |
| SN:2221                   | HRS                             | 5801      | 3000     | TSO 0    | 8801                      |           | 2272.7                                       |                  |
| WC#: 24.025               | AFL                             | 3399      |          | TSO 0    |                           |           |                                              |                  |
| PROC. REF: AMM 24-22-21   |                                 |           |          |          |                           |           | WO#: N950PC RH ENG MPI/CZI                   |                  |
| 242097                    | LEFT AC GENERATOR CONTROL UNIT  |           |          |          |                           |           |                                              | Component ATA:24 |
| PN:CB02701                | MOS/MSC                         | 30-May-96 | O/C      |          |                           |           |                                              |                  |
| SN:1917                   | HRS                             | 0         |          | TSN 0    |                           |           |                                              |                  |
| WC#: 24.035               | AFL                             | 0         |          |          |                           |           |                                              |                  |
| 242098                    | RIGHT AC GENERATOR CONTROL UNIT |           |          |          |                           |           |                                              | Component ATA:24 |
| PN:CB02701                | MOS/MSC                         | 30-May-96 | O/C      |          |                           |           |                                              |                  |
| SN:1934                   | HRS                             | 0         |          | TSN 0    |                           |           |                                              |                  |
| WC#: 24.035               | AFL                             | 0         |          |          |                           |           |                                              |                  |
| 243001                    | NO. 1 ENGINE STARTER/GENERATOR  |           |          |          |                           |           |                                              | Component ATA:24 |
| PN:23080-064              | MOS                             | 11-Dec-18 |          | TSO 0    |                           |           |                                              | OVERHAUL         |
| SN:6568                   | HRS                             | 5678.1    | 1000     | TSO 0    | 6678.1                    |           | 149.8                                        |                  |
| WC#: 24.045               | AFL                             | 3323      |          | TSO 0    |                           |           |                                              |                  |
| PROC. REF: AMM 24-30-21   |                                 |           |          |          |                           |           | WO#: N950PC RH ENG MPI/CZI,N950PC LH ENG MPI |                  |
| 243002                    | NO. 2 ENGINE STARTER/GENERATOR  |           |          |          |                           |           |                                              | Component ATA:24 |
| PN:23080-064              | MOS                             | 13-May-19 |          | TSO 1    |                           |           |                                              | OVERHAUL         |
| SN:3161                   | HRS                             | 5795      | 1000     | TSO 0    | 6795                      |           | 266.7                                        |                  |
| WC#: 24.045               | AFL                             | 3396      |          | TSO 0    |                           |           |                                              |                  |
| PROC. REF: AMM 24-30-21   |                                 |           |          |          |                           |           | WO#: N950PC RH ENG MPI/CZI                   |                  |
| 243037                    | NO. 1 DC GENERATOR CONTROL UNIT |           |          |          |                           |           |                                              | Component ATA:24 |
| PN:51539-006H             | MOS/MSC                         | 30-May-96 | O/C      |          |                           |           |                                              |                  |
| SN:95578                  | HRS                             | 0         |          | TSN 0    |                           |           |                                              |                  |
| WC#: 24.050               | AFL                             | 0         |          |          |                           |           |                                              |                  |
| PROC. REF: AMM 24-30-07   |                                 |           |          |          |                           |           |                                              |                  |
| 243038                    | NO. 2 DC GENERATOR CONTROL UNIT |           |          |          |                           |           |                                              | Component ATA:24 |
| PN:51539-006H             | MOS/MSC                         | 30-May-96 | O/C      |          |                           |           |                                              |                  |
| SN:95783                  | HRS                             | 0         |          | TSN 0    |                           |           |                                              |                  |
| WC#: 24.050               | AFL                             | 0         |          |          |                           |           |                                              |                  |
| PROC. REF: AMM 24-30-07   |                                 |           |          |          |                           |           |                                              |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                               | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition                  |
|---------------------------|------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------------------|
| ATA 24 - ELECTRICAL POWER |                                    |           |          |          |                           |           |           |                              |
| 243049                    | H (UPPER) CONTACTOR                |           |          |          |                           |           |           | Component ATA:24             |
| PN:A.703-ZS               | MOS/MSC                            | 30-May-96 | O/C      |          |                           |           |           |                              |
| SN:CL55359                | HRS                                | 0         |          | TSN 0    |                           |           |           |                              |
| WC#: 24.055               | AFL                                | 0         |          |          |                           |           |           |                              |
| 243050                    | H (LOWER) CONTACTOR                |           |          |          |                           |           |           | Component ATA:24             |
| PN:A.703.ZS               | MOS/MSC                            | 30-May-96 | O/C      |          |                           |           |           |                              |
| SN:UNKNOWN                | HRS                                | 0         |          | TSN 0    |                           |           |           |                              |
| WC#: 24.055               | AFL                                | 0         |          |          |                           |           |           |                              |
| 243061                    | G (UPPER) CONTACTOR                |           |          |          |                           |           |           | Component ATA:24             |
| PN:A.703-FSS              | MOS/MSC                            | 30-May-96 | O/C      |          |                           |           |           |                              |
| SN:CL50418                | HRS                                | 0         |          | TSN 0    |                           |           |           |                              |
| WC#: 24.060               | AFL                                | 0         |          |          |                           |           |           |                              |
| 243062                    | G (LOWER) CONTACTOR                |           |          |          |                           |           |           | Component ATA:24             |
| PN:A.703.FSS              | MOS/MSC                            | 30-May-96 | O/C      |          |                           |           |           |                              |
| SN:UNKNOWN                | HRS                                | 0         |          | TSN 0    |                           |           |           |                              |
| WC#: 24.060               | AFL                                | 0         |          |          |                           |           |           |                              |
| 243079                    | DC VOLTAGE SENSING UNIT            |           |          |          |                           |           |           | Component ATA:24             |
| PN:U3626-2                | MOS/MSC                            | 30-May-96 | O/C      |          |                           |           |           |                              |
| SN:2082                   | HRS                                | 0         |          | TSN 0    |                           |           |           |                              |
| WC#: 24.070               | AFL                                | 0         |          |          |                           |           |           |                              |
| 243091                    | GROUND SUPPLY START (E) CONTACTOR  |           |          |          |                           |           |           | Component ATA:24<br>OVERHAUL |
| PN:LDG150-Y4              | MOS                                | 15-Apr-21 |          | TSO 0    |                           |           |           |                              |
| SN:B3615                  | HRS                                | 5960.1    | 6000     | TSO 0    | 11960.1                   |           | 5431.8    |                              |
| WC#: 24.075               | AFL                                | 3523      |          | TSO 0    |                           |           |           |                              |
| 243103                    | APU STARTER/GENERATOR CONTROL UNIT |           |          |          |                           |           |           | Component ATA:24             |
| PN:51539-006H             | MOS/MSC                            | 30-Aug-96 | O/C      |          |                           |           |           |                              |
| SN:96252                  | HRS                                | 16        |          | TSN 0    |                           |           |           |                              |
| WC#: 24.080               | AFL                                | 9         |          |          |                           |           |           |                              |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                 | Unit                  | C/W       | Interval | TSX/Adj.  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------------------------------------|-----------------------|-----------|----------|-----------|---------------------------|-----------|-----------|------------------|
| ATA 24 - ELECTRICAL POWER                               |                       |           |          |           |                           |           |           |                  |
| 243115                                                  | APU STARTER/GENERATOR |           |          |           |                           |           |           | Component ATA:24 |
| PN:23080-005                                            | MOS                   | 15-Oct-19 |          | TSO 0     |                           |           |           | OVERHAUL         |
| SN:2175                                                 | HRS                   | 5795.3    |          | TSO 0     |                           |           |           |                  |
| WC#: 24.085                                             | AFL                   | 3397      |          | TSO 0     |                           |           |           |                  |
|                                                         | APH                   | 2963.42   | 1000     | TSO 0     | 3963.42                   |           | 614.3     |                  |
| PROC. REF: MMA 49-16-00, AMM 24-30-21                   |                       |           |          |           |                           |           |           |                  |
| 243137                                                  | NO. 1 BATTERY         |           |          |           |                           |           |           | Component ATA:24 |
| PN:RG-390E                                              | MOS/MSC               | 11-Oct-22 | O/C      | TSN 0     |                           |           |           |                  |
| SN:412553743                                            | HRS                   | 6446.4    |          | TSN 0     |                           |           |           |                  |
| WC#: 24.090                                             | AFL                   | 3873      |          | TSN 0     |                           |           |           |                  |
| PROC. REF: AMM 24-30-104, AMM 24-30-151                 |                       |           |          |           |                           |           |           |                  |
| 243138                                                  | NO. 2 BATTERY         |           |          |           |                           |           |           | Component ATA:24 |
| PN:RG-390E                                              | MOS/MSC               | 11-Oct-22 | O/C      | TSN 13    |                           |           |           |                  |
| SN:41177422                                             | HRS                   | 6446      |          | TSN 305.4 |                           |           |           |                  |
| WC#: 24.090                                             | AFL                   | 3873      |          | TSN 226   |                           |           |           |                  |
| PROC. REF: AMM 24-30-104, AMM 24-30-151                 |                       |           |          |           |                           |           |           |                  |
| 243139                                                  | NO. 3 BATTERY         |           |          |           |                           |           |           | Component ATA:24 |
| PN:RG-126                                               | MOS/MSC               | 11-Oct-22 | O/C      |           |                           |           |           |                  |
| SN:40596196                                             | HRS                   | 6446.4    |          |           |                           |           |           |                  |
| WC#: 24.210                                             | AFL                   | 3873      |          |           |                           |           |           |                  |
| PROC. REF: AMM 24-30-153, AMM 24-30-154                 |                       |           |          |           |                           |           |           |                  |
| 243140                                                  | NO. 4 BATTERY         |           |          |           |                           |           |           | Component ATA:24 |
| PN:RG-126                                               | MOS/MSC               | 11-Oct-22 | O/C      |           |                           |           |           |                  |
| SN:40716880                                             | HRS                   | 6446.4    |          |           |                           |           |           |                  |
| WC#: 24.220                                             | AFL                   | 3873      |          |           |                           |           |           |                  |
| PROC. REF: AMM 24-30-153, AMM 24-30-154                 |                       |           |          |           |                           |           |           |                  |
| 243141                                                  | NO. 5 BATTERY         |           |          |           |                           |           |           | Component ATA:24 |
| PN:RG-126                                               | MOS/MSC               | 11-Oct-22 | O/C      |           |                           |           |           |                  |
| SN:40596181                                             | HRS                   | 6446.4    |          |           |                           |           |           |                  |
| WC#: 24.230                                             | AFL                   | 3873      |          |           |                           |           |           |                  |
| PROC. REF: AFMS 24-30-155, AMM 24-30-153, AMM 24-30-154 |                       |           |          |           |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                 | Unit                         | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition    |
|-----------------------------------------|------------------------------|-----------|----------------|----------|---------------------------|-----------|-------------|----------------|
| ATA 24 - ELECTRICAL POWER               |                              |           |                |          |                           |           |             |                |
| 243154                                  | CAPACITY CHECK NO. 1 BATTERY |           |                |          |                           |           |             | Service ATA:24 |
| PN:RG-390E                              | MOS                          | 11-Oct-22 | 12 (+30d/-30d) |          | 11-Oct-23                 | 10-Nov-23 | 253 d (+30) |                |
| SN:412553743                            | HRS                          | 6446.4    |                |          |                           |           |             |                |
| WC#: 24.090                             | AFL                          | 3873      |                |          |                           |           |             |                |
| PROC. REF: AMM 24-30-104, AMM 24-30-151 |                              |           |                |          |                           |           |             |                |
| 243155                                  | CAPACITY CHECK NO. 2 BATTERY |           |                |          |                           |           |             | Service ATA:24 |
| PN:RG-390E                              | MOS                          | 11-Oct-22 | 12 (+30d/-30d) |          | 11-Oct-23                 | 10-Nov-23 | 253 d (+30) |                |
| SN:41177422                             | HRS                          | 6446      |                |          |                           |           |             |                |
| WC#: 24.090                             | AFL                          | 3873      |                |          |                           |           |             |                |
| PROC. REF: AMM 24-30-104, AMM 24-30-151 |                              |           |                |          |                           |           |             |                |
| 243156                                  | CAPACITY CHECK NO. 3 BATTERY |           |                |          |                           |           |             | Service ATA:24 |
| PN:RG-126                               | MOS                          | 11-Oct-22 | 12 (+30d/-30d) |          | 11-Oct-23                 | 10-Nov-23 | 253 d (+30) |                |
| SN:40596196                             | HRS                          | 6446.4    | 500            |          | 6946.4                    |           | 418.1       |                |
| WC#: 24.210                             | AFL                          | 3873      |                |          |                           |           |             |                |
| PROC. REF: AMM 24-30-153, AMM 24-30-154 |                              |           |                |          |                           |           |             |                |
| 243157                                  | CAPACITY CHECK NO. 4 BATTERY |           |                |          |                           |           |             | Service ATA:24 |
| PN:RG-126                               | MOS                          | 11-Oct-22 | 12 (+30d/-30d) |          | 11-Oct-23                 | 10-Nov-23 | 253 d (+30) |                |
| SN:40716880                             | HRS                          | 6446.4    | 500            |          | 6946.4                    |           | 418.1       |                |
| WC#: 24.220                             | AFL                          | 3873      |                |          |                           |           |             |                |
| PROC. REF: AMM 24-30-153, AMM 24-30-154 |                              |           |                |          |                           |           |             |                |
| 243158                                  | CAPACITY CHECK NO. 5 BATTERY |           |                |          |                           |           |             | Service ATA:24 |
| PN:RG-126                               | MOS                          | 11-Oct-22 | 12 (+30d/-30d) |          | 11-Oct-23                 | 10-Nov-23 | 253 d (+30) |                |
| SN:40596181                             | HRS                          | 6446.4    | 500            |          | 6946.4                    |           | 418.1       |                |
| WC#: 24.230                             | AFL                          | 3873      |                |          |                           |           |             |                |
| PROC. REF: AMM 24-30-153, AMM 24-30-154 |                              |           |                |          |                           |           |             |                |
| 243194 <sup>U</sup>                     | BENCH TEST THERMO            |           |                |          |                           |           |             | Service ATA:24 |
|                                         | MOS/MSC                      | 24-Sep-21 | O/C            |          |                           |           |             |                |
|                                         | HRS                          |           |                |          |                           |           |             |                |
| WC#: 24.090                             | AFL                          |           |                |          |                           |           |             |                |
| 243195 <sup>U</sup>                     | BENCH TEST THERMO            |           |                |          |                           |           |             | Service ATA:24 |
|                                         | MOS/MSC                      | 24-Sep-21 | O/C            |          |                           |           |             |                |
|                                         | HRS                          |           |                |          |                           |           |             |                |
| WC#: 24.090                             | AFL                          |           |                |          |                           |           |             |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|---------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 24 - ELECTRICAL POWER |                     |           |          |          |                           |           |           |                  |
| 243238                    | OVERVOLTAGE SENSOR  |           |          |          |                           |           |           | Component ATA:24 |
| PN:E311TS                 | MOS/MSC             | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:CL55807                | HRS                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 24.110               | AFL                 | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 24-30-146  |                     |           |          |          |                           |           |           |                  |
| 243246                    | THERMAL SWITCH      |           |          |          |                           |           |           | Component ATA:24 |
| PN:21346-6                | MOS/MSC             | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:4382                   | HRS                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 24.115               | AFL                 | 0         |          |          |                           |           |           |                  |
| 243247                    | S CONTACTOR         |           |          |          |                           |           |           | Component ATA:24 |
| PN:LDA-200-B18C           | MOS/MSC             | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:W4158                  | HRS                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 24.120               | AFL                 | 0         |          |          |                           |           |           |                  |
| 243253                    | FORWARD U CONTACTOR |           |          |          |                           |           |           | Component ATA:24 |
| PN:LDA-200-B18C           | MOS/MSC             | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:W4169                  | HRS                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 24.120               | AFL                 | 0         |          |          |                           |           |           |                  |
| 243259                    | J CONTACTOR         |           |          |          |                           |           |           | Component ATA:24 |
| PN:A.700-RSS              | MOS/MSC             | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:CL49651                | HRS                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 24.125               | AFL                 | 0         |          |          |                           |           |           |                  |
| 243265                    | K CONTACTOR         |           |          |          |                           |           |           | Component ATA:24 |
| PN:A.700-RSS              | MOS/MSC             | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:CL49712                | HRS                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 24.125               | AFL                 | 0         |          |          |                           |           |           |                  |
| 243271                    | AFT U CONTACTOR     |           |          |          |                           |           |           | Component ATA:24 |
| PN:A.848-MAS              | MOS/MSC             | 31-Mar-05 | O/C      |          |                           |           |           |                  |
| SN:CM-97010               | HRS                 | 2813      |          |          |                           |           |           |                  |
| WC#: 24.130               | AFL                 | 1554      |          |          |                           |           |           |                  |
| 243277                    | L CONTACTOR         |           |          |          |                           |           |           | Component ATA:24 |
| PN:9124-9290              | MOS/MSC             | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:80110                  | HRS                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 24.135               | AFL                 | 0         |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                            | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|---------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 24 - ELECTRICAL POWER |                                 |           |          |          |                           |           |           |                  |
| 243283                    | M CONTACTOR                     |           |          |          |                           |           |           | Component ATA:24 |
| PN:9124-9290              | MOS/MSC                         | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:79777                  | HRS                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 24.135               | AFL                             | 0         |          |          |                           |           |           |                  |
| 243290 <sup>U</sup>       | OVERVOLTAGE RELAY               |           |          |          |                           |           |           | Component ATA:24 |
| PN:E-311TS                | MOS/MSC                         | 15-May-05 | O/C      |          |                           |           |           |                  |
| SN:L-17929                | HRS                             | 2848.3    |          |          |                           |           |           |                  |
|                           | AFL                             | 1574      |          |          |                           |           |           |                  |
| 244160                    | CHECK NO. 1 BATTERY ELECTROLYTE |           |          |          |                           |           |           | Service ATA:24   |
| PN:RG-390E                | MOS/MSC                         | 11-Oct-22 | O/C      |          |                           |           |           |                  |
| SN:412553743              | HRS                             | 6446.4    |          |          |                           |           |           |                  |
| WC#: 24.090               | AFL                             | 3873      |          |          |                           |           |           |                  |
| 244161                    | CHECK NO. 2 BATTERY ELECTROLYTE |           |          |          |                           |           |           | Service ATA:24   |
| PN:RG-390E                | MOS/MSC                         | 11-Oct-22 | O/C      |          |                           |           |           |                  |
| SN:41177422               | HRS                             | 6446      |          |          |                           |           |           |                  |
| WC#: 24.090               | AFL                             | 3873      |          |          |                           |           |           |                  |
| 244162                    | CHECK NO. 3 BATTERY ELECTROLYTE |           |          |          |                           |           |           | Service ATA:24   |
| PN:RG-126                 | MOS/MSC                         | 11-Oct-22 | O/C      |          |                           |           |           |                  |
| SN:40596196               | HRS                             | 6446.4    |          |          |                           |           |           |                  |
| WC#: 24.210               | AFL                             | 3873      |          |          |                           |           |           |                  |
| 244163                    | CHECK NO. 4 BATTERY ELECTROLYTE |           |          |          |                           |           |           | Service ATA:24   |
| PN:RG-126                 | MOS/MSC                         | 11-Oct-22 | O/C      |          |                           |           |           |                  |
| SN:40716880               | HRS                             | 6446.4    |          |          |                           |           |           |                  |
| WC#: 24.220               | AFL                             | 3873      |          |          |                           |           |           |                  |
| 244164                    | CHECK NO. 5 BATTERY ELECTROLYTE |           |          |          |                           |           |           | Service ATA:24   |
| PN:RG-126                 | MOS/MSC                         | 11-Oct-22 | O/C      |          |                           |           |           |                  |
| SN:40596181               | HRS                             | 6446.4    |          |          |                           |           |           |                  |
| WC#: 24.230               | AFL                             | 3873      |          |          |                           |           |           |                  |
| 245001                    | BUS TIE (T) CONTACTOR           |           |          |          |                           |           |           | Component ATA:24 |
| PN:LDA150A8C              | MOS                             | 06-May-13 |          | TSO 0    |                           |           |           | OVERHAUL         |
| SN:W4574                  | HRS                             | 4942.5    | 5000     | TSO 0    | 9942.5                    |           | 3414.2    |                  |
| WC#: 24.140               | AFL                             | 2767      |          | TSO 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                        | Unit                                | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                             | Disposition      |
|--------------------------------|-------------------------------------|-----------|---------------|----------|---------------------------|-----------|---------------------------------------|------------------|
| ATA 24 - ELECTRICAL POWER      |                                     |           |               |          |                           |           |                                       |                  |
| 245043                         | TEMPERATURE SENSOR                  |           |               |          |                           |           |                                       | Component ATA:24 |
| PN:548408-1                    | MOS/MSC                             | 30-May-96 | O/C           |          |                           |           |                                       |                  |
| SN:036C-1709                   | HRS                                 | 0         |               | TSN 0    |                           |           |                                       |                  |
| WC#: 24.170                    | AFL                                 | 0         |               |          |                           |           |                                       |                  |
| ATA 25 - EQUIPMENT/FURNISHINGS |                                     |           |               |          |                           |           |                                       |                  |
| 250003                         | CHECK 3RD CREW MEMBERS SEAT         |           |               |          |                           |           |                                       | Service ATA:25   |
|                                | MOS                                 | 22-Jul-21 |               |          |                           |           |                                       |                  |
|                                | HRS                                 | 6077.4    | 800 (+40/-10) |          | 6877.4                    | 6917.4    | 349.1 (+40)                           |                  |
| WC#: 25.115                    | AFL                                 | 3596      |               |          |                           |           |                                       |                  |
| PROC. REF: AFMS INSPECTION B6  |                                     |           |               |          |                           |           | PKG:2,13<br>WO#: N950PC B & C CHECK   |                  |
| 250004 <sup>U</sup>            | FIRST AID KIT                       |           |               |          |                           |           |                                       | Component ATA:25 |
| PN:9302-25M                    | MOS/MSC                             | 14-Oct-22 | O/C           | TSN 0    |                           |           |                                       |                  |
| SN:KLM-01                      | HRS                                 | 6446.4    |               | TSN 0    |                           |           |                                       |                  |
|                                | AFL                                 | 3873      |               | TSN 0    |                           |           |                                       |                  |
| PROC. REF: AMM 27-10-31        |                                     |           |               |          |                           |           |                                       |                  |
| 250005                         | INSPECT EMERGENCY PACKS (IF FITTED) |           |               |          |                           |           |                                       | Service ATA:25   |
|                                | MOS                                 | 11-Oct-22 | 12 (+1m/-1m)  |          | 11-Oct-23                 | 11-Nov-23 | 253 d (+31)                           |                  |
|                                | HRS                                 | 6446.4    |               |          |                           |           |                                       |                  |
| WC#: 25.125                    | AFL                                 | 3873      |               |          |                           |           |                                       |                  |
| PROC. REF: AFMS INSPECTION E6  |                                     |           |               |          |                           |           | PKG:5,49<br>WO#: N950PC 48 MONTH INSP |                  |
| 250006                         | CHECK FIRST AID KITS                |           |               |          |                           |           |                                       | Service ATA:25   |
|                                | MOS                                 | 14-Oct-22 | 12 (+1m/-1m)  |          | 14-Oct-23                 | 14-Nov-23 | 256 d (+31)                           |                  |
|                                | HRS                                 | 6446.4    |               |          |                           |           |                                       |                  |
| WC#: 25.130                    | AFL                                 | 3873      |               |          |                           |           |                                       |                  |
| PROC. REF: AFMS INSPECTION E6  |                                     |           |               |          |                           |           | PKG:5,49<br>WO#: N950PC 48 MONTH INSP |                  |
| 250007                         | OPERATIONAL CHECK CREW SEATS        |           |               |          |                           |           |                                       | Service ATA:25   |
|                                | MOS                                 | 15-Oct-19 |               |          |                           |           |                                       |                  |
|                                | HRS                                 | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)                              |                  |
| WC#: 25.145                    | AFL                                 | 3397      |               |          |                           |           |                                       |                  |
| PROC. REF: AFMS INSPECTION B4  |                                     |           |               |          |                           |           | PKG:2,11<br>WO#: N950PC B & C CHECK   |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                                                                                                                                                                                                                 | Unit                               | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition      |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------|-----------|-----------------|----------|---------------------------|-----------|---------------|------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS                                                                                                                                                                                                                          |                                    |           |                 |          |                           |           |               |                  |
| 250008                                                                                                                                                                                                                                                  | DETAILED CHECK CREW SEATS          |           |                 |          |                           |           |               | Service ATA:25   |
|                                                                                                                                                                                                                                                         | MOS                                | 18-Aug-17 |                 |          |                           |           |               |                  |
|                                                                                                                                                                                                                                                         | HRS                                | 5554.6    | 3200 (+150/-50) |          | 8754.6                    | 8904.6    | 2226.3 (+150) |                  |
| WC#: 25.150                                                                                                                                                                                                                                             | AFL                                | 3197      |                 |          |                           |           |               |                  |
| PROC. REF: MMA 25-21-10, AFMS INSPECTION D4, AMM 25-10-14                                                                                                                                                                                               |                                    |           |                 |          |                           |           |               |                  |
| PKG:4,35                                                                                                                                                                                                                                                |                                    |           |                 |          |                           |           |               |                  |
| 2500H1 <sup>U</sup>                                                                                                                                                                                                                                     | HONEYWELL HAPP CONTRACT #440035137 |           |                 |          |                           |           |               | Service ATA:25   |
|                                                                                                                                                                                                                                                         | MOS/MSC                            | 08-Jun-22 | 12 / -          |          | 08-Jun-23                 |           | 128 d         |                  |
|                                                                                                                                                                                                                                                         | HRS                                |           |                 |          |                           |           |               |                  |
|                                                                                                                                                                                                                                                         | AFL                                |           |                 |          |                           |           |               |                  |
| PROC. REF: MMA 25-12-10, MMA 25-21-15, MMA 25-21-00, MMA 25-21-10, MMA 25-12-10, MMA 25-30-20, MMA 25-12-10, MMA 25-12-15, MMA 25-21-10, MMA 25-30-15, MMA 25-30-17, MMA 25-12-10, MMA 25-12-15, MMA 25-21-10, MMA 25-30-19, MMA 25-30-20, MMA 25-30-22 |                                    |           |                 |          |                           |           |               |                  |
| 2500H2 <sup>U</sup>                                                                                                                                                                                                                                     | HONEYWELL MSP CONTRACT # 440091957 |           |                 |          |                           |           |               | Service ATA:25   |
|                                                                                                                                                                                                                                                         | MOS                                | 01-Oct-18 | 72              |          | 01-Oct-24                 |           | 609 d         |                  |
|                                                                                                                                                                                                                                                         | HRS                                |           |                 |          |                           |           |               |                  |
|                                                                                                                                                                                                                                                         | AFL                                |           |                 |          |                           |           |               |                  |
| 251001                                                                                                                                                                                                                                                  | NO. 1 CREW SEAT                    |           |                 |          |                           |           |               | Component ATA:25 |
| PN:3A/026/0013/00-2                                                                                                                                                                                                                                     | MOS/MSC                            | 30-May-96 | O/C             |          |                           |           |               |                  |
| SN:26322                                                                                                                                                                                                                                                | HRS                                | 0         |                 | TSN 0    |                           |           |               |                  |
| WC#: 25.010                                                                                                                                                                                                                                             | AFL                                | 0         |                 |          |                           |           |               |                  |
| PROC. REF: AMM 25-10-14                                                                                                                                                                                                                                 |                                    |           |                 |          |                           |           |               |                  |
| 251002                                                                                                                                                                                                                                                  | NO. 2 CREW SEAT                    |           |                 |          |                           |           |               | Component ATA:25 |
| PN:3A/026/0014/00-2                                                                                                                                                                                                                                     | MOS/MSC                            | 30-May-96 | O/C             |          |                           |           |               |                  |
| SN:26326                                                                                                                                                                                                                                                | HRS                                | 0         |                 | TSN 0    |                           |           |               |                  |
| WC#: 25.010                                                                                                                                                                                                                                             | AFL                                | 0         |                 |          |                           |           |               |                  |
| PROC. REF: AMM 25-10-14                                                                                                                                                                                                                                 |                                    |           |                 |          |                           |           |               |                  |
| 251020                                                                                                                                                                                                                                                  | THROTTLE BOX                       |           |                 |          |                           |           |               | Component ATA:25 |
| PN:25-8CX179-577A                                                                                                                                                                                                                                       | MOS/MSC                            | 30-May-96 | O/C             |          |                           |           |               |                  |
| SN:534                                                                                                                                                                                                                                                  | HRS                                | 0         |                 | TSN 0    |                           |           |               |                  |
| WC#: 25.020                                                                                                                                                                                                                                             | AFL                                |           |                 |          |                           |           |               |                  |
| 251038                                                                                                                                                                                                                                                  | FLIGHT DECK CONTROLLER             |           |                 |          |                           |           |               | Component ATA:25 |
| PN:PN                                                                                                                                                                                                                                                   | MOS/MSC                            | 30-May-96 | O/C             | TSN 0    |                           |           |               |                  |
| SN:UNKNOWN                                                                                                                                                                                                                                              | HRS                                | 0         |                 | TSN 0    |                           |           |               |                  |
| WC#: 25.135                                                                                                                                                                                                                                             | AFL                                | 0         |                 | TSN 0    |                           |           |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                        | Unit                                 | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------------|--------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS |                                      |           |          |          |                           |           |           |                  |
| 251057                         | NO. 1 DIGITAL AUDIO AMPLIFIER        |           |          |          |                           |           |           | Component ATA:25 |
| PN:PN                          | MOS/MSC                              | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                     | HRS                                  | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 25.050                    | AFL                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF      |                                      |           |          |          |                           |           |           |                  |
| 251058                         | NO. 2 DIGITAL AUDIO AMPLIFIER        |           |          |          |                           |           |           | Component ATA:25 |
| PN:PN                          | MOS/MSC                              | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                     | HRS                                  | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 25.050                    | AFL                                  | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF      |                                      |           |          |          |                           |           |           |                  |
| 252001 <sup>U</sup>            | CUSTOMER OVER FLIGHT PERMIT RENEWAL  |           |          |          |                           |           |           | Service ATA:25   |
|                                | MOS                                  | 27-Aug-21 | 24       |          | 01-Sep-23 (M)             |           | 213 d     |                  |
|                                | HRS                                  | 6115.4    |          |          |                           |           |           |                  |
|                                | AFL                                  | 3626      |          |          |                           |           |           |                  |
| 252002 <sup>U</sup>            | CUSTOMS BOND RENEWAL                 |           |          |          |                           |           |           | Service ATA:25   |
|                                | MOS                                  | 07-Sep-22 | 12       |          | 05-Aug-23 (M)             |           | 186 d     |                  |
|                                | HRS                                  | 6428      |          |          |                           |           |           |                  |
|                                | AFL                                  | 3863      |          |          |                           |           |           |                  |
| 252003 <sup>U</sup>            | CUSTOMERS AIRCRAFT INSURANCE RENEWAL |           |          |          |                           |           |           | Service ATA:25   |
|                                | MOS                                  | 04-May-22 | 12       |          | 04-Apr-23 (M)             |           | 63 d      |                  |
|                                | HRS                                  |           |          |          |                           |           |           |                  |
|                                | AFL                                  |           |          |          |                           |           |           |                  |
| 252004 <sup>U</sup>            | AMM -- AIRCRAFT MANUAL RENEWAL       |           |          |          |                           |           |           | Service ATA:25   |
|                                | MOS                                  | 08-Sep-22 | 12       |          | 08-Sep-23                 |           | 220 d     |                  |
|                                | HRS                                  | 6428      |          |          |                           |           |           |                  |
|                                | AFL                                  | 3863      |          |          |                           |           |           |                  |
| 252006 <sup>U</sup>            | PAX SCALE CALAIBRATION               |           |          |          |                           |           |           | Service ATA:25   |
|                                | MOS                                  | 23-Oct-22 | 12       |          | 23-Oct-23                 |           | 265 d     |                  |
|                                | HRS                                  | 6453.1    |          |          |                           |           |           |                  |
|                                | AFL                                  | 3876      |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                             | Unit                                                | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                 | Disposition      |
|-----------------------------------------------------|-----------------------------------------------------|-----------|----------|----------|---------------------------|-----------|---------------------------|------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS                      |                                                     |           |          |          |                           |           |                           |                  |
| 252007 <sup>U</sup>                                 | U.S. CUSTOMS DECAL-                                 |           |          |          |                           |           |                           | Component ATA:25 |
| PN:2201-9690                                        | MOS                                                 | 26-Oct-22 | 12       | TSN 0    | 31-Dec-23 (M)             |           | 334 d                     |                  |
| SN:258300                                           | HRS                                                 | 6454.5    |          | TSN 0    |                           |           |                           |                  |
|                                                     | AFL                                                 | 3877      |          | TSN 0    |                           |           |                           |                  |
| 252008 <sup>U</sup>                                 | PAX SCALE                                           |           |          |          |                           |           |                           | Component ATA:25 |
| PN:SAB602DQ2-05                                     | MOS/MSC                                             | 29-Jul-21 | O/C      | TSN 0    |                           |           |                           |                  |
| SN:J344NT                                           | HRS                                                 | 6077.4    |          | TSN 0    |                           |           |                           |                  |
|                                                     | AFL                                                 | 3596      |          | TSN 0    |                           |           |                           |                  |
| 256001                                              | TRANSMITTER EMERGENCY LOCATOR - ELT                 |           |          |          |                           |           |                           | Component ATA:25 |
| PN:453-5060                                         | MOS/MSC                                             | 27-Jan-15 | O/C      |          |                           |           |                           |                  |
| SN:06605                                            | HRS                                                 | 5125.6    |          |          |                           |           |                           |                  |
| WC#: 25.025                                         | AFL                                                 | 2873      |          |          |                           |           |                           |                  |
| PROC. REF: MMA 25-61-05, MMA 25-61-10, MMA 25-61-15 |                                                     |           |          |          |                           |           | WO#: N950PC 48 MONTH INSP |                  |
| 256005                                              | INSPECT- ELT                                        |           |          |          |                           |           |                           | Service ATA:25   |
| PN:453-5060                                         | MOS                                                 | 21-Sep-22 | 12       |          | 21-Sep-23                 |           | 233 d                     |                  |
| SN:06605                                            | HRS                                                 | 6434.2    |          |          |                           |           |                           |                  |
| WC#: 25.025                                         | AFL                                                 | 3866      |          |          |                           |           |                           |                  |
|                                                     |                                                     |           |          |          |                           |           | WO#: N950PC 48 MONTH INSP |                  |
| 256006                                              | ELT REMOTE (CONTROL UNIT) SWITCH                    |           |          |          |                           |           |                           | Component ATA:25 |
| PN:345-6196-04                                      | MOS/MSC                                             | 24-Dec-08 | O/C      |          |                           |           |                           |                  |
| SN:N/A                                              | HRS                                                 | 3893      |          |          |                           |           |                           |                  |
| WC#: 25.030                                         | AFL                                                 | 2177      |          |          |                           |           |                           |                  |
| 256007                                              | REPLACE EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY |           |          |          |                           |           |                           | Service ATA:25   |
| PN:452-0133                                         | MOS/MSC                                             | 02-Dec-22 | DUE      |          | 28-Feb-24 (M)             |           | 393 d                     |                  |
| SN:37964-015                                        | HRS                                                 | 6488.1    |          |          |                           |           |                           |                  |
| WC#: 25.025                                         | AFL                                                 | 3901      |          |          |                           |           |                           |                  |
| PROC. REF: MMA 25-61-05, MMA 25-61-10, MMA 25-61-15 |                                                     |           |          |          |                           |           |                           |                  |
| 256009                                              | EMERGENCY LOCATOR TRANSMITTER ANTENNA               |           |          |          |                           |           |                           | Component ATA:25 |
| PN:110-340                                          | MOS/MSC                                             | 24-Dec-08 | O/C      |          |                           |           |                           |                  |
| SN:252836                                           | HRS                                                 | 3893      |          |          |                           |           |                           |                  |
| WC#: 25.015                                         | AFL                                                 | 2177      |          |          |                           |           |                           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                             | Unit                                                         | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                 | Disposition      |
|-----------------------------------------------------|--------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|---------------------------|------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS                      |                                                              |           |          |          |                           |           |                           |                  |
| 256010                                              | FUNCTION TEST-ELT                                            |           |          |          |                           |           |                           | Service ATA:25   |
| PN:453-5060                                         | MOS                                                          | 01-Aug-22 | 12       |          | 01-Aug-23                 |           | 182 d                     |                  |
| SN:06605                                            | HRS                                                          | 6400.5    |          |          |                           |           |                           |                  |
| WC#: 25.025                                         | AFL                                                          | 3840      |          |          |                           |           |                           |                  |
| PROC. REF: MMA 25-61-05, MMA 25-61-10, MMA 25-61-15 |                                                              |           |          |          |                           |           | WO#: N950PC 48 MONTH INSP |                  |
| 256011                                              | REPLACE ELT REMOTE (CONTROL UNIT) SWITCH BATTERY             |           |          |          |                           |           |                           | Service ATA:25   |
| PN:345-6196-04                                      | MOS/MSC                                                      |           | N/A      |          |                           |           |                           |                  |
| SN:N/A                                              | HRS                                                          |           |          |          |                           |           |                           |                  |
| WC#: 25.030                                         | AFL                                                          |           |          |          |                           |           |                           |                  |
| 256012 <sup>U</sup>                                 | AIRCRAFT ELT ICAO / SAR RENEWAL                              |           |          |          |                           |           |                           | Service ATA:25   |
| PN:453-5060                                         | MOS                                                          | 02-Dec-22 | 24       |          | 28-Nov-24 (M)             |           | 667 d                     |                  |
| SN:06605                                            | HRS                                                          | 6488.1    |          |          |                           |           |                           |                  |
|                                                     | AFL                                                          | 3901      |          |          |                           |           |                           |                  |
| 256013                                              | INSPECT LIFE VESTS                                           |           |          |          |                           |           |                           | Service ATA:25   |
|                                                     | DAYS                                                         | 22-Dec-22 | 60       |          | 20-Feb-23                 |           | 20 d                      |                  |
|                                                     | HRS                                                          | 6495.5    |          |          |                           |           |                           |                  |
| WC#: 25.040                                         | AFL                                                          | 3906      |          |          |                           |           |                           |                  |
| PKG:68                                              |                                                              |           |          |          |                           |           |                           |                  |
| 256014 <sup>U</sup>                                 | ELT SELF TEST - FUNCTIONAL CHECK                             |           |          |          |                           |           |                           | Service ATA:25   |
|                                                     | DAYS                                                         | 22-Dec-22 | 30       |          | 21-Jan-23                 |           | OVD                       |                  |
|                                                     | HRS                                                          | 6495      |          |          |                           |           |                           |                  |
|                                                     | AFL                                                          | 3906      |          |          |                           |           |                           |                  |
| WO#: N950PC KLM JAN 2023                            |                                                              |           |          |          |                           |           |                           |                  |
| 256022 <sup>U</sup>                                 | FLASHLIGHT (PILOT)                                           |           |          |          |                           |           |                           | Component ATA:25 |
| PN:PN-UNKNOWN                                       | MOS/MSC                                                      | 25-Nov-22 | O/C      | TSN 0    |                           |           |                           |                  |
| SN:DL-205-774150                                    | HRS                                                          | 6482.7    |          | TSN 0    |                           |           |                           |                  |
|                                                     | AFL                                                          | 3897      |          | TSN 0    |                           |           |                           |                  |
| 256022A <sup>U</sup>                                | LIGHT PILOT-FLASH LIGHT VISUAL INSPECTION / FUNCTIONAL CHECK |           |          |          |                           |           |                           | Service ATA:25   |
| PN:PN-UNKNOWN                                       | DAYS                                                         | 22-Dec-22 | 60       |          | 20-Feb-23                 |           | 20 d                      |                  |
| SN:DL-205-774150                                    | HRS                                                          | 6495.5    |          |          |                           |           |                           |                  |
|                                                     | AFL                                                          | 3906      |          |          |                           |           |                           |                  |
| PKG:68                                              |                                                              |           |          |          |                           |           |                           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                        | Unit                                                           | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------------|----------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS |                                                                |           |          |          |                           |           |           |                  |
| 256023 <sup>U</sup>            | FLASHLIGHT (COPILOT)                                           |           |          |          |                           |           |           | Component ATA:25 |
| PN:"D"CELL                     | MOS/MSC                                                        | 25-Nov-22 | O/C      | TSN 0    |                           |           |           |                  |
| SN:DL205774205                 | HRS                                                            | 6482.7    |          | TSN 0    |                           |           |           |                  |
|                                | AFL                                                            | 3897      |          | TSN 0    |                           |           |           |                  |
| 256023B <sup>U</sup>           | LIGHT COPILOT-FLASH LIGHT VISUAL INSPECTION / FUNCTIONAL CHECK |           |          |          |                           |           |           | Service ATA:25   |
| PN:"D"CELL                     | DAYS                                                           | 22-Dec-22 | 60       |          | 20-Feb-23                 |           | 20 d      |                  |
| SN:DL205774205                 | HRS                                                            | 6495.5    |          |          |                           |           |           |                  |
|                                | AFL                                                            | 3906      |          |          |                           |           |           |                  |
| PKG:68                         |                                                                |           |          |          |                           |           |           |                  |
| 256030 <sup>U</sup>            | PILOT SMOKE GOGGLES                                            |           |          |          |                           |           |           | Component ATA:25 |
| PN:MSP210-00                   | MOS/MSC                                                        | 15-Nov-21 | O/C      | TSN 0    |                           |           |           |                  |
| SN:NSN                         | HRS                                                            |           |          |          |                           |           |           |                  |
|                                | AFL                                                            |           |          |          |                           |           |           |                  |
| Manufacture Date:: 31-Oct-95   |                                                                |           |          |          |                           |           |           |                  |
| 256030A <sup>U</sup>           | INSPECT PILOT SMOKE GOGGLE                                     |           |          |          |                           |           |           | Service ATA:25   |
|                                | DAYS                                                           | 22-Dec-22 | 60       |          | 20-Feb-23                 |           | 20 d      |                  |
|                                | HRS                                                            | 6495.5    |          |          |                           |           |           |                  |
|                                | AFL                                                            | 3906      |          |          |                           |           |           |                  |
| PKG:68                         |                                                                |           |          |          |                           |           |           |                  |
| 256031 <sup>U</sup>            | CO-PILOT SMOKE GOGGLES                                         |           |          |          |                           |           |           | Component ATA:25 |
| PN:MSP210-00                   | MOS/MSC                                                        | 15-Nov-21 | O/C      | TSN 0    |                           |           |           |                  |
| SN:NSN                         | HRS                                                            |           |          |          |                           |           |           |                  |
|                                | AFL                                                            |           |          |          |                           |           |           |                  |
| Manufacture Date:: 06-Jun-17   |                                                                |           |          |          |                           |           |           |                  |
| 256031B <sup>U</sup>           | INSPECT CO-PILOT SMOKE GOGGLE                                  |           |          |          |                           |           |           | Service ATA:25   |
|                                | DAYS                                                           | 22-Dec-22 | 60       |          | 20-Feb-23                 |           | 20 d      |                  |
|                                | HRS                                                            | 6495.5    |          |          |                           |           |           |                  |
|                                | AFL                                                            | 3906      |          |          |                           |           |           |                  |
| PKG:68                         |                                                                |           |          |          |                           |           |           |                  |
| 256050 <sup>U</sup>            | DATA COMP UNIT AIRSHOW                                         |           |          |          |                           |           |           | Component ATA:25 |
| PN:929402                      | MOS/MSC                                                        | 02-Dec-22 | O/C      |          |                           |           |           |                  |
| SN:30121                       | HRS                                                            | 6488.1    |          |          |                           |           |           |                  |
|                                | AFL                                                            | 3901      |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                        | Unit                                 | C/W       | Interval | TSX/Adj.  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------------|--------------------------------------|-----------|----------|-----------|---------------------------|-----------|-----------|------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS |                                      |           |          |           |                           |           |           |                  |
| 256050A <sup>U</sup>           | TTD CONTROLLER- AIRSHOW              |           |          |           |                           |           |           | Component ATA:25 |
| PN:PN                          | MOS/MSC                              |           | A/R      |           |                           |           |           |                  |
| SN:UNKNOWN                     | HRS                                  |           |          |           |                           |           |           |                  |
|                                | AFL                                  |           |          |           |                           |           |           |                  |
| 256080 <sup>U</sup>            | PILOT LIFE VEST                      |           |          |           |                           |           |           | Component ATA:25 |
| PN:P1074-701                   | MOS/MSC                              | 08-Sep-22 | O/C      |           |                           |           |           |                  |
| SN:20021900406                 | HRS                                  | 6428.5    |          |           |                           |           |           |                  |
|                                | AFL                                  | 3863      |          |           |                           |           |           |                  |
| 256080A <sup>U</sup>           | RECERTIFY PILOT LIFE VEST            |           |          |           |                           |           |           | Service ATA:25   |
| PN:P1074-701                   | MOS                                  | 08-Sep-22 | 120      |           | 01-Aug-29 (M)             |           | 2374 d    |                  |
| SN:20021900406                 | HRS                                  | 6428.5    |          |           |                           |           |           |                  |
|                                | AFL                                  | 3863      |          |           |                           |           |           |                  |
| 256081 <sup>U</sup>            | COPILOT LIFE VEST                    |           |          |           |                           |           |           | Component ATA:25 |
| PN:PN-UNKNOWN                  | MOS/MSC                              | 29-Jul-21 | O/C      | TSN 0     |                           |           |           |                  |
| SN:200219000231                | HRS                                  | 6077      |          | TSN 0     |                           |           |           |                  |
|                                | AFL                                  | 3596      |          | TSN 0     |                           |           |           |                  |
| 256081A <sup>U</sup>           | RECERTIFY COPILOT LIFE VEST          |           |          |           |                           |           |           | Service ATA:25   |
| PN:PN-UNKNOWN                  | MOS                                  | 23-Mar-21 | 120      |           | 23-Mar-31                 |           | 2973 d    |                  |
| SN:200219000231                | HRS                                  |           |          |           |                           |           |           |                  |
|                                | AFL                                  |           |          |           |                           |           |           |                  |
| 256083 <sup>U</sup>            | NO. 1 LEFT CHAIR LIFE VEST           |           |          |           |                           |           |           | Component ATA:25 |
| PN:P1074-701                   | MOS/MSC                              | 08-Sep-22 | O/C      | TSN 14    |                           |           |           |                  |
| SN:20021900032                 | HRS                                  | 6428.5    |          | TSN 351.1 |                           |           |           |                  |
|                                | AFL                                  | 3863      |          | TSN 267   |                           |           |           |                  |
| 256083A <sup>U</sup>           | RECERTIFY NO. 1 LEFT CHAIR LIFE VEST |           |          |           |                           |           |           | Service ATA:25   |
| PN:P1074-701                   | MOS                                  | 08-Sep-22 | 120      |           | 01-Aug-29 (M)             |           | 2374 d    |                  |
| SN:20021900032                 | HRS                                  | 6428.5    |          |           |                           |           |           |                  |
|                                | AFL                                  | 3863      |          |           |                           |           |           |                  |
| 256084 <sup>U</sup>            | NO. 2 LEFT CHAIR LIFE VEST           |           |          |           |                           |           |           | Component ATA:25 |
| PN:P01074-101                  | MOS/MSC                              | 08-Sep-22 | O/C      | TSN 14    |                           |           |           |                  |
| SN:20021900389                 | HRS                                  | 6428.5    |          | TSN 351.1 |                           |           |           |                  |
|                                | AFL                                  | 3863      |          | TSN 267   |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                        | Unit    | C/W                                   | Interval | TSX/Adj.  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------------|---------|---------------------------------------|----------|-----------|---------------------------|-----------|-----------|------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS |         |                                       |          |           |                           |           |           |                  |
| 256084A <sup>U</sup>           |         | RECERTIFY NO. 2 LEFT CHAIR LIFE VEST  |          |           |                           |           |           | Service ATA:25   |
| PN:P01074-101                  | MOS     | 08-Sep-22                             | 120      |           | 01-Aug-29 (M)             |           | 2374 d    |                  |
| SN:20021900389                 | HRS     | 6428.5                                |          |           |                           |           |           |                  |
|                                | AFL     | 3863                                  |          |           |                           |           |           |                  |
| 256085 <sup>U</sup>            |         | NO. 3 LEFT CHAIR LIFE VEST            |          |           |                           |           |           | Component ATA:25 |
| PN:P01074-101                  | MOS/MSC | 08-Sep-22                             | O/C      | TSN 14    |                           |           |           |                  |
| SN:20021900014                 | HRS     | 6428.5                                |          | TSN 351.1 |                           |           |           |                  |
|                                | AFL     | 3863                                  |          | TSN 267   |                           |           |           |                  |
| 256085A <sup>U</sup>           |         | RECERTIFY NO. 3 LEFT CHAIR LIFE VEST  |          |           |                           |           |           | Service ATA:25   |
| PN:P01074-101                  | MOS     | 08-Sep-22                             | 120      |           | 01-Aug-29 (M)             |           | 2374 d    |                  |
| SN:20021900014                 | HRS     | 6428.5                                |          |           |                           |           |           |                  |
|                                | AFL     | 3863                                  |          |           |                           |           |           |                  |
| 256086 <sup>U</sup>            |         | NO. 1 RIGHT CHAIR LIFE VEST           |          |           |                           |           |           | Component ATA:25 |
| PN:P01074-101                  | MOS/MSC | 23-Jul-21                             | O/C      | TSN 0     |                           |           |           |                  |
| SN:20021900286                 | HRS     | 6077                                  |          | TSN 0     |                           |           |           |                  |
|                                | AFL     | 3596                                  |          | TSN 0     |                           |           |           |                  |
| 256086A <sup>U</sup>           |         | RECERTIFY NO. 1 RIGHT CHAIR LIFE VEST |          |           |                           |           |           | Service ATA:25   |
| PN:P01074-101                  | MOS     | 01-Aug-19                             | 120      |           | 01-Aug-29                 |           | 2374 d    |                  |
| SN:20021900286                 | HRS     |                                       |          |           |                           |           |           |                  |
|                                | AFL     |                                       |          |           |                           |           |           |                  |
| 256087 <sup>U</sup>            |         | NO. 2 RIGHT CHAIR LIFE VEST           |          |           |                           |           |           | Component ATA:25 |
| PN:P01074-101                  | MOS/MSC | 08-Sep-22                             | O/C      | TSN 37    |                           |           |           |                  |
| SN:20021900433                 | HRS     | 6428                                  |          |           |                           |           |           |                  |
|                                | AFL     | 3863                                  |          |           |                           |           |           |                  |
| 256087A <sup>U</sup>           |         | RECERTIFY NO. 2 RIGHT CHAIR LIFE VEST |          |           |                           |           |           | Service ATA:25   |
| PN:P01074-101                  | MOS     | 31-Aug-19                             | 120      |           | 01-Aug-29 (M)             |           | 2374 d    |                  |
| SN:20021900433                 | HRS     |                                       |          |           |                           |           |           |                  |
|                                | AFL     |                                       |          |           |                           |           |           |                  |
| 256088 <sup>U</sup>            |         | NO. 1 DIVAN LIFE VEST                 |          |           |                           |           |           | Component ATA:25 |
| PN:P0723E105P                  | MOS/MSC | 27-Aug-21                             | O/C      |           |                           |           |           |                  |
| SN:UNKNOWN                     | HRS     | 6115                                  |          |           |                           |           |           |                  |
|                                | AFL     | 3626                                  |          |           |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                        | Unit    | C/W                                       | Interval | TSX/Adj.  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------------|---------|-------------------------------------------|----------|-----------|---------------------------|-----------|-----------|------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS |         |                                           |          |           |                           |           |           |                  |
| 256088A <sup>U</sup>           |         | RECERTIFY NO. 1 DIVAN LIFE VEST           |          |           |                           |           |           | Service ATA:25   |
| PN:P0723E105P                  | MOS     | 27-Aug-21                                 | 60       |           | 21-Jun-25 (M)             |           | 872 d     |                  |
| SN:UNKNOWN                     | HRS     | 6115                                      |          |           |                           |           |           |                  |
|                                | AFL     | 3626                                      |          |           |                           |           |           |                  |
| 256089 <sup>U</sup>            |         | NO. 2 DIVAN LIFE VEST                     |          |           |                           |           |           | Component ATA:25 |
| PN:P01074-101                  | MOS/MSC | 08-Sep-22                                 | O/C      | TSN 14    |                           |           |           |                  |
| SN:20021900096                 | HRS     | 6428.5                                    |          | TSN 351.1 |                           |           |           |                  |
|                                | AFL     | 3863                                      |          | TSN 267   |                           |           |           |                  |
| 256089A <sup>U</sup>           |         | RECERTIFY NO. 2 DIVAN LIFE VEST           |          |           |                           |           |           | Service ATA:25   |
| PN:P01074-101                  | MOS     | 08-Sep-22                                 | 120      |           | 01-Aug-29 (M)             |           | 2374 d    |                  |
| SN:20021900096                 | HRS     | 6428.5                                    |          |           |                           |           |           |                  |
|                                | AFL     | 3863                                      |          |           |                           |           |           |                  |
| 256090 <sup>U</sup>            |         | NO. 3 DIVAN LIFE VEST                     |          |           |                           |           |           | Component ATA:25 |
| PN:P01074-101                  | MOS/MSC | 08-Sep-22                                 | O/C      | TSN 14    |                           |           |           |                  |
| SN:20021900097                 | HRS     | 6428.5                                    |          | TSN 351.1 |                           |           |           |                  |
|                                | AFL     | 3863                                      |          | TSN 267   |                           |           |           |                  |
| 256090A <sup>U</sup>           |         | RECERTIFY NO. 3 DIVAN LIFE VEST           |          |           |                           |           |           | Service ATA:25   |
| PN:P01074-101                  | MOS     | 08-Sep-22                                 | 120      |           | 01-Aug-29 (M)             |           | 2374 d    |                  |
| SN:20021900097                 | HRS     | 6428.5                                    |          |           |                           |           |           |                  |
|                                | AFL     | 3863                                      |          |           |                           |           |           |                  |
| 256091 <sup>U</sup>            |         | NO. 4 DIVAN- SPARE LIFE VEST              |          |           |                           |           |           | Component ATA:25 |
| PN:P01074-101                  | MOS/MSC | 08-Sep-22                                 | O/C      | TSN 14    |                           |           |           |                  |
| SN:20021900370                 | HRS     | 6428.5                                    |          | TSN 351.1 |                           |           |           |                  |
|                                | AFL     | 3863                                      |          | TSN 267   |                           |           |           |                  |
| PROC. REF: AMM 26-20-00        |         |                                           |          |           |                           |           |           |                  |
| 256091A <sup>U</sup>           |         | RECERTIFY NO. 4 DIVAN- SPARE LIFE VEST    |          |           |                           |           |           | Service ATA:25   |
| PN:P01074-101                  | MOS     | 08-Sep-22                                 | 120      |           | 01-Aug-29 (M)             |           | 2374 d    | RECERTIFY        |
| SN:20021900370                 | HRS     | 6428.5                                    |          |           |                           |           |           |                  |
|                                | AFL     | 3863                                      |          |           |                           |           |           |                  |
| 256301                         |         | BATTERY EMERGENCY LOCATOR TRANSMITTER-ELT |          |           |                           |           |           | Component ATA:25 |
| PN:452-0133                    | MOS/MSC | 02-Dec-22                                 | O/C      |           |                           |           |           |                  |
| SN:37964-015                   | HRS     | 6488                                      |          |           |                           |           |           |                  |
|                                | AFL     | 3901                                      |          |           |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                        | Unit                                                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------------|---------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS |                                                         |           |          |          |                           |           |           |                  |
| 256310 <sup>U</sup>            | HEX CODE - AIRCRAFT                                     |           |          |          |                           |           |           | Component ATA:25 |
| PN:PN                          | MOS/MSC                                                 |           | DUE      |          |                           |           |           |                  |
| SN:UNKNOWN                     | HRS                                                     |           |          |          |                           |           |           |                  |
|                                | AFL                                                     |           |          |          |                           |           |           |                  |
| 256311 <sup>U</sup>            | HEX CODE - LIFE RAFT                                    |           |          |          |                           |           |           | Component ATA:25 |
| PN:PN                          | MOS/MSC                                                 |           | DUE      |          |                           |           |           |                  |
| SN:UNKNOWN                     | HRS                                                     |           |          |          |                           |           |           |                  |
|                                | AFL                                                     |           |          |          |                           |           |           |                  |
| 258209 <sup>U</sup>            | LIFE RAFT                                               |           |          |          |                           |           |           | Component ATA:25 |
| PN:RAF1206-305                 | MOS/MSC                                                 | 13-Sep-21 | O/C      | TSO 0    |                           |           |           |                  |
| SN:1268GX                      | HRS                                                     | 6135.7    |          | TSO 0    |                           |           |           |                  |
|                                | AFL                                                     | 3643      |          | TSO 0    |                           |           |           |                  |
| 258210 <sup>U</sup>            | INSPECT LIFE RAFT                                       |           |          |          |                           |           |           | Service ATA:25   |
| PN:RAF1206-305                 | MOS                                                     | 08-Sep-22 | 36       |          | 01-Sep-23 (M)             |           | 213 d     |                  |
| SN:1268GX                      | HRS                                                     | 6428      |          |          |                           |           |           |                  |
|                                | AFL                                                     | 3863      |          |          |                           |           |           |                  |
| 258211 <sup>U</sup>            | VISUAL INSPECTION- LIFE RAFT AND EMERGENCY EQUIPMENT    |           |          |          |                           |           |           | Service ATA:25   |
|                                | DAYS                                                    | 22-Dec-22 | 60       |          | 20-Feb-23                 |           | 20 d      |                  |
|                                | HRS                                                     | 6495.5    |          |          |                           |           |           |                  |
|                                | AFL                                                     | 3906      |          |          |                           |           |           |                  |
| PKG:68                         |                                                         |           |          |          |                           |           |           |                  |
| 258218 <sup>U</sup>            | LIFE RAFT- ELT (EMERGENCY LOCATOR TRANSMITTER)          |           |          |          |                           |           |           | Component ATA:25 |
| PN:RAF 1206-305                | MOS/MSC                                                 | 13-Sep-21 | O/C      | TSN 0    |                           |           |           |                  |
| SN:1268GX                      | HRS                                                     | 6135.7    |          | TSN 0    |                           |           |           |                  |
|                                | AFL                                                     | 3643      |          | TSN 0    |                           |           |           |                  |
| 258219 <sup>U</sup>            | BATTERY- LIFE RAFT- ELT (EMERGENCY LOCATOR TRANSMITTER) |           |          |          |                           |           |           | Component ATA:25 |
| PN:UNKNOWN                     | MOS/MSC                                                 |           | A/R      |          | 01-Oct-26 (M)             |           | 1339 d    |                  |
| SN:UNKNOWN                     | HRS                                                     |           |          |          |                           |           |           |                  |
|                                | AFL                                                     |           |          |          |                           |           |           |                  |
| 258220 <sup>U</sup>            | LIFE RAFT LIFE RAFT ELT ICAO / SAR RENEWAL              |           |          |          |                           |           |           | Service ATA:25   |
| PN:RAF1206-305                 | MOS                                                     | 28-Nov-22 | 24       |          | 31-Dec-24 (M)             |           | 700 d     |                  |
| SN:1268GX                      | HRS                                                     | 6482.7    |          |          |                           |           |           |                  |
|                                | AFL                                                     | 3897      |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                     | Unit                                                         | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition                           |
|---------------------------------------------|--------------------------------------------------------------|-----------|---------------|----------|---------------------------|-----------|-------------|---------------------------------------|
| ATA 25 - EQUIPMENT/FURNISHINGS              |                                                              |           |               |          |                           |           |             |                                       |
| 25WB001 <sup>U</sup>                        | FAA SENSITIVE AREA REVIEW AS PER B450                        |           |               |          |                           |           |             | Service ATA:25                        |
|                                             | DAYS                                                         | 23-Nov-22 | 90            |          | 21-Feb-23                 |           | 21 d        |                                       |
|                                             | HRS                                                          | 6482.7    |               |          |                           |           |             |                                       |
|                                             | AFL                                                          | 3897      |               |          |                           |           |             |                                       |
| ATA 26 - FIRE PROTECTION                    |                                                              |           |               |          |                           |           |             |                                       |
| 260002                                      | FUNCTIONAL TEST REAR EQUIPMENT BAY OVERHEAT DETECTION SYSTEM |           |               |          |                           |           |             | Service ATA:26                        |
|                                             | MOS                                                          | 08-Jan-21 |               |          |                           |           |             |                                       |
|                                             | HRS                                                          | 5937.6    | 800 (+40/-10) |          | 6737.6                    | 6777.6    | 209.3 (+40) |                                       |
| WC#: 26.035                                 | AFL                                                          | 3502      |               |          |                           |           |             |                                       |
| PROC. REF: AFMS INSPECTION B1, AMM 26-10-00 |                                                              |           |               |          |                           |           |             | PKG:2,8<br>WO#: N950PC B & C CHECK    |
| 260003                                      | WEIGHT CHECK COCKPIT PORTABLE FIRE EXTINGUISHER              |           |               |          |                           |           |             | Service ATA:26                        |
| PN:C352                                     | MOS                                                          | 03-Oct-22 | 12 (+1m/-1m)  |          | 03-Oct-23                 | 03-Nov-23 | 245 d (+31) |                                       |
| SN:B-74100859                               | HRS                                                          |           |               |          |                           |           |             |                                       |
| WC#: 26.080                                 | AFL                                                          |           |               |          |                           |           |             |                                       |
| PROC. REF: AFMS INSPECTION E4               |                                                              |           |               |          |                           |           |             | PKG:5,47                              |
| 260004                                      | WEIGHT CHECK CABIN PORTABLE FIRE EXTINGUISHER                |           |               |          |                           |           |             | Service ATA:26                        |
| PN:C352                                     | MOS                                                          | 03-Oct-22 | 12 (+1m/-1m)  |          | 03-Oct-23                 | 03-Nov-23 | 245 d (+31) |                                       |
| SN:A-35480788                               | HRS                                                          |           |               |          |                           |           |             |                                       |
| WC#: 26.075                                 | AFL                                                          |           |               |          |                           |           |             |                                       |
| PROC. REF: AFMS INSPECTION E6               |                                                              |           |               |          |                           |           |             | PKG:5,49                              |
| 260005                                      | WEIGHT CHECK AFT ENGINE FIRE EXTINGUISHER                    |           |               |          |                           |           |             | Service ATA:26                        |
|                                             | MOS                                                          | 11-Oct-22 | 12 (+1m/-1m)  |          | 11-Oct-23                 | 11-Nov-23 | 253 d (+31) |                                       |
|                                             | HRS                                                          | 6446.4    |               |          |                           |           |             |                                       |
| WC#: 26.020                                 | AFL                                                          | 3873      |               |          |                           |           |             |                                       |
| PROC. REF: AFMS INSPECTION E7, AMM 26-20-12 |                                                              |           |               |          |                           |           |             | PKG:5,50<br>WO#: N950PC 48 MONTH INSP |
| 260005                                      | WEIGHT CHECK FORWARD ENGINE FIRE EXTINGUISHER                |           |               |          |                           |           |             | Service ATA:26                        |
|                                             | MOS                                                          | 11-Oct-22 | 12 (+1m/-1m)  |          | 11-Oct-23                 | 11-Nov-23 | 253 d (+31) |                                       |
|                                             | HRS                                                          | 6446.4    |               |          |                           |           |             |                                       |
| WC#: 26.010                                 | AFL                                                          | 3873      |               |          |                           |           |             |                                       |
| PROC. REF: AFMS INSPECTION E7, AMM 26-20-12 |                                                              |           |               |          |                           |           |             | PKG:5,50<br>WO#: N950PC 48 MONTH INSP |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                   | Unit                                                                          | C/W       | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                             | Disposition      |
|-----------------------------------------------------------|-------------------------------------------------------------------------------|-----------|--------------|----------|---------------------------|-----------|---------------------------------------|------------------|
| ATA 26 - FIRE PROTECTION                                  |                                                                               |           |              |          |                           |           |                                       |                  |
| 260007                                                    | CHECK/FUNCTIONAL TEST APU FIRE EXTINGUISHER                                   |           |              |          |                           |           |                                       | Service ATA:26   |
|                                                           | MOS                                                                           | 11-Oct-22 | 12 (+1m/-1m) |          | 11-Oct-23                 | 11-Nov-23 | 253 d (+31)                           |                  |
|                                                           | HRS                                                                           | 6446.4    |              |          |                           |           |                                       |                  |
| WC#: 26.090                                               | AFL                                                                           | 3873      |              |          |                           |           |                                       |                  |
| PROC. REF: AFMS INSPECTION E7, AMM 26-20-00, AMM 26-20-54 |                                                                               |           |              |          |                           |           | PKG:5,50<br>WO#: N950PC 48 MONTH INSP |                  |
| 260008                                                    | FUNCTIONAL TEST SMOKE DETECTION SYSTEM (IF FITTED)                            |           |              |          |                           |           |                                       | Service ATA:26   |
|                                                           | MOS                                                                           | 21-Sep-22 | 6 (+10%)     |          | 21-Mar-23                 | 08-Apr-23 | 49 d (+18)                            |                  |
|                                                           | HRS                                                                           | 6434.2    |              |          |                           |           |                                       |                  |
| WC#: 26.115                                               | AFL                                                                           | 3866      |              |          |                           |           |                                       |                  |
| PROC. REF: MMA 26-11-00, AFMS OUT OF PHASE INSPECTIONS    |                                                                               |           |              |          |                           |           |                                       |                  |
| 260009                                                    | FUNCTION TEST BAGGAGE PANNIER OR EXTERNAL BAGGAGE UNIT SMOKE DETECTION SYSTEM |           |              |          |                           |           |                                       | Service ATA:26   |
|                                                           | MOS/MSC                                                                       | 05-Jul-12 | N/R          |          |                           |           |                                       |                  |
|                                                           | HRS                                                                           | 4734      |              |          |                           |           |                                       |                  |
| WC#: 26.140                                               | AFL                                                                           | 2648      |              |          |                           |           |                                       |                  |
| PROC. REF: AFMS OUT OF PHASE INSPECTIONS                  |                                                                               |           |              |          |                           |           |                                       |                  |
| 260010                                                    | CHECK/FUNCTIONAL TEST APU FIRE EXTINGUISHER                                   |           |              |          |                           |           |                                       | Service ATA:26   |
|                                                           | MOS                                                                           | 11-Oct-22 | 12 (+1m/-1m) |          | 11-Oct-23                 | 11-Nov-23 | 253 d (+31)                           |                  |
|                                                           | HRS                                                                           | 6446.4    |              |          |                           |           |                                       |                  |
| WC#: 26.085                                               | AFL                                                                           | 3873      |              |          |                           |           |                                       |                  |
| PROC. REF: AFMS INSPECTION E7, CMM 26-20-02               |                                                                               |           |              |          |                           |           | PKG:5,50<br>WO#: N950PC 48 MONTH INSP |                  |
| 260011                                                    | INSPECT/CHECK/FUNCTIONAL TEST EXTERNAL BAGGAGE UNIT FIRE EXTINGUISHER         |           |              |          |                           |           |                                       | Service ATA:26   |
|                                                           | MOS                                                                           | 11-Oct-22 | 12 (+1m/-1m) |          | 11-Oct-23                 | 11-Nov-23 | 253 d (+31)                           |                  |
|                                                           | HRS                                                                           | 6446.4    |              |          |                           |           |                                       |                  |
| WC#: 26.150                                               | AFL                                                                           | 3873      |              |          |                           |           |                                       |                  |
| PROC. REF: AFMS INSPECTION E7                             |                                                                               |           |              |          |                           |           | PKG:5,50<br>WO#: N950PC 48 MONTH INSP |                  |
| 261030                                                    | APU ENCLOSURE HOT SECTION LOWER THERMAL SWITCH                                |           |              |          |                           |           |                                       | Component ATA:26 |
| PN:PN                                                     | MOS/MSC                                                                       | 15-Dec-07 | O/C          |          |                           |           |                                       |                  |
| SN:UNKNOWN                                                | HRS                                                                           | 3610.2    |              |          |                           |           |                                       |                  |
| WC#: 26.120                                               | AFL                                                                           | 2023      |              |          |                           |           |                                       |                  |
| PROC. REF: AMM 26-16-03                                   |                                                                               |           |              |          |                           |           | WO#: N950PC B & C CHECK               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                  | Unit                                                | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining               | Disposition      |
|--------------------------|-----------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-------------------------|------------------|
| ATA 26 - FIRE PROTECTION |                                                     |           |          |          |                           |           |                         |                  |
| 261031                   | APU ENCLOSURE FUEL CONTROL AREA THERMAL SWITCH      |           |          |          |                           |           |                         | Component ATA:26 |
| PN:17343-62-500          | MOS/MSC                                             | 15-Dec-07 | O/C      |          |                           |           |                         |                  |
| SN:UNKNOWN               | HRS                                                 | 3610.2    |          |          |                           |           |                         |                  |
| WC#: 26.125              | AFL                                                 | 2023      |          |          |                           |           |                         |                  |
| PROC. REF: AMM 26-16-03  |                                                     |           |          |          |                           |           | WO#: N950PC B & C CHECK |                  |
| 261032                   | APU ENCLOSURE HOT SECTION UPPER THERMAL SWITCH      |           |          |          |                           |           |                         | Component ATA:26 |
| PN:160275-1              | MOS/MSC                                             | 15-Dec-07 | O/C      |          |                           |           |                         |                  |
| SN:UNKNOWN               | HRS                                                 | 3610.2    |          |          |                           |           |                         |                  |
| WC#: 26.130              | AFL                                                 | 2023      |          |          |                           |           |                         |                  |
| PROC. REF: AMM 26-16-03  |                                                     |           |          |          |                           |           | WO#: N950PC B & C CHECK |                  |
| 261033                   | APU ENCLOSURE STARTER/GENERATOR AREA THERMAL SWITCH |           |          |          |                           |           |                         | Component ATA:26 |
| PN:67100-1-350           | MOS/MSC                                             | 15-Dec-07 | O/C      |          |                           |           |                         |                  |
| SN:UNKNOWN               | HRS                                                 | 3610.2    |          |          |                           |           |                         |                  |
| WC#: 26.135              | AFL                                                 | 2023      |          |          |                           |           |                         |                  |
| PROC. REF: AMM 26-16-03  |                                                     |           |          |          |                           |           | WO#: N950PC B & C CHECK |                  |
| 261034                   | TEST APU ENCLOSURE HOT SECTION LOWER THERMAL SWITCH |           |          |          |                           |           |                         | Service ATA:26   |
| PN:PN                    | MOS                                                 | 10-Oct-22 | 60       |          | 10-Oct-27                 |           | 1713 d                  |                  |
| SN:UNKNOWN               | HRS                                                 | 6446.4    |          |          |                           |           |                         |                  |
| WC#: 26.120              | AFL                                                 | 3873      |          |          |                           |           |                         |                  |
|                          |                                                     |           |          |          |                           |           | WO#: N950PC B & C CHECK |                  |
| 261035                   | TEST APU ENCLOSURE FUEL CONTROL AREA THERMAL SWITCH |           |          |          |                           |           |                         | Service ATA:26   |
| PN:17343-62-500          | MOS                                                 | 10-Oct-22 | 60       |          | 10-Oct-27                 |           | 1713 d                  |                  |
| SN:UNKNOWN               | HRS                                                 | 6446.4    |          |          |                           |           |                         |                  |
| WC#: 26.125              | AFL                                                 | 3873      |          |          |                           |           |                         |                  |
|                          |                                                     |           |          |          |                           |           | WO#: N950PC B & C CHECK |                  |
| 261036                   | TEST APU ENCLOSURE HOT SECTION UPPER THERMAL SWITCH |           |          |          |                           |           |                         | Service ATA:26   |
| PN:160275-1              | MOS                                                 | 10-Oct-22 | 60       |          | 10-Oct-27                 |           | 1713 d                  |                  |
| SN:UNKNOWN               | HRS                                                 | 6446.4    |          |          |                           |           |                         |                  |
| WC#: 26.130              | AFL                                                 | 3873      |          |          |                           |           |                         |                  |
|                          |                                                     |           |          |          |                           |           | WO#: N950PC B & C CHECK |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                                                     | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining               | Disposition      |
|---------------------------|----------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-------------------------|------------------|
| ATA 26 - FIRE PROTECTION  |                                                          |           |          |          |                           |           |                         |                  |
| 261037                    | TEST APU ENCLOSURE STARTER/GENERATOR AREA THERMAL SWITCH |           |          |          |                           |           |                         | Service ATA:26   |
| PN:67100-1-350            | MOS                                                      | 10-Oct-22 | 60       |          | 10-Oct-27                 |           | 1713 d                  |                  |
| SN:UNKNOWN                | HRS                                                      | 6446.4    |          |          |                           |           |                         |                  |
| WC#: 26.135               | AFL                                                      | 3873      |          |          |                           |           |                         |                  |
|                           |                                                          |           |          |          |                           |           | WO#: N950PC B & C CHECK |                  |
| 261074                    | OVERHEAT DETECTION SWITCHES TEST                         |           |          |          |                           |           |                         | Service ATA:26   |
|                           | MOS                                                      | 10-Oct-22 | 60       |          | 10-Oct-27                 |           | 1713 d                  |                  |
|                           | HRS                                                      | 6446.4    |          |          |                           |           |                         |                  |
| WC#: 26.030               | AFL                                                      | 3873      |          |          |                           |           |                         |                  |
| PROC. REF: AMM 26-20-00   |                                                          |           |          |          |                           |           | WO#: N950PC B & C CHECK |                  |
| 261171                    | NO. 1 ENGINE ZONE 1 FIRE DETECTOR                        |           |          |          |                           |           |                         | Component ATA:26 |
| PN:3001-112-900/400-10    | MOS/MSC                                                  | 11-Nov-96 | O/C      |          |                           |           |                         |                  |
| SN:77625                  | HRS                                                      | 20        |          | TSN 23   |                           |           |                         |                  |
| WC#: 26.050               | AFL                                                      | 11        |          |          |                           |           |                         |                  |
| PROC. REF: AMM 26-10-12   |                                                          |           |          |          |                           |           |                         |                  |
| 261172                    | NO. 2 ENGINE ZONE 1 FIRE DETECTOR                        |           |          |          |                           |           |                         | Component ATA:26 |
| PN:3001-112-900/400-10    | MOS/MSC                                                  | 30-May-96 | O/C      |          |                           |           |                         |                  |
| SN:77163                  | HRS                                                      | 0         |          | TSN 0    |                           |           |                         |                  |
| WC#: 26.055               | AFL                                                      | 0         |          |          |                           |           |                         |                  |
| PROC. REF: AMM 26-10-12   |                                                          |           |          |          |                           |           |                         |                  |
| 261183                    | NO. 1 ENGINE ZONE 2 FIRE DETECTOR                        |           |          |          |                           |           |                         | Component ATA:26 |
| PN:3001-133-900/500-6     | MOS/MSC                                                  | 11-Nov-96 | O/C      |          |                           |           |                         |                  |
| SN:77562                  | HRS                                                      | 20        |          | TSN 23   |                           |           |                         |                  |
| WC#: 26.050               | AFL                                                      | 11        |          |          |                           |           |                         |                  |
| PROC. REF: AMM 26-10-12   |                                                          |           |          |          |                           |           |                         |                  |
| 261184                    | NO. 2 ENGINE ZONE 2 FIRE DETECTOR                        |           |          |          |                           |           |                         | Component ATA:26 |
| PN:3001-133-900/500-6     | MOS/MSC                                                  | 30-May-96 | O/C      |          |                           |           |                         |                  |
| SN:76069                  | HRS                                                      | 0         |          | TSN 0    |                           |           |                         |                  |
| WC#: 26.055               | AFL                                                      | 0         |          |          |                           |           |                         |                  |
| PROC. REF: AMM 26-10-12   |                                                          |           |          |          |                           |           |                         |                  |
| 261187                    | NO. 1 ENGINE FIRE DETECTOR HARNESS                       |           |          |          |                           |           |                         | Component ATA:26 |
| PN:PN                     | MOS/MSC                                                  | 30-May-96 | O/C      | TSN 0    |                           |           |                         |                  |
| SN:UNKNOWN                | HRS                                                      | 0         |          | TSN 0    |                           |           |                         |                  |
| WC#: 26.161               | AFL                                                      | 0         |          | TSN 0    |                           |           |                         |                  |
| PROC. REF: GENERIC NO REF |                                                          |           |          |          |                           |           |                         |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|---------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 26 - FIRE PROTECTION  |                                                   |           |          |          |                           |           |           |                  |
| 261188                    | NO. 2 ENGINE FIRE DETECTOR HARNESS                |           |          |          |                           |           |           | Component ATA:26 |
| PN:PN                     | MOS/MSC                                           | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 26.162               | AFL                                               | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 262001                    | ENGINE FORWARD FIRE EXTINGUISHER                  |           |          |          |                           |           |           | Component ATA:26 |
| PN:33200002-3             | MOS/MSC                                           | 24-Sep-21 | O/C      | TSN 0    |                           |           |           |                  |
| SN:1442061                | HRS                                               | 6141      |          | TSN 0    |                           |           |           |                  |
| WC#: 26.010               | AFL                                               | 3647      |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 26-20-12   |                                                   |           |          |          |                           |           |           |                  |
| 262002                    | ENGINE AFT FIRE EXTINGUISHER                      |           |          |          |                           |           |           | Component ATA:26 |
| PN:33200002-3             | MOS/MSC                                           | 24-Sep-21 | O/C      |          |                           |           |           |                  |
| SN:14294C1                | HRS                                               | 6141      |          |          |                           |           |           |                  |
| WC#: 26.020               | AFL                                               | 3647      |          |          |                           |           |           |                  |
| PROC. REF: AMM 26-20-12   |                                                   |           |          |          |                           |           |           |                  |
| 262025                    | HYDROSTATIC TEST ENGINE FORWARD FIRE EXTINGUISHER |           |          |          |                           |           |           | Service ATA:26   |
| PN:33200002-3             | MOS                                               | 25-Jun-15 | 120      |          | 25-Jun-25                 |           | 876 d     |                  |
| SN:1442061                | HRS                                               |           |          |          |                           |           |           |                  |
| WC#: 26.010               | AFL                                               |           |          |          |                           |           |           |                  |
| 262026                    | HYDROSTATIC TEST ENGINE AFT FIRE EXTINGUISHER     |           |          |          |                           |           |           | Service ATA:26   |
| PN:33200002-3             | MOS                                               | 25-Jun-15 | 120      |          | 25-Jun-25                 |           | 876 d     |                  |
| SN:14294C1                | HRS                                               |           |          |          |                           |           |           |                  |
| WC#: 26.020               | AFL                                               |           |          |          |                           |           |           |                  |
| 262027                    | FORWARD ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE |           |          |          |                           |           |           | Component ATA:26 |
| PN:M30900000M             | MOS/MSC                                           | 08-Jan-21 | O/C      | TSN 15   |                           |           |           |                  |
| SN:09421                  | HRS                                               | 5937.6    |          | TSN 0    |                           |           |           |                  |
| WC#: 26.015               | AFL                                               | 3502      |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |
| 262028                    | AFT ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE     |           |          |          |                           |           |           | Component ATA:26 |
| PN:M30900000M             | MOS/MSC                                           | 08-Jan-21 | O/C      | TSN 15   |                           |           |           |                  |
| SN:09430                  | HRS                                               | 5937.6    |          | TSN 0    |                           |           |           |                  |
| WC#: 26.025               | AFL                                               | 3502      |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                                                                     | C/W       | Interval | TSX/Adj.  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|--------------------------------------------------------------------------|-----------|----------|-----------|---------------------------|-----------|-----------|------------------|
| ATA 26 - FIRE PROTECTION  |                                                                          |           |          |           |                           |           |           |                  |
| 262029                    | FORWARD ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE                        |           |          |           |                           |           |           | Component ATA:26 |
| PN:M30900000M             | MOS/MSC                                                                  | 08-Jan-21 | O/C      | TSN 0     |                           |           |           |                  |
| SN:09378                  | HRS                                                                      | 5937.6    |          | TSN 0     |                           |           |           |                  |
| WC#: 26.015               | AFL                                                                      | 3502      |          | TSN 0     |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                          |           |          |           |                           |           |           |                  |
| 262030                    | AFT ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE                            |           |          |           |                           |           |           | Component ATA:26 |
| PN:M30900000M             | MOS/MSC                                                                  | 08-Jan-21 | O/C      | TSN 15    |                           |           |           |                  |
| SN:09457                  | HRS                                                                      | 5937.6    |          | TSN 0     |                           |           |           |                  |
| WC#: 26.025               | AFL                                                                      | 3502      |          | TSN 0     |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                                          |           |          |           |                           |           |           |                  |
| 262037                    | REPLACE FORWARD ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE (SERVICE LIFE) |           |          |           |                           |           |           | Service ATA:26   |
| PN:M30900000M             | MOS                                                                      | 08-Jan-21 | 120      | 08-Jan-31 |                           | 2899 d    |           | LIFE LIMIT       |
| SN:09421                  | HRS                                                                      |           |          |           |                           |           |           |                  |
| WC#: 26.015               | AFL                                                                      |           |          |           |                           |           |           |                  |
| PROC. REF: AMM 26-20-22   |                                                                          |           |          |           |                           |           |           |                  |
| 262038                    | REPLACE AFT ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE (SERVICE LIFE)     |           |          |           |                           |           |           | Service ATA:26   |
| PN:M30900000M             | MOS                                                                      | 08-Jan-21 | 120      | 08-Jan-31 |                           | 2899 d    |           | LIFE LIMIT       |
| SN:09430                  | HRS                                                                      |           |          |           |                           |           |           |                  |
| WC#: 26.025               | AFL                                                                      |           |          |           |                           |           |           |                  |
| PROC. REF: AMM 26-20-22   |                                                                          |           |          |           |                           |           |           |                  |
| 262049                    | REPLACE FORWARD ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE (SERVICE LIFE) |           |          |           |                           |           |           | Service ATA:26   |
| PN:M30900000M             | MOS                                                                      | 08-Jan-21 | 120      | 08-Jan-31 |                           | 2899 d    |           | LIFE LIMIT       |
| SN:09378                  | HRS                                                                      |           |          |           |                           |           |           |                  |
| WC#: 26.015               | AFL                                                                      |           |          |           |                           |           |           |                  |
| PROC. REF: AMM 26-20-22   |                                                                          |           |          |           |                           |           |           |                  |
| 262050                    | REPLACE AFT ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE (SERVICE LIFE)     |           |          |           |                           |           |           | Service ATA:26   |
| PN:M30900000M             | MOS                                                                      | 08-Jan-21 | 120      | 08-Jan-31 |                           | 2899 d    |           | LIFE LIMIT       |
| SN:09457                  | HRS                                                                      |           |          |           |                           |           |           |                  |
| WC#: 26.025               | AFL                                                                      |           |          |           |                           |           |           |                  |
| PROC. REF: AMM 26-20-22   |                                                                          |           |          |           |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                  | Unit                                                                   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------|------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 26 - FIRE PROTECTION |                                                                        |           |          |          |                           |           |           |                  |
| 262061                   | REPLACE FORWARD ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE (LIFE LIMIT) |           |          |          |                           |           |           | Service ATA:26   |
| PN:M30900000M            | MOS                                                                    | 01-Oct-19 | 180      |          | 01-Oct-34                 |           | 4261 d    | LIFE LIMIT       |
| SN:09421                 | HRS                                                                    |           |          |          |                           |           |           |                  |
| WC#: 26.015              | AFL                                                                    |           |          |          |                           |           |           |                  |
| PROC. REF: AMM 26-20-22  |                                                                        |           |          |          |                           |           |           |                  |
| 262062                   | REPLACE AFT ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE (LIFE LIMIT)     |           |          |          |                           |           |           | Service ATA:26   |
| PN:M30900000M            | MOS                                                                    | 01-Oct-19 | 180      |          | 01-Oct-34                 |           | 4261 d    | LIFE LIMIT       |
| SN:09430                 | HRS                                                                    |           |          |          |                           |           |           |                  |
| WC#: 26.025              | AFL                                                                    |           |          |          |                           |           |           |                  |
| PROC. REF: AMM 26-20-22  |                                                                        |           |          |          |                           |           |           |                  |
| 262073                   | REPLACE FORWARD ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE (LIFE LIMIT) |           |          |          |                           |           |           | Service ATA:26   |
| PN:M30900000M            | MOS                                                                    | 01-Oct-19 | 180      |          | 01-Oct-34                 |           | 4261 d    | LIFE LIMIT       |
| SN:09378                 | HRS                                                                    |           |          |          |                           |           |           |                  |
| WC#: 26.015              | AFL                                                                    |           |          |          |                           |           |           |                  |
| PROC. REF: AMM 26-20-22  |                                                                        |           |          |          |                           |           |           |                  |
| 262074                   | REPLACE AFT ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE (LIFE LIMIT)     |           |          |          |                           |           |           | Service ATA:26   |
| PN:M30900000M            | MOS                                                                    | 01-Oct-19 | 180      |          | 01-Oct-34                 |           | 4261 d    | LIFE LIMIT       |
| SN:09457                 | HRS                                                                    |           |          |          |                           |           |           |                  |
| WC#: 26.025              | AFL                                                                    |           |          |          |                           |           |           |                  |
| PROC. REF: AMM 26-20-22  |                                                                        |           |          |          |                           |           |           |                  |
| 262091                   | CABIN PORTABLE FIRE EXTINGUISHER                                       |           |          |          |                           |           |           | Component ATA:26 |
| PN:C352                  | MOS/MSC                                                                | 15-Apr-21 | O/C      | TSO 0    |                           |           |           |                  |
| SN:A-35480788            | HRS                                                                    | 5960.5    |          | TSO 0    |                           |           |           |                  |
| WC#: 26.075              | AFL                                                                    | 3523      |          | TSO 0    |                           |           |           |                  |
| 262091A <sup>U</sup>     | CABIN PORTABLE FIRE EXTINGUISHER VISUAL INSPECTION                     |           |          |          |                           |           |           | Service ATA:26   |
| PN:C352                  | DAYS                                                                   | 22-Dec-22 | 30       |          | 21-Jan-23                 |           | OVD       |                  |
| SN:A-35480788            | HRS                                                                    | 6495.5    |          |          |                           |           |           |                  |
|                          | AFL                                                                    | 3906      |          |          |                           |           |           |                  |
| WO#: N950PC KLM JAN 2023 |                                                                        |           |          |          |                           |           |           |                  |
| 262091B <sup>U</sup>     | CABIN PORTABLE FIRE EXTINGUISHER WEIGHT CHECK                          |           |          |          |                           |           |           | Service ATA:26   |
| PN:C352                  | MOS                                                                    | 03-Oct-22 | 12       |          | 03-Oct-23                 |           | 245 d     |                  |
| SN:A-35480788            | HRS                                                                    |           |          |          |                           |           |           |                  |
|                          | AFL                                                                    |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                  | Unit                                                 | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------|------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 26 - FIRE PROTECTION |                                                      |           |          |          |                           |           |           |                  |
| 262091C <sup>U</sup>     | CABIN PORTABLE FIRE EXTINGUISHER SERVICE             |           |          |          |                           |           |           | Service ATA:26   |
| PN:C352                  | MOS                                                  | 15-Apr-21 | 72       |          | 15-Apr-27                 |           | 1535 d    |                  |
| SN:A-35480788            | HRS                                                  |           |          |          |                           |           |           |                  |
|                          | AFL                                                  |           |          |          |                           |           |           |                  |
| 262091D <sup>U</sup>     | CABIN PORTABLE FIRE EXTINGUISHER HYDRO               |           |          |          |                           |           |           | Service ATA:26   |
| PN:C352                  | MOS                                                  | 15-Apr-21 | 144      |          | 15-Apr-33                 |           | 3727 d    |                  |
| SN:A-35480788            | HRS                                                  | 1.5       |          |          |                           |           |           |                  |
|                          | AFL                                                  |           |          |          |                           |           |           |                  |
| 262109                   | COCKPIT PORTABLE FIRE EXTINGUISHER                   |           |          |          |                           |           |           | Component ATA:26 |
| PN:C352                  | MOS/MSC                                              | 15-Apr-21 | O/C      | TSO 0    |                           |           |           |                  |
| SN:B-74100859            | HRS                                                  | 5960.5    |          | TSO 0    |                           |           |           |                  |
| WC#: 26.080              | AFL                                                  | 3523      |          | TSO 0    |                           |           |           |                  |
| 262109A <sup>U</sup>     | COCKPIT PORTABLE FIRE EXTINGUISHER VISUAL INSPECTION |           |          |          |                           |           |           | Service ATA:26   |
| PN:C352                  | DAYS                                                 | 22-Dec-22 | 30       |          | 21-Jan-23                 |           | OVD       |                  |
| SN:B-74100859            | HRS                                                  | 6495.5    |          |          |                           |           |           |                  |
|                          | AFL                                                  | 3906      |          |          |                           |           |           |                  |
| WO#: N950PC KLM JAN 2023 |                                                      |           |          |          |                           |           |           |                  |
| 262109B <sup>U</sup>     | COCKPIT PORTABLE FIRE EXTINGUISHER WEIGHT CHECK      |           |          |          |                           |           |           | Service ATA:26   |
| PN:C352                  | MOS                                                  | 03-Oct-22 | 12       |          | 03-Oct-23                 |           | 245 d     |                  |
| SN:B-74100859            | HRS                                                  |           |          |          |                           |           |           |                  |
|                          | AFL                                                  |           |          |          |                           |           |           |                  |
| 262109C <sup>U</sup>     | COCKPIT PORTABLE FIRE EXTINGUISHER SERVICE           |           |          |          |                           |           |           | Service ATA:26   |
| PN:C352                  | MOS                                                  | 10-Apr-21 | 72       |          | 15-Apr-27 (M)             |           | 1535 d    |                  |
| SN:B-74100859            | HRS                                                  |           |          |          |                           |           |           |                  |
|                          | AFL                                                  |           |          |          |                           |           |           |                  |
| 262109D <sup>U</sup>     | COCKPIT PORTABLE FIRE EXTINGUISHER HYDRO             |           |          |          |                           |           |           | Service ATA:26   |
| PN:C352                  | MOS                                                  | 10-Apr-21 | 144      |          | 15-Apr-33 (M)             |           | 3727 d    |                  |
| SN:B-74100859            | HRS                                                  |           |          |          |                           |           |           |                  |
|                          | AFL                                                  |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                             | Unit                                         | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------------------------------------------|----------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 26 - FIRE PROTECTION                            |                                              |           |          |          |                           |           |           |                  |
| 262127                                              | APU FIRE EXTINGUISHER                        |           |          |          |                           |           |           | Component ATA:26 |
| PN:30402104                                         | MOS/MSC                                      | 25-Jun-20 | O/C      | TSO 1    |                           |           |           |                  |
| SN:23301B1                                          | HRS                                          | 5801      |          | TSO 0    |                           |           |           |                  |
| WC#: 26.085                                         | AFL                                          | 3399      |          | TSO 0    |                           |           |           |                  |
| PROC. REF: MMA 26-16-00, AMM 26-20-54, AMM 49-61-20 |                                              |           |          |          |                           |           |           |                  |
| 262137                                              | LEAK CHECK APU FIRE EXTINGUISHER             |           |          |          |                           |           |           | Service ATA:26   |
|                                                     | MOS/MSC                                      | 13-Sep-21 | O/C      |          |                           |           |           |                  |
|                                                     | HRS                                          | 6135.7    |          |          |                           |           |           |                  |
| WC#: 26.085                                         | AFL                                          | 3643      |          |          |                           |           |           |                  |
| PROC. REF: CMM 26-20-02                             |                                              |           |          |          |                           |           |           |                  |
| 262139                                              | HYDROSTATIC TEST APU FIRE EXTINGUISHER       |           |          |          |                           |           |           | Service ATA:26   |
| PN:30402104                                         | MOS                                          | 28-May-20 | 60       |          | 28-May-25                 |           | 848 d     |                  |
| SN:23301B1                                          | HRS                                          |           |          |          |                           |           |           |                  |
| WC#: 26.085                                         | AFL                                          |           |          |          |                           |           |           |                  |
| 262143                                              | APU FORWARD CARTRIDGE                        |           |          |          |                           |           |           | Component ATA:26 |
| PN:13083-5                                          | MOS/MSC                                      | 08-Jan-21 | O/C      | TSN 11   |                           |           |           |                  |
| SN:43819                                            | HRS                                          | 5937.6    |          | TSN 0    |                           |           |           |                  |
| WC#: 26.060                                         | AFL                                          | 3502      |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                           |                                              |           |          |          |                           |           |           |                  |
| 262144                                              | APU AFT CARTRIDGE                            |           |          |          |                           |           |           | Component ATA:26 |
| PN:M13083-5                                         | MOS/MSC                                      | 08-Jan-21 | O/C      | TSN 0    |                           |           |           |                  |
| SN:43822                                            | HRS                                          | 5937.6    |          | TSN 0    |                           |           |           |                  |
| WC#: 26.065                                         | AFL                                          | 3502      |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                           |                                              |           |          |          |                           |           |           |                  |
| 262145                                              | REPLACE APU FORWARD CARTRIDGE (SERVICE LIFE) |           |          |          |                           |           |           | Service ATA:26   |
| PN:13083-5                                          | MOS/MSC                                      | 08-Jan-21 | N/R      |          |                           |           |           |                  |
| SN:43819                                            | HRS                                          | 5937.6    |          |          |                           |           |           |                  |
| WC#: 26.060                                         | AFL                                          | 3502      |          |          |                           |           |           |                  |
| PROC. REF: AMM 26-20-54, CMM 26-20-02               |                                              |           |          |          |                           |           |           |                  |
| 262157                                              | REPLACE APU FORWARD CARTRIDGE (LIFE LIMIT)   |           |          |          |                           |           |           | Service ATA:26   |
| PN:13083-5                                          | MOS                                          | 01-Apr-20 | 72       |          | 01-Apr-26                 |           | 1156 d    | LIFE LIMIT       |
| SN:43819                                            | HRS                                          |           |          |          |                           |           |           |                  |
| WC#: 26.060                                         | AFL                                          |           |          |          |                           |           |           |                  |
| PROC. REF: AMM 26-20-54, CMM 26-20-02               |                                              |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                                                                       | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                 | Disposition      |
|---------------------------|----------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|---------------------------|------------------|
| ATA 26 - FIRE PROTECTION  |                                                                            |           |          |          |                           |           |                           |                  |
| 262163                    | REPLACE APU AFT CARTRIDGE (LIFE LIMIT)                                     |           |          |          |                           |           |                           | Service ATA:26   |
| PN:AE13083-5              | MOS                                                                        | 30-Apr-20 | 72       |          | 30-Apr-26                 |           | 1185 d                    | LIFE LIMIT       |
| SN:AEN1-183               | HRS                                                                        |           |          |          |                           |           |                           |                  |
| WC#: 26.065               | AFL                                                                        |           |          |          |                           |           |                           |                  |
| PROC. REF: AMM 26-20-54   |                                                                            |           |          |          |                           |           |                           |                  |
| 262190                    | FORWARD EXTINGUISHER GONE INDICATION FUSE CARTRIDGE                        |           |          |          |                           |           |                           | Component ATA:26 |
| PN:A1003(1)               | MOS/MSC                                                                    | 15-Jun-21 | O/C      | TSN 0    |                           |           |                           |                  |
| SN:NSN                    | HRS                                                                        | 6045.6    |          | TSN 0    |                           |           |                           |                  |
| WC#: 26.100               | AFL                                                                        | 3575      |          | TSN 0    |                           |           |                           |                  |
| PROC. REF: GENERIC NO REF |                                                                            |           |          |          |                           |           |                           |                  |
|                           |                                                                            |           |          |          |                           |           | WO#: N950PC 48 MONTH INSP |                  |
| 262195                    | AFT EXTINGUISHER GONE INDICATION FUSE CARTRIDGE                            |           |          |          |                           |           |                           | Component ATA:26 |
| PN:A1003(1)               | MOS/MSC                                                                    | 15-Jun-21 | O/C      | TSN 0    |                           |           |                           |                  |
| SN:NSN                    | HRS                                                                        | 6045.6    |          | TSN 0    |                           |           |                           |                  |
| WC#: 26.105               | AFL                                                                        | 3575      |          | TSN 0    |                           |           |                           |                  |
| PROC. REF: GENERIC NO REF |                                                                            |           |          |          |                           |           |                           |                  |
|                           |                                                                            |           |          |          |                           |           | WO#: N950PC 48 MONTH INSP |                  |
| 262199                    | REPLACE FORWARD EXTINGUISHER GONE INDICATION FUSE CARTRIDGE (LIFE LIMIT)   |           |          |          |                           |           |                           | Service ATA:26   |
| PN:A1003(1)               | MOS                                                                        | 01-Sep-20 | 48       |          | 01-Sep-24                 |           | 579 d                     | LIFE LIMIT       |
| SN:NSN                    | HRS                                                                        |           |          |          |                           |           |                           |                  |
| WC#: 26.100               | AFL                                                                        |           |          |          |                           |           |                           |                  |
| PROC. REF: AMM 26-20-41   |                                                                            |           |          |          |                           |           |                           |                  |
|                           |                                                                            |           |          |          |                           |           | WO#: N950PC 48 MONTH INSP |                  |
| 262200                    | REPLACE AFT EXTINGUISHER GONE INDICATION FUSE CARTRIDGE (LIFE LIMIT)       |           |          |          |                           |           |                           | Service ATA:26   |
| PN:A1003(1)               | MOS                                                                        | 01-Sep-20 | 48       |          | 01-Sep-24                 |           | 579 d                     | LIFE LIMIT       |
| SN:NSN                    | HRS                                                                        |           |          |          |                           |           |                           |                  |
| WC#: 26.105               | AFL                                                                        |           |          |          |                           |           |                           |                  |
| PROC. REF: AMM 26-20-41   |                                                                            |           |          |          |                           |           |                           |                  |
|                           |                                                                            |           |          |          |                           |           | WO#: N950PC 48 MONTH INSP |                  |
| 262201                    | REPLACE FORWARD EXTINGUISHER GONE INDICATION FUSE CARTRIDGE (SERVICE LIFE) |           |          |          |                           |           |                           | Service ATA:26   |
| PN:A1003(1)               | MOS                                                                        | 15-Jun-21 | 36       |          | 01-Sep-23 (M)             |           | 213 d                     | LIFE LIMIT       |
| SN:NSN                    | HRS                                                                        |           |          |          |                           |           |                           |                  |
| WC#: 26.100               | AFL                                                                        |           |          |          |                           |           |                           |                  |
| PROC. REF: AMM 26-20-41   |                                                                            |           |          |          |                           |           |                           |                  |
|                           |                                                                            |           |          |          |                           |           | WO#: N950PC 48 MONTH INSP |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                                                                                           | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                 | Disposition      |
|---------------------------|------------------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|---------------------------|------------------|
| ATA 26 - FIRE PROTECTION  |                                                                                                |           |          |          |                           |           |                           |                  |
| 262202                    | REPLACE AFT EXTINGUISHER GONE INDICATION FUSE CARTRIDGE (SERVICE LIFE)                         |           |          |          |                           |           |                           | Service ATA:26   |
| PN:A1003(1)               | MOS                                                                                            | 15-Jun-21 | 36       |          | 01-Sep-23 (M)             |           | 213 d                     | LIFE LIMIT       |
| SN:NSN                    | HRS                                                                                            |           |          |          |                           |           |                           |                  |
| WC#: 26.105               | AFL                                                                                            |           |          |          |                           |           |                           |                  |
| PROC. REF: AMM 26-20-41   |                                                                                                |           |          |          |                           |           | WO#: N950PC 48 MONTH INSP |                  |
| 262210                    | EXTERNAL BAGGAGE UNIT FIRE EXTINGUISHER                                                        |           |          |          |                           |           |                           | Component ATA:26 |
| PN:PN                     | MOS/MSC                                                                                        | 30-May-96 | O/C      | TSN 0    |                           |           |                           |                  |
| SN:UNKNOWN                | HRS                                                                                            | 0         |          | TSN 0    |                           |           |                           |                  |
| WC#: 26.145               | AFL                                                                                            | 0         |          | TSN 0    |                           |           |                           |                  |
| 262215                    | HYDROSTATIC TEST EXTERNAL BAGGAGE UNIT FIRE EXTINGUISHER                                       |           |          |          |                           |           |                           | Service ATA:26   |
| PN:PN                     | MOS/MSC                                                                                        |           | N/A      |          |                           |           |                           |                  |
| SN:UNKNOWN                | HRS                                                                                            |           |          |          |                           |           |                           |                  |
| WC#: 26.145               | AFL                                                                                            |           |          |          |                           |           |                           |                  |
| PROC. REF: GENERIC NO REF |                                                                                                |           |          |          |                           |           |                           |                  |
| 262220                    | EXTERNAL BAGGAGE UNIT FIRE EXTINGUISHER CARTRIDGE                                              |           |          |          |                           |           |                           | Component ATA:26 |
| PN:PN                     | MOS/MSC                                                                                        | 30-May-96 | O/C      | TSN 0    |                           |           |                           |                  |
| SN:UNKNOWN                | HRS                                                                                            | 0         |          | TSN 0    |                           |           |                           |                  |
| WC#: 26.160               | AFL                                                                                            | 0         |          | TSN 0    |                           |           |                           |                  |
| 262225                    | REPLACE EXTERNAL BAGGAGE UNIT FIRE EXTINGUISHER CARTRIDGE (LIFE LIMIT)                         |           |          |          |                           |           |                           | Service ATA:26   |
| PN:PN                     | MOS/MSC                                                                                        |           | N/A      |          |                           |           |                           |                  |
| SN:UNKNOWN                | HRS                                                                                            |           |          |          |                           |           |                           |                  |
| WC#: 26.160               | AFL                                                                                            |           |          |          |                           |           |                           |                  |
| PROC. REF: GENERIC NO REF |                                                                                                |           |          |          |                           |           |                           |                  |
| 262230                    | EXTERNAL BAGGAGE UNIT (EBU) EXTINGUISHER GONE INDICATION FUSE CARTRIDGE                        |           |          |          |                           |           |                           | Component ATA:26 |
| PN:PN                     | MOS/MSC                                                                                        |           | N/A      |          |                           |           |                           |                  |
| SN:UNKNOWN                | HRS                                                                                            |           |          |          |                           |           |                           |                  |
| WC#: 26.040               | AFL                                                                                            |           |          |          |                           |           |                           |                  |
| PROC. REF: GENERIC NO REF |                                                                                                |           |          |          |                           |           |                           |                  |
| 262235                    | REPLACE EXTERNAL BAGGAGE UNIT (EBU) EXTINGUISHER GONE INDICATION FUSE CARTRIDGE (SERVICE LIFE) |           |          |          |                           |           |                           | Service ATA:26   |
| PN:PN                     | MOS/MSC                                                                                        |           | N/A      |          |                           |           |                           |                  |
| SN:UNKNOWN                | HRS                                                                                            |           |          |          |                           |           |                           |                  |
| WC#: 26.040               | AFL                                                                                            |           |          |          |                           |           |                           |                  |
| PROC. REF: GENERIC NO REF |                                                                                                |           |          |          |                           |           |                           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                  | Unit                                           | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                           | Disposition      |
|------------------------------------------|------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-------------------------------------|------------------|
| ATA 26 - FIRE PROTECTION                 |                                                |           |                |          |                           |           |                                     |                  |
| 262301                                   | SMOKE DETECTOR AMPLIFIER                       |           |                |          |                           |           |                                     | Component ATA:26 |
| PN:30326-7                               | MOS/MSC                                        | 30-Aug-96 | O/C            |          |                           |           |                                     |                  |
| SN:1988                                  | HRS                                            | 16        |                | TSN 0    |                           |           |                                     |                  |
| WC#: 26.070                              | AFL                                            | 9         |                |          |                           |           |                                     |                  |
| 262307                                   | FORWARD BAGGAGE COMPARTMENT SMOKE DETECTOR     |           |                |          |                           |           |                                     | Component ATA:26 |
| PN:30231-3                               | MOS/MSC                                        | 30-May-96 | O/C            |          |                           |           |                                     |                  |
| SN:UNKNOWN                               | HRS                                            | 0         |                | TSN 0    |                           |           |                                     |                  |
| WC#: 26.110                              | AFL                                            | 0         |                |          |                           |           |                                     |                  |
| PROC. REF: MMA 26-11-00, AMM 26-10-51    |                                                |           |                |          |                           |           |                                     |                  |
| 262308                                   | AFT BAGGAGE COMPARTMENT SMOKE DETECTOR         |           |                |          |                           |           |                                     | Component ATA:26 |
| PN:30231-3                               | MOS/MSC                                        | 30-May-96 | O/C            |          |                           |           |                                     |                  |
| SN:UNKNOWN                               | HRS                                            | 0         |                | TSN 0    |                           |           |                                     |                  |
| WC#: 26.110                              | AFL                                            | 0         |                |          |                           |           |                                     |                  |
| PROC. REF: MMA 26-11-00, AMM 26-10-51    |                                                |           |                |          |                           |           |                                     |                  |
| 262309                                   | VANITY SMOKE DETECTOR                          |           |                |          |                           |           |                                     | Component ATA:26 |
| PN:30231-3                               | MOS/MSC                                        | 30-May-96 | O/C            |          |                           |           |                                     |                  |
| SN:UNKNOWN                               | HRS                                            | 0         |                | TSN 0    |                           |           |                                     |                  |
| WC#: 26.110                              | AFL                                            | 0         |                |          |                           |           |                                     |                  |
| PROC. REF: MMA 26-11-00                  |                                                |           |                |          |                           |           |                                     |                  |
| ATA 27 - FLIGHT CONTROLS                 |                                                |           |                |          |                           |           |                                     |                  |
| 270001                                   | OPERATIONAL TEST AIRBRAKE SELECTOR LEVER BAULK |           |                |          |                           |           |                                     | Service ATA:27   |
|                                          | MOS/MSC                                        |           | N/R            |          |                           |           |                                     |                  |
|                                          | HRS                                            | 0         |                |          |                           |           |                                     |                  |
| WC#: 27.265                              | AFL                                            |           |                |          |                           |           |                                     |                  |
| PROC. REF: AFMS OUT OF PHASE INSPECTIONS |                                                |           |                |          |                           |           |                                     |                  |
| 270002                                   | INSPECT LEFT WING FLAP VANE INNER              |           |                |          |                           |           |                                     | Service ATA:27   |
|                                          | MOS                                            | 06-May-15 |                |          |                           |           |                                     |                  |
|                                          | HRS                                            | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50)                         |                  |
| WC#: 27.490                              | AFL                                            | 2873      |                |          |                           |           |                                     |                  |
| PROC. REF: AFMS INSPECTION C9            |                                                |           |                |          |                           |           |                                     |                  |
|                                          |                                                |           |                |          |                           |           | PKG:3,28<br>WO#: N950PC B & C CHECK |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                     | Unit                                                    | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                           | Disposition    |
|---------------------------------------------|---------------------------------------------------------|-----------|---------------|----------|---------------------------|-----------|-------------------------------------|----------------|
| ATA 27 - FLIGHT CONTROLS                    |                                                         |           |               |          |                           |           |                                     |                |
| 270003                                      | INSPECT LEFT WING FLAP SCREWJACKS SCREW THREADS         |           |               |          |                           |           |                                     | Service ATA:27 |
|                                             | MOS                                                     | 15-Oct-19 |               |          |                           |           |                                     |                |
|                                             | HRS                                                     | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)                            |                |
| WC#: 27.495                                 | AFL                                                     | 3397      |               |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION B9               |                                                         |           |               |          |                           |           | PKG:2,16<br>WO#: N950PC B & C CHECK |                |
| 270004                                      | FUNCTIONAL TEST STALL WARNING AND IDENTIFICATION SYSTEM |           |               |          |                           |           |                                     | Service ATA:27 |
|                                             | MOS                                                     | 15-Oct-19 |               |          |                           |           |                                     |                |
|                                             | HRS                                                     | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)                            |                |
| WC#: 27.120                                 | AFL                                                     | 3397      |               |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION B2, AMM 27-33-00 |                                                         |           |               |          |                           |           | PKG:2,9<br>WO#: N950PC B & C CHECK  |                |
| 270008                                      | FUNCTIONAL TEST RUDDER BIAS STRUT HEATER MUFFS          |           |               |          |                           |           |                                     | Service ATA:27 |
|                                             | MOS                                                     | 15-Oct-19 |               |          |                           |           |                                     |                |
|                                             | HRS                                                     | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)                            |                |
| WC#: 27.060                                 | AFL                                                     | 3397      |               |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION B2, AMM 27-20-00 |                                                         |           |               |          |                           |           | PKG:2,9<br>WO#: N950PC B & C CHECK  |                |
| 270009                                      | FUNCTIONAL TEST STALL DETECTOR UNIT (THIRD CHANNEL)     |           |               |          |                           |           |                                     | Service ATA:27 |
|                                             | MOS                                                     | 15-Oct-19 |               |          |                           |           |                                     |                |
|                                             | HRS                                                     | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)                            |                |
| WC#: 27.110                                 | AFL                                                     | 3397      |               |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION B2, AMM 27-33-14 |                                                         |           |               |          |                           |           | PKG:2,9<br>WO#: N950PC B & C CHECK  |                |
| 270011                                      | INSPECT GUST LOCKS/AILERONS AND ELEVATORS               |           |               |          |                           |           |                                     | Service ATA:27 |
|                                             | MOS                                                     | 15-Oct-19 |               |          |                           |           |                                     |                |
|                                             | HRS                                                     | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)                            |                |
| WC#: 27.415                                 | AFL                                                     | 3397      |               |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION B4               |                                                         |           |               |          |                           |           | PKG:2,11<br>WO#: N950PC B & C CHECK |                |
| 270012                                      | CHECK AND INSPECT RUDDER TRIM TAB AND ANTI SERVO TAB    |           |               |          |                           |           |                                     | Service ATA:27 |
|                                             | MOS                                                     | 15-Oct-19 |               |          |                           |           |                                     |                |
|                                             | HRS                                                     | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)                            |                |
| WC#: 27.450                                 | AFL                                                     | 3397      |               |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION B8, AMM 27-20-00 |                                                         |           |               |          |                           |           | PKG:2,15<br>WO#: N950PC B & C CHECK |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                  | Unit                                                    | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition                                           |
|--------------------------|---------------------------------------------------------|-----------|---------------|----------|---------------------------|-----------|-----------|-------------------------------------------------------|
| ATA 27 - FLIGHT CONTROLS |                                                         |           |               |          |                           |           |           |                                                       |
| 270013                   | CHECK AND INSPECT ELEVATORS AND TRIM TABS               |           |               |          |                           |           |           | Service ATA:27                                        |
|                          | MOS                                                     | 15-Oct-19 |               |          |                           |           |           |                                                       |
|                          | HRS                                                     | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)  |                                                       |
| WC#: 27.485              | AFL                                                     | 3397      |               |          |                           |           |           |                                                       |
|                          | PROC. REF: AFMS INSPECTION B8, AMM 27-30-00             |           |               |          |                           |           |           | PKG:2,15<br>WO#: N950PC B & C CHECK                   |
| 270014                   | INSPECT RUDDER AND ELEVATORS PRIMARY SURFACES           |           |               |          |                           |           |           | Service ATA:27                                        |
|                          | MOS                                                     | 15-Oct-19 |               |          |                           |           |           |                                                       |
|                          | HRS                                                     | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)  |                                                       |
| WC#: 27.420              | AFL                                                     | 3397      |               |          |                           |           |           |                                                       |
|                          | PROC. REF: AFMS INSPECTION B8                           |           |               |          |                           |           |           | PKG:2,15<br>WO#: N950PC B & C CHECK                   |
| 270015                   | OPERATIONAL CHECK LEFT AILERON PRIMARY SURFACES         |           |               |          |                           |           |           | Service ATA:27                                        |
|                          | MOS                                                     | 15-Oct-19 |               |          |                           |           |           |                                                       |
|                          | HRS                                                     | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)  |                                                       |
| WC#: 27.425              | AFL                                                     | 3397      |               |          |                           |           |           |                                                       |
|                          | PROC. REF: AFMS INSPECTION B9                           |           |               |          |                           |           |           | PKG:2,16<br>WO#: N950PC B & C CHECK,KLM - HANGAR RASH |
| 270016                   | CHECK AND INSPECT LEFT AILERON TRIM AND SERVO TABS      |           |               |          |                           |           |           | Service ATA:27                                        |
|                          | MOS                                                     | 15-Oct-19 |               |          |                           |           |           |                                                       |
|                          | HRS                                                     | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)  |                                                       |
| WC#: 27.435              | AFL                                                     | 3397      |               |          |                           |           |           |                                                       |
|                          | PROC. REF: AFMS INSPECTION B9                           |           |               |          |                           |           |           | PKG:2,16<br>WO#: N950PC B & C CHECK                   |
| 270017                   | CHECK LEFT FLAP SCREWJACK AND REDUCTION GEARBOX         |           |               |          |                           |           |           | Service ATA:27                                        |
|                          | MOS                                                     | 15-Oct-19 |               |          |                           |           |           |                                                       |
|                          | HRS                                                     | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)  |                                                       |
| WC#: 27.500              | AFL                                                     | 3397      |               |          |                           |           |           |                                                       |
|                          | PROC. REF: AFMS INSPECTION B9, AMM 27-50-141            |           |               |          |                           |           |           | PKG:2,16<br>WO#: N950PC B & C CHECK                   |
| 270018                   | INSPECT LEFT FLAP SYNCHRONIZATION SYSTEM CONTROL CABLES |           |               |          |                           |           |           | Service ATA:27                                        |
|                          | MOS                                                     | 15-Oct-19 |               |          |                           |           |           |                                                       |
|                          | HRS                                                     | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)  |                                                       |
| WC#: 27.550              | AFL                                                     | 3397      |               |          |                           |           |           |                                                       |
|                          | PROC. REF: AFMS INSPECTION B9                           |           |               |          |                           |           |           | PKG:2,16<br>WO#: N950PC B & C CHECK                   |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                       | Unit                                             | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition                         |
|-----------------------------------------------|--------------------------------------------------|-----------|---------------|----------|---------------------------|-----------|-----------|-------------------------------------|
| ATA 27 - FLIGHT CONTROLS                      |                                                  |           |               |          |                           |           |           |                                     |
| 270019                                        | CHECK FLAP CONTROL UNIT                          |           |               |          |                           |           |           | Service ATA:27                      |
|                                               | MOS                                              | 15-Oct-19 |               |          |                           |           |           |                                     |
|                                               | HRS                                              | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)  |                                     |
| WC#: 27.525                                   | AFL                                              | 3397      |               |          |                           |           |           |                                     |
| PROC. REF: AFMS INSPECTION B9, AMM 27-50-02   |                                                  |           |               |          |                           |           |           | PKG:2,16<br>WO#: N950PC B & C CHECK |
| 270020                                        | OPERATE FLAP CONTROL UNIT                        |           |               |          |                           |           |           | Service ATA:27                      |
|                                               | MOS                                              | 15-Oct-19 |               |          |                           |           |           |                                     |
|                                               | HRS                                              | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)  |                                     |
| WC#: 27.520                                   | AFL                                              | 3397      |               |          |                           |           |           |                                     |
| PROC. REF: AFMS INSPECTION B9                 |                                                  |           |               |          |                           |           |           | PKG:2,16<br>WO#: N950PC B & C CHECK |
| 270021                                        | INSPECT LEFT FLAP DRIVE SHAFTS                   |           |               |          |                           |           |           | Service ATA:27                      |
|                                               | MOS                                              | 15-Oct-19 |               |          |                           |           |           |                                     |
|                                               | HRS                                              | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)  |                                     |
| WC#: 27.510                                   | AFL                                              | 3397      |               |          |                           |           |           |                                     |
| PROC. REF: AFMS INSPECTION B9                 |                                                  |           |               |          |                           |           |           | PKG:2,16<br>WO#: N950PC B & C CHECK |
| 270022                                        | OPERATIONAL CHECK RIGHT AILERON PRIMARY SURFACES |           |               |          |                           |           |           | Service ATA:27                      |
|                                               | MOS                                              | 15-Oct-19 |               |          |                           |           |           |                                     |
|                                               | HRS                                              | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)  |                                     |
| WC#: 27.425                                   | AFL                                              | 3397      |               |          |                           |           |           |                                     |
| PROC. REF: AFMS INSPECTION B10                |                                                  |           |               |          |                           |           |           | PKG:2,17<br>WO#: N950PC B & C CHECK |
| 270023                                        | CHECK AND INSPECT RIGHT AILERON SERVO TABS       |           |               |          |                           |           |           | Service ATA:27                      |
|                                               | MOS                                              | 15-Oct-19 |               |          |                           |           |           |                                     |
|                                               | HRS                                              | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)  |                                     |
| WC#: 27.435                                   | AFL                                              | 3397      |               |          |                           |           |           |                                     |
| PROC. REF: AFMS INSPECTION B10                |                                                  |           |               |          |                           |           |           | PKG:2,17<br>WO#: N950PC B & C CHECK |
| 270024                                        | CHECK RIGHT FLAP SCREWJACK AND REDUCTION GEARBOX |           |               |          |                           |           |           | Service ATA:27                      |
|                                               | MOS                                              | 15-Oct-19 |               |          |                           |           |           |                                     |
|                                               | HRS                                              | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)  |                                     |
| WC#: 27.500                                   | AFL                                              | 3397      |               |          |                           |           |           |                                     |
| PROC. REF: AFMS INSPECTION B10, AMM 27-50-141 |                                                  |           |               |          |                           |           |           | PKG:2,17<br>WO#: N950PC B & C CHECK |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                  | Unit                                                     | C/W       | Interval       | TSX/Adj.                                                  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition                         |
|--------------------------|----------------------------------------------------------|-----------|----------------|-----------------------------------------------------------|---------------------------|-----------|-------------|-------------------------------------|
| ATA 27 - FLIGHT CONTROLS |                                                          |           |                |                                                           |                           |           |             |                                     |
| 270025                   | INSPECT RIGHT FLAP SYNCHRONIZATION SYSTEM CONTROL CABLES |           |                |                                                           |                           |           |             | Service ATA:27                      |
|                          | MOS                                                      | 15-Oct-19 |                |                                                           |                           |           |             |                                     |
|                          | HRS                                                      | 5795.3    | 800 (+40/-10)  |                                                           | 6595.3                    | 6635.3    | 67 (+40)    |                                     |
| WC#: 27.550              | AFL                                                      | 3397      |                |                                                           |                           |           |             |                                     |
|                          |                                                          |           |                | PROC. REF: AFMS INSPECTION B10                            |                           |           |             | PKG:2,17<br>WO#: N950PC B & C CHECK |
| 270026                   | INSPECT RIGHT FLAP DRIVE SHAFTS                          |           |                |                                                           |                           |           |             | Service ATA:27                      |
|                          | MOS                                                      | 15-Oct-19 |                |                                                           |                           |           |             |                                     |
|                          | HRS                                                      | 5795.3    | 800 (+40/-10)  |                                                           | 6595.3                    | 6635.3    | 67 (+40)    |                                     |
| WC#: 27.510              | AFL                                                      | 3397      |                |                                                           |                           |           |             |                                     |
|                          |                                                          |           |                | PROC. REF: AFMS INSPECTION B10                            |                           |           |             | PKG:2,17<br>WO#: N950PC B & C CHECK |
| 270027                   | FUNCTIONAL TEST FLAP CONTROL SYSTEM                      |           |                |                                                           |                           |           |             | Service ATA:27                      |
|                          | MOS                                                      | 15-Oct-19 |                |                                                           |                           |           |             |                                     |
|                          | HRS                                                      | 5795.3    | 800 (+40/-10)  |                                                           | 6595.3                    | 6635.3    | 67 (+40)    |                                     |
| WC#: 27.200              | AFL                                                      | 3397      |                |                                                           |                           |           |             |                                     |
|                          |                                                          |           |                | PROC. REF: AFMS INSPECTION B12, AMM 27-50-02              |                           |           |             | PKG:2,19<br>WO#: N950PC B & C CHECK |
| 270028                   | FUNCTIONAL TEST AIRBRAKE AND LIFT DUMP SYSTEM            |           |                |                                                           |                           |           |             | Service ATA:27                      |
|                          | MOS                                                      | 15-Oct-19 |                |                                                           |                           |           |             |                                     |
|                          | HRS                                                      | 5795.3    | 800 (+40/-10)  |                                                           | 6595.3                    | 6635.3    | 67 (+40)    |                                     |
| WC#: 27.260              | AFL                                                      | 3397      |                |                                                           |                           |           |             |                                     |
|                          |                                                          |           |                | PROC. REF: AFMS INSPECTION B12, AMM 27-61-02              |                           |           |             | PKG:2,19<br>WO#: N950PC B & C CHECK |
| 270030                   | CHECK ELEVATOR TRIM SERVO                                |           |                |                                                           |                           |           |             | Service ATA:27                      |
|                          | MOS                                                      | 06-May-15 |                |                                                           |                           |           |             |                                     |
|                          | HRS                                                      | 5125.6    | 1600 (+50/-50) |                                                           | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 27.095              | AFL                                                      | 2873      |                |                                                           |                           |           |             |                                     |
|                          |                                                          |           |                | PROC. REF: AFMS INSPECTION C2                             |                           |           |             | PKG:3,21<br>WO#: N950PC B & C CHECK |
| 270032                   | CHECK AILERON AUTOPILOT SERVO CONTROL CABLES             |           |                |                                                           |                           |           |             | Service ATA:27                      |
|                          | MOS                                                      | 06-May-15 |                |                                                           |                           |           |             |                                     |
|                          | HRS                                                      | 5125.6    | 1600 (+50/-50) |                                                           | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 27.440              | AFL                                                      | 2873      |                |                                                           |                           |           |             |                                     |
|                          |                                                          |           |                | PROC. REF: AFMS INSPECTION C4, AMM 27-00-00, AMM 27-10-93 |                           |           |             | PKG:3,23<br>WO#: N950PC B & C CHECK |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                  | Unit                                                    | C/W       | Interval                                    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition                         |
|--------------------------|---------------------------------------------------------|-----------|---------------------------------------------|----------|---------------------------|-----------|-------------|-------------------------------------|
| ATA 27 - FLIGHT CONTROLS |                                                         |           |                                             |          |                           |           |             |                                     |
| 270033                   | INSPECT ELEVATOR CONTROL SYSTEM BALANCE/FEEL SPRING     |           |                                             |          |                           |           |             | Service ATA:27                      |
|                          | MOS                                                     | 06-May-15 |                                             |          |                           |           |             |                                     |
|                          | HRS                                                     | 5125.6    | 1600 (+50/-50)                              |          | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 27.100              | AFL                                                     | 2873      |                                             |          |                           |           |             |                                     |
|                          |                                                         |           | PROC. REF: AFMS INSPECTION C4               |          |                           |           |             | PKG:3,23<br>WO#: N950PC B & C CHECK |
| 270034                   | CHECK ELEVATOR PRIMARY CONTROL CABLES                   |           |                                             |          |                           |           |             | Service ATA:27                      |
|                          | MOS                                                     | 06-May-15 |                                             |          |                           |           |             |                                     |
|                          | HRS                                                     | 5125.6    | 1600 (+50/-50)                              |          | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 27.460              | AFL                                                     | 2873      |                                             |          |                           |           |             |                                     |
|                          |                                                         |           | PROC. REF: AFMS INSPECTION C5, AMM 27-30-00 |          |                           |           |             | PKG:3,24<br>WO#: N950PC B & C CHECK |
| 270035                   | CHECK FLAP CONTROL CABLES                               |           |                                             |          |                           |           |             | Service ATA:27                      |
|                          | MOS                                                     | 06-May-15 |                                             |          |                           |           |             |                                     |
|                          | HRS                                                     | 5125.6    | 1600 (+50/-50)                              |          | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 27.540              | AFL                                                     | 2873      |                                             |          |                           |           |             |                                     |
|                          |                                                         |           | PROC. REF: AFMS INSPECTION C5, AMM 27-50-02 |          |                           |           |             | PKG:3,24<br>WO#: N950PC B & C CHECK |
| 270036                   | CHECK ELEVATOR PRIMARY AND ELEVATOR TRIM CONTROL CABLES |           |                                             |          |                           |           |             | Service ATA:27                      |
|                          | MOS                                                     | 06-May-15 |                                             |          |                           |           |             |                                     |
|                          | HRS                                                     | 5125.6    | 1600 (+50/-50)                              |          | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 27.465              | AFL                                                     | 2873      |                                             |          |                           |           |             |                                     |
|                          |                                                         |           | PROC. REF: AFMS INSPECTION C7, AMM 27-30-00 |          |                           |           |             | PKG:3,26<br>WO#: N950PC B & C CHECK |
| 270037                   | CHECK RUDDER PRIMARY AND RUDDER TRIM CONTROL CABLES     |           |                                             |          |                           |           |             | Service ATA:27                      |
|                          | MOS                                                     | 06-May-15 |                                             |          |                           |           |             |                                     |
|                          | HRS                                                     | 5125.6    | 1600 (+50/-50)                              |          | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 27.455              | AFL                                                     | 2873      |                                             |          |                           |           |             |                                     |
|                          |                                                         |           | PROC. REF: AFMS INSPECTION C7, AMM 27-20-00 |          |                           |           |             | PKG:3,26<br>WO#: N950PC B & C CHECK |
| 270038                   | CHECK ELEVATOR AUTOPILOT SERVO CONTROL CABLES           |           |                                             |          |                           |           |             | Service ATA:27                      |
|                          | MOS                                                     | 06-May-15 |                                             |          |                           |           |             |                                     |
|                          | HRS                                                     | 5125.6    | 1600 (+50/-50)                              |          | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 27.475              | AFL                                                     | 2873      |                                             |          |                           |           |             |                                     |
|                          |                                                         |           | PROC. REF: AFMS INSPECTION C7, AMM 27-30-81 |          |                           |           |             | PKG:3,26<br>WO#: N950PC B & C CHECK |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                      | Unit                                               | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                           | Disposition    |
|----------------------------------------------|----------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-------------------------------------|----------------|
| ATA 27 - FLIGHT CONTROLS                     |                                                    |           |                |          |                           |           |                                     |                |
| 270039                                       | CHECK RUDDER AUTOPILOT SERVO CONTROL CABLES        |           |                |          |                           |           |                                     | Service ATA:27 |
|                                              | MOS                                                | 06-May-15 |                |          |                           |           |                                     |                |
|                                              | HRS                                                | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50)                         |                |
| WC#: 27.445                                  | AFL                                                | 2873      |                |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION C7, AMM 27-20-121 |                                                    |           |                |          |                           |           | PKG:3,26<br>WO#: N950PC B & C CHECK |                |
| 270040                                       | CHECK ELEVATOR AUTOPILOT TRIM-SERVO CONTROL CABLES |           |                |          |                           |           |                                     | Service ATA:27 |
|                                              | MOS                                                | 06-May-15 |                |          |                           |           |                                     |                |
|                                              | HRS                                                | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50)                         |                |
| WC#: 27.480                                  | AFL                                                | 2873      |                |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION C7, AMM 27-30-00  |                                                    |           |                |          |                           |           | PKG:3,26<br>WO#: N950PC B & C CHECK |                |
| 270041                                       | INSPECT ELEVATOR TRIM CABLES                       |           |                |          |                           |           |                                     | Service ATA:27 |
|                                              | MOS                                                | 06-May-15 |                |          |                           |           |                                     |                |
|                                              | HRS                                                | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50)                         |                |
| WC#: 27.470                                  | AFL                                                | 2873      |                |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION C8, AMM 27-30-00  |                                                    |           |                |          |                           |           | PKG:3,27<br>WO#: N950PC B & C CHECK |                |
| 270042                                       | CHECK LEFT AILERON PRIMARY AND TRIM CONTROL CABLES |           |                |          |                           |           |                                     | Service ATA:27 |
|                                              | MOS                                                | 06-May-15 |                |          |                           |           |                                     |                |
|                                              | HRS                                                | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50)                         |                |
| WC#: 27.430                                  | AFL                                                | 2873      |                |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION C9                |                                                    |           |                |          |                           |           | PKG:3,28<br>WO#: N950PC B & C CHECK |                |
| 270043                                       | INSPECT LEFT FLAP DRIVE SHAFT UNIVERSAL JOINT      |           |                |          |                           |           |                                     | Service ATA:27 |
|                                              | MOS                                                | 06-May-15 |                |          |                           |           |                                     |                |
|                                              | HRS                                                | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50)                         |                |
| WC#: 27.565                                  | AFL                                                | 2873      |                |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION C9                |                                                    |           |                |          |                           |           | PKG:3,28<br>WO#: N950PC B & C CHECK |                |
| 270044                                       | CHECK LEFT FLAP BEVEL DRIVE ASSEMBLY               |           |                |          |                           |           |                                     | Service ATA:27 |
|                                              | MOS                                                | 06-May-15 |                |          |                           |           |                                     |                |
|                                              | HRS                                                | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50)                         |                |
| WC#: 27.535                                  | AFL                                                | 2873      |                |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION C9                |                                                    |           |                |          |                           |           | PKG:3,28<br>WO#: N950PC B & C CHECK |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                  | Unit                                        | C/W       | Interval       | TSX/Adj.                                     | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition                         |
|--------------------------|---------------------------------------------|-----------|----------------|----------------------------------------------|---------------------------|-----------|-------------|-------------------------------------|
| ATA 27 - FLIGHT CONTROLS |                                             |           |                |                                              |                           |           |             |                                     |
| 270045                   | CHECK FLAP CONTROL UNIT BAULK RELEASE CABLE |           |                |                                              |                           |           |             | Service ATA:27                      |
|                          | MOS                                         | 06-May-15 |                |                                              |                           |           |             |                                     |
|                          | HRS                                         | 5125.6    | 1600 (+50/-50) |                                              | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 27.515              | AFL                                         | 2873      |                |                                              |                           |           |             |                                     |
|                          |                                             |           |                | PROC. REF: AFMS INSPECTION C9, AMM 27-50-02  |                           |           |             | PKG:3,28<br>WO#: N950PC B & C CHECK |
| 270046                   | CHECK FLAP/AIRBRAKE BAULK BOBBIN            |           |                |                                              |                           |           |             | Service ATA:27                      |
|                          | MOS                                         | 06-May-15 |                |                                              |                           |           |             |                                     |
|                          | HRS                                         | 5125.6    | 1600 (+50/-50) |                                              | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 27.575              | AFL                                         | 2873      |                |                                              |                           |           |             |                                     |
|                          |                                             |           |                | PROC. REF: AFMS INSPECTION C9, AMM 27-50-02  |                           |           |             | PKG:3,28<br>WO#: N950PC B & C CHECK |
| 270047                   | CHECK FLAP SPRING DRUM PULLEY-LEVER         |           |                |                                              |                           |           |             | Service ATA:27                      |
|                          | MOS                                         | 06-May-15 |                |                                              |                           |           |             |                                     |
|                          | HRS                                         | 5125.6    | 1600 (+50/-50) |                                              | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 27.555              | AFL                                         | 2873      |                |                                              |                           |           |             |                                     |
|                          |                                             |           |                | PROC. REF: AFMS INSPECTION C9                |                           |           |             | PKG:3,28<br>WO#: N950PC B & C CHECK |
| 270048                   | CHECK LEFT FLAP SCREWJACK/REDUCTION GEARBOX |           |                |                                              |                           |           |             | Service ATA:27                      |
|                          | MOS                                         | 06-May-15 |                |                                              |                           |           |             |                                     |
|                          | HRS                                         | 5125.6    | 1600 (+50/-50) |                                              | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 27.505              | AFL                                         | 2873      |                |                                              |                           |           |             |                                     |
|                          |                                             |           |                | PROC. REF: AFMS INSPECTION C9, AMM 27-50-141 |                           |           |             | PKG:3,28<br>WO#: N950PC B & C CHECK |
| 270049                   | CHECK LEFT FLAP SYNCHRONIZING SYSTEM        |           |                |                                              |                           |           |             | Service ATA:27                      |
|                          | MOS                                         | 06-May-15 |                |                                              |                           |           |             |                                     |
|                          | HRS                                         | 5125.6    | 1600 (+50/-50) |                                              | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 27.530              | AFL                                         | 2873      |                |                                              |                           |           |             |                                     |
|                          |                                             |           |                | PROC. REF: AFMS INSPECTION C9, AMM 27-50-02  |                           |           |             | PKG:3,28<br>WO#: N950PC B & C CHECK |
| 270050                   | CHECK LEFT AIRBRAKE CONTROL CABLES          |           |                |                                              |                           |           |             | Service ATA:27                      |
|                          | MOS                                         | 06-May-15 |                |                                              |                           |           |             |                                     |
|                          | HRS                                         | 5125.6    | 1600 (+50/-50) |                                              | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 27.570              | AFL                                         | 2873      |                |                                              |                           |           |             |                                     |
|                          |                                             |           |                | PROC. REF: AFMS INSPECTION C9, AMM 27-61-02  |                           |           |             | PKG:3,28<br>WO#: N950PC B & C CHECK |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                       | Unit                                                | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition                         |
|-----------------------------------------------|-----------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-------------|-------------------------------------|
| ATA 27 - FLIGHT CONTROLS                      |                                                     |           |                |          |                           |           |             |                                     |
| 270051                                        | CHECK RIGHT AILERON PRIMARY AND TRIM CONTROL CABLES |           |                |          |                           |           |             | Service ATA:27                      |
|                                               | MOS                                                 | 06-May-15 |                |          |                           |           |             |                                     |
|                                               | HRS                                                 | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 27.430                                   | AFL                                                 | 2873      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INSPECTION C10                |                                                     |           |                |          |                           |           |             | PKG:3,29<br>WO#: N950PC B & C CHECK |
| 270052                                        | INSPECT RIGHT FLAP DRIVE SHAFT UNIVERSAL JOINT      |           |                |          |                           |           |             | Service ATA:27                      |
|                                               | MOS                                                 | 06-May-15 |                |          |                           |           |             |                                     |
|                                               | HRS                                                 | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 27.565                                   | AFL                                                 | 2873      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INSPECTION C10                |                                                     |           |                |          |                           |           |             | PKG:3,29<br>WO#: N950PC B & C CHECK |
| 270053                                        | CHECK RIGHT FLAP BEVEL DRIVE ASSEMBLY               |           |                |          |                           |           |             | Service ATA:27                      |
|                                               | MOS                                                 | 06-May-15 |                |          |                           |           |             |                                     |
|                                               | HRS                                                 | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 27.535                                   | AFL                                                 | 2873      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INSPECTION C10                |                                                     |           |                |          |                           |           |             | PKG:3,29<br>WO#: N950PC B & C CHECK |
| 270054                                        | CHECK RIGHT FLAP SCREWJACK/REDUCTION GEARBOX        |           |                |          |                           |           |             | Service ATA:27                      |
|                                               | MOS                                                 | 06-May-15 |                |          |                           |           |             |                                     |
|                                               | HRS                                                 | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 27.505                                   | AFL                                                 | 2873      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INSPECTION C10, AMM 27-50-141 |                                                     |           |                |          |                           |           |             | PKG:3,29<br>WO#: N950PC B & C CHECK |
| 270055                                        | CHECK RIGHT FLAP SYNCHRONIZING SYSTEM               |           |                |          |                           |           |             | Service ATA:27                      |
|                                               | MOS                                                 | 06-May-15 |                |          |                           |           |             |                                     |
|                                               | HRS                                                 | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 27.530                                   | AFL                                                 | 2873      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INSPECTION C10, AMM 27-50-02  |                                                     |           |                |          |                           |           |             | PKG:3,29<br>WO#: N950PC B & C CHECK |
| 270056                                        | CHECK RIGHT AIRBRAKE CONTROL CABLES                 |           |                |          |                           |           |             | Service ATA:27                      |
|                                               | MOS                                                 | 06-May-15 |                |          |                           |           |             |                                     |
|                                               | HRS                                                 | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 27.570                                   | AFL                                                 | 2873      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INSPECTION C10, AMM 27-61-02  |                                                     |           |                |          |                           |           |             | PKG:3,29<br>WO#: N950PC B & C CHECK |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                              | Unit                                                                       | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                             | Disposition    |
|----------------------------------------------------------------------|----------------------------------------------------------------------------|-----------|-----------------|----------|---------------------------|-----------|---------------------------------------|----------------|
| ATA 27 - FLIGHT CONTROLS                                             |                                                                            |           |                 |          |                           |           |                                       |                |
| 270057                                                               | CHECK FLAP CONTROL FORWARD SPRING STRUT                                    |           |                 |          |                           |           |                                       | Service ATA:27 |
|                                                                      | MOS                                                                        | 18-Aug-17 |                 |          |                           |           |                                       |                |
|                                                                      | HRS                                                                        | 5554.6    | 3200 (+150/-50) |          | 8754.6                    | 8904.6    | 2226.3 (+150)                         |                |
| WC#: 27.560                                                          | AFL                                                                        | 3197      |                 |          |                           |           |                                       |                |
| PROC. REF: AFMS INSPECTION D4, AMM 27-50-02                          |                                                                            |           |                 |          |                           |           | PKG:4,35                              |                |
| 270058                                                               | CHECK FLAP CONTROL INPUT-CIRCUIT                                           |           |                 |          |                           |           |                                       | Service ATA:27 |
|                                                                      | MOS                                                                        | 18-Aug-17 |                 |          |                           |           |                                       |                |
|                                                                      | HRS                                                                        | 5554.6    | 3200 (+150/-50) |          | 8754.6                    | 8904.6    | 2226.3 (+150)                         |                |
| WC#: 27.210                                                          | AFL                                                                        | 3197      |                 |          |                           |           |                                       |                |
| PROC. REF: AFMS INSPECTION D4, AMM 27-50-02                          |                                                                            |           |                 |          |                           |           | PKG:4,35                              |                |
| 270059                                                               | INSPECT CONTROL CABLE PRESSURE SEALS AT REAR PRESSURE BULKHEAD             |           |                 |          |                           |           |                                       | Service ATA:27 |
|                                                                      | MOS                                                                        | 11-Oct-22 | 12 (+1m/-1m)    |          | 11-Oct-23                 | 11-Nov-23 | 253 d (+31)                           |                |
|                                                                      | HRS                                                                        | 6446.4    |                 |          |                           |           |                                       |                |
| WC#: 27.545                                                          | AFL                                                                        | 3873      |                 |          |                           |           |                                       |                |
| PROC. REF: AFMS INSPECTION E7                                        |                                                                            |           |                 |          |                           |           | PKG:5,50<br>WO#: N950PC 48 MONTH INSP |                |
| 270060                                                               | REPLACE FLAP AUXILIARY HYDRAULIC SYSTEM SUPPLY TO FLAP CONTROL UNIT FILTER |           |                 |          |                           |           |                                       | Service ATA:27 |
|                                                                      | MOS                                                                        | 18-Aug-17 |                 |          |                           |           |                                       |                |
|                                                                      | HRS                                                                        | 5554.6    | 3200 (+150/-50) |          | 8754.6                    | 8904.6    | 2226.3 (+150)                         |                |
| WC#: 27.215                                                          | AFL                                                                        | 3197      |                 |          |                           |           |                                       |                |
| PROC. REF: AFMS INSPECTION D10, AMM 29-20-00                         |                                                                            |           |                 |          |                           |           | PKG:4,41                              |                |
| 270061                                                               | CHECK FLIGHT CONTROL CABLES TENSION                                        |           |                 |          |                           |           |                                       | Service ATA:27 |
|                                                                      | MOS/MSC                                                                    | 29-May-97 | O/C             |          |                           |           |                                       |                |
|                                                                      | HRS                                                                        | 212       |                 |          |                           |           |                                       |                |
| WC#: 27.010                                                          | AFL                                                                        | 105       |                 |          |                           |           |                                       |                |
| PROC. REF: AFMS OUT OF PHASE INSPECTIONS, AMM 27-10-00, AMM 27-20-00 |                                                                            |           |                 |          |                           |           |                                       |                |
| 270063                                                               | LUBRICATE/CLEAN SERVOMOTOR ASSEMBLY SVO-85B (P/N 622-5027-001)             |           |                 |          |                           |           |                                       | Service ATA:27 |
|                                                                      | MOS/MSC                                                                    | 30-May-96 | N/R             |          |                           |           |                                       |                |
|                                                                      | HRS                                                                        | 0         |                 |          |                           |           |                                       |                |
| WC#: 27.030                                                          | AFL                                                                        | 0         |                 |          |                           |           |                                       |                |
| PROC. REF: AFMS OUT OF PHASE INSPECTIONS                             |                                                                            |           |                 |          |                           |           |                                       |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                        | Unit                                                                    | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition                         |
|--------------------------------|-------------------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-------------|-------------------------------------|
| ATA 27 - FLIGHT CONTROLS       |                                                                         |           |                |          |                           |           |             |                                     |
| 270064                         | INSPECT RIGHT WING FLAP VANE INNER                                      |           |                |          |                           |           |             | Service ATA:27                      |
|                                | MOS                                                                     | 06-May-15 |                |          |                           |           |             |                                     |
|                                | HRS                                                                     | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 27.490                    | AFL                                                                     | 2873      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INSPECTION C10 |                                                                         |           |                |          |                           |           |             | PKG:3,29<br>WO#: N950PC B & C CHECK |
| 270065                         | INSPECT RIGHT WING FLAP SCREWJACKS SCREW THREADS                        |           |                |          |                           |           |             | Service ATA:27                      |
|                                | MOS                                                                     | 15-Oct-19 |                |          |                           |           |             |                                     |
|                                | HRS                                                                     | 5795.3    | 800 (+40/-10)  |          | 6595.3                    | 6635.3    | 67 (+40)    |                                     |
| WC#: 27.495                    | AFL                                                                     | 3397      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INSPECTION B10 |                                                                         |           |                |          |                           |           |             | PKG:2,17<br>WO#: N950PC B & C CHECK |
| 270066                         | INSPECT LEFT AILERON CONTROL CABLE PRESSURE SEALS                       |           |                |          |                           |           |             | Service ATA:27                      |
|                                | MOS                                                                     | 15-Oct-19 |                |          |                           |           |             |                                     |
|                                | HRS                                                                     | 5795.3    | 800 (+40/-10)  |          | 6595.3                    | 6635.3    | 67 (+40)    |                                     |
| WC#: 27.600                    | AFL                                                                     | 3397      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INSPECTION B9  |                                                                         |           |                |          |                           |           |             | PKG:2,16<br>WO#: N950PC B & C CHECK |
| 270067                         | INSPECT RIGHT AILERON CONTROL CABLE PRESSURE SEALS                      |           |                |          |                           |           |             | Service ATA:27                      |
|                                | MOS                                                                     | 15-Oct-19 |                |          |                           |           |             |                                     |
|                                | HRS                                                                     | 5795.3    | 800 (+40/-10)  |          | 6595.3                    | 6635.3    | 67 (+40)    |                                     |
| WC#: 27.605                    | AFL                                                                     | 3397      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INSPECTION B10 |                                                                         |           |                |          |                           |           |             | PKG:2,17<br>WO#: N950PC B & C CHECK |
| 270068                         | LUBRICATE/CLEAN AILERON SERVOMOTOR ASSEMBLY SVO-85B (P/N 622-5027-001)  |           |                |          |                           |           |             | Service ATA:27                      |
|                                | MOS/MSC                                                                 |           | N/R            |          |                           |           |             |                                     |
|                                | HRS                                                                     |           |                |          |                           |           |             |                                     |
| WC#: 27.610                    | AFL                                                                     |           |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INSPECTION G   |                                                                         |           |                |          |                           |           |             |                                     |
| 270069                         | LUBRICATE/CLEAN ELEVATOR SERVOMOTOR ASSEMBLY SVO-85B (P/N 622-5027-001) |           |                |          |                           |           |             | Service ATA:27                      |
|                                | MOS/MSC                                                                 |           | N/R            |          |                           |           |             |                                     |
|                                | HRS                                                                     |           |                |          |                           |           |             |                                     |
| WC#: 27.615                    | AFL                                                                     |           |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INSPECTION G   |                                                                         |           |                |          |                           |           |             |                                     |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                     | Unit                                                                  | C/W       | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition                                 |
|---------------------------------------------|-----------------------------------------------------------------------|-----------|--------------|----------|---------------------------|-----------|-------------|---------------------------------------------|
| ATA 27 - FLIGHT CONTROLS                    |                                                                       |           |              |          |                           |           |             |                                             |
| 270070                                      | LUBRICATE/CLEAN RUDDER SERVOMOTOR ASSEMBLY SVO-85B (P/N 622-5027-001) |           |              |          |                           |           |             | Service ATA:27                              |
|                                             | MOS/MSC                                                               |           | N/R          |          |                           |           |             |                                             |
|                                             | HRS                                                                   |           |              |          |                           |           |             |                                             |
| WC#: 27.620                                 | AFL                                                                   |           |              |          |                           |           |             |                                             |
| PROC. REF: AFMS INSPECTION G                |                                                                       |           |              |          |                           |           |             |                                             |
| 270071                                      | INSPECT RUDDER TRIM JACK                                              |           |              |          |                           |           |             | Service ATA:27                              |
|                                             | MOS                                                                   | 15-Oct-19 | 48 (+2m/-2m) |          | 15-Oct-23                 | 15-Dec-23 | 257 d (+61) |                                             |
|                                             | HRS                                                                   | 5795.3    |              |          |                           |           |             |                                             |
|                                             | AFL                                                                   | 3397      |              |          |                           |           |             |                                             |
| PROC. REF: AFMS INSPECTION G, AMM 27-20-111 |                                                                       |           |              |          |                           |           |             |                                             |
|                                             |                                                                       |           |              |          |                           |           |             | PKG:7<br>WO#: N950PC 48 MONTH INSP          |
| 270072                                      | INSPECT ELEVATOR TRIM JACK                                            |           |              |          |                           |           |             | Service ATA:27                              |
|                                             | MOS                                                                   | 15-Oct-19 | 48 (+2m/-2m) |          | 15-Oct-23                 | 15-Dec-23 | 257 d (+61) |                                             |
|                                             | HRS                                                                   | 5795.3    |              |          |                           |           |             |                                             |
|                                             | AFL                                                                   | 3397      |              |          |                           |           |             |                                             |
| PROC. REF: AFMS INSPECTION G, AMM 27-30-51  |                                                                       |           |              |          |                           |           |             |                                             |
|                                             |                                                                       |           |              |          |                           |           |             | PKG:7<br>WO#: N950PC 48 MONTH INSP          |
| 270100                                      | LEFT CONTROL COLUMN                                                   |           |              |          |                           |           |             | Component ATA:27                            |
| PN:25-8CF53-217                             | MOS/MSC                                                               | 30-May-96 | O/C          |          |                           |           |             |                                             |
| SN:PPLS/DH/1055                             | HRS                                                                   | 0         |              | TSN 0    |                           |           |             |                                             |
| WC#: 27.015                                 | AFL                                                                   | 0         |              |          |                           |           |             |                                             |
| PROC. REF: AMM 27-10-11                     |                                                                       |           |              |          |                           |           |             |                                             |
| 270102                                      | RIGHT CONTROL COLUMN                                                  |           |              |          |                           |           |             | Component ATA:27                            |
| PN:25-8CF55-215                             | MOS/MSC                                                               | 30-May-96 | O/C          |          |                           |           |             |                                             |
| SN:PPLS/DH/1072                             | HRS                                                                   | 0         |              | TSN 0    |                           |           |             |                                             |
| WC#: 27.015                                 | AFL                                                                   | 0         |              |          |                           |           |             |                                             |
| PROC. REF: AMM 27-10-11                     |                                                                       |           |              |          |                           |           |             |                                             |
| 271001                                      | LEFTAILERON                                                           |           |              |          |                           |           |             | Component ATA:27                            |
| PN:25-9WG1-111A                             | MOS/MSC                                                               | 30-May-96 | O/C          |          |                           |           |             |                                             |
| SN:DHB559                                   | HRS                                                                   | 0         |              | TSN 0    |                           |           |             |                                             |
| WC#: 27.020                                 | AFL                                                                   | 0         |              |          |                           |           |             |                                             |
| PROC. REF: AMM 27-10-31                     |                                                                       |           |              |          |                           |           |             |                                             |
|                                             |                                                                       |           |              |          |                           |           |             | WO#: N950PC 48 MONTH INSP,KLM - HANGAR RASH |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                  | Unit                       | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                 | Disposition      |
|--------------------------|----------------------------|-----------|----------|----------|---------------------------|-----------|---------------------------|------------------|
| ATA 27 - FLIGHT CONTROLS |                            |           |          |          |                           |           |                           |                  |
| 271002                   | RIGHT AILERON              |           |          |          |                           |           |                           | Component ATA:27 |
| PN:25-9WG1-112A          | MOS/MSC                    | 30-May-96 | O/C      |          |                           |           |                           |                  |
| SN:DHB564                | HRS                        | 0         |          | TSN 0    |                           |           |                           |                  |
| WC#: 27.020              | AFL                        | 0         |          |          |                           |           |                           |                  |
| PROC. REF: AMM 27-10-31  |                            |           |          |          |                           |           | WO#: N950PC 48 MONTH INSP |                  |
| 271025                   | AILERON TRIM SCREWJACK     |           |          |          |                           |           |                           | Component ATA:27 |
| PN:25.8CW49/39A          | MOS/MSC                    | 30-May-96 | O/C      |          |                           |           |                           |                  |
| SN:CH8G363               | HRS                        | 0         |          | TSN 0    |                           |           |                           |                  |
| WC#: 27.025              | AFL                        | 0         |          |          |                           |           |                           |                  |
| PROC. REF: AMM 27-10-71  |                            |           |          |          |                           |           |                           |                  |
| 272001                   | RUDDER                     |           |          |          |                           |           |                           | Component ATA:27 |
| PN:25.TR235A/L           | MOS/MSC                    | 30-May-96 | O/C      |          |                           |           |                           |                  |
| SN:FL/DHB/8307           | HRS                        | 0         |          | TSN 0    |                           |           |                           |                  |
| WC#: 27.045              | AFL                        | 0         |          |          |                           |           |                           |                  |
| PROC. REF: AMM 27-20-23  |                            |           |          |          |                           |           | WO#: N950PC 48 MONTH INSP |                  |
| 272019                   | RUDDER TRIM JACK           |           |          |          |                           |           |                           | Component ATA:27 |
| PN:25.CW573G             | MOS/MSC                    | 30-May-96 | O/C      |          |                           |           |                           |                  |
| SN:MEC/DHB/2614          | HRS                        | 0         |          | TSN 0    |                           |           |                           |                  |
| WC#: 27.050              | AFL                        | 0         |          |          |                           |           |                           |                  |
| PROC. REF: AMM 27-20-111 |                            |           |          |          |                           |           |                           |                  |
| 272020                   | RUDDER GEARED TAB          |           |          |          |                           |           |                           | Component ATA:27 |
| PN:25TR209A/F            | MOS/MSC                    | 30-May-96 | O/C      |          |                           |           |                           |                  |
| SN:FL/DHB/8310A          | HRS                        | 0         |          | TSN 0    |                           |           |                           |                  |
| WC#: 27.125              | AFL                        | 0         |          |          |                           |           |                           |                  |
| 272021                   | RUDDER TRIM TAB            |           |          |          |                           |           |                           | Component ATA:27 |
| PN:25TR221A/F            | MOS/MSC                    | 30-May-96 | O/C      |          |                           |           |                           |                  |
| SN:FL/DHB/8309A          | HRS                        | 0         |          | TSN 0    |                           |           |                           |                  |
| WC#: 27.285              | AFL                        | 0         |          |          |                           |           |                           |                  |
| 272022                   | LEFT RUDDER PEDAL ASSEMBLY |           |          |          |                           |           |                           | Component ATA:27 |
| PN:25-CF1365A/G          | MOS/MSC                    | 30-May-96 | O/C      |          |                           |           |                           |                  |
| SN:CML/DHB/967           | HRS                        | 0         |          | TSN 0    |                           |           |                           |                  |
| WC#: 27.065              | AFL                        | 0         |          |          |                           |           |                           |                  |
| PROC. REF: AMM 27-20-35  |                            |           |          |          |                           |           |                           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                  | Unit                                | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------|-------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 27 - FLIGHT CONTROLS |                                     |           |          |          |                           |           |           |                  |
| 272023                   | RIGHT RUDDER PEDAL ASSEMBLY         |           |          |          |                           |           |           | Component ATA:27 |
| PN:25-CF1366A/G          | MOS/MSC                             | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:CML/DHB/968           | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 27.065              | AFL                                 | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 27-20-35  |                                     |           |          |          |                           |           |           |                  |
| 272049                   | LEFT RUDDER BIAS STRUT              |           |          |          |                           |           |           | Component ATA:27 |
| PN:ACA1218               | MOS/MSC                             | 30-Nov-98 | O/C      | TSO 0    |                           |           |           |                  |
| SN:E101                  | HRS                                 | 917       |          | TSO 0    |                           |           |           |                  |
| WC#: 27.055              | AFL                                 | 431       |          | TSO 0    |                           |           |           |                  |
| PROC. REF: AMM 27-20-51  |                                     |           |          |          |                           |           |           |                  |
| 272050                   | RIGHT RUDDER BIAS STRUT             |           |          |          |                           |           |           | Component ATA:27 |
| PN:ACA1218               | MOS/MSC                             | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:JP054                 | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 27.055              | AFL                                 | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 27-20-51  |                                     |           |          |          |                           |           |           |                  |
| 272066                   | LEFT RUDDER BIAS STRUT HEATER MUFF  |           |          |          |                           |           |           | Component ATA:27 |
| PN:XC5732                | MOS/MSC                             | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:667                   | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 27.060              | AFL                                 | 0         |          |          |                           |           |           |                  |
| 272067                   | RIGHT RUDDER BIAS STRUT HEATER MUFF |           |          |          |                           |           |           | Component ATA:27 |
| PN:XC5732                | MOS/MSC                             | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:632                   | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 27.061              | AFL                                 | 0         |          |          |                           |           |           |                  |
| 272103                   | LEFT RUDDER BIAS PRESSURE SWITCH    |           |          |          |                           |           |           | Component ATA:27 |
| PN:HTE.690011            | MOS/MSC                             | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:FRTR084               | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 27.290              | AFL                                 | 0         |          |          |                           |           |           |                  |
| 272105                   | RIGHT RUDDER BIAS PRESSURE SWITCH   |           |          |          |                           |           |           | Component ATA:27 |
| PN:HTE.690011            | MOS/MSC                             | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:FRTR077               | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 27.290              | AFL                                 | 0         |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                  | Unit                                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                 | Disposition      |
|--------------------------|-----------------------------------------|-----------|----------|----------|---------------------------|-----------|---------------------------|------------------|
| ATA 27 - FLIGHT CONTROLS |                                         |           |          |          |                           |           |                           |                  |
| 273001                   | LEFT ELEVATOR                           |           |          |          |                           |           |                           | Component ATA:27 |
| PN:258TE1-1A             | MOS/MSC                                 | 30-May-96 | O/C      |          |                           |           |                           |                  |
| SN:SD/DH/353             | HRS                                     | 0         |          | TSN 0    |                           |           |                           |                  |
| WC#: 27.070              | AFL                                     | 0         |          |          |                           |           |                           |                  |
| PROC. REF: AMM 27-30-22  |                                         |           |          |          |                           |           | WO#: N950PC 48 MONTH INSP |                  |
| 273002                   | RIGHT ELEVATOR                          |           |          |          |                           |           |                           | Component ATA:27 |
| PN:258TE1-2A             | MOS/MSC                                 | 30-May-96 | O/C      |          |                           |           |                           |                  |
| SN:SD/DH/358             | HRS                                     | 0         |          | TSN 0    |                           |           |                           |                  |
| WC#: 27.070              | AFL                                     | 0         |          |          |                           |           |                           |                  |
| PROC. REF: AMM 27-30-22  |                                         |           |          |          |                           |           | WO#: N950PC 48 MONTH INSP |                  |
| 273021                   | ELEVATOR TRIM SERVOMOTOR                |           |          |          |                           |           |                           | Component ATA:27 |
| PN:622-3260-001          | MOS                                     | 14-Dec-07 |          | TSO 0    |                           |           |                           | OVERHAUL         |
| SN:429                   | HRS                                     | 3601.5    | 3500     | TSO 0    | 7101.5                    |           | 573.2                     |                  |
| WC#: 27.085              | AFL                                     | 2018      |          | TSO 0    |                           |           |                           |                  |
| PROC. REF: AMM 27-30-61  |                                         |           |          |          |                           |           |                           |                  |
| 273022                   | ELEVATOR TRIM SERVOMOTOR MOUNT ASSEMBLY |           |          |          |                           |           |                           | Component ATA:27 |
| PN:PN                    | MOS/MSC                                 | 30-May-96 | O/C      | TSN 0    |                           |           |                           |                  |
| SN:UNKNOWN               | HRS                                     | 0         |          | TSN 0    |                           |           |                           |                  |
| WC#: 27.701              | AFL                                     | 0         |          | TSN 0    |                           |           |                           |                  |
| 273025                   | LEFT ELEVATOR TRIM JACK                 |           |          |          |                           |           |                           | Component ATA:27 |
| PN:25.8CT29-115A         | MOS/MSC                                 | 30-May-96 | O/C      |          |                           |           |                           |                  |
| SN:MEC/DHB/434           | HRS                                     | 0         |          | TSN 0    |                           |           |                           |                  |
| WC#: 27.080              | AFL                                     | 0         |          |          |                           |           |                           |                  |
| PROC. REF: AMM 27-30-51  |                                         |           |          |          |                           |           |                           |                  |
| 273026                   | RIGHT ELEVATOR TRIM JACK                |           |          |          |                           |           |                           | Component ATA:27 |
| PN:25.8CT29-116A         | MOS/MSC                                 | 30-May-96 | O/C      |          |                           |           |                           |                  |
| SN:MEC/DHB/425           | HRS                                     | 0         |          | TSN 0    |                           |           |                           |                  |
| WC#: 27.080              | AFL                                     | 0         |          |          |                           |           |                           |                  |
| PROC. REF: AMM 27-30-51  |                                         |           |          |          |                           |           |                           |                  |
| 273040                   | LEFT ELEVATOR TRIM TAB                  |           |          |          |                           |           |                           | Component ATA:27 |
| PN:258TE3-1A             | MOS/MSC                                 | 30-May-96 | O/C      |          |                           |           |                           |                  |
| SN:SD/DH/361             | HRS                                     | 0         |          | TSN 0    |                           |           |                           |                  |
| WC#: 27.090              | AFL                                     | 0         |          |          |                           |           |                           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                  | Unit                           | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------|--------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 27 - FLIGHT CONTROLS |                                |           |          |          |                           |           |           |                  |
| 273041                   | RIGHT ELEVATOR TRIM TAB        |           |          |          |                           |           |           | Component ATA:27 |
| PN:25.8TE3-2A            | MOS/MSC                        | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:SD/DH/372             | HRS                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 27.090              | AFL                            | 0         |          |          |                           |           |           |                  |
| 273104                   | LEFT STICK SHAKER              |           |          |          |                           |           |           | Component ATA:27 |
| PN:B1443/2               | MOS/MSC                        | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:8097                  | HRS                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 27.140              | AFL                            | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 27-33-20  |                                |           |          |          |                           |           |           |                  |
| 273105                   | RIGHT STICK SHAKER             |           |          |          |                           |           |           | Component ATA:27 |
| PN:B1443/2               | MOS/MSC                        | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:8089                  | HRS                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 27.140              | AFL                            | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 27-33-20  |                                |           |          |          |                           |           |           |                  |
| 273110                   | FORWARD STALL WARNING DETECTOR |           |          |          |                           |           |           | Component ATA:27 |
| PN:10201-1               | MOS/MSC                        | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:F102                  | HRS                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 27.145              | AFL                            | 0         |          |          |                           |           |           |                  |
| 273111                   | AFT STALL WARNING DETECTOR     |           |          |          |                           |           |           | Component ATA:27 |
| PN:C87706-1              | MOS/MSC                        | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:158                   | HRS                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 27.145              | AFL                            | 0         |          |          |                           |           |           |                  |
| 273115                   | NO. 1 STALL WARNING VANE       |           |          |          |                           |           |           | Component ATA:27 |
| PN:1703-12MODA           | MOS/MSC                        | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:1580                  | HRS                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 27.150              | AFL                            | 0         |          |          |                           |           |           |                  |
| 273116                   | NO. 2 STALL WARNING VANE       |           |          |          |                           |           |           | Component ATA:27 |
| PN:1703-12MODA           | MOS/MSC                        | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:1581                  | HRS                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 27.150              | AFL                            | 0         |          |          |                           |           |           |                  |
| 273121                   | THIRD CHANNEL STALL DETECTOR   |           |          |          |                           |           |           | Component ATA:27 |
| PN:10201-1               | MOS/MSC                        | 12-Nov-96 | O/C      |          |                           |           |           |                  |
| SN:F135                  | HRS                            | 20        |          |          |                           |           |           |                  |
| WC#: 27.305              | AFL                            | 11        |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                  | Unit                                       | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                 | Disposition      |
|--------------------------|--------------------------------------------|-----------|----------|----------|---------------------------|-----------|---------------------------|------------------|
| ATA 27 - FLIGHT CONTROLS |                                            |           |          |          |                           |           |                           |                  |
| 275001                   | LEFT FLAP                                  |           |          |          |                           |           |                           | Component ATA:27 |
| PN:25.8WF251-1A          | MOS/MSC                                    | 30-May-96 | O/C      |          |                           |           |                           |                  |
| SN:SD/DH/359             | HRS                                        | 0         |          | TSN 0    |                           |           |                           |                  |
| WC#: 27.155              | AFL                                        | 0         |          |          |                           |           |                           |                  |
| PROC. REF: AMM 27-50-151 |                                            |           |          |          |                           |           | WO#: N950PC 48 MONTH INSP |                  |
| 275002                   | RIGHT FLAP                                 |           |          |          |                           |           |                           | Component ATA:27 |
| PN:25.8WF251-2A          | MOS/MSC                                    | 30-May-96 | O/C      |          |                           |           |                           |                  |
| SN:SD/DH/364             | HRS                                        | 0         |          | TSN 0    |                           |           |                           |                  |
| WC#: 27.155              | AFL                                        | 0         |          |          |                           |           |                           |                  |
| PROC. REF: AMM 27-50-151 |                                            |           |          |          |                           |           | WO#: N950PC 48 MONTH INSP |                  |
| 275025                   | LEFT FLAP SCREWJACK AND REDUCTION GEARBOX  |           |          |          |                           |           |                           | Component ATA:27 |
| PN:25-CW159C             | MOS                                        | 14-Nov-96 |          |          |                           |           |                           | OVERHAUL         |
| SN:MEC/DHB/437           | HRS                                        | 24        |          | TSN 1    |                           |           |                           |                  |
| WC#: 27.160              | AFL                                        | 12        | 4000     | TSN 1    | 4011                      |           | 82                        |                  |
| PROC. REF: AMM 27-50-141 |                                            |           |          |          |                           |           | WO#: N950PC B & C CHECK   |                  |
| 275026                   | RIGHT FLAP SCREWJACK AND REDUCTION GEARBOX |           |          |          |                           |           |                           | Component ATA:27 |
| PN:25-CW161C             | MOS                                        | 14-Nov-96 |          |          |                           |           |                           | OVERHAUL         |
| SN:MEC/DHB/437           | HRS                                        | 24        |          | TSN 1    |                           |           |                           |                  |
| WC#: 27.160              | AFL                                        | 12        | 4000     | TSN 1    | 4011                      |           | 82                        |                  |
| PROC. REF: AMM 27-50-141 |                                            |           |          |          |                           |           | WO#: N950PC B & C CHECK   |                  |
| 275049                   | LEFT OUTBOARD FLAP VANE                    |           |          |          |                           |           |                           | Component ATA:27 |
| PN:25.8WF13-65A          | MOS/MSC                                    | 30-May-96 | O/C      |          |                           |           |                           |                  |
| SN:SD/DH/421             | HRS                                        | 0         |          | TSN 0    |                           |           |                           |                  |
| WC#: 27.165              | AFL                                        | 0         |          |          |                           |           |                           |                  |
| 275050                   | RIGHT OUTBOARD FLAP VANE                   |           |          |          |                           |           |                           | Component ATA:27 |
| PN:25.8WF13-66A          | MOS/MSC                                    | 30-May-96 | O/C      |          |                           |           |                           |                  |
| SN:SD/DH/382             | HRS                                        | 0         |          | TSN 0    |                           |           |                           |                  |
| WC#: 27.170              | AFL                                        | 0         |          |          |                           |           |                           |                  |
| 275051                   | LEFT INBOARD FLAP VANE                     |           |          |          |                           |           |                           | Component ATA:27 |
| PN:25-7WF101A            | MOS/MSC                                    | 30-May-96 | O/C      |          |                           |           |                           |                  |
| SN:SD/DH/389             | HRS                                        | 0         |          | TSN 0    |                           |           |                           |                  |
| WC#: 27.165              | AFL                                        | 0         |          |          |                           |           |                           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                  | Unit                               | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition             |
|--------------------------|------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|-------------------------|
| ATA 27 - FLIGHT CONTROLS |                                    |           |          |          |                           |           |           |                         |
| 275052                   | RIGHT INBOARD FLAP VANE            |           |          |          |                           |           |           | Component ATA:27        |
| PN:25-7WF102A            | MOS/MSC                            | 30-May-96 | O/C      |          |                           |           |           |                         |
| SN:SD/DH/388             | HRS                                | 0         |          | TSN 0    |                           |           |           |                         |
| WC#: 27.170              | AFL                                | 0         |          |          |                           |           |           |                         |
| 275057                   | LEFT FLAP BEVEL SHAFT ASSEMBLY     |           |          |          |                           |           |           | Component ATA:27        |
| PN:25.CF2667A/D          | MOS/MSC                            | 30-May-96 | O/C      |          |                           |           |           |                         |
| SN:829                   | HRS                                | 0         |          | TSN 0    |                           |           |           |                         |
| WC#: 27.175              | AFL                                | 0         |          |          |                           |           |           |                         |
| 275058                   | RIGHT FLAP BEVEL SHAFT ASSEMBLY    |           |          |          |                           |           |           | Component ATA:27        |
| PN:25.CF2668A/D          | MOS/MSC                            | 30-May-96 | O/C      |          |                           |           |           |                         |
| SN:826                   | HRS                                | 0         |          | TSN 0    |                           |           |           |                         |
| WC#: 27.175              | AFL                                | 0         |          |          |                           |           |           |                         |
| 275073                   | FLAP CONTROL UNIT                  |           |          |          |                           |           |           | Component ATA:27        |
| PN:614MK2                | MOS                                | 30-May-96 |          |          |                           |           |           | OVERHAUL                |
| SN:S791                  | HRS                                | 0         |          |          |                           |           |           |                         |
| WC#: 27.180              | AFL                                | 0         | 6000     | TSN 0    | 6000                      |           | 2071      |                         |
| PROC. REF: AMM 27-50-121 |                                    |           |          |          |                           |           |           |                         |
| 275074                   | FLAP DESIGN UNIT                   |           |          |          |                           |           |           | Component ATA:27        |
| PN:25-8NW111-1A          | MOS/MSC                            | 30-May-96 | O/C      |          |                           |           |           |                         |
| SN:BY6228                | HRS                                | 0         |          | TSN 0    |                           |           |           |                         |
| WC#: 27.590              | AFL                                | 0         |          |          |                           |           |           |                         |
| 275085                   | FLAP SYNCHRONIZING SYSTEM RECEIVER |           |          |          |                           |           |           | Component ATA:27        |
| PN:617MK4                | MOS                                | 30-May-96 |          |          |                           |           |           | OVERHAUL                |
| SN:S843                  | HRS                                | 0         |          |          |                           |           |           |                         |
| WC#: 27.185              | AFL                                | 0         | 4500     | TSN 0    | 4500                      |           | 571       |                         |
| PROC. REF: AMM 27-50-162 |                                    |           |          |          |                           |           |           | WO#: N950PC B & C CHECK |
| 275091                   | FLAP POSITION INDICATOR            |           |          |          |                           |           |           | Component ATA:27        |
| PN:2132-01-0011          | MOS/MSC                            | 30-May-96 | O/C      |          |                           |           |           |                         |
| SN:BG75668               | HRS                                | 0         |          | TSN 0    |                           |           |           |                         |
| WC#: 27.190              | AFL                                | 0         |          |          |                           |           |           |                         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                  | Unit                                      | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------|-------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 27 - FLIGHT CONTROLS |                                           |           |          |          |                           |           |           |                  |
| 275097                   | FLAP POSITION TRANSMITTER                 |           |          |          |                           |           |           | Component ATA:27 |
| PN:S132-3-22             | MOS/MSC                                   | 14-Nov-96 | O/C      |          |                           |           |           |                  |
| SN:BY005257              | HRS                                       | 24        |          | TSN 0    |                           |           |           |                  |
| WC#: 27.195              | AFL                                       | 12        |          |          |                           |           |           |                  |
| PROC. REF: AMM 27-50-181 |                                           |           |          |          |                           |           |           |                  |
| 275145                   | LEFT FLAP INBOARD FORWARD SYNCHRO CABLE   |           |          |          |                           |           |           | Component ATA:27 |
| PN:25CF3225-17           | MOS                                       | 30-May-96 |          |          |                           |           |           | LIFE LIMIT       |
| SN:UNKNOWN               | HRS                                       | 0         |          |          |                           |           |           |                  |
| WC#: 27.220              | AFL                                       | 0         | 5000     | TSN 0    | 5000                      |           | 1071      |                  |
| 275146                   | RIGHT FLAP INBOARD FORWARD SYNCHRO CABLE  |           |          |          |                           |           |           | Component ATA:27 |
| PN:25CF3225-9            | MOS                                       | 30-May-96 |          |          |                           |           |           | LIFE LIMIT       |
| SN:UNKNOWN               | HRS                                       | 0         |          |          |                           |           |           |                  |
| WC#: 27.225              | AFL                                       | 0         | 5000     | TSN 0    | 5000                      |           | 1071      |                  |
| 275147                   | LEFT FLAP INBOARD AFT SYNCHRO CABLE       |           |          |          |                           |           |           | Component ATA:27 |
| PN:25CF3225-19           | MOS                                       | 30-May-96 |          |          |                           |           |           | LIFE LIMIT       |
| SN:UNKNOWN               | HRS                                       | 0         |          |          |                           |           |           |                  |
| WC#: 27.220              | AFL                                       | 0         | 5000     | TSN 0    | 5000                      |           | 1071      |                  |
| 275148                   | RIGHT FLAP INBOARD AFT SYNCHRO CABLE      |           |          |          |                           |           |           | Component ATA:27 |
| PN:25CF3225-11           | MOS                                       | 30-May-96 |          |          |                           |           |           | LIFE LIMIT       |
| SN:UNKNOWN               | HRS                                       | 0         |          |          |                           |           |           |                  |
| WC#: 27.225              | AFL                                       | 0         | 5000     | TSN 0    | 5000                      |           | 1071      |                  |
| 275149                   | LEFT FLAP OUTBOARD FORWARD SYNCHRO CABLE  |           |          |          |                           |           |           | Component ATA:27 |
| PN:25CF3225-3            | MOS                                       | 30-May-96 |          |          |                           |           |           | LIFE LIMIT       |
| SN:UNKNOWN               | HRS                                       | 0         |          |          |                           |           |           |                  |
| WC#: 27.230              | AFL                                       | 0         | 5000     | TSN 0    | 5000                      |           | 1071      |                  |
| 275150                   | RIGHT FLAP OUTBOARD FORWARD SYNCHRO CABLE |           |          |          |                           |           |           | Component ATA:27 |
| PN:25CF3225-13           | MOS                                       | 30-May-96 |          |          |                           |           |           | LIFE LIMIT       |
| SN:UNKNOWN               | HRS                                       | 0         |          |          |                           |           |           |                  |
| WC#: 27.235              | AFL                                       | 0         | 5000     | TSN 0    | 5000                      |           | 1071      |                  |
| 275151                   | LEFT FLAP OUTBOARD AFT SYNCHRO CABLE      |           |          |          |                           |           |           | Component ATA:27 |
| PN:25CF3225-7            | MOS                                       | 30-May-96 |          |          |                           |           |           | LIFE LIMIT       |
| SN:UNKNOWN               | HRS                                       | 0         |          |          |                           |           |           |                  |
| WC#: 27.230              | AFL                                       | 0         | 5000     | TSN 0    | 5000                      |           | 1071      |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                  | Unit                                  | C/W       | Interval | TSX/Adj.   | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------|---------------------------------------|-----------|----------|------------|---------------------------|-----------|-----------|------------------|
| ATA 27 - FLIGHT CONTROLS |                                       |           |          |            |                           |           |           |                  |
| 275152                   | RIGHT FLAP OUTBOARD AFT SYNCHRO CABLE |           |          |            |                           |           |           | Component ATA:27 |
| PN:25CF3225-15           | MOS                                   | 30-May-96 |          | TSN 0      |                           |           |           | LIFE LIMIT       |
| SN:UNKNOWN               | HRS                                   | 0         |          | TSN 0      |                           |           |           |                  |
| WC#: 27.235              | AFL                                   | 0         | 5000     | TSN 0      | 5000                      |           | 1071      |                  |
| 276001                   | LEFT UPPER AIRBRAKE                   |           |          |            |                           |           |           | Component ATA:27 |
| PN:25.8WB9-1A            | MOS/MSC                               | 30-May-96 | O/C      |            |                           |           |           |                  |
| SN:DHB-W-59              | HRS                                   | 0         |          | TSN 0      |                           |           |           |                  |
| WC#: 27.240              | AFL                                   | 0         |          |            |                           |           |           |                  |
| PROC. REF: AMM 27-61-21  |                                       |           |          |            |                           |           |           |                  |
| 276002                   | RIGHT UPPER AIRBRAKE                  |           |          |            |                           |           |           | Component ATA:27 |
| PN:25.8WB9-2A            | MOS/MSC                               | 30-May-96 | O/C      |            |                           |           |           |                  |
| SN:DHB-W-60              | HRS                                   | 0         |          | TSN 0      |                           |           |           |                  |
| WC#: 27.245              | AFL                                   | 0         |          |            |                           |           |           |                  |
| PROC. REF: AMM 27-61-21  |                                       |           |          |            |                           |           |           |                  |
| 276003                   | LEFT LOWER AIRBRAKE                   |           |          |            |                           |           |           | Component ATA:27 |
| PN:25.7WB1A/B            | MOS/MSC                               | 30-May-96 | O/C      |            |                           |           |           |                  |
| SN:SAM39300-000          | HRS                                   | 0         |          | TSN 0      |                           |           |           |                  |
| WC#: 27.240              | AFL                                   | 0         |          |            |                           |           |           |                  |
| PROC. REF: AMM 27-61-21  |                                       |           |          |            |                           |           |           |                  |
| 276004                   | RIGHT LOWER AIRBRAKE                  |           |          |            |                           |           |           | Component ATA:27 |
| PN:25.7WB2A/B            | MOS/MSC                               | 30-May-96 | O/C      |            |                           |           |           |                  |
| SN:SAM40924-000          | HRS                                   | 0         |          | TSN 0      |                           |           |           |                  |
| WC#: 27.245              | AFL                                   | 0         |          |            |                           |           |           |                  |
| PROC. REF: AMM 27-61-21  |                                       |           |          |            |                           |           |           |                  |
| 276039                   | LEFT AIRBRAKE JACK ASSEMBLY           |           |          |            |                           |           |           | Component ATA:27 |
| PN:AIR46520-1            | MOS                                   | 11-Dec-18 |          |            |                           |           |           | OVERHAUL         |
| SN:APB960375             | HRS                                   | 5678.7    | 3000     | TSO 1260.1 | 7418.6                    |           | 890.3     |                  |
| WC#: 27.250              | AFL                                   | 3323      |          | TSO 761    |                           |           |           |                  |
| PROC. REF: AMM 27-61-31  |                                       |           |          |            |                           |           |           |                  |
| 276040                   | RIGHT AIRBRAKE JACK ASSEMBLY          |           |          |            |                           |           |           | Component ATA:27 |
| PN:46521-2               | MOS                                   | 23-Apr-12 |          | TSO 0      |                           |           |           | OVERHAUL         |
| SN:APB981538             | HRS                                   | 4659.4    | 3000     | TSO 0      | 7659.4                    |           | 1131.1    |                  |
| WC#: 27.255              | AFL                                   |           |          | TSO 0      |                           |           |           |                  |
| PROC. REF: AMM 27-61-31  |                                       |           |          |            |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                            | Unit                                        | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|------------------------------------|---------------------------------------------|-----------|---------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 27 - FLIGHT CONTROLS           |                                             |           |               |          |                           |           |           |                  |
| 276051                             | LEFT AIRBRAKE JACK BODY                     |           |               |          |                           |           |           | Component ATA:27 |
| PN: AIR111462                      | MOS                                         | 30-May-96 |               |          |                           |           |           | LIFE LIMIT       |
| SN: UNKNOWN                        | HRS                                         | 0         |               |          |                           |           |           |                  |
| WC#: 27.250                        | AFL                                         | 0         | 25000         | TSN 0    | 25000                     |           | 21071     |                  |
| PROC. REF: AMM 27-61-31            |                                             |           |               |          |                           |           |           |                  |
| 276052                             | RIGHT AIRBRAKE JACK BODY                    |           |               |          |                           |           |           | Component ATA:27 |
| PN: AIR111463                      | MOS                                         | 30-May-96 |               |          |                           |           |           | LIFE LIMIT       |
| SN: UNKNOWN                        | HRS                                         | 0         |               |          |                           |           |           |                  |
| WC#: 27.255                        | AFL                                         | 0         | 25000         | TSN 0    | 25000                     |           | 21071     |                  |
| PROC. REF: AMM 27-61-31            |                                             |           |               |          |                           |           |           |                  |
| 276063                             | LEFT AIRBRAKE JACK EYE END                  |           |               |          |                           |           |           | Component ATA:27 |
| PN: AIR150338                      | MOS/MSC                                     | 30-May-96 | O/C           |          |                           |           |           |                  |
| SN: UNKNOWN                        | HRS                                         | 0         |               | TSN 0    |                           |           |           |                  |
| WC#: 27.250                        | AFL                                         | 0         |               |          |                           |           |           |                  |
| PROC. REF: AMM 27-61-31            |                                             |           |               |          |                           |           |           |                  |
| 276064                             | RIGHT AIRBRAKE JACK EYE END                 |           |               |          |                           |           |           | Component ATA:27 |
| PN: AIR150339                      | MOS/MSC                                     | 30-May-96 | O/C           |          |                           |           |           |                  |
| SN: UNKNOWN                        | HRS                                         | 0         |               | TSN 0    |                           |           |           |                  |
| WC#: 27.255                        | AFL                                         | 0         |               |          |                           |           |           |                  |
| PROC. REF: AMM 27-61-31            |                                             |           |               |          |                           |           |           |                  |
| 276110                             | STICK PUSHER                                |           |               |          |                           |           |           | Component ATA:27 |
| PN: PN                             | MOS/MSC                                     | 30-May-96 | O/C           | TSN 0    |                           |           |           |                  |
| SN: UNKNOWN                        | HRS                                         | 0         |               | TSN 0    |                           |           |           |                  |
| WC#: 27.585                        | AFL                                         | 0         |               | TSN 0    |                           |           |           |                  |
| ATA 28 - FUEL                      |                                             |           |               |          |                           |           |           |                  |
| 280001                             | FLOW CHECK FUEL TRANSFER SYSTEM, WING TANKS |           |               |          |                           |           |           | Service ATA:28   |
|                                    | MOS                                         | 15-Oct-19 |               |          |                           |           |           |                  |
|                                    | HRS                                         | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)  |                  |
| WC#: 28.075                        | AFL                                         | 3397      |               |          |                           |           |           |                  |
| PROC. REF: AFMS INSPECTION B1      |                                             |           |               |          |                           |           |           |                  |
| PKG:2,8<br>WO#: N950PC B & C CHECK |                                             |           |               |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                   | Unit                                                                 | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition                         |
|-----------------------------------------------------------|----------------------------------------------------------------------|-----------|-----------------|----------|---------------------------|-----------|---------------|-------------------------------------|
| ATA 28 - FUEL                                             |                                                                      |           |                 |          |                           |           |               |                                     |
| 280002                                                    | CHECK FUEL VALVE CONTROL CABLES                                      |           |                 |          |                           |           |               | Service ATA:28                      |
|                                                           | MOS                                                                  | 06-May-15 |                 |          |                           |           |               |                                     |
|                                                           | HRS                                                                  | 5125.6    | 1600 (+50/-50)  |          | 6725.6                    | 6775.6    | 197.3 (+50)   |                                     |
| WC#: 28.010                                               | AFL                                                                  | 2873      |                 |          |                           |           |               |                                     |
| PROC. REF: AFMS INSPECTION C5                             |                                                                      |           |                 |          |                           |           |               | PKG:3,24<br>WO#: N950PC B & C CHECK |
| 280003                                                    | FUNCTIONAL TEST LP VALVES                                            |           |                 |          |                           |           |               | Service ATA:28                      |
|                                                           | MOS                                                                  | 18-Aug-17 |                 |          |                           |           |               |                                     |
|                                                           | HRS                                                                  | 5554.6    | 3200 (+150/-50) |          | 8754.6                    | 8904.6    | 2226.3 (+150) |                                     |
| WC#: 28.050                                               | AFL                                                                  | 3197      |                 |          |                           |           |               |                                     |
| PROC. REF: AFMS INSPECTION D1, AMM 28-20-00               |                                                                      |           |                 |          |                           |           |               | PKG:4,32                            |
| 280004                                                    | INSPECT/CLEAN OR REPLACE APU FUEL INLET FILTER ELEMENT (IF FITTED)   |           |                 |          |                           |           |               | Service ATA:28                      |
|                                                           | MOS                                                                  | 18-Aug-17 |                 |          |                           |           |               |                                     |
|                                                           | HRS                                                                  | 5554.6    | 3200 (+150/-50) |          | 8754.6                    | 8904.6    | 2226.3 (+150) |                                     |
| WC#: 28.085                                               | AFL                                                                  | 3197      |                 |          |                           |           |               |                                     |
| PROC. REF: AFMS INSPECTION D7, AMM 28-10-00, AMM 28-20-09 |                                                                      |           |                 |          |                           |           |               | PKG:4,38                            |
| 280005                                                    | VISUALLY INSPECT LEFT WING SUCTION PIPE STRAINERS                    |           |                 |          |                           |           |               | Service ATA:28                      |
|                                                           | MOS                                                                  | 06-May-15 |                 |          |                           |           |               |                                     |
|                                                           | HRS                                                                  | 5125.6    | 1600 (+50/-50)  |          | 6725.6                    | 6775.6    | 197.3 (+50)   |                                     |
| WC#: 28.165                                               | AFL                                                                  | 2873      |                 |          |                           |           |               |                                     |
| PROC. REF: AFMS INSPECTION C9                             |                                                                      |           |                 |          |                           |           |               | PKG:3,28<br>WO#: N950PC B & C CHECK |
| 280006                                                    | VISUALLY INSPECT LEFT WING WATER TRANSFER SYSTEM PIPE SUCTION BLOCKS |           |                 |          |                           |           |               | Service ATA:28                      |
|                                                           | MOS                                                                  | 06-May-15 |                 |          |                           |           |               |                                     |
|                                                           | HRS                                                                  | 5125.6    | 1600 (+50/-50)  |          | 6725.6                    | 6775.6    | 197.3 (+50)   |                                     |
| WC#: 28.170                                               | AFL                                                                  | 2873      |                 |          |                           |           |               |                                     |
| PROC. REF: AFMS INSPECTION C9                             |                                                                      |           |                 |          |                           |           |               | PKG:3,28<br>WO#: N950PC B & C CHECK |
| 280007                                                    | VISUALLY INSPECT RIGHT WING SUCTION PIPE STRAINERS                   |           |                 |          |                           |           |               | Service ATA:28                      |
|                                                           | MOS                                                                  | 06-May-15 |                 |          |                           |           |               |                                     |
|                                                           | HRS                                                                  | 5125.6    | 1600 (+50/-50)  |          | 6725.6                    | 6775.6    | 197.3 (+50)   |                                     |
| WC#: 28.165                                               | AFL                                                                  | 2873      |                 |          |                           |           |               |                                     |
| PROC. REF: AFMS INSPECTION C10                            |                                                                      |           |                 |          |                           |           |               | PKG:3,29<br>WO#: N950PC B & C CHECK |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                | Unit                                                                                                                | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition                         |
|--------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-------------|-------------------------------------|
| ATA 28 - FUEL                                          |                                                                                                                     |           |                |          |                           |           |             |                                     |
| 280008                                                 | VISUALLY INSPECT RIGHT WING WATER TRANSFER SYSTEM PIPE SUCTION BLOCKS                                               |           |                |          |                           |           |             | Service ATA:28                      |
|                                                        | MOS                                                                                                                 | 06-May-15 |                |          |                           |           |             |                                     |
|                                                        | HRS                                                                                                                 | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 28.170                                            | AFL                                                                                                                 | 2873      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INSPECTION C10                         |                                                                                                                     |           |                |          |                           |           |             | PKG:3,29<br>WO#: N950PC B & C CHECK |
| 280010                                                 | CHECK CABLE TENSION OF FUEL CONTROL VALVES                                                                          |           |                |          |                           |           |             | Service ATA:28                      |
|                                                        | MOS/MSC                                                                                                             | 30-May-96 | O/C            |          |                           |           |             |                                     |
|                                                        | HRS                                                                                                                 | 0         |                |          |                           |           |             |                                     |
| WC#: 28.020                                            | AFL                                                                                                                 | 0         |                |          |                           |           |             |                                     |
| PROC. REF: AFMS OUT OF PHASE INSPECTIONS, AMM 28-20-83 |                                                                                                                     |           |                |          |                           |           |             |                                     |
| 280014                                                 | CHECK LEFT BOOST PUMP BRUSH LENGTH                                                                                  |           |                |          |                           |           |             | Service ATA:28                      |
| PN:2C40-2                                              | MOS/MSC                                                                                                             | 30-May-96 | N/R            |          |                           |           |             |                                     |
| SN:6AL62                                               | HRS                                                                                                                 | 0         |                |          |                           |           |             |                                     |
| WC#: 28.080                                            | AFL                                                                                                                 | 0         |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INSPECTION C9                          |                                                                                                                     |           |                |          |                           |           |             | PKG:28                              |
| 280015                                                 | CHECK RIGHT BOOST PUMP BRUSH LENGTH                                                                                 |           |                |          |                           |           |             | Service ATA:28                      |
| PN:2C40-2                                              | MOS/MSC                                                                                                             | 30-May-96 | N/R            |          |                           |           |             |                                     |
| SN:8AL101                                              | HRS                                                                                                                 | 0         |                |          |                           |           |             |                                     |
| WC#: 28.080                                            | AFL                                                                                                                 | 0         |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INSPECTION C10                         |                                                                                                                     |           |                |          |                           |           |             | PKG:29                              |
| 280016                                                 | VISUAL INSPECTION LOW PRESSURE FUEL VALVE SUPPORT STRUT. PART NO. 25 PF361, 25 PF361-5A (MOD. 25G310A) AND 25 PF363 |           |                |          |                           |           |             | Service ATA:28                      |
|                                                        | MOS                                                                                                                 | 15-Oct-19 | 48 (+2m/-2m)   |          | 15-Oct-23                 | 15-Dec-23 | 257 d (+61) |                                     |
|                                                        | HRS                                                                                                                 | 5795.3    |                |          |                           |           |             |                                     |
| WC#: 28.195                                            | AFL                                                                                                                 | 3397      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INSPECTION G                           |                                                                                                                     |           |                |          |                           |           |             | PKG:7<br>WO#: N950PC 48 MONTH INSP  |
| 281004 <sup>U</sup>                                    | AIRCRAFT DEFUEL                                                                                                     |           |                |          |                           |           |             | Service ATA:28                      |
|                                                        | MOS/MSC                                                                                                             |           | A/R            |          |                           |           |             |                                     |
|                                                        | HRS                                                                                                                 |           |                |          |                           |           |             |                                     |
|                                                        | AFL                                                                                                                 |           |                |          |                           |           |             |                                     |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                               | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 28 - FUEL             |                                    |           |          |          |                           |           |           |                  |
| 281067                    | VENTRAL FUEL TANK                  |           |          |          |                           |           |           | Component ATA:28 |
| PN:25-8PT463.1A           | MOS/MSC                            | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:SD/DH/110              | HRS                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.015               | AFL                                | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-10-15   |                                    |           |          |          |                           |           |           |                  |
| 282001                    | LEFT WING HIGH LEVEL FLOAT SWITCH  |           |          |          |                           |           |           | Component ATA:28 |
| PN:3515000/107            | MOS/MSC                            | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:FRTR481AS              | HRS                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.025               | AFL                                | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-22-143  |                                    |           |          |          |                           |           |           |                  |
| 282002                    | RIGHT WING HIGH LEVEL FLOAT SWITCH |           |          |          |                           |           |           | Component ATA:28 |
| PN:3515000/107            | MOS/MSC                            | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:FRTR484AS              | HRS                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.025               | AFL                                | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-22-143  |                                    |           |          |          |                           |           |           |                  |
| 282004                    | LOW PRESSURE FUEL COCK VALVE       |           |          |          |                           |           |           | Component ATA:28 |
| PN:PN                     | MOS/MSC                            | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.191               | AFL                                | 0         |          | TSN 0    |                           |           |           |                  |
| 282005                    | LEFT FUEL COCK                     |           |          |          |                           |           |           | Component ATA:28 |
| PN:PN                     | MOS/MSC                            | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.180               | AFL                                | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                    |           |          |          |                           |           |           |                  |
| 282006                    | RIGHT FUEL COCK                    |           |          |          |                           |           |           | Component ATA:28 |
| PN:PN                     | MOS/MSC                            | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.180               | AFL                                | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                    |           |          |          |                           |           |           |                  |
| 282007                    | LEFT FUEL ACTUATOR                 |           |          |          |                           |           |           | Component ATA:28 |
| PN:PN                     | MOS/MSC                            | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.185               | AFL                                | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                    |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                        | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-----------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 28 - FUEL             |                             |           |          |          |                           |           |           |                  |
| 282008                    | RIGHT FUEL ACTUATOR         |           |          |          |                           |           |           | Component ATA:28 |
| PN:PN                     | MOS/MSC                     | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                         | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.185               | AFL                         | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                             |           |          |          |                           |           |           |                  |
| 282009                    | LEFT FUEL NON-RETURN VALVE  |           |          |          |                           |           |           | Component ATA:28 |
| PN:PN                     | MOS/MSC                     | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                         | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.190               | AFL                         | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-20-32   |                             |           |          |          |                           |           |           |                  |
| 282010                    | RIGHT FUEL NON-RETURN VALVE |           |          |          |                           |           |           | Component ATA:28 |
| PN:PN                     | MOS/MSC                     | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                         | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.190               | AFL                         | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-20-32   |                             |           |          |          |                           |           |           |                  |
| 282011                    | LEFT FUEL NON-RETURN VALVE  |           |          |          |                           |           |           | Component ATA:28 |
| PN:PN                     | MOS/MSC                     | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                         | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.192               | AFL                         | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-20-32   |                             |           |          |          |                           |           |           |                  |
| 282012                    | RIGHT FUEL NON-RETURN VALVE |           |          |          |                           |           |           | Component ATA:28 |
| PN:PN                     | MOS/MSC                     | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                         | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.193               | AFL                         | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 28-20-32   |                             |           |          |          |                           |           |           |                  |
| 282025                    | APU FUEL PRESSURE SWITCH    |           |          |          |                           |           |           | Component ATA:28 |
| PN:TP30093                | MOS/MSC                     | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                         |           |          |          |                           |           |           |                  |
| WC#: 28.030               | AFL                         |           |          |          |                           |           |           |                  |
|                           | APH                         | 0         |          | TSN 0    |                           |           |           |                  |
|                           | APS                         | 0         |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                             | Unit    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------------------------------------------|---------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 28 - FUEL                                       |         |           |          |          |                           |           |           |                  |
| 282032 <sup>U</sup> REFUELING PRESSURE RELIEF VALVE |         |           |          |          |                           |           |           | Component ATA:28 |
| PN:1159000-1                                        | MOS/MSC | 11-Mar-11 | O/C      |          |                           |           |           |                  |
| SN:FRTR.006/AT                                      | HRS     | 4390.9    |          |          |                           |           |           |                  |
|                                                     | AFL     | 2447      |          |          |                           |           |           |                  |
| 282053 LEFT FUEL SYSTEM RIB NO.8 NON-RETURN VALVE   |         |           |          |          |                           |           |           | Component ATA:28 |
| PN:AWE124-13                                        | MOS/MSC | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                                          | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.035                                         | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-20-32                             |         |           |          |          |                           |           |           |                  |
| 282054 RIGHT FUEL SYSTEM RIB NO.8 NON-RETURN VALVE  |         |           |          |          |                           |           |           | Component ATA:28 |
| PN:AWE124-13                                        | MOS/MSC | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                                          | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.035                                         | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-20-32                             |         |           |          |          |                           |           |           |                  |
| 282253 LEFT HAND LP FUEL VALVE                      |         |           |          |          |                           |           |           | Component ATA:28 |
| PN:HTE1984P                                         | MOS/MSC | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:M142VB196                                        | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.045                                         | AFL     | 0         |          |          |                           |           |           |                  |
| 282254 RIGHT HAND LP FUEL VALVE                     |         |           |          |          |                           |           |           | Component ATA:28 |
| PN:HTE1984                                          | MOS/MSC | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                                          | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.045                                         | AFL     | 0         |          |          |                           |           |           |                  |
| 282289 FUEL 3C VALVE                                |         |           |          |          |                           |           |           | Component ATA:28 |
| PN:HTE1984X                                         | MOS/MSC | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:M137VB196                                        | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.055                                         | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-20-61                             |         |           |          |          |                           |           |           |                  |
| 282295 FUEL 4S VALVE                                |         |           |          |          |                           |           |           | Component ATA:28 |
| PN:HTE1984S                                         | MOS/MSC | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:M370VB995                                        | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.060                                         | AFL     | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-20-61                             |         |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                                | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 28 - FUEL             |                                     |           |          |          |                           |           |           |                  |
| 282301                    | VENTRAL TANK FUEL TRANSFER VALVE    |           |          |          |                           |           |           | Component ATA:28 |
| PN:HTE1984F               | MOS/MSC                             | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:M136VB196              | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.065               | AFL                                 | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-20-78   |                                     |           |          |          |                           |           |           |                  |
| 282343                    | LEFT BOOST PUMP                     |           |          |          |                           |           |           | Component ATA:28 |
| PN:2C40-2                 | MOS/MSC                             | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:6AL62                  | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.080               | AFL                                 | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-20-12   |                                     |           |          |          |                           |           |           |                  |
| 282344                    | RIGHT BOOST PUMP                    |           |          |          |                           |           |           | Component ATA:28 |
| PN:2C40-2                 | MOS/MSC                             | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:8AL101                 | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.080               | AFL                                 | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-20-12   |                                     |           |          |          |                           |           |           |                  |
| 282384                    | SINGLE-POINT PRESSURE CONTROL VALVE |           |          |          |                           |           |           | Component ATA:28 |
| PN:PN                     | MOS/MSC                             | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.175               | AFL                                 | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                     |           |          |          |                           |           |           |                  |
| 284013                    | LEFT NO. 1 FUEL TANK UNIT           |           |          |          |                           |           |           | Component ATA:28 |
| PN:0207KTU1               | MOS/MSC                             | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:TU955481               | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.100               | AFL                                 | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-42-03   |                                     |           |          |          |                           |           |           |                  |
| 284014                    | RIGHT NO.1 FUEL TANK UNIT           |           |          |          |                           |           |           | Component ATA:28 |
| PN:0207KTU1               | MOS/MSC                             | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:TU955482               | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.100               | AFL                                 | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-42-03   |                                     |           |          |          |                           |           |           |                  |
| 284015                    | LEFT NO.2 FUEL TANK UNIT            |           |          |          |                           |           |           | Component ATA:28 |
| PN:0204KTU2               | MOS/MSC                             | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:934741                 | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.105               | AFL                                 | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-42-03   |                                     |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                 | Unit                      | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------|---------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 28 - FUEL           |                           |           |          |          |                           |           |           |                  |
| 284016                  | RIGHT NO.2 FUEL TANK UNIT |           |          |          |                           |           |           | Component ATA:28 |
| PN:0204KTU2             | MOS/MSC                   | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:954742               | HRS                       | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.105             | AFL                       | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-42-03 |                           |           |          |          |                           |           |           |                  |
| 284017                  | LEFT NO.3 FUEL TANK UNIT  |           |          |          |                           |           |           | Component ATA:28 |
| PN:0207KTU3             | MOS/MSC                   | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:TU955796             | HRS                       | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.110             | AFL                       | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-42-03 |                           |           |          |          |                           |           |           |                  |
| 284018                  | RIGHT NO.3 FUEL TANK UNIT |           |          |          |                           |           |           | Component ATA:28 |
| PN:0207KTU3             | MOS/MSC                   | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:TU955798             | HRS                       | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.110             | AFL                       | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-42-03 |                           |           |          |          |                           |           |           |                  |
| 284019                  | LEFT NO.4 FUEL TANK UNIT  |           |          |          |                           |           |           | Component ATA:28 |
| PN:0204KTU4             | MOS/MSC                   | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:955832               | HRS                       | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.115             | AFL                       | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-42-03 |                           |           |          |          |                           |           |           |                  |
| 284020                  | RIGHT NO.4 FUEL TANK UNIT |           |          |          |                           |           |           | Component ATA:28 |
| PN:0204KTU4             | MOS/MSC                   | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:955835               | HRS                       | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.115             | AFL                       | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-42-03 |                           |           |          |          |                           |           |           |                  |
| 284021                  | LEFT NO.5 FUEL TANK UNIT  |           |          |          |                           |           |           | Component ATA:28 |
| PN:0204KTU5             | MOS/MSC                   | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:955827               | HRS                       | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.120             | AFL                       | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-42-03 |                           |           |          |          |                           |           |           |                  |
| 284022                  | RIGHT NO.5 FUEL TANK UNIT |           |          |          |                           |           |           | Component ATA:28 |
| PN:0204KTU5             | MOS/MSC                   | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:955819               | HRS                       | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.120             | AFL                       | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-42-03 |                           |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                               | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 28 - FUEL             |                                    |           |          |          |                           |           |           |                  |
| 284023                    | LEFT NO.6 FUEL TANK UNIT           |           |          |          |                           |           |           | Component ATA:28 |
| PN:0204KTU6               | MOS/MSC                            | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:953268                 | HRS                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.125               | AFL                                | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-42-03   |                                    |           |          |          |                           |           |           |                  |
| 284024                    | RIGHT NO.6 FUEL TANK UNIT          |           |          |          |                           |           |           | Component ATA:28 |
| PN:0204KTU6               | MOS/MSC                            | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:961326                 | HRS                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.125               | AFL                                | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-42-03   |                                    |           |          |          |                           |           |           |                  |
| 284025                    | LEFT NO.7 FUEL TANK CONTENTS UNIT  |           |          |          |                           |           |           | Component ATA:28 |
| PN:0204KTU7               | MOS/MSC                            | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:955851                 | HRS                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.130               | AFL                                | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-42-03   |                                    |           |          |          |                           |           |           |                  |
| 284026                    | RIGHT NO.7 FUEL TANK CONTENTS UNIT |           |          |          |                           |           |           | Component ATA:28 |
| PN:0204KTU7               | MOS/MSC                            | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:955221                 | HRS                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.130               | AFL                                | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-42-03   |                                    |           |          |          |                           |           |           |                  |
| 284115                    | LEFT FUEL QUANTITY INDICATOR       |           |          |          |                           |           |           | Component ATA:28 |
| PN:WL1901KID-1            | MOS/MSC                            | 17-Sep-99 | O/C      |          |                           |           |           |                  |
| SN:961025                 | HRS                                |           |          |          |                           |           |           |                  |
| WC#: 28.140               | AFL                                |           |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-42-03   |                                    |           |          |          |                           |           |           |                  |
| 284116                    | RIGHT FUEL QUANTITY INDICATOR      |           |          |          |                           |           |           | Component ATA:28 |
| PN:WL1901KTD-1            | MOS/MSC                            | 17-Sep-99 | O/C      |          |                           |           |           |                  |
| SN:961027                 | HRS                                |           |          |          |                           |           |           |                  |
| WC#: 28.140               | AFL                                |           |          |          |                           |           |           |                  |
| PROC. REF: AMM 28-42-03   |                                    |           |          |          |                           |           |           |                  |
| 284130                    | FUEL PRESSURE SWITCH               |           |          |          |                           |           |           | Component ATA:28 |
| PN:PN                     | MOS/MSC                            | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 28.194               | AFL                                | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                    |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                     | Unit                                     | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------------------------|------------------------------------------|-----------|---------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 28 - FUEL                               |                                          |           |               |          |                           |           |           |                  |
| 284139                                      | VENTRAL TANK LOW LEVEL FLOAT SWITCH      |           |               |          |                           |           |           | Component ATA:28 |
| PN:3515000/149                              | MOS/MSC                                  | 30-May-96 | O/C           |          |                           |           |           |                  |
| SN:FRTR203AS                                | HRS                                      | 0         |               | TSN 0    |                           |           |           |                  |
| WC#: 28.145                                 | AFL                                      | 0         |               |          |                           |           |           |                  |
| PROC. REF: AMM 28-20-78                     |                                          |           |               |          |                           |           |           |                  |
| 284145                                      | VENTRAL TANK HIGH LEVEL FLOAT SWITCH     |           |               |          |                           |           |           | Component ATA:28 |
| PN:3515001-105                              | MOS/MSC                                  | 30-May-96 | O/C           |          |                           |           |           |                  |
| SN:FRTR180AP                                | HRS                                      | 0         |               | TSN 0    |                           |           |           |                  |
| WC#: 28.150                                 | AFL                                      | 0         |               |          |                           |           |           |                  |
| PROC. REF: AMM 28-22-143                    |                                          |           |               |          |                           |           |           |                  |
| 284151                                      | LEFT SURGE TANK FLOAT SWITCH             |           |               |          |                           |           |           | Component ATA:28 |
| PN:3515000/106                              | MOS/MSC                                  | 30-May-96 | O/C           |          |                           |           |           |                  |
| SN:FRTR467AS                                | HRS                                      | 0         |               | TSN 0    |                           |           |           |                  |
| WC#: 28.155                                 | AFL                                      | 0         |               |          |                           |           |           |                  |
| PROC. REF: AMM 28-44-43                     |                                          |           |               |          |                           |           |           |                  |
| 284152                                      | RIGHT SURGE TANK FLOAT SWITCH            |           |               |          |                           |           |           | Component ATA:28 |
| PN:3515000/106                              | MOS/MSC                                  | 30-May-96 | O/C           |          |                           |           |           |                  |
| SN:FRTR462AS                                | HRS                                      | 0         |               | TSN 0    |                           |           |           |                  |
| WC#: 28.155                                 | AFL                                      | 0         |               |          |                           |           |           |                  |
| PROC. REF: AMM 28-44-43                     |                                          |           |               |          |                           |           |           |                  |
| 28R650 <sup>U</sup>                         | SINGLE POINT TANK CONNECTOR              |           |               |          |                           |           |           | Component ATA:28 |
| PN:FCMX113MK2                               | MOS/MSC                                  | 13-Jun-11 | O/C           | TSN 0    |                           |           |           |                  |
| SN:156227-6                                 | HRS                                      | 4444.1    |               | TSN 0    |                           |           |           |                  |
|                                             | AFL                                      | 2480      |               | TSN 0    |                           |           |           |                  |
| ATA 29 - HYDRAULIC POWER                    |                                          |           |               |          |                           |           |           |                  |
| 290003                                      | REPLACE HYDRAULIC SUCTION FILTER ELEMENT |           |               |          |                           |           |           | Service ATA:29   |
|                                             | MOS                                      | 15-Oct-19 |               |          |                           |           |           |                  |
|                                             | HRS                                      | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)  |                  |
| WC#: 29.070                                 | AFL                                      | 3397      |               |          |                           |           |           |                  |
| PROC. REF: AFMS INSPECTION B7, AMM 29-10-21 |                                          |           |               |          |                           |           |           |                  |
| PKG:2,14<br>WO#: N950PC B & C CHECK         |                                          |           |               |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                      | Unit                                                                             | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition                         |
|----------------------------------------------|----------------------------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-------------|-------------------------------------|
| ATA 29 - HYDRAULIC POWER                     |                                                                                  |           |                |          |                           |           |             |                                     |
| 290004                                       | FUNCTIONAL TEST MAIN HYDRAULIC SYSTEM                                            |           |                |          |                           |           |             | Service ATA:29                      |
|                                              | MOS                                                                              | 15-Oct-19 |                |          |                           |           |             |                                     |
|                                              | HRS                                                                              | 5795.3    | 800 (+40/-10)  |          | 6595.3                    | 6635.3    | 67 (+40)    |                                     |
| WC#: 29.075                                  | AFL                                                                              | 3397      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INSPECTION B12, AMM 29-10-00 |                                                                                  |           |                |          |                           |           |             | PKG:2,19<br>WO#: N950PC B & C CHECK |
| 290005                                       | OPERATIONAL TEST LANDING GEAR AND FLAPS EMERGENCY LOWERING SYSTEM                |           |                |          |                           |           |             | Service ATA:29                      |
|                                              | MOS                                                                              | 15-Oct-19 |                |          |                           |           |             |                                     |
|                                              | HRS                                                                              | 5795.3    | 800 (+40/-10)  |          | 6595.3                    | 6635.3    | 67 (+40)    |                                     |
| WC#: 29.115                                  | AFL                                                                              | 3397      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INSPECTION B12, AMM 29-20-00 |                                                                                  |           |                |          |                           |           |             | PKG:2,19<br>WO#: N950PC B & C CHECK |
| 290006                                       | DRAIN HYDRAULIC TANK PRESSURIZATION SYSTEM                                       |           |                |          |                           |           |             | Service ATA:29                      |
|                                              | MOS                                                                              | 06-May-15 |                |          |                           |           |             |                                     |
|                                              | HRS                                                                              | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 29.160                                  | AFL                                                                              | 2873      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INSPECTION C7                |                                                                                  |           |                |          |                           |           |             | PKG:3,26<br>WO#: N950PC B & C CHECK |
| 290007                                       | TEST FLAPS, AIRBRAKES, LANDING GEAR, NOSEWHEEL STEERING, NOSE LEG SELF-CENTERING |           |                |          |                           |           |             | Service ATA:29                      |
|                                              | MOS                                                                              | 06-May-15 |                |          |                           |           |             |                                     |
|                                              | HRS                                                                              | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 29.165                                  | AFL                                                                              | 2873      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INSPECTION C12               |                                                                                  |           |                |          |                           |           |             | PKG:3,31<br>WO#: N950PC B & C CHECK |
| 290008                                       | CHECK EMERGENCY BRAKE SYSTEM LEAK RATE                                           |           |                |          |                           |           |             | Service ATA:29                      |
|                                              | MOS                                                                              | 06-May-15 |                |          |                           |           |             |                                     |
|                                              | HRS                                                                              | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 29.175                                  | AFL                                                                              | 2873      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INSPECTION C12, AMM 29-10-00 |                                                                                  |           |                |          |                           |           |             | PKG:3,31<br>WO#: N950PC B & C CHECK |
| 290009                                       | FUNCTIONAL TEST AUXILIARY RESERVOIR LOW-LEVEL WARNING SYSTEM                     |           |                |          |                           |           |             | Service ATA:29                      |
|                                              | MOS                                                                              | 15-Oct-19 |                |          |                           |           |             |                                     |
|                                              | HRS                                                                              | 5795.3    | 800 (+40/-10)  |          | 6595.3                    | 6635.3    | 67 (+40)    |                                     |
| WC#: 29.180                                  | AFL                                                                              | 3397      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INSPECTION B12, AMM 29-30-00 |                                                                                  |           |                |          |                           |           |             | PKG:2,19<br>WO#: N950PC B & C CHECK |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                      | Unit                                                      | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition                         |
|----------------------------------------------|-----------------------------------------------------------|-----------|-----------------|----------|---------------------------|-----------|---------------|-------------------------------------|
| ATA 29 - HYDRAULIC POWER                     |                                                           |           |                 |          |                           |           |               |                                     |
| 290010                                       | FUNCTIONAL TEST HYDRAULIC RESERVOIR PRESSURIZATION SYSTEM |           |                 |          |                           |           |               | Service ATA:29                      |
|                                              | MOS                                                       | 06-May-15 |                 |          |                           |           |               |                                     |
|                                              | HRS                                                       | 5125.6    | 1600 (+50/-50)  |          | 6725.6                    | 6775.6    | 197.3 (+50)   |                                     |
| WC#: 29.170                                  | AFL                                                       | 2873      |                 |          |                           |           |               |                                     |
| PROC. REF: AFMS INSPECTION C12, AMM 29-10-13 |                                                           |           |                 |          |                           |           |               | PKG:3,31<br>WO#: N950PC B & C CHECK |
| 290011                                       | CLEAN FULL-FLOW RELIEF VALVE                              |           |                 |          |                           |           |               | Service ATA:29                      |
|                                              | MOS                                                       | 18-Aug-17 |                 |          |                           |           |               |                                     |
|                                              | HRS                                                       | 5554.6    | 3200 (+150/-50) |          | 8754.6                    | 8904.6    | 2226.3 (+150) |                                     |
| WC#: 29.005                                  | AFL                                                       | 3197      |                 |          |                           |           |               |                                     |
| PROC. REF: AFMS INSPECTION D7, AMM 29-10-71  |                                                           |           |                 |          |                           |           |               | PKG:4,38                            |
| 290012                                       | INSPECT HYDRAULIC POWER HIGH TEMPERATURE WARNING SYSTEM   |           |                 |          |                           |           |               | Service ATA:29                      |
|                                              | MOS                                                       | 18-Aug-17 |                 |          |                           |           |               |                                     |
|                                              | HRS                                                       | 5554.6    | 3200 (+150/-50) |          | 8754.6                    | 8904.6    | 2226.3 (+150) |                                     |
| WC#: 29.145                                  | AFL                                                       | 3197      |                 |          |                           |           |               |                                     |
| PROC. REF: AFMS INSPECTION D7, AMM 29-30-00  |                                                           |           |                 |          |                           |           |               | PKG:4,38                            |
| 291018                                       | PRESSURE REGULATOR VALVE                                  |           |                 |          |                           |           |               | Component ATA:29                    |
| PN:PAS129-163                                | MOS/MSC                                                   | 30-May-96 | O/C             |          |                           |           |               |                                     |
| SN:RN599                                     | HRS                                                       | 0         |                 | TSN 0    |                           |           |               |                                     |
| WC#: 29.010                                  | AFL                                                       | 0         |                 |          |                           |           |               |                                     |
| 291025                                       | NO. 1 ENGINE HYDRAULIC PUMP CASE DRAIN NONRETURN VALVE    |           |                 |          |                           |           |               | Component ATA:29                    |
| PN:AIR87240/0                                | MOS/MSC                                                   | 30-May-96 | O/C             |          |                           |           |               |                                     |
| SN:APB951584                                 | HRS                                                       | 0         |                 | TSN 0    |                           |           |               |                                     |
| WC#: 29.015                                  | AFL                                                       | 0         |                 |          |                           |           |               |                                     |
| 291026                                       | NO. 2 ENGINE HYDRAULIC PUMP CASE DRAIN NONRETURN VALVE    |           |                 |          |                           |           |               | Component ATA:29                    |
| PN:AIR87240/0                                | MOS/MSC                                                   | 30-May-96 | O/C             |          |                           |           |               |                                     |
| SN:UNKNOWN                                   | HRS                                                       | 0         |                 | TSN 0    |                           |           |               |                                     |
| WC#: 29.015                                  | AFL                                                       | 0         |                 |          |                           |           |               |                                     |
| 291037                                       | LEFT HYDRAULIC SUCTION VALVE                              |           |                 |          |                           |           |               | Component ATA:29                    |
| PN:7907015E                                  | MOS/MSC                                                   | 30-May-96 | O/C             |          |                           |           |               |                                     |
| SN:FRTR026/AS                                | HRS                                                       | 0         |                 | TSN 0    |                           |           |               |                                     |
| WC#: 29.020                                  | AFL                                                       | 0         |                 |          |                           |           |               |                                     |
| PROC. REF: AMM 29-10-31                      |                                                           |           |                 |          |                           |           |               |                                     |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                  | Unit                                           | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------|------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 29 - HYDRAULIC POWER |                                                |           |          |          |                           |           |           |                  |
| 291038                   | RIGHT HYDRAULIC SUCTION VALVE                  |           |          |          |                           |           |           | Component ATA:29 |
| PN:7907015E              | MOS/MSC                                        | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:FRTR022/AS            | HRS                                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 29.020              | AFL                                            | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 29-10-31  |                                                |           |          |          |                           |           |           |                  |
| 291049                   | NO. 1 FULL FLOW HYDRAULIC RELIEF VALVE         |           |          |          |                           |           |           | Component ATA:29 |
| PN:AIR45394-0-2          | MOS                                            | 30-May-96 |          |          |                           |           |           | OVERHAUL         |
| SN:APB952173             | HRS                                            | 0         |          |          |                           |           |           |                  |
| WC#: 29.025              | AFL                                            | 0         | 4500     | TSN 0    | 4500                      |           | 571       |                  |
| 291050                   | NO. 2 FULL FLOW HYDRAULIC RELIEF VALVE         |           |          |          |                           |           |           | Component ATA:29 |
| PN:AIR45394-0-2          | MOS                                            | 30-May-96 |          |          |                           |           |           | OVERHAUL         |
| SN:APB952174             | HRS                                            | 0         |          |          |                           |           |           |                  |
| WC#: 29.025              | AFL                                            | 0         | 4500     | TSN 0    | 4500                      |           | 571       |                  |
| 291061                   | NO. 1 DUNLOP VALVE                             |           |          |          |                           |           |           | Component ATA:29 |
| PN:PN                    | MOS/MSC                                        | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN               | HRS                                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 29.106              | AFL                                            | 0         |          | TSN 0    |                           |           |           |                  |
| 291062                   | NO. 2 DUNLOP VALVE                             |           |          |          |                           |           |           | Component ATA:29 |
| PN:PN                    | MOS/MSC                                        | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN               | HRS                                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 29.106              | AFL                                            | 0         |          | TSN 0    |                           |           |           |                  |
| 291063                   | NO. 3 DUNLOP VALVE                             |           |          |          |                           |           |           | Component ATA:29 |
| PN:PN                    | MOS/MSC                                        | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN               | HRS                                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 29.106              | AFL                                            | 0         |          | TSN 0    |                           |           |           |                  |
| 291073                   | PRESSURE MAINTAINING VALVE                     |           |          |          |                           |           |           | Component ATA:29 |
| PN:AIR45474-0            | MOS                                            | 05-Jan-04 |          | TSO 0    |                           |           |           | OVERHAUL         |
| SN:LK0283                | HRS                                            | 2808.3    |          | TSO 0    |                           |           |           |                  |
| WC#: 29.030              | AFL                                            | 1552      | 5000     | TSO 0    | 6552                      |           | 2623      |                  |
| 291079                   | GROUND SERVICE HANDPUMP SUPPLY NONRETURN VALVE |           |          |          |                           |           |           | Component ATA:29 |
| PN:AIR48026-0-1          | MOS/MSC                                        | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:APB951840             | HRS                                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 29.035              | AFL                                            | 0         |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                        | C/W       | Interval | TSX/Adj.   | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition            |
|---------------------------|-----------------------------|-----------|----------|------------|---------------------------|-----------|-----------|------------------------|
| ATA 29 - HYDRAULIC POWER  |                             |           |          |            |                           |           |           |                        |
| 291091                    | MAIN HYDRAULIC RESERVOIR    |           |          |            |                           |           |           | Component ATA:29       |
| PN:25.8HC7/1A             | MOS/MSC                     | 30-May-96 | O/C      |            |                           |           |           |                        |
| SN:CHO6220/5              | HRS                         | 0         |          | TSN 0      |                           |           |           |                        |
| WC#: 29.040               | AFL                         | 0         |          |            |                           |           |           |                        |
| PROC. REF: AMM 29-10-13   |                             |           |          |            |                           |           |           |                        |
| 291096                    | HYDRAULIC PRESSURE GAUGE    |           |          |            |                           |           |           | Component ATA:29       |
| PN:18293201-1             | MOS/MSC                     | 30-May-96 | O/C      |            |                           |           |           |                        |
| SN:60045A                 | HRS                         | 0         |          | TSN 0      |                           |           |           |                        |
| WC#: 29.045               | AFL                         | 0         |          |            |                           |           |           |                        |
| 291103                    | MAIN HYDRAULIC ACCUMULATOR  |           |          |            |                           |           |           | Component ATA:29       |
| PN:AIR45574-3-4           | MOS/MSC                     | 30-May-96 | O/C      |            |                           |           |           |                        |
| SN:APB960917              | HRS                         | 0         |          | TSN 0      |                           |           |           |                        |
| WC#: 29.050               | AFL                         | 0         |          |            |                           |           |           |                        |
| PROC. REF: AMM 29-10-81   |                             |           |          |            |                           |           |           |                        |
| 291109                    | EMERGENCY BRAKE ACCUMULATOR |           |          |            |                           |           |           | Component ATA:29       |
| PN:AIR-45574-3-4          | MOS/MSC                     | 30-May-96 | O/C      |            |                           |           |           |                        |
| SN:APB960918              | HRS                         | 0         |          | TSN 0      |                           |           |           |                        |
| WC#: 29.055               | AFL                         | 0         |          |            |                           |           |           |                        |
| 291131                    | HYDRAULIC FILTER            |           |          |            |                           |           |           | Component ATA:29       |
| PN:PN-UNKNOWN             | MOS/MSC                     |           | O/C      |            |                           |           |           |                        |
| SN:NSN                    | HRS                         | 4942.5    |          |            |                           |           |           |                        |
| WC#: 29.060               | AFL                         | 2767      |          |            |                           |           |           |                        |
| PROC. REF: GENERIC NO REF |                             |           |          |            |                           |           |           |                        |
| 291132                    | PRESSURE FILTER ASSEMBLY    |           |          |            |                           |           |           | Component ATA:29       |
| PN:B2125-H4               | MOS/MSC                     | 16-Jun-08 | O/C      |            |                           |           |           |                        |
| SN:FYH189384              | HRS                         | 3733.7    |          | TSN 3733.7 |                           |           |           |                        |
| WC#: 29.065               | AFL                         | 2095      |          |            |                           |           |           |                        |
| PROC. REF: AMM 29-10-21   |                             |           |          |            |                           |           |           |                        |
| 291163                    | NO. 1 ENGINE HYDRAULIC PUMP |           |          |            |                           |           |           | Component ATA:29       |
| PN:42022-03               | MOS/MSC                     | 11-Nov-96 | O/C      |            |                           |           |           |                        |
| SN:1179                   | HRS                         | 20        |          | TSN 21     |                           |           |           |                        |
| WC#: 29.080               | AFL                         | 11        |          |            |                           |           |           |                        |
| PROC. REF: AMM 29-10-54   |                             |           |          |            |                           |           |           | WO#: N950PC LH ENG MPI |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                                       | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                  | Disposition      |
|---------------------------|--------------------------------------------|-----------|----------|----------|---------------------------|-----------|----------------------------|------------------|
| ATA 29 - HYDRAULIC POWER  |                                            |           |          |          |                           |           |                            |                  |
| 291164                    | NO. 2 ENGINE HYDRAULIC PUMP                |           |          |          |                           |           |                            | Component ATA:29 |
| PN:42022-03               | MOS/MSC                                    | 01-Feb-06 | O/C      | TSO 0    |                           |           |                            |                  |
| SN:HC28                   | HRS                                        | 3069.9    |          | TSO 0    |                           |           |                            |                  |
| WC#: 29.080               | AFL                                        | 1718      |          | TSO 0    |                           |           |                            |                  |
| PROC. REF: AMM 29-10-54   |                                            |           |          |          |                           |           | WO#: N950PC RH ENG MPI/CZI |                  |
| 291165                    | NO. 1 ENGINE HYDRAULIC OIL PRESSURE SENSOR |           |          |          |                           |           |                            | Component ATA:29 |
| PN:PN                     | MOS/MSC                                    | 30-May-96 | O/C      | TSN 0    |                           |           |                            |                  |
| SN:UNKNOWN                | HRS                                        | 0         |          | TSN 0    |                           |           |                            |                  |
| WC#: 29.181               | AFL                                        | 0         |          | TSN 0    |                           |           |                            |                  |
| PROC. REF: GENERIC NO REF |                                            |           |          |          |                           |           |                            |                  |
| 291166                    | NO. 2 ENGINE HYDRAULIC OIL PRESSURE SENSOR |           |          |          |                           |           |                            | Component ATA:29 |
| PN:PN                     | MOS/MSC                                    | 30-May-96 | O/C      | TSN 0    |                           |           |                            |                  |
| SN:UNKNOWN                | HRS                                        | 0         |          | TSN 0    |                           |           |                            |                  |
| WC#: 29.182               | AFL                                        | 0         |          | TSN 0    |                           |           |                            |                  |
| PROC. REF: GENERIC NO REF |                                            |           |          |          |                           |           |                            |                  |
| 291170                    | HYDRAULIC RESERVOIR RELIEF VALVE           |           |          |          |                           |           |                            | Component ATA:29 |
| PN:PN                     | MOS/MSC                                    | 30-May-96 | O/C      | TSN 0    |                           |           |                            |                  |
| SN:UNKNOWN                | HRS                                        | 0         |          | TSN 0    |                           |           |                            |                  |
| WC#: 29.117               | AFL                                        | 0         |          | TSN 0    |                           |           |                            |                  |
| 291178                    | BANJO ASSEMBLY                             |           |          |          |                           |           |                            | Component ATA:29 |
| PN:PN                     | MOS/MSC                                    | 30-May-96 | O/C      | TSN 0    |                           |           |                            |                  |
| SN:UNKNOWN                | HRS                                        | 0         |          | TSN 0    |                           |           |                            |                  |
| WC#: 29.118               | AFL                                        | 0         |          | TSN 0    |                           |           |                            |                  |
| 291182                    | GROUND SERVICING HANDPUMP                  |           |          |          |                           |           |                            | Component ATA:29 |
| PN:AIR45424-0             | MOS/MSC                                    | 30-May-96 | O/C      |          |                           |           |                            |                  |
| SN:APB951422              | HRS                                        | 0         |          | TSN 0    |                           |           |                            |                  |
| WC#: 29.085               | AFL                                        | 0         |          |          |                           |           |                            |                  |
| 291186                    | NO. 1 NON-RETURN TANK PRESSURE VALVE       |           |          |          |                           |           |                            | Component ATA:29 |
| PN:HTE4350                | MOS/MSC                                    | 30-May-96 | O/C      |          |                           |           |                            |                  |
| SN:M311VNR1195            | HRS                                        | 0         |          | TSN 0    |                           |           |                            |                  |
| WC#: 29.090               | AFL                                        | 0         |          |          |                           |           |                            |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                  | Unit                                                | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------|-----------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 29 - HYDRAULIC POWER |                                                     |           |          |          |                           |           |           |                  |
| 291193                   | NO. 2 NON-RETURN TANK PRESSURE VALVE                |           |          |          |                           |           |           | Component ATA:29 |
| PN:HTE4350               | MOS/MSC                                             | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:M307VNR1195           | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 29.090              | AFL                                                 | 0         |          |          |                           |           |           |                  |
| 292001                   | EMERGENCY HYDRAULIC TANK                            |           |          |          |                           |           |           | Component ATA:29 |
| PN:25.HC161A/D           | MOS/MSC                                             | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:CH05943NO.E           | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 29.095              | AFL                                                 | 0         |          |          |                           |           |           |                  |
| 292003                   | SUCTION FILTER ASSEMBLY                             |           |          |          |                           |           |           | Component ATA:29 |
| PN:AIR87366-0            | MOS/MSC                                             | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:BF96/001              | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 29.100              | AFL                                                 | 0         |          |          |                           |           |           |                  |
| 292007                   | EMERGENCY HYDRAULIC HAND PUMP                       |           |          |          |                           |           |           | Component ATA:29 |
| PN:AIR45448              | MOS/MSC                                             | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:APB951927             | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 29.105              | AFL                                                 | 0         |          |          |                           |           |           |                  |
| 292013                   | AUXILIARY RESERVOIR LOW-LEVEL WARNING SYSTEM SWITCH |           |          |          |                           |           |           | Component ATA:29 |
| PN:3515000/76            | MOS/MSC                                             | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN               | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 29.110              | AFL                                                 | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 29-30-00  |                                                     |           |          |          |                           |           |           |                  |
| 292031                   | EMERGENCY TANK ON/OFF HAND PUMP VALVE               |           |          |          |                           |           |           | Component ATA:29 |
| PN:AIR45446-1-2          | MOS/MSC                                             | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN               | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 29.120              | AFL                                                 | 0         |          |          |                           |           |           |                  |
| 292037                   | EMERGENCY SYSTEM CHECK VALVE                        |           |          |          |                           |           |           | Component ATA:29 |
| PN:AIR48026-0-1          | MOS/MSC                                             | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN               | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 29.125              | AFL                                                 | 0         |          | TSN 0    |                           |           |           |                  |
| 293001                   | NO. 1 ENGINE HYDRAULIC PUMP LOW PRESSURE SWITCH     |           |          |          |                           |           |           | Component ATA:29 |
| PN:211C223-647           | MOS/MSC                                             | 23-May-12 | O/C      |          |                           |           |           |                  |
| SN:M014997               | HRS                                                 | 4693.9    |          |          |                           |           |           |                  |
| WC#: 29.130              | AFL                                                 | 2628      |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                  | Unit                                            | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------|-------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 29 - HYDRAULIC POWER |                                                 |           |          |          |                           |           |           |                  |
| 293002                   | NO. 2 ENGINE HYDRAULIC PUMP LOW PRESSURE SWITCH |           |          |          |                           |           |           | Component ATA:29 |
| PN:211C223-647           | MOS/MSC                                         | 07-Jun-12 | O/C      | TSN 0    |                           |           |           |                  |
| SN:L046070               | HRS                                             | 4710.6    |          | TSN 0    |                           |           |           |                  |
| WC#: 29.130              | AFL                                             | 2635      |          | TSN 0    |                           |           |           |                  |
| 293013                   | EMERGENCY BRAKE LOW PRESSURE WARNING SWITCH     |           |          |          |                           |           |           | Component ATA:29 |
| PN:TP42001               | MOS                                             | 06-May-13 |          | TSO 0    |                           |           |           | OVERHAUL         |
| SN:1711                  | HRS                                             | 4942.5    | 5000     | TSO 0    | 9942.5                    |           | 3414.2    |                  |
| WC#: 29.135              | AFL                                             | 2767      |          | TSO 0    |                           |           |           |                  |
| 293019                   | HYDRAULIC PRESSURE TRANSDUCER                   |           |          |          |                           |           |           | Component ATA:29 |
| PN:695-4-20              | MOS/MSC                                         | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:BY6069                | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 29.140              | AFL                                             | 0         |          |          |                           |           |           |                  |
| 293024                   | HYDRAULIC SYSTEM OVERTEMPERATURE SWITCH         |           |          |          |                           |           |           | Component ATA:29 |
| PN:150T283               | MOS/MSC                                         | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:959                   | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 29.145              | AFL                                             | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 29-30-00  |                                                 |           |          |          |                           |           |           |                  |
| 294001                   | LEFT HYDRAULIC NON-RETURN VALVE                 |           |          |          |                           |           |           | Component ATA:29 |
| PN:PN                    | MOS/MSC                                         | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN               | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 29.183              | AFL                                             | 0         |          | TSN 0    |                           |           |           |                  |
| 294002                   | RIGHT HYDRAULIC NON-RETURN VALVE                |           |          |          |                           |           |           | Component ATA:29 |
| PN:PN                    | MOS/MSC                                         | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN               | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 29.184              | AFL                                             | 0         |          | TSN 0    |                           |           |           |                  |
| 294003                   | NO. 1 HYDRAULIC NON-RETURN VALVE                |           |          |          |                           |           |           | Component ATA:29 |
| PN:PN                    | MOS/MSC                                         | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN               | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 29.186              | AFL                                             | 0         |          | TSN 0    |                           |           |           |                  |
| 294004                   | NO. 2 HYDRAULIC NON-RETURN VALVE                |           |          |          |                           |           |           | Component ATA:29 |
| PN:PN                    | MOS/MSC                                         | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN               | HRS                                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 29.187              | AFL                                             | 0         |          | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                     | Unit                                                 | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition                         |
|---------------------------------------------|------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|--------------|-------------------------------------|
| ATA 29 - HYDRAULIC POWER                    |                                                      |           |                |          |                           |           |              |                                     |
| 294005                                      | HYDRAULIC NON-RETURN VALVE                           |           |                |          |                           |           |              | Component ATA:29                    |
| PN:PN                                       | MOS/MSC                                              | 30-May-96 | O/C            | TSN 0    |                           |           |              |                                     |
| SN:UNKNOWN                                  | HRS                                                  | 0         |                | TSN 0    |                           |           |              |                                     |
| WC#: 29.188                                 | AFL                                                  | 0         |                | TSN 0    |                           |           |              |                                     |
| 294006                                      | HYDRAULIC RELIEF VALVE                               |           |                |          |                           |           |              | Component ATA:29                    |
| PN:PN                                       | MOS/MSC                                              | 30-May-96 | O/C            | TSN 0    |                           |           |              |                                     |
| SN:UNKNOWN                                  | HRS                                                  | 0         |                | TSN 0    |                           |           |              |                                     |
| WC#: 29.189                                 | AFL                                                  | 0         |                | TSN 0    |                           |           |              |                                     |
| PROC. REF: GENERIC NO REF                   |                                                      |           |                |          |                           |           |              |                                     |
| 294007                                      | LEFT HYDRAULIC NON-RETURN VALVE                      |           |                |          |                           |           |              | Component ATA:29                    |
| PN:PN                                       | MOS/MSC                                              | 30-May-96 | O/C            | TSN 0    |                           |           |              |                                     |
| SN:UNKNOWN                                  | HRS                                                  | 0         |                | TSN 0    |                           |           |              |                                     |
| WC#: 29.190                                 | AFL                                                  | 0         |                | TSN 0    |                           |           |              |                                     |
| 294008                                      | RIGHT HYDRAULIC NON-RETURN VALVE                     |           |                |          |                           |           |              | Component ATA:29                    |
| PN:PN                                       | MOS/MSC                                              | 30-May-96 | O/C            | TSN 0    |                           |           |              |                                     |
| SN:UNKNOWN                                  | HRS                                                  | 0         |                | TSN 0    |                           |           |              |                                     |
| WC#: 29.191                                 | AFL                                                  | 0         |                | TSN 0    |                           |           |              |                                     |
| ATA 30 - ICE AND RAIN PROTECTION            |                                                      |           |                |          |                           |           |              |                                     |
| 300001                                      | FUNCTIONAL TEST ROTARY ICE DETECTOR                  |           |                |          |                           |           |              | Service ATA:30                      |
|                                             | MOS                                                  | 15-Oct-19 |                |          |                           |           |              |                                     |
|                                             | HRS                                                  | 5795.3    | 800 (+40/-10)  |          | 6595.3                    | 6635.3    | 67 (+40)     |                                     |
| WC#: 30.085                                 | AFL                                                  | 3397      |                |          |                           |           |              |                                     |
| PROC. REF: AFMS INSPECTION B1, AMM 30-80-00 |                                                      |           |                |          |                           |           |              |                                     |
|                                             |                                                      |           |                |          |                           |           |              | PKG:2,8<br>WO#: N950PC B & C CHECK  |
| 300002                                      | OPERATIONAL TEST WINDSHIELD ELECTRICAL DE-ICE SYSTEM |           |                |          |                           |           |              | Service ATA:30                      |
|                                             | MOS                                                  | 07-Apr-22 |                |          |                           |           |              |                                     |
|                                             | HRS                                                  | 6316.6    | 1600 (+50/-50) |          | 7916.6                    | 7966.6    | 1388.3 (+50) |                                     |
| WC#: 30.080                                 | AFL                                                  | 3776      |                |          |                           |           |              |                                     |
| PROC. REF: AFMS INSPECTION C1, AMM 30-41-00 |                                                      |           |                |          |                           |           |              |                                     |
|                                             |                                                      |           |                |          |                           |           |              | PKG:3,20<br>WO#: N950PC B & C CHECK |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                | Unit                                                | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                           | Disposition      |
|--------------------------------------------------------|-----------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-------------------------------------|------------------|
| ATA 30 - ICE AND RAIN PROTECTION                       |                                                     |           |                |          |                           |           |                                     |                  |
| 300003                                                 | REPLACE AIRFRAME DE-ICING FILTER ELEMENT            |           |                |          |                           |           |                                     | Service ATA:30   |
|                                                        | MOS                                                 | 15-Oct-19 |                |          |                           |           |                                     |                  |
|                                                        | HRS                                                 | 5795.3    | 800 (+40/-10)  |          | 6595.3                    | 6635.3    | 67 (+40)                            |                  |
| WC#: 30.020                                            | AFL                                                 | 3397      |                |          |                           |           |                                     |                  |
| PROC. REF: AFMS INSPECTION B6, AMM 30-10-52            |                                                     |           |                |          |                           |           | PKG:2,13<br>WO#: N950PC B & C CHECK |                  |
| 300004                                                 | FUNCTIONAL TEST PITOT HEAD AND STATIC PLATE HEATERS |           |                |          |                           |           |                                     | Service ATA:30   |
|                                                        | MOS                                                 | 06-May-15 |                |          |                           |           |                                     |                  |
|                                                        | HRS                                                 | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50)                         |                  |
| WC#: 30.065                                            | AFL                                                 | 2873      |                |          |                           |           |                                     |                  |
| PROC. REF: AFMS INSPECTION C1, AMM 30-35-15            |                                                     |           |                |          |                           |           | PKG:3,20<br>WO#: N950PC B & C CHECK |                  |
| 300005                                                 | REPLACE AIRFRAME DE-ICING PUMP SUCTION FILTER       |           |                |          |                           |           |                                     | Service ATA:30   |
|                                                        | MOS                                                 | 06-May-15 |                |          |                           |           |                                     |                  |
|                                                        | HRS                                                 | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50)                         |                  |
| WC#: 30.045                                            | AFL                                                 | 2873      |                |          |                           |           |                                     |                  |
| PROC. REF: AFMS INSPECTION C6, AMM 30-10-43            |                                                     |           |                |          |                           |           | PKG:3,25<br>WO#: N950PC B & C CHECK |                  |
| 300007                                                 | PURGE ICE PROTECTION SYSTEM                         |           |                |          |                           |           |                                     | Service ATA:30   |
|                                                        | MOS                                                 | 22-Dec-22 | 1              |          | 22-Jan-23                 |           | OVD                                 |                  |
|                                                        | HRS                                                 | 6495      |                |          |                           |           |                                     |                  |
| WC#: 30.090                                            | AFL                                                 | 3906      |                |          |                           |           |                                     |                  |
| PROC. REF: AMM 12-30-00, AFMS OUT OF PHASE INSPECTIONS |                                                     |           |                |          |                           |           | WO#: N950PC KLM JAN 2023            |                  |
| 300012 <sup>U</sup>                                    | SERVICE TKS FLUID                                   |           |                |          |                           |           |                                     | Service ATA:30   |
|                                                        | MOS/MSC                                             | 22-Dec-22 | A/R            |          |                           |           |                                     |                  |
|                                                        | HRS                                                 | 6495.5    |                |          |                           |           |                                     |                  |
|                                                        | AFL                                                 | 3906      |                |          |                           |           |                                     |                  |
|                                                        |                                                     |           |                |          |                           |           | PKG:68                              |                  |
| 301001                                                 | TKS DE-ICER TANK                                    |           |                |          |                           |           |                                     | Component ATA:30 |
| PN:08301-01                                            | MOS/MSC                                             | 30-May-96 | O/C            |          |                           |           |                                     |                  |
| SN:AST96D365                                           | HRS                                                 | 0         |                | TSN 0    |                           |           |                                     |                  |
| WC#: 30.010                                            | AFL                                                 | 0         |                |          |                           |           |                                     |                  |
| PROC. REF: AMM 30-10-35                                |                                                     |           |                |          |                           |           |                                     |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                          | Unit                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------|-----------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 30 - ICE AND RAIN PROTECTION |                                   |           |          |          |                           |           |           |                  |
| 301007                           | AIRFRAME DE-ICING PUMP ASSEMBLY   |           |          |          |                           |           |           | Component ATA:30 |
| PN:XA9511E009                    | MOS/MSC                           | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:F102                          | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.015                      | AFL                               | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 30-10-43          |                                   |           |          |          |                           |           |           |                  |
| 301013                           | AIRFRAME DE-ICING FILTER ASSEMBLY |           |          |          |                           |           |           | Component ATA:30 |
| PN:TKSF903                       | MOS/MSC                           | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                       | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.020                      | AFL                               | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 30-10-52          |                                   |           |          |          |                           |           |           |                  |
| 301025                           | DE-ICING VALVE ASSEMBLY           |           |          |          |                           |           |           | Component ATA:30 |
| PN:FV131-1                       | MOS/MSC                           | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:AST95E198                     | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.025                      | AFL                               | 0         |          |          |                           |           |           |                  |
| 301037                           | DE-ICING SYSTEM CONTENTS GAUGE    |           |          |          |                           |           |           | Component ATA:30 |
| PN:S458-3-191                    | MOS/MSC                           | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:BG75450                       | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.030                      | AFL                               | 0         |          |          |                           |           |           |                  |
| 301043                           | DE-ICING SYSTEM CONTENTS FLOAT    |           |          |          |                           |           |           | Component ATA:30 |
| PN:FRH070001                     | MOS/MSC                           | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:FR006AR                       | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.035                      | AFL                               | 0         |          |          |                           |           |           |                  |
| 301063                           | EMPENNAGE TKS PROPORTION UNIT     |           |          |          |                           |           |           | Component ATA:30 |
| PN:PU308JT40                     | MOS/MSC                           | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:AST95G075                     | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.050                      | AFL                               | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 30-10-25          |                                   |           |          |          |                           |           |           |                  |
| 301067                           | TKS VENT VALVE                    |           |          |          |                           |           |           | Component ATA:30 |
| PN:FV141                         | MOS/MSC                           | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:AST96B235                     | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.055                      | AFL                               | 0         |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                          | Unit                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------|---------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 30 - ICE AND RAIN PROTECTION |                                       |           |          |          |                           |           |           |                  |
| 301069                           | TKS PRESSURE SWITCH                   |           |          |          |                           |           |           | Component ATA:30 |
| PN:P067D-075                     | MOS/MSC                               | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:AST93A402                     | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.060                      | AFL                                   | 0         |          |          |                           |           |           |                  |
| 304019                           | NO. 1 WINDSCREEN (A PANEL) CONTROLLER |           |          |          |                           |           |           | Component ATA:30 |
| PN:ND0075-2011                   | MOS/MSC                               | 31-Jan-07 | O/C      |          |                           |           |           |                  |
| SN:L360624                       | HRS                                   | 3375.3    |          |          |                           |           |           |                  |
| WC#: 30.070                      | AFL                                   | 1898      |          |          |                           |           |           |                  |
| 304020                           | NO. 2 WINDSCREEN (A PANEL) CONTROLLER |           |          |          |                           |           |           | Component ATA:30 |
| PN:ND00752011MK22                | MOS/MSC                               | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:L243926                       | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.070                      | AFL                                   | 0         |          |          |                           |           |           |                  |
| 304022                           | NO. 1 WINDSCREEN (B PANEL) CONTROLLER |           |          |          |                           |           |           | Component ATA:30 |
| PN:ND00752011-2                  | MOS/MSC                               | 18-Mar-09 | O/C      |          |                           |           |           |                  |
| SN:L375715                       | HRS                                   | 3933.2    |          |          |                           |           |           |                  |
| WC#: 30.075                      | AFL                                   | 2200      |          |          |                           |           |           |                  |
| 304023                           | NO. 2 WINDSCREEN (B PANEL) CONTROLLER |           |          |          |                           |           |           | Component ATA:30 |
| PN:ND00752001MK20                | MOS/MSC                               | 17-Aug-08 | O/C      | TSN 0    |                           |           |           |                  |
| SN:L367480                       | HRS                                   | 3779.9    |          | TSN 0    |                           |           |           |                  |
| WC#: 30.075                      | AFL                                   | 2117      |          | TSN 0    |                           |           |           |                  |
| 305001 <sup>U</sup>              | ELECTROSTATIC FILTER                  |           |          |          |                           |           |           | Component ATA:30 |
| PN:NB00075-2260                  | MOS/MSC                               | 30-Jan-12 | O/C      |          |                           |           |           |                  |
| SN:L392521                       | HRS                                   |           |          |          |                           |           |           |                  |
|                                  | AFL                                   |           |          |          |                           |           |           |                  |
| 308001                           | ROTARY ICE DETECTOR                   |           |          |          |                           |           |           | Component ATA:30 |
| PN:NF0075-667                    | MOS/MSC                               | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:L244105                       | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 30.085                      | AFL                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 30-80-00          |                                       |           |          |          |                           |           |           |                  |
| 30R100 <sup>U</sup>              | LEFT HAND WINDSHIELD RELAY            |           |          |          |                           |           |           | Component ATA:30 |
| PN:H-A5N                         | MOS/MSC                               | 15-Nov-08 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                       | HRS                                   | 3864.2    |          |          |                           |           |           |                  |
|                                  | AFL                                   | 2162      |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                               | Unit                     | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------------------|--------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 31 - INDICATING/RECORDING SYSTEMS |                          |           |          |          |                           |           |           |                  |
| 310002                                | LIGHTNING SENSOR ANTENNA |           |          |          |                           |           |           | Component ATA:31 |
| PN:4057697-901                        | MOS/MSC                  | 30-Aug-96 | O/C      |          |                           |           |           |                  |
| SN:96020898                           | HRS                      | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 31.015                           | AFL                      | 9         |          |          |                           |           |           |                  |
| 310100                                | LIGHTNING PROCESSOR UNIT |           |          |          |                           |           |           | Component ATA:31 |
| PN:7011822-903                        | MOS/MSC                  | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 31.010                           | AFL                      | 0         |          |          |                           |           |           |                  |
| PROC. REF: MMA 34-43-05, MMA 34-43-10 |                          |           |          |          |                           |           |           |                  |
| 311001                                | TKS TIMER                |           |          |          |                           |           |           | Component ATA:31 |
| PN:25-7NF1565A                        | MOS/MSC                  | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:007063                             | HRS                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 31.020                           | AFL                      | 0         |          |          |                           |           |           |                  |
| 312001                                | PILOT CLOCK              |           |          |          |                           |           |           | Component ATA:31 |
| PN:6420093-4                          | MOS/MSC                  | 08-Apr-22 | O/C      | TSN 0    |                           |           |           |                  |
| SN:C22-10066                          | HRS                      | 6316.6    |          | TSN 0    |                           |           |           |                  |
| WC#: 31.025                           | AFL                      | 3776      |          | TSN 0    |                           |           |           |                  |
| 312001A <sup>U</sup>                  | BATTERY- PILOT CLOCK     |           |          |          |                           |           |           | Component ATA:31 |
| PN:BR2032                             | MOS/MSC                  | 08-Apr-22 | A/R      | TSN 0    |                           |           |           |                  |
| SN:NSN                                | HRS                      | 6316.6    |          | TSN 0    |                           |           |           |                  |
|                                       | AFL                      | 3776      |          | TSN 0    |                           |           |           |                  |
| 312002                                | COPILOT CLOCK            |           |          |          |                           |           |           | Component ATA:31 |
| PN:6420093-4                          | MOS/MSC                  | 08-Apr-22 | O/C      | TSN 0    |                           |           |           |                  |
| SN:C22-10065                          | HRS                      | 6316.6    |          | TSN 0    |                           |           |           |                  |
| WC#: 31.025                           | AFL                      | 3776      |          | TSN 0    |                           |           |           |                  |
| 312002A <sup>U</sup>                  | BATTERY- CO PILOT CLOCK  |           |          |          |                           |           |           | Component ATA:31 |
| PN:BR2032                             | MOS/MSC                  | 08-Apr-22 | A/R      | TSN 0    |                           |           |           |                  |
| SN:NSN                                | HRS                      | 6316.6    |          | TSN 0    |                           |           |           |                  |
|                                       | AFL                      | 3776      |          | TSN 0    |                           |           |           |                  |
| 312008                                | O.A.T. INDICATOR         |           |          |          |                           |           |           | Component ATA:31 |
| PN:2141-01-0014                       | MOS/MSC                  | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:BG75623                            | HRS                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 31.030                           | AFL                      | 0         |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                               | Unit                          | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------------------|-------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 31 - INDICATING/RECORDING SYSTEMS |                               |           |          |          |                           |           |           |                  |
| 312009                                | PITOT AMMETER                 |           |          |          |                           |           |           | Component ATA:31 |
| PN:2132-1-62                          | MOS/MSC                       | 09-Mar-04 | O/C      | TSN 0    |                           |           |           |                  |
| SN:82649                              | HRS                           | 2632.6    |          | TSN 0    |                           |           |           |                  |
| WC#: 31.035                           | AFL                           | 1434      |          | TSN 0    |                           |           |           |                  |
| 313003                                | NO. 1 CURRENT MONITOR-        |           |          |          |                           |           |           | Component ATA:31 |
| PN:PN                                 | MOS/MSC                       | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                           | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 31.300                           | AFL                           | 0         |          | TSN 0    |                           |           |           |                  |
| 313004                                | NO. 2 CURRENT MONITOR-        |           |          |          |                           |           |           | Component ATA:31 |
| PN:PN                                 | MOS/MSC                       | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                           | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 31.300                           | AFL                           | 0         |          | TSN 0    |                           |           |           |                  |
| 313005                                | LEFT CURRENT LEVEL INDICATOR  |           |          |          |                           |           |           | Component ATA:31 |
| PN:770-537                            | MOS/MSC                       | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:1104                               | HRS                           | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 31.040                           | AFL                           | 0         |          |          |                           |           |           |                  |
| 313006                                | RIGHT CURRENT LEVEL INDICATOR |           |          |          |                           |           |           | Component ATA:31 |
| PN:770-537                            | MOS/MSC                       | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:1112                               | HRS                           | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 31.040                           | AFL                           | 0         |          |          |                           |           |           |                  |
| 313007                                | CABIN TEMPERATURE INDICATOR   |           |          |          |                           |           |           | Component ATA:31 |
| PN:2132-01-0015                       | MOS/MSC                       | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:BG75878                            | HRS                           | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 31.045                           | AFL                           | 0         |          |          |                           |           |           |                  |
| 313008                                | DC VOLTMETER                  |           |          |          |                           |           |           | Component ATA:31 |
| PN:2132-01-0012                       | MOS/MSC                       | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:BG75899                            | HRS                           | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 31.050                           | AFL                           | 0         |          |          |                           |           |           |                  |
| 313009                                | LEFT DC AMMETER               |           |          |          |                           |           |           | Component ATA:31 |
| PN:2132-01-0013                       | MOS/MSC                       | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:BG75416                            | HRS                           | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 31.055                           | AFL                           | 0         |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                               | Unit                           | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------------------|--------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 31 - INDICATING/RECORDING SYSTEMS |                                |           |          |          |                           |           |           |                  |
| 313010                                | AC VOLTMETER                   |           |          |          |                           |           |           | Component ATA:31 |
| PN:2132-01-0014                       | MOS/MSC                        | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:BG75552                            | HRS                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 31.060                           | AFL                            | 0         |          |          |                           |           |           |                  |
| 313011                                | RIGHT DC AMMETER               |           |          |          |                           |           |           | Component ATA:31 |
| PN:2132-01-0013                       | MOS/MSC                        | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:BG75419                            | HRS                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 31.065                           | AFL                            | 0         |          |          |                           |           |           |                  |
| 313012                                | FLIGHT DATA ACCELEROMETER      |           |          |          |                           |           |           | Component ATA:31 |
| PN:PN                                 | MOS/MSC                        | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 31.120                           | AFL                            | 0         |          | TSN 0    |                           |           |           |                  |
| 313014                                | DUCT AIR TEMPERATURE INDICATOR |           |          |          |                           |           |           | Component ATA:31 |
| PN:2132-01-0018                       | MOS/MSC                        | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:BG75567                            | HRS                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 31.070                           | AFL                            | 0         |          |          |                           |           |           |                  |
| 313015                                | TEMPERATURE SELECTOR           |           |          |          |                           |           |           | Component ATA:31 |
| PN:25-6MC415                          | MOS/MSC                        | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:035C-0875                          | HRS                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 31.075                           | AFL                            | 0         |          |          |                           |           |           |                  |
| 313020                                | FUEL PROCESSOR UNIT            |           |          |          |                           |           |           | Component ATA:31 |
| PN:0107KPU-1                          | MOS/MSC                        | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:961011                             | HRS                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 31.080                           | AFL                            | 0         |          |          |                           |           |           |                  |
| 313030                                | FILTER UNIT                    |           |          |          |                           |           |           | Component ATA:31 |
| PN:PN                                 | MOS/MSC                        | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 31.303                           | AFL                            | 0         |          | TSN 0    |                           |           |           |                  |
| 313031                                | FILTER UNIT                    |           |          |          |                           |           |           | Component ATA:31 |
| PN:PN                                 | MOS/MSC                        | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 31.303                           | AFL                            | 0         |          | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                               | Unit                               | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------------------|------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 31 - INDICATING/RECORDING SYSTEMS |                                    |           |          |          |                           |           |           |                  |
| 313032                                | FILTER UNIT                        |           |          |          |                           |           |           | Component ATA:31 |
| PN:PN                                 | MOS/MSC                            | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 31.303                           | AFL                                | 0         |          | TSN 0    |                           |           |           |                  |
| 313033                                | FILTER UNIT                        |           |          |          |                           |           |           | Component ATA:31 |
| PN:PN                                 | MOS/MSC                            | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 31.303                           | AFL                                | 0         |          | TSN 0    |                           |           |           |                  |
| 313101                                | ANGLE OF ATTACK INDICATOR COMPUTER |           |          |          |                           |           |           | Component ATA:31 |
| PN:C-87705-4                          | MOS/MSC                            | 12-Nov-96 | O/C      |          |                           |           |           |                  |
| SN:220                                | HRS                                | 20        |          | TSN 4    |                           |           |           |                  |
| WC#: 31.095                           | AFL                                | 11        |          |          |                           |           |           |                  |
| PROC. REF: MMA 31-20-06, AMM 31-20-05 |                                    |           |          |          |                           |           |           |                  |
| 313109                                | NO. 1 ANGLE OF ATTACK INDEXER      |           |          |          |                           |           |           | Component ATA:31 |
| PN:965-0113-003                       | MOS/MSC                            | 30-Aug-96 | O/C      |          |                           |           |           |                  |
| SN:1492                               | HRS                                | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 31.100                           | AFL                                | 9         |          |          |                           |           |           |                  |
| PROC. REF: MMA 31-20-06, AMM 31-20-05 |                                    |           |          |          |                           |           |           |                  |
| 313110                                | NO. 2 ANGLE OF ATTACK INDEXER      |           |          |          |                           |           |           | Component ATA:31 |
| PN:965-0113-003                       | MOS/MSC                            | 30-Aug-96 | O/C      |          |                           |           |           |                  |
| SN:1500                               | HRS                                | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 31.100                           | AFL                                | 9         |          |          |                           |           |           |                  |
| PROC. REF: MMA 31-20-06, AMM 31-20-05 |                                    |           |          |          |                           |           |           |                  |
| 313201                                | BRAKE PRESSURE INDICATOR           |           |          |          |                           |           |           | Component ATA:31 |
| PN:696-01-0013                        | MOS/MSC                            | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:BG75514                            | HRS                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 31.105                           | AFL                                | 0         |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF             |                                    |           |          |          |                           |           |           |                  |
| 313301                                | FATIGUE METER                      |           |          |          |                           |           |           | Component ATA:31 |
| PN:PN                                 | MOS/MSC                            | 30-May-96 | N/R      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 31.110                           | AFL                                | 0         |          | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                      | Unit                            | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------|---------------------------------|-----------|---------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 31 - INDICATING/RECORDING SYSTEMS        |                                 |           |               |          |                           |           |           |                  |
| 314008                                       | NO. 1 INCLINOMETER              |           |               |          |                           |           |           | Component ATA:31 |
| PN:7005400-901                               | MOS/MSC                         | 30-May-96 | O/C           |          |                           |           |           |                  |
| SN:UNKNOWN                                   | HRS                             | 0         |               | TSN 0    |                           |           |           |                  |
| WC#: 31.115                                  | AFL                             | 0         |               |          |                           |           |           |                  |
| 314009                                       | NO. 2 INCLINOMETER              |           |               |          |                           |           |           | Component ATA:31 |
| PN:7005400-901                               | MOS/MSC                         | 30-May-96 | O/C           |          |                           |           |           |                  |
| SN:UNKNOWN                                   | HRS                             | 0         |               | TSN 0    |                           |           |           |                  |
| WC#: 31.115                                  | AFL                             | 0         |               |          |                           |           |           |                  |
| 314012                                       | NO. 1 IAPS (ICC 3000) CARD CAGE |           |               |          |                           |           |           | Component ATA:31 |
| PN:PN                                        | MOS/MSC                         | 30-May-96 | O/C           | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                   | HRS                             | 0         |               | TSN 0    |                           |           |           |                  |
|                                              | AFL                             | 0         |               | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                    |                                 |           |               |          |                           |           |           |                  |
| 314012                                       | NO. 2 IAPS (ICC 3000) CARD CAGE |           |               |          |                           |           |           | Component ATA:31 |
| PN:PN                                        | MOS/MSC                         | 30-May-96 | O/C           | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                   | HRS                             | 0         |               | TSN 0    |                           |           |           |                  |
|                                              | AFL                             | 0         |               | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                    |                                 |           |               |          |                           |           |           |                  |
| 314014                                       | MAINTENANCE DIAGNOSTIC COMPUTER |           |               |          |                           |           |           | Component ATA:31 |
| PN:PN                                        | MOS/MSC                         | 30-May-96 | O/C           | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                   | HRS                             | 0         |               | TSN 0    |                           |           |           |                  |
| WC#: 31.130                                  | AFL                             | 0         |               | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                    |                                 |           |               |          |                           |           |           |                  |
| ATA 32 - LANDING GEAR                        |                                 |           |               |          |                           |           |           |                  |
| 320001                                       | TEST BRAKING SYSTEMS            |           |               |          |                           |           |           | Service ATA:32   |
|                                              | MOS                             | 15-Oct-19 |               |          |                           |           |           |                  |
|                                              | HRS                             | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)  |                  |
| WC#: 32.305                                  | AFL                             | 3397      |               |          |                           |           |           |                  |
| PROC. REF: AFMS INSPECTION B12, AMM 32-40-00 |                                 |           |               |          |                           |           |           |                  |
| PKG:2,19<br>WO#: N950PC B & C CHECK          |                                 |           |               |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                    | Unit                                                                       | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition                         |
|------------------------------------------------------------|----------------------------------------------------------------------------|-----------|---------------|----------|---------------------------|-----------|-----------|-------------------------------------|
| ATA 32 - LANDING GEAR                                      |                                                                            |           |               |          |                           |           |           |                                     |
| 320002                                                     | FUNCTIONAL TEST MAXARET UNITS                                              |           |               |          |                           |           |           | Service ATA:32                      |
|                                                            | MOS                                                                        | 15-Oct-19 |               |          |                           |           |           |                                     |
|                                                            | HRS                                                                        | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)  |                                     |
| WC#: 32.370                                                | AFL                                                                        | 3397      |               |          |                           |           |           |                                     |
| PROC. REF: AFMS INSPECTION B12, AMM 32-40-101              |                                                                            |           |               |          |                           |           |           | PKG:2,19<br>WO#: N950PC B & C CHECK |
| 320003                                                     | CHECK NOSE GEAR LEG ASSEMBLY                                               |           |               |          |                           |           |           | Service ATA:32                      |
|                                                            | MOS                                                                        | 15-Oct-19 |               |          |                           |           |           |                                     |
|                                                            | HRS                                                                        | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)  |                                     |
| WC#: 32.430                                                | AFL                                                                        | 3397      |               |          |                           |           |           |                                     |
| PROC. REF: AFMS INSPECTION B12, AMM 12-32-00, AMM 32-20-12 |                                                                            |           |               |          |                           |           |           | PKG:2,19<br>WO#: N950PC B & C CHECK |
| 320004                                                     | CHECK NOSE GEAR LEG LOCK AND CHANGE OVER MICROSWITCHES OPERATING MECHANISM |           |               |          |                           |           |           | Service ATA:32                      |
|                                                            | MOS                                                                        | 15-Oct-19 |               |          |                           |           |           |                                     |
|                                                            | HRS                                                                        | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)  |                                     |
| WC#: 32.435                                                | AFL                                                                        | 3397      |               |          |                           |           |           |                                     |
| PROC. REF: AFMS INSPECTION B12                             |                                                                            |           |               |          |                           |           |           | PKG:2,19<br>WO#: N950PC B & C CHECK |
| 320005                                                     | INSPECT NOSEWHEEL STEERING JACK                                            |           |               |          |                           |           |           | Service ATA:32                      |
|                                                            | MOS                                                                        | 15-Oct-19 |               |          |                           |           |           |                                     |
|                                                            | HRS                                                                        | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)  |                                     |
| WC#: 32.470                                                | AFL                                                                        | 3397      |               |          |                           |           |           |                                     |
| PROC. REF: AFMS INSPECTION B12, AMM 32-50-00               |                                                                            |           |               |          |                           |           |           | PKG:2,19<br>WO#: N950PC B & C CHECK |
| 320006                                                     | INSPECT NOSE GEAR RETRACTION AND STEERING SYSTEM SPRING STRUTS             |           |               |          |                           |           |           | Service ATA:32                      |
|                                                            | MOS                                                                        | 15-Oct-19 |               |          |                           |           |           |                                     |
|                                                            | HRS                                                                        | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)  |                                     |
| WC#: 32.450                                                | AFL                                                                        | 3397      |               |          |                           |           |           |                                     |
| PROC. REF: AFMS INSPECTION B12                             |                                                                            |           |               |          |                           |           |           | PKG:2,19<br>WO#: N950PC B & C CHECK |
| 320007                                                     | INSPECT NOSEWHEEL STEERING ON/OFF VALVE                                    |           |               |          |                           |           |           | Service ATA:32                      |
|                                                            | MOS                                                                        | 15-Oct-19 |               |          |                           |           |           |                                     |
|                                                            | HRS                                                                        | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)  |                                     |
| WC#: 32.350                                                | AFL                                                                        | 3397      |               |          |                           |           |           |                                     |
| PROC. REF: AFMS INSPECTION B12                             |                                                                            |           |               |          |                           |           |           | PKG:2,19<br>WO#: N950PC B & C CHECK |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                    | Unit                                                  | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition                         |
|------------------------------------------------------------|-------------------------------------------------------|-----------|---------------|----------|---------------------------|-----------|-----------|-------------------------------------|
| ATA 32 - LANDING GEAR                                      |                                                       |           |               |          |                           |           |           |                                     |
| 320008                                                     | CHECK NOSE GEAR DRAG STAY ASSEMBLY                    |           |               |          |                           |           |           | Service ATA:32                      |
|                                                            | MOS                                                   | 15-Oct-19 |               |          |                           |           |           |                                     |
|                                                            | HRS                                                   | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)  |                                     |
| WC#: 32.440                                                | AFL                                                   | 3397      |               |          |                           |           |           |                                     |
| PROC. REF: AFMS INSPECTION B12, AMM 32-20-21               |                                                       |           |               |          |                           |           |           | PKG:2,19<br>WO#: N950PC B & C CHECK |
| 320009                                                     | DETAIL INSPECT NOSEWHEEL STEERING JACK SELECTOR VALVE |           |               |          |                           |           |           | Service ATA:32                      |
|                                                            | MOS                                                   | 15-Oct-19 |               |          |                           |           |           |                                     |
|                                                            | HRS                                                   | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)  |                                     |
| WC#: 32.545                                                | AFL                                                   | 3397      |               |          |                           |           |           |                                     |
| PROC. REF: AFMS INSPECTION B12, AMM 32-50-11               |                                                       |           |               |          |                           |           |           | PKG:2,19<br>WO#: N950PC B & C CHECK |
| 320010                                                     | CHECK MAIN GEAR LEG ASSEMBLIES                        |           |               |          |                           |           |           | Service ATA:32                      |
|                                                            | MOS                                                   | 15-Oct-19 |               |          |                           |           |           |                                     |
|                                                            | HRS                                                   | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)  |                                     |
| WC#: 32.420                                                | AFL                                                   | 3397      |               |          |                           |           |           |                                     |
| PROC. REF: AFMS INSPECTION B12, AMM 12-32-00, AMM 32-10-12 |                                                       |           |               |          |                           |           |           | PKG:2,19<br>WO#: N950PC B & C CHECK |
| 320011                                                     | INSPECT MAIN LANDING GEAR SIDE-STAYS                  |           |               |          |                           |           |           | Service ATA:32                      |
|                                                            | MOS                                                   | 15-Oct-19 |               |          |                           |           |           |                                     |
|                                                            | HRS                                                   | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)  |                                     |
| WC#: 32.010                                                | AFL                                                   | 3397      |               |          |                           |           |           |                                     |
| PROC. REF: AFMS INSPECTION B12, AMM 32-10-25, AMM 32-10-25 |                                                       |           |               |          |                           |           |           | PKG:2,19<br>WO#: N950PC B & C CHECK |
| 320012                                                     | CHECK MAIN LANDING GEAR TORQUE LINKS                  |           |               |          |                           |           |           | Service ATA:32                      |
|                                                            | MOS                                                   | 15-Oct-19 |               |          |                           |           |           |                                     |
|                                                            | HRS                                                   | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)  |                                     |
| WC#: 32.015                                                | AFL                                                   | 3397      |               |          |                           |           |           |                                     |
| PROC. REF: AFMS INSPECTION B12, AMM 32-10-12               |                                                       |           |               |          |                           |           |           | PKG:2,19<br>WO#: N950PC B & C CHECK |
| 320013                                                     | INSPECT MAIN LANDING GEAR DOORS                       |           |               |          |                           |           |           | Service ATA:32                      |
|                                                            | MOS                                                   | 15-Oct-19 |               |          |                           |           |           |                                     |
|                                                            | HRS                                                   | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)  |                                     |
| WC#: 32.460                                                | AFL                                                   | 3397      |               |          |                           |           |           |                                     |
| PROC. REF: AFMS INSPECTION B12                             |                                                       |           |               |          |                           |           |           | PKG:2,19<br>WO#: N950PC B & C CHECK |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                      | Unit                                                        | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition                         |
|----------------------------------------------|-------------------------------------------------------------|-----------|-----------------|----------|---------------------------|-----------|---------------|-------------------------------------|
| ATA 32 - LANDING GEAR                        |                                                             |           |                 |          |                           |           |               |                                     |
| 320014                                       | INSPECT/CLEAN MAIN LANDING GEAR DOOR UPLOCK SPRING STRUTS   |           |                 |          |                           |           |               | Service ATA:32                      |
|                                              | MOS                                                         | 15-Oct-19 |                 |          |                           |           |               |                                     |
|                                              | HRS                                                         | 5795.3    | 800 (+40/-10)   |          | 6595.3                    | 6635.3    | 67 (+40)      |                                     |
| WC#: 32.425                                  | AFL                                                         | 3397      |                 |          |                           |           |               |                                     |
| PROC. REF: AFMS INSPECTION B12               |                                                             |           |                 |          |                           |           |               | PKG:2,19<br>WO#: N950PC B & C CHECK |
| 320015                                       | INSPECT REVERSING VALVES AND OPERATING MECHANISMS           |           |                 |          |                           |           |               | Service ATA:32                      |
|                                              | MOS                                                         | 15-Oct-19 |                 |          |                           |           |               |                                     |
|                                              | HRS                                                         | 5795.3    | 800 (+40/-10)   |          | 6595.3                    | 6635.3    | 67 (+40)      |                                     |
| WC#: 32.445                                  | AFL                                                         | 3397      |                 |          |                           |           |               |                                     |
| PROC. REF: AFMS INSPECTION B12               |                                                             |           |                 |          |                           |           |               | PKG:2,19<br>WO#: N950PC B & C CHECK |
| 320016                                       | CHECK STEERING SYSTEM CABLES AND CHAINS                     |           |                 |          |                           |           |               | Service ATA:32                      |
|                                              | MOS                                                         | 06-May-15 |                 |          |                           |           |               |                                     |
|                                              | HRS                                                         | 5125.6    | 1600 (+50/-50)  |          | 6725.6                    | 6775.6    | 197.3 (+50)   |                                     |
| WC#: 32.475                                  | AFL                                                         | 2873      |                 |          |                           |           |               |                                     |
| PROC. REF: AFMS INSPECTION C4, AMM 32-50-00  |                                                             |           |                 |          |                           |           |               | PKG:3,23<br>WO#: N950PC B & C CHECK |
| 320017                                       | CHECK NOSE LANDING GEAR RETRACTION SPRING STRUT             |           |                 |          |                           |           |               | Service ATA:32                      |
|                                              | MOS                                                         | 06-May-15 |                 |          |                           |           |               |                                     |
|                                              | HRS                                                         | 5125.6    | 1600 (+50/-50)  |          | 6725.6                    | 6775.6    | 197.3 (+50)   |                                     |
| WC#: 32.180                                  | AFL                                                         | 2873      |                 |          |                           |           |               |                                     |
| PROC. REF: AFMS INSPECTION C12, AMM 32-20-21 |                                                             |           |                 |          |                           |           |               | PKG:3,31<br>WO#: N950PC B & C CHECK |
| 320018                                       | CHECK NOSEWHEEL STEERING SYSTEM SPRING STRUT BREAK-OUT LOAD |           |                 |          |                           |           |               | Service ATA:32                      |
|                                              | MOS                                                         | 06-May-15 |                 |          |                           |           |               |                                     |
|                                              | HRS                                                         | 5125.6    | 1600 (+50/-50)  |          | 6725.6                    | 6775.6    | 197.3 (+50)   |                                     |
| WC#: 32.350                                  | AFL                                                         | 2873      |                 |          |                           |           |               |                                     |
| PROC. REF: AFMS INSPECTION C12               |                                                             |           |                 |          |                           |           |               | PKG:3,31<br>WO#: N950PC B & C CHECK |
| 320019                                       | INSPECT/CLEAN STEERING SYSTEM FILTER ELEMENT                |           |                 |          |                           |           |               | Service ATA:32                      |
|                                              | MOS                                                         | 18-Aug-17 |                 |          |                           |           |               |                                     |
|                                              | HRS                                                         | 5554.6    | 3200 (+150/-50) |          | 8754.6                    | 8904.6    | 2226.3 (+150) |                                     |
| WC#: 32.385                                  | AFL                                                         | 3197      |                 |          |                           |           |               |                                     |
| PROC. REF: AFMS INSPECTION D12, AMM 32-30-22 |                                                             |           |                 |          |                           |           |               | PKG:4,43                            |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                      | Unit                                               | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                           | Disposition    |
|--------------------------------------------------------------|----------------------------------------------------|-----------|-----------------|----------|---------------------------|-----------|-------------------------------------|----------------|
| ATA 32 - LANDING GEAR                                        |                                                    |           |                 |          |                           |           |                                     |                |
| 320020                                                       | CLEAN FILTERS, HYDRAULIC SUPPLY (4 OFF)            |           |                 |          |                           |           |                                     | Service ATA:32 |
|                                                              | MOS                                                | 18-Aug-17 |                 |          |                           |           |                                     |                |
|                                                              | HRS                                                | 5554.6    | 3200 (+150/-50) |          | 8754.6                    | 8904.6    | 2226.3 (+150)                       |                |
| WC#: 32.185                                                  | AFL                                                | 3197      |                 |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION D12, AMM 32-30-22                 |                                                    |           |                 |          |                           |           | PKG:4,43                            |                |
| 320021                                                       | CLEAN RESTRICTOR VALVES                            |           |                 |          |                           |           |                                     | Service ATA:32 |
|                                                              | MOS                                                | 18-Aug-17 |                 |          |                           |           |                                     |                |
|                                                              | HRS                                                | 5554.6    | 3200 (+150/-50) |          | 8754.6                    | 8904.6    | 2226.3 (+150)                       |                |
| WC#: 32.145                                                  | AFL                                                | 3197      |                 |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION D12, AMM 32-30-01                 |                                                    |           |                 |          |                           |           | PKG:4,43                            |                |
| 320022                                                       | CHECK BRAKE MASTER CYLINDERS                       |           |                 |          |                           |           |                                     | Service ATA:32 |
|                                                              | MOS                                                | 15-Oct-19 |                 |          |                           |           |                                     |                |
|                                                              | HRS                                                | 5795.3    | 800 (+40/-10)   |          | 6595.3                    | 6635.3    | 67 (+40)                            |                |
| WC#: 32.465                                                  | AFL                                                | 3397      |                 |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION B4, AMM 32-40-00                  |                                                    |           |                 |          |                           |           | PKG:2,11<br>WO#: N950PC B & C CHECK |                |
| 320023                                                       | CHECK BRAKE HOSES TO MASTER CYLINDERS              |           |                 |          |                           |           |                                     | Service ATA:32 |
|                                                              | MOS                                                | 06-May-15 |                 |          |                           |           |                                     |                |
|                                                              | HRS                                                | 5125.6    | 1600 (+50/-50)  |          | 6725.6                    | 6775.6    | 197.3 (+50)                         |                |
| WC#: 32.455                                                  | AFL                                                | 2873      |                 |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION C4                                |                                                    |           |                 |          |                           |           | PKG:3,23<br>WO#: N950PC B & C CHECK |                |
| 320024                                                       | REMOVE/INSPECT AXLE/MAXARET/MODULATOR/PLUNGER TUBE |           |                 |          |                           |           |                                     | Service ATA:32 |
|                                                              | MOS                                                | 06-May-15 |                 |          |                           |           |                                     |                |
|                                                              | HRS                                                | 5125.6    | 1600 (+50/-50)  |          | 6725.6                    | 6775.6    | 197.3 (+50)                         |                |
| WC#: 32.375                                                  | AFL                                                | 2873      |                 |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION C12, AMM 32-40-101, AMM 32-40-101 |                                                    |           |                 |          |                           |           | PKG:3,31<br>WO#: N950PC B & C CHECK |                |
| 320027                                                       | VISUALLY INSPECT NOSE-WHEEL STEERING ON/OFF VALVE  |           |                 |          |                           |           |                                     | Service ATA:32 |
|                                                              | MOS                                                | 15-Oct-19 | 48 (+2m/-2m)    |          | 15-Oct-23                 | 15-Dec-23 | 257 d (+61)                         |                |
|                                                              | HRS                                                | 5795.3    |                 |          |                           |           |                                     |                |
| WC#: 32.350                                                  | AFL                                                | 3397      |                 |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION G                                 |                                                    |           |                 |          |                           |           | PKG:7<br>WO#: N950PC 48 MONTH INSP  |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                | Unit                                                         | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C           | Max Limit | Remaining   | Disposition    |
|--------------------------------------------------------|--------------------------------------------------------------|-----------|----------------|----------|-------------------------------------|-----------|-------------|----------------|
| ATA 32 - LANDING GEAR                                  |                                                              |           |                |          |                                     |           |             |                |
| 320028                                                 | INSPECT/NDT MAIN LANDING GEAR FAIRING STRUT                  |           |                |          |                                     |           |             | Service ATA:32 |
|                                                        | MOS                                                          | 25-Jun-20 | 48 (+3m)       |          | 25-Jun-24                           | 25-Sep-24 | 511 d (+92) |                |
|                                                        | HRS                                                          | 5801      |                |          |                                     |           |             |                |
| WC#: 32.035                                            | AFL                                                          | 3399      |                |          |                                     |           |             |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS, NTM 32-10-103  |                                                              |           |                |          | WO#: N950PC 48 MONTH INSP           |           |             |                |
| 320029                                                 | CHECK NOSE LANDING GEAR DRAG STAY                            |           |                |          |                                     |           |             | Service ATA:32 |
|                                                        | MOS/MSC                                                      | 29-Jan-22 | A/R            |          |                                     |           |             |                |
|                                                        | HRS                                                          | 6264.3    |                |          |                                     |           |             |                |
| WC#: 32.070                                            | AFL                                                          | 3756      |                |          |                                     |           |             |                |
| PROC. REF: AFMS OUT OF PHASE INSPECTIONS, AMM 32-20-21 |                                                              |           |                |          |                                     |           |             |                |
| 320032 <sup>U</sup>                                    | SERVICE TIRES                                                |           |                |          |                                     |           |             | Service ATA:32 |
|                                                        | MOS/MSC                                                      | 06-Jan-23 | A/R            |          |                                     |           |             |                |
|                                                        | HRS                                                          | 6519.5    |                |          |                                     |           |             |                |
|                                                        | AFL                                                          | 3923      |                |          |                                     |           |             |                |
|                                                        |                                                              |           |                |          | PKG:68<br>WO#: N950PC KLM JAN 2023  |           |             |                |
| 320033                                                 | DETAIL INSPECT MAIN GEAR RETRACTION ACTUATOR                 |           |                |          |                                     |           |             | Service ATA:32 |
|                                                        | MOS                                                          | 15-Oct-19 |                |          |                                     |           |             |                |
|                                                        | HRS                                                          | 5795.3    | 800 (+40/-10)  |          | 6595.3                              | 6635.3    | 67 (+40)    |                |
| WC#: 32.095                                            | AFL                                                          | 3397      |                |          |                                     |           |             |                |
| PROC. REF: AFMS INSPECTION B12                         |                                                              |           |                |          | PKG:2,19<br>WO#: N950PC B & C CHECK |           |             |                |
| 320034                                                 | INSPECT MAIN LANDING GEAR PLUNGER TUBE/AXLE JOINT            |           |                |          |                                     |           |             | Service ATA:32 |
|                                                        | MOS                                                          | 15-Oct-19 |                |          |                                     |           |             |                |
|                                                        | HRS                                                          | 5795.3    | 800 (+40/-10)  |          | 6595.3                              | 6635.3    | 67 (+40)    |                |
| WC#: 32.510                                            | AFL                                                          | 3397      |                |          |                                     |           |             |                |
| PROC. REF: AFMS INSPECTION B12                         |                                                              |           |                |          | PKG:2,19<br>WO#: N950PC B & C CHECK |           |             |                |
| 320035                                                 | INSPECT MAIN LANDING GEAR MAIN LEG ASSEMBLY RETRACTION LEVER |           |                |          |                                     |           |             | Service ATA:32 |
|                                                        | MOS                                                          | 06-May-15 |                |          |                                     |           |             |                |
|                                                        | HRS                                                          | 5125.6    | 1600 (+50/-50) |          | 6725.6                              | 6775.6    | 197.3 (+50) |                |
| WC#: 32.520                                            | AFL                                                          | 2873      |                |          |                                     |           |             |                |
| PROC. REF: AFMS INSPECTION C12                         |                                                              |           |                |          | PKG:3,31<br>WO#: N950PC B & C CHECK |           |             |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                    | Unit                                                            | C/W       | Interval       | TSX/Adj.        | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition                         |
|------------------------------------------------------------|-----------------------------------------------------------------|-----------|----------------|-----------------|---------------------------|-----------|-------------|-------------------------------------|
| ATA 32 - LANDING GEAR                                      |                                                                 |           |                |                 |                           |           |             |                                     |
| 320036                                                     | INSPECT MAIN LANDING GEAR SIDESTAY ASSEMBLY LOCK MECHANISM LINK |           |                |                 |                           |           |             | Service ATA:32                      |
|                                                            | MOS                                                             | 06-May-15 |                |                 |                           |           |             |                                     |
|                                                            | HRS                                                             | 5125.6    | 1600 (+50/-50) |                 | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 32.530                                                | AFL                                                             | 2873      |                |                 |                           |           |             |                                     |
| PROC. REF: AFMS INSPECTION C12                             |                                                                 |           |                |                 |                           |           |             | PKG:3,31<br>WO#: N950PC B & C CHECK |
| 320037                                                     | CHECK NOSE LEG ASSEMBLY TORQUE LINKS                            |           |                |                 |                           |           |             | Service ATA:32                      |
|                                                            | MOS                                                             | 15-Oct-19 |                |                 |                           |           |             |                                     |
|                                                            | HRS                                                             | 5795.3    | 800 (+40/-10)  |                 | 6595.3                    | 6635.3    | 67 (+40)    |                                     |
| WC#: 32.540                                                | AFL                                                             | 3397      |                |                 |                           |           |             |                                     |
| PROC. REF: AFMS INSPECTION B12, AMM 32-20-12               |                                                                 |           |                |                 |                           |           |             | PKG:2,19<br>WO#: N950PC B & C CHECK |
| 320038                                                     | LUBRICATE MAIN LANDING GEAR SIDESTAY SHIMS                      |           |                |                 |                           |           |             | Service ATA:32                      |
|                                                            | MOS/MSC                                                         | 10-Oct-22 | A/R            |                 |                           |           |             |                                     |
|                                                            | HRS                                                             | 6446.4    |                |                 |                           |           |             |                                     |
| WC#: 32.570                                                | AFL                                                             | 3873      |                |                 |                           |           |             |                                     |
| PROC. REF: AFMS OUT OF PHASE INSPECTIONS, AFMS LUBRICATION |                                                                 |           |                |                 |                           |           |             |                                     |
| 321001                                                     | LEFT MAIN LEG                                                   |           |                |                 |                           |           |             | Component ATA:32                    |
| PN:140-810044-17                                           | MOS                                                             | 25-Jun-20 | 144            | TSO 1           | 25-May-32                 |           | 3402 d      | OVERHAUL                            |
| SN:DHL/DH1579                                              | HRS                                                             | 5801      |                | TSO 0           |                           |           |             |                                     |
| WC#: 32.020                                                | AFL                                                             | 3399      | 5000           | TSN 6137, TSO 0 | 8399                      |           | 4470        |                                     |
| PROC. REF: AMM 32-10-12                                    |                                                                 |           |                |                 |                           |           |             |                                     |
| 321002                                                     | RIGHT MAIN LEG                                                  |           |                |                 |                           |           |             | Component ATA:32                    |
| PN:140-810044-18                                           | MOS                                                             | 25-Jun-20 | 144            | TSO 1           | 25-May-32                 |           | 3402 d      | OVERHAUL                            |
| SN:SAM/DHB/8S/014                                          | HRS                                                             | 5801      |                | TSO 0           |                           |           |             |                                     |
| WC#: 32.020                                                | AFL                                                             | 3399      | 5000           | TSN 8110, TSO 0 | 8399                      |           | 4470        |                                     |
| PROC. REF: AMM 32-10-12                                    |                                                                 |           |                |                 |                           |           |             |                                     |
| 321013                                                     | LEFT SIDESTAY                                                   |           |                |                 |                           |           |             | Component ATA:32                    |
| PN:140-810043-11                                           | MOS                                                             | 25-Jun-20 | 144            | TSO 4           | 25-Feb-32                 |           | 3312 d      | OVERHAUL                            |
| SN:SAM/DHB/8SSP/352                                        | HRS                                                             | 5801      |                | TSO 0           |                           |           |             |                                     |
| WC#: 32.025                                                | AFL                                                             | 3399      | 5000           | TSN 2525, TSO 0 | 8399                      |           | 4470        |                                     |
| PROC. REF: AMM 32-10-25                                    |                                                                 |           |                |                 |                           |           |             |                                     |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                             | Unit                                       | C/W       | Interval | TSX/Adj.        | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------------------------------------------|--------------------------------------------|-----------|----------|-----------------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR                               |                                            |           |          |                 |                           |           |           |                  |
| 321014                                              | RIGHT SIDESTAY                             |           |          |                 |                           |           |           | Component ATA:32 |
| PN:140-810043-12                                    | MOS                                        | 25-Jun-20 | 144      | TSO 13          | 25-May-31                 |           | 3036 d    | OVERHAUL         |
| SN:SAM/DHB/8SSS/132                                 | HRS                                        | 5801      |          | TSO 0           |                           |           |           |                  |
| WC#: 32.030                                         | AFL                                        | 3399      | 5000     | TSN 8863, TSO 0 | 8399                      |           | 4470      |                  |
| PROC. REF: AMM 32-10-25                             |                                            |           |          |                 |                           |           |           |                  |
| 321015                                              | LEFT MAIN LANDING GEAR SIDESTAY UPPER ARM  |           |          |                 |                           |           |           | Component ATA:32 |
| PN:NP-8UM71-3                                       | MOS                                        | 25-Jun-20 |          | TSN 0           |                           |           |           | LIFE LIMIT       |
| SN:AV8-00036                                        | HRS                                        | 5801      |          | TSN 0           |                           |           |           |                  |
| WC#: 32.025                                         | AFL                                        | 3399      | 10000    | TSN 0           | 13399                     |           | 9470      |                  |
| MOC: - REPEAT REF 321015<br>PROC. REF: AMM 32-10-25 |                                            |           |          |                 |                           |           |           |                  |
| 321016                                              | RIGHT MAIN LANDING GEAR SIDESTAY UPPER ARM |           |          |                 |                           |           |           | Component ATA:32 |
| PN:25-8UM29-4                                       | MOS                                        | 09-Mar-08 |          |                 |                           |           |           | LIFE LIMIT       |
| SN:UNKNOWN                                          | HRS                                        | 3656.4    |          |                 |                           |           |           |                  |
| WC#: 32.030                                         | AFL                                        | 2050      | 10000    | TSN 2050        | 10000                     |           | 6071      |                  |
| MOC: - REPEAT REF 321016<br>PROC. REF: AMM 32-10-25 |                                            |           |          |                 |                           |           |           |                  |
| 321017                                              | LEFT MAIN LANDING GEAR SIDESTAY LOWER ARM  |           |          |                 |                           |           |           | Component ATA:32 |
| PN:NP-UM1944-5                                      | MOS                                        | 25-Jun-20 |          | TSN 0           |                           |           |           | LIFE LIMIT       |
| SN:AV8-00013                                        | HRS                                        | 5801      |          | TSN 0           |                           |           |           |                  |
| WC#: 32.025                                         | AFL                                        | 3399      | 12000    | TSN 0           | 15399                     |           | 11470     |                  |
| PROC. REF: AMM 32-10-25                             |                                            |           |          |                 |                           |           |           |                  |
| 321018                                              | RIGHT MAIN LANDING GEAR SIDESTAY LOWER ARM |           |          |                 |                           |           |           | Component ATA:32 |
| PN:25-8UM31                                         | MOS                                        | 09-Mar-08 |          |                 |                           |           |           | LIFE LIMIT       |
| SN:UNKNOWN                                          | HRS                                        | 3656.4    |          | TSN 3656.4      |                           |           |           |                  |
| WC#: 32.030                                         | AFL                                        | 2050      | 12000    | TSN 2050        | 12000                     |           | 8071      |                  |
| PROC. REF: AMM 32-10-25                             |                                            |           |          |                 |                           |           |           |                  |
| 321050                                              | LEFT MAIN LANDING GEAR UPPER CASING        |           |          |                 |                           |           |           | Component ATA:32 |
| PN:25-8UM169-5                                      | MOS                                        | 25-Jun-20 |          |                 |                           |           |           | LIFE LIMIT       |
| SN:BB503                                            | HRS                                        | 5801      |          |                 |                           |           |           |                  |
| WC#: 32.390                                         | AFL                                        | 3399      | 24000    | TSN 6777        | 20622                     |           | 16693     |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                 | Unit                                          | C/W       | Interval | TSX/Adj.        | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------|-----------------------------------------------|-----------|----------|-----------------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR   |                                               |           |          |                 |                           |           |           |                  |
| 321051                  | RIGHT MAIN LANDING GEAR UPPER CASING          |           |          |                 |                           |           |           | Component ATA:32 |
| PN:25-8UM69-6           | MOS                                           | 25-Jun-20 |          |                 |                           |           |           | LIFE LIMIT       |
| SN:SAM8402              | HRS                                           | 5801      |          |                 |                           |           |           |                  |
| WC#: 32.390             | AFL                                           | 3399      | 24000    | TSN 4581        | 22818                     |           | 18889     |                  |
| 321061                  | LEFT MAIN LANDING GEAR JACK PIVOT             |           |          |                 |                           |           |           | Component ATA:32 |
| PN:25UM1333-3           | MOS/MSC                                       | 25-Jun-20 | O/C      | TSO 0           |                           |           |           |                  |
| SN:SAM352               | HRS                                           | 5801      |          | TSO 0           |                           |           |           |                  |
| WC#: 32.040             | AFL                                           | 3399      |          | TSN 2525, TSO 0 |                           |           |           |                  |
| 321062                  | RIGHT MAIN LANDING GEAR JACK PIVOT            |           |          |                 |                           |           |           | Component ATA:32 |
| PN:25UM1229A            | MOS                                           | 30-May-96 |          |                 |                           |           |           | LIFE LIMIT       |
| SN:UNKNOWN              | HRS                                           | 0         |          |                 |                           |           |           |                  |
| WC#: 32.040             | AFL                                           | 0         | 4000     | TSN 0           | 4000                      |           | 71        |                  |
| WO#: N950PC B & C CHECK |                                               |           |          |                 |                           |           |           |                  |
| 321065                  | LEFT MAIN LANDING GEAR UPPER TORQUE LINK PIN  |           |          |                 |                           |           |           | Component ATA:32 |
| PN:25-8UM15-1A          | MOS                                           | 30-May-96 |          |                 |                           |           |           | LIFE LIMIT       |
| SN:UNKNOWN              | HRS                                           | 0         |          | TSN 0           |                           |           |           |                  |
| WC#: 32.400             | AFL                                           | 0         | 20000    | TSN 0           | 20000                     |           | 16071     |                  |
| 321066                  | RIGHT MAIN LANDING GEAR UPPER TORQUE LINK PIN |           |          |                 |                           |           |           | Component ATA:32 |
| PN:25-8UM15-1A          | MOS                                           | 30-May-96 |          |                 |                           |           |           | LIFE LIMIT       |
| SN:UNKNOWN              | HRS                                           | 0         |          | TSN 0           |                           |           |           |                  |
| WC#: 32.400             | AFL                                           | 0         | 20000    | TSN 0           | 20000                     |           | 16071     |                  |
| 321067                  | LEFT MAIN LANDING GEAR LOWER TORQUE LINK PIN  |           |          |                 |                           |           |           | Component ATA:32 |
| PN:25-8UM15-1A          | MOS                                           | 30-May-96 |          |                 |                           |           |           | LIFE LIMIT       |
| SN:UNKNOWN              | HRS                                           | 0         |          | TSN 0           |                           |           |           |                  |
| WC#: 32.495             | AFL                                           | 0         | 20000    | TSN 0           | 20000                     |           | 16071     |                  |
| 321068                  | RIGHT MAIN LANDING GEAR LOWER TORQUE LINK PIN |           |          |                 |                           |           |           | Component ATA:32 |
| PN:25-8UM15-1A          | MOS                                           | 30-May-96 |          |                 |                           |           |           | LIFE LIMIT       |
| SN:UNKNOWN              | HRS                                           | 0         |          | TSN 0           |                           |           |           |                  |
| WC#: 32.495             | AFL                                           | 0         | 20000    | TSN 0           | 20000                     |           | 16071     |                  |
| 321071                  | LEFT MAIN LANDING GEAR JACK DISTANCE PIN      |           |          |                 |                           |           |           | Component ATA:32 |
| PN:NPFA25UM423-1        | MOS                                           | 25-Jun-20 |          | TSN 0           |                           |           |           | LIFE LIMIT       |
| SN:AV8-00043            | HRS                                           | 5801      |          | TSN 0           |                           |           |           |                  |
| WC#: 32.045             | AFL                                           | 3399      | 24000    | TSN 0           | 27399                     |           | 23470     |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN               | Unit                                      | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------------|-------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR |                                           |           |          |          |                           |           |           |                  |
| 321072                | RIGHT MAIN LANDING GEAR JACK DISTANCE PIN |           |          |          |                           |           |           | Component ATA:32 |
| PN:25UM423            | MOS                                       | 30-May-96 |          |          |                           |           |           | LIFE LIMIT       |
| SN:UNKNOWN            | HRS                                       | 0         |          |          |                           |           |           |                  |
| WC#: 32.045           | AFL                                       | 0         | 24000    | TSN 0    | 24000                     |           | 20071     |                  |
| 321075                | LEFT MAIN LANDING GEAR PLUNGER TUBE       |           |          |          |                           |           |           | Component ATA:32 |
| PN:140-810016-1       | MOS                                       | 25-Jun-20 |          |          |                           |           |           | LIFE LIMIT       |
| SN:BB210L             | HRS                                       | 5801      |          |          |                           |           |           |                  |
| WC#: 32.410           | AFL                                       | 3399      | 17000    | TSN 6137 | 14262                     |           | 10333     |                  |
| 321076                | RIGHT MAIN LANDING GEAR PLUNGER TUBE      |           |          |          |                           |           |           | Component ATA:32 |
| PN:140-810016-2       | MOS                                       | 25-Jun-20 |          |          |                           |           |           | LIFE LIMIT       |
| SN:DHL467/W11462      | HRS                                       | 5801      |          |          |                           |           |           |                  |
| WC#: 32.410           | AFL                                       | 3399      | 17000    | TSN 8127 | 12272                     |           | 8343      |                  |
| 321081                | LEFT MAIN LANDING GEAR UPPER TORQUE LINK  |           |          |          |                           |           |           | Component ATA:32 |
| PN:25-9UM9-3          | MOS                                       | 25-Jun-20 |          |          |                           |           |           | LIFE LIMIT       |
| SN:GA-8169-01         | HRS                                       | 5801      |          |          |                           |           |           |                  |
| WC#: 32.550           | AFL                                       | 3399      | 20000    | TSN 6137 | 17262                     |           | 13333     |                  |
| 321082                | RIGHT MAIN LANDING GEAR UPPER TORQUE LINK |           |          |          |                           |           |           | Component ATA:32 |
| PN:25-9UM9-3          | MOS                                       | 25-Jun-20 |          |          |                           |           |           | LIFE LIMIT       |
| SN:B4867              | HRS                                       | 5801      |          |          |                           |           |           |                  |
| WC#: 32.550           | AFL                                       | 3399      | 20000    | TSN 8110 | 15289                     |           | 11360     |                  |
| 321083                | LEFT MAIN LANDING GEAR LOWER TORQUE LINK  |           |          |          |                           |           |           | Component ATA:32 |
| PN:NP-9UM11-3         | MOS                                       | 25-Jun-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN:AV8-0008           | HRS                                       | 5801      |          | TSN 0    |                           |           |           |                  |
| WC#: 32.555           | AFL                                       | 3399      | 20000    | TSN 0    | 23399                     |           | 19470     |                  |
| 321084                | RIGHT MAIN LANDING GEAR LOWER TORQUE LINK |           |          |          |                           |           |           | Component ATA:32 |
| PN:25-9UM11-3         | MOS                                       | 25-Jun-20 |          |          |                           |           |           | LIFE LIMIT       |
| SN:108DA              | HRS                                       | 5801      |          |          |                           |           |           |                  |
| WC#: 32.555           | AFL                                       | 3399      | 20000    | TSN 8110 | 15289                     |           | 11360     |                  |
| 321087                | LEFT MAIN LANDING GEAR AXLE ASSEMBLY      |           |          |          |                           |           |           | Component ATA:32 |
| PN:PN                 | MOS/MSC                                   | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN            | HRS                                       | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.571           | AFL                                       | 0         |          | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                 | Unit                                       | C/W       | Interval | TSX/Adj.        | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------|--------------------------------------------|-----------|----------|-----------------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR   |                                            |           |          |                 |                           |           |           |                  |
| 321088                  | RIGHT MAIN LANDING GEAR AXLE ASSEMBLY      |           |          |                 |                           |           |           | Component ATA:32 |
| PN:PN                   | MOS/MSC                                    | 30-May-96 | O/C      | TSN 0           |                           |           |           |                  |
| SN:UNKNOWN              | HRS                                        | 0         |          | TSN 0           |                           |           |           |                  |
| WC#: 32.572             | AFL                                        | 0         |          | TSN 0           |                           |           |           |                  |
| 322001                  | NOSE LEG ASSEMBLY                          |           |          |                 |                           |           |           | Component ATA:32 |
| PN:25-9UN1-407A         | MOS                                        | 25-Jun-20 | 144      | TSO 5           | 25-Jan-32                 |           | 3281 d    | OVERHAUL         |
| SN:SAM/DHB/9N/161       | HRS                                        | 5801      |          | TSO 0           |                           |           |           |                  |
| WC#: 32.050             | AFL                                        | 3399      | 5000     | TSN 8466, TSO 0 | 8399                      |           | 4470      |                  |
| PROC. REF: AMM 32-20-12 |                                            |           |          |                 |                           |           |           |                  |
| 322003                  | NOSE LANDING GEAR PIVOT PIN                |           |          |                 |                           |           |           | Component ATA:32 |
| PN:25UN645A             | MOS                                        | 25-Jun-20 |          |                 |                           |           |           | LIFE LIMIT       |
| SN:3039A                | HRS                                        | 5801      |          |                 |                           |           |           |                  |
| WC#: 32.055             | AFL                                        | 3399      | 16000    | TSN 8466        | 10933                     |           | 7004      |                  |
| 322007                  | NOSE LANDING GEAR DRAG STAY                |           |          |                 |                           |           |           | Component ATA:32 |
| PN:25-8UN3-143A         | MOS                                        | 25-Jun-20 | 144      | TSO 20          | 25-Oct-30                 |           | 2824 d    | OVERHAUL         |
| SN:DHL/DH/772           | HRS                                        | 5801      |          | TSO 0           |                           |           |           |                  |
| WC#: 32.070             | AFL                                        | 3399      | 5000     | TSN 6137, TSO 0 | 8399                      |           | 4470      |                  |
| PROC. REF: AMM 32-20-21 |                                            |           |          |                 |                           |           |           |                  |
| 322009                  | NOSE LANDING GEAR JACK LOWER PIVOT PIN     |           |          |                 |                           |           |           | Component ATA:32 |
| PN:25UN597              | MOS                                        | 25-Jun-20 |          |                 |                           |           |           | LIFE LIMIT       |
| SN:SAM1223              | HRS                                        | 5801      |          |                 |                           |           |           |                  |
| WC#: 32.075             | AFL                                        | 3399      | 22000    | TSN 8466        | 16933                     |           | 13004     |                  |
| 322011                  | NOSE LANDING GEAR DRAG STAY BRIDGE CASTING |           |          |                 |                           |           |           | Component ATA:32 |
| PN:25-8UN487-1A         | MOS                                        | 30-May-96 |          |                 |                           |           |           | LIFE LIMIT       |
| SN:UNKNOWN              | HRS                                        | 0         |          |                 |                           |           |           |                  |
| WC#: 32.075             | AFL                                        | 0         | 33000    | TSN 0           | 33000                     |           | 29071     |                  |
| 322015                  | NOSE LANDING GEAR UPPER TORQUE LINK        |           |          |                 |                           |           |           | Component ATA:32 |
| PN:25-8UN267-5          | MOS                                        | 25-Jun-20 |          |                 |                           |           |           | LIFE LIMIT       |
| SN:SAM0804              | HRS                                        | 5801      |          |                 |                           |           |           |                  |
| WC#: 32.080             | AFL                                        | 3399      | 32000    | TSN 8466        | 26933                     |           | 23004     |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                 | Unit                                             | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------|--------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR   |                                                  |           |          |          |                           |           |           |                  |
| 322016                  | NOSE LANDING GEAR LOWER TORQUE LINK              |           |          |          |                           |           |           | Component ATA:32 |
| PN:25-8UN269-3          | MOS                                              | 25-Jun-20 |          |          |                           |           |           | LIFE LIMIT       |
| SN:SAM1904              | HRS                                              | 5801      |          |          |                           |           |           |                  |
| WC#: 32.080             | AFL                                              | 3399      | 32000    | TSN 8466 | 26933                     |           | 23004     |                  |
| 322017                  | NOSE LANDING GEAR DRAG STRUT PICK-UP             |           |          |          |                           |           |           | Component ATA:32 |
| PN:25-8UN265-23         | MOS                                              | 25-Jun-20 |          |          |                           |           |           | LIFE LIMIT       |
| SN:7522-1               | HRS                                              | 5801      |          |          |                           |           |           |                  |
| WC#: 32.560             | AFL                                              | 3399      | 13900    | TSN 8747 | 8552                      |           | 4623      |                  |
| 322025                  | NOSE GEAR MAIN PICK-UP TRUNNION ATTACHMENT BOLTS |           |          |          |                           |           |           | Component ATA:32 |
| PN:A102/28J             | MOS                                              | 25-Jun-20 |          |          |                           |           |           | LIFE LIMIT       |
| SN:UNKNOWN              | HRS                                              | 5801      |          |          |                           |           |           |                  |
| WC#: 32.380             | AFL                                              | 3399      | 10000    | TSN 3565 | 9834                      |           | 5905      |                  |
| 322031                  | NOSE GEAR RADIUS ROD PICK-UP ATTACHMENT BOLTS    |           |          |          |                           |           |           | Component ATA:32 |
| PN:A102/21J             | MOS                                              | 30-May-96 |          |          |                           |           |           | LIFE LIMIT       |
| SN:UNKNOWN              | HRS                                              | 0         |          |          |                           |           |           |                  |
| WC#: 32.085             | AFL                                              | 0         | 10000    | TSN 0    | 10000                     |           | 6071      |                  |
| 322045                  | NOSE LANDING GEAR PLUNGER TUBE                   |           |          |          |                           |           |           | Component ATA:32 |
| PN:25UN649              | MOS                                              | 25-Jun-20 |          |          |                           |           |           | LIFE LIMIT       |
| SN:J001901-000/W11953   | HRS                                              | 5801      |          |          |                           |           |           |                  |
| WC#: 32.075             | AFL                                              | 3399      | 20000    | TSN 1706 | 21693                     |           | 17764     |                  |
| 323001                  | NOSE LANDING GEAR RETRACTION JACK                |           |          |          |                           |           |           | Component ATA:32 |
| PN:AIR45404-1           | MOS                                              | 06-May-15 |          | TSO 0    |                           |           |           | OVERHAUL         |
| SN:APB052019            | HRS                                              | 5125.6    |          | TSO 0    |                           |           |           |                  |
| WC#: 32.090             | AFL                                              | 2873      | 5000     | TSO 0    | 7873                      |           | 3944      |                  |
| PROC. REF: AMM 32-30-28 |                                                  |           |          |          |                           |           |           |                  |
| 323007                  | LEFT MAIN LANDING GEAR RETRACTION JACK           |           |          |          |                           |           |           | Component ATA:32 |
| PN:AIR48502-6           | MOS                                              | 06-May-10 |          | TSO 0    |                           |           |           | OVERHAUL         |
| SN:LK8707954            | HRS                                              | 4187.8    |          | TSO 0    |                           |           |           |                  |
| WC#: 32.100             | AFL                                              | 2339      | 5000     | TSO 0    | 7339                      |           | 3410      |                  |
| PROC. REF: AMM 32-30-27 |                                                  |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                 | Unit                                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------|-----------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR   |                                         |           |          |          |                           |           |           |                  |
| 323008                  | RIGHT MAIN LANDING GEAR RETRACTION JACK |           |          |          |                           |           |           | Component ATA:32 |
| PN:AIR48503-6           | MOS                                     | 06-May-10 |          | TSO 0    |                           |           |           | OVERHAUL         |
| SN:LK9100772            | HRS                                     | 4187.8    |          | TSO 0    |                           |           |           |                  |
| WC#: 32.100             | AFL                                     | 2339      | 5000     | TSO 0    | 7339                      |           | 3410      |                  |
| PROC. REF: AMM 32-30-27 |                                         |           |          |          |                           |           |           |                  |
| 323019                  | LEFT MAIN LANDING GEAR DOOR JACK        |           |          |          |                           |           |           | Component ATA:32 |
| PN:AIR48485-3           | MOS                                     | 30-May-96 |          |          |                           |           |           | OVERHAUL         |
| SN:APB960068            | HRS                                     | 0         |          |          |                           |           |           |                  |
| WC#: 32.105             | AFL                                     | 0         | 5000     | TSN 0    | 5000                      |           | 1071      |                  |
| 323020                  | RIGHT MAIN LANDING GEAR DOOR JACK       |           |          |          |                           |           |           | Component ATA:32 |
| PN:AIR48484-3           | MOS                                     | 30-May-96 |          |          |                           |           |           | OVERHAUL         |
| SN:APB960592            | HRS                                     | 0         |          |          |                           |           |           |                  |
| WC#: 32.105             | AFL                                     | 0         | 5000     | TSN 0    | 5000                      |           | 1071      |                  |
| 323031                  | LEFT SEQUENCE VALVE                     |           |          |          |                           |           |           | Component ATA:32 |
| PN:AIR48540/1           | MOS                                     | 25-Jun-20 | 144      | TSO 6    | 25-Dec-31                 |           | 3250 d    | OVERHAUL         |
| SN:LK0461               | HRS                                     | 5801      |          | TSO 0    |                           |           |           |                  |
| WC#: 32.110             | AFL                                     | 3399      | 5000     | TSO 0    | 8399                      |           | 4470      |                  |
| PROC. REF: AMM 32-30-41 |                                         |           |          |          |                           |           |           |                  |
| 323032                  | RIGHT SEQUENCE VALVE                    |           |          |          |                           |           |           | Component ATA:32 |
| PN:AIR48540/1           | MOS                                     | 25-Jun-20 | 144      | TSO 7    | 25-Nov-31                 |           | 3220 d    | OVERHAUL         |
| SN:LK8903009            | HRS                                     | 5801      |          | TSO 0    |                           |           |           |                  |
| WC#: 32.110             | AFL                                     | 3399      | 5000     | TSO 0    | 8399                      |           | 4470      |                  |
| PROC. REF: AMM 32-30-41 |                                         |           |          |          |                           |           |           |                  |
| 323043                  | LEFT REVERSING VALVE                    |           |          |          |                           |           |           | Component ATA:32 |
| PN:AIR48542-1-3         | MOS                                     | 04-Jan-13 | 144      | TSO 0    | 04-Jan-25                 |           | 704 d     | OVERHAUL         |
| SN:LK8401989            | HRS                                     | 4858      |          | TSO 0    |                           |           |           |                  |
| WC#: 32.115             | AFL                                     | 2719      | 5000     | TSO 0    | 7719                      |           | 3790      |                  |
| PROC. REF: AMM 32-30-31 |                                         |           |          |          |                           |           |           |                  |
| 323044                  | RIGHT REVERSING VALVE                   |           |          |          |                           |           |           | Component ATA:32 |
| PN:AIR48543/1           | MOS                                     | 25-Jun-20 | 144      | TSO 2    | 25-Apr-32                 |           | 3372 d    | OVERHAUL         |
| SN:APB073343            | HRS                                     | 5801      |          | TSO 0    |                           |           |           |                  |
| WC#: 32.115             | AFL                                     | 3399      | 5000     | TSO 0    | 8399                      |           | 4470      |                  |
| PROC. REF: AMM 32-30-31 |                                         |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN               | Unit                                           | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------------|------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR |                                                |           |          |          |                           |           |           |                  |
| 323079                | LEFT MAIN LANDING GEAR EXTEND NONRETURN VALVE  |           |          |          |                           |           |           | Component ATA:32 |
| PN: AIR48026-0        | MOS/MSC                                        | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN: APB960085         | HRS                                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.120           | AFL                                            | 0         |          |          |                           |           |           |                  |
| 323080                | RIGHT MAIN LANDING GEAR EXTEND NONRETURN VALVE |           |          |          |                           |           |           | Component ATA:32 |
| PN: AIR48026-0        | MOS/MSC                                        | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN: APB960095         | HRS                                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.120           | AFL                                            | 0         |          |          |                           |           |           |                  |
| 323090                | FRAME 15A NON-RETURN VALVE                     |           |          |          |                           |           |           | Component ATA:32 |
| PN: PN                | MOS/MSC                                        | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN: UNKNOWN           | HRS                                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.505           | AFL                                            | 0         |          | TSN 0    |                           |           |           |                  |
| 323091                | MAIN LANDING GEAR CENTER NONRETURN VALVE       |           |          |          |                           |           |           | Component ATA:32 |
| PN: AIR48026-0        | MOS/MSC                                        | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN: APB960091         | HRS                                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.125           | AFL                                            | 0         |          |          |                           |           |           |                  |
| 323097                | FRAME 14 NON-RETURN VALVE                      |           |          |          |                           |           |           | Component ATA:32 |
| PN: AIR45420-0        | MOS/MSC                                        | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN: APB952244         | HRS                                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.130           | AFL                                            | 0         |          |          |                           |           |           |                  |
| 323098                | FRAME 14A NONRETURN VALVE                      |           |          |          |                           |           |           | Component ATA:32 |
| PN: AIR45420-0        | MOS/MSC                                        | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN: APB952239         | HRS                                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.130           | AFL                                            | 0         |          |          |                           |           |           |                  |
| 323099                | FRAME 15A NONRETURN VALVE                      |           |          |          |                           |           |           | Component ATA:32 |
| PN: AIR45420-0        | MOS/MSC                                        | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN: APB952228         | HRS                                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.130           | AFL                                            | 0         |          |          |                           |           |           |                  |
| 323103                | LANDING GEAR SELECTOR/DUMP VALVE               |           |          |          |                           |           |           | Component ATA:32 |
| PN: AIR45406-1        | MOS/MSC                                        | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN: LK9205048         | HRS                                            | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.135           | AFL                                            | 0         |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR     |                                                       |           |          |          |                           |           |           |                  |
| 323115                    | LEFT MAIN LANDING GEAR RETRACT JACK RESTRICTOR VALVE  |           |          |          |                           |           |           | Component ATA:32 |
| PN: AIR45444-0-1          | MOS/MSC                                               | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN: APB952013             | HRS                                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.140               | AFL                                                   | 0         |          |          |                           |           |           |                  |
| 323116                    | RIGHT MAIN LANDING GEAR RETRACT JACK RESTRICTOR VALVE |           |          |          |                           |           |           | Component ATA:32 |
| PN: AIR45444-0-1          | MOS/MSC                                               | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN: APB952006             | HRS                                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.140               | AFL                                                   | 0         |          |          |                           |           |           |                  |
| 323139                    | LEFT MAIN LANDING GEAR JACK PIVOT BOLT                |           |          |          |                           |           |           | Component ATA:32 |
| PN: 25UM153A              | MOS                                                   | 25-Jun-20 |          |          |                           |           |           | LIFE LIMIT       |
| SN: SAM352                | HRS                                                   | 5801      |          |          |                           |           |           |                  |
| WC#: 32.150               | AFL                                                   | 3399      | 30000    | TSN 2525 | 30874                     |           | 26945     |                  |
| 323140                    | RIGHT MAIN LANDING GEAR JACK PIVOT BOLT               |           |          |          |                           |           |           | Component ATA:32 |
| PN: 25UM153A              | MOS                                                   | 25-Jun-20 |          |          |                           |           |           | LIFE LIMIT       |
| SN: NSN                   | HRS                                                   | 5801      |          |          |                           |           |           |                  |
| WC#: 32.150               | AFL                                                   | 3399      | 30000    | TSN 4000 | 29399                     |           | 25470     |                  |
| 323151                    | LEFT MAIN LANDING GEAR JACK CYLINDER HEAD             |           |          |          |                           |           |           | Component ATA:32 |
| PN: PN                    | MOS                                                   | 06-May-10 | 168      | TSN 0    | 06-May-24                 |           | 461 d     | LIFE LIMIT       |
| SN: UNKNOWN               | HRS                                                   | 4187.8    |          | TSN 0    |                           |           |           |                  |
| WC#: 32.155               | AFL                                                   | 2339      | 12000    | TSN 0    | 14339                     |           | 10410     |                  |
| WO#: N950PC 48 MONTH INSP |                                                       |           |          |          |                           |           |           |                  |
| 323152                    | RIGHT MAIN LANDING GEAR JACK CYLINDER HEAD            |           |          |          |                           |           |           | Component ATA:32 |
| PN: PN                    | MOS                                                   | 06-May-10 | 168      | TSN 0    | 06-May-24                 |           | 461 d     | LIFE LIMIT       |
| SN: UNKNOWN               | HRS                                                   | 4187.8    |          | TSN 0    |                           |           |           |                  |
| WC#: 32.155               | AFL                                                   | 2339      | 12000    | TSN 0    | 14339                     |           | 10410     |                  |
| WO#: N950PC 48 MONTH INSP |                                                       |           |          |          |                           |           |           |                  |
| 323163                    | LEFT MAIN LANDING GEAR JACK EYE END                   |           |          |          |                           |           |           | Component ATA:32 |
| PN: AIR158922             | MOS                                                   | 30-May-96 |          |          |                           |           |           | LIFE LIMIT       |
| SN: UNKNOWN               | HRS                                                   | 0         |          |          |                           |           |           |                  |
| WC#: 32.160               | AFL                                                   | 0         | 10000    | TSN 0    | 10000                     |           | 6071      |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                 | Unit                                       | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------|--------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR   |                                            |           |          |          |                           |           |           |                  |
| 323164                  | RIGHT MAIN LANDING GEAR JACK EYE END       |           |          |          |                           |           |           | Component ATA:32 |
| PN: AIR158922           | MOS                                        | 30-May-96 |          |          |                           |           |           | LIFE LIMIT       |
| SN: UNKNOWN             | HRS                                        | 0         |          |          |                           |           |           |                  |
| WC#: 32.160             | AFL                                        | 0         | 10000    | TSN 0    | 10000                     |           | 6071      |                  |
| 323175                  | LEFT MAIN LANDING GEAR RETRACTION ARM      |           |          |          |                           |           |           | Component ATA:32 |
| PN: 25-8UM63-2A         | MOS                                        | 25-Jun-20 |          |          |                           |           |           | LIFE LIMIT       |
| SN: DHL465              | HRS                                        | 5801      |          |          |                           |           |           |                  |
| WC#: 32.165             | AFL                                        | 3399      | 12000    | TSN 6137 | 9262                      |           | 5333      |                  |
| 323176                  | RIGHT MAIN LANDING GEAR RETRACTION ARM     |           |          |          |                           |           |           | Component ATA:32 |
| PN: NP-8UM63-2A         | MOS                                        | 25-Jun-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN: AV8-00032           | HRS                                        | 5801      |          | TSN 0    |                           |           |           |                  |
| WC#: 32.165             | AFL                                        | 3399      | 12000    | TSN 0    | 15399                     |           | 11470     |                  |
| 323181                  | LEFT MAIN LANDING GEAR RETRACTION ARM PIN  |           |          |          |                           |           |           | Component ATA:32 |
| PN: 25UM787             | MOS                                        | 25-Jun-20 |          |          |                           |           |           | LIFE LIMIT       |
| SN: DHL210              | HRS                                        | 5801      |          |          |                           |           |           |                  |
| WC#: 32.170             | AFL                                        | 3399      | 32000    | TSN 6137 | 29262                     |           | 25333     |                  |
| 323182                  | RIGHT MAIN LANDING GEAR RETRACTION ARM PIN |           |          |          |                           |           |           | Component ATA:32 |
| PN: N9-UM787-1          | MOS                                        | 25-Jun-20 |          | TSN 0    |                           |           |           | LIFE LIMIT       |
| SN: SAM014              | HRS                                        | 5801      |          | TSN 0    |                           |           |           |                  |
| WC#: 32.170             | AFL                                        | 3399      | 32000    | TSN 0    | 35399                     |           | 31470     |                  |
| 323187                  | LANDING GEAR LEVER LOCK SOLENOID           |           |          |          |                           |           |           | Component ATA:32 |
| PN: D5327               | MOS/MSC                                    | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN: X4396               | HRS                                        | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.175             | AFL                                        | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 32-30-21 |                                            |           |          |          |                           |           |           |                  |
| 324001                  | NOSE LANDING GEAR AXLE BARREL              |           |          |          |                           |           |           | Component ATA:32 |
| PN: 25-8UN257-3         | MOS                                        | 25-Jun-20 |          |          |                           |           |           | LIFE LIMIT       |
| SN: SAM2909             | HRS                                        | 5801      |          |          |                           |           |           |                  |
| WC#: 32.195             | AFL                                        | 3399      | 30000    | TSN 8466 | 24933                     |           | 21004     |                  |
| PROC. REF: AMM 32-40-31 |                                            |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                                                | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-----------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR     |                                                     |           |          |          |                           |           |           |                  |
| 324002                    | NOSE LANDING GEAR AXLE ASSEMBLY                     |           |          |          |                           |           |           | Component ATA:32 |
| PN:PN                     | MOS/MSC                                             | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.573               | AFL                                                 | 0         |          | TSN 0    |                           |           |           |                  |
| 324003                    | LEFT NOSE LANDING GEAR DOOR PIVOT BRACKET ASSEMBLY  |           |          |          |                           |           |           | Component ATA:32 |
| PN:PN                     | MOS/MSC                                             | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.574               | AFL                                                 | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                     |           |          |          |                           |           |           |                  |
| 324004                    | RIGHT NOSE LANDING GEAR DOOR PIVOT BRACKET ASSEMBLY |           |          |          |                           |           |           | Component ATA:32 |
| PN:PN                     | MOS/MSC                                             | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.575               | AFL                                                 | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                     |           |          |          |                           |           |           |                  |
| 324006                    | NOSE LANDING GEAR OUTER CASING                      |           |          |          |                           |           |           | Component ATA:32 |
| PN:PN                     | MOS/MSC                                             | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.576               | AFL                                                 | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                     |           |          |          |                           |           |           |                  |
| 324007                    | LEFT NOSE WHEEL                                     |           |          |          |                           |           |           | Component ATA:32 |
| PN:AH52339                | MOS/MSC                                             | 11-Feb-22 | O/C      | TSO 0    |                           |           |           |                  |
| SN:QH066                  | HRS                                                 | 6264.3    |          | TSO 0    |                           |           |           |                  |
| WC#: 32.200               | AFL                                                 | 3756      |          | TSO 0    |                           |           |           |                  |
| PROC. REF: AMM 32-40-21   |                                                     |           |          |          |                           |           |           |                  |
| 324007A <sup>U</sup>      | PERFORM LEFT NOSE WHEEL NDT INSPECTION              |           |          |          |                           |           |           | Service ATA:32   |
|                           | MOS/MSC                                             | 11-Feb-22 | T/C      |          |                           |           |           |                  |
|                           | HRS                                                 | 6264.3    |          |          |                           |           |           |                  |
|                           | AFL                                                 | 3756      |          |          |                           |           |           |                  |
| 324008                    | RIGHT NOSE WHEEL                                    |           |          |          |                           |           |           | Component ATA:32 |
| PN:AH52339                | MOS/MSC                                             | 11-Feb-22 | O/C      | TSO 0    |                           |           |           |                  |
| SN:PD032                  | HRS                                                 | 6264.3    |          | TSO 0    |                           |           |           |                  |
| WC#: 32.205               | AFL                                                 | 3756      |          | TSO 0    |                           |           |           |                  |
| PROC. REF: AMM 32-40-21   |                                                     |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                                                                     | Unit    | C/W                                             | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------------------------------------------------------------------------------------------|---------|-------------------------------------------------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR                                                                                       |         |                                                 |          |          |                           |           |           |                  |
| 324008A <sup>U</sup>                                                                                        |         | PERFORM RIGHT NOSE WHEEL NDT INSPECTION         |          |          |                           |           |           | Service ATA:32   |
|                                                                                                             | MOS/MSC | 11-Feb-22                                       | T/C      |          |                           |           |           |                  |
|                                                                                                             | HRS     | 6264.3                                          |          |          |                           |           |           |                  |
|                                                                                                             | AFL     | 3756                                            |          |          |                           |           |           |                  |
| 324009                                                                                                      |         | NOSE LANDING GEAR TOP LEVER ASSEMBLY            |          |          |                           |           |           | Component ATA:32 |
| PN:PN                                                                                                       | MOS/MSC | 30-May-96                                       | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                                                                                  | HRS     | 0                                               |          | TSN 0    |                           |           |           |                  |
| WC#: 32.577                                                                                                 | AFL     | 0                                               |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                                                                                   |         |                                                 |          |          |                           |           |           |                  |
| 324010                                                                                                      |         | NOSE LANDING GEAR BOTTOM LEVER ASSEMBLY         |          |          |                           |           |           | Component ATA:32 |
| PN:PN                                                                                                       | MOS/MSC | 30-May-96                                       | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                                                                                  | HRS     | 0                                               |          | TSN 0    |                           |           |           |                  |
| WC#: 32.578                                                                                                 | AFL     | 0                                               |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                                                                                   |         |                                                 |          |          |                           |           |           |                  |
| 324019                                                                                                      |         | LEFT NOSE TIRE                                  |          |          |                           |           |           | Component ATA:32 |
| PN:031-595-0                                                                                                | MOS/MSC | 11-Feb-22                                       | T/C      | TSN 0    |                           |           |           |                  |
| SN:1253T00392                                                                                               | HRS     | 6264.3                                          |          | TSN 0    |                           |           |           |                  |
| WC#: 32.200                                                                                                 | AFL     | 3756                                            |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-40-41                                                                                     |         |                                                 |          |          |                           |           |           |                  |
| 324020                                                                                                      |         | RIGHT NOSE TIRE                                 |          |          |                           |           |           | Component ATA:32 |
| PN:031-595-0                                                                                                | MOS/MSC | 11-Feb-22                                       | T/C      | TSN 0    |                           |           |           |                  |
| SN:1255T00226                                                                                               | HRS     | 6264.3                                          |          | TSN 0    |                           |           |           |                  |
| WC#: 32.205                                                                                                 | AFL     | 3756                                            |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-40-41                                                                                     |         |                                                 |          |          |                           |           |           |                  |
| 324031                                                                                                      |         | LEFT OUTBOARD MAIN WHEEL                        |          |          |                           |           |           | Component ATA:32 |
| PN:AHA1814                                                                                                  | MOS/MSC | 16-Aug-22                                       | O/C      | TSO 0    |                           |           |           |                  |
| SN:RS199                                                                                                    | HRS     | 6412                                            |          | TSO 0    |                           |           |           |                  |
| WC#: 32.210                                                                                                 | AFL     | 3846                                            |          | TSO 0    |                           |           |           |                  |
| PROC. REF: AMM 32-40-12                                                                                     |         |                                                 |          |          |                           |           |           |                  |
| 324031A <sup>U</sup>                                                                                        |         | PERFORM LEFT OUTBOARD MAIN WHEEL NDT INSPECTION |          |          |                           |           |           | Service ATA:32   |
|                                                                                                             | MOS/MSC | 16-Aug-22                                       | T/C      |          |                           |           |           |                  |
|                                                                                                             | HRS     | 6412                                            |          |          |                           |           |           |                  |
|                                                                                                             | AFL     | 3846                                            |          |          |                           |           |           |                  |
| PROC. REF: AMM 32-20-12, AMM 32-20-12, AMM 32-20-12, AMM 12-32-00, CMP 12-32-00, AMM 12-32-00, AMM 32-20-12 |         |                                                 |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                 | Unit                                             | C/W       | Interval | TSX/Adj.  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------|--------------------------------------------------|-----------|----------|-----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR   |                                                  |           |          |           |                           |           |           |                  |
| 324032                  | RIGHT OUTBOARD MAIN WHEEL                        |           |          |           |                           |           |           | Component ATA:32 |
| PN: AHA1814             | MOS/MSC                                          | 25-Nov-22 | O/C      | TSO 11    |                           |           |           |                  |
| SN: ZQ013               | HRS                                              | 6482.7    |          | TSO 218.4 |                           |           |           |                  |
| WC#: 32.215             | AFL                                              | 3897      |          | TSO 154   |                           |           |           |                  |
| PROC. REF: AMM 32-40-12 |                                                  |           |          |           |                           |           |           |                  |
| 324032A <sup>U</sup>    | PERFORM RIGHT OUTBOARD MAIN WHEEL NDT INSPECTION |           |          |           |                           |           |           | Service ATA:32   |
|                         | MOS/MSC                                          | 19-Jul-22 | T/C      |           |                           |           |           |                  |
|                         | HRS                                              | 6389      |          |           |                           |           |           |                  |
|                         | AFL                                              | 3829      |          |           |                           |           |           |                  |
| 324032B <sup>U</sup>    | REPACK WHEEL BEARINGS -RIGHT OUTBOARD MAIN WHEEL |           |          |           |                           |           |           | Service ATA:32   |
|                         | MOS                                              | 06-Jan-23 |          |           |                           |           |           |                  |
|                         | HRS                                              | 6519.5    |          |           |                           |           |           |                  |
|                         | AFL                                              | 3923      | 20       |           | 3943                      |           | 14        |                  |
| 324033                  | LEFT INBOARD MAIN WHEEL                          |           |          |           |                           |           |           | Component ATA:32 |
| PN: AHA1814             | MOS/MSC                                          | 16-Aug-22 | O/C      | TSO 0     |                           |           |           |                  |
| SN: XH150               | HRS                                              | 6412      |          | TSO 0     |                           |           |           |                  |
| WC#: 32.220             | AFL                                              | 3846      |          | TSO 0     |                           |           |           |                  |
| PROC. REF: AMM 32-40-12 |                                                  |           |          |           |                           |           |           |                  |
| 324033A <sup>U</sup>    | PERFORM LEFT INBOARD MAIN WHEEL NDT INSPECTION   |           |          |           |                           |           |           | Service ATA:32   |
|                         | MOS/MSC                                          | 16-Aug-22 | T/C      |           |                           |           |           |                  |
|                         | HRS                                              | 6412      |          |           |                           |           |           |                  |
|                         | AFL                                              | 3846      |          |           |                           |           |           |                  |
| 324034                  | RIGHT INBOARD MAIN WHEEL                         |           |          |           |                           |           |           | Component ATA:32 |
| PN: AHA1814             | MOS/MSC                                          | 25-Nov-22 | O/C      |           |                           |           |           |                  |
| SN: 5037EW              | HRS                                              | 6482.7    |          | TSO 16.7  |                           |           |           |                  |
| WC#: 32.225             | AFL                                              | 3897      |          | TSO 9     |                           |           |           |                  |
| PROC. REF: AMM 32-40-12 |                                                  |           |          |           |                           |           |           |                  |
| 324034A <sup>U</sup>    | PERFORM RIGHT INBOARD MAIN WHEEL NDT INSPECTION  |           |          |           |                           |           |           | Service ATA:32   |
|                         | MOS/MSC                                          | 10-Nov-22 | T/C      |           |                           |           |           |                  |
|                         | HRS                                              | 6466.9    |          |           |                           |           |           |                  |
|                         | AFL                                              | 3888      |          |           |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                 | Unit    | C/W                                             | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------|---------|-------------------------------------------------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR   |         |                                                 |          |          |                           |           |           |                  |
| 324034B <sup>U</sup>    |         | REPACK WHEEL BEARINGS -RIGHT INBOARD MAIN WHEEL |          |          |                           |           |           | Service ATA:32   |
|                         | MOS     | 06-Jan-23                                       |          |          |                           |           |           |                  |
|                         | HRS     | 6519.5                                          |          |          |                           |           |           |                  |
|                         | AFL     | 3923                                            | 20       |          | 3943                      |           | 14        |                  |
| 324055                  |         | LEFT OUTBOARD MAIN TIRE                         |          |          |                           |           |           | Component ATA:32 |
| PN:027-504-0            | MOS/MSC | 16-Aug-22                                       | T/C      | TSN 8    |                           |           |           |                  |
| SN:1322P00017           | HRS     | 6412                                            |          | TSN 0    |                           |           |           |                  |
| WC#: 32.210             | AFL     | 3846                                            |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-40-41 |         |                                                 |          |          |                           |           |           |                  |
| 324056                  |         | RIGHT OUTBOARD MAIN TIRE                        |          |          |                           |           |           | Component ATA:32 |
| PN:027-504-0            | MOS/MSC | 19-Jul-22                                       | T/C      | TSN 0    |                           |           |           |                  |
| SN:1319P00119           | HRS     | 6389                                            |          | TSN 0    |                           |           |           |                  |
| WC#: 32.215             | AFL     | 3829                                            |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-40-41 |         |                                                 |          |          |                           |           |           |                  |
| 324057                  |         | LEFT INBOARD MAIN TIRE                          |          |          |                           |           |           | Component ATA:32 |
| PN:027-504-0            | MOS/MSC | 16-Aug-22                                       | T/C      | TSN 0    |                           |           |           |                  |
| SN:1321P00045           | HRS     | 6412                                            |          | TSN 0    |                           |           |           |                  |
| WC#: 32.220             | AFL     | 3846                                            |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-40-41 |         |                                                 |          |          |                           |           |           |                  |
| 324058                  |         | RIGHT INBOARD MAIN TIRE                         |          |          |                           |           |           | Component ATA:32 |
| PN:DR14628T             | MOS/MSC | 10-Nov-22                                       | T/C      | TSN 0    |                           |           |           |                  |
| SN:22221314             | HRS     | 6466.9                                          |          | TSN 0    |                           |           |           |                  |
| WC#: 32.225             | AFL     | 3888                                            |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 32-40-41 |         |                                                 |          |          |                           |           |           |                  |
| 324065                  |         | RIGHT WHEEL WELL FILTER                         |          |          |                           |           |           | Component ATA:32 |
| PN:AIR48538             | MOS/MSC | 30-May-96                                       | O/C      |          |                           |           |           |                  |
| SN:BF95/0145            | HRS     | 0                                               |          | TSN 0    |                           |           |           |                  |
| WC#: 32.230             | AFL     | 0                                               |          |          |                           |           |           |                  |
| PROC. REF: AMM 32-30-22 |         |                                                 |          |          |                           |           |           |                  |
| 324066                  |         | LEFT FRAME 14A FILTER                           |          |          |                           |           |           | Component ATA:32 |
| PN:AIR48538-0           | MOS/MSC | 30-May-96                                       | O/C      |          |                           |           |           |                  |
| SN:BF96-000037          | HRS     | 0                                               |          | TSN 0    |                           |           |           |                  |
| WC#: 32.235             | AFL     | 0                                               |          |          |                           |           |           |                  |
| PROC. REF: AMM 32-30-22 |         |                                                 |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                 | Unit                       | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------|----------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR   |                            |           |          |          |                           |           |           |                  |
| 324067                  | RIGHT FRAME 14A FILTER     |           |          |          |                           |           |           | Component ATA:32 |
| PN: AIR48538-0          | MOS/MSC                    | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN: BF96-000036         | HRS                        | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.235             | AFL                        | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 32-30-22 |                            |           |          |          |                           |           |           |                  |
| 324068                  | FRAME 15 FILTER            |           |          |          |                           |           |           | Component ATA:32 |
| PN: AIR48538-0          | MOS/MSC                    | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN: BF96-000035         | HRS                        | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.235             | AFL                        | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 32-30-22 |                            |           |          |          |                           |           |           |                  |
| 324069                  | NOSE WHEEL STEERING FILTER |           |          |          |                           |           |           | Component ATA:32 |
| PN: AIR45412-0          | MOS/MSC                    | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN: BF95/113            | HRS                        | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.240             | AFL                        | 0         |          |          |                           |           |           |                  |
| 324077                  | PORT SHUTTLE VALVES        |           |          |          |                           |           |           | Component ATA:32 |
| PN: PN                  | MOS/MSC                    | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN: UNKNOWN             | HRS                        | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.407             | AFL                        | 0         |          | TSN 0    |                           |           |           |                  |
| 324078                  | STARBOARD SHUTTLE VALVES   |           |          |          |                           |           |           | Component ATA:32 |
| PN: PN                  | MOS/MSC                    | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN: UNKNOWN             | HRS                        | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.407             | AFL                        | 0         |          | TSN 0    |                           |           |           |                  |
| 324079                  | PORT SHUTTLE VALVES        |           |          |          |                           |           |           | Component ATA:32 |
| PN: PN                  | MOS/MSC                    | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN: UNKNOWN             | HRS                        | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.407             | AFL                        | 0         |          | TSN 0    |                           |           |           |                  |
| 324080                  | STARBOARD SHUTTLE VALVES   |           |          |          |                           |           |           | Component ATA:32 |
| PN: PN                  | MOS/MSC                    | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN: UNKNOWN             | HRS                        | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.407             | AFL                        | 0         |          | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                 | Unit                                       | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------|--------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR   |                                            |           |          |          |                           |           |           |                  |
| 324115                  | BRAKE CONTROL VALVE                        |           |          |          |                           |           |           | Component ATA:32 |
| PN:AC67732              | MOS/MSC                                    | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN: SX237               | HRS                                        | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.245             | AFL                                        | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 32-40-71 |                                            |           |          |          |                           |           |           |                  |
| 324121                  | BRAKE CONTROL VALVE LEFT OUTER KNIFE EDGE  |           |          |          |                           |           |           | Component ATA:32 |
| PN:AC0-34630            | MOS                                        | 30-May-96 |          |          |                           |           |           | LIFE LIMIT       |
| SN: UNKNOWN             | HRS                                        | 0         |          |          |                           |           |           |                  |
| WC#: 32.245             | AFL                                        | 0         | 4500     | TSN 0    | 4500                      |           | 571       |                  |
| PROC. REF: AMM 32-40-71 |                                            |           |          |          |                           |           |           |                  |
| 324122                  | BRAKE CONTROL VALVE RIGHT OUTER KNIFE EDGE |           |          |          |                           |           |           | Component ATA:32 |
| PN:AC0-34629            | MOS                                        | 30-May-96 |          |          |                           |           |           | LIFE LIMIT       |
| SN: UNKNOWN             | HRS                                        | 0         |          |          |                           |           |           |                  |
| WC#: 32.245             | AFL                                        | 0         | 4500     | TSN 0    | 4500                      |           | 571       |                  |
| PROC. REF: AMM 32-40-71 |                                            |           |          |          |                           |           |           |                  |
| 324123                  | BRAKE CONTROL VALVE INNER KNIFE EDGE       |           |          |          |                           |           |           | Component ATA:32 |
| PN:AC0-36133            | MOS                                        | 30-May-96 |          |          |                           |           |           | LIFE LIMIT       |
| SN: UNKNOWN             | HRS                                        | 0         |          |          |                           |           |           |                  |
| WC#: 32.245             | AFL                                        | 0         | 4500     | TSN 0    | 4500                      |           | 571       |                  |
| PROC. REF: AMM 32-40-71 |                                            |           |          |          |                           |           |           |                  |
| 324145                  | MAIN REDUCING VALVE                        |           |          |          |                           |           |           | Component ATA:32 |
| PN:AC61518              | MOS/MSC                                    | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN: SH163               | HRS                                        | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.250             | AFL                                        | 0         |          |          |                           |           |           |                  |
| 324151                  | EMERGENCY REDUCING VALVE                   |           |          |          |                           |           |           | Component ATA:32 |
| PN:AC69784              | MOS/MSC                                    | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN: WB999               | HRS                                        | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.255             | AFL                                        | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 32-40-51 |                                            |           |          |          |                           |           |           |                  |
| 324157                  | EMERGENCY REDUCING VALVE LEFT KNIFE EDGE   |           |          |          |                           |           |           | Component ATA:32 |
| PN:AC0-34630            | MOS                                        | 30-May-96 |          |          |                           |           |           | LIFE LIMIT       |
| SN: UNKNOWN             | HRS                                        | 0         |          |          |                           |           |           |                  |
| WC#: 32.255             | AFL                                        | 0         | 4500     | TSN 0    | 4500                      |           | 571       |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                  | Unit                                      | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------|-------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR    |                                           |           |          |          |                           |           |           |                  |
| 324158                   | EMERGENCY REDUCING VALVE RIGHT KNIFE EDGE |           |          |          |                           |           |           | Component ATA:32 |
| PN:AC0-34629             | MOS                                       | 30-May-96 |          |          |                           |           |           | LIFE LIMIT       |
| SN:UNKNOWN               | HRS                                       | 0         |          |          |                           |           |           |                  |
| WC#: 32.255              | AFL                                       | 0         | 4500     | TSN 0    | 4500                      |           | 571       |                  |
| 324169                   | EMERGENCY BRAKE PRESSURE NONRETURN VALVE  |           |          |          |                           |           |           | Component ATA:32 |
| PN:AIR45420-0-1          | MOS/MSC                                   | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:APB960009             | HRS                                       | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.500              | AFL                                       | 0         |          |          |                           |           |           |                  |
| 324175                   | LEFT OUTBOARD BRAKE UNIT                  |           |          |          |                           |           |           | Component ATA:32 |
| PN:AHA1897               | MOS/MSC                                   | 08-Apr-11 | O/C      |          |                           |           |           |                  |
| SN:TN091                 | HRS                                       | 4411.6    |          |          |                           |           |           |                  |
| WC#: 32.265              | AFL                                       | 2460      |          |          |                           |           |           |                  |
| PROC. REF: AMM 32-40-114 |                                           |           |          |          |                           |           |           |                  |
| 324176                   | RIGHT OUTBOARD BRAKE UNIT                 |           |          |          |                           |           |           | Component ATA:32 |
| PN:AHA1897               | MOS/MSC                                   | 30-Jul-21 | O/C      | TSO 0    |                           |           |           |                  |
| SN:NL019                 | HRS                                       | 6087.1    |          | TSO 0    |                           |           |           |                  |
| WC#: 32.260              | AFL                                       | 3605      |          | TSO 0    |                           |           |           |                  |
| PROC. REF: AMM 32-40-114 |                                           |           |          |          |                           |           |           |                  |
| 324177                   | LEFT INBOARD BRAKE UNIT                   |           |          |          |                           |           |           | Component ATA:32 |
| PN:AHA1897               | MOS/MSC                                   | 01-Apr-11 | O/C      |          |                           |           |           |                  |
| SN:UC156                 | HRS                                       | 4403.8    |          |          |                           |           |           |                  |
| WC#: 32.265              | AFL                                       | 2457      |          |          |                           |           |           |                  |
| PROC. REF: AMM 32-40-114 |                                           |           |          |          |                           |           |           |                  |
| 324178                   | RIGHT INBOARD BRAKE UNIT                  |           |          |          |                           |           |           | Component ATA:32 |
| PN:AHA1897               | MOS/MSC                                   | 23-Jul-19 | O/C      | TSO 4    |                           |           |           |                  |
| SN:5065JD                | HRS                                       | 5795      |          | TSO 0    |                           |           |           |                  |
| WC#: 32.260              | AFL                                       | 3396      |          | TSO 0    |                           |           |           |                  |
| PROC. REF: AMM 32-40-114 |                                           |           |          |          |                           |           |           |                  |
| 324223                   | LEFT OUTBOARD MAXARET                     |           |          |          |                           |           |           | Component ATA:32 |
| PN:AC65218               | MOS                                       | 09-Mar-04 |          | TSO 0    |                           |           |           | OVERHAUL         |
| SN:GA003                 | HRS                                       | 2632.6    |          | TSO 0    |                           |           |           |                  |
| WC#: 32.270              | AFL                                       | 1434      | 3000     | TSO 0    | 4434                      |           | 505       |                  |
| PROC. REF: AMM 32-40-101 |                                           |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                  | Unit                         | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------|------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR    |                              |           |          |          |                           |           |           |                  |
| 324224                   | RIGHT OUTBOARD MAXARET       |           |          |          |                           |           |           | Component ATA:32 |
| PN:AC65216               | MOS                          | 02-Nov-11 |          | TSO 0    |                           |           |           | OVERHAUL         |
| SN:CA226                 | HRS                          | 4563.1    |          | TSO 0    |                           |           |           |                  |
| WC#: 32.275              | AFL                          | 2554      | 3000     | TSO 0    | 5554                      |           | 1625      |                  |
| PROC. REF: AMM 32-40-101 |                              |           |          |          |                           |           |           |                  |
| 324225                   | LEFT INBOARD MAXARET         |           |          |          |                           |           |           | Component ATA:32 |
| PN:AC65216               | MOS                          | 23-May-16 |          | TSO 1    |                           |           |           | OVERHAUL         |
| SN:YU142                 | HRS                          | 5289.6    |          | TSO 0    |                           |           |           |                  |
| WC#: 32.270              | AFL                          | 3010      | 3000     | TSO 0    | 6010                      |           | 2081      |                  |
| PROC. REF: AMM 32-40-101 |                              |           |          |          |                           |           |           |                  |
| 324226                   | RIGHT INBOARD MAXARET        |           |          |          |                           |           |           | Component ATA:32 |
| PN:AC65218               | MOS                          | 22-Mar-11 |          | TSO 0    |                           |           |           | OVERHAUL         |
| SN:NH325                 | HRS                          | 4393.3    |          | TSO 0    |                           |           |           |                  |
| WC#: 32.275              | AFL                          | 2449      | 3000     | TSO 0    | 5449                      |           | 1520      |                  |
| PROC. REF: AMM 32-40-101 |                              |           |          |          |                           |           |           |                  |
| 324260                   | LEFT MAIN LANDING GEAR DOOR  |           |          |          |                           |           |           | Component ATA:32 |
| PN:25.8UD111-1A          | MOS/MSC                      | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:CFTW/DHB069           | HRS                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.280              | AFL                          | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 32-10-41  |                              |           |          |          |                           |           |           |                  |
| 324261                   | RIGHT MAIN LANDING GEAR DOOR |           |          |          |                           |           |           | Component ATA:32 |
| PN:25.8UD111-2A          | MOS/MSC                      | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:CFTW/DHB072           | HRS                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.280              | AFL                          | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 32-10-41  |                              |           |          |          |                           |           |           |                  |
| 324262                   | LEFT NOSE GEAR DOOR          |           |          |          |                           |           |           | Component ATA:32 |
| PN:25.8UD1-103A          | MOS/MSC                      | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:CFTU/DHB142           | HRS                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.285              | AFL                          | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 32-20-42  |                              |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                 | Unit                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------|---------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR   |                                       |           |          |          |                           |           |           |                  |
| 324263                  | RIGHT NOSE GEAR DOOR                  |           |          |          |                           |           |           | Component ATA:32 |
| PN:25.8UD1-104A         | MOS/MSC                               | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:CFTU/DHB142          | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.285             | AFL                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 32-20-42 |                                       |           |          |          |                           |           |           |                  |
| 324264                  | NOSE GEAR DOOR (LEG FAIRING) ASSEMBLY |           |          |          |                           |           |           | Component ATA:32 |
| PN:25.8UD63-1A          | MOS/MSC                               | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:CFTU/DHB142          | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.290             | AFL                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 32-20-42 |                                       |           |          |          |                           |           |           |                  |
| 324265                  | LEFT MAIN LANDING GEAR FAIRING        |           |          |          |                           |           |           | Component ATA:32 |
| PN:25.8UD43-115A        | MOS/MSC                               | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:CFTW/DHB/164         | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.295             | AFL                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 32-10-32 |                                       |           |          |          |                           |           |           |                  |
| 324266                  | RIGHT MAIN LANDING GEAR FAIRING       |           |          |          |                           |           |           | Component ATA:32 |
| PN:25.8UD43-116A        | MOS/MSC                               | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:CFTW/DHB/150         | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.295             | AFL                                   | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 32-10-32 |                                       |           |          |          |                           |           |           |                  |
| 324267                  | VENTRAL FAIRING ASSEMBLY              |           |          |          |                           |           |           | Component ATA:32 |
| PN:PN                   | MOS/MSC                               | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN              | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.295             | AFL                                   | 0         |          | TSN 0    |                           |           |           |                  |
| 324271                  | LEFT BRAKE MODULATOR                  |           |          |          |                           |           |           | Component ATA:32 |
| PN:ACM22740             | MOS/MSC                               | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:SZ010                | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.300             | AFL                                   | 0         |          |          |                           |           |           |                  |
| 324272                  | RIGHT BRAKE MODULATOR                 |           |          |          |                           |           |           | Component ATA:32 |
| PN:ACM22742             | MOS/MSC                               | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:PQ069                | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.300             | AFL                                   | 0         |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN               | Unit                                          | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------------|-----------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR |                                               |           |          |          |                           |           |           |                  |
| 324301                | PILOT LEFT BRAKE MASTER CYLINDER              |           |          |          |                           |           |           | Component ATA:32 |
| PN:ACM26274           | MOS/MSC                                       | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:TY070              | HRS                                           | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.310           | AFL                                           | 0         |          |          |                           |           |           |                  |
| 324302                | PILOT RIGHT BRAKE MASTER CYLINDER             |           |          |          |                           |           |           | Component ATA:32 |
| PN:ACM30946           | MOS/MSC                                       | 23-Jan-01 | O/C      | TSO 4    |                           |           |           |                  |
| SN:N1680              | HRS                                           | 1822      |          | TSO 0    |                           |           |           |                  |
| WC#: 32.310           | AFL                                           | 982       |          | TSO 0    |                           |           |           |                  |
| 324303                | COPILOT LEFT BRAKE MASTER CYLINDER            |           |          |          |                           |           |           | Component ATA:32 |
| PN:ACM26274           | MOS/MSC                                       | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:TY073              | HRS                                           | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.315           | AFL                                           | 0         |          |          |                           |           |           |                  |
| 324304                | COPILOT RIGHT BRAKE MASTER CYLINDER           |           |          |          |                           |           |           | Component ATA:32 |
| PN:ACM26274           | MOS/MSC                                       | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:TY069              | HRS                                           | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.315           | AFL                                           | 0         |          |          |                           |           |           |                  |
| 324325                | LEFT EMERGENCY BRAKE PRESSURE WARNING SWITCH  |           |          |          |                           |           |           | Component ATA:32 |
| PN:TP42000            | MOS                                           | 06-May-13 |          | TSO 0    |                           |           |           | OVERHAUL         |
| SN:3149               | HRS                                           | 4942.5    | 5000     | TSO 0    | 9942.5                    |           | 3414.2    |                  |
| WC#: 32.320           | AFL                                           | 2767      |          | TSO 0    |                           |           |           |                  |
| 324326                | RIGHT EMERGENCY BRAKE PRESSURE WARNING SWITCH |           |          |          |                           |           |           | Component ATA:32 |
| PN:TP42000            | MOS                                           | 06-May-13 |          | TSO 0    |                           |           |           | OVERHAUL         |
| SN:980                | HRS                                           | 4942.5    | 5000     | TSO 0    | 9942.5                    |           | 3414.2    |                  |
| WC#: 32.320           | AFL                                           | 2767      |          | TSO 0    |                           |           |           |                  |
| 324337                | FORWARD HIGH PRESSURE TRANSDUCER              |           |          |          |                           |           |           | Component ATA:32 |
| PN:FDA695-4-21        | MOS/MSC                                       | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:BY6575             | HRS                                           | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.325           | AFL                                           | 0         |          |          |                           |           |           |                  |
| 324338                | AFT HIGH PRESSURE TRANSDUCER                  |           |          |          |                           |           |           | Component ATA:32 |
| PN:FDA695-4-21        | MOS/MSC                                       | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:BY6573             | HRS                                           | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.325           | AFL                                           | 0         |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                  | Unit                                         | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------|----------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR    |                                              |           |          |          |                           |           |           |                  |
| 325001                   | STEERING JACK                                |           |          |          |                           |           |           | Component ATA:32 |
| PN: AIR45396-5           | MOS/MSC                                      | 10-Apr-08 | O/C      |          |                           |           |           |                  |
| SN: LK0435               | HRS                                          | 3693      |          |          |                           |           |           |                  |
| WC#: 32.330              | AFL                                          | 2070      |          |          |                           |           |           |                  |
| PROC. REF: AMM 32-50-11  |                                              |           |          |          |                           |           |           |                  |
| 325003                   | NOSE LANDING GEAR CONNECTING ROD             |           |          |          |                           |           |           | Component ATA:32 |
| PN: 25-8UN433-1A         | MOS                                          | 30-May-96 |          |          |                           |           |           | LIFE LIMIT       |
| SN: UNKNOWN              | HRS                                          | 0         |          |          |                           |           |           |                  |
| WC#: 32.335              | AFL                                          | 0         | 20000    | TSN 0    | 20000                     |           | 16071     |                  |
| 325007                   | STEERING JACK EYE END                        |           |          |          |                           |           |           | Component ATA:32 |
| PN: AIR110646            | MOS                                          | 30-May-96 |          |          |                           |           |           | LIFE LIMIT       |
| SN: UNKNOWN              | HRS                                          | 0         |          |          |                           |           |           |                  |
| WC#: 32.340              | AFL                                          | 0         | 14400    | TSN 0    | 14400                     |           | 10471     |                  |
| 325008                   | PORT WING TO FUSELAGE FAIRING                |           |          |          |                           |           |           | Component ATA:32 |
| PN: PN                   | MOS/MSC                                      | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN: UNKNOWN              | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.295              | AFL                                          | 0         |          | TSN 0    |                           |           |           |                  |
| 325009                   | WING TO FUSELAGE FAIRING                     |           |          |          |                           |           |           | Component ATA:32 |
| PN: PN                   | MOS/MSC                                      | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN: UNKNOWN              | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.295              | AFL                                          | 0         |          | TSN 0    |                           |           |           |                  |
| 325010                   | UNDERCARRIAGE FAIRING                        |           |          |          |                           |           |           | Component ATA:32 |
| PN: PN                   | MOS/MSC                                      | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN: UNKNOWN              | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.295              | AFL                                          | 0         |          | TSN 0    |                           |           |           |                  |
| 325011                   | NOSE LANDING GEAR TORQUE LINK PICK UP SLEEVE |           |          |          |                           |           |           | Component ATA:32 |
| PN: 25-8UN441/5          | MOS                                          | 25-Jun-20 |          |          |                           |           |           | LIFE LIMIT       |
| SN: W0-81162-11/EPI-0144 | HRS                                          | 5801      |          |          |                           |           |           |                  |
| WC#: 32.335              | AFL                                          | 3399      | 20000    | TSN 2246 | 21153                     |           | 17224     |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN               | Unit                                         | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------------|----------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 32 - LANDING GEAR |                                              |           |          |          |                           |           |           |                  |
| 325012                | FAIRING SUB ASSEMBLY                         |           |          |          |                           |           |           | Component ATA:32 |
| PN:PN                 | MOS/MSC                                      | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN            | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.295           | AFL                                          | 0         |          | TSN 0    |                           |           |           |                  |
| 325013                | COVER                                        |           |          |          |                           |           |           | Component ATA:32 |
| PN:PN                 | MOS/MSC                                      | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN            | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.303           | AFL                                          | 0         |          | TSN 0    |                           |           |           |                  |
| 325015                | NOSE LANDING GEAR STEERING PIN               |           |          |          |                           |           |           | Component ATA:32 |
| PN:25UN605            | MOS                                          | 30-May-96 |          |          |                           |           |           | LIFE LIMIT       |
| SN:UNKNOWN            | HRS                                          | 0         |          |          |                           |           |           |                  |
| WC#: 32.345           | AFL                                          | 0         | 25000    | TSN 0    | 25000                     |           | 21071     |                  |
| 325021                | NOSE LANDING GEAR MAIN CASING BOLT           |           |          |          |                           |           |           | Component ATA:32 |
| PN:25UN603            | MOS                                          | 25-Jun-20 |          |          |                           |           |           | LIFE LIMIT       |
| SN:3040DA             | HRS                                          | 5801      |          |          |                           |           |           |                  |
| WC#: 32.345           | AFL                                          | 3399      | 33000    | TSN 8466 | 27933                     |           | 24004     |                  |
| 325025                | NOSE WHEEL STEERING ON/OFF VALVE             |           |          |          |                           |           |           | Component ATA:32 |
| PN:AIR45408/0         | MOS/MSC                                      | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:APB960387          | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.350           | AFL                                          | 0         |          |          |                           |           |           |                  |
| 325031                | NOSE WHEEL ANTI-SHIMMING VALVE               |           |          |          |                           |           |           | Component ATA:32 |
| PN:AIR48284-1         | MOS/MSC                                      | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:APB960907          | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 32.355           | AFL                                          | 0         |          |          |                           |           |           |                  |
| 325041                | NOSE LANDING GEAR UPPER STEERING MAIN MEMBER |           |          |          |                           |           |           | Component ATA:32 |
| PN:25-8UN431-1A       | MOS                                          | 25-Jun-20 |          |          |                           |           |           | LIFE LIMIT       |
| SN:SAM1507            | HRS                                          | 5801      |          |          |                           |           |           |                  |
| WC#: 32.360           | AFL                                          | 3399      | 35000    | TSN 8466 | 29933                     |           | 26004     |                  |
| 325042                | NOSE LANDING GEAR LOWER STEERING MAIN MEMBER |           |          |          |                           |           |           | Component ATA:32 |
| PN:25-8UN431-2A       | MOS                                          | 25-Jun-20 |          |          |                           |           |           | LIFE LIMIT       |
| SN:R648048            | HRS                                          | 5801      |          |          |                           |           |           |                  |
| WC#: 32.360           | AFL                                          | 3399      | 35000    | TSN 7316 | 31083                     |           | 27154     |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                       | Unit                                           | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                          | Disposition      |
|-------------------------------|------------------------------------------------|-----------|---------------|----------|---------------------------|-----------|------------------------------------|------------------|
| ATA 32 - LANDING GEAR         |                                                |           |               |          |                           |           |                                    |                  |
| 325051                        | NOSE LANDING GEAR STEERING JACK PICK-UP        |           |               |          |                           |           |                                    | Component ATA:32 |
| PN:25-8UN263-1A               | MOS                                            | 25-Jun-20 |               |          |                           |           |                                    | LIFE LIMIT       |
| SN:SAM1809                    | HRS                                            | 5801      |               |          |                           |           |                                    |                  |
| WC#: 32.365                   | AFL                                            | 3399      | 18000         | TSN 8466 | 12933                     |           | 9004                               |                  |
| 325058                        | NOSE LANDING GEAR STEERING SLEEVE              |           |               |          |                           |           |                                    | Component ATA:32 |
| PN:25-8UN439-1A               | MOS                                            | 25-Jun-20 |               |          |                           |           |                                    | LIFE LIMIT       |
| SN:EPI-0088                   | HRS                                            | 5801      |               |          |                           |           |                                    |                  |
| WC#: 32.365                   | AFL                                            | 3399      | 20000         | TSN 3565 | 19834                     |           | 15905                              |                  |
| 32R100 <sup>U</sup>           | RIGHT MAIN LANDING GEAR WHEEL AXLE             |           |               |          |                           |           |                                    | Component ATA:32 |
| PN:25-8UM53-16                | MOS/MSC                                        | 22-Mar-11 | O/C           | TSN 0    |                           |           |                                    |                  |
| SN:07MDZ00291                 | HRS                                            | 4393.3    |               | TSN 0    |                           |           |                                    |                  |
|                               | AFL                                            | 2449      |               | TSN 0    |                           |           |                                    |                  |
| ATA 33 - LIGHTS               |                                                |           |               |          |                           |           |                                    |                  |
| 330003                        | CLEAN/TEST/REPLACE ANTI-COLLISION LIGHT SYSTEM |           |               |          |                           |           |                                    | Service ATA:33   |
|                               | MOS                                            | 15-Oct-19 |               |          |                           |           |                                    |                  |
|                               | HRS                                            | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)                           |                  |
| WC#: 33.080                   | AFL                                            | 3397      |               |          |                           |           |                                    |                  |
| PROC. REF: AFMS INSPECTION B1 |                                                |           |               |          |                           |           | PKG:2,8<br>WO#: N950PC B & C CHECK |                  |
| 330007                        | MAIN CG ILLUMINATED LABEL                      |           |               |          |                           |           |                                    | Component ATA:33 |
| PN:JW125-1L-317               | MOS/MSC                                        | 30-May-96 | O/C           |          |                           |           |                                    |                  |
| SN:JWBA677                    | HRS                                            | 0         |               | TSN 0    |                           |           |                                    |                  |
| WC#: 33.015                   | AFL                                            | 0         |               |          |                           |           |                                    |                  |
| 330008                        | FORWARD CG ILLUMINATED LABEL                   |           |               |          |                           |           |                                    | Component ATA:33 |
| PN:JW125-1L-210               | MOS/MSC                                        | 30-May-96 | O/C           |          |                           |           |                                    |                  |
| SN:JWBA670                    | HRS                                            | 0         |               | TSN 0    |                           |           |                                    |                  |
| WC#: 33.015                   | AFL                                            | 0         |               |          |                           |           |                                    |                  |
| 330030 <sup>U</sup>           | ICE INSPECTION LIGHT ASSY                      |           |               |          |                           |           |                                    | Component ATA:33 |
| PN:PN                         | MOS/MSC                                        |           | O/C           |          |                           |           |                                    |                  |
| SN:UNKNOWN                    | HRS                                            |           |               |          |                           |           |                                    |                  |
|                               | AFL                                            |           |               |          |                           |           |                                    |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                 | Unit    | C/W                                    | Interval      | TSX/Adj.        | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition      |
|-------------------------|---------|----------------------------------------|---------------|-----------------|---------------------------|-----------|-------------|------------------|
| ATA 33 - LIGHTS         |         |                                        |               |                 |                           |           |             |                  |
| 330030B <sup>U</sup>    |         | ICE INSPECTION LIGHT ASSY - BULB       |               |                 |                           |           |             | Component ATA:33 |
| PN:PN                   | MOS/MSC |                                        | O/C           |                 |                           |           |             |                  |
| SN:UNKNOWN              | HRS     |                                        |               |                 |                           |           |             |                  |
|                         | AFL     |                                        |               |                 |                           |           |             |                  |
| 334001                  |         | TOP ANTI COLLISION BEACON              |               |                 |                           |           |             | Component ATA:33 |
| PN:69950-1              | MOS/MSC | 31-Mar-05                              | O/C           |                 |                           |           |             |                  |
| SN:4467                 | HRS     | 2813                                   |               |                 |                           |           |             |                  |
| WC#: 33.020             | AFL     | 1554                                   |               |                 |                           |           |             |                  |
| PROC. REF: AMM 33-40-42 |         |                                        |               |                 |                           |           |             |                  |
| 334002                  |         | BOTTOM ANTI COLLISION BEACON           |               |                 |                           |           |             | Component ATA:33 |
| PN:01-0790724-17        | MOS/MSC | 22-Dec-22                              | O/C           | TSN 0           |                           |           |             |                  |
| SN:13289410003          | HRS     | 6495.5                                 |               | TSN 0           |                           |           |             |                  |
| WC#: 33.020             | AFL     | 3906                                   |               | TSN 0           |                           |           |             |                  |
| PROC. REF: AMM 33-40-42 |         |                                        |               |                 |                           |           |             |                  |
| 334013                  |         | LEFT WING STROBE LIGHT                 |               |                 |                           |           |             | Component ATA:33 |
| PN:30-0538-7            | MOS/MSC | 23-Aug-02                              | O/C           | TSN 0           |                           |           |             |                  |
| SN:10141                | HRS     | 2317                                   |               | TSN 0           |                           |           |             |                  |
| WC#: 33.025             | AFL     | 1283                                   |               | TSN 0           |                           |           |             |                  |
| PROC. REF: AMM 33-40-11 |         |                                        |               |                 |                           |           |             |                  |
| 334014                  |         | RIGHT WING STROBE LIGHT                |               |                 |                           |           |             | Component ATA:33 |
| PN:30-0538-8            | MOS/MSC | 13-May-19                              | O/C           | TSN 201, TSO 0  |                           |           |             |                  |
| SN:10135                | HRS     | 5795                                   |               | TSN 3478, TSO 0 |                           |           |             |                  |
| WC#: 33.025             | AFL     | 3396                                   |               | TSN 2113, TSO 0 |                           |           |             |                  |
| PROC. REF: AMM 33-40-11 |         |                                        |               |                 |                           |           |             |                  |
| 334016                  |         | TEST LEFT WING STROBE LIGHT INTENSITY  |               |                 |                           |           |             | Service ATA:33   |
| PN:30-0538-7            | MOS     | 09-Dec-21                              |               |                 |                           |           |             |                  |
| SN:10141                | HRS     | 6248                                   | 400 (+50/-50) |                 | 6648                      | 6698      | 119.7 (+50) |                  |
| WC#: 33.025             | AFL     | 3719                                   |               |                 |                           |           |             |                  |
| 334017                  |         | TEST RIGHT WING STROBE LIGHT INTENSITY |               |                 |                           |           |             | Service ATA:33   |
| PN:30-0538-8            | MOS     | 09-Dec-21                              |               |                 |                           |           |             |                  |
| SN:10135                | HRS     | 6248                                   | 400 (+50/-50) |                 | 6648                      | 6698      | 119.7 (+50) |                  |
| WC#: 33.025             | AFL     | 3719                                   |               |                 |                           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                 | Unit                             | C/W       | Interval      | TSX/Adj.        | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition      |
|-------------------------|----------------------------------|-----------|---------------|-----------------|---------------------------|-----------|-------------|------------------|
| ATA 33 - LIGHTS         |                                  |           |               |                 |                           |           |             |                  |
| 334021                  | NO. 1 POWER CONVERTER            |           |               |                 |                           |           |             | Component ATA:33 |
| PN:PN                   | MOS/MSC                          | 30-May-96 | O/C           | TSN 0           |                           |           |             |                  |
| SN:UNKNOWN              | HRS                              | 0         |               | TSN 0           |                           |           |             |                  |
| WC#: 33.070             | AFL                              | 0         |               | TSN 0           |                           |           |             |                  |
| 334022                  | NO. 2 POWER CONVERTER            |           |               |                 |                           |           |             | Component ATA:33 |
| PN:PN                   | MOS/MSC                          | 30-May-96 | O/C           | TSN 0           |                           |           |             |                  |
| SN:UNKNOWN              | HRS                              | 0         |               | TSN 0           |                           |           |             |                  |
| WC#: 33.070             | AFL                              | 0         |               | TSN 0           |                           |           |             |                  |
| 334032                  | LEFT STROBE LIGHT POWER SUPPLY   |           |               |                 |                           |           |             | Component ATA:33 |
| PN:PN                   | MOS/MSC                          | 30-May-96 | O/C           | TSN 0           |                           |           |             |                  |
| SN:UNKNOWN              | HRS                              | 0         |               | TSN 0           |                           |           |             |                  |
| WC#: 33.030             | AFL                              | 0         |               | TSN 0           |                           |           |             |                  |
| 334033                  | RIGHT STROBE LIGHT POWER SUPPLY  |           |               |                 |                           |           |             | Component ATA:33 |
| PN:PN                   | MOS/MSC                          | 30-May-96 | O/C           | TSN 0           |                           |           |             |                  |
| SN:UNKNOWN              | HRS                              | 0         |               | TSN 0           |                           |           |             |                  |
| WC#: 33.030             | AFL                              | 0         |               | TSN 0           |                           |           |             |                  |
| 334044                  | TAIL STROBE LIGHT                |           |               |                 |                           |           |             | Component ATA:33 |
| PN:30-0516-1            | MOS/MSC                          | 13-May-19 | O/C           | TSN 201, TSO 0  |                           |           |             |                  |
| SN:5995                 | HRS                              | 5795      |               | TSN 3478, TSO 0 |                           |           |             |                  |
| WC#: 33.040             | AFL                              | 3396      |               | TSN 2113, TSO 0 |                           |           |             |                  |
| PROC. REF: AMM 33-40-11 |                                  |           |               |                 |                           |           |             |                  |
| 334045                  | TAIL STROBE LIGHT POWER SUPPLY   |           |               |                 |                           |           |             | Component ATA:33 |
| PN:PN                   | MOS/MSC                          | 30-May-96 | O/C           | TSN 0           |                           |           |             |                  |
| SN:UNKNOWN              | HRS                              | 0         |               | TSN 0           |                           |           |             |                  |
| WC#: 33.035             | AFL                              | 0         |               | TSN 0           |                           |           |             |                  |
| 334047                  | TEST TAIL STROBE LIGHT INTENSITY |           |               |                 |                           |           |             | Service ATA:33   |
| PN:30-0516-1            | MOS                              | 09-Dec-21 |               |                 |                           |           |             |                  |
| SN:5995                 | HRS                              | 6248      | 400 (+50/-50) |                 | 6648                      | 6698      | 119.7 (+50) |                  |
| WC#: 33.040             | AFL                              | 3719      |               |                 |                           |           |             |                  |
| 334061                  | STROBE LIGHTS POWER SUPPLY       |           |               |                 |                           |           |             | Component ATA:33 |
| PN:701571               | MOS/MSC                          | 03-Jan-12 | O/C           | TSO 0           |                           |           |             |                  |
| SN:4750                 | HRS                              | 4572.3    |               | TSO 0           |                           |           |             |                  |
| WC#: 33.045             | AFL                              | 2562      |               | TSO 0           |                           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-----------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 33 - LIGHTS           |                                         |           |          |          |                           |           |           |                  |
| 334204                    | LH WING NAV LIGHT ASSY                  |           |          |          |                           |           |           | Component ATA:33 |
| PN:PN                     | MOS/MSC                                 | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                           | AFL                                     | 0         |          | TSN 0    |                           |           |           |                  |
| 334204B <sup>U</sup>      | LH WING NAV LIGHT - BULB                |           |          |          |                           |           |           | Component ATA:33 |
| PN:PN                     | MOS/MSC                                 |           | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                     |           |          |          |                           |           |           |                  |
|                           | AFL                                     |           |          |          |                           |           |           |                  |
| 334205                    | RH WING NAV LIGHT ASSY                  |           |          |          |                           |           |           | Component ATA:33 |
| PN:PN                     | MOS/MSC                                 | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                           | AFL                                     | 0         |          | TSN 0    |                           |           |           |                  |
| 334205B <sup>U</sup>      | RH WING NAV LIGHT - BULB                |           |          |          |                           |           |           | Component ATA:33 |
| PN:PN                     | MOS/MSC                                 |           | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                     |           |          |          |                           |           |           |                  |
|                           | AFL                                     |           |          |          |                           |           |           |                  |
| 334244 <sup>U</sup>       | TAIL NAV LIGHT ASSY                     |           |          |          |                           |           |           | Component ATA:33 |
| PN:PN                     | MOS/MSC                                 |           | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                     |           |          |          |                           |           |           |                  |
|                           | AFL                                     |           |          |          |                           |           |           |                  |
| 334244B <sup>U</sup>      | TAIL NAV LIGHT ASSY - BULB              |           |          |          |                           |           |           | Component ATA:33 |
| PN:PN                     | MOS/MSC                                 |           | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                     |           |          |          |                           |           |           |                  |
|                           | AFL                                     |           |          |          |                           |           |           |                  |
| 335001                    | EMERGENCY LIGHTING INERTIA SWITCH       |           |          |          |                           |           |           | Component ATA:33 |
| PN:PN                     | MOS/MSC                                 | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 33.050               | AFL                                     | 0         |          | TSN 0    |                           |           |           |                  |
| 335009                    | FORWARD EMERGENCY LIGHTING POWER SUPPLY |           |          |          |                           |           |           | Component ATA:33 |
| PN:60-0304-51             | MOS/MSC                                 | 09-Mar-04 | O/C      | TSN 0    |                           |           |           |                  |
| SN:32531                  | HRS                                     | 2632.6    |          | TSN 0    |                           |           |           |                  |
| WC#: 33.090               | AFL                                     | 1434      |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                         |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                                | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 33 - LIGHTS           |                                     |           |          |          |                           |           |           |                  |
| 335011                    | AFT EMERGENCY LIGHTING POWER SUPPLY |           |          |          |                           |           |           | Component ATA:33 |
| PN:60-0304-51             | MOS/MSC                             | 02-Oct-20 | O/C      |          |                           |           |           |                  |
| SN:32284                  | HRS                                 | 5801      |          |          |                           |           |           |                  |
| WC#: 33.095               | AFL                                 | 3399      |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                     |           |          |          |                           |           |           |                  |
| 335025                    | NO. 1 (AA PNL) DIMMER               |           |          |          |                           |           |           | Component ATA:33 |
| PN:LT-52A                 | MOS/MSC                             | 30-Aug-96 | O/C      |          |                           |           |           |                  |
| SN:13668                  | HRS                                 | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 33.055               | AFL                                 | 9         |          |          |                           |           |           |                  |
| 335027                    | NO. 2 (AA PNL) DIMMER               |           |          |          |                           |           |           | Component ATA:33 |
| PN:LT-52A                 | MOS/MSC                             | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:13499                  | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 33.055               | AFL                                 | 0         |          |          |                           |           |           |                  |
| 335029                    | NO. 1 (AB PNL) DIMMER               |           |          |          |                           |           |           | Component ATA:33 |
| PN:LT-52A                 | MOS/MSC                             | 30-Aug-96 | O/C      |          |                           |           |           |                  |
| SN:13562                  | HRS                                 | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 33.060               | AFL                                 | 9         |          |          |                           |           |           |                  |
| 335031                    | NO. 2 (AB PNL) DIMMER               |           |          |          |                           |           |           | Component ATA:33 |
| PN:LT-52A                 | MOS/MSC                             | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:13573                  | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 33.060               | AFL                                 | 0         |          |          |                           |           |           |                  |
| 335200                    | PULSELIGHT CONTROL UNIT             |           |          |          |                           |           |           | Component ATA:33 |
| PN:2400-25-4-4            | MOS/MSC                             | 16-Dec-22 | O/C      |          |                           |           |           |                  |
| SN:1T01177                | HRS                                 | 6495.5    |          |          |                           |           |           |                  |
| WC#: 33.085               | AFL                                 | 3906      |          |          |                           |           |           |                  |
| 335201 <sup>U</sup>       | PULSE LIGHT CURRENT LIMITER         |           |          |          |                           |           |           | Component ATA:33 |
| PN:5000                   | MOS/MSC                             | 30-May-96 | A/R      | TSN 0    |                           |           |           |                  |
| SN:CL0011                 | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
|                           | AFL                                 | 0         |          | TSN 0    |                           |           |           |                  |
| 335301B <sup>U</sup>      | LH RADOME / NOSE- TAXI LIGHT- BULB  |           |          |          |                           |           |           | Component ATA:33 |
| PN:PN                     | MOS/MSC                             |           | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                 |           |          |          |                           |           |           |                  |
|                           | AFL                                 |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN               | Unit    | C/W                                | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |
|-----------------------|---------|------------------------------------|----------|----------|---------------------------|-----------|-----------|-------------|
| ATA 33 - LIGHTS       |         |                                    |          |          |                           |           |           |             |
| 335302B <sup>U</sup>  |         | RH RADOME / NOSE- TAXI LIGHT- BULB |          |          |                           |           | Component | ATA:33      |
| PN:GE4594             | MOS/MSC | 21-Dec-21                          | O/C      | TSN 0    |                           |           |           |             |
| SN:NSN                | HRS     | 6264.3                             |          | TSN 0    |                           |           |           |             |
|                       | AFL     | 3743                               |          | TSN 0    |                           |           |           |             |
| 335704LB <sup>U</sup> |         | LH WING LANDING LIGHT - BULB       |          |          |                           |           | Component | ATA:33      |
| PN:PN                 | MOS/MSC |                                    | O/C      |          |                           |           |           |             |
| SN:UNKNOWN            | HRS     |                                    |          |          |                           |           |           |             |
|                       | AFL     |                                    |          |          |                           |           |           |             |
| 335704TB <sup>U</sup> |         | LH WING TAXI LIGHT - BULB          |          |          |                           |           | Component | ATA:33      |
| PN:PN                 | MOS/MSC |                                    | O/C      |          |                           |           |           |             |
| SN:UNKNOWN            | HRS     |                                    |          |          |                           |           |           |             |
|                       | AFL     |                                    |          |          |                           |           |           |             |
| 335705LB <sup>U</sup> |         | RH WING LANDING LIGHT - BULB       |          |          |                           |           | Component | ATA:33      |
| PN:PN                 | MOS/MSC |                                    | O/C      |          |                           |           |           |             |
| SN:UNKNOWN            | HRS     |                                    |          |          |                           |           |           |             |
|                       | AFL     |                                    |          |          |                           |           |           |             |
| 335705TB <sup>U</sup> |         | RH WING TAXI LIGHT - BULB          |          |          |                           |           | Component | ATA:33      |
| PN:PN                 | MOS/MSC |                                    | O/C      |          |                           |           |           |             |
| SN:UNKNOWN            | HRS     |                                    |          |          |                           |           |           |             |
|                       | AFL     |                                    |          |          |                           |           |           |             |
| 336010 <sup>U</sup>   |         | CABIN LIGHT CONTROLLER             |          |          |                           |           | Component | ATA:33      |
| PN:MSM2804-4          | MOS/MSC | 11-Mar-06                          | O/C      |          |                           |           |           |             |
| SN:301480             | HRS     | 3095.4                             |          |          |                           |           |           |             |
|                       | AFL     | 1734                               |          |          |                           |           |           |             |
| 336027                |         | NO. 5 POWER CONVERTER              |          |          |                           |           | Component | ATA:33      |
| PN:PN                 | MOS/MSC | 30-May-96                          | O/C      | TSN 0    |                           |           |           |             |
| SN:UNKNOWN            | HRS     | 0                                  |          | TSN 0    |                           |           |           |             |
| WC#: 33.070           | AFL     | 0                                  |          | TSN 0    |                           |           |           |             |
| 336028                |         | NO. 6 POWER CONVERTER              |          |          |                           |           | Component | ATA:33      |
| PN:PN                 | MOS/MSC | 30-May-96                          | O/C      | TSN 0    |                           |           |           |             |
| SN:UNKNOWN            | HRS     | 0                                  |          | TSN 0    |                           |           |           |             |
| WC#: 33.070           | AFL     | 0                                  |          | TSN 0    |                           |           |           |             |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN             | Unit                               | C/W       | Interval                                             | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition      |
|---------------------|------------------------------------|-----------|------------------------------------------------------|----------|---------------------------|-----------|---------------|------------------|
| ATA 33 - LIGHTS     |                                    |           |                                                      |          |                           |           |               |                  |
| 336029              | NO. 7 POWER CONVERTER              |           |                                                      |          |                           |           |               | Component ATA:33 |
| PN:PN               | MOS/MSC                            | 30-May-96 | O/C                                                  | TSN 0    |                           |           |               |                  |
| SN:UNKNOWN          | HRS                                | 0         |                                                      | TSN 0    |                           |           |               |                  |
| WC#: 33.070         | AFL                                | 0         |                                                      | TSN 0    |                           |           |               |                  |
| 336030              | NO. 8 POWER CONVERTER              |           |                                                      |          |                           |           |               | Component ATA:33 |
| PN:PN               | MOS/MSC                            | 30-May-96 | O/C                                                  | TSN 0    |                           |           |               |                  |
| SN:UNKNOWN          | HRS                                | 0         |                                                      | TSN 0    |                           |           |               |                  |
| WC#: 33.070         | AFL                                | 0         |                                                      | TSN 0    |                           |           |               |                  |
| 336040              | ESCAPE HATCH BETALIGHT "EXIT" SIGN |           |                                                      |          |                           |           |               | Component ATA:33 |
| PN:132848-11        | MOS                                | 24-Sep-21 | 72 (+24m)                                            | TSN 0    | 03-Sep-27                 | 03-Sep-29 | 1676 d (+731) | REPLACE          |
| SN:40846            | HRS                                | 6141.4    |                                                      | TSN 0    |                           |           |               |                  |
|                     | AFL                                | 3647      |                                                      | TSN 0    |                           |           |               |                  |
|                     |                                    |           | Manufacture Date:: 03-Sep-21 PROC. REF: AMM 33-50-05 |          |                           |           |               |                  |
| 336071 <sup>U</sup> | #1 L/H UPPER INVERTER              |           |                                                      |          |                           |           |               | Component ATA:33 |
| PN:AL-0581          | MOS/MSC                            | 20-Jan-09 | O/C                                                  |          |                           |           |               |                  |
| SN:8995             | HRS                                |           |                                                      |          |                           |           |               |                  |
|                     | AFL                                |           |                                                      |          |                           |           |               |                  |
| 336072 <sup>U</sup> | #2 TOP RIGHT INVERTER              |           |                                                      |          |                           |           |               | Component ATA:33 |
| PN:AL-0581          | MOS/MSC                            | 19-Jan-09 | O/C                                                  |          |                           |           |               |                  |
| SN:10432            | HRS                                | 3898.2    |                                                      |          |                           |           |               |                  |
|                     | AFL                                | 2179      |                                                      |          |                           |           |               |                  |
| 336073 <sup>U</sup> | #3 LOWER INVERTER                  |           |                                                      |          |                           |           |               | Component ATA:33 |
| PN:AL-0581          | MOS/MSC                            | 20-Jan-09 | O/C                                                  |          |                           |           |               |                  |
| SN:10656            | HRS                                |           |                                                      |          |                           |           |               |                  |
|                     | AFL                                |           |                                                      |          |                           |           |               |                  |
| ATA 34 - NAVIGATION |                                    |           |                                                      |          |                           |           |               |                  |
| 340001 <sup>U</sup> | AVIONICS INSPECTION                |           |                                                      |          |                           |           |               | Service ATA:34   |
|                     | MOS                                | 20-Jan-23 | 24                                                   |          | 31-Jan-25                 |           | 731 d         |                  |
|                     | HRS                                | 6526.5    |                                                      |          |                           |           |               |                  |
|                     | AFL                                | 3926      |                                                      |          |                           |           |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                | Unit                                                         | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition                         |
|--------------------------------------------------------|--------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-------------|-------------------------------------|
| ATA 34 - NAVIGATION                                    |                                                              |           |                |          |                           |           |             |                                     |
| 340002                                                 | DRAIN PITOT/STATIC DRAIN TRAPS                               |           |                |          |                           |           |             | Service ATA:34                      |
|                                                        | MOS                                                          | 20-Jan-23 | 24 (+2m)       |          | 20-Jan-25                 | 20-Mar-25 | 720 d (+59) |                                     |
|                                                        | HRS                                                          | 6526.5    |                |          |                           |           |             |                                     |
| WC#: 34.025                                            | AFL                                                          | 3926      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS OUT OF PHASE INSPECTIONS, AMM 34-11-19 |                                                              |           |                |          |                           |           |             |                                     |
| 340003                                                 | INSPECT AUTOPILOT AILERON SERVO UNIT AND MOUNT               |           |                |          |                           |           |             | Service ATA:34                      |
|                                                        | MOS                                                          | 06-May-15 |                |          |                           |           |             |                                     |
|                                                        | HRS                                                          | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 34.405                                            | AFL                                                          | 2873      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INSPECTION C4                          |                                                              |           |                |          |                           |           |             |                                     |
|                                                        |                                                              |           |                |          |                           |           |             | PKG:3,23<br>WO#: N950PC B & C CHECK |
| 340004                                                 | INSPECT AUTOPILOT SERVO UNITS, RUDDER AND ELEVATOR           |           |                |          |                           |           |             | Service ATA:34                      |
|                                                        | MOS                                                          | 06-May-15 |                |          |                           |           |             |                                     |
|                                                        | HRS                                                          | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 34.410                                            | AFL                                                          | 2873      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INSPECTION C7                          |                                                              |           |                |          |                           |           |             |                                     |
|                                                        |                                                              |           |                |          |                           |           |             | PKG:3,26<br>WO#: N950PC B & C CHECK |
| 340005                                                 | INSPECT AUTOPILOT ELEVATOR TRIM SERVO UNIT AND MOUNT         |           |                |          |                           |           |             | Service ATA:34                      |
|                                                        | MOS                                                          | 06-May-15 |                |          |                           |           |             |                                     |
|                                                        | HRS                                                          | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 34.415                                            | AFL                                                          | 2873      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INSPECTION C7                          |                                                              |           |                |          |                           |           |             |                                     |
|                                                        |                                                              |           |                |          |                           |           |             | PKG:3,26<br>WO#: N950PC B & C CHECK |
| 340006                                                 | PRESSURE/SUCTION TEST PITOT/STATIC AND STALL WARNING SYSTEMS |           |                |          |                           |           |             | Service ATA:34                      |
|                                                        | MOS                                                          | 20-Jan-23 | 24 (+2m)       |          | 20-Jan-25                 | 20-Mar-25 | 720 d (+59) |                                     |
|                                                        | HRS                                                          | 6526.5    |                |          |                           |           |             |                                     |
| WC#: 34.015                                            | AFL                                                          | 3926      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS OUT OF PHASE INSPECTIONS, AMM 34-11-19 |                                                              |           |                |          |                           |           |             |                                     |
| 340007                                                 | CHECK PITOT SYSTEM ISOLATION VALVES                          |           |                |          |                           |           |             | Service ATA:34                      |
|                                                        | MOS                                                          | 20-Jan-23 | 24 (+2m)       |          | 20-Jan-25                 | 20-Mar-25 | 720 d (+59) |                                     |
|                                                        | HRS                                                          | 6526.5    |                |          |                           |           |             |                                     |
| WC#: 34.290                                            | AFL                                                          | 3926      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS OUT OF PHASE INSPECTIONS               |                                                              |           |                |          |                           |           |             |                                     |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                                             | Unit                                                               | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition    |
|-------------------------------------------------------------------------------------|--------------------------------------------------------------------|-----------|-----------------|----------|---------------------------|-----------|---------------|----------------|
| ATA 34 - NAVIGATION                                                                 |                                                                    |           |                 |          |                           |           |               |                |
| 340008                                                                              | TEST MACH TRIM SYSTEM                                              |           |                 |          |                           |           |               | Service ATA:34 |
|                                                                                     | MOS                                                                | 18-Aug-17 |                 |          |                           |           |               |                |
|                                                                                     | HRS                                                                | 5554.6    | 3200 (+150/-50) |          | 8754.6                    | 8904.6    | 2226.3 (+150) |                |
| WC#: 34.270                                                                         | AFL                                                                | 3197      |                 |          |                           |           |               |                |
| PROC. REF: AFMS INSPECTION D1, AMM 34-24-00                                         |                                                                    |           |                 |          |                           |           | PKG:4,32      |                |
| 340010                                                                              | TEST AUTOTRIM COMMAND ISOLATION RELAY AND AUTOTRIM SWITCHING RELAY |           |                 |          |                           |           |               | Service ATA:34 |
|                                                                                     | MOS                                                                | 18-Aug-17 |                 |          |                           |           |               |                |
|                                                                                     | HRS                                                                | 5554.6    | 3200 (+150/-50) |          | 8754.6                    | 8904.6    | 2226.3 (+150) |                |
| WC#: 34.425                                                                         | AFL                                                                | 3197      |                 |          |                           |           |               |                |
| PROC. REF: AFMS INSPECTION D1, AMM 27-30-00                                         |                                                                    |           |                 |          |                           |           | PKG:4,32      |                |
| 340011                                                                              | CHECK MACH TRIM FAIL ANNUNCIATION RELAYS                           |           |                 |          |                           |           |               | Service ATA:34 |
|                                                                                     | MOS                                                                | 18-Aug-17 |                 |          |                           |           |               |                |
|                                                                                     | HRS                                                                | 5554.6    | 3200 (+150/-50) |          | 8754.6                    | 8904.6    | 2226.3 (+150) |                |
| WC#: 34.420                                                                         | AFL                                                                | 3197      |                 |          |                           |           |               |                |
| PROC. REF: AFMS INSPECTION D1                                                       |                                                                    |           |                 |          |                           |           | PKG:4,32      |                |
| 340012                                                                              | SWING CHECK NO. 1 COMPASS                                          |           |                 |          |                           |           |               | Service ATA:34 |
|                                                                                     | MOS                                                                | 20-Jan-23 | 36 (+2m)        |          | 20-Jan-26                 | 20-Mar-26 | 1085 d (+59)  |                |
|                                                                                     | HRS                                                                | 6526.5    |                 |          |                           |           |               |                |
| WC#: 34.095                                                                         | AFL                                                                | 3926      |                 |          |                           |           |               |                |
| PROC. REF: AMM 34-23-61, AMM 34-09-111, AFMS OUT OF PHASE INSPECTIONS, AMM 34-20-15 |                                                                    |           |                 |          |                           |           |               |                |
| 340012                                                                              | SWING CHECK NO. 2 COMPASS                                          |           |                 |          |                           |           |               | Service ATA:34 |
|                                                                                     | MOS                                                                | 20-Jan-23 | 36 (+2m)        |          | 20-Jan-26                 | 20-Mar-26 | 1085 d (+59)  |                |
|                                                                                     | HRS                                                                | 6526.5    |                 |          |                           |           |               |                |
| WC#: 34.095                                                                         | AFL                                                                | 3926      |                 |          |                           |           |               |                |
| PROC. REF: AMM 34-23-61, AMM 34-09-111, AFMS OUT OF PHASE INSPECTIONS, AMM 34-20-15 |                                                                    |           |                 |          |                           |           |               |                |
| 340012                                                                              | SWING CHECK STANDBY COMPASS                                        |           |                 |          |                           |           |               | Service ATA:34 |
|                                                                                     | MOS                                                                | 20-Jan-23 | 36 (+2m)        |          | 20-Jan-26                 | 20-Mar-26 | 1085 d (+59)  |                |
|                                                                                     | HRS                                                                | 6526.5    |                 |          |                           |           |               |                |
| WC#: 34.095                                                                         | AFL                                                                | 3926      |                 |          |                           |           |               |                |
| PROC. REF: AMM 34-23-61, AMM 34-09-111, AFMS OUT OF PHASE INSPECTIONS, AMM 34-20-15 |                                                                    |           |                 |          |                           |           |               |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                  | Unit                                                             | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|------------------------------------------|------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION                      |                                                                  |           |          |          |                           |           |           |                  |
| 340013                                   | COMPLY WITH RVSM REQUIREMENTS FOR THE STATIC PLATES AND AIRFRAME |           |          |          |                           |           |           | Service ATA:34   |
|                                          | MOS/MSC                                                          | 26-Dec-06 | A/R      |          |                           |           |           |                  |
|                                          | HRS                                                              | 3347.2    |          |          |                           |           |           |                  |
| WC#: 34.020                              | AFL                                                              | 1880      |          |          |                           |           |           |                  |
| PROC. REF: AFMS OUT OF PHASE INSPECTIONS |                                                                  |           |          |          |                           |           |           |                  |
| 341001                                   | LEFT PITOT PRESSURE HEAD                                         |           |          |          |                           |           |           | Component ATA:34 |
| PN:853JF1                                | MOS/MSC                                                          | 09-Mar-04 | O/C      | TSN 0    |                           |           |           |                  |
| SN:10932                                 | HRS                                                              | 2632.6    |          | TSN 0    |                           |           |           |                  |
| WC#: 34.010                              | AFL                                                              | 1434      |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 34-11-24                  |                                                                  |           |          |          |                           |           |           |                  |
| 341002                                   | RIGHT PITOT PRESSURE HEAD                                        |           |          |          |                           |           |           | Component ATA:34 |
| PN:853JF1                                | MOS/MSC                                                          | 09-Mar-04 | O/C      | TSN 0    |                           |           |           |                  |
| SN:11043                                 | HRS                                                              | 2632.6    |          | TSN 0    |                           |           |           |                  |
| WC#: 34.010                              | AFL                                                              | 1434      |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 34-11-24                  |                                                                  |           |          |          |                           |           |           |                  |
| 341003 <sup>U</sup>                      | LEFT HEATED STATIC PORT                                          |           |          |          |                           |           |           | Component ATA:34 |
| PN:E42024-1                              | MOS/MSC                                                          | 15-Oct-07 | O/C      |          |                           |           |           |                  |
| SN:5562                                  | HRS                                                              | 3557.1    |          |          |                           |           |           |                  |
|                                          | AFL                                                              | 2001      |          |          |                           |           |           |                  |
| 341004 <sup>U</sup>                      | RIGHT HEATED STATIC PORT                                         |           |          |          |                           |           |           | Component ATA:34 |
| PN:E42024-2                              | MOS/MSC                                                          | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                               | HRS                                                              | 0         |          | TSN 0    |                           |           |           |                  |
|                                          | AFL                                                              | 0         |          | TSN 0    |                           |           |           |                  |
| 341073                                   | LEFT ALTIMETER                                                   |           |          |          |                           |           |           | Component ATA:34 |
| PN:4016341-905                           | MOS/MSC                                                          | 20-Jan-23 | O/C      |          |                           |           |           |                  |
| SN:87064645                              | HRS                                                              | 6526.5    |          |          |                           |           |           |                  |
| WC#: 34.030                              | AFL                                                              | 3926      |          |          |                           |           |           |                  |
| PROC. REF: AMM 34-10-05                  |                                                                  |           |          |          |                           |           |           |                  |
| 341074                                   | RIGHT ALTIMETER                                                  |           |          |          |                           |           |           | Component ATA:34 |
| PN:4016341-905                           | MOS/MSC                                                          | 20-Jan-23 | O/C      |          |                           |           |           |                  |
| SN:96078394                              | HRS                                                              | 6526.5    |          |          |                           |           |           |                  |
| WC#: 34.035                              | AFL                                                              | 3926      |          |          |                           |           |           |                  |
| PROC. REF: AMM 34-10-05                  |                                                                  |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                    | Unit                                | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------|-------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION        |                                     |           |          |          |                           |           |           |                  |
| 341085                     | TEST LEFT ALTIMETER (FAR 91.411)    |           |          |          |                           |           |           | Service ATA:34   |
| PN:4016341-905             | MOS                                 | 20-Jan-23 | 24       |          | 20-Jan-25                 |           | 720 d     | MANDATORY        |
| SN:87064645                | HRS                                 |           |          |          |                           |           |           |                  |
| WC#: 34.030                | AFL                                 |           |          |          |                           |           |           |                  |
| PROC. REF: FAR FAR PART 91 |                                     |           |          |          |                           |           |           |                  |
| 341086                     | TEST RIGHT ALTIMETER (FAR 91.411)   |           |          |          |                           |           |           | Service ATA:34   |
| PN:4016341-905             | MOS                                 | 20-Jan-23 | 24       |          | 20-Jan-25                 |           | 720 d     | MANDATORY        |
| SN:96078394                | HRS                                 |           |          |          |                           |           |           |                  |
| WC#: 34.035                | AFL                                 |           |          |          |                           |           |           |                  |
| PROC. REF: FAR FAR PART 91 |                                     |           |          |          |                           |           |           |                  |
| 341097                     | STANDBY ALTIMETER                   |           |          |          |                           |           |           | Component ATA:34 |
| PN:1611AM3                 | MOS/MSC                             | 20-Jan-23 | O/C      |          |                           |           |           |                  |
| SN:AH792                   | HRS                                 | 6526.5    |          |          |                           |           |           |                  |
| WC#: 34.040                | AFL                                 | 3926      |          |          |                           |           |           |                  |
| PROC. REF: AMM NO REF      |                                     |           |          |          |                           |           |           |                  |
| 341103                     | TEST STANDBY ALTIMETER (FAR 91.411) |           |          |          |                           |           |           | Service ATA:34   |
| PN:1611AM3                 | MOS                                 | 20-Jan-23 | 24       |          | 20-Jan-25                 |           | 720 d     | MANDATORY        |
| SN:AH792                   | HRS                                 |           |          |          |                           |           |           |                  |
| WC#: 34.040                | AFL                                 |           |          |          |                           |           |           |                  |
| PROC. REF: FAR FAR PART 91 |                                     |           |          |          |                           |           |           |                  |
| 341115                     | STANDBY AIRSPEED INDICATOR          |           |          |          |                           |           |           | Component ATA:34 |
| PN:WL271ASI                | MOS/MSC                             | 30-Aug-96 | O/C      |          |                           |           |           |                  |
| SN:AJ993                   | HRS                                 | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 34.045                | AFL                                 | 9         |          |          |                           |           |           |                  |
| PROC. REF: AMM NO REF      |                                     |           |          |          |                           |           |           |                  |
| 341163                     | LEFT SAT/TAS INDICATOR              |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                      | MOS/MSC                             | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                 | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.320                | AFL                                 | 0         |          | TSN 0    |                           |           |           |                  |
| 341164                     | RIGHT SAT/TAS INDICATOR             |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                      | MOS/MSC                             | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                 | HRS                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.320                | AFL                                 | 0         |          | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                               | Unit                        | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------------------------------------|-----------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION                                   |                             |           |          |          |                           |           |           |                  |
| 341195                                                | VOICE ADVISORY              |           |          |          |                           |           |           | Component ATA:34 |
| PN:7001433-902(VA-100)                                | MOS/MSC                     | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                                            | HRS                         | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.060                                           | AFL                         | 0         |          |          |                           |           |           |                  |
| PROC. REF: MMA 31-50-00, AMM NO REF                   |                             |           |          |          |                           |           |           |                  |
| 341228                                                | NO. 1 AIR DATA COMPUTER     |           |          |          |                           |           |           | Component ATA:34 |
| PN:7000700-668                                        | MOS/MSC                     | 20-Jan-23 | O/C      |          |                           |           |           |                  |
| SN:96067176                                           | HRS                         | 6526.5    |          |          |                           |           |           |                  |
| WC#: 34.065                                           | AFL                         | 3926      |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF, AMM 34-10-05, AMM 34-10-17 |                             |           |          |          |                           |           |           |                  |
| 341229                                                | NO. 2 AIR DATA COMPUTER     |           |          |          |                           |           |           | Component ATA:34 |
| PN:7000700-668                                        | MOS/MSC                     | 20-Jan-23 | O/C      |          |                           |           |           |                  |
| SN:96077240                                           | HRS                         | 6526.5    |          |          |                           |           |           |                  |
| WC#: 34.066                                           | AFL                         | 3926      |          |          |                           |           |           |                  |
| PROC. REF: GENERIC NO REF, AMM 34-10-05, AMM 34-10-17 |                             |           |          |          |                           |           |           |                  |
| 341230                                                | NO. 1 AIR DATA MODULE       |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                                                 | MOS/MSC                     | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                            | HRS                         | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.325                                           | AFL                         | 0         |          | TSN 0    |                           |           |           |                  |
| 341231                                                | NO. 2 AIR DATA MODULE       |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                                                 | MOS/MSC                     | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                            | HRS                         | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.325                                           | AFL                         | 0         |          | TSN 0    |                           |           |           |                  |
| 341234                                                | SIGNAL INTERFERENCE ADAPTER |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                                                 | MOS/MSC                     | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                            | HRS                         | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.330                                           | AFL                         | 0         |          | TSN 0    |                           |           |           |                  |
| 341235                                                | (ESIS) MAGNETOMETER         |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                                                 | MOS/MSC                     | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                            | HRS                         | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.485                                           | AFL                         | 0         |          | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                | Unit                                     | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition               |
|--------------------------------------------------------|------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|---------------------------|
| ATA 34 - NAVIGATION                                    |                                          |           |          |          |                           |           |           |                           |
| 341237                                                 | AIR DATA ESIS UNIT                       |           |          |          |                           |           |           | Component ATA:34          |
| PN:PN-UNKNOWN                                          | MOS/MSC                                  | 20-Jan-23 | O/C      |          |                           |           |           |                           |
| SN:UNKNOWN                                             | HRS                                      | 6526.5    |          |          |                           |           |           |                           |
| WC#: 34.435                                            | AFL                                      | 3926      |          |          |                           |           |           |                           |
| 341238                                                 | TEST AIR DATA ESIS UNIT (FAA 91.411)     |           |          |          |                           |           |           | Service ATA:34            |
| PN:PN-UNKNOWN                                          | MOS                                      | 20-Jan-23 | 24       |          | 20-Jan-25                 |           | 720 d     | MANDATORY                 |
| SN:UNKNOWN                                             | HRS                                      |           |          |          |                           |           |           |                           |
| WC#: 34.435                                            | AFL                                      |           |          |          |                           |           |           |                           |
| PROC. REF: FAR FAR PART 91                             |                                          |           |          |          |                           |           |           |                           |
| 341240                                                 | TEST NO.1 AIR DATA COMPUTER (FAA 91.411) |           |          |          |                           |           |           | Service ATA:34            |
| PN:7000700-668                                         | MOS                                      | 20-Jan-23 | 24       |          | 20-Jan-25                 |           | 720 d     | MANDATORY                 |
| SN:96067176                                            | HRS                                      |           |          |          |                           |           |           |                           |
| WC#: 34.065                                            | AFL                                      |           |          |          |                           |           |           |                           |
| PROC. REF: AMM 34-10-05, AMM 34-10-15, FAR FAR PART 91 |                                          |           |          |          |                           |           |           |                           |
| 341241                                                 | TEST NO.2 AIR DATA COMPUTER (FAA 91.411) |           |          |          |                           |           |           | Service ATA:34            |
| PN:7000700-668                                         | MOS                                      | 20-Jan-23 | 24       |          | 20-Jan-25                 |           | 720 d     | MANDATORY                 |
| SN:96077240                                            | HRS                                      |           |          |          |                           |           |           |                           |
| WC#: 34.066                                            | AFL                                      |           |          |          |                           |           |           |                           |
| PROC. REF: AMM 34-10-05, AMM 34-10-15, FAR FAR PART 91 |                                          |           |          |          |                           |           |           |                           |
| 341276                                                 | RADIO ALTIMETER UNIT                     |           |          |          |                           |           |           | Component ATA:34          |
| PN:7001840-912                                         | MOS/MSC                                  | 17-Aug-08 | O/C      | TSO 0    |                           |           |           |                           |
| SN:88092736                                            | HRS                                      | 3779.9    |          | TSO 0    |                           |           |           |                           |
| WC#: 34.070                                            | AFL                                      | 2117      |          | TSO 0    |                           |           |           |                           |
| PROC. REF: AMM 34-40-05                                |                                          |           |          |          |                           |           |           | WO#: N950PC 48 MONTH INSP |
| 341279                                                 | LEFT RADIO ALTIMETER ANTENNA             |           |          |          |                           |           |           | Component ATA:34          |
| PN:S67-2002                                            | MOS/MSC                                  | 30-Aug-96 | O/C      |          |                           |           |           |                           |
| SN:9357                                                | HRS                                      | 16        |          | TSN 0    |                           |           |           |                           |
| WC#: 34.075                                            | AFL                                      | 9         |          |          |                           |           |           |                           |
| PROC. REF: AMM 34-40-05                                |                                          |           |          |          |                           |           |           |                           |
| 341281                                                 | RIGHT RADIO ALTIMETER ANTENNA            |           |          |          |                           |           |           | Component ATA:34          |
| PN:S67-2002                                            | MOS/MSC                                  | 30-Aug-96 | O/C      |          |                           |           |           |                           |
| SN:9379                                                | HRS                                      | 16        |          | TSN 0    |                           |           |           |                           |
| WC#: 34.080                                            | AFL                                      | 9         |          |          |                           |           |           |                           |
| PROC. REF: AMM 34-40-05                                |                                          |           |          |          |                           |           |           |                           |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                                                                     | Unit                                 | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                 | Disposition      |
|-------------------------------------------------------------------------------------------------------------|--------------------------------------|-----------|----------|----------|---------------------------|-----------|---------------------------|------------------|
| ATA 34 - NAVIGATION                                                                                         |                                      |           |          |          |                           |           |                           |                  |
| 342013                                                                                                      | EMERGENCY GYRO HORIZON INDICATOR     |           |          |          |                           |           |                           | Component ATA:34 |
| PN:501-1656-02                                                                                              | MOS/MSC                              | 29-Jul-10 | O/C      |          |                           |           |                           |                  |
| SN:1410                                                                                                     | HRS                                  | 4239.6    |          |          |                           |           |                           |                  |
| WC#: 34.090                                                                                                 | AFL                                  | 2368      |          |          |                           |           |                           |                  |
| PROC. REF: AMM NO REF                                                                                       |                                      |           |          |          |                           |           |                           |                  |
| 342097                                                                                                      | STANDBY COMPASS (E2B) INDICATOR      |           |          |          |                           |           |                           | Component ATA:34 |
| PN:KCA0104W                                                                                                 | MOS/MSC                              | 30-May-96 | O/C      |          |                           |           |                           |                  |
| SN:AHO570395                                                                                                | HRS                                  | 0         |          | TSN 0    |                           |           |                           |                  |
| WC#: 34.106                                                                                                 | AFL                                  | 0         |          |          |                           |           |                           |                  |
| PROC. REF: AMM 34-09-111                                                                                    |                                      |           |          |          |                           |           |                           |                  |
| 342145                                                                                                      | NO. 1 DATA LOADER                    |           |          |          |                           |           |                           | Component ATA:34 |
| PN:G7226-01                                                                                                 | MOS/MSC                              | 08-Jul-05 | O/C      |          |                           |           |                           |                  |
| SN:235                                                                                                      | HRS                                  | 2883      |          |          |                           |           |                           |                  |
| WC#: 34.115                                                                                                 | AFL                                  | 1598      |          |          |                           |           |                           |                  |
| PROC. REF: AMM 34-60-05, AMM 34-60-15, AMM 34-60-25                                                         |                                      |           |          |          |                           |           |                           |                  |
| 342215 <sup>U</sup>                                                                                         | NO. 1 NAV COMPUTER BATTERY- FMS      |           |          |          |                           |           |                           | Component ATA:34 |
| PN:7020116-1                                                                                                | MOS                                  | 07-Jan-22 | 24       | TSN 1    | 01-Jan-26 (M)             |           | 1066 d                    |                  |
| SN:N/A                                                                                                      | HRS                                  |           |          | TSN 0    |                           |           |                           |                  |
|                                                                                                             | AFL                                  |           |          | TSN 0    |                           |           |                           |                  |
| 342216 <sup>U</sup>                                                                                         | NO. 2 NAV COMPUTER BATTERY- FMS      |           |          |          |                           |           |                           | Component ATA:34 |
| PN:7020116-1                                                                                                | MOS                                  | 09-Aug-22 | 24       | TSN 0    | 01-Aug-26 (M)             |           | 1278 d                    |                  |
| SN:N/A                                                                                                      | DAYS                                 |           |          |          |                           |           |                           |                  |
|                                                                                                             | HRS                                  | 6405      |          | TSN 0    |                           |           |                           |                  |
|                                                                                                             | AFL                                  | 3842      |          | TSN 0    |                           |           |                           |                  |
| 342220                                                                                                      | NO.1 FLIGHT MANAGEMENT COMPUTER- FMS |           |          |          |                           |           |                           | Component ATA:34 |
| PN:7018879-03034                                                                                            | MOS/MSC                              | 06-Sep-18 | O/C      | TSR 0    |                           |           |                           |                  |
| SN:01093397                                                                                                 | HRS                                  |           |          | TSR 0    |                           |           |                           |                  |
| WC#: 34.350                                                                                                 | AFL                                  |           |          | TSR 0    |                           |           |                           |                  |
| PROC. REF: MMA 34-60-15, MMA 34-60-15, MMA 34-60-25, MMA 34-60-25, AMM 34-60-05, AMM 34-60-15, AMM 34-60-25 |                                      |           |          |          |                           |           | WO#: N950PC 48 MONTH INSP |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                                                                     | Unit                                 | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                 | Disposition      |
|-------------------------------------------------------------------------------------------------------------|--------------------------------------|-----------|----------|----------|---------------------------|-----------|---------------------------|------------------|
| ATA 34 - NAVIGATION                                                                                         |                                      |           |          |          |                           |           |                           |                  |
| 342221                                                                                                      | NO.2 FLIGHT MANAGEMENT COMPUTER- FMS |           |          |          |                           |           |                           | Component ATA:34 |
| PN:7018879-03034                                                                                            | MOS/MSC                              | 25-Sep-19 | O/C      | TSR 0    |                           |           |                           |                  |
| SN:96030884                                                                                                 | HRS                                  |           |          | TSR 0    |                           |           |                           |                  |
| WC#: 34.350                                                                                                 | AFL                                  |           |          | TSR 0    |                           |           |                           |                  |
| PROC. REF: MMA 34-60-15, MMA 34-60-15, MMA 34-60-25, MMA 34-60-25, AMM 34-60-05, AMM 34-60-15, AMM 34-60-25 |                                      |           |          |          |                           |           | WO#: N950PC 48 MONTH INSP |                  |
| 342225 <sup>U</sup>                                                                                         | CONTROL NO.1 DISPLAY                 |           |          |          |                           |           |                           | Component ATA:34 |
| PN:7007549-905                                                                                              | MOS/MSC                              | 30-Aug-18 | O/C      | TSR 9    |                           |           |                           |                  |
| SN:00094057                                                                                                 | HRS                                  | 5584.3    |          | TSR 0    |                           |           |                           |                  |
|                                                                                                             | AFL                                  | 3250      |          | TSR 0    |                           |           |                           |                  |
| 342226 <sup>U</sup>                                                                                         | CONTROL NO.2 DISPLAY                 |           |          |          |                           |           |                           | Component ATA:34 |
| PN:7007549-905                                                                                              | MOS/MSC                              | 22-Feb-06 | O/C      |          |                           |           |                           |                  |
| SN:92041118                                                                                                 | HRS                                  | 3079.6    |          |          |                           |           |                           |                  |
|                                                                                                             | AFL                                  | 1724      |          |          |                           |           |                           |                  |
| 342253                                                                                                      | NO. 1 COMPASS FLUX VALVE             |           |          |          |                           |           |                           | Component ATA:34 |
| PN:7010133                                                                                                  | MOS/MSC                              | 30-Aug-96 | O/C      |          |                           |           |                           |                  |
| SN:96033057                                                                                                 | HRS                                  | 16        |          | TSN 0    |                           |           |                           |                  |
| WC#: 34.120                                                                                                 | AFL                                  | 9         |          |          |                           |           |                           |                  |
| PROC. REF: AMM 34-20-15                                                                                     |                                      |           |          |          |                           |           |                           |                  |
| 342254                                                                                                      | NO. 2 COMPASS FLUX VALVE             |           |          |          |                           |           |                           | Component ATA:34 |
| PN:7010133                                                                                                  | MOS/MSC                              | 30-Aug-96 | O/C      |          |                           |           |                           |                  |
| SN:95102904                                                                                                 | HRS                                  | 16        |          | TSN 0    |                           |           |                           |                  |
| WC#: 34.120                                                                                                 | AFL                                  | 9         |          |          |                           |           |                           |                  |
| PROC. REF: AMM 34-20-15                                                                                     |                                      |           |          |          |                           |           |                           |                  |
| 342265                                                                                                      | NO. 1 AHRs COMPUTER                  |           |          |          |                           |           |                           | Component ATA:34 |
| PN:7003360-943                                                                                              | MOS/MSC                              | 23-Jun-11 | O/C      |          |                           |           |                           |                  |
| SN:89101502                                                                                                 | HRS                                  | 4454.6    |          |          |                           |           |                           |                  |
| WC#: 34.125                                                                                                 | AFL                                  | 2487      |          |          |                           |           |                           |                  |
| PROC. REF: AMM 34-23-61                                                                                     |                                      |           |          |          |                           |           |                           |                  |
| 342266                                                                                                      | NO. 2 AHRs COMPUTER                  |           |          |          |                           |           |                           | Component ATA:34 |
| PN:7003360-943                                                                                              | MOS/MSC                              | 28-Jun-17 | O/C      | TSR 0    |                           |           |                           |                  |
| SN:91042013                                                                                                 | HRS                                  |           |          | TSR 0    |                           |           |                           |                  |
| WC#: 34.125                                                                                                 | AFL                                  |           |          | TSR 0    |                           |           |                           |                  |
| PROC. REF: AMM 34-23-61                                                                                     |                                      |           |          |          |                           |           |                           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                 | Unit                                                                        | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------|-----------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION     |                                                                             |           |          |          |                           |           |           |                  |
| 342289                  | NO. 1 AHRS CONTROLLER                                                       |           |          |          |                           |           |           | Component ATA:34 |
| PN:7004545-901          | MOS/MSC                                                                     | 30-Aug-96 | O/C      |          |                           |           |           |                  |
| SN:96031710             | HRS                                                                         | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 34.140             | AFL                                                                         | 9         |          |          |                           |           |           |                  |
| PROC. REF: AMM 34-20-15 |                                                                             |           |          |          |                           |           |           |                  |
| 342290                  | NO. 2 AHRS CONTROLLER                                                       |           |          |          |                           |           |           | Component ATA:34 |
| PN:7004545-901          | MOS/MSC                                                                     | 30-Aug-96 | O/C      |          |                           |           |           |                  |
| SN:96041734             | HRS                                                                         | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 34.140             | AFL                                                                         | 9         |          |          |                           |           |           |                  |
| PROC. REF: AMM 34-20-15 |                                                                             |           |          |          |                           |           |           |                  |
| 342501                  | NO. 1 MULTIFUNCTION DISPLAY                                                 |           |          |          |                           |           |           | Component ATA:34 |
| PN:7510100-731          | MOS/MSC                                                                     | 15-Oct-10 | O/C      | TSR 0    |                           |           |           |                  |
| SN:88080175             | HRS                                                                         | 4275.1    |          | TSR 0    |                           |           |           |                  |
| WC#: 34.130             | AFL                                                                         | 2389      |          | TSR 0    |                           |           |           |                  |
| PROC. REF: AMM 34-70-05 |                                                                             |           |          |          |                           |           |           |                  |
| 342502                  | NO. 2 MULTIFUNCTION DISPLAY                                                 |           |          |          |                           |           |           | Component ATA:34 |
| PN:7003110-901          | MOS/MSC                                                                     | 02-Apr-14 | O/C      |          |                           |           |           |                  |
| SN:84070448             | HRS                                                                         | 5099.1    |          |          |                           |           |           |                  |
| WC#: 34.135             | AFL                                                                         | 2856      |          |          |                           |           |           |                  |
| PROC. REF: AMM 34-70-05 |                                                                             |           |          |          |                           |           |           |                  |
| 342503                  | NO. 1 ELECTRONIC FLIGHT INSTRUMENT SYSTEM ATTITUDE DIRECTION INDICATOR(ADI) |           |          |          |                           |           |           | Component ATA:34 |
| PN:7003110-901          | MOS/MSC                                                                     | 25-Jan-19 | O/C      | TSR 1    |                           |           |           |                  |
| SN:86081401             | HRS                                                                         |           |          | TSR 0    |                           |           |           |                  |
|                         | AFL                                                                         |           |          | TSR 0    |                           |           |           |                  |
| 342504                  | NO. 2 ELECTRONIC FLIGHT INSTRUMENT SYSTEM ATTITUDE DIRECTION INDICATOR(ADI) |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                   | MOS/MSC                                                                     | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN              | HRS                                                                         | 0         |          | TSN 0    |                           |           |           |                  |
|                         | AFL                                                                         | 0         |          | TSN 0    |                           |           |           |                  |
| 342513                  | NO. 1 PRIMARY FLIGHT DISPLAY                                                |           |          |          |                           |           |           | Component ATA:34 |
| PN:7003110-901          | MOS/MSC                                                                     | 21-Sep-08 | O/C      |          |                           |           |           |                  |
| SN:0104A299             | HRS                                                                         | 3803.7    |          |          |                           |           |           |                  |
| WC#: 34.130             | AFL                                                                         | 2128      |          |          |                           |           |           |                  |
| PROC. REF: AMM 34-70-05 |                                                                             |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                               | Unit                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------------------|---------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION                   |                                       |           |          |          |                           |           |           |                  |
| 342514                                | NO. 2 PRIMARY FLIGHT DISPLAY          |           |          |          |                           |           |           | Component ATA:34 |
| PN:7003110-901                        | MOS/MSC                               | 11-Sep-09 | O/C      |          |                           |           |           |                  |
| SN:92022325                           | HRS                                   | 4035.1    |          |          |                           |           |           |                  |
| WC#: 34.135                           | AFL                                   | 2258      |          |          |                           |           |           |                  |
| PROC. REF: AMM 34-70-05               |                                       |           |          |          |                           |           |           |                  |
| 342515                                | EFIS MULTIFUNCTION ELECTRONIC DISPLAY |           |          |          |                           |           |           | Component ATA:34 |
| PN:7003110-901                        | MOS/MSC                               | 02-Dec-22 | O/C      |          |                           |           |           |                  |
| SN:91035618                           | HRS                                   | 6488.1    |          |          |                           |           |           |                  |
| WC#: 34.140                           | AFL                                   | 3901      |          |          |                           |           |           |                  |
| PROC. REF: MMA 34-70-13, AMM 34-20-15 |                                       |           |          |          |                           |           |           |                  |
| 342516                                | NO. 1 REMOTE INSTRUMENT CONTROL       |           |          |          |                           |           |           | Component ATA:34 |
| PN:7011345-901                        | MOS/MSC                               | 25-May-11 | O/C      |          |                           |           |           |                  |
| SN:00071405                           | HRS                                   | 4436.4    |          |          |                           |           |           |                  |
| WC#: 34.145                           | AFL                                   | 2475      |          |          |                           |           |           |                  |
| PROC. REF: AMM 34-70-05               |                                       |           |          |          |                           |           |           |                  |
| 342517                                | NO. 2 REMOTE INSTRUMENT CONTROL       |           |          |          |                           |           |           | Component ATA:34 |
| PN:7011345-911                        | MOS/MSC                               | 30-Aug-96 | O/C      |          |                           |           |           |                  |
| SN:96041057                           | HRS                                   | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 34.145                           | AFL                                   | 9         |          |          |                           |           |           |                  |
| PROC. REF: AMM 34-70-05               |                                       |           |          |          |                           |           |           |                  |
| 342523                                | MULTIFUNCTION PROCESS UNIT            |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                                 | MOS/MSC                               | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.335                           | AFL                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WO#: N950PC 48 MONTH INSP             |                                       |           |          |          |                           |           |           |                  |
| 342525                                | NO. 1 EFIS DISPLAY PROCESSOR          |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                                 | MOS/MSC                               | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.335                           | AFL                                   | 0         |          | TSN 0    |                           |           |           |                  |
| 342526                                | NO. 2 EFIS DISPLAY PROCESSOR          |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                                 | MOS/MSC                               | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.335                           | AFL                                   | 0         |          | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                               | Unit                           | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition               |
|---------------------------------------|--------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|---------------------------|
| ATA 34 - NAVIGATION                   |                                |           |          |          |                           |           |           |                           |
| 342527                                | NO. 1 EFIS SYMBOL GENERATOR    |           |          |          |                           |           |           | Component ATA:34          |
| PN:7011674-119                        | MOS/MSC                        | 09-Mar-04 | O/C      |          |                           |           |           |                           |
| SN:94091108                           | HRS                            | 2632.6    |          |          |                           |           |           |                           |
| WC#: 34.150                           | AFL                            | 1434      |          |          |                           |           |           |                           |
| PROC. REF: AMM 34-70-05               |                                |           |          |          |                           |           |           |                           |
| 342528                                | NO. 2 EFIS SYMBOL GENERATOR    |           |          |          |                           |           |           | Component ATA:34          |
| PN:7011674-119                        | MOS/MSC                        | 15-Sep-12 | O/C      |          |                           |           |           |                           |
| SN:92050834                           | HRS                            | 4799      |          |          |                           |           |           |                           |
| WC#: 34.150                           | AFL                            | 2687      |          |          |                           |           |           |                           |
| PROC. REF: AMM 34-70-05               |                                |           |          |          |                           |           |           |                           |
| 342530                                | MULTIFUNCTION SYMBOL GENERATOR |           |          |          |                           |           |           | Component ATA:34          |
| PN:7011675-119                        | MOS/MSC                        | 21-Jan-22 | O/C      | TSR 0    |                           |           |           |                           |
| SN:98070801                           | HRS                            | 6264.3    |          | TSR 0    |                           |           |           |                           |
| WC#: 34.150                           | AFL                            | 3756      |          | TSR 0    |                           |           |           |                           |
| PROC. REF: AMM 34-70-05               |                                |           |          |          |                           |           |           |                           |
| 342537                                | NO. 1 DISPLAY CONTROL PANEL    |           |          |          |                           |           |           | Component ATA:34          |
| PN:7005819-707                        | MOS/MSC                        | 30-Aug-96 | O/C      |          |                           |           |           |                           |
| SN:95123048                           | HRS                            | 16        |          | TSN 0    |                           |           |           |                           |
| WC#: 34.155                           | AFL                            | 9         |          |          |                           |           |           |                           |
| PROC. REF: MMA 34-70-13, AMM 34-70-05 |                                |           |          |          |                           |           |           |                           |
| 342538                                | NO. 2 DISPLAY CONTROL PANEL    |           |          |          |                           |           |           | Component ATA:34          |
| PN:7005819-707                        | MOS/MSC                        | 30-Aug-96 | O/C      |          |                           |           |           |                           |
| SN:96032875                           | HRS                            | 16        |          | TSN 0    |                           |           |           |                           |
| WC#: 34.155                           | AFL                            | 9         |          |          |                           |           |           |                           |
| PROC. REF: MMA 34-70-13, AMM 34-70-05 |                                |           |          |          |                           |           |           |                           |
| 342539                                | MULTI FUNCTION EFIS CONTROL    |           |          |          |                           |           |           | Component ATA:34          |
| PN:7007062-921                        | MOS/MSC                        | 30-Aug-96 | O/C      |          |                           |           |           |                           |
| SN:96031620                           | HRS                            | 16        |          | TSN 0    |                           |           |           |                           |
| WC#: 34.160                           | AFL                            | 9         |          |          |                           |           |           |                           |
| PROC. REF: AMM 34-70-05               |                                |           |          |          |                           |           |           | WO#: N950PC 48 MONTH INSP |
| 342540                                | FLIGHT GUIDANCE PANEL          |           |          |          |                           |           |           | Component ATA:34          |
| PN:PN                                 | MOS/MSC                        | 30-May-96 | O/C      | TSN 0    |                           |           |           |                           |
| SN:UNKNOWN                            | HRS                            | 0         |          | TSN 0    |                           |           |           |                           |
| WC#: 34.440                           | AFL                            | 0         |          | TSN 0    |                           |           |           |                           |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                             | Unit                               | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------------------------------------------|------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION                                 |                                    |           |          |          |                           |           |           |                  |
| 342541                                              | NO. 1 CONSOLE CONTROL DISPLAY UNIT |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                                               | MOS/MSC                            | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                          | HRS                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.445                                         | AFL                                | 0         |          | TSN 0    |                           |           |           |                  |
| 342542                                              | NO. 2 CONSOLE CONTROL DISPLAY UNIT |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                                               | MOS/MSC                            | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                          | HRS                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.450                                         | AFL                                | 0         |          | TSN 0    |                           |           |           |                  |
| 342543                                              | PILOT OPTIONAL CONTROL MODULE      |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                                               | MOS/MSC                            | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                          | HRS                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.495                                         | AFL                                | 0         |          | TSN 0    |                           |           |           |                  |
| 342544                                              | COPILOT OPTIONAL CONTROL MODULE    |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                                               | MOS/MSC                            | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                          | HRS                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.495                                         | AFL                                | 0         |          | TSN 0    |                           |           |           |                  |
| 342545                                              | NO. 1 FLUX DETECTOR                |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                                               | MOS/MSC                            | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                          | HRS                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.500                                         | AFL                                | 0         |          | TSN 0    |                           |           |           |                  |
| 342547                                              | NO. 2 FLUX DETECTOR                |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                                               | MOS/MSC                            | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                          | HRS                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.500                                         | AFL                                | 0         |          | TSN 0    |                           |           |           |                  |
| 342550                                              | IAPS ENVIROMENTAL CONTROLLER       |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                                               | MOS/MSC                            | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                          | HRS                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.505                                         | AFL                                | 0         |          | TSN 0    |                           |           |           |                  |
| 342561                                              | TCAS COMPUTER                      |           |          |          |                           |           |           | Component ATA:34 |
| PN:4066010-910                                      | MOS/MSC                            | 02-Dec-22 | O/C      |          |                           |           |           |                  |
| SN:95072510                                         | HRS                                | 6488.1    |          |          |                           |           |           |                  |
| WC#: 34.175                                         | AFL                                | 3901      |          |          |                           |           |           |                  |
| PROC. REF: MMA 34-45-06, MMA 34-45-07, AMM 34-45-05 |                                    |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                           | Unit                                            | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------------------------------------------------|-------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION                                               |                                                 |           |          |          |                           |           |           |                  |
| 342562                                                            | TCAS (TOP) ANTENNA                              |           |          |          |                           |           |           | Component ATA:34 |
| PN:7514081-910                                                    | MOS/MSC                                         | 30-Aug-96 | O/C      |          |                           |           |           |                  |
| SN:96065696                                                       | HRS                                             | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 34.180                                                       | AFL                                             | 9         |          |          |                           |           |           |                  |
| PROC. REF: MMA 34-45-00, MMA 34-45-06, MMA 34-45-07, AMM 34-45-05 |                                                 |           |          |          |                           |           |           |                  |
| 342563                                                            | TCAS (BOTTOM) ANTENNA                           |           |          |          |                           |           |           | Component ATA:34 |
| PN:S65-5366-11L                                                   | MOS/MSC                                         | 30-Aug-96 | O/C      |          |                           |           |           |                  |
| SN:3364                                                           | HRS                                             | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 34.180                                                       | AFL                                             | 9         |          |          |                           |           |           |                  |
| PROC. REF: MMA 34-45-00, MMA 34-45-06, MMA 34-45-07, AMM 34-45-05 |                                                 |           |          |          |                           |           |           |                  |
| 342601                                                            | NO. 1 INTEGRATED NAVIGATION (RNZ-850/-851) UNIT |           |          |          |                           |           |           | Component ATA:34 |
| PN:7510100-731                                                    | MOS/MSC                                         | 02-Dec-22 | O/C      |          |                           |           |           |                  |
| SN:00034245                                                       | HRS                                             | 6488.1    |          |          |                           |           |           |                  |
| WC#: 34.185                                                       | AFL                                             | 3901      |          |          |                           |           |           |                  |
| PROC. REF: AMM 34-30-05                                           |                                                 |           |          |          |                           |           |           |                  |
| 342602                                                            | NO. 2 INTEGRATED NAVIGATION (RNZ-850/-851) UNIT |           |          |          |                           |           |           | Component ATA:34 |
| PN:7510100-731                                                    | MOS/MSC                                         | 02-Dec-22 | O/C      |          |                           |           |           |                  |
| SN:88080175                                                       | HRS                                             | 6488.1    |          |          |                           |           |           |                  |
| WC#: 34.185                                                       | AFL                                             | 3901      |          |          |                           |           |           |                  |
| PROC. REF: AMM 34-30-05                                           |                                                 |           |          |          |                           |           |           |                  |
| 342624                                                            | NO. 1 ADF ANTENNA                               |           |          |          |                           |           |           | Component ATA:34 |
| PN:7510300-901                                                    | MOS/MSC                                         | 09-Mar-04 | O/C      | TSR 0    |                           |           |           |                  |
| SN:02016072                                                       | HRS                                             | 2632.6    |          | TSR 0    |                           |           |           |                  |
| WC#: 34.190                                                       | AFL                                             | 1434      |          | TSR 0    |                           |           |           |                  |
| PROC. REF: AMM 34-51-05                                           |                                                 |           |          |          |                           |           |           |                  |
| 342625                                                            | NO. 2 ADF ANTENNA                               |           |          |          |                           |           |           | Component ATA:34 |
| PN:7510300-901                                                    | MOS/MSC                                         | 30-Aug-96 | O/C      |          |                           |           |           |                  |
| SN:95111841                                                       | HRS                                             | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 34.190                                                       | AFL                                             | 9         |          |          |                           |           |           |                  |
| PROC. REF: AMM 34-51-05                                           |                                                 |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                             | Unit                                     | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------------------|------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION                 |                                          |           |          |          |                           |           |           |                  |
| 342640                              | EGPWS COMPUTER                           |           |          |          |                           |           |           | Component ATA:34 |
| PN:965-1076-001-206-206             | MOS/MSC                                  | 02-Dec-22 | O/C      |          |                           |           |           |                  |
| SN:1356                             | HRS                                      | 6488.1    |          |          |                           |           |           |                  |
| WC#: 34.455                         | AFL                                      | 3901      |          |          |                           |           |           |                  |
| PROC. REF: MMA 34-44-06, AMM NO REF |                                          |           |          |          |                           |           |           |                  |
| 342701                              | NO. 1 DATA CONCENTRATOR UNIT             |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                               | MOS/MSC                                  | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                          | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.515                         | AFL                                      | 0         |          | TSN 0    |                           |           |           |                  |
| 342703                              | NO. 2 DATA CONCENTRATOR UNIT             |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                               | MOS/MSC                                  | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                          | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.515                         | AFL                                      | 0         |          | TSN 0    |                           |           |           |                  |
| 342705                              | NO. 3 DATA CONCENTRATOR UNIT             |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                               | MOS/MSC                                  | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                          | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.520                         | AFL                                      | 0         |          | TSN 0    |                           |           |           |                  |
| 342707                              | NO. 4 DATA CONCENTRATOR UNIT             |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                               | MOS/MSC                                  | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                          | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.520                         | AFL                                      | 0         |          | TSN 0    |                           |           |           |                  |
| 342709                              | DA PANEL ASSEMBLY                        |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                               | MOS/MSC                                  | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                          | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.525                         | AFL                                      | 0         |          | TSN 0    |                           |           |           |                  |
| 342801                              | NO. 1 INPUT / OUTPUT CONCENTRATOR MODULE |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                               | MOS/MSC                                  | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                          | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.530                         | AFL                                      | 0         |          | TSN 0    |                           |           |           |                  |
| 342802                              | NO. 2 INPUT / OUTPUT CONCENTRATOR MODULE |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                               | MOS/MSC                                  | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                          | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.530                         | AFL                                      | 0         |          | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                       | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|----------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION       |                            |           |          |          |                           |           |           |                  |
| 342805                    | NO. 1 IAPS POWER SUPPLY    |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                     | MOS/MSC                    | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                        | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.535               | AFL                        | 0         |          | TSN 0    |                           |           |           |                  |
| 342806                    | NO. 2 IAPS POWER SUPPLY    |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                     | MOS/MSC                    | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                        | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.535               | AFL                        | 0         |          | TSN 0    |                           |           |           |                  |
| 342809                    | AURAL WARNING GENERATOR    |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                     | MOS/MSC                    | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                        | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.540               | AFL                        | 0         |          | TSN 0    |                           |           |           |                  |
| 342810                    | NO. 1 CURSOR CONTROL PANEL |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                     | MOS/MSC                    | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                        | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.545               | AFL                        | 0         |          | TSN 0    |                           |           |           |                  |
| 342811                    | NO. 2 CURSOR CONTROL PANEL |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                     | MOS/MSC                    | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                        | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.545               | AFL                        | 0         |          | TSN 0    |                           |           |           |                  |
| 342812                    | NO. 1 FILE SERVER UNIT     |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                     | MOS/MSC                    | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                        | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.550               | AFL                        | 0         |          | TSN 0    |                           |           |           |                  |
| 342813                    | NO. 2 FILE SERVER UNIT     |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                     | MOS/MSC                    | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                        | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.550               | AFL                        | 0         |          | TSN 0    |                           |           |           |                  |
| 342815                    | FSU (MMT-5000) MOUNT       |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                     | MOS/MSC                    | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                        | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.600               | AFL                        | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                            |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                             | Unit                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------------------------------------------|-----------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION                                 |                                   |           |          |          |                           |           |           |                  |
| 343001                                              | GLIDE SLOPE AERIAL                |           |          |          |                           |           |           | Component ATA:34 |
| PN:17-21F6                                          | MOS/MSC                           | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:787                                              | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.195                                         | AFL                               | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 34-32-725                            |                                   |           |          |          |                           |           |           |                  |
| 343013                                              | MARKER AERIAL                     |           |          |          |                           |           |           | Component ATA:34 |
| PN:17-5C                                            | MOS/MSC                           | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:129                                              | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.200                                         | AFL                               | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 34-33-612                            |                                   |           |          |          |                           |           |           |                  |
| 344001                                              | NO. 1 WEATHER RADAR CONTROL PANEL |           |          |          |                           |           |           | Component ATA:34 |
| PN:7008471-801                                      | MOS/MSC                           | 25-Oct-22 | O/C      | TSR 0    |                           |           |           |                  |
| SN:94042002                                         | HRS                               | 6454.6    |          | TSR 0    |                           |           |           |                  |
| WC#: 34.205                                         | AFL                               | 3877      |          | TSR 0    |                           |           |           |                  |
| PROC. REF: MMA 34-41-29, AMM 34-41-05, AMM 34-41-15 |                                   |           |          |          |                           |           |           |                  |
| 344002                                              | NO. 2 WEATHER RADAR CONTROL PANEL |           |          |          |                           |           |           | Component ATA:34 |
| PN:7008471-803                                      | MOS/MSC                           | 07-Feb-08 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                                          | HRS                               | 3650.5    |          |          |                           |           |           |                  |
| WC#: 34.205                                         | AFL                               |           |          |          |                           |           |           |                  |
| PROC. REF: MMA 34-41-29, AMM 34-41-05, AMM 34-41-15 |                                   |           |          |          |                           |           |           |                  |
| 344005                                              | WEATHER RADAR TRANSCEIVER         |           |          |          |                           |           |           | Component ATA:34 |
| PN:7012640-922                                      | MOS/MSC                           | 01-Jun-05 | O/C      |          |                           |           |           |                  |
| SN:89010230                                         | HRS                               | 2857.7    |          |          |                           |           |           |                  |
| WC#: 34.210                                         | AFL                               | 1583      |          |          |                           |           |           |                  |
| PROC. REF: MMA 34-41-29, AMM 34-41-05, AMM 34-41-15 |                                   |           |          |          |                           |           |           |                  |
| 344016                                              | RADAR CHECKLIST MODULE            |           |          |          |                           |           |           | Component ATA:34 |
| PN:7990197-131                                      | MOS/MSC                           | 30-Aug-96 | O/C      |          |                           |           |           |                  |
| SN:96051498                                         | HRS                               | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 34.215                                         | AFL                               | 9         |          |          |                           |           |           |                  |
| PROC. REF: AMM NO REF                               |                                   |           |          |          |                           |           |           |                  |
| 344036                                              | ISOLATION VALVE                   |           |          |          |                           |           |           | Component ATA:34 |
| PN:25-MC2175                                        | MOS/MSC                           | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:006/AS                                           | HRS                               | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.220                                         | AFL                               |           |          |          |                           |           |           |                  |
| PROC. REF: AMM 34-11-52                             |                                   |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                  | Unit                   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------|------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION      |                        |           |          |          |                           |           |           |                  |
| 345003                   | DATA BASE UNIT         |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                    | MOS/MSC                | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN               | HRS                    | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.503              | AFL                    | 0         |          | TSN 0    |                           |           |           |                  |
| 345008                   | SENSOR UNIT DISPLAY    |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                    | MOS/MSC                | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN               | HRS                    | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.295              | AFL                    | 0         |          | TSN 0    |                           |           |           |                  |
| 345009                   | SENSOR DRIVER DISPLAY  |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                    | MOS/MSC                | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN               | HRS                    | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.295              | AFL                    | 0         |          | TSN 0    |                           |           |           |                  |
| 345037                   | LEFT VOR/LOC AERIAL    |           |          |          |                           |           |           | Component ATA:34 |
| PN:S65-247-12            | MOS/MSC                | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:2087                  | HRS                    | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.230              | AFL                    | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 34-32-675 |                        |           |          |          |                           |           |           |                  |
| 345038                   | RIGHT VOR/LOC AERIAL   |           |          |          |                           |           |           | Component ATA:34 |
| PN:S65-247-12            | MOS/MSC                | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:2086                  | HRS                    | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.230              | AFL                    | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 34-32-675 |                        |           |          |          |                           |           |           |                  |
| 345049                   | NO. 1 ADF LOOP ANTENNA |           |          |          |                           |           |           | Component ATA:34 |
| PN:622-3710-001          | MOS/MSC                | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:3039                  | HRS                    | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.235              | AFL                    | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM NO REF    |                        |           |          |          |                           |           |           |                  |
| 345097                   | PHASING COUPLER        |           |          |          |                           |           |           | Component ATA:34 |
| PN:SSPD-113-10           | MOS/MSC                | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:1473                  | HRS                    | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.240              | AFL                    | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM NO REF    |                        |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                  | Unit                         | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------|------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION      |                              |           |          |          |                           |           |           |                  |
| 345098                   | COUPLER ANTENNA              |           |          |          |                           |           |           | Component ATA:34 |
| PN:SSPD-113-13           | MOS/MSC                      | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:409                   | HRS                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.245              | AFL                          | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM NO REF    |                              |           |          |          |                           |           |           |                  |
| 345109                   | NO. 1 DME AERIAL             |           |          |          |                           |           |           | Component ATA:34 |
| PN:10A-1                 | MOS/MSC                      | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:3990                  | HRS                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.250              | AFL                          | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 34-42-652 |                              |           |          |          |                           |           |           |                  |
| 345110                   | NO. 2 DME AERIAL             |           |          |          |                           |           |           | Component ATA:34 |
| PN:10A-1                 | MOS/MSC                      | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:3976                  | HRS                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.250              | AFL                          | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 34-42-652 |                              |           |          |          |                           |           |           |                  |
| 345133                   | NO. 1 ATC TRANSPONDER AERIAL |           |          |          |                           |           |           | Component ATA:34 |
| PN:C1105-17-L            | MOS/MSC                      | 21-Feb-20 | O/C      |          |                           |           |           |                  |
| SN:623596                | HRS                          | 5797.9    |          |          |                           |           |           |                  |
| WC#: 34.255              | AFL                          | 3397      |          |          |                           |           |           |                  |
| PROC. REF: AMM 34-43-742 |                              |           |          |          |                           |           |           |                  |
| 345134                   | NO. 2 ATC TRANSPONDER AERIAL |           |          |          |                           |           |           | Component ATA:34 |
| PN:C1105-17-L            | MOS/MSC                      | 21-Feb-20 | O/C      |          |                           |           |           |                  |
| SN:623597                | HRS                          | 5797.9    |          |          |                           |           |           |                  |
| WC#: 34.255              | AFL                          | 3397      |          |          |                           |           |           |                  |
| PROC. REF: AMM 34-43-742 |                              |           |          |          |                           |           |           |                  |
| 345135                   | FORWARD TRANSPONDER ANTENNA  |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                    | MOS/MSC                      | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN               | HRS                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.460              | AFL                          | 0         |          | TSN 0    |                           |           |           |                  |
| 345136                   | AFT TRANSPONDER ANTENNA      |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                    | MOS/MSC                      | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN               | HRS                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.465              | AFL                          | 0         |          | TSN 0    |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                           | Unit                                          | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------------------------------------------------|-----------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION                                               |                                               |           |          |          |                           |           |           |                  |
| 345205                                                            | NO. 1 DME TRANSCEIVER                         |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                                                             | MOS/MSC                                       | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                                        | HRS                                           | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.305                                                       | AFL                                           | 0         |          | TSN 0    |                           |           |           |                  |
| 345206                                                            | NO. 2 DME TRANSCEIVER                         |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                                                             | MOS/MSC                                       | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                                        | HRS                                           | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.305                                                       | AFL                                           | 0         |          | TSN 0    |                           |           |           |                  |
| 345217                                                            | NO. 1 ATC TRANSPONDER                         |           |          |          |                           |           |           | Component ATA:34 |
| PN:75110100-866                                                   | MOS/MSC                                       | 20-Jan-23 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                                                        | HRS                                           | 6526.5    |          |          |                           |           |           |                  |
| WC#: 34.260                                                       | AFL                                           | 3926      |          |          |                           |           |           |                  |
| PROC. REF: MMA 34-43-64, AMM 34-43-64, AMM 34-52-05, AMM 34-52-15 |                                               |           |          |          |                           |           |           |                  |
| 345218                                                            | NO. 2 ATC TRANSPONDER                         |           |          |          |                           |           |           | Component ATA:34 |
| PN:75110100-866                                                   | MOS/MSC                                       | 20-Jan-23 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                                                        | HRS                                           | 6526.5    |          |          |                           |           |           |                  |
| WC#: 34.260                                                       | AFL                                           | 3926      |          |          |                           |           |           |                  |
| PROC. REF: MMA 34-43-64, AMM 34-43-64, AMM 34-52-05, AMM 34-52-15 |                                               |           |          |          |                           |           |           |                  |
| 345229                                                            | SYSTEM TEST NO.1 ATC TRANSPONDER (FAA 91.413) |           |          |          |                           |           |           | Service ATA:34   |
| PN:75110100-866                                                   | MOS                                           | 20-Jan-23 | 24       |          | 20-Jan-25                 |           | 720 d     | MANDATORY        |
| SN:UNKNOWN                                                        | HRS                                           |           |          |          |                           |           |           |                  |
| WC#: 34.260                                                       | AFL                                           |           |          |          |                           |           |           |                  |
| PROC. REF: FAR FAR PART 91                                        |                                               |           |          |          |                           |           |           |                  |
| 345230                                                            | SYSTEM TEST NO.2 ATC TRANSPONDER (FAA 91.413) |           |          |          |                           |           |           | Service ATA:34   |
| PN:75110100-866                                                   | MOS                                           | 20-Jan-23 | 24       |          | 20-Jan-25                 |           | 720 d     | MANDATORY        |
| SN:UNKNOWN                                                        | HRS                                           |           |          |          |                           |           |           |                  |
| WC#: 34.260                                                       | AFL                                           |           |          |          |                           |           |           |                  |
| PROC. REF: FAR FAR PART 91                                        |                                               |           |          |          |                           |           |           |                  |
| 345305                                                            | MACH TRIM COMPUTER                            |           |          |          |                           |           |           | Component ATA:34 |
| PN:8220872-001                                                    | MOS/MSC                                       | 14-Jul-00 | O/C      | TSO 2    |                           |           |           |                  |
| SN:122                                                            | HRS                                           | 1488      |          | TSO 0    |                           |           |           |                  |
| WC#: 34.270                                                       | AFL                                           | 771       |          | TSO 0    |                           |           |           |                  |
| PROC. REF: AMM NO REF                                             |                                               |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                           | Unit                               | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------------------------------------------------|------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION                                               |                                    |           |          |          |                           |           |           |                  |
| 345309                                                            | AFIS DMU                           |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                                                             | MOS/MSC                            | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                                        | HRS                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.470                                                       | AFL                                | 0         |          | TSN 0    |                           |           |           |                  |
| 345310                                                            | AFIS CONFIGURATION MODULE          |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                                                             | MOS/MSC                            | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                                        | HRS                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.475                                                       | AFL                                | 0         |          | TSN 0    |                           |           |           |                  |
| 345404                                                            | NO. 1 GPS SENSOR UNIT              |           |          |          |                           |           |           | Component ATA:34 |
| PN:HG2021GD02                                                     | MOS/MSC                            | 30-Aug-96 | O/C      |          |                           |           |           |                  |
| SN:96091835                                                       | HRS                                | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 34.275                                                       | AFL                                | 9         |          |          |                           |           |           |                  |
| PROC. REF: AMM 34-53-05                                           |                                    |           |          |          |                           |           |           |                  |
| 345405                                                            | NO. 2 GPS SENSOR UNIT              |           |          |          |                           |           |           | Component ATA:34 |
| PN:HG2021GD02                                                     | MOS/MSC                            | 30-Aug-96 | O/C      |          |                           |           |           |                  |
| SN:96091834                                                       | HRS                                | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 34.275                                                       | AFL                                | 9         |          |          |                           |           |           |                  |
| PROC. REF: AMM 34-53-05                                           |                                    |           |          |          |                           |           |           |                  |
| 345406                                                            | NO. 1 GPS ANTENNA                  |           |          |          |                           |           |           | Component ATA:34 |
| PN:S67-1575-20                                                    | MOS/MSC                            | 30-Aug-96 | O/C      |          |                           |           |           |                  |
| SN:3454                                                           | HRS                                | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 34.280                                                       | AFL                                | 9         |          |          |                           |           |           |                  |
| PROC. REF: MMA 34-48-30, MMA 34-48-32, MMA 34-50-00, AMM 34-53-05 |                                    |           |          |          |                           |           |           |                  |
| 345407                                                            | NO. 2 GPS ANTENNA                  |           |          |          |                           |           |           | Component ATA:34 |
| PN:S67-1575-20                                                    | MOS/MSC                            | 30-Aug-96 | O/C      |          |                           |           |           |                  |
| SN:3457                                                           | HRS                                | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 34.280                                                       | AFL                                | 9         |          |          |                           |           |           |                  |
| PROC. REF: MMA 34-48-30, MMA 34-48-32, MMA 34-50-00, AMM 34-53-05 |                                    |           |          |          |                           |           |           |                  |
| 345413                                                            | NO. 1 CONFIGURATION STRAPPING UNIT |           |          |          |                           |           |           | Component ATA:34 |
| PN:7014940-903                                                    | MOS/MSC                            | 30-Aug-96 | O/C      |          |                           |           |           |                  |
| SN:96041265                                                       | HRS                                | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 34.285                                                       | AFL                                | 9         |          |          |                           |           |           |                  |
| PROC. REF: AMM NO REF                                             |                                    |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-----------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION       |                                         |           |          |          |                           |           |           |                  |
| 345414                    | NO. 2 CONFIGURATION STRAPPING UNIT      |           |          |          |                           |           |           | Component ATA:34 |
| PN:7014940-903            | MOS/MSC                                 | 30-Aug-96 | O/C      |          |                           |           |           |                  |
| SN:96041262               | HRS                                     | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 34.285               | AFL                                     | 9         |          |          |                           |           |           |                  |
| PROC. REF: AMM NO REF     |                                         |           |          |          |                           |           |           |                  |
| 345513                    | NO. 1 (AHRs) EXTERNAL COMPENSATION UNIT |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                     | MOS/MSC                                 | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.480               | AFL                                     | 0         |          | TSN 0    |                           |           |           |                  |
| 345514                    | NO. 2 (AHRs) EXTERNAL COMPENSATION UNIT |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                     | MOS/MSC                                 | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.480               | AFL                                     | 0         |          | TSN 0    |                           |           |           |                  |
| 345515                    | NO. 1 (IFIS) EXTERNAL COMPENSATION UNIT |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                     | MOS/MSC                                 | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.555               | AFL                                     | 0         |          | TSN 0    |                           |           |           |                  |
| 345516                    | NO. 2 (IFIS) EXTERNAL COMPENSATION UNIT |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                     | MOS/MSC                                 | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.602               | AFL                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                         |           |          |          |                           |           |           |                  |
| 345517                    | NO. 3 (IFIS) EXTERNAL COMPENSATION UNIT |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                     | MOS/MSC                                 | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.603               | AFL                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                         |           |          |          |                           |           |           |                  |
| 346101 <sup>U</sup>       | NOSE EXHAUST FAN                        |           |          |          |                           |           |           | Component ATA:34 |
| PN:011099                 | MOS/MSC                                 | 12-May-07 | O/C      |          |                           |           |           |                  |
| SN:101441559              | HRS                                     | 3447      |          |          |                           |           |           |                  |
|                           | AFL                                     | 1932      |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                                               | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|----------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 34 - NAVIGATION       |                                                    |           |          |          |                           |           |           |                  |
| 346810                    | OBSERVERS AMPLIFIER                                |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                     | MOS/MSC                                            | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.601               | AFL                                                | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                    |           |          |          |                           |           |           |                  |
| 348001                    | ACSS TAWS COMPUTER                                 |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                     | MOS/MSC                                            | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.604               | AFL                                                | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                    |           |          |          |                           |           |           |                  |
| 348002                    | AP-950 CONFIGURATION MODULE                        |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN                     | MOS/MSC                                            | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                                | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.605               | AFL                                                | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                    |           |          |          |                           |           |           |                  |
| 348601 <sup>U</sup>       | SATELLITE DATA RECEIVER                            |           |          |          |                           |           |           | Component ATA:34 |
| PN:305391-000             | MOS/MSC                                            |           | O/C      |          |                           |           |           |                  |
| SN:444                    | HRS                                                |           |          |          |                           |           |           |                  |
|                           | AFL                                                |           |          |          |                           |           |           |                  |
| 349000 <sup>U</sup>       | EGPWS / TAWS DATA BASE                             |           |          |          |                           |           |           | Service ATA:34   |
|                           | MOS                                                | 20-Jan-23 | 12       |          | 20-Jan-24                 |           | 354 d     |                  |
|                           | HRS                                                | 6526.5    |          |          |                           |           |           |                  |
|                           | AFL                                                | 3926      |          |          |                           |           |           |                  |
| 349001 <sup>U</sup>       | FMS DATA BASE (NAV)                                |           |          |          |                           |           |           | Service ATA:34   |
|                           | DAYS                                               | 28-Nov-22 | 28       |          | 26-Dec-22                 |           | OVD       |                  |
|                           | HRS                                                | 6485.2    |          |          |                           |           |           |                  |
|                           | AFL                                                | 3898      |          |          |                           |           |           |                  |
| WO#: N950PC KLM JAN 2023  |                                                    |           |          |          |                           |           |           |                  |
| 349002 <sup>U</sup>       | HONEYWELL NAV DATA BASE RENEWAL - ACCT: A46AB33378 |           |          |          |                           |           |           | Service ATA:34   |
|                           | MOS                                                | 12-Jul-22 | 12       |          | 01-Jun-23 (M)             |           | 121 d     |                  |
|                           | HRS                                                | 6386.7    |          |          |                           |           |           |                  |
|                           | AFL                                                | 3827      |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                      | Unit                                                       | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition                         |
|----------------------------------------------|------------------------------------------------------------|-----------|-----------------|----------|---------------------------|-----------|---------------|-------------------------------------|
| ATA 34 - NAVIGATION                          |                                                            |           |                 |          |                           |           |               |                                     |
| 349003 <sup>U</sup>                          | RVSM OVER FLY                                              |           |                 |          |                           |           |               | Service ATA:34                      |
|                                              | MOS                                                        | 18-Oct-21 | 24              |          | 18-Oct-23                 |           | 260 d         |                                     |
|                                              | HRS                                                        | 6169.5    | 1000            |          | 7169.5                    |           | 641.2         |                                     |
|                                              | AFL                                                        | 3664      |                 |          |                           |           |               |                                     |
| 349004 <sup>U</sup>                          | VOR RECEIVER CHECK                                         |           |                 |          |                           |           |               | Service ATA:34                      |
|                                              | DAYS                                                       | 26-Dec-22 | 30              |          | 25-Jan-23                 |           | OVD           |                                     |
|                                              | HRS                                                        | 6499.5    |                 |          |                           |           |               |                                     |
|                                              | AFL                                                        | 3910      |                 |          |                           |           |               |                                     |
|                                              |                                                            |           |                 |          |                           |           |               | WO#: N950PC KLM JAN 2023            |
| 349005 <sup>U</sup>                          | FMS DATA (NZ) BASE HONEYWELL ACCOUNT INFORMATION # 397491  |           |                 |          |                           |           |               | Service ATA:34                      |
|                                              | MOS                                                        | 05-Oct-22 | 12              |          | 05-Oct-23                 |           | 247 d         |                                     |
|                                              | HRS                                                        |           |                 |          |                           |           |               |                                     |
|                                              | AFL                                                        |           |                 |          |                           |           |               |                                     |
| 349101                                       | PASSENGER SPEAKER AMPLIFIER                                |           |                 |          |                           |           |               | Component ATA:34                    |
| PN:PN                                        | MOS/MSC                                                    | 30-May-96 | O/C             | TSN 0    |                           |           |               |                                     |
| SN:UNKNOWN                                   | HRS                                                        | 0         |                 | TSN 0    |                           |           |               |                                     |
| WC#: 34.606                                  | AFL                                                        | 0         |                 | TSN 0    |                           |           |               |                                     |
| PROC. REF: GENERIC NO REF                    |                                                            |           |                 |          |                           |           |               |                                     |
| 34R003 <sup>U</sup>                          | PERFORM AUTOPILOT ALTITUDE HOLD OPERATIONAL CHECK IAW RVSM |           |                 |          |                           |           |               | Service ATA:34                      |
|                                              | MOS/MSC                                                    |           | A/R             |          |                           |           |               |                                     |
|                                              | HRS                                                        |           |                 |          |                           |           |               |                                     |
|                                              | AFL                                                        |           |                 |          |                           |           |               |                                     |
| ATA 35 - OXYGEN                              |                                                            |           |                 |          |                           |           |               |                                     |
| 350001                                       | CHECK OXYGEN SYSTEM MASTER SUPPLY VALVE                    |           |                 |          |                           |           |               | Service ATA:35                      |
|                                              | MOS                                                        | 15-Oct-19 |                 |          |                           |           |               |                                     |
|                                              | HRS                                                        | 5795.3    | 800 (+40/-10)   |          | 6595.3                    | 6635.3    | 67 (+40)      |                                     |
| WC#: 35.110                                  | AFL                                                        | 3397      |                 |          |                           |           |               |                                     |
| PROC. REF: AFMS INSPECTION B4                |                                                            |           |                 |          |                           |           |               | PKG:2,11<br>WO#: N950PC B & C CHECK |
| 350002                                       | FUNCTIONAL TEST AUTOMATIC SHUT-OFF VALVE                   |           |                 |          |                           |           |               | Service ATA:35                      |
|                                              | MOS                                                        | 18-Aug-17 |                 |          |                           |           |               |                                     |
|                                              | HRS                                                        | 5554.6    | 3200 (+150/-50) |          | 8754.6                    | 8904.6    | 2226.3 (+150) |                                     |
| WC#: 35.035                                  | AFL                                                        | 3197      |                 |          |                           |           |               |                                     |
| PROC. REF: AFMS INSPECTION D2, AMM 35-10-141 |                                                            |           |                 |          |                           |           |               | PKG:4,33                            |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                                 | Unit                                                     | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                                                | Disposition      |
|-------------------------------------------------------------------------|----------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|----------------------------------------------------------|------------------|
| ATA 35 - OXYGEN                                                         |                                                          |           |                |          |                           |           |                                                          |                  |
| 350004                                                                  | TEST/INSPECT PASSENGER OXYGEN SYSTEM                     |           |                |          |                           |           |                                                          | Service ATA:35   |
|                                                                         | MOS                                                      | 11-Oct-22 | 12 (+1m/-1m)   |          | 11-Oct-23                 | 11-Nov-23 | 253 d (+31)                                              |                  |
|                                                                         | HRS                                                      | 6446.4    |                |          |                           |           |                                                          |                  |
| WC#: 35.075                                                             | AFL                                                      | 3873      |                |          |                           |           |                                                          |                  |
| PROC. REF: MMA 35-06-00, MMA 35-20-05, AFMS INSPECTION E2, AMM 35-06-00 |                                                          |           |                |          |                           |           | PKG:5,45<br>WO#: N950PC B & C CHECK,N950PC 48 MONTH INSP |                  |
| 350005                                                                  | CHECK BAROMATIC CONTROL VALVE                            |           |                |          |                           |           |                                                          | Service ATA:35   |
|                                                                         | MOS                                                      | 11-Oct-22 | 12 (+1m/-1m)   |          | 11-Oct-23                 | 11-Nov-23 | 253 d (+31)                                              |                  |
|                                                                         | HRS                                                      | 6446.4    |                |          |                           |           |                                                          |                  |
| WC#: 35.100                                                             | AFL                                                      | 3873      |                |          |                           |           |                                                          |                  |
| PROC. REF: AFMS INSPECTION E2                                           |                                                          |           |                |          |                           |           | PKG:5,45<br>WO#: N950PC B & C CHECK,N950PC 48 MONTH INSP |                  |
| 350006                                                                  | INSPECT CREW MASKS, SMOKE SET MASK (IF FITTED) AND HOSES |           |                |          |                           |           |                                                          | Service ATA:35   |
|                                                                         | MOS                                                      | 11-Oct-22 | 12 (+1m/-1m)   |          | 11-Oct-23                 | 11-Nov-23 | 253 d (+31)                                              |                  |
|                                                                         | HRS                                                      | 6446.4    |                |          |                           |           |                                                          |                  |
| WC#: 35.115                                                             | AFL                                                      | 3873      |                |          |                           |           |                                                          |                  |
| PROC. REF: AFMS INSPECTION E4                                           |                                                          |           |                |          |                           |           | PKG:5,47<br>WO#: N950PC B & C CHECK,N950PC 48 MONTH INSP |                  |
| 350007                                                                  | INSPECT PORTABLE BREATHING EQUIPMENT                     |           |                |          |                           |           |                                                          | Service ATA:35   |
|                                                                         | MOS                                                      | 11-Oct-22 | 12 (+1m/-1m)   |          | 11-Oct-23                 | 11-Nov-23 | 253 d (+31)                                              |                  |
|                                                                         | HRS                                                      | 6446.4    |                |          |                           |           |                                                          |                  |
| WC#: 35.120                                                             | AFL                                                      | 3873      |                |          |                           |           |                                                          |                  |
| PROC. REF: AFMS INSPECTION E4                                           |                                                          |           |                |          |                           |           | PKG:5,47<br>WO#: N950PC B & C CHECK,N950PC 48 MONTH INSP |                  |
| 350008                                                                  | INSPECT OXYGEN CYLINDERS                                 |           |                |          |                           |           |                                                          | Service ATA:35   |
|                                                                         | MOS                                                      | 06-May-15 |                |          |                           |           |                                                          |                  |
|                                                                         | HRS                                                      | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50)                                              |                  |
| WC#: 35.105                                                             | AFL                                                      | 2873      |                |          |                           |           |                                                          |                  |
| PROC. REF: AFMS INSPECTION C7                                           |                                                          |           |                |          |                           |           | PKG:3,26<br>WO#: N950PC B & C CHECK                      |                  |
| 350009 <sup>U</sup>                                                     | PORTABLE BREATHING EQUIPMENT                             |           |                |          |                           |           |                                                          | Component ATA:35 |
| PN:802300-14                                                            | MOS/MSC                                                  | 18-Jul-03 | O/C            |          |                           |           |                                                          | LIFE LIMIT       |
| SN:0503002566                                                           | HRS                                                      |           |                |          |                           |           |                                                          |                  |
|                                                                         | AFL                                                      |           |                |          |                           |           |                                                          |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                  | Unit                              | C/W       | Interval | TSX/Adj.        | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--------------------------|-----------------------------------|-----------|----------|-----------------|---------------------------|-----------|-----------|------------------|
| ATA 35 - OXYGEN          |                                   |           |          |                 |                           |           |           |                  |
| 351001                   | MASTER OXYGEN SUPPLY VALVE        |           |          |                 |                           |           |           | Component ATA:35 |
| PN:SDV1012               | MOS/MSC                           | 30-May-96 | O/C      |                 |                           |           |           |                  |
| SN:8961                  | HRS                               | 0         |          | TSN 0           |                           |           |           |                  |
| WC#: 35.030              | AFL                               | 0         |          |                 |                           |           |           |                  |
| PROC. REF: AMM 35-10-62  |                                   |           |          |                 |                           |           |           |                  |
| 351003 <sup>U</sup>      | SERVICE OXYGEN SYSTEM             |           |          |                 |                           |           |           | Service ATA:35   |
|                          | MOS/MSC                           | 06-Jan-23 | A/R      |                 |                           |           |           |                  |
|                          | HRS                               | 6519.5    |          |                 |                           |           |           |                  |
|                          | AFL                               | 3923      |          |                 |                           |           |           |                  |
| WO#: N950PC KLM JAN 2023 |                                   |           |          |                 |                           |           |           |                  |
| 351013                   | OXYGEN PRESSURE GAUGE             |           |          |                 |                           |           |           | Component ATA:35 |
| PN:ST10015               | MOS/MSC                           | 30-May-96 | O/C      |                 |                           |           |           |                  |
| SN:F179                  | HRS                               | 0         |          | TSN 0           |                           |           |           |                  |
| WC#: 35.040              | AFL                               | 0         |          |                 |                           |           |           |                  |
| PROC. REF: AMM 35-10-32  |                                   |           |          |                 |                           |           |           |                  |
| 351014                   | ALTERNATIVE OXYGEN PRESSURE GAUGE |           |          |                 |                           |           |           | Component ATA:35 |
| PN:ST10015               | MOS/MSC                           | 30-May-96 | O/C      |                 |                           |           |           |                  |
| SN:F168                  | HRS                               | 0         |          | TSN 0           |                           |           |           |                  |
| WC#: 35.040              | AFL                               | 0         |          |                 |                           |           |           |                  |
| PROC. REF: AMM 35-10-33  |                                   |           |          |                 |                           |           |           |                  |
| 351015                   | OXYGEN CHARGING FILTER ASSEMBLY   |           |          |                 |                           |           |           | Component ATA:35 |
| PN:PN                    | MOS/MSC                           | 30-May-96 | O/C      | TSN 0           |                           |           |           |                  |
| SN:UNKNOWN               | HRS                               | 0         |          | TSN 0           |                           |           |           |                  |
| WC#: 35.215              | AFL                               | 0         |          | TSN 0           |                           |           |           |                  |
| 351025                   | OXYGEN REDUCING VALVE             |           |          |                 |                           |           |           | Component ATA:35 |
| PN:WKA29720-2            | MOS/MSC                           | 11-Oct-22 | O/C      | TSR 0           |                           |           |           |                  |
| SN:1226                  | HRS                               | 6446.4    |          | TSR 0           |                           |           |           |                  |
| WC#: 35.045              | AFL                               | 3873      |          | TSR 0           |                           |           |           |                  |
| 351031                   | PILOT OXYGEN MASK                 |           |          |                 |                           |           |           | Component ATA:35 |
| PN:MC10-14-124           | MOS                               | 16-Jan-22 | 72       | TSN 383, TSO 25 | 16-Dec-25                 |           | 1050 d    | OVERHAUL         |
| SN:28133                 | HRS                               | 6264.1    |          | TSO 523.4       |                           |           |           |                  |
| WC#: 35.050              | AFL                               | 3756      |          | TSO 366         |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN         | Unit                          | C/W                          | Interval               | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------|-------------------------------|------------------------------|------------------------|----------|---------------------------|-----------|-----------|------------------|
| ATA 35 - OXYGEN |                               |                              |                        |          |                           |           |           |                  |
| 351032          | COPILOT OXYGEN MASK           |                              |                        |          |                           |           |           | Component ATA:35 |
| PN:MC10-14-124  | MOS                           | 08-Jul-22                    | 72                     | TSO 4    | 08-Mar-28                 |           | 1863 d    | OVERHAUL         |
| SN:S18592       | HRS                           | 6369                         |                        | TSO 0    |                           |           |           |                  |
| WC#: 35.050     | AFL                           | 3814                         |                        | TSO 0    |                           |           |           |                  |
| 351043          | LEFT OXYGEN OUTLET VALVE      |                              |                        |          |                           |           |           | Component ATA:35 |
| PN:DPB181-01    | MOS/MSC                       | 30-May-96                    | O/C                    |          |                           |           |           |                  |
| SN:21965        | HRS                           | 0                            |                        | TSN 0    |                           |           |           |                  |
| WC#: 35.055     | AFL                           | 0                            |                        |          |                           |           |           |                  |
| 351044          | RIGHT OXYGEN OUTLET VALVE     |                              |                        |          |                           |           |           | Component ATA:35 |
| PN:DPB181-01    | MOS/MSC                       | 30-May-96                    | O/C                    |          |                           |           |           |                  |
| SN:22405        | HRS                           | 0                            |                        | TSN 0    |                           |           |           |                  |
| WC#: 35.055     | AFL                           | 0                            |                        |          |                           |           |           |                  |
| 351050          | GALLEY/ JUMP SEAT OXYGEN MASK |                              |                        |          |                           |           |           | Component ATA:35 |
| PN:289-601-228  | MOS                           | 24-Sep-21                    | 72                     |          | 03-Sep-27                 |           | 1676 d    | OVERHAUL         |
| SN:N/A          | HRS                           | 6141.4                       |                        | TSN 0    |                           |           |           |                  |
| WC#: 35.145     | AFL                           | 3647                         |                        | TSN 0    |                           |           |           |                  |
|                 |                               | Manufacture Date:: 03-Sep-21 | PROC. REF: GENERIC CMM |          |                           |           |           |                  |
| 351051          | NO. 1 PASSENGER OXYGEN MASK   |                              |                        |          |                           |           |           | Component ATA:35 |
| PN:289-601-228  | MOS                           | 24-Sep-21                    | 72                     |          | 03-Sep-27                 |           | 1676 d    | OVERHAUL         |
| SN:NA           | HRS                           | 6141.4                       |                        | TSN 0    |                           |           |           |                  |
| WC#: 35.150     | AFL                           | 3647                         |                        | TSN 0    |                           |           |           |                  |
|                 |                               | Manufacture Date:: 03-Sep-21 | PROC. REF: GENERIC CMM |          |                           |           |           |                  |
| 351052          | NO. 2 PASSENGER OXYGEN MASK   |                              |                        |          |                           |           |           | Component ATA:35 |
| PN:289-601-228  | MOS                           | 24-Sep-21                    | 72                     |          | 03-Sep-27                 |           | 1676 d    | OVERHAUL         |
| SN:NA           | HRS                           | 6141.4                       |                        | TSN 0    |                           |           |           |                  |
| WC#: 35.150     | AFL                           | 3647                         |                        | TSN 0    |                           |           |           |                  |
|                 |                               | Manufacture Date:: 03-Sep-21 | PROC. REF: GENERIC CMM |          |                           |           |           |                  |
| 351053          | NO. 3 PASSENGER OXYGEN MASK   |                              |                        |          |                           |           |           | Component ATA:35 |
| PN:289-601-228  | MOS                           | 24-Sep-21                    | 72                     |          | 03-Sep-27                 |           | 1676 d    | OVERHAUL         |
| SN:NA           | HRS                           | 6141.4                       |                        | TSN 0    |                           |           |           |                  |
| WC#: 35.155     | AFL                           | 3647                         |                        | TSN 0    |                           |           |           |                  |
|                 |                               | Manufacture Date:: 03-Sep-21 | PROC. REF: GENERIC CMM |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN         | Unit                            | C/W                          | Interval | TSX/Adj.               | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------|---------------------------------|------------------------------|----------|------------------------|---------------------------|-----------|-----------|------------------|
| ATA 35 - OXYGEN |                                 |                              |          |                        |                           |           |           |                  |
| 351054          | NO. 4 PASSENGER OXYGEN MASK     |                              |          |                        |                           |           |           | Component ATA:35 |
| PN:289-601-228  | MOS                             | 24-Sep-21                    | 72       |                        | 03-Sep-27                 |           | 1676 d    | OVERHAUL         |
| SN:NA           | HRS                             | 6141.4                       |          | TSN 0                  |                           |           |           |                  |
| WC#: 35.155     | AFL                             | 3647                         |          | TSN 0                  |                           |           |           |                  |
|                 |                                 | Manufacture Date:: 03-Sep-21 |          | PROC. REF: GENERIC CMM |                           |           |           |                  |
| 351055          | NO. 5 PASSENGER OXYGEN MASK     |                              |          |                        |                           |           |           | Component ATA:35 |
| PN:289-601-228  | MOS                             | 24-Sep-21                    | 72       |                        | 03-Sep-27                 |           | 1676 d    | OVERHAUL         |
| SN:NA           | HRS                             | 6141.4                       |          | TSN 0                  |                           |           |           |                  |
| WC#: 35.160     | AFL                             | 3647                         |          | TSN 0                  |                           |           |           |                  |
|                 |                                 | Manufacture Date:: 03-Sep-21 |          | PROC. REF: GENERIC CMM |                           |           |           |                  |
| 351056          | NO. 6 PASSENGER OXYGEN MASK     |                              |          |                        |                           |           |           | Component ATA:35 |
| PN:289-601-228  | MOS                             | 24-Sep-21                    | 72       |                        | 03-Sep-27                 |           | 1676 d    | OVERHAUL         |
| SN:NA           | HRS                             | 6141.4                       |          | TSN 0                  |                           |           |           |                  |
| WC#: 35.160     | AFL                             | 3647                         |          | TSN 0                  |                           |           |           |                  |
|                 |                                 | Manufacture Date:: 03-Sep-21 |          | PROC. REF: GENERIC CMM |                           |           |           |                  |
| 351057          | NO. 7 PASSENGER OXYGEN MASK     |                              |          |                        |                           |           |           | Component ATA:35 |
| PN:289-601-228  | MOS                             | 24-Sep-21                    | 72       |                        | 03-Sep-27                 |           | 1676 d    | OVERHAUL         |
| SN:NA           | HRS                             | 6141.4                       |          | TSN 0                  |                           |           |           |                  |
| WC#: 35.170     | AFL                             | 3647                         |          | TSN 0                  |                           |           |           |                  |
|                 |                                 | Manufacture Date:: 03-Sep-21 |          | PROC. REF: GENERIC CMM |                           |           |           |                  |
| 351058          | NO. 8 PASSENGER OXYGEN MASK     |                              |          |                        |                           |           |           | Component ATA:35 |
| PN:289-601-228  | MOS                             | 24-Sep-21                    | 72       |                        | 03-Sep-27                 |           | 1676 d    | OVERHAUL         |
| SN:NA           | HRS                             | 6141.4                       |          | TSN 0                  |                           |           |           |                  |
| WC#: 35.170     | AFL                             | 3647                         |          | TSN 0                  |                           |           |           |                  |
|                 |                                 | Manufacture Date:: 03-Sep-21 |          | PROC. REF: GENERIC CMM |                           |           |           |                  |
| 351061          | LAV PASSENGER OXYGEN MASK       |                              |          |                        |                           |           |           | Component ATA:35 |
| PN:289-601-228  | MOS                             | 24-Sep-21                    | 72       |                        | 03-Sep-27                 |           | 1676 d    | OVERHAUL         |
| SN:NA           | HRS                             | 6141.4                       |          | TSN 0                  |                           |           |           |                  |
| WC#: 35.190     | AFL                             | 3647                         |          | TSN 0                  |                           |           |           |                  |
|                 |                                 | Manufacture Date:: 03-Sep-21 |          | PROC. REF: GENERIC CMM |                           |           |           |                  |
| 351080          | NO. 1 MASK DEPLOYMENT CONTAINER |                              |          |                        |                           |           |           | Component ATA:35 |
| PN:PN           | MOS/MSC                         | 30-May-96                    | O/C      | TSN 0                  |                           |           |           |                  |
| SN:UNKNOWN      | HRS                             | 0                            |          | TSN 0                  |                           |           |           |                  |
| WC#: 35.195     | AFL                             | 0                            |          | TSN 0                  |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                 | Unit                            | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------|---------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 35 - OXYGEN         |                                 |           |          |          |                           |           |           |                  |
| 351081                  | NO. 2 MASK DEPLOYMENT CONTAINER |           |          |          |                           |           |           | Component ATA:35 |
| PN:PN                   | MOS/MSC                         | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN              | HRS                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 35.195             | AFL                             | 0         |          | TSN 0    |                           |           |           |                  |
| 351082                  | NO. 3 MASK DEPLOYMENT CONTAINER |           |          |          |                           |           |           | Component ATA:35 |
| PN:PN                   | MOS/MSC                         | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN              | HRS                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 35.200             | AFL                             | 0         |          | TSN 0    |                           |           |           |                  |
| 351083                  | NO. 4 MASK DEPLOYMENT CONTAINER |           |          |          |                           |           |           | Component ATA:35 |
| PN:PN                   | MOS/MSC                         | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN              | HRS                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 35.200             | AFL                             | 0         |          | TSN 0    |                           |           |           |                  |
| 351084                  | NO. 5 MASK DEPLOYMENT CONTAINER |           |          |          |                           |           |           | Component ATA:35 |
| PN:PN                   | MOS/MSC                         | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN              | HRS                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 35.205             | AFL                             | 0         |          | TSN 0    |                           |           |           |                  |
| 351085                  | NO. 6 MASK DEPLOYMENT CONTAINER |           |          |          |                           |           |           | Component ATA:35 |
| PN:PN                   | MOS/MSC                         | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN              | HRS                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 35.205             | AFL                             | 0         |          | TSN 0    |                           |           |           |                  |
| 351086                  | NO. 7 MASK DEPLOYMENT CONTAINER |           |          |          |                           |           |           | Component ATA:35 |
| PN:PN                   | MOS/MSC                         | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN              | HRS                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 35.210             | AFL                             | 0         |          | TSN 0    |                           |           |           |                  |
| 351093                  | OXYGEN PRESSURE SWITCH          |           |          |          |                           |           |           | Component ATA:35 |
| PN:PN                   | MOS/MSC                         | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN              | HRS                             | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 35.125             | AFL                             | 0         |          | TSN 0    |                           |           |           |                  |
| 351101                  | NO. 1 OXYGEN CYLINDER           |           |          |          |                           |           |           | Component ATA:35 |
| PN:176531-35            | MOS/MSC                         | 24-Sep-21 | O/C      |          |                           |           |           |                  |
| SN:616868               | HRS                             | 6141.4    |          |          |                           |           |           |                  |
| WC#: 35.010             | AFL                             | 3647      |          |          |                           |           |           |                  |
| PROC. REF: AMM 35-10-14 |                                 |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                               | Unit                                   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------------------|----------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 35 - OXYGEN                       |                                        |           |          |          |                           |           |           |                  |
| 351102                                | NO. 2 OXYGEN CYLINDER                  |           |          |          |                           |           |           | Component ATA:35 |
| PN:WKA37447                           | MOS/MSC                                | 25-Jun-20 | O/C      |          |                           |           |           |                  |
| SN:710187                             | HRS                                    | 5801      |          |          |                           |           |           |                  |
| WC#: 35.015                           | AFL                                    | 3399      |          |          |                           |           |           |                  |
| PROC. REF: AMM 35-10-14               |                                        |           |          |          |                           |           |           |                  |
| 351103                                | NO. 3 OXYGEN CYLINDER                  |           |          |          |                           |           |           | Component ATA:35 |
| PN:WKA37447                           | MOS/MSC                                | 25-Jun-20 | O/C      |          |                           |           |           |                  |
| SN:365487                             | HRS                                    | 5801      |          |          |                           |           |           |                  |
| WC#: 35.020                           | AFL                                    | 3399      |          |          |                           |           |           |                  |
| PROC. REF: MMA 35-06-01, AMM 35-10-14 |                                        |           |          |          |                           |           |           |                  |
| 351104                                | NO. 4 OXYGEN CYLINDER                  |           |          |          |                           |           |           | Component ATA:35 |
| PN:PN                                 | MOS/MSC                                | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                            | HRS                                    | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 35.025                           | AFL                                    | 0         |          | TSN 0    |                           |           |           |                  |
| 351110                                | HYDROSTATIC TEST NO. 1 OXYGEN CYLINDER |           |          |          |                           |           |           | Service ATA:35   |
| PN:176531-35                          | MOS                                    |           | 60       |          | 01-Jun-25 (M)             |           | 852 d     |                  |
| SN:616868                             | HRS                                    |           |          |          |                           |           |           |                  |
| WC#: 35.010                           | AFL                                    |           |          |          |                           |           |           |                  |
| PROC. REF: GENERIC CMM                |                                        |           |          |          |                           |           |           |                  |
| 351110                                | HYDROSTATIC TEST NO. 2 OXYGEN CYLINDER |           |          |          |                           |           |           | Service ATA:35   |
| PN:WKA37447                           | MOS                                    | 24-Jun-20 | 60       |          | 01-Jun-25 (M)             |           | 852 d     |                  |
| SN:710187                             | HRS                                    |           |          |          |                           |           |           |                  |
| WC#: 35.015                           | AFL                                    |           |          |          |                           |           |           |                  |
| PROC. REF: GENERIC CMM                |                                        |           |          |          |                           |           |           |                  |
| 351110                                | HYDROSTATIC TEST NO. 3 OXYGEN CYLINDER |           |          |          |                           |           |           | Service ATA:35   |
| PN:WKA37447                           | MOS                                    | 24-Jun-20 | 60       |          | 24-Jun-25                 |           | 875 d     |                  |
| SN:365487                             | HRS                                    |           |          |          |                           |           |           |                  |
| WC#: 35.020                           | AFL                                    |           |          |          |                           |           |           |                  |
| PROC. REF: GENERIC CMM                |                                        |           |          |          |                           |           |           |                  |
| 352001                                | ON/OFF OXYGEN VALVE                    |           |          |          |                           |           |           | Component ATA:35 |
| PN:SDV1012                            | MOS/MSC                                | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:9179                               | HRS                                    | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 35.065                           | AFL                                    | 0         |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                                            | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition             |
|---------------------------|-------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|-------------------------|
| ATA 35 - OXYGEN           |                                                 |           |          |          |                           |           |           |                         |
| 352007                    | BAROMATIC VALVE                                 |           |          |          |                           |           |           | Component ATA:35        |
| PN:K38002-1               | MOS/MSC                                         | 30-Aug-96 | O/C      |          |                           |           |           |                         |
| SN:532                    | HRS                                             | 16        |          | TSN 0    |                           |           |           |                         |
| WC#: 35.070               | AFL                                             | 9         |          |          |                           |           |           |                         |
| PROC. REF: AMM 35-20-42   |                                                 |           |          |          |                           |           |           |                         |
| 353001                    | PORTABLE OXYGEN BOTTLE                          |           |          |          |                           |           |           | Component ATA:35        |
| PN:176960-14              | MOS/MSC                                         | 25-Mar-21 | O/C      |          |                           |           |           |                         |
| SN:547299                 | HRS                                             |           |          |          |                           |           |           |                         |
| WC#: 35.080               | AFL                                             |           |          |          |                           |           |           |                         |
| 353007                    | HYDROSTATIC TEST PORTABLE OXYGEN BOTTLE         |           |          |          |                           |           |           | Service ATA:35          |
| PN:176960-14              | MOS                                             | 25-Mar-21 | 60       |          | 01-Jun-25 (M)             |           | 852 d     | MANDATORY               |
| SN:547299                 | HRS                                             |           |          |          |                           |           |           |                         |
| WC#: 35.080               | AFL                                             |           |          |          |                           |           |           |                         |
| 353031                    | (PBE) PROTECTIVE BREATHING EQUIPMENT            |           |          |          |                           |           |           | Component ATA:35        |
| PN:802300-14              | MOS                                             | 06-Jan-14 | 120      | TSN 0    | 01-Sep-23 (M)             |           | 213 d     | LIFE LIMIT              |
| SN:E13090363              | HRS                                             | 5056.7    |          | TSN 0    |                           |           |           |                         |
| WC#: 35.085               | AFL                                             | 2830      |          | TSN 0    |                           |           |           |                         |
| PROC. REF: GENERIC NO REF |                                                 |           |          |          |                           |           |           | WO#: N950PC B & C CHECK |
| 353031A <sup>U</sup>      | INSPECTION (PBE) PROTECTIVE BREATHING EQUIPMENT |           |          |          |                           |           |           | Service ATA:35          |
| PN:802300-14              | MOS                                             | 21-Jun-22 | 12       |          | 21-Jun-23                 |           | 141 d     |                         |
| SN:E13090363              | HRS                                             | 6373      |          |          |                           |           |           |                         |
|                           | AFL                                             | 3814      |          |          |                           |           |           |                         |
|                           |                                                 |           |          |          |                           |           |           | WO#: N950PC B & C CHECK |
| 354000                    | AUTOMATIC SHUT OFF VALVE                        |           |          |          |                           |           |           | Component ATA:35        |
| PN:PN                     | MOS/MSC                                         | 30-May-96 | O/C      | TSN 0    |                           |           |           |                         |
| SN:UNKNOWN                | HRS                                             | 0         |          | TSN 0    |                           |           |           |                         |
| WC#: 35.130               | AFL                                             | 0         |          | TSN 0    |                           |           |           |                         |
| 35R160 <sup>U</sup>       | LINE FILTER                                     |           |          |          |                           |           |           | Component ATA:35        |
| PN:WKA27942-2             | MOS/MSC                                         | 30-Oct-08 | O/C      |          |                           |           |           |                         |
| SN:1724                   | HRS                                             | 3853.1    |          |          |                           |           |           |                         |
|                           | AFL                                             | 2158      |          |          |                           |           |           |                         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                                 | Unit                                                                               | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition                         |
|-------------------------------------------------------------------------|------------------------------------------------------------------------------------|-----------|---------------|----------|---------------------------|-----------|-----------|-------------------------------------|
| ATA 38 - WATER/WASTE                                                    |                                                                                    |           |               |          |                           |           |           |                                     |
| 380001                                                                  | INSPECT TOILET AND GALLEY WATER SYSTEMS                                            |           |               |          |                           |           |           | Service ATA:38                      |
|                                                                         | MOS                                                                                | 15-Oct-19 |               |          |                           |           |           |                                     |
|                                                                         | HRS                                                                                | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)  |                                     |
| WC#: 38.010                                                             | AFL                                                                                | 3397      |               |          |                           |           |           |                                     |
| PROC. REF: AMM 12-38-00                                                 |                                                                                    |           |               |          |                           |           |           | PKG:2,13<br>WO#: N950PC B & C CHECK |
| 381090                                                                  | CLEAN GALLEY WATER SYSTEM                                                          |           |               |          |                           |           |           | Service ATA:38                      |
|                                                                         | MOS/MSC                                                                            | 15-Apr-21 | A/R           |          |                           |           |           |                                     |
|                                                                         | HRS                                                                                | 5960.1    |               |          |                           |           |           |                                     |
| WC#: 38.020                                                             | AFL                                                                                | 3523      |               |          |                           |           |           |                                     |
| 381091                                                                  | CLEAN LAVATORY WATER SYSTEM                                                        |           |               |          |                           |           |           | Service ATA:38                      |
|                                                                         | MOS/MSC                                                                            |           | A/R           |          |                           |           |           |                                     |
|                                                                         | HRS                                                                                | 0         |               |          |                           |           |           |                                     |
| WC#: 38.030                                                             | AFL                                                                                |           |               |          |                           |           |           |                                     |
| ATA 49 - AIRBORNE AUXILIARY POWER                                       |                                                                                    |           |               |          |                           |           |           |                                     |
| 490002                                                                  | REMOVE/CLEAN/INSPECT APU IGNITER PLUG                                              |           |               |          |                           |           |           | Service ATA:49                      |
|                                                                         | MOS/MSC                                                                            | 23-Jul-21 | N/R           |          |                           |           |           |                                     |
|                                                                         | HRS                                                                                | 6077.4    |               |          |                           |           |           |                                     |
| WC#: 49.210                                                             | AFL                                                                                | 3596      |               |          |                           |           |           |                                     |
| PROC. REF: AFMS OUT OF PHASE INSPECTIONS                                |                                                                                    |           |               |          |                           |           |           |                                     |
| 490003                                                                  | ACCOMPLISH APU (OPTION 1) OIL AND FILTER CHANGE AND MAGNETIC DRAIN PLUG INSPECTION |           |               |          |                           |           |           | Service ATA:49                      |
|                                                                         | MOS/MSC                                                                            |           | N/R           |          |                           |           |           |                                     |
|                                                                         | HRS                                                                                | 0         |               |          |                           |           |           |                                     |
| WC#: 49.220                                                             | AFL                                                                                |           |               |          |                           |           |           |                                     |
| PROC. REF: AFMS OUT OF PHASE INSPECTIONS, AFMS OUT OF PHASE INSPECTIONS |                                                                                    |           |               |          |                           |           |           |                                     |
| 490003                                                                  | ACCOMPLISH APU (OPTION 2) S.O.A.P CHECK                                            |           |               |          |                           |           |           | Service ATA:49                      |
|                                                                         | MOS/MSC                                                                            |           | N/R           |          |                           |           |           |                                     |
|                                                                         | HRS                                                                                | 0         |               |          |                           |           |           |                                     |
| WC#: 49.221                                                             | AFL                                                                                |           |               |          |                           |           |           |                                     |
| PROC. REF: AFMS OUT OF PHASE INSPECTIONS, AFMS OUT OF PHASE INSPECTIONS |                                                                                    |           |               |          |                           |           |           |                                     |
| 490004                                                                  | REMOVE AND REPLACE APU FUEL FILTER ELEMENT                                         |           |               |          |                           |           |           | Service ATA:49                      |
|                                                                         | MOS/MSC                                                                            |           | N/R           |          |                           |           |           |                                     |
|                                                                         | HRS                                                                                | 0         |               |          |                           |           |           |                                     |
| WC#: 49.230                                                             | AFL                                                                                |           |               |          |                           |           |           |                                     |
| PROC. REF: AFMS OUT OF PHASE INSPECTIONS                                |                                                                                    |           |               |          |                           |           |           |                                     |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                                 | Unit                                                     | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition             |
|-------------------------------------------------------------------------|----------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|-------------------------|
| ATA 49 - AIRBORNE AUXILIARY POWER                                       |                                                          |           |          |          |                           |           |           |                         |
| 490005                                                                  | FLOW CHECK APU FUEL NOZZLE ASSEMBLIES                    |           |          |          |                           |           |           | Service ATA:49          |
|                                                                         | MOS/MSC                                                  | 23-Jul-21 | N/R      |          |                           |           |           |                         |
|                                                                         | HRS                                                      | 6077.4    |          |          |                           |           |           |                         |
| WC#: 49.240                                                             | AFL                                                      | 3596      |          |          |                           |           |           |                         |
| PROC. REF: AFMS OUT OF PHASE INSPECTIONS                                |                                                          |           |          |          |                           |           |           |                         |
| 490006                                                                  | ACCOMPLISH APU DETAILED HOT SECTION INSPECTION           |           |          |          |                           |           |           | Service ATA:49          |
|                                                                         | MOS/MSC                                                  |           | N/R      |          |                           |           |           |                         |
|                                                                         | HRS                                                      | 0         |          |          |                           |           |           |                         |
| WC#: 49.250                                                             | AFL                                                      |           |          |          |                           |           |           |                         |
| PROC. REF: AFMS OUT OF PHASE INSPECTIONS, AFMS OUT OF PHASE INSPECTIONS |                                                          |           |          |          |                           |           |           |                         |
| 490007                                                                  | VISUALLY CHECK APU COMPRESSOR ROTOR                      |           |          |          |                           |           |           | Service ATA:49          |
|                                                                         | MOS/MSC                                                  |           | N/R      |          |                           |           |           |                         |
|                                                                         | HRS                                                      | 0         |          |          |                           |           |           |                         |
| WC#: 49.260                                                             | AFL                                                      |           |          |          |                           |           |           |                         |
| PROC. REF: AFMS OUT OF PHASE INSPECTIONS                                |                                                          |           |          |          |                           |           |           |                         |
| 490010                                                                  | APU - ACCOMPLISH 6 MONTH/125 HOUR/250 CYCLE INSPECTION   |           |          |          |                           |           |           | Service ATA:49          |
|                                                                         | MOS                                                      | 11-Oct-22 | 6        |          | 11-Apr-23                 |           | 70 d      |                         |
|                                                                         | HRS                                                      | 3334.45   | 125      |          | 3459.45                   |           | 110.3     |                         |
| WC#: 49.010                                                             | APUS                                                     | 6272      | 250      |          | 6522                      |           | 220       |                         |
| PROC. REF: SB SB-T-62T-49-77, MM 49-20-00                               |                                                          |           |          |          |                           |           |           | WO#: N950PC B & C CHECK |
| 490020                                                                  | APU - ACCOMPLISH 6 MONTH/250 HOUR/500 CYCLE INSPECTION   |           |          |          |                           |           |           | Service ATA:49          |
|                                                                         | MOS                                                      | 11-Oct-22 | 6        |          | 11-Apr-23                 |           | 70 d      |                         |
|                                                                         | HRS                                                      | 3334.45   | 250      |          | 3584.45                   |           | 235.3     |                         |
| WC#: 49.015                                                             | APUS                                                     | 6272      | 500      |          | 6772                      |           | 470       |                         |
| PROC. REF: SB SB-T-62T-49-77                                            |                                                          |           |          |          |                           |           |           | WO#: N950PC B & C CHECK |
| 490028 <sup>U</sup>                                                     | APU FUEL NOZZLE CLEAN                                    |           |          |          |                           |           |           | Service ATA:49          |
|                                                                         | MOS/MSC                                                  | 06-Jan-23 | A/R      |          |                           |           |           |                         |
|                                                                         | HRS                                                      | 6519.5    |          |          |                           |           |           |                         |
|                                                                         | AFL                                                      | 3923      |          |          |                           |           |           |                         |
| 490030                                                                  | APU - ACCOMPLISH 12 MONTH/500 HOUR/1000 CYCLE INSPECTION |           |          |          |                           |           |           | Service ATA:49          |
|                                                                         | MOS                                                      | 07-Apr-22 | 12       |          | 07-Apr-23                 |           | 66 d      |                         |
|                                                                         | HRS                                                      | 3275.52   | 500      |          | 3775.52                   |           | 426.4     |                         |
| WC#: 49.020                                                             | APUS                                                     | 6181      | 1000     |          | 7181                      |           | 879       |                         |
| PROC. REF: SB SB-T-62T-49-77, MM 49-20-00                               |                                                          |           |          |          |                           |           |           |                         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                   | Unit                                                      | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining               | Disposition      |
|-------------------------------------------|-----------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-------------------------|------------------|
| ATA 49 - AIRBORNE AUXILIARY POWER         |                                                           |           |          |          |                           |           |                         |                  |
| 490040                                    | APU - ACCOMPLISH 12 MONTH/1000 HOUR/2000 CYCLE INSPECTION |           |          |          |                           |           |                         | Service ATA:49   |
|                                           | MOS                                                       | 07-Apr-22 | 12       |          | 07-Apr-23                 |           | 66 d                    |                  |
|                                           | HRS                                                       | 3275.52   | 1000     |          | 4275.52                   |           | 926.4                   |                  |
| WC#: 49.025                               | APUS                                                      | 6181      | 2000     |          | 8181                      |           | 1879                    |                  |
| PROC. REF: SB SB-T-62T-49-77, MM 49-20-00 |                                                           |           |          |          |                           |           | WO#: N950PC B & C CHECK |                  |
| 490050                                    | APU - ACCOMPLISH 24 MONTH/1500 HOUR/3000 CYCLE INSPECTION |           |          |          |                           |           |                         | Service ATA:49   |
|                                           | MOS                                                       | 15-Apr-21 | 24       |          | 15-Apr-23                 |           | 74 d                    |                  |
|                                           | HRS                                                       | 3074.4    | 1500     |          | 4574.4                    |           | 1225.3                  |                  |
| WC#: 49.030                               | APUS                                                      | 5816      | 3000     |          | 8816                      |           | 2514                    |                  |
| PROC. REF: SB SB-T-62T-49-77, MM 49-20-00 |                                                           |           |          |          |                           |           | WO#: N950PC B & C CHECK |                  |
| 490079 <sup>U</sup>                       | APU ADD OIL                                               |           |          |          |                           |           |                         | Service ATA:49   |
|                                           | MOS/MSC                                                   | 06-Jan-23 | A/R      |          |                           |           |                         |                  |
|                                           | HRS                                                       | 6519.5    |          |          |                           |           |                         |                  |
|                                           | AFL                                                       | 3923      |          |          |                           |           |                         |                  |
| 491005                                    | APU BLEED AIR CHECK VALVE                                 |           |          |          |                           |           |                         | Component ATA:49 |
| PN:PN                                     | MOS/MSC                                                   | 30-May-96 | O/C      | TSN 0    |                           |           |                         |                  |
| SN:UNKNOWN                                | HRS                                                       | 0         |          | TSN 0    |                           |           |                         |                  |
|                                           | AFL                                                       | 0         |          | TSN 0    |                           |           |                         |                  |
| PROC. REF: GENERIC NO REF                 |                                                           |           |          |          |                           |           |                         |                  |
| 491010                                    | APU - TURBINE ROTOR                                       |           |          |          |                           |           |                         | Component ATA:49 |
| PN:4502951                                | MOS                                                       | 29-Jan-99 |          | TSN 0    |                           |           |                         | LIFE LIMIT       |
| SN:V22-H577P                              | HRS                                                       | 458.27    |          | TSN 0    |                           |           |                         |                  |
| WC#: 49.035                               | APUS                                                      | 710       | 9000     | TSN 0    | 9710                      |           | 3408                    |                  |
| PROC. REF: GENERIC NO REF                 |                                                           |           |          |          |                           |           |                         |                  |
| 491020                                    | APU - COMPRESSOR ROTOR                                    |           |          |          |                           |           |                         | Component ATA:49 |
| PN:4502892                                | MOS                                                       | 29-Jan-99 |          | TSN 0    |                           |           |                         | LIFE LIMIT       |
| SN:V45-C1980                              | HRS                                                       | 458.27    |          | TSN 0    |                           |           |                         |                  |
| WC#: 49.040                               | APUS                                                      | 710       | 18000    | TSN 0    | 18710                     |           | 12408                   |                  |
| PROC. REF: GENERIC NO REF                 |                                                           |           |          |          |                           |           |                         |                  |
| 491021 <sup>U</sup>                       | APU - PINION ASSEMBLY INPUT                               |           |          |          |                           |           |                         | Component ATA:49 |
| PN:44647-0                                | MOS/MSC                                                   | 13-Jul-96 | A/R      | TSN 0    |                           |           |                         |                  |
| SN:D90-0095                               | HRS                                                       | 7.9       |          | TSN 7.9  |                           |           |                         |                  |
|                                           | APUS                                                      | 38        |          | TSN 38   |                           |           |                         |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                           | Unit    | C/W                          | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |
|-----------------------------------|---------|------------------------------|----------|----------|---------------------------|-----------|-----------|-------------|
| ATA 49 - AIRBORNE AUXILIARY POWER |         |                              |          |          |                           |           |           |             |
| 491022 <sup>U</sup>               |         | APU - ROLLER BEARING         |          |          |                           |           | Component | ATA:49      |
| PN:171146-1                       | MOS/MSC | 13-Jul-96                    | A/R      | TSN 0    |                           |           |           |             |
| SN:V13-S-1844                     | HRS     | 7.9                          |          | TSN 7.9  |                           |           |           |             |
|                                   | APUS    | 38                           |          | TSN 38   |                           |           |           |             |
| 491023 <sup>U</sup>               |         | APU - ROTOR ASSEMBLY         |          |          |                           |           | Component | ATA:49      |
| PN:161335-502A                    | MOS/MSC | 13-Jul-96                    | A/R      | TSN 0    |                           |           |           |             |
| SN:Y94-K059                       | HRS     | 7.9                          |          | TSN 7.9  |                           |           |           |             |
|                                   | APUS    | 38                           |          | TSN 38   |                           |           |           |             |
| 491024 <sup>U</sup>               |         | APU - ROTOR SHAFT            |          |          |                           |           | Component | ATA:49      |
| PN:103334-100                     | MOS/MSC | 13-Jul-96                    | A/R      | TSN 0    |                           |           |           |             |
| SN:Y94-K059                       | HRS     | 7.9                          |          | TSN 7.9  |                           |           |           |             |
|                                   | APUS    | 38                           |          | TSN 38   |                           |           |           |             |
| 491025 <sup>U</sup>               |         | APU - TRUST BEARING          |          |          |                           |           | Component | ATA:49      |
| PN:169660-2                       | MOS/MSC | 13-Jul-96                    | A/R      | TSN 0    |                           |           |           |             |
| SN:1787-1247                      | HRS     | 7.9                          |          | TSN 7.9  |                           |           |           |             |
|                                   | APUS    | 38                           |          | TSN 38   |                           |           |           |             |
| 491026 <sup>U</sup>               |         | APU - TURBINE ASSEMBLY       |          |          |                           |           | Component | ATA:49      |
| PN:160183-601A                    | MOS/MSC | 13-Jul-96                    | A/R      | TSN 0    |                           |           |           |             |
| SN:4G21                           | HRS     | 7.3                          |          | TSN 7.9  |                           |           |           |             |
|                                   | APUS    | 38                           |          | TSN 38   |                           |           |           |             |
| 491027 <sup>U</sup>               |         | APU - TURBINE NOZZLE         |          |          |                           |           | Component | ATA:49      |
| PN:113089-200                     | MOS/MSC | 13-Jul-96                    | A/R      | TSN 0    |                           |           |           |             |
| SN:NA                             | HRS     | 7.9                          |          | TSN 7.9  |                           |           |           |             |
|                                   | APUS    | 38                           |          | TSN 38   |                           |           |           |             |
| 491028 <sup>U</sup>               |         | APU - CARRIER ASSEMBLY       |          |          |                           |           | Component | ATA:49      |
| PN:161352-100A                    | MOS/MSC | 13-Jul-96                    | O/C      |          |                           |           |           |             |
| SN:205                            | HRS     | 7.9                          |          | TSN 7.9  |                           |           |           |             |
|                                   | APUS    | 38                           |          | TSN 38   |                           |           |           |             |
| 491029 <sup>U</sup>               |         | APU - PINION ACCESSORY DRIVE |          |          |                           |           | Component | ATA:49      |
| PN:30418-1                        | MOS/MSC | 13-Jul-96                    | O/C      |          |                           |           |           |             |
| SN:D74-0420                       | HRS     | 7.9                          |          | TSN 7.9  |                           |           |           |             |
|                                   | APUS    | 38                           |          | TSN 38   |                           |           |           |             |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                                    | Unit                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------------------------------------------------|---------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 49 - AIRBORNE AUXILIARY POWER                                          |                                       |           |          |          |                           |           |           |                  |
| 492000                                                                     | APU - PRESERVATION AND STORAGE OF APU |           |          |          |                           |           |           | Service ATA:49   |
|                                                                            | MOS/MSC                               | 11-Sep-96 | A/R      |          |                           |           |           |                  |
|                                                                            | HRS                                   | 9         |          |          |                           |           |           |                  |
|                                                                            | APUS                                  | 47        |          |          |                           |           |           |                  |
| 492001 <sup>U</sup>                                                        | APU DOWNLOAD                          |           |          |          |                           |           |           | Service ATA:49   |
|                                                                            | DAYS                                  | 06-Jan-23 | 60       |          | 07-Mar-23                 |           | 35 d      |                  |
|                                                                            | HRS                                   | 6519.5    |          |          |                           |           |           |                  |
|                                                                            | AFL                                   | 3923      |          |          |                           |           |           |                  |
| 492010                                                                     | APU - COMBUSTOR HOUSING ASSEMBLY      |           |          |          |                           |           |           | Component ATA:49 |
| PN:160184-201                                                              | MOS/MSC                               | 13-Jul-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:F96-001                                                                 | HRS                                   | 7.9       |          | TSN 7.9  |                           |           |           |                  |
| WC#: 49.130                                                                | APUS                                  | 38        |          | TSN 38   |                           |           |           |                  |
| PROC. REF: MM 49-20-00 , MM IPC 49-20-21, MM IPC 49-20-21, MM IPC 49-20-21 |                                       |           |          |          |                           |           |           |                  |
| 492015 <sup>U</sup>                                                        | APU - COMBUSTOR LINER                 |           |          |          |                           |           |           | Component ATA:49 |
| PN:171924-100                                                              | MOS/MSC                               | 13-Jul-96 | A/R      | TSN 0    |                           |           |           |                  |
| SN:F96-018                                                                 | HRS                                   | 7.9       |          | TSN 7.9  |                           |           |           |                  |
|                                                                            | APUS                                  | 38        |          | TSN 38   |                           |           |           |                  |
| 492020                                                                     | APU - INLET AIR ASSEMBLY DUCT         |           |          |          |                           |           |           | Component ATA:49 |
| PN:105769-200                                                              | MOS/MSC                               | 29-Jan-99 | O/C      | TSN 0    |                           |           |           |                  |
| SN:7K22                                                                    | HRS                                   |           |          | TSN 0    |                           |           |           |                  |
| WC#: 49.140                                                                | APUS                                  |           |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                                                  |                                       |           |          |          |                           |           |           |                  |
| 493001 <sup>U</sup>                                                        | APU FUEL BOOST PUMP                   |           |          |          |                           |           |           | Component ATA:49 |
| PN:1500-00-65                                                              | MOS/MSC                               | 19-Aug-21 | O/C      | TSO 0    |                           |           |           |                  |
| SN:0197                                                                    | HRS                                   | 6108.8    |          | TSO 0    |                           |           |           |                  |
|                                                                            | AFL                                   | 3621      |          | TSO 0    |                           |           |           |                  |
| 493010                                                                     | APU - FUEL PUMP                       |           |          |          |                           |           |           | Component ATA:49 |
| PN:49500037                                                                | MOS/MSC                               | 11-Sep-96 | O/C      |          |                           |           |           |                  |
| SN:V68-T0062                                                               | HRS                                   | 9         |          | TSN 9    |                           |           |           |                  |
| WC#: 49.045                                                                | APUS                                  | 47        |          | TSN 47   |                           |           |           |                  |
| PROC. REF: MM 49-20-00 , MM IPC 49-20-21, MM IPC 49-20-21                  |                                       |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                   | Unit                                | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------------------------------------------------|-------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 49 - AIRBORNE AUXILIARY POWER                         |                                     |           |          |          |                           |           |           |                  |
| 493070                                                    | APU - COMBUSTOR DRAIN VALVE         |           |          |          |                           |           |           | Component ATA:49 |
| PN:45352-100                                              | MOS/MSC                             | 11-Sep-96 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                                                | HRS                                 | 9         |          | TSN 9    |                           |           |           |                  |
| WC#: 49.050                                               | APUS                                | 47        |          | TSN 47   |                           |           |           |                  |
| PROC. REF: MM IPC 49-20-21, MM 49-20-00                   |                                     |           |          |          |                           |           |           |                  |
| 493080                                                    | APU - FUEL START NOZZLE             |           |          |          |                           |           |           | Component ATA:49 |
| PN:169111-2                                               | MOS/MSC                             | 09-Dec-21 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN                                                | HRS                                 | 3215      |          |          |                           |           |           |                  |
| WC#: 49.055                                               | APUS                                |           |          |          |                           |           |           |                  |
| PROC. REF: MM 49-20-00 , MM IPC 49-20-21, MM IPC 49-20-21 |                                     |           |          |          |                           |           |           |                  |
| 493090                                                    | APU - START BYPASS VALVE            |           |          |          |                           |           |           | Component ATA:49 |
| PN:160360-4                                               | MOS/MSC                             | 11-Sep-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:1318                                                   | HRS                                 | 9         |          | TSN 0    |                           |           |           |                  |
| WC#: 49.060                                               | APUS                                | 47        |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 49-20-00 , MM IPC 49-20-21                  |                                     |           |          |          |                           |           |           |                  |
| 493110                                                    | APU - ACCELERATION CONTROL ASSEMBLY |           |          |          |                           |           |           | Component ATA:49 |
| PN:4500946                                                | MOS/MSC                             | 11-Sep-96 | O/C      |          |                           |           |           |                  |
| SN:029602                                                 | HRS                                 | 9         |          | TSN 9    |                           |           |           |                  |
| WC#: 49.115                                               | APUS                                | 47        |          | TSN 47   |                           |           |           |                  |
| PROC. REF: MM 49-20-00 , MM IPC 49-20-21, MM IPC 49-20-21 |                                     |           |          |          |                           |           |           |                  |
| 493210                                                    | APU - FLOW RESTRICTOR               |           |          |          |                           |           |           | Component ATA:49 |
| PN:179290-1                                               | MOS/MSC                             | 19-Sep-17 | O/C      | TSR 0    |                           |           |           |                  |
| SN:05951371                                               | HRS                                 | 2805.08   |          | TSR 0    |                           |           |           |                  |
| WC#: 49.065                                               | APUS                                | 5381      |          | TSR 0    |                           |           |           |                  |
| PROC. REF: MM 49-20-00 , MM IPC 49-20-21                  |                                     |           |          |          |                           |           |           |                  |
| 494010                                                    | APU - IGNITION EXCITER              |           |          |          |                           |           |           | Component ATA:49 |
| PN:110418-1                                               | MOS/MSC                             | 11-Sep-96 | O/C      |          |                           |           |           |                  |
| SN:96241547                                               | HRS                                 | 9         |          | TSN 9    |                           |           |           |                  |
| WC#: 49.070                                               | APUS                                | 47        |          | TSN 47   |                           |           |           |                  |
| PROC. REF: MM 49-20-00 , MM IPC 49-20-21                  |                                     |           |          |          |                           |           |           |                  |
| 494020                                                    | APU - IGNITER PLUG                  |           |          |          |                           |           |           | Component ATA:49 |
| PN:FHE159-6                                               | MOS/MSC                             | 13-Oct-15 | O/C      | TSN 0    |                           |           |           |                  |
| SN:NSN                                                    | HRS                                 |           |          | TSN 0    |                           |           |           |                  |
| WC#: 49.075                                               | APUS                                |           |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 49-20-00 , MM IPC 49-20-21                  |                                     |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                   | Unit                             | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------------------------------------------------|----------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 49 - AIRBORNE AUXILIARY POWER                         |                                  |           |          |          |                           |           |           |                  |
| 495020                                                    | APU - BLEED AIR MODULATING VALVE |           |          |          |                           |           |           | Component ATA:49 |
| PN:160290-100                                             | MOS/MSC                          | 13-Jul-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:NA                                                     | HRS                              | 7.9       |          | TSN 7.9  |                           |           |           |                  |
| WC#: 49.080                                               | APUS                             | 38        |          | TSN 38   |                           |           |           |                  |
| PROC. REF: MM 49-20-00 , MM IPC 49-20-21                  |                                  |           |          |          |                           |           |           |                  |
| 495021 <sup>U</sup>                                       | APU - EGT THERMOCOUPLE           |           |          |          |                           |           |           | Component ATA:49 |
| PN:160021-3                                               | MOS/MSC                          | 13-Jul-96 | A/R      | TSN 0    |                           |           |           |                  |
| SN:NA                                                     | HRS                              | 7.9       |          | TSN 7.9  |                           |           |           |                  |
|                                                           | APUS                             | 38        |          | TSN 38   |                           |           |           |                  |
| 496010                                                    | APU - ELECTRONIC SEQUENCE UNIT   |           |          |          |                           |           |           | Component ATA:49 |
| PN:164540-800A                                            | MOS/MSC                          | 09-Jul-98 | O/C      | TSN 0    |                           |           |           |                  |
| SN:1021                                                   | HRS                              | 354       |          | TSN 0    |                           |           |           |                  |
| WC#: 49.085                                               | APUS                             |           |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                                 |                                  |           |          |          |                           |           |           |                  |
| 496020                                                    | APU - ANALOG CONVERTER CONTROL   |           |          |          |                           |           |           | Component ATA:49 |
| PN:160240-600                                             | MOS/MSC                          | 11-Sep-96 | O/C      |          |                           |           |           |                  |
| SN:7375-0389                                              | HRS                              | 9         |          | TSN 9    |                           |           |           |                  |
| WC#: 49.090                                               | APUS                             | 47        |          | TSN 47   |                           |           |           |                  |
| PROC. REF: GENERIC NO REF                                 |                                  |           |          |          |                           |           |           |                  |
| 496030                                                    | APU - MAGNETIC PICK-UP           |           |          |          |                           |           |           | Component ATA:49 |
| PN:PN                                                     | MOS/MSC                          | 11-Sep-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                                | HRS                              | 9         |          | TSN 0    |                           |           |           |                  |
| WC#: 49.095                                               | APUS                             | 47        |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 49-20-00 , MM IPC 49-20-21                  |                                  |           |          |          |                           |           |           |                  |
| 497030                                                    | APU - EVENT COUNTER/HOURMETER    |           |          |          |                           |           |           | Component ATA:49 |
| PN:PN                                                     | MOS/MSC                          | 11-Sep-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                                                | HRS                              | 9         |          | TSN 0    |                           |           |           |                  |
| WC#: 49.100                                               | APUS                             | 47        |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 49-20-00 , MM IPC 49-20-21, MM IPC 49-20-21 |                                  |           |          |          |                           |           |           |                  |
| 497201 <sup>U</sup>                                       | APU - NO.1 VALVE- SOLENOID       |           |          |          |                           |           |           | Component ATA:49 |
| PN:161798-1                                               | MOS/MSC                          | 13-Jul-96 | O/C      |          |                           |           |           |                  |
| SN:4294                                                   | HRS                              | 7.9       |          | TSN 7.9  |                           |           |           |                  |
|                                                           | APUS                             | 38        |          | TSN 38   |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                           | Unit    | C/W                        | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |
|-----------------------------------|---------|----------------------------|----------|----------|---------------------------|-----------|-----------|-------------|
| ATA 49 - AIRBORNE AUXILIARY POWER |         |                            |          |          |                           |           |           |             |
| 497202 <sup>U</sup>               |         | APU - NO.2 VALVE- SOLENOID |          |          |                           |           | Component | ATA:49      |
| PN:161798-1                       | MOS/MSC | 13-Jul-96                  | O/C      |          |                           |           |           |             |
| SN:4291                           | HRS     | 7.9                        |          | TSN 7.9  |                           |           |           |             |
|                                   | APUS    | 38                         |          | TSN 38   |                           |           |           |             |
| 497203 <sup>U</sup>               |         | APU - NO.3 VALVE- SOLENOID |          |          |                           |           | Component | ATA:49      |
| PN:161798-3                       | MOS/MSC | 13-Jul-96                  | O/C      |          |                           |           |           |             |
| SN:997                            | HRS     | 7.9                        |          | TSN 7.9  |                           |           |           |             |
|                                   | APUS    | 38                         |          | TSN 38   |                           |           |           |             |
| 497251 <sup>U</sup>               |         | APU - ACCESSORY DRIVE GEAR |          |          |                           |           | Component | ATA:49      |
| PN:36714-0                        | MOS/MSC | 13-Jul-96                  | O/C      |          |                           |           |           |             |
| SN:D27-0010                       | HRS     | 7.9                        |          | TSN 7.9  |                           |           |           |             |
|                                   | APUS    | 38                         |          | TSN 38   |                           |           |           |             |
| 497252 <sup>U</sup>               |         | APU - GEAR- INTERMEDIATE   |          |          |                           |           | Component | ATA:49      |
| PN:30419-1                        | MOS/MSC | 13-Jul-96                  | O/C      |          |                           |           |           |             |
| SN:035-0012                       | HRS     | 7.9                        |          | TSN 7.9  |                           |           |           |             |
|                                   | APUS    | 38                         |          | TSN 38   |                           |           |           |             |
| 497253 <sup>U</sup>               |         | APU - GEAR- RING           |          |          |                           |           | Component | ATA:49      |
| PN:30276-1                        | MOS/MSC | 13-Jul-96                  | O/C      |          |                           |           |           |             |
| SN:V33-K007                       | HRS     | 7.9                        |          | TSN 7.9  |                           |           |           |             |
|                                   | APUS    | 38                         |          | TSN 38   |                           |           |           |             |
| 497254 <sup>U</sup>               |         | APU - GEAR STAR- SET       |          |          |                           |           | Component | ATA:49      |
| PN:30277-0                        | MOS/MSC | 13-Jul-96                  | O/C      |          |                           |           |           |             |
| SN:D09-0003                       | HRS     | 7.9                        |          | TSN 7.9  |                           |           |           |             |
|                                   | APUS    | 38                         |          | TSN 38   |                           |           |           |             |
| 497255 <sup>U</sup>               |         | APU - GEAR- ZEROL          |          |          |                           |           | Component | ATA:49      |
| PN:30416-1                        | MOS/MSC | 13-Jul-96                  | O/C      |          |                           |           |           |             |
| SN:V23-0420                       | HRS     | 7.9                        |          | TSN 7.9  |                           |           |           |             |
|                                   | APUS    | 38                         |          | TSN 38   |                           |           |           |             |
| 497310 <sup>U</sup>               |         | APU - FUEL MANIFOLD ASSY.  |          |          |                           |           | Component | ATA:49      |
| PN:172338-200                     | MOS/MSC | 13-Jul-96                  | O/C      |          |                           |           |           |             |
| SN:0094                           | HRS     | 7.9                        |          | TSN 7.9  |                           |           |           |             |
|                                   | APUS    | 38                         |          | TSN 38   |                           |           |           |             |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                               | Unit                                        | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|-------------------------------------------------------|---------------------------------------------|-----------|---------------|----------|---------------------------|-----------|--------------|------------------|
| ATA 49 - AIRBORNE AUXILIARY POWER                     |                                             |           |               |          |                           |           |              |                  |
| 498163 <sup>U</sup>                                   | APU FUEL VALVE                              |           |               |          |                           |           |              | Component ATA:49 |
| PN:7032B0000                                          | MOS/MSC                                     | 11-Sep-96 | O/C           |          |                           |           |              |                  |
| SN:UNKNOWN                                            | HRS                                         | 9         |               | TSN 9    |                           |           |              |                  |
|                                                       | AFL                                         | 47        |               | TSN 47   |                           |           |              |                  |
| 499060 <sup>U</sup>                                   | APU - OIL-HIGH TEMP SWITCH                  |           |               |          |                           |           |              | Component ATA:49 |
| PN:160260-3                                           | MOS/MSC                                     | 13-Jul-96 | O/C           |          |                           |           |              |                  |
| SN:105843                                             | HRS                                         | 7         |               | TSN 7    |                           |           |              |                  |
|                                                       | APUS                                        | 38        |               | TSN 38   |                           |           |              |                  |
| 499070                                                | APU - OIL PRESSURE SWITCH                   |           |               |          |                           |           |              | Component ATA:49 |
| PN:P18M-H14                                           | MOS/MSC                                     | 29-Oct-22 | O/C           |          |                           |           |              |                  |
| SN:3862                                               | HRS                                         |           |               |          |                           |           |              |                  |
| WC#: 49.105                                           | APUS                                        |           |               |          |                           |           |              |                  |
| PROC. REF: MM 49-20-00 , MM IPC 49-20-21              |                                             |           |               |          |                           |           |              |                  |
| 499110                                                | APU - SOAP CHECK OIL                        |           |               |          |                           |           |              | Service ATA:49   |
|                                                       | MOS/MSC                                     | 11-Sep-96 | A/R           |          |                           |           |              |                  |
|                                                       | HRS                                         | 9.5       |               |          |                           |           |              |                  |
| WC#: 49.110                                           | APUS                                        | 47        |               |          |                           |           |              |                  |
| PROC. REF: MM 49-20-00 , MM 49-20-00                  |                                             |           |               |          |                           |           |              |                  |
| 49APU1                                                | APU                                         |           |               |          |                           |           |              | Component ATA:49 |
| PN:165101-200                                         | MOS/MSC                                     |           | E/C           |          |                           |           |              |                  |
| SN:SP-E965277                                         | HRS                                         |           |               |          |                           |           |              |                  |
| WC#: 49.APU1                                          | AFL                                         |           |               |          |                           |           |              |                  |
| PROC. REF: AMM 49-16-00                               |                                             |           |               |          |                           |           |              |                  |
| ATA 51 - STD PRACTICES AND STRUCT-GENRL               |                                             |           |               |          |                           |           |              |                  |
| 510001                                                | INSPECT/NDT NOSE LANDING GEAR BAY SIDEWALLS |           |               |          |                           |           |              | Service ATA:51   |
|                                                       | MOS                                         | 25-Jun-20 | 144 (+3m)     |          | 25-Jun-32                 | 25-Sep-32 | 3433 d (+92) |                  |
|                                                       | HRS                                         | 5801      |               |          |                           |           |              |                  |
| WC#: 51.100                                           | AFL                                         | 3399      | 5000 (+10%)   |          | 8399                      | 8899      | 4470 (+500)  |                  |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS, NTM 53-10-111 |                                             |           |               |          |                           |           |              |                  |
| 510002                                                | DETAIL INSPECT FRONT PRESSURE BULKHEAD      |           |               |          |                           |           |              | Service ATA:51   |
|                                                       | MOS                                         | 30-May-96 |               |          |                           |           |              |                  |
|                                                       | HRS                                         | 0         |               |          |                           |           |              |                  |
| WC#: 51.010                                           | AFL                                         | 0         | T:5000 (+10%) |          | 5000                      | 5500      | 1071 (+500)  |                  |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS                |                                             |           |               |          |                           |           |              |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                                                             | Unit                                                                                                         | C/W       | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition    |
|-----------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------|-----------|--------------|----------|---------------------------|-----------|--------------|----------------|
| ATA 51 - STD PRACTICES AND STRUCT-GENRL                                                             |                                                                                                              |           |              |          |                           |           |              |                |
| 510003                                                                                              | INSPECT/NDT FLIGHT COMPARTMENT SKIN AND WINDOW STRUCTURE ABOVE WINDSHIELDS                                   |           |              |          |                           |           |              | Service ATA:51 |
|                                                                                                     | MOS                                                                                                          | 25-Jun-20 | 48 (+3m)     |          | 25-Jun-24                 | 25-Sep-24 | 511 d (+92)  |                |
|                                                                                                     | HRS                                                                                                          | 5801      |              |          |                           |           |              |                |
| WC#: 51.020                                                                                         | AFL                                                                                                          | 3399      |              |          |                           |           |              |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS, NTM 53-10-105A                                              |                                                                                                              |           |              |          | WO#: N950PC 48 MONTH INSP |           |              |                |
| 510004                                                                                              | DETAIL INSPECT UPPER CANOPY RAIL AT INTERSECTION WITH THE CANOPY POSTS                                       |           |              |          |                           |           |              | Service ATA:51 |
|                                                                                                     | MOS                                                                                                          | 30-May-96 |              |          |                           |           |              |                |
|                                                                                                     | HRS                                                                                                          | 0         |              |          |                           |           |              |                |
| WC#: 51.030                                                                                         | AFL                                                                                                          | 0         | 20000 (+500) |          | 20000                     | 20500     | 16071 (+500) |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS                                                              |                                                                                                              |           |              |          |                           |           |              |                |
| 510005                                                                                              | INSPECT/NDT CENTER FUSELAGE STRUCTURE BELOW THE FLOOR, NOSE LANDING GEAR BAY TO FRAME 13 AND FRAMES 16 TO 19 |           |              |          |                           |           |              | Service ATA:51 |
|                                                                                                     | MOS                                                                                                          | 25-Jun-20 | 96 (+3m)     |          | 25-Jun-28                 | 25-Sep-28 | 1972 d (+92) |                |
|                                                                                                     | HRS                                                                                                          | 5801      |              |          |                           |           |              |                |
| WC#: 51.040                                                                                         | AFL                                                                                                          | 3399      |              |          |                           |           |              |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS, NTM 53-10-107, NTM 53-10-108, NTM 53-10-108B, NTM 53-10-109 |                                                                                                              |           |              |          |                           |           |              |                |
| 510006                                                                                              | DETAIL INSPECT STRUCTURE BELOW ESCAPE HATCH, FRAMES 13 TO 14                                                 |           |              |          |                           |           |              | Service ATA:51 |
|                                                                                                     | MOS                                                                                                          | 25-Jun-20 | 96 (+3m)     |          | 25-Jun-28                 | 25-Sep-28 | 1972 d (+92) |                |
|                                                                                                     | HRS                                                                                                          | 5801      |              |          |                           |           |              |                |
| WC#: 51.050                                                                                         | AFL                                                                                                          | 3399      |              |          |                           |           |              |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS                                                              |                                                                                                              |           |              |          |                           |           |              |                |
| 510007                                                                                              | INSPECT/NDT CENTER FUSELAGE STRUCTURE BELOW THE FLOOR, FRAMES 8 TO 17                                        |           |              |          |                           |           |              | Service ATA:51 |
|                                                                                                     | MOS                                                                                                          | 25-Jun-20 | 96 (+3m)     |          | 25-Jun-28                 | 25-Sep-28 | 1972 d (+92) |                |
|                                                                                                     | HRS                                                                                                          | 5801      |              |          |                           |           |              |                |
| WC#: 51.060                                                                                         | AFL                                                                                                          | 3399      |              |          |                           |           |              |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS, NTM 53-10-106A                                              |                                                                                                              |           |              |          |                           |           |              |                |
| 510008                                                                                              | X-RAY CENTER FUSELAGE STRUCTURE BELOW THE FLOOR, FRAMES 13 TO 16                                             |           |              |          |                           |           |              | Service ATA:51 |
|                                                                                                     | MOS                                                                                                          | 25-Jun-20 | 96 (+3m)     |          | 25-Jun-28                 | 25-Sep-28 | 1972 d (+92) |                |
|                                                                                                     | HRS                                                                                                          | 5801      |              |          |                           |           |              |                |
| WC#: 51.070                                                                                         | AFL                                                                                                          | 3399      |              |          |                           |           |              |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS, NTM 53-10-108A                                              |                                                                                                              |           |              |          |                           |           |              |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                                                                            | Unit                                                                                                                                    | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                           | Disposition    |
|--------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-------------------------------------|----------------|
| ATA 51 - STD PRACTICES AND STRUCT-GENRL                                                                            |                                                                                                                                         |           |                |          |                           |           |                                     |                |
| 510009                                                                                                             | DETAIL INSPECT ENTRY DOOR SURROUND                                                                                                      |           |                |          |                           |           |                                     | Service ATA:51 |
|                                                                                                                    | MOS                                                                                                                                     | 25-Jun-20 | 48 (+3m)       |          | 25-Jun-24                 | 25-Sep-24 | 511 d (+92)                         |                |
|                                                                                                                    | HRS                                                                                                                                     | 5801      |                |          |                           |           |                                     |                |
| WC#: 51.080                                                                                                        | AFL                                                                                                                                     | 3399      |                |          |                           |           |                                     |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS                                                                             |                                                                                                                                         |           |                |          |                           |           | WO#: N950PC 48 MONTH INSP           |                |
| 510010                                                                                                             | INSPECT/NDT CENTER FUSELAGE STRUCTURE, ABOVE THE FLOOR                                                                                  |           |                |          |                           |           |                                     | Service ATA:51 |
|                                                                                                                    | MOS                                                                                                                                     | 25-Jun-20 | 96 (+3m)       |          | 25-Jun-28                 | 25-Sep-28 | 1972 d (+92)                        |                |
|                                                                                                                    | HRS                                                                                                                                     | 5801      |                |          |                           |           |                                     |                |
| WC#: 51.090                                                                                                        | AFL                                                                                                                                     | 3399      |                |          |                           |           |                                     |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS, NTM 53-10-104, NTM 53-10-101, NTM 53-10-102, NTM 53-10-103A, NTM 53-10-106 |                                                                                                                                         |           |                |          |                           |           |                                     |                |
| ATA 52 - DOORS                                                                                                     |                                                                                                                                         |           |                |          |                           |           |                                     |                |
| 520002                                                                                                             | OPERATIONAL TEST BAGGAGE PANNIER LOADING DOOR/UPPER HATCH WARNING SYSTEM (IF FITTED)OR EXTERNAL BAGGAGE UNIT (EBU) (750 AIRPLANES ONLY) |           |                |          |                           |           |                                     | Service ATA:52 |
|                                                                                                                    | MOS                                                                                                                                     | 06-May-15 |                |          |                           |           |                                     |                |
|                                                                                                                    | HRS                                                                                                                                     | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50)                         |                |
| WC#: 52.020                                                                                                        | AFL                                                                                                                                     | 2873      |                |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION C1                                                                                      |                                                                                                                                         |           |                |          |                           |           | PKG:3,20<br>WO#: N950PC B & C CHECK |                |
| 520003                                                                                                             | INSPECT BAGGAGE PANNIER DOOR (IF FITTED) OR EXTERNAL BAGGAGE UNIT (EBU) (750 AIRPLANES ONLY)                                            |           |                |          |                           |           |                                     | Service ATA:52 |
|                                                                                                                    | MOS                                                                                                                                     | 06-May-15 |                |          |                           |           |                                     |                |
|                                                                                                                    | HRS                                                                                                                                     | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50)                         |                |
| WC#: 52.040                                                                                                        | AFL                                                                                                                                     | 2873      |                |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION C3                                                                                      |                                                                                                                                         |           |                |          |                           |           | PKG:3,22<br>WO#: N950PC B & C CHECK |                |
| 520004                                                                                                             | CHECK MAIN ENTRY DOOR "NOT LOCKED" WARNING MICROSWITCHES                                                                                |           |                |          |                           |           |                                     | Service ATA:52 |
|                                                                                                                    | MOS                                                                                                                                     | 06-May-15 |                |          |                           |           |                                     |                |
|                                                                                                                    | HRS                                                                                                                                     | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50)                         |                |
| WC#: 52.025                                                                                                        | AFL                                                                                                                                     | 2873      |                |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION C6, AMM 12-24-00                                                                        |                                                                                                                                         |           |                |          |                           |           | PKG:3,25<br>WO#: N950PC B & C CHECK |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                     | Unit                                                   | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                           | Disposition    |
|---------------------------------------------|--------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-------------------------------------|----------------|
| ATA 52 - DOORS                              |                                                        |           |                |          |                           |           |                                     |                |
| 520005                                      | CHECK ESCAPE HATCH RELEASE MECHANISM                   |           |                |          |                           |           |                                     | Service ATA:52 |
|                                             | MOS                                                    | 15-Oct-19 |                |          |                           |           |                                     |                |
|                                             | HRS                                                    | 5795.3    | 800 (+40/-10)  |          | 6595.3                    | 6635.3    | 67 (+40)                            |                |
| WC#: 52.015                                 | AFL                                                    | 3397      |                |          |                           |           |                                     |                |
| PROC. REF: AMM 52-20-00                     |                                                        |           |                |          |                           |           | PKG:2,13<br>WO#: N950PC B & C CHECK |                |
| 520006                                      | INSPECT ESCAPE HATCH SEALS                             |           |                |          |                           |           |                                     | Service ATA:52 |
|                                             | MOS                                                    | 15-Oct-19 |                |          |                           |           |                                     |                |
|                                             | HRS                                                    | 5795.3    | 800 (+40/-10)  |          | 6595.3                    | 6635.3    | 67 (+40)                            |                |
| WC#: 52.035                                 | AFL                                                    | 3397      |                |          |                           |           |                                     |                |
|                                             |                                                        |           |                |          |                           |           | PKG:2,13<br>WO#: N950PC B & C CHECK |                |
| 520007                                      | INSPECT/CHECK ENTRY DOOR                               |           |                |          |                           |           |                                     | Service ATA:52 |
|                                             | MOS                                                    | 06-May-15 |                |          |                           |           |                                     |                |
|                                             | HRS                                                    | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50)                         |                |
| WC#: 52.010                                 | AFL                                                    | 2873      |                |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION C6, AMM 52-11-00 |                                                        |           |                |          |                           |           | PKG:3,25<br>WO#: N950PC B & C CHECK |                |
| 520008                                      | INSPECT/NDT MAIN ENTRY DOOR                            |           |                |          |                           |           |                                     | Service ATA:52 |
|                                             | MOS                                                    | 01-Mar-16 | 96 (+3m)       |          | 01-Mar-24                 | 01-Jun-24 | 395 d (+92)                         |                |
|                                             | HRS                                                    | 5272.6    |                |          |                           |           |                                     |                |
| WC#: 52.010                                 | AFL                                                    | 2978      |                |          |                           |           |                                     |                |
| PROC. REF: NTM 52-80-102                    |                                                        |           |                |          |                           |           | WO#: N950PC 48 MONTH INSP           |                |
| 520009                                      | DETAIL INSPECT ESCAPE HATCH                            |           |                |          |                           |           |                                     | Service ATA:52 |
|                                             | MOS                                                    | 25-Jun-20 | 96 (+3m)       |          | 25-Jun-28                 | 25-Sep-28 | 1972 d (+92)                        |                |
|                                             | HRS                                                    | 5801      |                |          |                           |           |                                     |                |
| WC#: 52.015                                 | AFL                                                    | 3399      |                |          |                           |           |                                     |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS      |                                                        |           |                |          |                           |           |                                     |                |
| 520010                                      | INSPECT MAIN ENTRY DOOR - FOLDING HANDRAIL (IF FITTED) |           |                |          |                           |           |                                     | Service ATA:52 |
|                                             | MOS                                                    | 06-May-15 |                |          |                           |           |                                     |                |
|                                             | HRS                                                    | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50)                         |                |
| WC#: 52.050                                 | AFL                                                    | 2873      |                |          |                           |           |                                     |                |
| PROC. REF: MMA 52-15-00, AFMS INSPECTION C6 |                                                        |           |                |          |                           |           | PKG:3,25<br>WO#: N950PC B & C CHECK |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                | Unit                                                                      | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                 | Disposition      |
|----------------------------------------|---------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|---------------------------|------------------|
| ATA 52 - DOORS                         |                                                                           |           |          |          |                           |           |                           |                  |
| 521001                                 | MAIN ENTRY DOOR ASSEMBLY                                                  |           |          |          |                           |           |                           | Component ATA:52 |
| PN:25.FC7905A/C                        | MOS/MSC                                                                   | 30-May-96 | O/C      |          |                           |           |                           |                  |
| SN:SD/DH/176                           | HRS                                                                       | 0         |          | TSN 0    |                           |           |                           |                  |
| WC#: 52.010                            | AFL                                                                       | 0         |          |          |                           |           |                           |                  |
| PROC. REF: AMM 52-11-00, AMM 52-11-00  |                                                                           |           |          |          |                           |           |                           |                  |
| 521010 <sup>U</sup>                    | MAIN CABIN DOOR SEAL                                                      |           |          |          |                           |           |                           | Component ATA:52 |
| PN:25-8FC3003                          | MOS/MSC                                                                   | 07-May-07 | O/C      |          |                           |           |                           |                  |
| SN:UNKNOWN                             | HRS                                                                       | 3447      |          |          |                           |           |                           |                  |
|                                        | AFL                                                                       | 1932      |          |          |                           |           |                           |                  |
| 521016                                 | LONG RANGE TANK DOOR                                                      |           |          |          |                           |           |                           | Component ATA:52 |
| PN:25.8PT111-87A                       | MOS/MSC                                                                   | 30-May-96 | O/C      |          |                           |           |                           |                  |
| SN:SD/DH/117                           | HRS                                                                       | 0         |          | TSN 0    |                           |           |                           |                  |
| WC#: 52.055                            | AFL                                                                       | 0         |          |          |                           |           |                           |                  |
| 522001                                 | ESCAPE HATCH                                                              |           |          |          |                           |           |                           | Component ATA:52 |
| PN:25.8FC461-161A                      | MOS/MSC                                                                   | 30-May-96 | O/C      |          |                           |           |                           |                  |
| SN:CFTW/DHB/066                        | HRS                                                                       | 0         |          | TSN 0    |                           |           |                           |                  |
| WC#: 52.015                            | AFL                                                                       | 0         |          |          |                           |           |                           |                  |
| PROC. REF: AMM 52-20-00                |                                                                           |           |          |          |                           |           |                           |                  |
| 522005                                 | (EBU) EXTERNAL BAGGAGE UNIT                                               |           |          |          |                           |           |                           | Component ATA:52 |
| PN:PN                                  | MOS/MSC                                                                   | 30-May-96 | O/C      | TSN 0    |                           |           |                           |                  |
| SN:UNKNOWN                             | HRS                                                                       | 0         |          | TSN 0    |                           |           |                           |                  |
| WC#: 52.030                            | AFL                                                                       | 0         |          | TSN 0    |                           |           |                           |                  |
| ATA 53 - FUSELAGE                      |                                                                           |           |          |          |                           |           |                           |                  |
| 530001                                 | DETAIL INSPECT SKIN EXTERIOR UNDER THE DORSAL INTAKE, FORWARD OF FRAME 19 |           |          |          |                           |           |                           | Service ATA:53   |
|                                        | MOS                                                                       | 25-Jun-20 | 48 (+3m) |          | 25-Jun-24                 | 25-Sep-24 | 511 d (+92)               |                  |
|                                        | HRS                                                                       | 5801      |          |          |                           |           |                           |                  |
| WC#: 53.115                            | AFL                                                                       | 3399      |          |          |                           |           |                           |                  |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS |                                                                           |           |          |          |                           |           | WO#: N950PC 48 MONTH INSP |                  |
| 530002                                 | INSPECT FUSELAGE SKIN UNDER WING-TO-FUSELAGE FAIRINGS                     |           |          |          |                           |           |                           | Service ATA:53   |
|                                        | MOS                                                                       | 25-Jun-20 | 48 (+3m) |          | 25-Jun-24                 | 25-Sep-24 | 511 d (+92)               |                  |
|                                        | HRS                                                                       | 5801      |          |          |                           |           |                           |                  |
| WC#: 53.040                            | AFL                                                                       | 3399      |          |          |                           |           |                           |                  |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS |                                                                           |           |          |          |                           |           | WO#: N950PC 48 MONTH INSP |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                | Unit                                                                                                       | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition    |
|----------------------------------------|------------------------------------------------------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|--------------|----------------|
| ATA 53 - FUSELAGE                      |                                                                                                            |           |                |          |                           |           |              |                |
| 530003                                 | DETAIL INSPECT FUSELAGE SKIN COVERED BY THE VENTRAL FUEL TANK (IF FITTED).                                 |           |                |          |                           |           |              | Service ATA:53 |
|                                        | MOS                                                                                                        | 25-Jun-20 | 96 (+3m)       |          | 25-Jun-28                 | 25-Sep-28 | 1972 d (+92) |                |
|                                        | HRS                                                                                                        | 5801      |                |          |                           |           |              |                |
| WC#: 53.110                            | AFL                                                                                                        | 3399      |                |          |                           |           |              |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS |                                                                                                            |           |                |          |                           |           |              |                |
| 530004                                 | DETAIL INSPECT VENTRAL FUEL TANK AND ATTACHMENTS, (IF FITTED)                                              |           |                |          |                           |           |              | Service ATA:53 |
|                                        | MOS                                                                                                        | 25-Jun-20 | 96 (+3m)       |          | 25-Jun-28                 | 25-Sep-28 | 1972 d (+92) |                |
|                                        | HRS                                                                                                        | 5801      |                |          |                           |           |              |                |
| WC#: 28.015                            | AFL                                                                                                        | 3399      |                |          |                           |           |              |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS |                                                                                                            |           |                |          |                           |           |              |                |
| 530005                                 | DETAIL INSPECT FUSELAGE SKIN COVERED BY THE VENTRAL BAGGAGE PANNIER OR EBU (750AIRPLANES) (IF FITTED).     |           |                |          |                           |           |              | Service ATA:53 |
|                                        | MOS/MSC                                                                                                    |           | N/R            |          |                           |           |              |                |
|                                        | HRS                                                                                                        | 0         |                |          |                           |           |              |                |
| WC#: 53.180                            | AFL                                                                                                        |           |                |          |                           |           |              |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS |                                                                                                            |           |                |          |                           |           |              |                |
| 530006                                 | DETAIL INSPECT VENTRAL BAGGAGE PANNIER (IF FITTED) INTERNAL STRUCTURE                                      |           |                |          |                           |           |              | Service ATA:53 |
|                                        | MOS/MSC                                                                                                    |           | N/R            |          |                           |           |              |                |
|                                        | HRS                                                                                                        | 0         |                |          |                           |           |              |                |
| WC#: 53.180                            | AFL                                                                                                        |           |                |          |                           |           |              |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS |                                                                                                            |           |                |          |                           |           |              |                |
| 530007                                 | DETAIL INSPECT WING TO FUSELAGE ATTACHMENT LINKS, BRACKETS AND BOLTS                                       |           |                |          |                           |           |              | Service ATA:53 |
|                                        | MOS                                                                                                        | 03-Feb-16 | 96 (+3m)       |          | 03-Feb-24                 | 03-May-24 | 368 d (+90)  |                |
|                                        | HRS                                                                                                        | 5272      |                |          |                           |           |              |                |
| WC#: 53.105                            | AFL                                                                                                        | 2978      |                |          |                           |           |              |                |
| PROC. REF: AMM 53-40-01                |                                                                                                            |           |                |          |                           |           |              |                |
| 530009                                 | INSPECT/NDT FUSELAGE LAP JOINTS                                                                            |           |                |          |                           |           |              | Service ATA:53 |
|                                        | MOS                                                                                                        | 30-May-96 |                |          |                           |           |              |                |
|                                        | HRS                                                                                                        | 0         |                |          |                           |           |              |                |
| WC#: 53.125                            | AFL                                                                                                        | 0         | T:27000 (+500) |          | 27000                     | 27500     | 23071 (+500) |                |
| PROC. REF: NTM 53-10-104               |                                                                                                            |           |                |          |                           |           |              |                |
| 530010                                 | DETAIL INSPECT SKIN OF THE FUSELAGE, WING ATTACHMENT BRACKETS, DRAG SPIGOT BEARING AND DRAG SPIGOT HOUSING |           |                |          |                           |           |              | Service ATA:53 |
|                                        | MOS/MSC                                                                                                    |           | A/R            |          |                           |           |              |                |
|                                        | HRS                                                                                                        | 0         |                |          |                           |           |              |                |
| WC#: 53.020                            | AFL                                                                                                        |           |                |          |                           |           |              |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                | Unit                                                                     | C/W       | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                 | Disposition    |
|--------------------------------------------------------|--------------------------------------------------------------------------|-----------|--------------|----------|---------------------------|-----------|---------------------------|----------------|
| ATA 53 - FUSELAGE                                      |                                                                          |           |              |          |                           |           |                           |                |
| 530011                                                 | INSPECT LEFT-HAND SIDE FRONT FACE OF REAR PRESSURE BULKHEAD (FRAME 19)   |           |              |          |                           |           |                           | Service ATA:53 |
|                                                        | MOS                                                                      | 25-Jun-20 | 48 (+3m)     |          | 25-Jun-24                 | 25-Sep-24 | 511 d (+92)               |                |
|                                                        | HRS                                                                      | 5801      |              |          |                           |           |                           |                |
| WC#: 53.175                                            | AFL                                                                      | 3399      |              |          |                           |           |                           |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS                 |                                                                          |           |              |          |                           |           | WO#: N950PC 48 MONTH INSP |                |
| 530012                                                 | INSPECT RIGHT- HAND SIDE FRONT FACE OF REAR PRESSURE BULKHEAD (FRAME 19) |           |              |          |                           |           |                           | Service ATA:53 |
|                                                        | MOS                                                                      | 25-Jun-20 | 96 (+3m)     |          | 25-Jun-28                 | 25-Sep-28 | 1972 d (+92)              |                |
|                                                        | HRS                                                                      | 5801      |              |          |                           |           |                           |                |
| WC#: 53.070                                            | AFL                                                                      | 3399      |              |          |                           |           |                           |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS                 |                                                                          |           |              |          |                           |           |                           |                |
| 530013                                                 | INSPECT/NDT PYLON ENGINE MAIN MOUNTING ATTACHMENT FITTINGS               |           |              |          |                           |           |                           | Service ATA:53 |
|                                                        | MOS                                                                      | 30-May-96 |              |          |                           |           |                           |                |
|                                                        | HRS                                                                      | 0         | 10000 (+500) |          | 10000                     | 10500     | 3471.7 (+500)             |                |
| WC#: 53.030                                            | AFL                                                                      | 0         |              |          |                           |           |                           |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS, NTM 53-10-110  |                                                                          |           |              |          |                           |           |                           |                |
| 530013                                                 | INSPECT/NDT RH PYLON ENGINE MAIN MOUNTING ATTACHMENT FITTINGS            |           |              |          |                           |           |                           | Service ATA:53 |
|                                                        | MOS                                                                      | 30-May-96 |              |          |                           |           |                           |                |
|                                                        | HRS                                                                      | 0         | 10000        |          | 10000                     |           | 3471.7                    |                |
|                                                        | AFL                                                                      | 0         |              |          |                           |           |                           |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS, NTM 53-10-110  |                                                                          |           |              |          |                           |           |                           |                |
| 530014                                                 | INSPECT/NDT REAR ENGINE MOUNT FITTINGS                                   |           |              |          |                           |           |                           | Service ATA:53 |
|                                                        | MOS                                                                      | 30-May-96 |              |          |                           |           |                           |                |
|                                                        | HRS                                                                      | 0         | 20000 (+500) |          | 20000                     | 20500     | 13471.7 (+500)            |                |
| WC#: 53.035                                            | AFL                                                                      | 0         |              |          |                           |           |                           |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS, NTM 53-10-110A |                                                                          |           |              |          |                           |           |                           |                |
| 530014                                                 | INSPECT/NDT RH REAR ENGINE MOUNT FITTINGS                                |           |              |          |                           |           |                           | Service ATA:53 |
|                                                        | MOS                                                                      | 30-May-96 |              |          |                           |           |                           |                |
|                                                        | HRS                                                                      | 0         | 10000        |          | 10000                     |           | 3471.7                    |                |
|                                                        | AFL                                                                      | 0         |              |          |                           |           |                           |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS, NTM 53-10-110A |                                                                          |           |              |          |                           |           |                           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                               | Unit                                                                | C/W       | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                                              | Disposition    |
|-------------------------------------------------------|---------------------------------------------------------------------|-----------|--------------|----------|---------------------------|-----------|--------------------------------------------------------|----------------|
| ATA 53 - FUSELAGE                                     |                                                                     |           |              |          |                           |           |                                                        |                |
| 530015                                                | INSPECT/NDT VERTICAL STABILIZER ROOT ATTACHMENT TO FUSELAGE         |           |              |          |                           |           |                                                        | Service ATA:53 |
|                                                       | MOS                                                                 | 30-May-96 |              |          |                           |           |                                                        |                |
|                                                       | HRS                                                                 | 0         | 30000 (+500) |          | 30000                     | 30500     | 23471.7 (+500)                                         |                |
| WC#: 53.015                                           | AFL                                                                 | 0         |              |          |                           |           |                                                        |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS, NTM 55-30-104 |                                                                     |           |              |          |                           |           |                                                        |                |
| 530016                                                | DETAIL INSPECT ENGINE BEAM                                          |           |              |          |                           |           |                                                        | Service ATA:53 |
|                                                       | MOS                                                                 | 30-May-96 |              |          |                           |           |                                                        |                |
|                                                       | HRS                                                                 | 0         | 10000 (+500) |          | 10000                     | 10500     | 3471.7 (+500)                                          |                |
| WC#: 53.080                                           | AFL                                                                 | 0         |              |          |                           |           |                                                        |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS                |                                                                     |           |              |          |                           |           |                                                        |                |
| 530017                                                | INSPECT NO. 1 ENGINE MOUNTING BRACKETS                              |           |              |          |                           |           |                                                        | Service ATA:53 |
|                                                       | MOS/MSC                                                             | 09-Mar-04 | E/C          |          |                           |           |                                                        | PART OF MPI    |
|                                                       | HRS                                                                 | 2632.6    |              |          |                           |           |                                                        |                |
| WC#: 53.200                                           | AFL                                                                 | 1434      |              |          |                           |           |                                                        |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS                |                                                                     |           |              |          |                           |           | WO#: N950PC JET HARBOR MPI CHANGE,N950PC LH<br>ENG MPI |                |
| 530017                                                | INSPECT NO. 2 ENGINE MOUNTING BRACKETS                              |           |              |          |                           |           |                                                        | Service ATA:53 |
|                                                       | MOS/MSC                                                             |           | E/C          |          |                           |           |                                                        | PART OF MPI    |
|                                                       | HRS                                                                 | 0         |              |          |                           |           |                                                        |                |
| WC#: 53.200                                           | AFL                                                                 |           |              |          |                           |           |                                                        |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS                |                                                                     |           |              |          |                           |           | WO#: N950PC JET HARBOR MPI CHANGE                      |                |
| 530018                                                | DETAIL INSPECT FUSELAGE SKIN ADJACENT TO CABIN WINDOW CUTOUTS       |           |              |          |                           |           |                                                        | Service ATA:53 |
|                                                       | MOS                                                                 | 03-Jan-12 |              |          |                           |           |                                                        |                |
|                                                       | HRS                                                                 | 4572.3    | 2400 (+10%)  |          | 6972.3                    | 7212.3    | 444 (+240)                                             |                |
| WC#: 53.205                                           | AFL                                                                 | 2562      |              |          |                           |           |                                                        |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS                |                                                                     |           |              |          |                           |           |                                                        |                |
| 530019                                                | DETAIL INSPECT APU SUPPORT STRUCTURE EXTERNAL TO THE FIRE ENCLOSURE |           |              |          |                           |           |                                                        | Service ATA:53 |
|                                                       | MOS/MSC                                                             |           | N/R          |          |                           |           |                                                        |                |
|                                                       | HRS                                                                 | 0         |              |          |                           |           |                                                        |                |
| WC#: 53.210                                           | AFL                                                                 |           |              |          |                           |           |                                                        |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS                |                                                                     |           |              |          |                           |           |                                                        |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                             | Unit                                                                                       | C/W | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|---------------------------------------------------------------------|--------------------------------------------------------------------------------------------|-----|----------|----------|---------------------------|-----------|-----------|----------------|
| ATA 53 - FUSELAGE                                                   |                                                                                            |     |          |          |                           |           |           |                |
| 530021                                                              | DETAIL INSPECT APU SUPPORT STRUCTURE                                                       |     |          |          |                           |           |           | Service ATA:53 |
|                                                                     | MOS/MSC                                                                                    |     | N/R      |          |                           |           |           |                |
|                                                                     | HRS                                                                                        | 0   |          |          |                           |           |           |                |
| WC#: 53.010                                                         | AFL                                                                                        |     |          |          |                           |           |           |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS                              |                                                                                            |     |          |          |                           |           |           |                |
| 530022                                                              | DETAIL INSPECT APU MOUNTING HARDWARE                                                       |     |          |          |                           |           |           | Service ATA:53 |
|                                                                     | MOS/MSC                                                                                    |     | N/R      |          |                           |           |           |                |
|                                                                     | HRS                                                                                        | 0   |          |          |                           |           |           |                |
| WC#: 53.215                                                         | AFL                                                                                        |     |          |          |                           |           |           |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS, AFMS STRUCTURAL INSPECTIONS |                                                                                            |     |          |          |                           |           |           |                |
| 530023                                                              | DETAIL INSPECT FUSELAGE STRUCTURE FOR CRACKS                                               |     |          |          |                           |           |           | Service ATA:53 |
|                                                                     | MOS/MSC                                                                                    |     | N/R      |          |                           |           |           |                |
|                                                                     | HRS                                                                                        | 0   |          |          |                           |           |           |                |
| WC#: 53.220                                                         | AFL                                                                                        |     |          |          |                           |           |           |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS                              |                                                                                            |     |          |          |                           |           |           |                |
| 530024                                                              | FLUORESCENT PENETRANT INSPECT APU SUPPORT HARDWARE                                         |     |          |          |                           |           |           | Service ATA:53 |
|                                                                     | MOS/MSC                                                                                    |     | N/R      |          |                           |           |           |                |
|                                                                     | HRS                                                                                        | 0   |          |          |                           |           |           |                |
| WC#: 53.225                                                         | AFL                                                                                        |     |          |          |                           |           |           |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS, AFMS STRUCTURAL INSPECTIONS |                                                                                            |     |          |          |                           |           |           |                |
| 530025                                                              | DETAIL INSPECT APU EXHAUST AND INLET DOUBLER FRAMES AND STRINGERS                          |     |          |          |                           |           |           | Service ATA:53 |
|                                                                     | MOS/MSC                                                                                    |     | N/R      |          |                           |           |           |                |
|                                                                     | HRS                                                                                        | 0   |          |          |                           |           |           |                |
| WC#: 53.170                                                         | AFL                                                                                        |     |          |          |                           |           |           |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS                              |                                                                                            |     |          |          |                           |           |           |                |
| 530026                                                              | DETAILED VISUAL INSPECTION EXTERNAL BAGGAGE UNIT (EBU) FORWARD AND AFT ATTACHMENT FITTINGS |     |          |          |                           |           |           | Service ATA:53 |
|                                                                     | MOS/MSC                                                                                    |     | N/R      |          |                           |           |           |                |
|                                                                     | HRS                                                                                        | 0   |          |          |                           |           |           |                |
| WC#: 53.230                                                         | AFL                                                                                        |     |          |          |                           |           |           |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS                              |                                                                                            |     |          |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                              | Unit                                                  | C/W       | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                          | Disposition      |
|------------------------------------------------------|-------------------------------------------------------|-----------|--------------|----------|---------------------------|-----------|------------------------------------|------------------|
| ATA 53 - FUSELAGE                                    |                                                       |           |              |          |                           |           |                                    |                  |
| 530027                                               | VISUAL INSPECTION FUSELAGE SKIN                       |           |              |          |                           |           |                                    | Service ATA:53   |
|                                                      | MOS                                                   | 15-Oct-19 | 48 (+2m/-2m) |          | 15-Oct-23                 | 15-Dec-23 | 257 d (+61)                        |                  |
|                                                      | HRS                                                   | 5795.3    |              |          |                           |           |                                    |                  |
| WC#: 53.235                                          | AFL                                                   | 3397      |              |          |                           |           |                                    |                  |
| PROC. REF: AFMS INSPECTION G                         |                                                       |           |              |          |                           |           | PKG:7<br>WO#: N950PC 48 MONTH INSP |                  |
| 531146                                               | RADOME                                                |           |              |          |                           |           |                                    | Component ATA:53 |
| PN:25.8RF13-1A                                       | MOS/MSC                                               | 30-May-96 | O/C          |          |                           |           |                                    |                  |
| SN:DHB346                                            | HRS                                                   | 0         |              | TSN 0    |                           |           |                                    |                  |
| WC#: 53.135                                          | AFL                                                   | 0         |              |          |                           |           |                                    |                  |
| PROC. REF: AMM 53-50-14                              |                                                       |           |              |          |                           |           |                                    |                  |
| 531152                                               | TAIL CONE FAIRING                                     |           |              |          |                           |           |                                    | Component ATA:53 |
| PN:25.8GF/Z27-1A                                     | MOS/MSC                                               | 30-May-96 | O/C          |          |                           |           |                                    |                  |
| SN:FL179                                             | HRS                                                   | 0         |              | TSN 0    |                           |           |                                    |                  |
| WC#: 53.140                                          | AFL                                                   | 0         |              |          |                           |           |                                    |                  |
| PROC. REF: AMM 53-50-16                              |                                                       |           |              |          |                           |           |                                    |                  |
| 531154                                               | FUSELAGE                                              |           |              |          |                           |           |                                    | Component ATA:53 |
| PN:25.8FA1                                           | MOS/MSC                                               | 30-May-96 | O/C          |          |                           |           |                                    |                  |
| SN:258301                                            | HRS                                                   | 0         |              | TSN 0    |                           |           |                                    |                  |
| WC#: 53.145                                          | AFL                                                   | 0         |              |          |                           |           |                                    |                  |
| ATA 55 - STABILIZERS                                 |                                                       |           |              |          |                           |           |                                    |                  |
| 550001                                               | DETAIL INSPECT ELEVATORS AND TABS                     |           |              |          |                           |           |                                    | Service ATA:55   |
|                                                      | MOS                                                   | 25-Jun-20 | 48 (+3m)     |          | 25-Jun-24                 | 25-Sep-24 | 511 d (+92)                        |                  |
|                                                      | HRS                                                   | 5801      |              |          |                           |           |                                    |                  |
| WC#: 27.070                                          | AFL                                                   | 3399      |              |          |                           |           |                                    |                  |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS               |                                                       |           |              |          |                           |           | WO#: N950PC 48 MONTH INSP          |                  |
| 550002                                               | LUBRICATE/REPLACE ELEVATOR TRIM TABS, CONNECTING RODS |           |              |          |                           |           |                                    | Service ATA:55   |
|                                                      | MOS                                                   | 25-Jun-20 | 48 (+3m)     |          | 25-Jun-24                 | 25-Sep-24 | 511 d (+92)                        |                  |
|                                                      | HRS                                                   | 5801      |              |          |                           |           |                                    |                  |
| WC#: 55.075                                          | AFL                                                   | 3399      |              |          |                           |           |                                    |                  |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS, AMM 27-30-00 |                                                       |           |              |          |                           |           | WO#: N950PC 48 MONTH INSP          |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                              | Unit                                                                         | C/W       | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                             | Disposition    |
|----------------------------------------------------------------------|------------------------------------------------------------------------------|-----------|--------------|----------|---------------------------|-----------|---------------------------------------|----------------|
| ATA 55 - STABILIZERS                                                 |                                                                              |           |              |          |                           |           |                                       |                |
| 550003                                                               | XRAY ELEVATORS                                                               |           |              |          |                           |           |                                       | Service ATA:55 |
|                                                                      | MOS                                                                          | 25-Jun-20 | 48 (+3m)     |          | 25-Jun-24                 | 25-Sep-24 | 511 d (+92)                           |                |
|                                                                      | HRS                                                                          | 5801      |              |          |                           |           |                                       |                |
| WC#: 55.055                                                          | AFL                                                                          | 3399      |              |          |                           |           |                                       |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS, NTM 55-20-101, NTM 55-20-102 |                                                                              |           |              |          |                           |           | WO#: N950PC 48 MONTH INSP             |                |
| 550004                                                               | DETAIL INSPECT RUDDER AND TAB                                                |           |              |          |                           |           |                                       | Service ATA:55 |
|                                                                      | MOS                                                                          | 25-Jun-20 | 48 (+3m)     |          | 25-Jun-24                 | 25-Sep-24 | 511 d (+92)                           |                |
|                                                                      | HRS                                                                          | 5801      |              |          |                           |           |                                       |                |
| WC#: 27.045                                                          | AFL                                                                          | 3399      |              |          |                           |           |                                       |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS, AMM 27-20-23                 |                                                                              |           |              |          |                           |           | WO#: N950PC 48 MONTH INSP             |                |
| 550005                                                               | INSPECT RUDDER CONNECTING RODS, RUDDER TRIM TAB AND ANTI-SERVO TAB           |           |              |          |                           |           |                                       | Service ATA:55 |
|                                                                      | MOS                                                                          | 25-Jun-20 | 48 (+3m)     |          | 25-Jun-24                 | 25-Sep-24 | 511 d (+92)                           |                |
|                                                                      | HRS                                                                          | 5801      |              |          |                           |           |                                       |                |
| WC#: 55.065                                                          | AFL                                                                          | 3399      |              |          |                           |           |                                       |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS                               |                                                                              |           |              |          |                           |           | WO#: N950PC 48 MONTH INSP             |                |
| 550006                                                               | X-RAY RUDDER (IN-SITU)                                                       |           |              |          |                           |           |                                       | Service ATA:55 |
|                                                                      | MOS                                                                          | 25-Jun-20 | 48 (+3m)     |          | 25-Jun-24                 | 25-Sep-24 | 511 d (+92)                           |                |
|                                                                      | HRS                                                                          | 5801      |              |          |                           |           |                                       |                |
| WC#: 27.045                                                          | AFL                                                                          | 3399      |              |          |                           |           |                                       |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS, NTM 55-40-101                |                                                                              |           |              |          |                           |           | WO#: N950PC 48 MONTH INSP             |                |
| 550007                                                               | DETAIL INSPECT RUDDER HINGE BRACKETS AND ATTACHMENTS                         |           |              |          |                           |           |                                       | Service ATA:55 |
|                                                                      | MOS                                                                          | 25-Jun-20 | 96 (+3m)     |          | 25-Jun-28                 | 25-Sep-28 | 1972 d (+92)                          |                |
|                                                                      | HRS                                                                          | 5801      |              |          |                           |           |                                       |                |
| WC#: 27.045                                                          | AFL                                                                          | 3399      |              |          |                           |           |                                       |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS                               |                                                                              |           |              |          |                           |           | WO#: N950PC 48 MONTH INSP             |                |
| 550008                                                               | INSPECT HORIZONTAL STABILIZER TO VERTICAL STABILIZER REAR ATTACHMENT FITTING |           |              |          |                           |           |                                       | Service ATA:55 |
|                                                                      | MOS                                                                          | 11-Oct-22 | 24 (+2m/-2m) |          | 11-Oct-24                 | 11-Dec-24 | 619 d (+61)                           |                |
|                                                                      | HRS                                                                          | 6446.4    |              |          |                           |           |                                       |                |
| WC#: 55.010                                                          | AFL                                                                          | 3873      |              |          |                           |           |                                       |                |
| PROC. REF: AFMS INSPECTION F8                                        |                                                                              |           |              |          |                           |           | PKG:6,63<br>WO#: N950PC 48 MONTH INSP |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                                                            | Unit                                                                                                           | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition    |
|----------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|--------------|----------------|
| ATA 55 - STABILIZERS                                                                               |                                                                                                                |           |                |          |                           |           |              |                |
| 550009                                                                                             | DETAIL INSPECT HORIZONTAL STABILIZER                                                                           |           |                |          |                           |           |              | Service ATA:55 |
|                                                                                                    | MOS                                                                                                            | 25-Jun-20 | 96 (+3m)       |          | 25-Jun-28                 | 25-Sep-28 | 1972 d (+92) |                |
|                                                                                                    | HRS                                                                                                            | 5801      |                |          |                           |           |              |                |
| WC#: 55.040                                                                                        | AFL                                                                                                            | 3399      |                |          |                           |           |              |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS, AMM 55-13-00                                               |                                                                                                                |           |                |          |                           |           |              |                |
| 550010                                                                                             | INSPECT/NDT VERTICAL STABILIZER                                                                                |           |                |          |                           |           |              | Service ATA:55 |
|                                                                                                    | MOS                                                                                                            | 25-Jun-20 | 96 (+3m)       |          | 25-Jun-28                 | 25-Sep-28 | 1972 d (+92) |                |
|                                                                                                    | HRS                                                                                                            | 5801      |                |          |                           |           |              |                |
| WC#: 55.050                                                                                        | AFL                                                                                                            | 3399      |                |          |                           |           |              |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS, NTM 55-30-101, NTM 55-30-102, NTM 55-30-103                |                                                                                                                |           |                |          |                           |           |              |                |
| 550011                                                                                             | INSPECT HORIZONTAL STABILIZER TO VERTICAL STABILIZER ATTACHMENTS                                               |           |                |          |                           |           |              | Service ATA:55 |
|                                                                                                    | MOS                                                                                                            | 25-Jun-20 | 96 (+3m)       |          | 25-Jun-28                 | 25-Sep-28 | 1972 d (+92) |                |
|                                                                                                    | HRS                                                                                                            | 5801      |                |          |                           |           |              |                |
| WC#: 55.025                                                                                        | AFL                                                                                                            | 3399      |                |          |                           |           |              |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS                                                             |                                                                                                                |           |                |          |                           |           |              |                |
| 550012                                                                                             | INSPECT/NDT HORIZONTAL STABILIZER                                                                              |           |                |          |                           |           |              | Service ATA:55 |
|                                                                                                    | MOS                                                                                                            | 25-Jun-20 | 96 (+3m)       |          | 25-Jun-28                 | 25-Sep-28 | 1972 d (+92) |                |
|                                                                                                    | HRS                                                                                                            | 5801      |                |          |                           |           |              |                |
| WC#: 55.045                                                                                        | AFL                                                                                                            | 3399      |                |          |                           |           |              |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS, NTM 55-10-104A, NTM 55-10-104B, NTM 55-10-104C             |                                                                                                                |           |                |          |                           |           |              |                |
| 550013                                                                                             | X-RAY HORIZONTAL STABILIZER                                                                                    |           |                |          |                           |           |              | Service ATA:55 |
|                                                                                                    | MOS                                                                                                            | 25-Jun-20 | 96 (+3m)       |          | 25-Jun-28                 | 25-Sep-28 | 1972 d (+92) |                |
|                                                                                                    | HRS                                                                                                            | 5801      |                |          |                           |           |              |                |
| WC#: 55.035                                                                                        | AFL                                                                                                            | 3399      |                |          |                           |           |              |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS, NTM 55-10-101, NTM 55-10-102, NTM 55-10-103, NTM 55-10-105 |                                                                                                                |           |                |          |                           |           |              |                |
| 550014                                                                                             | DETAIL INSPECT HORIZONTAL STABILIZER TOP SKIN 'T' FITTING AND JOINT STRAP AT THE CENTER LINE OF THE STABILIZER |           |                |          |                           |           |              | Service ATA:55 |
|                                                                                                    | MOS                                                                                                            | 30-May-96 |                |          |                           |           |              |                |
|                                                                                                    | HRS                                                                                                            | 0         |                |          |                           |           |              |                |
| WC#: 55.060                                                                                        | AFL                                                                                                            | 0         | T:15000 (+500) |          | 15000                     | 15500     | 11071 (+500) |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS                                                             |                                                                                                                |           |                |          |                           |           |              |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                     | Unit                                                      | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                           | Disposition      |
|---------------------------------------------|-----------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-------------------------------------|------------------|
| ATA 55 - STABILIZERS                        |                                                           |           |                |          |                           |           |                                     |                  |
| 550015                                      | INSPECT ELEVATOR MASS BALANCE WEIGHTS AND SPIGOTS         |           |                |          |                           |           |                                     | Service ATA:55   |
|                                             | MOS                                                       | 16-Aug-22 | 24 (+2m)       |          | 16-Aug-24                 | 16-Oct-24 | 563 d (+61)                         |                  |
|                                             | HRS                                                       | 6412.1    |                |          |                           |           |                                     |                  |
| WC#: 55.070                                 | AFL                                                       | 3846      |                |          |                           |           |                                     |                  |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS      |                                                           |           |                |          |                           |           | WO#: N950PC 48 MONTH INSP           |                  |
| 551004                                      | UPPER VERTICAL STABILIZER                                 |           |                |          |                           |           |                                     | Component ATA:55 |
| PN:25-8TF513-1A                             | MOS/MSC                                                   | 30-May-96 | O/C            | TSN 0    |                           |           |                                     |                  |
| SN:FL/DHB/8306                              | HRS                                                       | 0         |                | TSN 0    |                           |           |                                     |                  |
| WC#: 55.015                                 | AFL                                                       | 0         |                | TSN 0    |                           |           |                                     |                  |
| PROC. REF: AMM 55-32-00                     |                                                           |           |                |          |                           |           |                                     |                  |
| 551006                                      | TAILPLANE                                                 |           |                |          |                           |           |                                     | Component ATA:55 |
| PN:25-8TP257-1A                             | MOS/MSC                                                   | 30-May-96 | O/C            | TSN 0    |                           |           |                                     |                  |
| SN:UNKNOWN                                  | HRS                                                       | 0         |                | TSN 0    |                           |           |                                     |                  |
| WC#: 55.020                                 | AFL                                                       | 0         |                | TSN 0    |                           |           |                                     |                  |
| 551010                                      | BULLET FAIRING                                            |           |                |          |                           |           |                                     | Component ATA:55 |
| PN:25.8GF173-1A                             | MOS/MSC                                                   | 30-May-96 | O/C            |          |                           |           |                                     |                  |
| SN:CFTW/DHB/095                             | HRS                                                       | 0         |                | TSN 0    |                           |           |                                     |                  |
| WC#: 55.030                                 | AFL                                                       | 0         |                |          |                           |           |                                     |                  |
| 553005                                      | FIN LEADING EDGE                                          |           |                |          |                           |           |                                     | Component ATA:55 |
| PN:PN                                       | MOS/MSC                                                   | 30-May-96 | O/C            | TSN 0    |                           |           |                                     |                  |
| SN:UNKNOWN                                  | HRS                                                       | 0         |                | TSN 0    |                           |           |                                     |                  |
| WC#: 55.305                                 | AFL                                                       | 0         |                | TSN 0    |                           |           |                                     |                  |
| ATA 56 - WINDOWS                            |                                                           |           |                |          |                           |           |                                     |                  |
| 560004                                      | INSPECT WINDOWS DRY-AIR SYSTEM FILTER ELEMENT (IF FITTED) |           |                |          |                           |           |                                     | Service ATA:56   |
|                                             | MOS                                                       | 06-May-15 |                |          |                           |           |                                     |                  |
|                                             | HRS                                                       | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50)                         |                  |
| WC#: 56.065                                 | AFL                                                       | 2873      |                |          |                           |           |                                     |                  |
| PROC. REF: AFMS INSPECTION C6, AMM 56-00-00 |                                                           |           |                |          |                           |           | PKG:3,25<br>WO#: N950PC B & C CHECK |                  |
| 560005                                      | CHECK PASSENGER CABIN WINDOWS                             |           |                |          |                           |           |                                     | Service ATA:56   |
|                                             | MOS                                                       | 15-Oct-19 |                |          |                           |           |                                     |                  |
|                                             | HRS                                                       | 5795.3    | 800 (+40/-10)  |          | 6595.3                    | 6635.3    | 67 (+40)                            |                  |
| WC#: 56.090                                 | AFL                                                       | 3397      |                |          |                           |           |                                     |                  |
| PROC. REF: AFMS INSPECTION B3, AMM 56-00-00 |                                                           |           |                |          |                           |           | PKG:2,10<br>WO#: N950PC B & C CHECK |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                       | Unit                                                                                                   | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                             | Disposition      |
|-------------------------------|--------------------------------------------------------------------------------------------------------|-----------|---------------|----------|---------------------------|-----------|---------------------------------------|------------------|
| ATA 56 - WINDOWS              |                                                                                                        |           |               |          |                           |           |                                       |                  |
| 560006                        | INSPECT WINDSHIELD PANEL 'C' SILICA GEL CONTAINER                                                      |           |               |          |                           |           |                                       | Service ATA:56   |
|                               | MOS                                                                                                    | 15-Oct-19 |               |          |                           |           |                                       |                  |
|                               | HRS                                                                                                    | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)                              |                  |
| WC#: 56.070                   | AFL                                                                                                    | 3397      |               |          |                           |           |                                       |                  |
| PROC. REF: AFMS INSPECTION B4 |                                                                                                        |           |               |          |                           |           | PKG:2,11<br>WO#: N950PC B & C CHECK   |                  |
| 560007                        | SCREEN HEAT CIRCUIT BREAKERS - DO A VISUAL INSPECTION FOR HEAT DISTRESS, DISCOLORATION AND DEFORMATION |           |               |          |                           |           |                                       | Service ATA:56   |
|                               | MOS                                                                                                    | 11-Oct-22 | 24 (+2m/-2m)  |          | 11-Oct-24                 | 11-Dec-24 | 619 d (+61)                           |                  |
|                               | HRS                                                                                                    | 6446.4    |               |          |                           |           |                                       |                  |
|                               | AFL                                                                                                    | 3873      |               |          |                           |           |                                       |                  |
| PROC. REF: AFMS INSPECTION F6 |                                                                                                        |           |               |          |                           |           | PKG:6,61<br>WO#: N950PC 48 MONTH INSP |                  |
| 561001                        | LEFT (PANEL A) HEATED WINDSCREEN                                                                       |           |               |          |                           |           |                                       | Component ATA:56 |
| PN:196600-01                  | MOS/MSC                                                                                                | 07-Apr-22 | O/C           | TSN 1    |                           |           |                                       |                  |
| SN:0829                       | HRS                                                                                                    | 6316.6    |               | TSN 0    |                           |           |                                       |                  |
| WC#: 56.010                   | AFL                                                                                                    | 3776      |               | TSN 0    |                           |           |                                       |                  |
| PROC. REF: AMM 56-10-11       |                                                                                                        |           |               |          |                           |           |                                       |                  |
| 561002                        | RIGHT (PANEL A) HEATED WINDSCREEN                                                                      |           |               |          |                           |           |                                       | Component ATA:56 |
| PN:196600-02                  | MOS/MSC                                                                                                | 23-Oct-21 | O/C           | TSN 1    |                           |           |                                       |                  |
| SN:0798                       | HRS                                                                                                    | 6169      |               | TSN 0    |                           |           |                                       |                  |
| WC#: 56.010                   | AFL                                                                                                    | 3664      |               | TSN 0    |                           |           |                                       |                  |
| PROC. REF: AMM 56-10-11       |                                                                                                        |           |               |          |                           |           |                                       |                  |
| 561003                        | LEFT DIRECT VIEW B WINDOW                                                                              |           |               |          |                           |           |                                       | Component ATA:56 |
| PN:NH24016-91                 | MOS/MSC                                                                                                | 05-Jul-12 | O/C           |          |                           |           |                                       |                  |
| SN:L382638                    | HRS                                                                                                    | 4734      |               |          |                           |           |                                       |                  |
| WC#: 56.015                   | AFL                                                                                                    | 2648      |               |          |                           |           |                                       |                  |
| PROC. REF: AMM 56-10-22       |                                                                                                        |           |               |          |                           |           |                                       |                  |
| 561004                        | RIGHT DIRECT VIEW B WINDOW                                                                             |           |               |          |                           |           |                                       | Component ATA:56 |
| PN:NH24016-92                 | MOS/MSC                                                                                                | 20-Jul-05 | O/C           | TSN 0    |                           |           |                                       |                  |
| SN:L350818                    | HRS                                                                                                    | 2898.5    |               | TSN 0    |                           |           |                                       |                  |
| WC#: 56.015                   | AFL                                                                                                    | 1611      |               | TSN 0    |                           |           |                                       |                  |
| PROC. REF: AMM 56-10-22       |                                                                                                        |           |               |          |                           |           |                                       |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                 | Unit                     | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------|--------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 56 - WINDOWS        |                          |           |          |          |                           |           |           |                  |
| 561005                  | LEFT C WINDOW            |           |          |          |                           |           |           | Component ATA:56 |
| PN:25-8FN353-43A        | MOS/MSC                  | 09-Mar-04 | O/C      |          |                           |           |           |                  |
| SN:L285656              | HRS                      | 2632.6    |          |          | TSN 2632.6, TSR 0         |           |           |                  |
| WC#: 56.020             | AFL                      | 1434      |          |          | TSN 1434, TSR 0           |           |           |                  |
| PROC. REF: AMM 56-10-31 |                          |           |          |          |                           |           |           |                  |
| 561006                  | RIGHT C WINDOW           |           |          |          |                           |           |           | Component ATA:56 |
| PN:25-8FN353-44A        | MOS/MSC                  | 09-Mar-04 | O/C      |          |                           |           |           |                  |
| SN:L286294              | HRS                      | 2632.6    |          |          | TSN 2616.6, TSR 0         |           |           |                  |
| WC#: 56.020             | AFL                      | 1434      |          |          | TSN 1425, TSR 0           |           |           |                  |
| PROC. REF: AMM 56-10-31 |                          |           |          |          |                           |           |           |                  |
| 562001                  | NO. 1 LEFT CABIN WINDOW  |           |          |          |                           |           |           | Component ATA:56 |
| PN:25.FC7881-41A        | MOS/MSC                  | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:DHB6284              | HRS                      | 0         |          |          | TSN 0                     |           |           |                  |
| WC#: 56.025             | AFL                      | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 56-20-11 |                          |           |          |          |                           |           |           |                  |
| 562002                  | NO. 1 RIGHT CABIN WINDOW |           |          |          |                           |           |           | Component ATA:56 |
| PN:25.FC7881-41A        | MOS/MSC                  | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:DHB5961              | HRS                      | 0         |          |          | TSN 0                     |           |           |                  |
| WC#: 56.025             | AFL                      | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 56-20-11 |                          |           |          |          |                           |           |           |                  |
| 562003                  | NO. 2 LEFT CABIN WINDOW  |           |          |          |                           |           |           | Component ATA:56 |
| PN:25FC7881-41A         | MOS/MSC                  | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:DHB6274              | HRS                      | 0         |          |          | TSN 0                     |           |           |                  |
| WC#: 56.030             | AFL                      | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 56-20-11 |                          |           |          |          |                           |           |           |                  |
| 562004                  | NO. 2 RIGHT CABIN WINDOW |           |          |          |                           |           |           | Component ATA:56 |
| PN:25.FC7881-41A        | MOS/MSC                  | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:DHB6278              | HRS                      | 0         |          |          | TSN 0                     |           |           |                  |
| WC#: 56.030             | AFL                      | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 56-20-11 |                          |           |          |          |                           |           |           |                  |
| 562005                  | NO. 3 LEFT CABIN WINDOW  |           |          |          |                           |           |           | Component ATA:56 |
| PN:25.FC7881-41A        | MOS/MSC                  | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:DHB6275              | HRS                      | 0         |          |          | TSN 0                     |           |           |                  |
| WC#: 56.035             | AFL                      | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 56-20-11 |                          |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                 | Unit                     | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------|--------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 56 - WINDOWS        |                          |           |          |          |                           |           |           |                  |
| 562006                  | NO. 3 RIGHT CABIN WINDOW |           |          |          |                           |           |           | Component ATA:56 |
| PN:25.FC7881-41A        | MOS/MSC                  | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:DHB6262              | HRS                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.035             | AFL                      | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 56-20-11 |                          |           |          |          |                           |           |           |                  |
| 562007                  | NO. 4 LEFT CABIN WINDOW  |           |          |          |                           |           |           | Component ATA:56 |
| PN:25.FC7881-41A        | MOS/MSC                  | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:DHB6268              | HRS                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.040             | AFL                      | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 56-20-11 |                          |           |          |          |                           |           |           |                  |
| 562008                  | NO. 4 RIGHT CABIN WINDOW |           |          |          |                           |           |           | Component ATA:56 |
| PN:25.FC7881-41A        | MOS/MSC                  | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:DHB693               | HRS                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.040             | AFL                      | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 56-20-11 |                          |           |          |          |                           |           |           |                  |
| 562009                  | NO. 5 LEFT CABIN WINDOW  |           |          |          |                           |           |           | Component ATA:56 |
| PN:25.FC7881-41A        | MOS/MSC                  | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:DHB6273              | HRS                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.045             | AFL                      | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 56-20-11 |                          |           |          |          |                           |           |           |                  |
| 562010                  | NO. 5 RIGHT CABIN WINDOW |           |          |          |                           |           |           | Component ATA:56 |
| PN:25.FC7881-41A        | MOS/MSC                  | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:DHB6281              | HRS                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.045             | AFL                      | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 56-20-11 |                          |           |          |          |                           |           |           |                  |
| 562011                  | NO. 6 LEFT CABIN WINDOW  |           |          |          |                           |           |           | Component ATA:56 |
| PN:25.FC7881-41A        | MOS/MSC                  | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:DHB5965              | HRS                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.050             | AFL                      | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 56-20-11 |                          |           |          |          |                           |           |           |                  |
| 562012                  | NO. 6 RIGHT CABIN WINDOW |           |          |          |                           |           |           | Component ATA:56 |
| PN:25.FC7881-41A        | MOS/MSC                  | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:DHB6378              | HRS                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 56.050             | AFL                      | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 56-20-11 |                          |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                        | Unit                                                                                | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                             | Disposition    |
|--------------------------------|-------------------------------------------------------------------------------------|-----------|---------------|----------|---------------------------|-----------|---------------------------------------|----------------|
| ATA 57 - WINGS                 |                                                                                     |           |               |          |                           |           |                                       |                |
| 570001                         | INSPECT LEFT FLAP HINGE FITTINGS                                                    |           |               |          |                           |           |                                       | Service ATA:57 |
|                                | MOS                                                                                 | 15-Oct-19 |               |          |                           |           |                                       |                |
|                                | HRS                                                                                 | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)                              |                |
| WC#: 57.095                    | AFL                                                                                 | 3397      |               |          |                           |           |                                       |                |
| PROC. REF: AFMS INSPECTION B9  |                                                                                     |           |               |          |                           |           | PKG:2,16<br>WO#: N950PC B & C CHECK   |                |
| 570002                         | INSPECT RIGHT FLAP HINGE FITTINGS                                                   |           |               |          |                           |           |                                       | Service ATA:57 |
|                                | MOS                                                                                 | 15-Oct-19 |               |          |                           |           |                                       |                |
|                                | HRS                                                                                 | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)                              |                |
| WC#: 57.095                    | AFL                                                                                 | 3397      |               |          |                           |           |                                       |                |
| PROC. REF: AFMS INSPECTION B10 |                                                                                     |           |               |          |                           |           | PKG:2,17<br>WO#: N950PC B & C CHECK   |                |
| 570003                         | DETAIL INSPECT LEFT WING INTERNAL STRUCTURE OF THE WING IN THE AREA OF RIBS 0 TO 4  |           |               |          |                           |           |                                       | Service ATA:57 |
|                                | MOS                                                                                 | 11-Oct-22 | 24 (+2m/-2m)  |          | 11-Oct-24                 | 11-Dec-24 | 619 d (+61)                           |                |
|                                | HRS                                                                                 | 6446.4    |               |          |                           |           |                                       |                |
| WC#: 57.090                    | AFL                                                                                 | 3873      |               |          |                           |           |                                       |                |
| PROC. REF: AFMS INSPECTION F9  |                                                                                     |           |               |          |                           |           | PKG:6,64<br>WO#: N950PC 48 MONTH INSP |                |
| 570004                         | INSPECT LEFT FLAP SKIN PROTECTION PANELS (IF FITTED)                                |           |               |          |                           |           |                                       | Service ATA:57 |
|                                | MOS                                                                                 | 11-Oct-22 | 24 (+2m/-2m)  |          | 11-Oct-24                 | 11-Dec-24 | 619 d (+61)                           |                |
|                                | HRS                                                                                 | 6446.4    |               |          |                           |           |                                       |                |
| WC#: 57.140                    | AFL                                                                                 | 3873      |               |          |                           |           |                                       |                |
| PROC. REF: AFMS INSPECTION F9  |                                                                                     |           |               |          |                           |           | PKG:6,64<br>WO#: N950PC 48 MONTH INSP |                |
| 570005                         | DETAIL INSPECT RIGHT WING INTERNAL STRUCTURE OF THE WING IN THE AREA OF RIBS 0 TO 4 |           |               |          |                           |           |                                       | Service ATA:57 |
|                                | MOS                                                                                 | 11-Oct-22 | 24 (+2m/-2m)  |          | 11-Oct-24                 | 11-Dec-24 | 619 d (+61)                           |                |
|                                | HRS                                                                                 | 6446.4    |               |          |                           |           |                                       |                |
| WC#: 57.090                    | AFL                                                                                 | 3873      |               |          |                           |           |                                       |                |
| PROC. REF: AFMS INSPECTION F10 |                                                                                     |           |               |          |                           |           | PKG:6,65<br>WO#: N950PC 48 MONTH INSP |                |
| 570006                         | INSPECT RIGHT FLAP SKIN PROTECTION PANELS (IF FITTED)                               |           |               |          |                           |           |                                       | Service ATA:57 |
|                                | MOS                                                                                 | 11-Oct-22 | 24 (+2m/-2m)  |          | 11-Oct-24                 | 11-Dec-24 | 619 d (+61)                           |                |
|                                | HRS                                                                                 | 6446.4    |               |          |                           |           |                                       |                |
| WC#: 57.140                    | AFL                                                                                 | 3873      |               |          |                           |           |                                       |                |
| PROC. REF: AFMS INSPECTION F10 |                                                                                     |           |               |          |                           |           | PKG:6,65<br>WO#: N950PC 48 MONTH INSP |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                            | Unit                                                                                                                                                 | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                 | Disposition    |
|--------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|-------------|----------|---------------------------|-----------|---------------------------|----------------|
| ATA 57 - WINGS                                                     |                                                                                                                                                      |           |             |          |                           |           |                           |                |
| 570007                                                             | X-RAY WING BOTTOM SKINS AND STRINGERS BETWEEN THE FRONT AND REAR SPARS, RIB 0 TO RIB 1 AND BETWEEN THE CENTER SPAR AND REAR SPAR FROM RIB 1 TO RIB 4 |           |             |          |                           |           |                           | Service ATA:57 |
|                                                                    | MOS                                                                                                                                                  | 25-Jun-20 | 48 (+3m)    |          | 25-Jun-24                 | 25-Sep-24 | 511 d (+92)               |                |
|                                                                    | HRS                                                                                                                                                  | 5801      |             |          |                           |           |                           |                |
| WC#: 57.040                                                        | AFL                                                                                                                                                  | 3399      |             |          |                           |           |                           |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS, NTM 57-30-101              |                                                                                                                                                      |           |             |          |                           |           | WO#: N950PC 48 MONTH INSP |                |
| 570008                                                             | DETAIL INSPECT MAIN LANDING GEAR AND SIDESTAY ATTACHMENT FITTINGS                                                                                    |           |             |          |                           |           |                           | Service ATA:57 |
|                                                                    | MOS                                                                                                                                                  | 25-Jun-20 | 48 (+3m)    |          | 25-Jun-24                 | 25-Sep-24 | 511 d (+92)               |                |
|                                                                    | HRS                                                                                                                                                  | 5801      |             |          |                           |           |                           |                |
| WC#: 57.035                                                        | AFL                                                                                                                                                  | 3399      |             |          |                           |           |                           |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS                             |                                                                                                                                                      |           |             |          |                           |           | WO#: N950PC 48 MONTH INSP |                |
| 570009                                                             | DETAIL INSPECT WING BOTTOM SKIN (LH AND RH) ADJACENT TO FLAP OUTBOARD HINGE AT RIB 8                                                                 |           |             |          |                           |           |                           | Service ATA:57 |
|                                                                    | MOS                                                                                                                                                  | 15-Apr-21 |             |          |                           |           |                           |                |
|                                                                    | HRS                                                                                                                                                  | 5960.1    | 1200 (+10%) |          | 7160.1                    | 7280.1    | 631.8 (+120)              |                |
| WC#: 57.070                                                        | AFL                                                                                                                                                  | 3523      |             |          |                           |           |                           |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS                             |                                                                                                                                                      |           |             |          |                           |           |                           |                |
| 570010                                                             | DETAIL INSPECT WING FRONT SPAR, FORWARD FACE                                                                                                         |           |             |          |                           |           |                           | Service ATA:57 |
|                                                                    | MOS                                                                                                                                                  | 25-Jun-20 | 96 (+3m)    |          | 25-Jun-28                 | 25-Sep-28 | 1972 d (+92)              |                |
|                                                                    | HRS                                                                                                                                                  | 5801      | 4800 (+10%) |          | 10601                     | 11081     | 4072.7 (+480)             |                |
| WC#: 57.020                                                        | AFL                                                                                                                                                  | 3399      |             |          |                           |           |                           |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS, MMS 57-00-00, MMS 57-00-00 |                                                                                                                                                      |           |             |          |                           |           |                           |                |
| 570011                                                             | INSPECT WING REAR SPAR, REAR FACE                                                                                                                    |           |             |          |                           |           |                           | Service ATA:57 |
|                                                                    | MOS                                                                                                                                                  | 25-Jun-20 | 48 (+3m)    |          | 25-Jun-24                 | 25-Sep-24 | 511 d (+92)               |                |
|                                                                    | HRS                                                                                                                                                  | 5801      | 2400 (+10%) |          | 8201                      | 8441      | 1672.7 (+240)             |                |
| WC#: 57.030                                                        | AFL                                                                                                                                                  | 3399      |             |          |                           |           |                           |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS                             |                                                                                                                                                      |           |             |          |                           |           | WO#: N950PC 48 MONTH INSP |                |
| 570012                                                             | DETAIL INSPECT LEFT LOWER AIRBRAKE                                                                                                                   |           |             |          |                           |           |                           | Service ATA:57 |
|                                                                    | MOS                                                                                                                                                  | 25-Jun-20 | 48 (+3m)    |          | 25-Jun-24                 | 25-Sep-24 | 511 d (+92)               |                |
|                                                                    | HRS                                                                                                                                                  | 5801      | 2400 (+10%) |          | 8201                      | 8441      | 1672.7 (+240)             |                |
| WC#: 27.240                                                        | AFL                                                                                                                                                  | 3399      |             |          |                           |           |                           |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS                             |                                                                                                                                                      |           |             |          |                           |           | WO#: N950PC 48 MONTH INSP |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                               | Unit                                                   | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                                   | Disposition    |
|-------------------------------------------------------|--------------------------------------------------------|-----------|-------------|----------|---------------------------|-----------|---------------------------------------------|----------------|
| ATA 57 - WINGS                                        |                                                        |           |             |          |                           |           |                                             |                |
| 570012                                                | DETAIL INSPECT LEFT UPPER AIRBRAKE                     |           |             |          |                           |           |                                             | Service ATA:57 |
|                                                       | MOS                                                    | 25-Jun-20 | 48 (+3m)    |          | 25-Jun-24                 | 25-Sep-24 | 511 d (+92)                                 |                |
|                                                       | HRS                                                    | 5801      | 2400 (+10%) |          | 8201                      | 8441      | 1672.7 (+240)                               |                |
| WC#: 27.240                                           | AFL                                                    | 3399      |             |          |                           |           |                                             |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS                |                                                        |           |             |          |                           |           | WO#: N950PC 48 MONTH INSP                   |                |
| 570012                                                | DETAIL INSPECT RIGHT LOWER AIRBRAKE                    |           |             |          |                           |           |                                             | Service ATA:57 |
|                                                       | MOS                                                    | 25-Jun-20 | 48 (+3m)    |          | 25-Jun-24                 | 25-Sep-24 | 511 d (+92)                                 |                |
|                                                       | HRS                                                    | 5801      | 2400 (+10%) |          | 8201                      | 8441      | 1672.7 (+240)                               |                |
| WC#: 27.245                                           | AFL                                                    | 3399      |             |          |                           |           |                                             |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS                |                                                        |           |             |          |                           |           | WO#: N950PC 48 MONTH INSP                   |                |
| 570012                                                | DETAIL INSPECT RIGHT UPPER AIRBRAKE                    |           |             |          |                           |           |                                             | Service ATA:57 |
|                                                       | MOS                                                    | 25-Jun-20 | 48 (+3m)    |          | 25-Jun-24                 | 25-Sep-24 | 511 d (+92)                                 |                |
|                                                       | HRS                                                    | 5801      | 2400 (+10%) |          | 8201                      | 8441      | 1672.7 (+240)                               |                |
| WC#: 27.245                                           | AFL                                                    | 3399      |             |          |                           |           |                                             |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS                |                                                        |           |             |          |                           |           | WO#: N950PC 48 MONTH INSP                   |                |
| 570013                                                | DETAIL INSPECT AILERONS                                |           |             |          |                           |           |                                             | Service ATA:57 |
|                                                       | MOS                                                    | 25-Jun-20 | 48 (+3m)    |          | 25-Jun-24                 | 25-Sep-24 | 511 d (+92)                                 |                |
|                                                       | HRS                                                    | 5801      | 2400 (+10%) |          | 8201                      | 8441      | 1672.7 (+240)                               |                |
| WC#: 27.020                                           | AFL                                                    | 3399      |             |          |                           |           |                                             |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS, AMM 27-10-31  |                                                        |           |             |          |                           |           | WO#: N950PC 48 MONTH INSP,KLM - HANGAR RASH |                |
| 570014                                                | LUBRICATE CONNECTING RODS, AILERON TRIM AND SERVO TABS |           |             |          |                           |           |                                             | Service ATA:57 |
|                                                       | MOS                                                    | 25-Jun-20 | 48 (+3m)    |          | 25-Jun-24                 | 25-Sep-24 | 511 d (+92)                                 |                |
|                                                       | HRS                                                    | 5801      | 2400 (+10%) |          | 8201                      | 8441      | 1672.7 (+240)                               |                |
| WC#: 57.145                                           | AFL                                                    | 3399      |             |          |                           |           |                                             |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS                |                                                        |           |             |          |                           |           | WO#: N950PC 48 MONTH INSP                   |                |
| 570015                                                | INSPECT/X RAY AILERONS                                 |           |             |          |                           |           |                                             | Service ATA:57 |
|                                                       | MOS                                                    | 25-Jun-20 | 48 (+3m)    |          | 25-Jun-24                 | 25-Sep-24 | 511 d (+92)                                 |                |
|                                                       | HRS                                                    | 5801      | 2400 (+10%) |          | 8201                      | 8441      | 1672.7 (+240)                               |                |
| WC#: 57.100                                           | AFL                                                    | 3399      |             |          |                           |           |                                             |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS, NTM 57-50-107 |                                                        |           |             |          |                           |           | WO#: N950PC 48 MONTH INSP,KLM - HANGAR RASH |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                              | Unit                                                                                                             | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                 | Disposition    |
|----------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|---------------------------|----------------|
| ATA 57 - WINGS                                                       |                                                                                                                  |           |                |          |                           |           |                           |                |
| 570016                                                               | INSPECT/X RAY FLAPS AND FLAP VANES                                                                               |           |                |          |                           |           |                           | Service ATA:57 |
|                                                                      | MOS                                                                                                              | 25-Jun-20 | 48 (+3m)       |          | 25-Jun-24                 | 25-Sep-24 | 511 d (+92)               |                |
|                                                                      | HRS                                                                                                              | 5801      | 2400 (+10%)    |          | 8201                      | 8441      | 1672.7 (+240)             |                |
| WC#: 57.130                                                          | AFL                                                                                                              | 3399      |                |          |                           |           |                           |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS, NTM 57-50-105, NTM 57-50-106 |                                                                                                                  |           |                |          |                           |           | WO#: N950PC 48 MONTH INSP |                |
| 570017                                                               | DETAIL INSPECT WING BOTTOM SKIN AT ATTACHMENT TO FRONT SPAR, BETWEEN RIBS 1 AND 7                                |           |                |          |                           |           |                           | Service ATA:57 |
|                                                                      | MOS                                                                                                              | 03-Jan-12 |                |          |                           |           |                           |                |
|                                                                      | HRS                                                                                                              | 4572.3    | 4800 (+10%)    |          | 9372.3                    | 9852.3    | 2844 (+480)               |                |
| WC#: 57.055                                                          | AFL                                                                                                              | 2562      |                |          |                           |           |                           |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS, MMS 57-00-00                 |                                                                                                                  |           |                |          |                           |           |                           |                |
| 570018                                                               | DETAIL INSPECT WING BOTTOM SKIN CENTERLINE JOINT STRAP                                                           |           |                |          |                           |           |                           | Service ATA:57 |
|                                                                      | MOS                                                                                                              | 30-May-96 |                |          |                           |           |                           |                |
|                                                                      | HRS                                                                                                              |           | T:24000 (+500) |          | 24000                     | 24500     | 17471.7 (+500)            |                |
| WC#: 57.080                                                          | AFL                                                                                                              |           |                |          |                           |           |                           |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS, MMS 57-00-00                 |                                                                                                                  |           |                |          |                           |           |                           |                |
| 570019                                                               | INSPECT/NDT UPPER SURFACE OF THE WING BOTTOM SKIN AT THE ATTACHMENT TO THE CENTERLINE JOINT ADJACENT TO RIB 0    |           |                |          |                           |           |                           | Service ATA:57 |
|                                                                      | MOS                                                                                                              | 30-May-96 |                |          |                           |           |                           |                |
|                                                                      | HRS                                                                                                              |           | T:24000 (+500) |          | 24000                     | 24500     | 17471.7 (+500)            |                |
| WC#: 57.060                                                          | AFL                                                                                                              |           |                |          |                           |           |                           |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS, NTM 57-30-104, MMS 57-00-00  |                                                                                                                  |           |                |          |                           |           |                           |                |
| 570020                                                               | INSPECT/NDT WING BOTTOM SKIN CENTERLINE BUTT STRAP AND CENTER SECTION BEAMS (24 POSITIONS)                       |           |                |          |                           |           |                           | Service ATA:57 |
|                                                                      | MOS                                                                                                              | 30-May-96 |                |          |                           |           |                           |                |
|                                                                      | HRS                                                                                                              | 0         | 12000 (+500)   |          | 12000                     | 12500     | 5471.7 (+500)             |                |
| WC#: 57.075                                                          | AFL                                                                                                              |           |                |          |                           |           |                           |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS, NTM 57-00-102                |                                                                                                                  |           |                |          |                           |           |                           |                |
| 570021                                                               | DETAIL INSPECT WING TOP SKIN IN THE AREA THAT IS COVERED BY THE FUSELAGE STRUCTURE AND MAIN ATTACHMENT BRACKETS. |           |                |          |                           |           |                           | Service ATA:57 |
|                                                                      | MOS/MSC                                                                                                          |           | A/R            |          |                           |           |                           |                |
|                                                                      | HRS                                                                                                              | 0         |                |          |                           |           |                           |                |
| WC#: 57.010                                                          | AFL                                                                                                              |           |                |          |                           |           |                           |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS                               |                                                                                                                  |           |                |          |                           |           |                           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                             | Unit                                                                                                                                                                                                   | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition    |
|---------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|---------------|----------------|
| ATA 57 - WINGS                                                      |                                                                                                                                                                                                        |           |                |          |                           |           |               |                |
| 570022                                                              | DETAIL INSPECT REAR SPAR, REAR FACE BETWEEN RIB 1 LH AND RIB 1 RH                                                                                                                                      |           |                |          |                           |           |               | Service ATA:57 |
|                                                                     | MOS                                                                                                                                                                                                    | 03-Jan-12 |                |          |                           |           |               |                |
|                                                                     | HRS                                                                                                                                                                                                    | 4572.3    | 4800 (+10%)    |          | 9372.3                    | 9852.3    | 2844 (+480)   |                |
| WC#: 57.050                                                         | AFL                                                                                                                                                                                                    | 2562      |                |          |                           |           |               |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS, MMS 57-00-00                |                                                                                                                                                                                                        |           |                |          |                           |           |               |                |
| 570023                                                              | INSPECT/NDT AILERON HORN BALANCE WEIGHT                                                                                                                                                                |           |                |          |                           |           |               | Service ATA:57 |
|                                                                     | MOS                                                                                                                                                                                                    | 25-Jun-20 | 48 (+3m)       |          | 25-Jun-24                 | 25-Sep-24 | 511 d (+92)   |                |
|                                                                     | HRS                                                                                                                                                                                                    | 5801      |                |          |                           |           |               |                |
| WC#: 57.135                                                         | AFL                                                                                                                                                                                                    | 3399      |                |          |                           |           |               |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS, NTM 57-50-107, MMS 57-00-00 |                                                                                                                                                                                                        |           |                |          |                           |           |               |                |
| 570024                                                              | DETAIL INSPECT WING BOTTOM SKIN AT ATTACHMENT TO RIB 1 LH AND RH                                                                                                                                       |           |                |          |                           |           |               | Service ATA:57 |
|                                                                     | MOS                                                                                                                                                                                                    | 30-May-96 |                |          |                           |           |               |                |
|                                                                     | HRS                                                                                                                                                                                                    |           | T:12000 (+500) |          | 12000                     | 12500     | 5471.7 (+500) |                |
| WC#: 57.065                                                         | AFL                                                                                                                                                                                                    |           |                |          |                           |           |               |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS, MMS 57-00-00                |                                                                                                                                                                                                        |           |                |          |                           |           |               |                |
| 570025                                                              | DETAIL INSPECT WING BOTTOM SKIN AT ATTACHMENT TO THE REAR SPAR, BETWEEN RIB 1 LH AND RIB 1 RH                                                                                                          |           |                |          |                           |           |               | Service ATA:57 |
|                                                                     | MOS                                                                                                                                                                                                    | 03-Jan-12 |                |          |                           |           |               |                |
|                                                                     | HRS                                                                                                                                                                                                    | 4572.3    | 4800 (+10%)    |          | 9372.3                    | 9852.3    | 2844 (+480)   |                |
| WC#: 57.050                                                         | AFL                                                                                                                                                                                                    | 2562      |                |          |                           |           |               |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS, MMS 57-00-00                |                                                                                                                                                                                                        |           |                |          |                           |           |               |                |
| 570026                                                              | INSPECT WING LEADING EDGES                                                                                                                                                                             |           |                |          |                           |           |               | Service ATA:57 |
|                                                                     | MOS                                                                                                                                                                                                    | 25-Jun-20 | 48 (+3m)       |          | 25-Jun-24                 | 25-Sep-24 | 511 d (+92)   |                |
|                                                                     | HRS                                                                                                                                                                                                    | 5801      |                |          |                           |           |               |                |
| WC#: 57.025                                                         | AFL                                                                                                                                                                                                    | 3399      |                |          |                           |           |               |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS                              |                                                                                                                                                                                                        |           |                |          |                           |           |               |                |
| 570027                                                              | DETAIL INSPECT WING INTERNAL STRUCTURE FORWARD OF THE CENTER SPAR INCLUDING THE FRONT AND CENTER SPARS FROM RIBS 0 TO 4, AND BETWEEN AND INCLUDING THE FRONT AND REAR SPARS FROM RIB 4 TO THE WING TIP |           |                |          |                           |           |               | Service ATA:57 |
|                                                                     | MOS                                                                                                                                                                                                    | 25-Jun-20 | 96 (+3m)       |          | 25-Jun-28                 | 25-Sep-28 | 1972 d (+92)  |                |
|                                                                     | HRS                                                                                                                                                                                                    | 5801      | 4800 (+10%)    |          | 10601                     | 11081     | 4072.7 (+480) |                |
| WC#: 57.045                                                         | AFL                                                                                                                                                                                                    | 3399      |                |          |                           |           |               |                |
| PROC. REF: AFMS STRUCTURAL INSPECTIONS                              |                                                                                                                                                                                                        |           |                |          |                           |           |               |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                            | Unit                                                                                   | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                                   | Disposition      |
|--------------------------------------------------------------------|----------------------------------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|---------------------------------------------|------------------|
| ATA 57 - WINGS                                                     |                                                                                        |           |                |          |                           |           |                                             |                  |
| 570028                                                             | INSPECT AILERON AT OUTBOARD HINGE CASTING                                              |           |                |          |                           |           |                                             | Service ATA:57   |
|                                                                    | MOS                                                                                    | 25-Jun-20 | 48 (+3m)       |          | 25-Jun-24                 | 25-Sep-24 | 511 d (+92)                                 |                  |
|                                                                    | HRS                                                                                    | 5801      |                |          |                           |           |                                             |                  |
| WC#: 57.125                                                        | AFL                                                                                    | 3399      |                |          |                           |           |                                             |                  |
| PROC. REF: AMM 27-10-31, AFMS STRUCTURAL INSPECTIONS, AMM 27-10-31 |                                                                                        |           |                |          |                           |           | WO#: N950PC 48 MONTH INSP,KLM - HANGAR RASH |                  |
| 571010                                                             | WING                                                                                   |           |                |          |                           |           |                                             | Component ATA:57 |
| PN:25.8WS1                                                         | MOS/MSC                                                                                | 30-May-96 | O/C            |          |                           |           |                                             |                  |
| SN:DHB8300                                                         | HRS                                                                                    | 0         |                | TSN 0    |                           |           |                                             |                  |
| WC#: 57.010                                                        | AFL                                                                                    | 0         |                |          |                           |           |                                             |                  |
| 571109                                                             | REPLACE LEFT FLAP HINGE ATTACHMENT ANGLES TO MAIN LANDING GEAR MOUNTING FITTING BOLTS  |           |                |          |                           |           |                                             | Service ATA:57   |
|                                                                    | MOS                                                                                    | 30-May-96 |                |          |                           |           |                                             | LIFE LIMIT       |
|                                                                    | HRS                                                                                    | 0         |                |          |                           |           |                                             |                  |
| WC#: 57.150                                                        | AFL                                                                                    | 0         | 14600          |          | 14600                     |           | 10671                                       |                  |
| 571110                                                             | REPLACE RIGHT FLAP HINGE ATTACHMENT ANGLES TO MAIN LANDING GEAR MOUNTING FITTING BOLTS |           |                |          |                           |           |                                             | Service ATA:57   |
|                                                                    | MOS                                                                                    | 30-May-96 |                |          |                           |           |                                             | LIFE LIMIT       |
|                                                                    | HRS                                                                                    | 0         |                |          |                           |           |                                             |                  |
| WC#: 57.150                                                        | AFL                                                                                    | 0         | 14600          |          | 14600                     |           | 10671                                       |                  |
| 574001                                                             | LEFT LEADING EDGE ASSEMBLY                                                             |           |                |          |                           |           |                                             | Component ATA:57 |
| PN:25.8WS3299-3A                                                   | MOS/MSC                                                                                | 30-May-96 | O/C            |          |                           |           |                                             |                  |
| SN:AST96C217                                                       | HRS                                                                                    | 0         |                | TSN 0    |                           |           |                                             |                  |
| WC#: 57.085                                                        | AFL                                                                                    | 0         |                |          |                           |           |                                             |                  |
|                                                                    |                                                                                        |           |                |          |                           |           | WO#: N950PC 48 MONTH INSP                   |                  |
| 574002                                                             | RIGHT LEADING EDGE ASSEMBLY                                                            |           |                |          |                           |           |                                             | Component ATA:57 |
| PN:S25-9WS7-347A                                                   | MOS/MSC                                                                                | 03-Jan-12 | O/C            | TSN 0    |                           |           |                                             |                  |
| SN:AST91K026                                                       | HRS                                                                                    | 4572.3    |                | TSN 0    |                           |           |                                             |                  |
| WC#: 57.085                                                        | AFL                                                                                    | 2562      |                | TSN 0    |                           |           |                                             |                  |
| 579011-API                                                         | DETAIL INSPECT LOWER LUGS OF THE FRONT SPAR ATTACH FITTING (LH AND RH)                 |           |                |          |                           |           |                                             | Service ATA:57   |
|                                                                    | MOS                                                                                    |           |                |          |                           |           |                                             |                  |
|                                                                    | HRS                                                                                    | 0         | T:20000 (+500) |          | 20000                     | 20500     | 13471.7 (+500)                              |                  |
| WC#: 57.105                                                        | AFL                                                                                    |           |                |          |                           |           |                                             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                 | Unit                                                                                                                      | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition      |
|-------------------------|---------------------------------------------------------------------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|---------------|------------------|
| ATA 57 - WINGS          |                                                                                                                           |           |                |          |                           |           |               |                  |
| 579012-API              | EDDY CURRENT INSPECT FASTENER HOLES (LH AND RH) COMMON TO THE LOWER SKIN, FRONT SPAR CHORD, AND FRONT SPAR ATTACH FITTING |           |                |          |                           |           |               | Service ATA:57   |
|                         | MOS                                                                                                                       |           |                |          |                           |           |               |                  |
|                         | HRS                                                                                                                       | 0         | T:13500 (+500) |          | 13500                     | 14000     | 6971.7 (+500) |                  |
| WC#: 57.110             | AFL                                                                                                                       |           |                |          |                           |           |               |                  |
| PROC. REF: MMS 57-00-00 |                                                                                                                           |           |                |          |                           |           |               |                  |
| 579021-API              | DETAIL INSPECT LOWER LUGS OF THE REAR SPAR ATTACH FITTING (LH AND RH)                                                     |           |                |          |                           |           |               | Service ATA:57   |
|                         | MOS                                                                                                                       |           |                |          |                           |           |               |                  |
|                         | HRS                                                                                                                       | 0         | T:15000 (+500) |          | 15000                     | 15500     | 8471.7 (+500) |                  |
| WC#: 57.115             | AFL                                                                                                                       |           |                |          |                           |           |               |                  |
| PROC. REF: MMS 57-00-00 |                                                                                                                           |           |                |          |                           |           |               |                  |
| 579022-API              | EDDY CURRENT INSPECT FASTENER HOLES (LH AND RH) COMMON TO THE LOWER SKIN, REAR SPAR CHORD, AND LOWER REAR SPAR ANGLE      |           |                |          |                           |           |               | Service ATA:57   |
|                         | MOS                                                                                                                       |           |                |          |                           |           |               |                  |
|                         | HRS                                                                                                                       | 0         | T:9000 (+500)  |          | 9000                      | 9500      | 2471.7 (+500) |                  |
| WC#: 57.120             | AFL                                                                                                                       |           |                |          |                           |           |               |                  |
| ATA 71 - POWER PLANT    |                                                                                                                           |           |                |          |                           |           |               |                  |
| 710049                  | COMPRESSOR WASH NO. 1 ENGINE                                                                                              |           |                |          |                           |           |               | Service ATA:71   |
|                         | MOS/MSC                                                                                                                   | 10-Oct-01 | O/C            |          |                           |           |               |                  |
|                         | HRS                                                                                                                       | 2057      |                |          |                           |           |               |                  |
| WC#: 71.025             | AFL                                                                                                                       | 1144      |                |          |                           |           |               |                  |
| PROC. REF: GENERIC CMM  |                                                                                                                           |           |                |          |                           |           |               |                  |
| 710050                  | COMPRESSOR WASH NO. 2 ENGINE                                                                                              |           |                |          |                           |           |               | Service ATA:71   |
|                         | MOS/MSC                                                                                                                   | 30-May-96 | O/C            |          |                           |           |               |                  |
|                         | HRS                                                                                                                       | 0         |                |          |                           |           |               |                  |
| WC#: 71.025             | AFL                                                                                                                       |           |                |          |                           |           |               |                  |
| PROC. REF: GENERIC CMM  |                                                                                                                           |           |                |          |                           |           |               |                  |
| 710081                  | NO. 1 ENGINE INLET COWL                                                                                                   |           |                |          |                           |           |               | Component ATA:71 |
| PN:C46B-11000-21        | MOS/MSC                                                                                                                   | 23-Jul-19 | O/C            |          |                           |           |               |                  |
| SN:B-135                | HRS                                                                                                                       | 5795      |                |          |                           |           |               |                  |
| WC#: 71.055             | AFL                                                                                                                       | 3396      |                |          |                           |           |               |                  |
| PROC. REF: AMM 71-10-00 |                                                                                                                           |           |                |          |                           |           |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                             | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|----------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 71 - POWER PLANT      |                                  |           |          |          |                           |           |           |                  |
| 710082                    | NO. 2 ENGINE INLET COWL          |           |          |          |                           |           |           | Component ATA:71 |
| PN:C46B-11000-22          | MOS/MSC                          | 23-Jul-19 | O/C      |          |                           |           |           |                  |
| SN:B-135                  | HRS                              | 5795      |          |          |                           |           |           |                  |
| WC#: 71.055               | AFL                              | 3396      |          |          |                           |           |           |                  |
| PROC. REF: AMM 71-10-00   |                                  |           |          |          |                           |           |           |                  |
| 710083                    | NO. 1 ENGINE UPPER FAN COWL DOOR |           |          |          |                           |           |           | Component ATA:71 |
| PN:C46B-14000-3           | MOS/MSC                          | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:B-138                  | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 71.060               | AFL                              | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 71-10-00   |                                  |           |          |          |                           |           |           |                  |
| 710084                    | NO. 2 ENGINE UPPER FAN COWL DOOR |           |          |          |                           |           |           | Component ATA:71 |
| PN:C46B-14000-4           | MOS/MSC                          | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:B-138                  | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 71.060               | AFL                              | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 71-10-00   |                                  |           |          |          |                           |           |           |                  |
| 710089                    | NO. 1 ENGINE LOWER FAN COWL DOOR |           |          |          |                           |           |           | Component ATA:71 |
| PN:C46B-15000-21          | MOS/MSC                          | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:B-138                  | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 71.070               | AFL                              | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 71-10-00   |                                  |           |          |          |                           |           |           |                  |
| 710090                    | NO. 2 ENGINE LOWER FAN COWL DOOR |           |          |          |                           |           |           | Component ATA:71 |
| PN:C46B-15000-23          | MOS/MSC                          | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:B-138                  | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 71.070               | AFL                              | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 71-10-00   |                                  |           |          |          |                           |           |           |                  |
| 712001                    | NO. 1 ENGINE MOUNTING            |           |          |          |                           |           |           | Component ATA:71 |
| PN:PN                     | MOS/MSC                          | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 71.075               | AFL                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                  |           |          |          |                           |           |           |                  |
| 712002                    | NO. 2 ENGINE MOUNTING            |           |          |          |                           |           |           | Component ATA:71 |
| PN:PN                     | MOS/MSC                          | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 71.080               | AFL                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                  |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                                                   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                           | Disposition      |
|---------------------------|--------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-------------------------------------|------------------|
| ATA 71 - POWER PLANT      |                                                        |           |          |          |                           |           |                                     |                  |
| 714010                    | NO. 1 ENGINE - CHECK ELECTRICAL WIRING AND CONNECTIONS |           |          |          |                           |           |                                     | Service ATA:71   |
|                           | MOS                                                    | 11-Oct-22 |          |          |                           |           |                                     |                  |
|                           | HRS                                                    | 6450.1    | 800      |          | (7250.1)<br>7246.9        |           | 718.6                               |                  |
| WC#: 71.030               | ENC                                                    | 3876      |          |          |                           |           |                                     |                  |
| PROC. REF: GENERIC NO REF |                                                        |           |          |          |                           |           | PKG:4<br>WO#: N950PC LH ENG MPI     |                  |
| 714010                    | NO. 2 ENGINE - CHECK ELECTRICAL WIRING AND CONNECTIONS |           |          |          |                           |           |                                     | Service ATA:71   |
|                           | MOS                                                    | 11-Oct-22 |          |          |                           |           |                                     |                  |
|                           | HRS                                                    | 6365.3    | 800      |          | (7165.3)<br>7246.4        |           | 718.1                               |                  |
| WC#: 71.030               | ENC                                                    | 3828      |          |          |                           |           |                                     |                  |
| PROC. REF: GENERIC NO REF |                                                        |           |          |          |                           |           | PKG:4<br>WO#: N950PC RH ENG MPI/CZI |                  |
| 715010                    | NO. 1 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS    |           |          |          |                           |           |                                     | Service ATA:71   |
|                           | MOS                                                    | 11-Oct-22 |          |          |                           |           |                                     |                  |
|                           | HRS                                                    | 6450.1    | 800      |          | (7250.1)<br>7246.9        |           | 718.6                               |                  |
| WC#: 71.040               | ENC                                                    | 3876      |          |          |                           |           |                                     |                  |
| PROC. REF: GENERIC NO REF |                                                        |           |          |          |                           |           | PKG:4<br>WO#: N950PC LH ENG MPI     |                  |
| 715010                    | NO. 2 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS    |           |          |          |                           |           |                                     | Service ATA:71   |
|                           | MOS                                                    | 11-Oct-22 |          |          |                           |           |                                     |                  |
|                           | HRS                                                    | 6365.3    | 800      |          | (7165.3)<br>7246.4        |           | 718.1                               |                  |
| WC#: 71.040               | ENC                                                    | 3828      |          |          |                           |           |                                     |                  |
| PROC. REF: GENERIC NO REF |                                                        |           |          |          |                           |           | PKG:4<br>WO#: N950PC RH ENG MPI/CZI |                  |
| 71EN1                     | NO. 1 ENGINE                                           |           |          |          |                           |           |                                     | Component ATA:71 |
| PN:3075160-3              | MOS/MSC                                                |           | E/C      |          |                           |           |                                     |                  |
| SN:P-107171               | HRS                                                    |           |          |          |                           |           |                                     |                  |
|                           | AFL                                                    |           |          |          |                           |           |                                     |                  |
| PROC. REF: AMM 71-00-01   |                                                        |           |          |          |                           |           | WO#: N950PC LH ENG MPI              |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                  | Unit                                                                                                                   | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                  | Disposition |        |
|------------------------------------------|------------------------------------------------------------------------------------------------------------------------|-----------|-------------|----------|---------------------------|-----------|----------------------------|-------------|--------|
| ATA 71 - POWER PLANT                     |                                                                                                                        |           |             |          |                           |           |                            |             |        |
| 71EN2                                    | NO. 2 ENGINE                                                                                                           |           |             |          |                           |           |                            | Component   | ATA:71 |
| PN:3075160-3                             | MOS/MSC                                                                                                                | 18-Jan-02 | E/C         |          |                           |           |                            |             |        |
| SN:P-107151                              | HRS                                                                                                                    | 2137      |             | TSN 2057 |                           |           |                            |             |        |
|                                          | AFL                                                                                                                    | 1186      |             |          |                           |           |                            |             |        |
| PROC. REF: AMM 71-00-01                  |                                                                                                                        |           |             |          |                           |           | WO#: N950PC RH ENG MPI/CZI |             |        |
| ATA 72 - ENGINE                          |                                                                                                                        |           |             |          |                           |           |                            |             |        |
| 720000                                   | NO. 1 ENGINE - SPECIAL INSPECTION - RENTAL/LOANER ENGINE PRE-REMOVAL SERVICEABILITY AND ENGINE PRESERVATION INSPECTION |           |             |          |                           |           |                            | Service     | ATA:72 |
|                                          | MOS/MSC                                                                                                                | 11-Nov-96 | A/R         |          |                           |           |                            |             |        |
|                                          | HRS                                                                                                                    | 20        |             |          |                           |           |                            |             |        |
|                                          | ENC                                                                                                                    | 12        |             |          |                           |           |                            |             |        |
| PROC. REF: LMM 72-00-00                  |                                                                                                                        |           |             |          |                           |           |                            |             |        |
| 720000                                   | NO. 2 ENGINE - SPECIAL INSPECTION - RENTAL/LOANER ENGINE PRE-REMOVAL SERVICEABILITY AND ENGINE PRESERVATION INSPECTION |           |             |          |                           |           |                            | Service     | ATA:72 |
|                                          | MOS/MSC                                                                                                                | 30-May-96 | A/R         |          |                           |           |                            |             |        |
|                                          | HRS                                                                                                                    | 0         |             |          |                           |           |                            |             |        |
|                                          | ENC                                                                                                                    | 0         |             |          |                           |           |                            |             |        |
| PROC. REF: LMM 72-00-00                  |                                                                                                                        |           |             |          |                           |           |                            |             |        |
| 720001                                   | NO. 1 ENGINE - SPECIAL INSPECTION - ACCIDENT OR INCIDENT INSPECTION REQUIREMENTS                                       |           |             |          |                           |           |                            | Service     | ATA:72 |
|                                          | MOS/MSC                                                                                                                | 11-Nov-96 | A/R         |          |                           |           |                            |             |        |
|                                          | HRS                                                                                                                    | 20        |             |          |                           |           |                            |             |        |
|                                          | ENC                                                                                                                    | 12        |             |          |                           |           |                            |             |        |
| PROC. REF: LMM 72-00-00                  |                                                                                                                        |           |             |          |                           |           |                            |             |        |
| 720001                                   | NO. 2 ENGINE - SPECIAL INSPECTION - ACCIDENT OR INCIDENT INSPECTION REQUIREMENTS                                       |           |             |          |                           |           |                            | Service     | ATA:72 |
|                                          | MOS/MSC                                                                                                                | 30-May-96 | A/R         |          |                           |           |                            |             |        |
|                                          | HRS                                                                                                                    | 0         |             |          |                           |           |                            |             |        |
|                                          | ENC                                                                                                                    | 0         |             |          |                           |           |                            |             |        |
| PROC. REF: LMM 72-00-00                  |                                                                                                                        |           |             |          |                           |           |                            |             |        |
| 720002                                   | INSPECT NO. 1 ENGINE AFT COWLING/INNER FAN DUCT AND EXHAUST DUCT                                                       |           |             |          |                           |           |                            | Service     | ATA:72 |
|                                          | MOS                                                                                                                    | 09-Mar-04 |             |          |                           |           |                            | PART OF MPI |        |
|                                          | HRS                                                                                                                    | 2632.6    | 2500 (+10%) |          | 6729.9 (M)                | 6979.9    | 201.6 (+250)               |             |        |
| WC#: 72.030                              | AFL                                                                                                                    | 1434      |             |          |                           |           |                            |             |        |
| PROC. REF: AFMS OUT OF PHASE INSPECTIONS |                                                                                                                        |           |             |          |                           |           | WO#: N950PC LH ENG MPI     |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                  | Unit                                                                         | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C  | Max Limit | Remaining     | Disposition    |
|------------------------------------------|------------------------------------------------------------------------------|-----------|-------------|----------|----------------------------|-----------|---------------|----------------|
| ATA 72 - ENGINE                          |                                                                              |           |             |          |                            |           |               |                |
| 720002                                   | INSPECT NO. 2 ENGINE AFT COWLING/INNER FAN DUCT AND EXHAUST DUCT             |           |             |          |                            |           |               | Service ATA:72 |
|                                          | MOS                                                                          | 09-Feb-10 |             |          |                            |           |               | PART OF MPI    |
|                                          | HRS                                                                          | 4129.9    | 2500 (+10%) |          | 6629.9                     | 6879.9    | 101.6 (+250)  |                |
| WC#: 72.030                              | AFL                                                                          | 2305      |             |          |                            |           |               |                |
| PROC. REF: AFMS OUT OF PHASE INSPECTIONS |                                                                              |           |             |          | WO#: N950PC RH ENG MPI/CZI |           |               |                |
| 720002                                   | NO. 1 ENGINE - SPECIAL INSPECTION - LIGHTNING STRIKE INSPECTION REQUIREMENTS |           |             |          |                            |           |               | Service ATA:72 |
|                                          | MOS/MSC                                                                      | 11-Nov-96 | A/R         |          |                            |           |               |                |
|                                          | HRS                                                                          | 20        |             |          |                            |           |               |                |
|                                          | ENC                                                                          | 12        |             |          |                            |           |               |                |
| PROC. REF: LMM 72-00-00                  |                                                                              |           |             |          |                            |           |               |                |
| 720002                                   | NO. 2 ENGINE - SPECIAL INSPECTION - LIGHTNING STRIKE INSPECTION REQUIREMENTS |           |             |          |                            |           |               | Service ATA:72 |
|                                          | MOS/MSC                                                                      | 30-May-96 | A/R         |          |                            |           |               |                |
|                                          | HRS                                                                          | 0         |             |          |                            |           |               |                |
|                                          | ENC                                                                          | 0         |             |          |                            |           |               |                |
| PROC. REF: LMM 72-00-00                  |                                                                              |           |             |          |                            |           |               |                |
| 720003                                   | DETAIL INSPECT NO. 1 ENGINE EXHAUST NOZZLE/EXHAUST PIPE V CLAMP              |           |             |          |                            |           |               | Service ATA:72 |
|                                          | MOS                                                                          | 10-Oct-22 |             |          |                            |           |               | PART OF MPI    |
|                                          | HRS                                                                          | 6446.4    | 2500 (+10%) |          | 8946.4                     | 9196.4    | 2418.1 (+250) |                |
| WC#: 72.040                              | AFL                                                                          | 3873      |             |          |                            |           |               |                |
| PROC. REF: AFMS OUT OF PHASE INSPECTIONS |                                                                              |           |             |          |                            |           |               |                |
| 720003                                   | DETAIL INSPECT NO. 2 ENGINE EXHAUST NOZZLE/EXHAUST PIPE V CLAMP              |           |             |          |                            |           |               | Service ATA:72 |
|                                          | MOS                                                                          | 09-Feb-10 |             |          |                            |           |               | PART OF MPI    |
|                                          | HRS                                                                          | 4129.9    | 2500 (+10%) |          | 6629.9                     | 6879.9    | 101.6 (+250)  |                |
| WC#: 72.040                              | AFL                                                                          | 2305      |             |          |                            |           |               |                |
| PROC. REF: AFMS OUT OF PHASE INSPECTIONS |                                                                              |           |             |          | WO#: N950PC RH ENG MPI/CZI |           |               |                |
| 720003                                   | NO. 1 ENGINE - SPECIAL INSPECTION - OVERTEMPERATURE INSPECTION REQUIREMENTS  |           |             |          |                            |           |               | Service ATA:72 |
|                                          | MOS/MSC                                                                      | 11-Nov-96 | A/R         |          |                            |           |               |                |
|                                          | HRS                                                                          | 20        |             |          |                            |           |               |                |
|                                          | ENC                                                                          | 12        |             |          |                            |           |               |                |
| PROC. REF: LMM 72-00-00                  |                                                                              |           |             |          |                            |           |               |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                 | Unit                                                                                          | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition    |
|-------------------------|-----------------------------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|----------------|
| ATA 72 - ENGINE         |                                                                                               |           |          |          |                           |           |           |                |
| 720003                  | NO. 2 ENGINE - SPECIAL INSPECTION - OVERTEMPERATURE INSPECTION REQUIREMENTS                   |           |          |          |                           |           |           | Service ATA:72 |
|                         | MOS/MSC                                                                                       | 30-May-96 | A/R      |          |                           |           |           |                |
|                         | HRS                                                                                           | 0         |          |          |                           |           |           |                |
|                         | ENC                                                                                           | 0         |          |          |                           |           |           |                |
| PROC. REF: LMM 72-00-00 |                                                                                               |           |          |          |                           |           |           |                |
| 720004                  | NO. 1 ENGINE - SPECIAL INSPECTION - FOREIGN OBJECT DAMAGE (FOD) AND/OR BIRD STRIKE INSPECTION |           |          |          |                           |           |           | Service ATA:72 |
|                         | MOS/MSC                                                                                       | 11-Nov-96 | A/R      |          |                           |           |           |                |
|                         | HRS                                                                                           | 20        |          |          |                           |           |           |                |
|                         | ENC                                                                                           | 12        |          |          |                           |           |           |                |
| PROC. REF: LMM 72-00-00 |                                                                                               |           |          |          |                           |           |           |                |
| 720004                  | NO. 2 ENGINE - SPECIAL INSPECTION - FOREIGN OBJECT DAMAGE (FOD) AND/OR BIRD STRIKE INSPECTION |           |          |          |                           |           |           | Service ATA:72 |
|                         | MOS/MSC                                                                                       | 30-May-96 | A/R      |          |                           |           |           |                |
|                         | HRS                                                                                           | 0         |          |          |                           |           |           |                |
|                         | ENC                                                                                           | 0         |          |          |                           |           |           |                |
| PROC. REF: LMM 72-00-00 |                                                                                               |           |          |          |                           |           |           |                |
| 720005                  | NO. 1 ENGINE - SPECIAL INSPECTION - OIL AND FILTER ANALYSIS                                   |           |          |          |                           |           |           | Service ATA:72 |
|                         | MOS/MSC                                                                                       | 11-Oct-22 | A/R      |          |                           |           |           |                |
|                         | HRS                                                                                           | 6450.1    |          |          |                           |           |           |                |
|                         | ENC                                                                                           | 3876      |          |          |                           |           |           |                |
| PROC. REF: LMM 72-00-00 |                                                                                               |           |          |          |                           |           |           |                |
| 720005                  | NO. 2 ENGINE - SPECIAL INSPECTION - OIL AND FILTER ANALYSIS                                   |           |          |          |                           |           |           | Service ATA:72 |
|                         | MOS/MSC                                                                                       | 11-Oct-22 | A/R      |          |                           |           |           |                |
|                         | HRS                                                                                           | 6365.3    |          |          |                           |           |           |                |
|                         | ENC                                                                                           | 3828      |          |          |                           |           |           |                |
| PROC. REF: LMM 72-00-00 |                                                                                               |           |          |          |                           |           |           |                |
| 720006                  | NO. 1 ENGINE - SPECIAL INSPECTION - OVERSPEED INSPECTION                                      |           |          |          |                           |           |           | Service ATA:72 |
|                         | MOS/MSC                                                                                       | 11-Nov-96 | A/R      |          |                           |           |           |                |
|                         | HRS                                                                                           | 20        |          |          |                           |           |           |                |
|                         | ENC                                                                                           | 12        |          |          |                           |           |           |                |
| PROC. REF: LMM 72-00-00 |                                                                                               |           |          |          |                           |           |           |                |
| 720006                  | NO. 2 ENGINE - SPECIAL INSPECTION - OVERSPEED INSPECTION                                      |           |          |          |                           |           |           | Service ATA:72 |
|                         | MOS/MSC                                                                                       | 30-May-96 | A/R      |          |                           |           |           |                |
|                         | HRS                                                                                           | 0         |          |          |                           |           |           |                |
|                         | ENC                                                                                           | 0         |          |          |                           |           |           |                |
| PROC. REF: LMM 72-00-00 |                                                                                               |           |          |          |                           |           |           |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN         | Unit                                             | C/W       | Interval    | TSX/Adj.                | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition                         |
|-----------------|--------------------------------------------------|-----------|-------------|-------------------------|---------------------------|-----------|--------------|-------------------------------------|
| ATA 72 - ENGINE |                                                  |           |             |                         |                           |           |              |                                     |
| 720120          | NO. 1 ENGINE - MAJOR PERIODIC INSPECTION (MPI)   |           |             |                         |                           |           |              | Service ATA:72                      |
|                 | MOS                                              | 28-Feb-10 |             |                         |                           |           |              |                                     |
|                 | HRS                                              | 4129.9    | 2500 (+100) |                         | (6629.9)<br>6626.7        | 6729.9    | 98.4 (+100)  |                                     |
| WC#: 71.010     | ENC                                              | 2305      |             |                         |                           |           |              |                                     |
|                 |                                                  |           |             | PROC. REF: LMM 72-00-00 |                           |           |              | WO#: N950PC LH ENG MPI              |
| 720120          | NO. 2 ENGINE - MAJOR PERIODIC INSPECTION (MPI)   |           |             |                         |                           |           |              | Service ATA:72                      |
|                 | MOS                                              | 09-Feb-10 |             |                         |                           |           |              |                                     |
|                 | HRS                                              | 4050      | 2500 (+100) |                         | (6550)<br>6631.1          | 6650      | 102.8 (+100) |                                     |
| WC#: 71.010     | ENC                                              | 2263      |             |                         |                           |           |              |                                     |
|                 |                                                  |           |             | PROC. REF: LMM 72-00-00 |                           |           |              | WO#: N950PC RH ENG MPI/CZI          |
| 720130          | NO. 1 ENGINE - INSPECT FAN ROTOR ASSEMBLY BLADES |           |             |                         |                           |           |              | Service ATA:72                      |
|                 | MOS                                              | 11-Oct-22 |             |                         |                           |           |              |                                     |
|                 | HRS                                              | 6450.1    | 800         |                         | (7250.1)<br>7246.9        |           | 718.6        |                                     |
| WC#: 71.020     | ENC                                              | 3876      |             |                         |                           |           |              |                                     |
|                 |                                                  |           |             | PROC. REF: LMM 72-00-00 |                           |           |              | PKG:4<br>WO#: N950PC LH ENG MPI     |
| 720130          | NO. 2 ENGINE - INSPECT FAN ROTOR ASSEMBLY BLADES |           |             |                         |                           |           |              | Service ATA:72                      |
|                 | MOS                                              | 11-Oct-22 |             |                         |                           |           |              |                                     |
|                 | HRS                                              | 6365.3    | 800         |                         | (7165.3)<br>7246.4        |           | 718.1        |                                     |
| WC#: 71.020     | ENC                                              | 3828      |             |                         |                           |           |              |                                     |
|                 |                                                  |           |             | PROC. REF: LMM 72-00-00 |                           |           |              | PKG:4<br>WO#: N950PC RH ENG MPI/CZI |
| 721001          | NO. 1 ENGINE - PRESERVATION OF ENGINE            |           |             |                         |                           |           |              | Service ATA:72                      |
|                 | MOS/MSC                                          | 11-Nov-96 | O/C         |                         |                           |           |              |                                     |
|                 | HRS                                              | 20        |             |                         |                           |           |              |                                     |
| WC#: 72.001     | ENC                                              | 12        |             |                         |                           |           |              |                                     |
|                 |                                                  |           |             | PROC. REF: LMM 72-00-00 |                           |           |              |                                     |
| 721001          | NO. 2 ENGINE - PRESERVATION OF ENGINE            |           |             |                         |                           |           |              | Service ATA:72                      |
|                 | MOS/MSC                                          | 30-May-96 | O/C         |                         |                           |           |              |                                     |
|                 | HRS                                              | 0         |             |                         |                           |           |              |                                     |
| WC#: 72.001     | ENC                                              | 0         |             |                         |                           |           |              |                                     |
|                 |                                                  |           |             | PROC. REF: LMM 72-00-00 |                           |           |              |                                     |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                 | Unit                                             | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition                |
|-------------------------|--------------------------------------------------|-----------|-------------|----------|---------------------------|-----------|---------------|----------------------------|
| ATA 72 - ENGINE         |                                                  |           |             |          |                           |           |               |                            |
| 721002                  | NO. 1 ENGINE - PERFORM ENGINE PRESERVATION CHECK |           |             |          |                           |           |               | Service ATA:72             |
|                         | MOS/MSC                                          | 11-Nov-96 | O/C         |          |                           |           |               |                            |
|                         | HRS                                              | 20        |             |          |                           |           |               |                            |
| WC#: 72.001             | ENC                                              | 12        |             |          |                           |           |               |                            |
| PROC. REF: LMM 72-00-00 |                                                  |           |             |          |                           |           |               |                            |
| 721002                  | NO. 2 ENGINE - PERFORM ENGINE PRESERVATION CHECK |           |             |          |                           |           |               | Service ATA:72             |
|                         | MOS/MSC                                          | 30-May-96 | O/C         |          |                           |           |               |                            |
|                         | HRS                                              | 0         |             |          |                           |           |               |                            |
| WC#: 72.001             | ENC                                              | 0         |             |          |                           |           |               |                            |
| PROC. REF: LMM 72-00-00 |                                                  |           |             |          |                           |           |               |                            |
| 721003                  | NO. 1 ENGINE - DE-PRESERVATION OF ENGINE         |           |             |          |                           |           |               | Service ATA:72             |
|                         | MOS/MSC                                          | 11-Nov-96 | O/C         |          |                           |           |               |                            |
|                         | HRS                                              | 20        |             |          |                           |           |               |                            |
| WC#: 72.001             | ENC                                              | 12        |             |          |                           |           |               |                            |
| PROC. REF: LMM 72-00-00 |                                                  |           |             |          |                           |           |               |                            |
| 721003                  | NO. 2 ENGINE - DE-PRESERVATION OF ENGINE         |           |             |          |                           |           |               | Service ATA:72             |
|                         | MOS/MSC                                          | 30-May-96 | O/C         |          |                           |           |               |                            |
|                         | HRS                                              | 0         |             |          |                           |           |               |                            |
| WC#: 72.001             | ENC                                              | 0         |             |          |                           |           |               |                            |
| PROC. REF: LMM 72-00-00 |                                                  |           |             |          |                           |           |               |                            |
| 723110                  | NO. 1 ENGINE - COMPRESSOR ZONE INSPECTION (CZI)  |           |             |          |                           |           |               | Service ATA:72             |
|                         | MOS                                              | 22-Feb-10 |             |          |                           |           |               |                            |
|                         | HRS                                              | 4129.9    | 5000 (+200) |          | (9129.9)<br>9126.7        | 9329.9    | 2598.4 (+200) |                            |
| WC#: 72.010             | ENC                                              | 2305      |             |          |                           |           |               |                            |
| PROC. REF: LMM 72-00-00 |                                                  |           |             |          |                           |           |               |                            |
| 723110                  | NO. 2 ENGINE - COMPRESSOR ZONE INSPECTION (CZI)  |           |             |          |                           |           |               | Service ATA:72             |
|                         | MOS                                              | 18-Jan-02 |             |          |                           |           |               |                            |
|                         | HRS                                              | 2057.3    | 5000 (+200) |          | (7057.3)<br>7138.4        | 7257.3    | 610.1 (+200)  |                            |
| WC#: 72.010             | ENC                                              | 1144      |             |          |                           |           |               |                            |
| PROC. REF: LMM 72-00-00 |                                                  |           |             |          |                           |           |               | WO#: N950PC RH ENG MPI/CZI |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                                                  | C/W       | Interval    | TSX/Adj.   | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining              | Disposition      |
|---------------------------|-------------------------------------------------------|-----------|-------------|------------|---------------------------|-----------|------------------------|------------------|
| ATA 72 - ENGINE           |                                                       |           |             |            |                           |           |                        |                  |
| 724110                    | NO. 1 ENGINE - COMBUSTION CHAMBER PLENUM CASE         |           |             |            |                           |           |                        | Component ATA:72 |
| PN:3072443-5              | MOS/MSC                                               | 02-Jul-96 | O/C         |            |                           |           |                        |                  |
| SN:6-22151-4161           | HRS                                                   | 0         |             | TSN 0      |                           |           |                        |                  |
| WC#: 72.020               | ENC                                                   | 0         |             | TSN 0      |                           |           |                        |                  |
| PROC. REF: GENERIC NO REF |                                                       |           |             |            |                           |           | WO#: N950PC LH ENG MPI |                  |
| 724110                    | NO. 2 ENGINE - COMBUSTION CHAMBER PLENUM CASE         |           |             |            |                           |           |                        | Component ATA:72 |
| PN:3072443-5              | MOS/MSC                                               | 04-May-15 | O/C         |            |                           |           |                        |                  |
| SN:6-22151-3954           | HRS                                                   | 5125.6    |             | TSN 5125.6 |                           |           |                        |                  |
| WC#: 72.020               | ENC                                                   | 2873      |             | TSN 2873   |                           |           |                        |                  |
| PROC. REF: GENERIC NO REF |                                                       |           |             |            |                           |           |                        |                  |
| 724120                    | NO. 1 ENGINE - INSPECT COMBUSTION CHAMBER PLENUM CASE |           |             |            |                           |           |                        | Service ATA:72   |
| PN:3072443-5              | MOS                                                   | 22-Feb-10 |             |            |                           |           |                        |                  |
| SN:6-22151-4161           | HRS                                                   | 4129.9    | 2500 (+100) |            | (6629.9)<br>6626.7        | 6729.9    | 98.4 (+100)            |                  |
|                           | ENC                                                   | 2305      |             |            |                           |           |                        |                  |
| PROC. REF: LMM 72-40-04   |                                                       |           |             |            |                           |           | WO#: N950PC LH ENG MPI |                  |
| 724120                    | NO. 2 ENGINE - INSPECT COMBUSTION CHAMBER PLENUM CASE |           |             |            |                           |           |                        | Service ATA:72   |
| PN:3072443-5              | MOS                                                   | 04-May-15 |             |            |                           |           |                        |                  |
| SN:6-22151-3954           | HRS                                                   | 5125.6    | 2500 (+100) |            | (7625.6)<br>7706.7        | 7725.6    | 1178.4 (+100)          |                  |
|                           | ENC                                                   | 2873      |             |            |                           |           |                        |                  |
| PROC. REF: LMM 72-40-04   |                                                       |           |             |            |                           |           |                        |                  |
| 725010                    | NO. 1 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC      |           |             |            |                           |           |                        | Component ATA:72 |
| PN:3075446-2              | MOS                                                   | 02-Jul-96 |             |            |                           |           |                        | LIFE LIMIT       |
| SN:950322903586           | HRS                                                   | 0         |             | TSN 0      |                           |           |                        |                  |
| WC#: 72.040               | ENC                                                   | 0         | 10000       | TSN 0      | (10000)<br>9997           |           | 6068                   |                  |
| PROC. REF: GENERIC NO REF |                                                       |           |             |            |                           |           |                        |                  |
| 725010                    | NO. 2 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC      |           |             |            |                           |           |                        | Component ATA:72 |
| PN:70080021-2             | MOS                                                   | 04-May-15 |             | TSN 2      |                           |           |                        | LIFE LIMIT       |
| SN:14-156103-00184        | HRS                                                   | 5125.6    |             | TSN 0      |                           |           |                        |                  |
| WC#: 72.040               | ENC                                                   | 2873      | 10000       | TSN 0      | (12873)<br>12918          |           | 8989                   |                  |
| PROC. REF: GENERIC NO REF |                                                       |           |             |            |                           |           |                        |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                                             | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                  | Disposition      |
|---------------------------|--------------------------------------------------|-----------|----------|----------|---------------------------|-----------|----------------------------|------------------|
| ATA 72 - ENGINE           |                                                  |           |          |          |                           |           |                            |                  |
| 725020                    | NO. 1 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC |           |          |          |                           |           |                            | Component ATA:72 |
| PN:3075425-1              | MOS                                              | 02-Jul-96 |          |          |                           |           |                            | LIFE LIMIT       |
| SN:950322904335           | HRS                                              | 0         |          | TSN 0    |                           |           |                            |                  |
| WC#: 72.050               | ENC                                              | 0         | 10000    | TSN 0    | (10000)<br>9997           |           | 6068                       |                  |
| PROC. REF: GENERIC NO REF |                                                  |           |          |          |                           |           |                            |                  |
| 725020                    | NO. 2 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC |           |          |          |                           |           |                            | Component ATA:72 |
| PN:3075425-1              | MOS                                              | 21-Feb-96 |          |          |                           |           |                            | LIFE LIMIT       |
| SN:5-03229-3471           | HRS                                              | 0         |          | TSN 0    |                           |           |                            |                  |
| WC#: 72.050               | ENC                                              | 0         | 10000    | TSN 0    | (10000)<br>10045          |           | 6116                       |                  |
| PROC. REF: GENERIC NO REF |                                                  |           |          |          |                           |           |                            |                  |
|                           |                                                  |           |          |          |                           |           | WO#: N950PC RH ENG MPI/CZI |                  |
| 725030                    | NO. 1 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC |           |          |          |                           |           |                            | Component ATA:72 |
| PN:3075436-1              | MOS                                              | 02-Jul-96 |          |          |                           |           |                            | LIFE LIMIT       |
| SN:951217200924           | HRS                                              | 0         |          | TSN 0    |                           |           |                            |                  |
| WC#: 72.060               | ENC                                              | 0         | 10000    | TSN 0    | (10000)<br>9997           |           | 6068                       |                  |
| PROC. REF: GENERIC NO REF |                                                  |           |          |          |                           |           |                            |                  |
| 725030                    | NO. 2 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC |           |          |          |                           |           |                            | Component ATA:72 |
| PN:3075436-1              | MOS                                              | 21-Feb-96 |          |          |                           |           |                            | LIFE LIMIT       |
| SN:5-12172-899            | HRS                                              | 0         |          | TSN 0    |                           |           |                            |                  |
| WC#: 72.060               | ENC                                              | 0         | 10000    | TSN 0    | (10000)<br>10045          |           | 6116                       |                  |
| PROC. REF: GENERIC NO REF |                                                  |           |          |          |                           |           |                            |                  |
| 725040                    | NO. 1 ENGINE - HIGH PRESSURE TURBINE DISC        |           |          |          |                           |           |                            | Component ATA:72 |
| PN:3075227-2              | MOS                                              | 02-Jul-96 |          |          |                           |           |                            | LIFE LIMIT       |
| SN:5-12172-1069           | HRS                                              | 0         |          | TSN 0    |                           |           |                            |                  |
| WC#: 72.070               | ENC                                              | 0         | 10000    | TSN 0    | (10000)<br>9997           |           | 6068                       |                  |
| PROC. REF: LMM 72-50-06   |                                                  |           |          |          |                           |           |                            |                  |
| 725040                    | NO. 2 ENGINE - HIGH PRESSURE TURBINE DISC        |           |          |          |                           |           |                            | Component ATA:72 |
| PN:3075227-2              | MOS                                              | 21-Feb-96 |          |          |                           |           |                            | LIFE LIMIT       |
| SN:5-12172-0840           | HRS                                              | 0         |          | TSN 0    |                           |           |                            |                  |
| WC#: 72.070               | ENC                                              | 0         | 10000    | TSN 0    | (10000)<br>10045          |           | 6116                       |                  |
| PROC. REF: LMM 72-50-06   |                                                  |           |          |          |                           |           |                            |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                                                | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-----------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE           |                                                     |           |          |          |                           |           |           |                  |
| 725050                    | NO. 1 ENGINE - FAN DISC                             |           |          |          |                           |           |           | Component ATA:72 |
| PN:3074621-4              | MOS                                                 | 02-Jul-96 |          |          |                           |           |           | LIFE LIMIT       |
| SN:5-03229-5327           | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 72.080               | ENC                                                 | 0         | 10000    | TSN 0    | (10000)<br>9997           |           | 6068      |                  |
| PROC. REF: GENERIC NO REF |                                                     |           |          |          |                           |           |           |                  |
| 725050                    | NO. 2 ENGINE - FAN DISC                             |           |          |          |                           |           |           | Component ATA:72 |
| PN:3074621-4              | MOS                                                 | 21-Feb-96 |          |          |                           |           |           | LIFE LIMIT       |
| SN:5-03229-3891           | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 72.080               | ENC                                                 | 0         | 10000    | TSN 0    | (10000)<br>10045          |           | 6116      |                  |
| PROC. REF: GENERIC NO REF |                                                     |           |          |          |                           |           |           |                  |
| 725060                    | NO. 1 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC |           |          |          |                           |           |           | Component ATA:72 |
| PN:3072395-2              | MOS                                                 | 02-Jul-96 |          |          |                           |           |           | LIFE LIMIT       |
| SN:5-03160-3994           | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 72.090               | ENC                                                 | 0         | 10000    | TSN 0    | (10000)<br>9997           |           | 6068      |                  |
| PROC. REF: GENERIC NO REF |                                                     |           |          |          |                           |           |           |                  |
| 725060                    | NO. 2 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC |           |          |          |                           |           |           | Component ATA:72 |
| PN:3072395-2              | MOS                                                 | 21-Feb-96 |          |          |                           |           |           | LIFE LIMIT       |
| SN:5-03160-2477           | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 72.090               | ENC                                                 | 0         | 10000    | TSN 0    | (10000)<br>10045          |           | 6116      |                  |
| PROC. REF: GENERIC NO REF |                                                     |           |          |          |                           |           |           |                  |
| 725070                    | NO. 1 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC |           |          |          |                           |           |           | Component ATA:72 |
| PN:3072396-3              | MOS                                                 | 02-Jul-96 |          |          |                           |           |           | LIFE LIMIT       |
| SN:95031603494            | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 72.100               | ENC                                                 | 0         | 10000    | TSN 0    | (10000)<br>9997           |           | 6068      |                  |
| PROC. REF: GENERIC NO REF |                                                     |           |          |          |                           |           |           |                  |
| 725070                    | NO. 2 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC |           |          |          |                           |           |           | Component ATA:72 |
| PN:3072396-3              | MOS                                                 | 21-Feb-96 |          |          |                           |           |           | LIFE LIMIT       |
| SN:5-03160-3301           | HRS                                                 | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 72.100               | ENC                                                 | 0         | 10000    | TSN 0    | (10000)<br>10045          |           | 6116      |                  |
| PROC. REF: GENERIC NO REF |                                                     |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                                                | C/W       | Interval | TSX/Adj.       | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-----------------------------------------------------|-----------|----------|----------------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE           |                                                     |           |          |                |                           |           |           |                  |
| 725080                    | NO. 1 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC |           |          |                |                           |           |           | Component ATA:72 |
| PN:3072397-3              | MOS                                                 | 02-Jul-96 |          |                |                           |           |           | LIFE LIMIT       |
| SN:950316003897           | HRS                                                 | 0         |          | TSN 0          |                           |           |           |                  |
| WC#: 72.110               | ENC                                                 | 0         | 10000    | TSN 0          | (10000)<br>9997           |           | 6068      |                  |
| PROC. REF: GENERIC NO REF |                                                     |           |          |                |                           |           |           |                  |
| 725080                    | NO. 2 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC |           |          |                |                           |           |           | Component ATA:72 |
| PN:3072397-3              | MOS                                                 | 21-Feb-96 |          |                |                           |           |           | LIFE LIMIT       |
| SN:5-03160-2564           | HRS                                                 | 0         |          | TSN 0          |                           |           |           |                  |
| WC#: 72.110               | ENC                                                 | 0         | 10000    | TSN 0          | (10000)<br>10045          |           | 6116      |                  |
| PROC. REF: GENERIC NO REF |                                                     |           |          |                |                           |           |           |                  |
| 725090                    | NO. 1 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC |           |          |                |                           |           |           | Component ATA:72 |
| PN:3075326-3              | MOS                                                 | 02-Jul-96 |          |                |                           |           |           | LIFE LIMIT       |
| SN:960350100510           | HRS                                                 | 0         |          | TSN 0          |                           |           |           |                  |
| WC#: 72.120               | ENC                                                 | 0         | 20000    | TSN 0          | (20000)<br>19997          |           | 16068     |                  |
| PROC. REF: GENERIC NO REF |                                                     |           |          |                |                           |           |           |                  |
| 725090                    | NO. 2 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC |           |          |                |                           |           |           | Component ATA:72 |
| PN:3075326-3              | MOS                                                 | 21-Feb-96 |          |                |                           |           |           | LIFE LIMIT       |
| SN:5-03501-4476           | HRS                                                 | 0         |          | TSN 0          |                           |           |           |                  |
| WC#: 72.120               | ENC                                                 | 0         | 20000    | TSN 0          | (20000)<br>20045          |           | 16116     |                  |
| PROC. REF: GENERIC NO REF |                                                     |           |          |                |                           |           |           |                  |
| 725091                    | NO. 1 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD      |           |          |                |                           |           |           | Component ATA:72 |
| PN:3074744-1              | MOS/MSC                                             | 10-Oct-01 | O/C      | TSO 3          |                           |           |           |                  |
| SN:97P11467               | HRS                                                 | 2060      |          | TSN 686, TSO 0 |                           |           |           |                  |
| WC#: 72.130               | ENC                                                 | 1144      |          | TSN 398, TSO 0 |                           |           |           |                  |
| PROC. REF: LMM 72-30-10   |                                                     |           |          |                |                           |           |           |                  |
| 725091                    | NO. 2 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD      |           |          |                |                           |           |           | Component ATA:72 |
| PN:3074744-1              | MOS/MSC                                             | 04-May-15 | O/C      |                |                           |           |           |                  |
| SN:0P9935                 | HRS                                                 | 5125.6    |          | TSN 6034.9     |                           |           |           |                  |
| WC#: 72.130               | ENC                                                 | 2873      |          | TSN 3427       |                           |           |           |                  |
| PROC. REF: LMM 72-30-10   |                                                     |           |          |                |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                    | Unit                                                     | C/W       | Interval | TSX/Adj.   | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------|----------------------------------------------------------|-----------|----------|------------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE            |                                                          |           |          |            |                           |           |           |                  |
| 725110                     | NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR IMPELLER         |           |          |            |                           |           |           | Component ATA:72 |
| PN:3073398-2               | MOS                                                      | 02-Jul-96 |          |            |                           |           |           | LIFE LIMIT       |
| SN:952331501963            | HRS                                                      | 0         |          | TSN 0      |                           |           |           |                  |
| WC#: 72.140                | ENC                                                      | 0         | 10000    | TSN 0      | (10000)<br>9997           |           | 6068      |                  |
| PROC. REF: GENERIC NO REF  |                                                          |           |          |            |                           |           |           |                  |
| 725110                     | NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR IMPELLER         |           |          |            |                           |           |           | Component ATA:72 |
| PN:3073398-2               | MOS                                                      | 09-Feb-10 |          | TSN 165    |                           |           |           | LIFE LIMIT       |
| SN:5-23315-477             | HRS                                                      | 3970.1    |          | TSN 3970.1 |                           |           |           |                  |
| WC#: 72.140                | ENC                                                      | 2219      | 10000    | TSN 2219   | (10000)<br>10045          |           | 6116      |                  |
| PROC. REF: GENERIC NO REF  |                                                          |           |          |            |                           |           |           |                  |
| WO#: N950PC RH ENG MPI/CZI |                                                          |           |          |            |                           |           |           |                  |
| 725120                     | NO. 1 ENGINE - ROTATING AIR SEAL                         |           |          |            |                           |           |           | Component ATA:72 |
| PN:PN                      | MOS/MSC                                                  | 11-Nov-96 | O/C      | TSN 0      |                           |           |           |                  |
| SN:UNKNOWN                 | HRS                                                      | 20        |          | TSN 0      |                           |           |           |                  |
| WC#: 72.260                | ENC                                                      | 12        |          | TSN 0      |                           |           |           |                  |
| PROC. REF: GENERIC NO REF  |                                                          |           |          |            |                           |           |           |                  |
| 725120                     | NO. 2 ENGINE - ROTATING AIR SEAL                         |           |          |            |                           |           |           | Component ATA:72 |
| PN:PN                      | MOS/MSC                                                  | 30-May-96 | O/C      | TSN 0      |                           |           |           |                  |
| SN:UNKNOWN                 | HRS                                                      | 0         |          | TSN 0      |                           |           |           |                  |
| WC#: 72.260                | ENC                                                      | 0         |          | TSN 0      |                           |           |           |                  |
| PROC. REF: GENERIC NO REF  |                                                          |           |          |            |                           |           |           |                  |
| 725130                     | NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR SHOULDERED SHAFT |           |          |            |                           |           |           | Component ATA:72 |
| PN:3072545-1               | MOS                                                      | 02-Jul-96 |          |            |                           |           |           | LIFE LIMIT       |
| SN:96P10640                | HRS                                                      | 0         |          | TSN 0      |                           |           |           |                  |
| WC#: 72.150                | ENC                                                      | 0         | 12000    | TSN 0      | (12000)<br>11997          |           | 8068      |                  |
| PROC. REF: GENERIC NO REF  |                                                          |           |          |            |                           |           |           |                  |
| 725130                     | NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR SHOULDERED SHAFT |           |          |            |                           |           |           | Component ATA:72 |
| PN:3072545-1               | MOS                                                      | 21-Feb-96 |          |            |                           |           |           | LIFE LIMIT       |
| SN:960740400735            | HRS                                                      | 0         |          | TSN 0      |                           |           |           |                  |
| WC#: 72.150                | ENC                                                      | 0         | 12000    | TSN 0      | (12000)<br>12045          |           | 8116      |                  |
| PROC. REF: GENERIC NO REF  |                                                          |           |          |            |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                                                  | C/W       | Interval | TSX/Adj.   | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-------------------------------------------------------|-----------|----------|------------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE           |                                                       |           |          |            |                           |           |           |                  |
| 725140                    | NO. 1 ENGINE - HIGH PRESSURE TURBINE ROTOR SEAL PLATE |           |          |            |                           |           |           | Component ATA:72 |
| PN:3075579-1              | MOS                                                   | 02-Jul-96 |          |            |                           |           |           | LIFE LIMIT       |
| SN:950316003011           | HRS                                                   | 0         |          | TSN 0      |                           |           |           |                  |
| WC#: 72.160               | ENC                                                   | 0         | 30000    | TSN 0      | (30000)<br>29997          |           | 26068     |                  |
| PROC. REF: GENERIC NO REF |                                                       |           |          |            |                           |           |           |                  |
| 725140                    | NO. 2 ENGINE - HIGH PRESSURE TURBINE ROTOR SEAL PLATE |           |          |            |                           |           |           | Component ATA:72 |
| PN:3075579-1              | MOS                                                   | 21-Feb-96 |          |            |                           |           |           | LIFE LIMIT       |
| SN:4-03160-3044           | HRS                                                   | 0         |          | TSN 0      |                           |           |           |                  |
| WC#: 72.160               | ENC                                                   | 0         | 30000    | TSN 0      | (30000)<br>30045          |           | 26116     |                  |
| PROC. REF: GENERIC NO REF |                                                       |           |          |            |                           |           |           |                  |
| 725150                    | NO. 1 ENGINE - FAN DRIVE SHAFT                        |           |          |            |                           |           |           | Component ATA:72 |
| PN:3074641-3              | MOS/MSC                                               | 02-Jul-96 | O/C      |            |                           |           |           |                  |
| SN:96P09764               | HRS                                                   | 0         |          | TSN 0      |                           |           |           |                  |
| WC#: 72.170               | ENC                                                   | 0         |          | TSN 0      |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                       |           |          |            |                           |           |           |                  |
| 725150                    | NO. 2 ENGINE - FAN DRIVE SHAFT                        |           |          |            |                           |           |           | Component ATA:72 |
| PN:3074641-3              | MOS/MSC                                               | 21-Feb-96 | O/C      |            |                           |           |           |                  |
| SN:950740420575           | HRS                                                   | 0         |          | TSN 0      |                           |           |           |                  |
| WC#: 72.170               | ENC                                                   | 0         |          | TSN 0      |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                       |           |          |            |                           |           |           |                  |
| 725160                    | NO. 1 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT     |           |          |            |                           |           |           | Component ATA:72 |
| PN:3075292-4              | MOS/MSC                                               | 11-Feb-10 | O/C      |            |                           |           |           |                  |
| SN:04P06446               | HRS                                                   | 4129.9    |          | TSN 2152.6 |                           |           |           |                  |
| WC#: 72.180               | ENC                                                   | 2305      |          |            |                           |           |           |                  |
| PROC. REF: LMM 72-50-05   |                                                       |           |          |            |                           |           |           |                  |
| 725160                    | NO. 2 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT     |           |          |            |                           |           |           | Component ATA:72 |
| PN:3075292-4              | MOS/MSC                                               | 04-May-15 | O/C      |            |                           |           |           |                  |
| SN:07P01612               | HRS                                                   | 5125.6    |          |            |                           |           |           |                  |
| WC#: 72.180               | ENC                                                   | 2873      |          |            |                           |           |           |                  |
| PROC. REF: LMM 72-50-05   |                                                       |           |          |            |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                 | Unit                                                          | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-----------------------------------------|---------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 72 - ENGINE                         |                                                               |           |          |          |                           |           |           |                  |
| 725180                                  | NO. 1 ENGINE - STAGE 1 LOW PRESSURE TURBINE NOZZLE            |           |          |          |                           |           |           | Component ATA:72 |
| PN:3075406-6                            | MOS/MSC                                                       | 02-Jul-96 | O/C      |          |                           |           |           |                  |
| SN:96P06464                             | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 72.190                             | ENC                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF               |                                                               |           |          |          |                           |           |           |                  |
| 725180                                  | NO. 2 ENGINE - STAGE 1 LOW PRESSURE TURBINE NOZZLE            |           |          |          |                           |           |           | Component ATA:72 |
| PN:3075406-8                            | MOS/MSC                                                       | 21-Feb-96 | O/C      |          |                           |           |           |                  |
| SN:950740419911                         | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 72.190                             | ENC                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF               |                                                               |           |          |          |                           |           |           |                  |
| 725190                                  | NO. 1 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL         |           |          |          |                           |           |           | Component ATA:72 |
| PN:3073765-9                            | MOS/MSC                                                       | 02-Jul-96 | O/C      |          |                           |           |           |                  |
| SN:96P07088                             | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 72.200                             | ENC                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF               |                                                               |           |          |          |                           |           |           |                  |
| 725190                                  | NO. 2 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL         |           |          |          |                           |           |           | Component ATA:72 |
| PN:3073765-9                            | MOS/MSC                                                       | 21-Feb-96 | O/C      |          |                           |           |           |                  |
| SN:96074041023                          | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 72.200                             | ENC                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF               |                                                               |           |          |          |                           |           |           |                  |
| 725191                                  | NO. 1 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL SUPPORT |           |          |          |                           |           |           | Component ATA:72 |
| PN:3074052-1                            | MOS/MSC                                                       | 02-Jul-96 | O/C      |          |                           |           |           |                  |
| SN:96P09193                             | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 72.210                             | ENC                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF               |                                                               |           |          |          |                           |           |           |                  |
| 725191                                  | NO. 2 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL SUPPORT |           |          |          |                           |           |           | Component ATA:72 |
| PN:3074052-1                            | MOS/MSC                                                       | 21-Feb-96 | O/C      |          |                           |           |           |                  |
| SN:960740400239                         | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 72.210                             | ENC                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF               |                                                               |           |          |          |                           |           |           |                  |
| 725230                                  | NO. 1 ENGINE - FAN SPINNER                                    |           |          |          |                           |           |           | Component ATA:72 |
| PN:3074623-3                            | MOS/MSC                                                       | 02-Jul-96 | O/C      |          |                           |           |           |                  |
| SN:4-13262-244                          | HRS                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 72.220                             | ENC                                                           | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF, LMM 72-70-01 |                                                               |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                 | Unit                                     | C/W       | Interval    | TSX/Adj.   | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition                |
|-----------------------------------------|------------------------------------------|-----------|-------------|------------|---------------------------|-----------|---------------|----------------------------|
| ATA 72 - ENGINE                         |                                          |           |             |            |                           |           |               |                            |
| 725230                                  | NO. 2 ENGINE - FAN SPINNER               |           |             |            |                           |           |               | Component ATA:72           |
| PN:3074623-3                            | MOS/MSC                                  | 21-Feb-96 | O/C         |            |                           |           |               |                            |
| SN:961326200323                         | HRS                                      | 0         |             | TSN 0      |                           |           |               |                            |
| WC#: 72.220                             | ENC                                      | 0         |             | TSN 0      |                           |           |               |                            |
| PROC. REF: GENERIC NO REF, LMM 72-70-01 |                                          |           |             |            |                           |           |               |                            |
| 726110                                  | NO. 1 ENGINE - ACCESSORY GEARBOX         |           |             |            |                           |           |               | Component ATA:72           |
| PN:3070003-29                           | MOS/MSC                                  | 22-Feb-10 | O/C         |            |                           |           |               |                            |
| SN:S568                                 | HRS                                      | 4129.9    |             | TSN 4129.9 |                           |           |               |                            |
| WC#: 72.230                             | ENC                                      | 2305      |             | TSN 2305   |                           |           |               |                            |
| PROC. REF: LMM 72-60-02                 |                                          |           |             |            |                           |           |               |                            |
| 726110                                  | NO. 2 ENGINE - ACCESSORY GEARBOX         |           |             |            |                           |           |               | Component ATA:72           |
| PN:3070003-29                           | MOS/MSC                                  | 21-Feb-96 | O/C         |            |                           |           |               |                            |
| SN:S507                                 | HRS                                      | 0         |             | TSN 0      |                           |           |               |                            |
| WC#: 72.230                             | ENC                                      | 0         |             | TSN 0      |                           |           |               |                            |
| PROC. REF: LMM 72-60-02                 |                                          |           |             |            |                           |           |               | WO#: N950PC RH ENG MPI/CZI |
| 726120                                  | NO. 1 ENGINE - INSPECT ACCESSORY GEARBOX |           |             |            |                           |           |               | Service ATA:72             |
| PN:3070003-29                           | MOS                                      | 22-Feb-10 |             |            |                           |           |               |                            |
| SN:S568                                 | HRS                                      | 4129.9    | 5000 (+200) |            | (9129.9)<br>9126.7        | 9329.9    | 2598.4 (+200) |                            |
| WC#: 72.240                             | ENC                                      | 2305      |             |            |                           |           |               |                            |
| PROC. REF: LMM 72-60-02                 |                                          |           |             |            |                           |           |               |                            |
| 726120                                  | NO. 2 ENGINE - INSPECT ACCESSORY GEARBOX |           |             |            |                           |           |               | Service ATA:72             |
| PN:3070003-29                           | MOS                                      | 18-Jan-02 |             |            |                           |           |               |                            |
| SN:S507                                 | HRS                                      | 2057.3    | 5000 (+200) |            | (7057.3)<br>7138.4        | 7257.3    | 610.1 (+200)  |                            |
| WC#: 72.240                             | ENC                                      | 1144      |             |            |                           |           |               |                            |
| PROC. REF: LMM 72-60-02                 |                                          |           |             |            |                           |           |               | WO#: N950PC RH ENG MPI/CZI |
| 726130                                  | NO. 1 ENGINE - TRANSFER GEARBOX          |           |             |            |                           |           |               | Component ATA:72           |
| PN:3070093-12                           | MOS/MSC                                  | 02-Jul-96 | O/C         |            |                           |           |               |                            |
| SN:P8224                                | HRS                                      | 0         |             | TSN 0      |                           |           |               |                            |
| WC#: 72.250                             | ENC                                      | 0         |             | TSN 0      |                           |           |               |                            |
| PROC. REF: LMM 72-60-01                 |                                          |           |             |            |                           |           |               |                            |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                          | Unit                                        | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                           | Disposition      |
|----------------------------------|---------------------------------------------|-----------|---------------|----------|---------------------------|-----------|-------------------------------------|------------------|
| ATA 72 - ENGINE                  |                                             |           |               |          |                           |           |                                     |                  |
| 726130                           | NO. 2 ENGINE - TRANSFER GEARBOX             |           |               |          |                           |           |                                     | Component ATA:72 |
| PN:3070093-12                    | MOS/MSC                                     | 21-Feb-96 | O/C           |          |                           |           |                                     |                  |
| SN:P8106                         | HRS                                         | 0         |               | TSN 0    |                           |           |                                     |                  |
| WC#: 72.250                      | ENC                                         | 0         |               | TSN 0    |                           |           |                                     |                  |
| PROC. REF: LMM 72-60-01          |                                             |           |               |          |                           |           | WO#: N950PC RH ENG MPI/CZI          |                  |
| 726140                           | NO. 1 ENGINE - INSPECT TRANSFER GEARBOX     |           |               |          |                           |           |                                     | Service ATA:72   |
| PN:3070093-12                    | MOS/MSC                                     | 11-Nov-96 | O/C           |          |                           |           |                                     |                  |
| SN:P8224                         | HRS                                         | 20        |               |          |                           |           |                                     |                  |
| WC#: 72.280                      | ENC                                         | 12        |               |          |                           |           |                                     |                  |
| PROC. REF: LMM 72-00-00          |                                             |           |               |          |                           |           |                                     |                  |
| 726140                           | NO. 2 ENGINE - INSPECT TRANSFER GEARBOX     |           |               |          |                           |           |                                     | Service ATA:72   |
| PN:3070093-12                    | MOS/MSC                                     | 30-May-96 | O/C           |          |                           |           |                                     |                  |
| SN:P8106                         | HRS                                         | 0         |               |          |                           |           |                                     |                  |
| WC#: 72.250                      | ENC                                         | 0         |               |          |                           |           |                                     |                  |
| PROC. REF: LMM 72-00-00          |                                             |           |               |          |                           |           | WO#: N950PC RH ENG MPI/CZI          |                  |
| 727110                           | NO. 1 ENGINE - INSPECT FAN SUPPORT ASSEMBLY |           |               |          |                           |           |                                     | Service ATA:72   |
|                                  | MOS                                         | 22-Feb-10 |               |          |                           |           |                                     |                  |
|                                  | HRS                                         | 4129.9    | 5000 (+200)   |          | (9129.9)<br>9126.7        | 9329.9    | 2598.4 (+200)                       |                  |
| WC#: 72.270                      | ENC                                         | 2305      |               |          |                           |           |                                     |                  |
| PROC. REF: LMM 72-70-06          |                                             |           |               |          |                           |           |                                     |                  |
| 727110                           | NO. 2 ENGINE - INSPECT FAN SUPPORT ASSEMBLY |           |               |          |                           |           |                                     | Service ATA:72   |
|                                  | MOS                                         | 18-Jan-02 |               |          |                           |           |                                     |                  |
|                                  | HRS                                         | 2057.3    | 5000 (+200)   |          | (7057.3)<br>7138.4        | 7257.3    | 610.1 (+200)                        |                  |
| WC#: 72.270                      | ENC                                         | 1144      |               |          |                           |           |                                     |                  |
| PROC. REF: LMM 72-70-06          |                                             |           |               |          |                           |           | WO#: N950PC RH ENG MPI/CZI          |                  |
| ATA 73 - ENGINE FUEL AND CONTROL |                                             |           |               |          |                           |           |                                     |                  |
| 730001                           | DRAIN PT2 PIPELINES TO FUEL COMPUTERS       |           |               |          |                           |           |                                     | Service ATA:73   |
|                                  | MOS                                         | 15-Oct-19 |               |          |                           |           |                                     |                  |
|                                  | HRS                                         | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)                            |                  |
| WC#: 73.050                      | AFL                                         | 3397      |               |          |                           |           |                                     |                  |
| PROC. REF: AFMS INSPECTION B7    |                                             |           |               |          |                           |           | PKG:2,14<br>WO#: N950PC B & C CHECK |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                               | Unit                                                  | C/W       | Interval   | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                           | Disposition      |
|---------------------------------------|-------------------------------------------------------|-----------|------------|----------|---------------------------|-----------|-------------------------------------|------------------|
| ATA 73 - ENGINE FUEL AND CONTROL      |                                                       |           |            |          |                           |           |                                     |                  |
| 730051 <sup>U</sup>                   | LEFT ENGINE FUEL FILTER                               |           |            |          |                           |           |                                     | Component ATA:73 |
| PN:PN                                 | MOS/MSC                                               | 30-May-96 | O/C        |          |                           |           |                                     |                  |
| SN:UNKNOWN                            | HRS                                                   | 0         |            |          |                           |           |                                     |                  |
|                                       | AFL                                                   | 0         |            |          |                           |           |                                     |                  |
| 730052 <sup>U</sup>                   | RIGHT ENGINE FUEL FILTER                              |           |            |          |                           |           |                                     | Component ATA:73 |
| PN:PN                                 | MOS/MSC                                               | 30-May-96 | O/C        |          |                           |           |                                     |                  |
| SN:UNKNOWN                            | HRS                                                   | 0         |            |          |                           |           |                                     |                  |
|                                       | AFL                                                   | 0         |            |          |                           |           |                                     |                  |
| 731110                                | NO. 1 ENGINE - FUEL PUMP                              |           |            |          |                           |           |                                     | Component ATA:73 |
| PN:3060710-16                         | MOS/MSC                                               | 02-Jul-96 | O/C        |          |                           |           |                                     |                  |
| SN:0160                               | HRS                                                   | 0         |            | TSN 0    |                           |           |                                     |                  |
| WC#: 73.010                           | ENC                                                   | 0         |            | TSN 0    |                           |           |                                     |                  |
| PROC. REF: LMM 73-20-01, LMM 73-21-02 |                                                       |           |            |          |                           |           |                                     |                  |
| 731110                                | NO. 2 ENGINE - FUEL PUMP                              |           |            |          |                           |           |                                     | Component ATA:73 |
| PN:3060710-16                         | MOS/MSC                                               | 21-Feb-96 | O/C        |          |                           |           |                                     |                  |
| SN:0138                               | HRS                                                   | 0         |            | TSN 0    |                           |           |                                     |                  |
| WC#: 73.010                           | ENC                                                   | 0         |            | TSN 0    |                           |           |                                     |                  |
| PROC. REF: LMM 73-20-01, LMM 73-21-02 |                                                       |           |            |          |                           |           | WO#: N950PC RH ENG MPI/CZI          |                  |
| 731120                                | NO. 1 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT |           |            |          |                           |           |                                     | Service ATA:73   |
|                                       | MOS                                                   | 11-Oct-22 |            |          |                           |           |                                     |                  |
|                                       | HRS                                                   | 6450.1    | 300 (+100) |          | (6750.1)<br>6746.9        | 6850.1    | 218.6 (+100)                        |                  |
| WC#: 73.010                           | ENC                                                   | 3876      |            |          |                           |           |                                     |                  |
| PROC. REF: LMM 73-21-02, LMM 73-21-02 |                                                       |           |            |          |                           |           | PKG:2<br>WO#: N950PC LH ENG MPI     |                  |
| 731120                                | NO. 2 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT |           |            |          |                           |           |                                     | Service ATA:73   |
|                                       | MOS                                                   | 11-Oct-22 |            |          |                           |           |                                     |                  |
|                                       | HRS                                                   | 6365.3    | 300 (+100) |          | (6665.3)<br>6746.4        | 6765.3    | 218.1 (+100)                        |                  |
| WC#: 73.010                           | ENC                                                   | 3828      |            |          |                           |           |                                     |                  |
| PROC. REF: LMM 73-21-02, LMM 73-21-02 |                                                       |           |            |          |                           |           | PKG:2<br>WO#: N950PC RH ENG MPI/CZI |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                          | Unit                                                             | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                           | Disposition      |
|----------------------------------|------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-------------------------------------|------------------|
| ATA 73 - ENGINE FUEL AND CONTROL |                                                                  |           |          |          |                           |           |                                     |                  |
| 731130                           | NO. 1 ENGINE - FLOW DIVIDER/DRAIN VALVE                          |           |          |          |                           |           |                                     | Component ATA:73 |
| PN:PN                            | MOS/MSC                                                          | 11-Nov-96 | O/C      | TSN 0    |                           |           |                                     |                  |
| SN:UNKNOWN                       | HRS                                                              | 20        |          | TSN 0    |                           |           |                                     |                  |
| WC#: 73.030                      | ENC                                                              | 12        |          | TSN 0    |                           |           |                                     |                  |
| PROC. REF: GENERIC NO REF        |                                                                  |           |          |          |                           |           |                                     |                  |
| 731130                           | NO. 2 ENGINE - FLOW DIVIDER/DRAIN VALVE                          |           |          |          |                           |           |                                     | Component ATA:73 |
| PN:394396-2-1                    | MOS/MSC                                                          | 30-May-96 | O/C      | TSN 0    |                           |           |                                     |                  |
| SN:UNKNOWN                       | HRS                                                              | 0         |          | TSN 0    |                           |           |                                     |                  |
| WC#: 73.030                      | ENC                                                              | 0         |          | TSN 0    |                           |           |                                     |                  |
| PROC. REF: GENERIC NO REF        |                                                                  |           |          |          |                           |           | WO#: N950PC RH ENG MPI/CZI          |                  |
| 731140                           | NO. 1 ENGINE - FUEL HEATER                                       |           |          |          |                           |           |                                     | Component ATA:73 |
| PN:158670-5                      | MOS/MSC                                                          | 02-Jul-96 | O/C      |          |                           |           |                                     |                  |
| SN:16-6880                       | HRS                                                              | 0         |          | TSN 0    |                           |           |                                     |                  |
| WC#: 73.040                      | ENC                                                              | 0         |          | TSN 0    |                           |           |                                     |                  |
| PROC. REF: LMM 73-10-04          |                                                                  |           |          |          |                           |           |                                     |                  |
| 731140                           | NO. 2 ENGINE - FUEL HEATER                                       |           |          |          |                           |           |                                     | Component ATA:73 |
| PN:158670-5                      | MOS/MSC                                                          | 21-Feb-96 | O/C      |          |                           |           |                                     |                  |
| SN:15-6621                       | HRS                                                              | 0         |          | TSN 0    |                           |           |                                     |                  |
| WC#: 73.040                      | ENC                                                              | 0         |          | TSN 0    |                           |           |                                     |                  |
| PROC. REF: LMM 73-10-04          |                                                                  |           |          |          |                           |           |                                     |                  |
| 731150                           | NO. 1 ENGINE - CHECK FUEL HEATER OIL TUBES (FLUID TRANSFER TUBE) |           |          |          |                           |           |                                     | Service ATA:73   |
|                                  | MOS                                                              | 11-Oct-22 |          |          |                           |           |                                     |                  |
|                                  | HRS                                                              | 6450.1    | 800      |          | (7250.1)<br>7246.9        |           | 718.6                               |                  |
| WC#: 73.050                      | ENC                                                              | 3876      |          |          |                           |           |                                     |                  |
| PROC. REF: LMM 79-20-06          |                                                                  |           |          |          |                           |           | PKG:4<br>WO#: N950PC LH ENG MPI     |                  |
| 731150                           | NO. 2 ENGINE - CHECK FUEL HEATER OIL TUBES (FLUID TRANSFER TUBE) |           |          |          |                           |           |                                     | Service ATA:73   |
|                                  | MOS                                                              | 11-Oct-22 |          |          |                           |           |                                     |                  |
|                                  | HRS                                                              | 6365.3    | 800      |          | (7165.3)<br>7246.4        |           | 718.1                               |                  |
| WC#: 73.050                      | ENC                                                              | 3828      |          |          |                           |           |                                     |                  |
| PROC. REF: LMM 79-20-06          |                                                                  |           |          |          |                           |           | PKG:4<br>WO#: N950PC RH ENG MPI/CZI |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                          | Unit                                        | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|----------------------------------|---------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 73 - ENGINE FUEL AND CONTROL |                                             |           |          |          |                           |           |           |                  |
| 731160                           | NO. 1 ENGINE - FUEL HEATER CHECK VALVE      |           |          |          |                           |           |           | Component ATA:73 |
| PN:PN                            | MOS/MSC                                     | 11-Nov-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                       | HRS                                         | 20        |          | TSN 0    |                           |           |           |                  |
| WC#: 73.060                      | ENC                                         | 12        |          | TSN 0    |                           |           |           |                  |
| PROC. REF: LMM 73-10-04          |                                             |           |          |          |                           |           |           |                  |
| 731160                           | NO. 2 ENGINE - FUEL HEATER CHECK VALVE      |           |          |          |                           |           |           | Component ATA:73 |
| PN:3073932-4                     | MOS/MSC                                     | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                       | HRS                                         | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 73.060                      | ENC                                         | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: LMM 73-10-04          |                                             |           |          |          |                           |           |           |                  |
| 732025                           | NO. 1 ENGINE LOW FUEL PRESSURE SWITCH       |           |          |          |                           |           |           | Component ATA:73 |
| PN:HTE690014/1                   | MOS/MSC                                     | 11-Nov-96 | O/C      |          |                           |           |           |                  |
| SN:FRTR006AT                     | HRS                                         | 20        |          | TSN 23   |                           |           |           |                  |
| WC#: 73.020                      | AFL                                         |           |          |          |                           |           |           |                  |
| PROC. REF: AMM 73-32-11          |                                             |           |          |          |                           |           |           |                  |
| 732026                           | NO. 2 ENGINE LOW FUEL PRESSURE SWITCH       |           |          |          |                           |           |           | Component ATA:73 |
| PN:HTE690014-1                   | MOS/MSC                                     | 21-Feb-96 | O/C      |          |                           |           |           |                  |
| SN:FRTR003AT                     | HRS                                         | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 73.020                      | AFL                                         | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 73-32-11          |                                             |           |          |          |                           |           |           |                  |
| 732037                           | NO. 1 ENGINE FUEL FILTER TEMPERATURE SWITCH |           |          |          |                           |           |           | Component ATA:73 |
| PN:HE60010                       | MOS/MSC                                     | 11-Nov-96 | O/C      |          |                           |           |           |                  |
| SN:0651TW                        | HRS                                         | 20        |          | TSN 23   |                           |           |           |                  |
| WC#: 73.025                      | AFL                                         |           |          |          |                           |           |           |                  |
| PROC. REF: AMM 73-33-11          |                                             |           |          |          |                           |           |           |                  |
| 732038                           | NO. 2 ENGINE FUEL FILTER TEMPERATURE SWITCH |           |          |          |                           |           |           | Component ATA:73 |
| PN:HE60010                       | MOS/MSC                                     | 10-Oct-01 | O/C      |          |                           |           |           |                  |
| SN:LOANER                        | HRS                                         | 2057      |          |          |                           |           |           |                  |
| WC#: 73.025                      | AFL                                         | 1144      |          |          |                           |           |           |                  |
| PROC. REF: AMM 73-33-11          |                                             |           |          |          |                           |           |           |                  |
| 732109                           | ENGINE FUEL SYNCHRONIZER                    |           |          |          |                           |           |           | Component ATA:73 |
| PN:2118756-1                     | MOS/MSC                                     | 04-Apr-08 | O/C      |          |                           |           |           |                  |
| SN:64-B0076                      | HRS                                         | 3684.8    |          |          |                           |           |           |                  |
| WC#: 73.035                      | AFL                                         | 2066      |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                          | Unit                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                  | Disposition      |
|----------------------------------|---------------------------------------|-----------|----------|----------|---------------------------|-----------|----------------------------|------------------|
| ATA 73 - ENGINE FUEL AND CONTROL |                                       |           |          |          |                           |           |                            |                  |
| 732110                           | NO. 1 ENGINE - FUEL CONTROL UNIT      |           |          |          |                           |           |                            | Component ATA:73 |
| PN:3070800-26                    | MOS/MSC                               | 15-Mar-10 | O/C      | TSO 0    |                           |           |                            |                  |
| SN:A8933C                        | HRS                                   | 4152.5    |          | TSO 0    |                           |           |                            |                  |
| WC#: 73.070                      | ENC                                   | 2317      |          | TSO 0    |                           |           |                            |                  |
| PROC. REF: LMM 73-20-01          |                                       |           |          |          |                           |           |                            |                  |
| 732110                           | NO. 2 ENGINE - FUEL CONTROL UNIT      |           |          |          |                           |           |                            | Component ATA:73 |
| PN:3070800-35                    | MOS/MSC                               | 10-Apr-08 | O/C      |          |                           |           |                            |                  |
| SN:A7975C                        | HRS                                   | 3604.9    |          |          |                           |           |                            |                  |
| WC#: 73.070                      | ENC                                   | 2022      |          |          |                           |           |                            |                  |
| PROC. REF: LMM 73-20-01          |                                       |           |          |          |                           |           | WO#: N950PC RH ENG MPI/CZI |                  |
| 732120                           | NO. 1 ENGINE - PRESSURE LIMITER VALVE |           |          |          |                           |           |                            | Component ATA:73 |
| PN:PN                            | MOS/MSC                               | 11-Nov-96 | O/C      | TSN 0    |                           |           |                            |                  |
| SN:UNKNOWN                       | HRS                                   | 20        |          | TSN 0    |                           |           |                            |                  |
| WC#: 73.080                      | ENC                                   | 12        |          | TSN 0    |                           |           |                            |                  |
| PROC. REF: GENERIC NO REF        |                                       |           |          |          |                           |           |                            |                  |
| 732120                           | NO. 2 ENGINE - PRESSURE LIMITER VALVE |           |          |          |                           |           |                            | Component ATA:73 |
| PN:3070685-6                     | MOS/MSC                               | 30-May-96 | O/C      | TSN 0    |                           |           |                            |                  |
| SN:UNKNOWN                       | HRS                                   | 0         |          | TSN 0    |                           |           |                            |                  |
| WC#: 73.080                      | ENC                                   | 0         |          | TSN 0    |                           |           |                            |                  |
| PROC. REF: GENERIC NO REF        |                                       |           |          |          |                           |           |                            |                  |
| 732160                           | NO. 1 ENGINE - FUEL FLOW TRANSMITTER  |           |          |          |                           |           |                            | Component ATA:73 |
| PN:9-127-55                      | MOS/MSC                               | 02-Jul-96 | O/C      |          |                           |           |                            |                  |
| SN:7802                          | HRS                                   | 0         |          | TSN 0    |                           |           |                            |                  |
| WC#: 73.090                      | ENC                                   | 0         |          | TSN 0    |                           |           |                            |                  |
| PROC. REF: GENERIC NO REF        |                                       |           |          |          |                           |           |                            |                  |
| 732160                           | NO. 2 ENGINE - FUEL FLOW TRANSMITTER  |           |          |          |                           |           |                            | Component ATA:73 |
| PN:9-127-55                      | MOS/MSC                               | 21-Feb-96 | O/C      |          |                           |           |                            |                  |
| SN:7630                          | HRS                                   | 0         |          | TSN 0    |                           |           |                            |                  |
| WC#: 73.090                      | ENC                                   | 0         |          | TSN 0    |                           |           |                            |                  |
| PROC. REF: GENERIC NO REF        |                                       |           |          |          |                           |           |                            |                  |
| 733001                           | NO. 1 ENGINE FUEL FLOW TRANSMITTER    |           |          |          |                           |           |                            | Component ATA:73 |
| PN:PN                            | MOS/MSC                               | 30-May-96 | O/C      | TSN 0    |                           |           |                            |                  |
| SN:UNKNOWN                       | HRS                                   | 0         |          | TSN 0    |                           |           |                            |                  |
| WC#: 73.040                      | AFL                                   | 0         |          | TSN 0    |                           |           |                            |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                          | Unit                                             | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition                     |
|----------------------------------|--------------------------------------------------|-----------|-------------|----------|---------------------------|-----------|---------------|---------------------------------|
| ATA 73 - ENGINE FUEL AND CONTROL |                                                  |           |             |          |                           |           |               |                                 |
| 733002                           | NO. 2 ENGINE FUEL FLOW TRANSMITTER               |           |             |          |                           |           |               | Component ATA:73                |
| PN:PN                            | MOS/MSC                                          | 30-May-96 | O/C         | TSN 0    |                           |           |               |                                 |
| SN:UNKNOWN                       | HRS                                              | 0         |             | TSN 0    |                           |           |               |                                 |
| WC#: 73.040                      | AFL                                              | 0         |             | TSN 0    |                           |           |               |                                 |
| 733013                           | NO. 1 ENGINE FUEL FLOW INDICATOR                 |           |             |          |                           |           |               | Component ATA:73                |
| PN:9-328-26                      | MOS/MSC                                          | 30-May-96 | O/C         |          |                           |           |               |                                 |
| SN:3276                          | HRS                                              | 0         |             | TSN 0    |                           |           |               |                                 |
| WC#: 73.045                      | AFL                                              | 0         |             |          |                           |           |               |                                 |
| 733014                           | NO. 2 ENGINE FUEL FLOW INDICATOR                 |           |             |          |                           |           |               | Component ATA:73                |
| PN:9-328-26                      | MOS/MSC                                          | 23-Jan-01 | O/C         | TSO 2    |                           |           |               |                                 |
| SN:1820                          | HRS                                              | 1822      |             | TSO 0    |                           |           |               |                                 |
| WC#: 73.045                      | AFL                                              | 982       |             | TSO 0    |                           |           |               |                                 |
| ATA 74 - IGNITION                |                                                  |           |             |          |                           |           |               |                                 |
| 741110                           | NO. 1 ENGINE - IGNITION UNIT                     |           |             |          |                           |           |               | Component ATA:74                |
| PN:3073914-4                     | MOS/MSC                                          | 02-Oct-13 | O/C         | TSO 0    |                           |           |               |                                 |
| SN:95193008                      | HRS                                              | 5015      |             | TSO 0    |                           |           |               |                                 |
| WC#: 74.010                      | ENC                                              | 2807      |             | TSO 0    |                           |           |               |                                 |
| PROC. REF: LMM 74-00-01          |                                                  |           |             |          |                           |           |               |                                 |
| 741110                           | NO. 2 ENGINE - IGNITION UNIT                     |           |             |          |                           |           |               | Component ATA:74                |
| PN:3073914-1                     | MOS/MSC                                          | 31-Jan-07 | O/C         |          |                           |           |               |                                 |
| SN:95193014                      | HRS                                              | 3296.4    |             |          |                           |           |               |                                 |
| WC#: 74.010                      | ENC                                              | 1854      |             |          |                           |           |               |                                 |
| PROC. REF: LMM 74-00-01          |                                                  |           |             |          |                           |           |               |                                 |
| 741120                           | NO. 1 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM |           |             |          |                           |           |               | Service ATA:74                  |
|                                  | MOS                                              | 10-Oct-22 |             |          |                           |           |               |                                 |
|                                  | HRS                                              | 6450.1    | 1200 (+200) |          | (7650.1)<br>7646.9        | 7850.1    | 1118.6 (+200) |                                 |
| WC#: 74.010                      | ENC                                              | 3876      |             |          |                           |           |               |                                 |
| PROC. REF: LMM 74-00-01          |                                                  |           |             |          |                           |           |               |                                 |
|                                  |                                                  |           |             |          |                           |           |               | PKG:0<br>WO#: N950PC LH ENG MPI |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                 | Unit                                                                        | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition                         |
|-------------------------|-----------------------------------------------------------------------------|-----------|-------------|----------|---------------------------|-----------|---------------|-------------------------------------|
| ATA 74 - IGNITION       |                                                                             |           |             |          |                           |           |               |                                     |
| 741120                  | NO. 2 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM                            |           |             |          |                           |           |               | Service ATA:74                      |
|                         | MOS                                                                         | 10-Oct-22 |             |          |                           |           |               |                                     |
|                         | HRS                                                                         | 6365.3    | 1200 (+200) |          | (7565.3)<br>7646.4        | 7765.3    | 1118.1 (+200) |                                     |
| WC#: 74.010             | ENC                                                                         | 3828      |             |          |                           |           |               |                                     |
| PROC. REF: LMM 74-00-01 |                                                                             |           |             |          |                           |           |               | PKG:0<br>WO#: N950PC RH ENG MPI/CZI |
| 742110                  | NO. 1 ENGINE - 6 O'CLOCK IGNITOR PLUG                                       |           |             |          |                           |           |               | Component ATA:74                    |
| PN:CH31815              | MOS/MSC                                                                     | 28-Jan-00 | O/C         |          |                           |           |               |                                     |
| SN:UNKNOWN              | HRS                                                                         | 1340      |             |          |                           |           |               |                                     |
| WC#: 74.030             | ENC                                                                         |           |             |          |                           |           |               |                                     |
| PROC. REF: LMM 74-00-01 |                                                                             |           |             |          |                           |           |               |                                     |
| 742110                  | NO. 2 ENGINE - 6 O'CLOCK IGNITOR PLUG                                       |           |             |          |                           |           |               | Component ATA:74                    |
| PN:CH31815              | MOS/MSC                                                                     | 28-Jan-00 | O/C         |          |                           |           |               |                                     |
| SN:UNKNOWN              | HRS                                                                         | 1337      |             |          |                           |           |               |                                     |
| WC#: 74.030             | ENC                                                                         |           |             |          |                           |           |               |                                     |
| PROC. REF: LMM 74-00-01 |                                                                             |           |             |          |                           |           |               |                                     |
| 742120                  | NO. 1 ENGINE - REMOVE AND INSPECT 6 O'CLOCK IGNITER PLUG AND LEADS IN PLACE |           |             |          |                           |           |               | Service ATA:74                      |
|                         | MOS                                                                         | 04-May-15 |             |          |                           |           |               |                                     |
|                         | HRS                                                                         | 5125      | 1600        |          | (6725)<br>6721.8          |           | 193.5         |                                     |
| WC#: 74.030             | ENC                                                                         | 2873      |             |          |                           |           |               |                                     |
| PROC. REF: LMM 74-00-01 |                                                                             |           |             |          |                           |           |               | PKG:5<br>WO#: N950PC LH ENG MPI     |
| 742120                  | NO. 2 ENGINE - REMOVE AND INSPECT 6 O'CLOCK IGNITER PLUG AND LEADS IN PLACE |           |             |          |                           |           |               | Service ATA:74                      |
|                         | MOS                                                                         | 04-May-15 |             |          |                           |           |               |                                     |
|                         | HRS                                                                         | 5125.6    | 1600        |          | (6725.6)<br>6806.7        |           | 278.4         |                                     |
| WC#: 74.030             | ENC                                                                         | 2873      |             |          |                           |           |               |                                     |
| PROC. REF: LMM 74-00-01 |                                                                             |           |             |          |                           |           |               | PKG:5<br>WO#: N950PC RH ENG MPI/CZI |
| 742130                  | NO. 1 ENGINE - 7 O'CLOCK IGNITOR PLUG                                       |           |             |          |                           |           |               | Component ATA:74                    |
| PN:3070967-1            | MOS/MSC                                                                     | 02-Jul-96 | O/C         |          |                           |           |               |                                     |
| SN:UNKNOWN              | HRS                                                                         | 0         |             |          |                           |           |               |                                     |
| WC#: 74.050             | ENC                                                                         | 0         |             |          |                           |           |               |                                     |
| PROC. REF: LMM 74-00-01 |                                                                             |           |             |          |                           |           |               |                                     |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                 | Unit                                                                        | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                           | Disposition      |
|-------------------------|-----------------------------------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-------------------------------------|------------------|
| ATA 74 - IGNITION       |                                                                             |           |          |          |                           |           |                                     |                  |
| 742130                  | NO. 2 ENGINE - 7 O'CLOCK IGNITOR PLUG                                       |           |          |          |                           |           |                                     | Component ATA:74 |
| PN:3070967-1            | MOS/MSC                                                                     | 21-Feb-96 | O/C      |          |                           |           |                                     |                  |
| SN:UNKNOWN              | HRS                                                                         | 0         |          | TSN 0    |                           |           |                                     |                  |
| WC#: 74.050             | ENC                                                                         | 0         |          | TSN 0    |                           |           |                                     |                  |
| PROC. REF: LMM 74-00-01 |                                                                             |           |          |          |                           |           |                                     |                  |
| 742140                  | NO. 1 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEADS IN PLACE |           |          |          |                           |           |                                     | Service ATA:74   |
|                         | MOS                                                                         | 04-May-15 |          |          |                           |           |                                     |                  |
|                         | HRS                                                                         | 5125      | 1600     |          | (6725)<br>6721.8          |           | 193.5                               |                  |
| WC#: 74.050             | ENC                                                                         | 2873      |          |          |                           |           |                                     |                  |
| PROC. REF: LMM 74-00-01 |                                                                             |           |          |          |                           |           |                                     |                  |
| 742140                  | NO. 2 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEADS IN PLACE |           |          |          |                           |           |                                     | Service ATA:74   |
|                         | MOS                                                                         | 04-May-15 |          |          |                           |           |                                     |                  |
|                         | HRS                                                                         | 5125.6    | 1600     |          | (6725.6)<br>6806.7        |           | 278.4                               |                  |
| WC#: 74.050             | ENC                                                                         | 2873      |          |          |                           |           |                                     |                  |
| PROC. REF: LMM 74-00-01 |                                                                             |           |          |          |                           |           |                                     |                  |
|                         |                                                                             |           |          |          |                           |           | PKG:5<br>WO#: N950PC LH ENG MPI     |                  |
|                         |                                                                             |           |          |          |                           |           | PKG:5<br>WO#: N950PC RH ENG MPI/CZI |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                                             | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|--------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 75 - AIR              |                                                  |           |          |          |                           |           |           |                  |
| 750130                    | NO. 2 ENGINE - INLET PRESSURE/TEMPERATURE SENSOR |           |          |          |                           |           |           | Component ATA:75 |
| PN:3070816-4              | MOS/MSC                                          | 15-Sep-12 | O/C      |          |                           |           |           |                  |
| SN:1216901765114          | HRS                                              | 4719.1    |          |          |                           |           |           |                  |
| WC#: 75.010               | ENC                                              | 2645      |          |          |                           |           |           |                  |
| PROC. REF: LMM 75-40-01   |                                                  |           |          |          |                           |           |           |                  |
| 751010                    | NO. 1 ENGINE - ANTI-ICE VALVE                    |           |          |          |                           |           |           | Component ATA:75 |
| PN:F10A-5-SCP-102-5       | MOS/MSC                                          | 02-Jul-96 | O/C      |          |                           |           |           |                  |
| SN:IIALIO                 | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 75.020               | ENC                                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                  |           |          |          |                           |           |           |                  |
| 751010                    | NO. 2 ENGINE - ANTI-ICE VALVE                    |           |          |          |                           |           |           | Component ATA:75 |
| PN:F10A-5-SCP-102-5       | MOS/MSC                                          | 21-Feb-96 | O/C      |          |                           |           |           |                  |
| SN:11AL11                 | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 75.020               | ENC                                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                                  |           |          |          |                           |           |           |                  |
| 751013                    | NO. 1 ENGINE THERMAL ANTI-ICE VALVE              |           |          |          |                           |           |           | Component ATA:75 |
| PN:PN                     | MOS/MSC                                          | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 75.020               | AFL                                              | 0         |          | TSN 0    |                           |           |           |                  |
| 751014                    | NO. 2 ENGINE THERMAL ANTI-ICE VALVE              |           |          |          |                           |           |           | Component ATA:75 |
| PN:PN                     | MOS/MSC                                          | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 75.021               | AFL                                              | 0         |          | TSN 0    |                           |           |           |                  |
| 754010                    | NO. 1 ENGINE ANTI-ICE PRESSURE SWITCH            |           |          |          |                           |           |           | Component ATA:75 |
| PN:HE12423                | MOS/MSC                                          | 11-Nov-96 | O/C      |          |                           |           |           |                  |
| SN:1841TW                 | HRS                                              | 20        |          | TSN 23   |                           |           |           |                  |
| WC#: 75.015               | AFL                                              |           |          |          |                           |           |           |                  |
| PROC. REF: AMM 75-40-11   |                                                  |           |          |          |                           |           |           |                  |
| 754011                    | NO. 2 ENGINE ANTI-ICE PRESSURE SWITCH            |           |          |          |                           |           |           | Component ATA:75 |
| PN:HE12423                | MOS/MSC                                          | 21-Feb-96 | O/C      |          |                           |           |           |                  |
| SN:1842TW                 | HRS                                              | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 75.015               | AFL                                              | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 75-40-11   |                                                  |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                     | Unit                                                                         | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                           | Disposition      |
|---------------------------------------------|------------------------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-------------------------------------|------------------|
| ATA 76 - ENGINE CONTROLS                    |                                                                              |           |                |          |                           |           |                                     |                  |
| 760001                                      | CHECK THROTTLE LEVER CONTROLS                                                |           |                |          |                           |           |                                     | Service ATA:76   |
|                                             | MOS                                                                          | 15-Oct-19 |                |          |                           |           |                                     |                  |
|                                             | HRS                                                                          | 5795.3    | 800 (+40/-10)  |          | 6595.3                    | 6635.3    | 67 (+40)                            |                  |
| WC#: 76.030                                 | AFL                                                                          | 3397      |                |          |                           |           |                                     |                  |
| PROC. REF: AFMS INSPECTION B4, AMM 27-72-00 |                                                                              |           |                |          |                           |           | PKG:2,11<br>WO#: N950PC B & C CHECK |                  |
| 760002                                      | CHECK ENGINE POWER CONTROL CABLES                                            |           |                |          |                           |           |                                     | Service ATA:76   |
|                                             | MOS                                                                          | 06-May-15 |                |          |                           |           |                                     |                  |
|                                             | HRS                                                                          | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50)                         |                  |
| WC#: 76.010                                 | AFL                                                                          | 2873      |                |          |                           |           |                                     |                  |
| PROC. REF: AFMS INSPECTION C5, AMM 76-10-00 |                                                                              |           |                |          |                           |           | PKG:3,24<br>WO#: N950PC B & C CHECK |                  |
| 760003                                      | CHECK POWER CONTROL CABLES                                                   |           |                |          |                           |           |                                     | Service ATA:76   |
|                                             | MOS/MSC                                                                      | 30-May-96 | O/C            |          |                           |           |                                     |                  |
|                                             | HRS                                                                          | 0         |                |          |                           |           |                                     |                  |
| WC#: 76.020                                 | AFL                                                                          | 0         |                |          |                           |           |                                     |                  |
| PROC. REF: AMM 76-10-00                     |                                                                              |           |                |          |                           |           |                                     |                  |
| 760004                                      | LUBRICATE NO. 1 ENGINE THRUST CONTROL TELEFLEX CABLE AND DISCONNECT COUPLING |           |                |          |                           |           |                                     | Service ATA:76   |
|                                             | MOS                                                                          |           |                |          |                           |           |                                     |                  |
|                                             | HRS                                                                          |           | 2400           |          | 6729.9 (M)                |           | 201.6                               |                  |
| WC#: 76.040                                 | AFL                                                                          |           |                |          |                           |           |                                     |                  |
| PROC. REF: AFMS LUBRICATION                 |                                                                              |           |                |          |                           |           | WO#: N950PC LH ENG MPI              |                  |
| 760004                                      | LUBRICATE NO. 2 ENGINE THRUST CONTROL TELEFLEX CABLE AND DISCONNECT COUPLING |           |                |          |                           |           |                                     | Service ATA:76   |
|                                             | MOS                                                                          | 09-Feb-10 |                |          |                           |           |                                     |                  |
|                                             | HRS                                                                          | 4129.9    | 2400           |          | 6650 (M)                  |           | 121.7                               |                  |
| WC#: 76.040                                 | AFL                                                                          | 2305      |                |          |                           |           |                                     |                  |
| PROC. REF: AFMS LUBRICATION                 |                                                                              |           |                |          |                           |           | WO#: N950PC RH ENG MPI/CZ1          |                  |
| 760110 <sup>U</sup>                         | NO. 1 ENGINE - DIGITAL ELECTRONIC ENGINE CONTROL                             |           |                |          |                           |           |                                     | Component ATA:76 |
| PN:2119010-8000                             | MOS/MSC                                                                      | 29-Oct-19 | O/C            |          |                           |           |                                     |                  |
| SN:107-BY0963                               | HRS                                                                          | 5795      |                |          |                           |           |                                     |                  |
| WC#: 76.010                                 | ENC                                                                          | 3397      |                |          |                           |           |                                     |                  |
| PROC. REF: GENERIC NO REF                   |                                                                              |           |                |          |                           |           |                                     |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                       | Unit                                                        | C/W       | Interval   | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition      |
|-----------------------------------------------|-------------------------------------------------------------|-----------|------------|----------|---------------------------|-----------|--------------|------------------|
| ATA 76 - ENGINE CONTROLS                      |                                                             |           |            |          |                           |           |              |                  |
| 760110 <sup>U</sup>                           | NO. 2 ENGINE - DIGITAL ELECTRONIC ENGINE CONTROL            |           |            |          |                           |           |              | Component ATA:76 |
| PN:2119010-8000                               | MOS/MSC                                                     | 21-Sep-12 | O/C        |          |                           |           |              |                  |
| SN:126-BY0862                                 | HRS                                                         | 4730.1    |            |          |                           |           |              |                  |
| WC#: 76.010                                   | ENC                                                         | 2649      |            |          |                           |           |              |                  |
| PROC. REF: GENERIC NO REF                     |                                                             |           |            |          |                           |           |              |                  |
| 760120                                        | NO. 1 ENGINE - BITE CHECK DIGITAL ELECTRONIC ENGINE CONTROL |           |            |          |                           |           |              | Service ATA:76   |
|                                               | MOS                                                         | 11-Oct-22 |            |          |                           |           |              |                  |
|                                               | HRS                                                         | 6450.1    | 300 (+100) |          | (6750.1)<br>6746.9        | 6850.1    | 218.6 (+100) |                  |
| WC#: 76.020                                   | ENC                                                         | 3876      |            |          |                           |           |              |                  |
| PROC. REF: LMM 76-10-03, LMM 72-00-00         |                                                             |           |            |          |                           |           |              |                  |
| 760120                                        | NO. 2 ENGINE - BITE CHECK DIGITAL ELECTRONIC ENGINE CONTROL |           |            |          |                           |           |              | Service ATA:76   |
|                                               | MOS                                                         | 11-Oct-22 |            |          |                           |           |              |                  |
|                                               | HRS                                                         | 6365.3    | 300 (+100) |          | (6665.3)<br>6746.4        | 6765.3    | 218.1 (+100) |                  |
| WC#: 76.020                                   | ENC                                                         | 3828      |            |          |                           |           |              |                  |
| PROC. REF: LMM 76-10-03, LMM 72-00-00         |                                                             |           |            |          |                           |           |              |                  |
| 760130                                        | NO. 1 ENGINE - DOWNLOAD ECTM                                |           |            |          |                           |           |              | Service ATA:76   |
|                                               | DAYS                                                        | 06-Jan-23 | 30         |          | 05-Feb-23                 |           | 5 d          |                  |
|                                               | HRS                                                         | 6522.7    |            |          |                           |           |              |                  |
| WC#: 76.050                                   | ENC                                                         | 3926      | 30 (+10)   |          | (3956)<br>3953            | 3966      | 24 (+10)     |                  |
| PROC. REF: MSC CAMP EHM ADENDUM, LMM 76-10-03 |                                                             |           |            |          |                           |           |              |                  |
| 760130                                        | NO. 2 ENGINE - DOWNLOAD ECTM                                |           |            |          |                           |           |              | Service ATA:76   |
|                                               | DAYS                                                        | 06-Jan-23 | 30         |          | 05-Feb-23                 |           | 5 d          |                  |
|                                               | HRS                                                         | 6438.4    |            |          |                           |           |              |                  |
| WC#: 76.050                                   | ENC                                                         | 3878      | 30 (+10)   |          | (3908)<br>3953            | 3918      | 24 (+10)     |                  |
| PROC. REF: MSC CAMP EHM ADENDUM, LMM 76-10-03 |                                                             |           |            |          |                           |           |              |                  |
| 761310                                        | NO. 2 ENGINE - SURGE BLEED VALVE                            |           |            |          |                           |           |              | Component ATA:76 |
| PN:978812-5-1                                 | MOS/MSC                                                     | 30-May-96 | O/C        | TSN 0    |                           |           |              |                  |
| SN:UNKNOWN                                    | HRS                                                         | 0         |            | TSN 0    |                           |           |              |                  |
| WC#: 76.030                                   | ENC                                                         | 0         |            | TSN 0    |                           |           |              |                  |
| PROC. REF: LMM 76-10-01                       |                                                             |           |            |          |                           |           |              |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                    | Unit                                         | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                  | Disposition      |
|----------------------------|----------------------------------------------|-----------|----------|----------|---------------------------|-----------|----------------------------|------------------|
| ATA 76 - ENGINE CONTROLS   |                                              |           |          |          |                           |           |                            |                  |
| 761320                     | NO. 2 ENGINE - SOLENOID CONTROLLER VALVE     |           |          |          |                           |           |                            | Component ATA:76 |
| PN:109696-4-1              | MOS/MSC                                      | 30-May-96 | O/C      | TSN 0    |                           |           |                            |                  |
| SN:UNKNOWN                 | HRS                                          | 0         |          | TSN 0    |                           |           |                            |                  |
| WC#: 76.040                | ENC                                          | 0         |          | TSN 0    |                           |           |                            |                  |
| PROC. REF: LMM 76-10-01    |                                              |           |          |          |                           |           |                            |                  |
| ATA 77 - ENGINE INDICATING |                                              |           |          |          |                           |           |                            |                  |
| 771025                     | NO. 1 ENGINE LOW-PRESSURE (N1) INDICATOR     |           |          |          |                           |           |                            | Component ATA:77 |
| PN:WL717RSA5               | MOS/MSC                                      | 10-Oct-01 | O/C      |          |                           |           |                            |                  |
| SN:AM558                   | HRS                                          | 2057      |          |          |                           |           |                            |                  |
| WC#: 77.010                | AFL                                          | 1144      |          |          |                           |           |                            |                  |
| 771026                     | NO. 2 ENGINE LOW-PRESSURE (N1) INDICATOR     |           |          |          |                           |           |                            | Component ATA:77 |
| PN:WL717RSA-5              | MOS/MSC                                      | 10-Oct-01 | O/C      |          |                           |           |                            |                  |
| SN:AL244                   | HRS                                          | 2057      |          |          |                           |           |                            |                  |
| WC#: 77.010                | AFL                                          | 1144      |          |          |                           |           |                            |                  |
| 771037                     | NO. 1 ENGINE HIGH-PRESSURE (N2) INDICATOR    |           |          |          |                           |           |                            | Component ATA:77 |
| PN:WL656RSA-7              | MOS/MSC                                      | 30-May-96 | O/C      |          |                           |           |                            |                  |
| SN:AK975                   | HRS                                          | 0         |          | TSN 0    |                           |           |                            |                  |
| WC#: 77.015                | AFL                                          | 0         |          |          |                           |           |                            |                  |
| 771038                     | NO. 2 ENGINE HIGH-PRESSURE (N2) INDICATOR    |           |          |          |                           |           |                            | Component ATA:77 |
| PN:WL656RSA-7              | MOS/MSC                                      | 30-May-96 | O/C      |          |                           |           |                            |                  |
| SN:AL195                   | HRS                                          | 0         |          | TSN 0    |                           |           |                            |                  |
| WC#: 77.015                | AFL                                          | 0         |          |          |                           |           |                            |                  |
| 771110                     | NO. 2 ENGINE - LOW PRESSURE (N1) TRANSDUCER  |           |          |          |                           |           |                            | Component ATA:77 |
| PN:3073827-3               | MOS/MSC                                      | 30-May-96 | O/C      | TSN 0    |                           |           |                            |                  |
| SN:UNKNOWN                 | HRS                                          | 0         |          | TSN 0    |                           |           |                            |                  |
| WC#: 77.010                | ENC                                          | 0         |          | TSN 0    |                           |           |                            |                  |
| PROC. REF: LMM 77-10-03    |                                              |           |          |          |                           |           |                            |                  |
| 771120                     | NO. 2 ENGINE - HIGH PRESSURE (N2) TRANSDUCER |           |          |          |                           |           |                            | Component ATA:77 |
| PN:3070722-3               | MOS/MSC                                      | 30-May-96 | O/C      | TSN 0    |                           |           |                            |                  |
| SN:UNKNOWN                 | HRS                                          | 0         |          | TSN 0    |                           |           |                            |                  |
| WC#: 77.020                | ENC                                          | 0         |          | TSN 0    |                           |           |                            |                  |
| PROC. REF: LMM 77-10-05    |                                              |           |          |          |                           |           |                            |                  |
|                            |                                              |           |          |          |                           |           | WO#: N950PC RH ENG MPI/CZI |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                      | Unit                                        | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition                         |
|----------------------------------------------|---------------------------------------------|-----------|---------------|----------|---------------------------|-----------|-----------|-------------------------------------|
| ATA 77 - ENGINE INDICATING                   |                                             |           |               |          |                           |           |           |                                     |
| 772110                                       | NO. 2 ENGINE - ITT THERMOCOUPLE HARNESS     |           |               |          |                           |           |           | Component ATA:77                    |
| PN:3073995-1                                 | MOS/MSC                                     | 30-May-96 | O/C           | TSN 0    |                           |           |           |                                     |
| SN:UNKNOWN                                   | HRS                                         | 0         |               | TSN 0    |                           |           |           |                                     |
| WC#: 77.030                                  | ENC                                         | 0         |               | TSN 0    |                           |           |           |                                     |
| PROC. REF: LMM 77-20-01                      |                                             |           |               |          |                           |           |           |                                     |
| 773005                                       | LEFT TIME DELAY SWITCH                      |           |               |          |                           |           |           | Component ATA:77                    |
| PN:TDA310A                                   | MOS/MSC                                     | 30-May-96 | O/C           |          |                           |           |           |                                     |
| SN:2401T                                     | HRS                                         | 0         |               | TSN 0    |                           |           |           |                                     |
| WC#: 77.025                                  | AFL                                         | 0         |               |          |                           |           |           |                                     |
| 773006                                       | RIGHT TIME DELAY SWITCH                     |           |               |          |                           |           |           | Component ATA:77                    |
| PN:TDA310A                                   | MOS/MSC                                     | 30-May-96 | O/C           |          |                           |           |           |                                     |
| SN:2400T                                     | HRS                                         | 0         |               | TSN 0    |                           |           |           |                                     |
| WC#: 77.025                                  | AFL                                         | 0         |               |          |                           |           |           |                                     |
| 774013                                       | NO. 1 ENGINE ITT INDICATOR                  |           |               |          |                           |           |           | Component ATA:77                    |
| PN:WL718RSA-5                                | MOS/MSC                                     | 30-May-96 | O/C           |          |                           |           |           |                                     |
| SN:AL275                                     | HRS                                         | 0         |               | TSN 0    |                           |           |           |                                     |
| WC#: 77.030                                  | AFL                                         | 0         |               |          |                           |           |           |                                     |
| 774014                                       | NO. 2 ENGINE ITT INDICATOR                  |           |               |          |                           |           |           | Component ATA:77                    |
| PN:WL718RSA-5                                | MOS/MSC                                     | 30-May-96 | O/C           |          |                           |           |           |                                     |
| SN:AL287                                     | HRS                                         | 0         |               | TSN 0    |                           |           |           |                                     |
| WC#: 77.030                                  | AFL                                         | 0         |               |          |                           |           |           |                                     |
| ATA 78 - EXHAUST                             |                                             |           |               |          |                           |           |           |                                     |
| 780001                                       | INSPECT THRUST REVERSER LINK ARM ASSEMBLIES |           |               |          |                           |           |           | Service ATA:78                      |
|                                              | MOS                                         | 15-Oct-19 |               |          |                           |           |           |                                     |
|                                              | HRS                                         | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)  |                                     |
| WC#: 78.110                                  | AFL                                         | 3397      |               |          |                           |           |           |                                     |
| PROC. REF: AFMS INSPECTION B11, AMM 78-31-10 |                                             |           |               |          |                           |           |           |                                     |
|                                              |                                             |           |               |          |                           |           |           | PKG:2,18<br>WO#: N950PC B & C CHECK |
| 780002                                       | INSPECT REVERSER DOOR SEALS                 |           |               |          |                           |           |           | Service ATA:78                      |
|                                              | MOS                                         | 15-Oct-19 |               |          |                           |           |           |                                     |
|                                              | HRS                                         | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)  |                                     |
| WC#: 78.120                                  | AFL                                         | 3397      |               |          |                           |           |           |                                     |
| PROC. REF: AFMS INSPECTION B11, AMM 78-31-20 |                                             |           |               |          |                           |           |           |                                     |
|                                              |                                             |           |               |          |                           |           |           | PKG:2,18<br>WO#: N950PC B & C CHECK |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                      | Unit                                                       | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                           | Disposition    |
|----------------------------------------------|------------------------------------------------------------|-----------|-----------------|----------|---------------------------|-----------|-------------------------------------|----------------|
| ATA 78 - EXHAUST                             |                                                            |           |                 |          |                           |           |                                     |                |
| 780003                                       | TEST THRUST REVERSER STOW/DEPLOY MICROSWITCHES             |           |                 |          |                           |           |                                     | Service ATA:78 |
|                                              | MOS                                                        | 06-May-15 |                 |          |                           |           |                                     |                |
|                                              | HRS                                                        | 5125.6    | 1600 (+50/-50)  |          | 6725.6                    | 6775.6    | 197.3 (+50)                         |                |
| WC#: 78.130                                  | AFL                                                        | 2873      |                 |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION C4, AMM 78-34-20  |                                                            |           |                 |          |                           |           | PKG:3,23<br>WO#: N950PC B & C CHECK |                |
| 780004                                       | INSPECT PYLON SKIN PANELS                                  |           |                 |          |                           |           |                                     | Service ATA:78 |
|                                              | MOS                                                        | 06-May-15 |                 |          |                           |           |                                     |                |
|                                              | HRS                                                        | 5125.6    | 1600 (+50/-50)  |          | 6725.6                    | 6775.6    | 197.3 (+50)                         |                |
| WC#: 78.135                                  | AFL                                                        | 2873      |                 |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION C11               |                                                            |           |                 |          |                           |           | PKG:3,30<br>WO#: N950PC B & C CHECK |                |
| 780005                                       | DETAIL INSPECT DOOR LINK RODS AND PIVOT BRACKETS           |           |                 |          |                           |           |                                     | Service ATA:78 |
|                                              | MOS                                                        | 06-May-15 |                 |          |                           |           |                                     |                |
|                                              | HRS                                                        | 5125.6    | 1600 (+50/-50)  |          | 6725.6                    | 6775.6    | 197.3 (+50)                         |                |
| WC#: 78.140                                  | AFL                                                        | 2873      |                 |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION C11, AMM 78-31-10 |                                                            |           |                 |          |                           |           | PKG:3,30<br>WO#: N950PC B & C CHECK |                |
| 780006                                       | CHECK THRUST REVERSER LEVER BAULK MECHANISM                |           |                 |          |                           |           |                                     | Service ATA:78 |
|                                              | MOS                                                        | 18-Aug-17 |                 |          |                           |           |                                     |                |
|                                              | HRS                                                        | 5554.6    | 3200 (+150/-50) |          | 8754.6                    | 8904.6    | 2226.3 (+150)                       |                |
| WC#: 78.125                                  | AFL                                                        | 3197      |                 |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION D4                |                                                            |           |                 |          |                           |           | PKG:4,35                            |                |
| 780009                                       | INSPECT THRUST REVERSER AFTERBODY, DOORS AND FAN FLAPS     |           |                 |          |                           |           |                                     | Service ATA:78 |
|                                              | MOS                                                        | 15-Oct-19 |                 |          |                           |           |                                     |                |
|                                              | HRS                                                        | 5795.3    | 800 (+40/-10)   |          | 6595.3                    | 6635.3    | 67 (+40)                            |                |
| WC#: 78.155                                  | AFL                                                        | 3397      |                 |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION B11               |                                                            |           |                 |          |                           |           | PKG:2,18<br>WO#: N950PC B & C CHECK |                |
| 780010                                       | INSPECT THRUST REVERSER HYDRAULIC LINES AND WIRING HARNESS |           |                 |          |                           |           |                                     | Service ATA:78 |
|                                              | MOS                                                        | 15-Oct-19 |                 |          |                           |           |                                     |                |
|                                              | HRS                                                        | 5795.3    | 800 (+40/-10)   |          | 6595.3                    | 6635.3    | 67 (+40)                            |                |
| WC#: 78.160                                  | AFL                                                        | 3397      |                 |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION B7                |                                                            |           |                 |          |                           |           | PKG:2,14<br>WO#: N950PC B & C CHECK |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                      | Unit                                                       | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                           | Disposition    |
|----------------------------------------------|------------------------------------------------------------|-----------|---------------|----------|---------------------------|-----------|-------------------------------------|----------------|
| ATA 78 - EXHAUST                             |                                                            |           |               |          |                           |           |                                     |                |
| 780011                                       | DETAIL INSPECT THRUST REVERSER EXHAUST NOZZLES             |           |               |          |                           |           |                                     | Service ATA:78 |
|                                              | MOS                                                        | 15-Oct-19 |               |          |                           |           |                                     |                |
|                                              | HRS                                                        | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)                            |                |
| WC#: 78.165                                  | AFL                                                        | 3397      |               |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION B11               |                                                            |           |               |          |                           |           | PKG:2,18<br>WO#: N950PC B & C CHECK |                |
| 780012                                       | INSPECT THRUST REVERSER HYDRAULIC LINES                    |           |               |          |                           |           |                                     | Service ATA:78 |
|                                              | MOS                                                        | 15-Oct-19 |               |          |                           |           |                                     |                |
|                                              | HRS                                                        | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)                            |                |
| WC#: 78.170                                  | AFL                                                        | 3397      |               |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION B11               |                                                            |           |               |          |                           |           | PKG:2,18<br>WO#: N950PC B & C CHECK |                |
| 780013                                       | INSPECT THRUST REVERSER WIRE HARNESSSES                    |           |               |          |                           |           |                                     | Service ATA:78 |
|                                              | MOS                                                        | 15-Oct-19 |               |          |                           |           |                                     |                |
|                                              | HRS                                                        | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)                            |                |
| WC#: 78.175                                  | AFL                                                        | 3397      |               |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION B11               |                                                            |           |               |          |                           |           | PKG:2,18<br>WO#: N950PC B & C CHECK |                |
| 780014                                       | INSPECT THRUST REVERSER FAN DUCTS                          |           |               |          |                           |           |                                     | Service ATA:78 |
|                                              | MOS                                                        | 15-Oct-19 |               |          |                           |           |                                     |                |
|                                              | HRS                                                        | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)                            |                |
| WC#: 78.180                                  | AFL                                                        | 3397      |               |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION B11               |                                                            |           |               |          |                           |           | PKG:2,18<br>WO#: N950PC B & C CHECK |                |
| 780015                                       | INSPECT THRUST REVERSER LATCH BOX SPRINGS                  |           |               |          |                           |           |                                     | Service ATA:78 |
|                                              | MOS                                                        | 15-Oct-19 |               |          |                           |           |                                     |                |
|                                              | HRS                                                        | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)                            |                |
| WC#: 78.185                                  | AFL                                                        | 3397      |               |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION B11               |                                                            |           |               |          |                           |           | PKG:2,18<br>WO#: N950PC B & C CHECK |                |
| 780016                                       | OPERATIONAL TEST THRUST REVERSER LATCH MONITORING SWITCHES |           |               |          |                           |           |                                     | Service ATA:78 |
|                                              | MOS                                                        | 15-Oct-19 |               |          |                           |           |                                     |                |
|                                              | HRS                                                        | 5795.3    | 800 (+40/-10) |          | 6595.3                    | 6635.3    | 67 (+40)                            |                |
| WC#: 78.190                                  | AFL                                                        | 3397      |               |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION B11, AMM 78-32-40 |                                                            |           |               |          |                           |           | PKG:2,18<br>WO#: N950PC B & C CHECK |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                    | Unit                                                          | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                           | Disposition    |
|------------------------------------------------------------|---------------------------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-------------------------------------|----------------|
| ATA 78 - EXHAUST                                           |                                                               |           |                |          |                           |           |                                     |                |
| 780017                                                     | INSPECT THRUST REVERSER LATCHES AND LATCH RECEPTACLES         |           |                |          |                           |           |                                     | Service ATA:78 |
|                                                            | MOS                                                           | 15-Oct-19 |                |          |                           |           |                                     |                |
|                                                            | HRS                                                           | 5795.3    | 800 (+40/-10)  |          | 6595.3                    | 6635.3    | 67 (+40)                            |                |
| WC#: 78.195                                                | AFL                                                           | 3397      |                |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION B11, AMM 78-31-35               |                                                               |           |                |          |                           |           | PKG:2,18<br>WO#: N950PC B & C CHECK |                |
| 780018                                                     | INSPECT THRUST REVERSER PRIMARY AND LATCH HYDRAULIC ACTUATORS |           |                |          |                           |           |                                     | Service ATA:78 |
|                                                            | MOS                                                           | 15-Oct-19 |                |          |                           |           |                                     |                |
|                                                            | HRS                                                           | 5795.3    | 800 (+40/-10)  |          | 6595.3                    | 6635.3    | 67 (+40)                            |                |
| WC#: 78.200                                                | AFL                                                           | 3397      |                |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION B11, AMM 78-32-40, AMM 78-32-50 |                                                               |           |                |          |                           |           | PKG:2,18<br>WO#: N950PC B & C CHECK |                |
| 780019                                                     | INSPECT THRUST REVERSER THROTTLE RETARD HYDRAULIC ACTUATORS   |           |                |          |                           |           |                                     | Service ATA:78 |
|                                                            | MOS                                                           | 15-Oct-19 |                |          |                           |           |                                     |                |
|                                                            | HRS                                                           | 5795.3    | 800 (+40/-10)  |          | 6595.3                    | 6635.3    | 67 (+40)                            |                |
| WC#: 78.205                                                | AFL                                                           | 3397      |                |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION B11, AMM 78-32-30               |                                                               |           |                |          |                           |           | PKG:2,18<br>WO#: N950PC B & C CHECK |                |
| 780020                                                     | INSPECT THRUST REVERSER FAN FLAP HYDRAULIC ACTUATORS          |           |                |          |                           |           |                                     | Service ATA:78 |
|                                                            | MOS                                                           | 15-Oct-19 |                |          |                           |           |                                     |                |
|                                                            | HRS                                                           | 5795.3    | 800 (+40/-10)  |          | 6595.3                    | 6635.3    | 67 (+40)                            |                |
| WC#: 78.210                                                | AFL                                                           | 3397      |                |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION B11, AMM 78-32-40               |                                                               |           |                |          |                           |           | PKG:2,18<br>WO#: N950PC B & C CHECK |                |
| 780021                                                     | INSPECT THRUST REVERSER PYLON PLUGS                           |           |                |          |                           |           |                                     | Service ATA:78 |
|                                                            | MOS                                                           | 15-Oct-19 |                |          |                           |           |                                     |                |
|                                                            | HRS                                                           | 5795.3    | 800 (+40/-10)  |          | 6595.3                    | 6635.3    | 67 (+40)                            |                |
| WC#: 78.215                                                | AFL                                                           | 3397      |                |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION B11                             |                                                               |           |                |          |                           |           | PKG:2,18<br>WO#: N950PC B & C CHECK |                |
| 780022                                                     | CHECK DOOR LINK RODS                                          |           |                |          |                           |           |                                     | Service ATA:78 |
|                                                            | MOS                                                           | 06-May-15 |                |          |                           |           |                                     |                |
|                                                            | HRS                                                           | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50)                         |                |
| WC#: 78.220                                                | AFL                                                           | 2873      |                |          |                           |           |                                     |                |
| PROC. REF: AFMS INSPECTION C11, AMM 78-31-10               |                                                               |           |                |          |                           |           | PKG:3,30<br>WO#: N950PC B & C CHECK |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                        | Unit                                          | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition                         |
|--------------------------------|-----------------------------------------------|-----------|----------------|----------|---------------------------|-----------|-------------|-------------------------------------|
| ATA 78 - EXHAUST               |                                               |           |                |          |                           |           |             |                                     |
| 780023                         | CHECK BONDING STRAPS - 900XP AIRPLANES        |           |                |          |                           |           |             | Service ATA:78                      |
|                                | MOS                                           | 06-May-15 |                |          |                           |           |             |                                     |
|                                | HRS                                           | 5125.6    | 1600 (+50/-50) |          | 6725.6                    | 6775.6    | 197.3 (+50) |                                     |
| WC#: 78.225                    | AFL                                           | 2873      |                |          |                           |           |             |                                     |
| PROC. REF: AFMS INSPECTION C11 |                                               |           |                |          |                           |           |             | PKG:3,30<br>WO#: N950PC B & C CHECK |
| 781001                         | NO. 1 ENGINE THRUST REVERSER AFTERBODY        |           |                |          |                           |           |             | Component ATA:78                    |
| PN:5451101/69                  | MOS/MSC                                       | 12-Nov-96 | O/C            |          |                           |           |             |                                     |
| SN:024                         | HRS                                           | 20        |                | TSN 14   |                           |           |             |                                     |
| WC#: 78.015                    | AFL                                           | 11        |                | TSN 5    |                           |           |             |                                     |
| PROC. REF: AMM 78-33-40        |                                               |           |                |          |                           |           |             |                                     |
| 781002                         | NO. 2 ENGINE THRUST REVERSER AFTERBODY        |           |                |          |                           |           |             | Component ATA:78                    |
| PN:5451101/71                  | MOS/MSC                                       | 12-Nov-96 | O/C            |          |                           |           |             |                                     |
| SN:024                         | HRS                                           | 20        |                | TSN 14   |                           |           |             |                                     |
| WC#: 78.015                    | AFL                                           | 11        |                | TSN 5    |                           |           |             |                                     |
| PROC. REF: AMM 78-33-40        |                                               |           |                |          |                           |           |             |                                     |
| 781013                         | NO. 1 ENGINE THRUST REVERSER ASSEMBLY         |           |                |          |                           |           |             | Component ATA:78                    |
| PN:HS7830100-3                 | MOS/MSC                                       | 12-Nov-96 | O/C            |          |                           |           |             |                                     |
| SN:024                         | HRS                                           | 20        |                | TSN 14   |                           |           |             |                                     |
| WC#: 78.010                    | AFL                                           | 11        |                | TSN 5    |                           |           |             |                                     |
| PROC. REF: AMM 78-31-00        |                                               |           |                |          |                           |           |             |                                     |
| 781014                         | NO. 2 ENGINE THRUST REVERSER ASSEMBLY         |           |                |          |                           |           |             | Component ATA:78                    |
| PN:HS7830100-4                 | MOS/MSC                                       | 12-Nov-96 | O/C            |          |                           |           |             |                                     |
| SN:024                         | HRS                                           | 20        |                | TSN 14   |                           |           |             |                                     |
| WC#: 78.011                    | AFL                                           | 11        |                | TSN 5    |                           |           |             |                                     |
| PROC. REF: AMM 78-31-00        |                                               |           |                |          |                           |           |             |                                     |
| 781026                         | NO. 1 ENGINE THRUST REVERSER INBOARD ACTUATOR |           |                |          |                           |           |             | Component ATA:78                    |
| PN:5453512-15                  | MOS/MSC                                       | 12-Nov-96 | O/C            |          |                           |           |             |                                     |
| SN:072                         | HRS                                           | 20        |                | TSN 14   |                           |           |             |                                     |
| WC#: 78.020                    | AFL                                           | 11        |                | TSN 5    |                           |           |             |                                     |
| PROC. REF: AMM 78-32-40        |                                               |           |                |          |                           |           |             |                                     |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                 | Unit                                           | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------|------------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 78 - EXHAUST        |                                                |           |          |          |                           |           |           |                  |
| 781027                  | NO. 1 ENGINE THRUST REVERSER OUTBOARD ACTUATOR |           |          |          |                           |           |           | Component ATA:78 |
| PN:5453512-16           | MOS/MSC                                        | 12-Nov-96 | O/C      |          |                           |           |           |                  |
| SN:DHC1029              | HRS                                            | 20        |          | TSN 4    |                           |           |           |                  |
| WC#: 78.020             | AFL                                            | 11        |          | TSN 2    |                           |           |           |                  |
| PROC. REF: AMM 78-32-40 |                                                |           |          |          |                           |           |           |                  |
| 781028                  | NO. 2 ENGINE THRUST REVERSER INBOARD ACTUATOR  |           |          |          |                           |           |           | Component ATA:78 |
| PN:545312-15            | MOS/MSC                                        | 12-Nov-96 | O/C      |          |                           |           |           |                  |
| SN:DHC1017              | HRS                                            | 20        |          | TSN 4    |                           |           |           |                  |
| WC#: 78.025             | AFL                                            | 11        |          | TSN 2    |                           |           |           |                  |
| 781029                  | NO. 2 ENGINE THRUST REVERSER OUTBOARD ACTUATOR |           |          |          |                           |           |           | Component ATA:78 |
| PN:5453512-16           | MOS/MSC                                        | 12-Nov-96 | O/C      |          |                           |           |           |                  |
| SN:069                  | HRS                                            | 20        |          | TSN 14   |                           |           |           |                  |
| WC#: 78.025             | AFL                                            | 11        |          | TSN 5    |                           |           |           |                  |
| 781053                  | NO. 1 ENGINE INBOARD LATCH ACTUATOR ASSEMBLY   |           |          |          |                           |           |           | Component ATA:78 |
| PN:5453521-7            | MOS/MSC                                        | 12-Nov-96 | O/C      |          |                           |           |           |                  |
| SN:997                  | HRS                                            | 20        |          | TSN 14   |                           |           |           |                  |
| WC#: 78.030             | AFL                                            | 11        |          | TSN 5    |                           |           |           |                  |
| PROC. REF: AMM 78-32-50 |                                                |           |          |          |                           |           |           |                  |
| 781054                  | NO. 1 ENGINE OUTBOARD LATCH ACTUATOR ASSEMBLY  |           |          |          |                           |           |           | Component ATA:78 |
| PN:5453521-7            | MOS/MSC                                        | 12-Nov-96 | O/C      |          |                           |           |           |                  |
| SN:1000                 | HRS                                            | 20        |          | TSN 14   |                           |           |           |                  |
| WC#: 78.030             | AFL                                            | 11        |          | TSN 5    |                           |           |           |                  |
| PROC. REF: AMM 78-32-50 |                                                |           |          |          |                           |           |           |                  |
| 781055                  | NO. 2 ENGINE INBOARD LATCH ACTUATOR ASSEMBLY   |           |          |          |                           |           |           | Component ATA:78 |
| PN:5453521-7            | MOS/MSC                                        | 12-Nov-96 | O/C      |          |                           |           |           |                  |
| SN:985                  | HRS                                            | 20        |          | TSN 14   |                           |           |           |                  |
| WC#: 78.035             | AFL                                            | 11        |          | TSN 5    |                           |           |           |                  |
| PROC. REF: AMM 78-32-50 |                                                |           |          |          |                           |           |           |                  |
| 781056                  | NO. 2 ENGINE OUTBOARD LATCH ACTUATOR ASSEMBLY  |           |          |          |                           |           |           | Component ATA:78 |
| PN:5453521-7            | MOS/MSC                                        | 12-Nov-96 | O/C      |          |                           |           |           |                  |
| SN:UNKNOWN              | HRS                                            | 20        |          | TSN 14   |                           |           |           |                  |
| WC#: 78.035             | AFL                                            | 11        |          | TSN 5    |                           |           |           |                  |
| PROC. REF: AMM 78-32-50 |                                                |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                 | Unit                                          | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------|-----------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 78 - EXHAUST        |                                               |           |          |          |                           |           |           |                  |
| 781090                  | NO. 1 ENGINE UPPER FAN FLAP ACTUATOR ASSEMBLY |           |          |          |                           |           |           | Component ATA:78 |
| PN:5453511-11           | MOS/MSC                                       | 12-Nov-96 | O/C      |          |                           |           |           |                  |
| SN:965                  | HRS                                           | 20        |          | TSN 14   |                           |           |           |                  |
| WC#: 78.040             | AFL                                           | 11        |          | TSN 5    |                           |           |           |                  |
| PROC. REF: AMM 78-32-60 |                                               |           |          |          |                           |           |           |                  |
| 781091                  | NO. 1 ENGINE LOWER FAN FLAP ACTUATOR ASSEMBLY |           |          |          |                           |           |           | Component ATA:78 |
| PN:5453511-11           | MOS/MSC                                       | 12-Nov-96 | O/C      |          |                           |           |           |                  |
| SN:943                  | HRS                                           | 20        |          | TSN 14   |                           |           |           |                  |
| WC#: 78.040             | AFL                                           | 11        |          | TSN 5    |                           |           |           |                  |
| PROC. REF: AMM 78-32-60 |                                               |           |          |          |                           |           |           |                  |
| 781092                  | NO. 2 ENGINE UPPER FAN FLAP ACTUATOR ASSEMBLY |           |          |          |                           |           |           | Component ATA:78 |
| PN:5453511-11           | MOS/MSC                                       | 12-Nov-96 | O/C      |          |                           |           |           |                  |
| SN:977                  | HRS                                           | 20        |          | TSN 14   |                           |           |           |                  |
| WC#: 78.045             | AFL                                           | 11        |          | TSN 5    |                           |           |           |                  |
| PROC. REF: AMM 78-32-60 |                                               |           |          |          |                           |           |           |                  |
| 781093                  | NO. 2 ENGINE LOWER FAN FLAP ACTUATOR ASSEMBLY |           |          |          |                           |           |           | Component ATA:78 |
| PN:5453511-11           | MOS/MSC                                       | 12-Nov-96 | O/C      |          |                           |           |           |                  |
| SN:942                  | HRS                                           | 20        |          | TSN 14   |                           |           |           |                  |
| WC#: 78.045             | AFL                                           | 11        |          | TSN 5    |                           |           |           |                  |
| PROC. REF: AMM 78-32-60 |                                               |           |          |          |                           |           |           |                  |
| 781117                  | NO. 1 ENGINE RETARD THROTTLE ASSEMBLY         |           |          |          |                           |           |           | Component ATA:78 |
| PN:5453303              | MOS/MSC                                       | 28-Feb-00 | O/C      |          |                           |           |           |                  |
| SN:DHC0196              | HRS                                           | 1345      |          |          |                           |           |           |                  |
| WC#: 78.050             | AFL                                           | 672       |          |          |                           |           |           |                  |
| PROC. REF: AMM 78-32-30 |                                               |           |          |          |                           |           |           |                  |
| 781118                  | NO. 2 ENGINE RETARD THROTTLE ASSEMBLY         |           |          |          |                           |           |           | Component ATA:78 |
| PN:5453305-3            | MOS/MSC                                       | 12-Nov-96 | O/C      |          |                           |           |           |                  |
| SN:442                  | HRS                                           | 20        |          | TSN 14   |                           |           |           |                  |
| WC#: 78.050             | AFL                                           | 11        |          | TSN 5    |                           |           |           |                  |
| PROC. REF: AMM 78-32-30 |                                               |           |          |          |                           |           |           |                  |
| 781129                  | THRUST REVERSER TIME DELAY RELAY              |           |          |          |                           |           |           | Component ATA:78 |
| PN:5400619-1            | MOS/MSC                                       | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:049                  | HRS                                           | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 78.055             | AFL                                           | 0         |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                 | Unit                                       | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------|--------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 78 - EXHAUST        |                                            |           |          |          |                           |           |           |                  |
| 781130                  | CONTROL RELAY BOX                          |           |          |          |                           |           |           | Component ATA:78 |
| PN:5400612-1            | MOS/MSC                                    | 30-Jul-21 | O/C      |          |                           |           |           |                  |
| SN:HX5-102-06           | HRS                                        | 6087.1    |          |          |                           |           |           |                  |
| WC#: 78.060             | AFL                                        | 3605      |          |          |                           |           |           |                  |
| PROC. REF: AMM 78-33-20 |                                            |           |          |          |                           |           |           |                  |
| 781136                  | AUXILIARY RELAY BOX                        |           |          |          |                           |           |           | Component ATA:78 |
| PN:5400605-1            | MOS/MSC                                    | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:1599                 | HRS                                        | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 78.065             | AFL                                        | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 78-33-30 |                                            |           |          |          |                           |           |           |                  |
| 781142                  | NO. 1 ENGINE THRUST REVERSER CONTROL VALVE |           |          |          |                           |           |           | Component ATA:78 |
| PN:5400505-1            | MOS/MSC                                    | 30-Aug-96 | O/C      |          |                           |           |           |                  |
| SN:0168                 | HRS                                        | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 78.070             | AFL                                        | 9         |          |          |                           |           |           |                  |
| PROC. REF: AMM 78-32-20 |                                            |           |          |          |                           |           |           |                  |
| 781143                  | NO. 2 ENGINE THRUST REVERSER CONTROL VALVE |           |          |          |                           |           |           | Component ATA:78 |
| PN:5400505-1            | MOS/MSC                                    | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:0789                 | HRS                                        | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 78.070             | AFL                                        | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 78-32-20 |                                            |           |          |          |                           |           |           |                  |
| 781155                  | THRUST REVERSER ACCUMULATOR                |           |          |          |                           |           |           | Component ATA:78 |
| PN:D5259-3              | MOS/MSC                                    | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:8424-13210           | HRS                                        | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 78.075             | AFL                                        | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 78-32-10 |                                            |           |          |          |                           |           |           |                  |
| 781156                  | HYDRAULIC RELIEF VALVE                     |           |          |          |                           |           |           | Component ATA:78 |
| PN:D63450               | MOS/MSC                                    | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:59461                | HRS                                        | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 78.080             | AFL                                        | 0         |          |          |                           |           |           |                  |
| 781161                  | THRUST REVERSER CONTROL PANEL              |           |          |          |                           |           |           | Component ATA:78 |
| PN:5412600-3            | MOS/MSC                                    | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:188                  | HRS                                        | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 78.085             | AFL                                        | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 78-33-10 |                                            |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                 | Unit                                         | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------|----------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 78 - EXHAUST        |                                              |           |          |          |                           |           |           |                  |
| 781167                  | NO. 1 ENGINE THRUST REVERSER PRESSURE SWITCH |           |          |          |                           |           |           | Component ATA:78 |
| PN:2365-15              | MOS/MSC                                      | 30-Aug-96 | O/C      |          |                           |           |           |                  |
| SN:766                  | HRS                                          | 16        |          | TSN 0    |                           |           |           |                  |
| WC#: 78.090             | AFL                                          | 9         |          |          |                           |           |           |                  |
| 781169                  | NO. 2 ENGINE THRUST REVERSER PRESSURE SWITCH |           |          |          |                           |           |           | Component ATA:78 |
| PN:2365-15              | MOS/MSC                                      | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:1453                 | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 78.090             | AFL                                          | 0         |          |          |                           |           |           |                  |
| 781173                  | THRUST REVERSER PRESSURE GAUGE               |           |          |          |                           |           |           | Component ATA:78 |
| PN:5413508              | MOS/MSC                                      | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:93174                | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 78.090             | AFL                                          | 0         |          |          |                           |           |           |                  |
| 783008                  | NO. 1 ENGINE LOWER THRUST REVERSER DOOR      |           |          |          |                           |           |           | Component ATA:78 |
| PN:HS7832000-3          | MOS/MSC                                      | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:025-151              | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 78.095             | AFL                                          | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 78-31-10 |                                              |           |          |          |                           |           |           |                  |
| 783009                  | NO. 2 ENGINE LOWER THRUST REVERSER DOOR      |           |          |          |                           |           |           | Component ATA:78 |
| PN:HS7832000-4          | MOS/MSC                                      | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:024                  | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 78.095             | AFL                                          | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 78-31-10 |                                              |           |          |          |                           |           |           |                  |
| 783010                  | NO. 1 ENGINE UPPER THRUST REVERSER DOOR      |           |          |          |                           |           |           | Component ATA:78 |
| PN:HS7832000-1          | MOS/MSC                                      | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:025-153              | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 78.100             | AFL                                          | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 78-31-10 |                                              |           |          |          |                           |           |           |                  |
| 783011                  | NO. 2 ENGINE UPPER THRUST REVERSER DOOR      |           |          |          |                           |           |           | Component ATA:78 |
| PN:HS7832000-1          | MOS/MSC                                      | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:025-154              | HRS                                          | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 78.100             | AFL                                          | 0         |          |          |                           |           |           |                  |
| PROC. REF: AMM 78-31-10 |                                              |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                                                | Unit                                            | C/W       | Interval   | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition      |
|--------------------------------------------------------|-------------------------------------------------|-----------|------------|----------|---------------------------|-----------|-------------|------------------|
| ATA 78 - EXHAUST                                       |                                                 |           |            |          |                           |           |             |                  |
| 783013                                                 | NO. 1 ENGINE INNER FAN DUCT ASSEMBLY            |           |            |          |                           |           |             | Component ATA:78 |
| PN:PN                                                  | MOS/MSC                                         | 30-May-96 | O/C        | TSN 0    |                           |           |             |                  |
| SN:UNKNOWN                                             | HRS                                             | 0         |            | TSN 0    |                           |           |             |                  |
| WC#: 78.230                                            | AFL                                             | 0         |            | TSN 0    |                           |           |             |                  |
| PROC. REF: GENERIC NO REF                              |                                                 |           |            |          |                           |           |             |                  |
| 783014                                                 | NO. 2 ENGINE INNER FAN DUCT ASSEMBLY            |           |            |          |                           |           |             | Component ATA:78 |
| PN:PN                                                  | MOS/MSC                                         | 30-May-96 | O/C        | TSN 0    |                           |           |             |                  |
| SN:UNKNOWN                                             | HRS                                             | 0         |            | TSN 0    |                           |           |             |                  |
| WC#: 78.231                                            | AFL                                             | 0         |            | TSN 0    |                           |           |             |                  |
| PROC. REF: GENERIC NO REF                              |                                                 |           |            |          |                           |           |             |                  |
| ATA 79 - OIL                                           |                                                 |           |            |          |                           |           |             |                  |
| 790001 <sup>U</sup>                                    | LH ENGINE ADD OIL                               |           |            |          |                           |           |             | Service ATA:79   |
|                                                        | MOS/MSC                                         | 22-Dec-22 | A/R        |          |                           |           |             |                  |
|                                                        | HRS                                             | 6495.5    |            |          |                           |           |             |                  |
|                                                        | AFL                                             | 3906      |            |          |                           |           |             |                  |
| 790002 <sup>U</sup>                                    | RH ENGINE ADD OIL                               |           |            |          |                           |           |             | Service ATA:79   |
|                                                        | MOS/MSC                                         | 25-Nov-22 | A/R        |          |                           |           |             |                  |
|                                                        | HRS                                             | 6482.3    |            |          |                           |           |             |                  |
|                                                        | AFL                                             | 3897      |            |          |                           |           |             |                  |
| 790111                                                 | NO. 1 ENGINE - ANALYZE OIL AND FILTER-(S.O.A.P) |           |            |          |                           |           |             | Service ATA:79   |
|                                                        | MOS                                             | 11-Oct-22 |            |          |                           |           |             |                  |
|                                                        | HRS                                             | 6450.1    | 150 (+100) |          | (6600.1)<br>6596.9        | 6700.1    | 68.6 (+100) |                  |
| WC#: 79.010                                            | ENC                                             | 3876      |            |          |                           |           |             |                  |
| PKG:1<br>WO#: N950PC B & C CHECK,N950PC LH ENG MPI     |                                                 |           |            |          |                           |           |             |                  |
| 790111                                                 | NO. 2 ENGINE - ANALYZE OIL AND FILTER-(S.O.A.P) |           |            |          |                           |           |             | Service ATA:79   |
|                                                        | MOS                                             | 11-Oct-22 |            |          |                           |           |             |                  |
|                                                        | HRS                                             | 6365.3    | 150 (+100) |          | (6515.3)<br>6596.4        | 6615.3    | 68.1 (+100) |                  |
| WC#: 79.010                                            | ENC                                             | 3828      |            |          |                           |           |             |                  |
| PKG:1<br>WO#: N950PC B & C CHECK,N950PC RH ENG MPI/CZI |                                                 |           |            |          |                           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                 | Unit                                     | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition                                            |
|-------------------------|------------------------------------------|-----------|-------------|----------|---------------------------|-----------|--------------|--------------------------------------------------------|
| ATA 79 - OIL            |                                          |           |             |          |                           |           |              |                                                        |
| 790120                  | NO. 1 ENGINE - CHANGE OIL                |           |             |          |                           |           |              | Service ATA:79                                         |
|                         | MOS                                      | 09-Jun-17 |             |          |                           |           |              |                                                        |
|                         | HRS                                      | 5529.4    | 1200 (+100) |          | (6729.4)<br>6726.2        | 6829.4    | 197.9 (+100) |                                                        |
| WC#: 79.020             | ENC                                      | 3183      |             |          |                           |           |              |                                                        |
| PROC. REF: LMM 72-00-00 |                                          |           |             |          |                           |           |              | WO#: N950PC LH ENG MPI                                 |
| 790120                  | NO. 2 ENGINE - CHANGE OIL                |           |             |          |                           |           |              | Service ATA:79                                         |
|                         | MOS                                      | 09-Jun-17 |             |          |                           |           |              |                                                        |
|                         | HRS                                      | 5447      | 1200 (+100) |          | (6647)<br>6728.1          | 6747      | 199.8 (+100) |                                                        |
| WC#: 79.020             | ENC                                      | 3138      |             |          |                           |           |              |                                                        |
| PROC. REF: LMM 72-00-00 |                                          |           |             |          |                           |           |              | WO#: N950PC RH ENG MPI/CZI                             |
| 790130                  | NO. 1 ENGINE - INSPECT OIL CHIP DETECTOR |           |             |          |                           |           |              | Service ATA:79                                         |
|                         | MOS                                      | 11-Oct-22 |             |          |                           |           |              |                                                        |
|                         | HRS                                      | 6450.1    | 150 (+100)  |          | (6600.1)<br>6596.9        | 6700.1    | 68.6 (+100)  |                                                        |
| WC#: 79.030             | ENC                                      | 3876      |             |          |                           |           |              |                                                        |
| PROC. REF: LMM 79-20-03 |                                          |           |             |          |                           |           |              | PKG:1<br>WO#: N950PC B & C CHECK,N950PC LH ENG MPI     |
| 790130                  | NO. 2 ENGINE - INSPECT OIL CHIP DETECTOR |           |             |          |                           |           |              | Service ATA:79                                         |
|                         | MOS                                      | 11-Oct-22 |             |          |                           |           |              |                                                        |
|                         | HRS                                      | 6365.3    | 150 (+100)  |          | (6515.3)<br>6596.4        | 6615.3    | 68.1 (+100)  |                                                        |
| WC#: 79.030             | ENC                                      | 3828      |             |          |                           |           |              |                                                        |
| PROC. REF: LMM 79-20-03 |                                          |           |             |          |                           |           |              | PKG:1<br>WO#: N950PC B & C CHECK,N950PC RH ENG MPI/CZI |
| 791001 <sup>U</sup>     | NO. 1 ENGINE OIL TANK                    |           |             |          |                           |           |              | Component ATA:79                                       |
| PN:3075207-1G           | MOS/MSC                                  | 11-Nov-96 | O/C         |          |                           |           |              |                                                        |
| SN:UNKNOWN              | HRS                                      | 20        |             | TSN 23   |                           |           |              |                                                        |
|                         | AFL                                      |           |             |          |                           |           |              |                                                        |
| 791002 <sup>U</sup>     | NO. 2 ENGINE OIL TANK                    |           |             |          |                           |           |              | Component ATA:79                                       |
| PN:3075207-1G           | MOS/MSC                                  | 21-Feb-96 | O/C         |          |                           |           |              |                                                        |
| SN:UNKNOWN              | HRS                                      | 0         |             | TSN 0    |                           |           |              |                                                        |
|                         | AFL                                      | 0         |             | TSN 0    |                           |           |              |                                                        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                 | Unit                                            | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining                  | Disposition      |
|-------------------------|-------------------------------------------------|-----------|----------|----------|---------------------------|-----------|----------------------------|------------------|
| ATA 79 - OIL            |                                                 |           |          |          |                           |           |                            |                  |
| 792110                  | NO. 1 ENGINE - OIL PUMP                         |           |          |          |                           |           |                            | Component ATA:79 |
| PN:3071949-11           | MOS/MSC                                         | 02-Jul-96 | O/C      |          |                           |           |                            |                  |
| SN:96-140570121         | HRS                                             | 0         |          | TSN 0    |                           |           |                            |                  |
| WC#: 79.040             | ENC                                             | 0         |          | TSN 0    |                           |           |                            |                  |
| PROC. REF: LMM 79-20-03 |                                                 |           |          |          |                           |           |                            |                  |
| 792110                  | NO. 2 ENGINE - OIL PUMP                         |           |          |          |                           |           |                            | Component ATA:79 |
| PN:3071949-9            | MOS/MSC                                         | 21-Feb-96 | O/C      |          |                           |           |                            |                  |
| SN:95-140573260         | HRS                                             | 0         |          | TSN 0    |                           |           |                            |                  |
| WC#: 79.040             | ENC                                             | 0         |          | TSN 0    |                           |           |                            |                  |
| PROC. REF: LMM 79-20-03 |                                                 |           |          |          |                           |           | WO#: N950PC RH ENG MPI/CZI |                  |
| 792120                  | NO. 1 ENGINE - BY-PASS INDICATOR VALVE          |           |          |          |                           |           |                            | Component ATA:79 |
| PN:PN                   | MOS/MSC                                         | 11-Nov-96 | O/C      | TSN 0    |                           |           |                            |                  |
| SN:UNKNOWN              | HRS                                             | 20        |          | TSN 0    |                           |           |                            |                  |
| WC#: 79.050             | ENC                                             | 12        |          | TSN 0    |                           |           |                            |                  |
| PROC. REF: LMM 79-30-01 |                                                 |           |          |          |                           |           |                            |                  |
| 792120                  | NO. 2 ENGINE - BY-PASS INDICATOR VALVE          |           |          |          |                           |           |                            | Component ATA:79 |
| PN:PN                   | MOS/MSC                                         | 30-May-96 | O/C      | TSN 0    |                           |           |                            |                  |
| SN:UNKNOWN              | HRS                                             | 0         |          | TSN 0    |                           |           |                            |                  |
| WC#: 79.050             | ENC                                             | 0         |          | TSN 0    |                           |           |                            |                  |
| PROC. REF: LMM 79-30-01 |                                                 |           |          |          |                           |           | WO#: N950PC RH ENG MPI/CZI |                  |
| 792130                  | NO. 1 ENGINE - PRESSURE BREATHER VALVE ASSEMBLY |           |          |          |                           |           |                            | Component ATA:79 |
| PN:PN                   | MOS/MSC                                         | 11-Nov-96 | O/C      | TSN 0    |                           |           |                            |                  |
| SN:UNKNOWN              | HRS                                             | 20        |          | TSN 0    |                           |           |                            |                  |
| WC#: 79.060             | ENC                                             | 12        |          | TSN 0    |                           |           |                            |                  |
| PROC. REF: LMM 79-20-02 |                                                 |           |          |          |                           |           |                            |                  |
| 792130                  | NO. 2 ENGINE - PRESSURE BREATHER VALVE ASSEMBLY |           |          |          |                           |           |                            | Component ATA:79 |
| PN:PN                   | MOS/MSC                                         | 30-May-96 | O/C      | TSN 0    |                           |           |                            |                  |
| SN:UNKNOWN              | HRS                                             | 0         |          | TSN 0    |                           |           |                            |                  |
| WC#: 79.060             | ENC                                             | 0         |          | TSN 0    |                           |           |                            |                  |
| PROC. REF: LMM 79-20-02 |                                                 |           |          |          |                           |           | WO#: N950PC RH ENG MPI/CZI |                  |
| 792140                  | NO. 1 ENGINE - UPPER OIL COOLER                 |           |          |          |                           |           |                            | Component ATA:79 |
| PN:PN                   | MOS/MSC                                         | 11-Nov-96 | O/C      | TSN 0    |                           |           |                            |                  |
| SN:UNKNOWN              | HRS                                             | 20        |          | TSN 0    |                           |           |                            |                  |
| WC#: 79.070             | ENC                                             | 12        |          | TSN 0    |                           |           |                            |                  |
| PROC. REF: LMM 79-20-09 |                                                 |           |          |          |                           |           |                            |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                 | Unit                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------|---------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 79 - OIL            |                                       |           |          |          |                           |           |           |                  |
| 792140                  | NO. 2 ENGINE - UPPER OIL COOLER       |           |          |          |                           |           |           | Component ATA:79 |
| PN:158600-7             | MOS/MSC                               | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN              | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 79.070             | ENC                                   | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: LMM 79-20-09 |                                       |           |          |          |                           |           |           |                  |
| 792144                  | NO. 1 ENGINE OIL LOW PRESSURE SWITCH  |           |          |          |                           |           |           | Component ATA:79 |
| PN:HTE690012            | MOS/MSC                               | 11-Nov-96 | O/C      |          |                           |           |           |                  |
| SN:FR008AP              | HRS                                   | 20        |          | TSN 23   |                           |           |           |                  |
| WC#: 79.030             | AFL                                   |           |          |          |                           |           |           |                  |
| PROC. REF: AMM 79-33-11 |                                       |           |          |          |                           |           |           |                  |
| 792145                  | NO. 2 ENGINE OIL LOW PRESSURE SWITCH  |           |          |          |                           |           |           | Component ATA:79 |
| PN:HTE690012            | MOS/MSC                               | 21-Feb-96 | O/C      |          |                           |           |           |                  |
| SN:FRTR054AS            | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 79.030             | AFL                                   | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 79-33-11 |                                       |           |          |          |                           |           |           |                  |
| 792150                  | NO. 1 ENGINE - LOWER LEFT OIL COOLER  |           |          |          |                           |           |           | Component ATA:79 |
| PN:PN                   | MOS/MSC                               | 11-Nov-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN              | HRS                                   | 20        |          | TSN 0    |                           |           |           |                  |
| WC#: 79.080             | ENC                                   | 12        |          | TSN 0    |                           |           |           |                  |
| PROC. REF: LMM 79-20-09 |                                       |           |          |          |                           |           |           |                  |
| 792150                  | NO. 2 ENGINE - LOWER LEFT OIL COOLER  |           |          |          |                           |           |           | Component ATA:79 |
| PN:159900-3             | MOS/MSC                               | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN              | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 79.080             | ENC                                   | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: LMM 79-20-09 |                                       |           |          |          |                           |           |           |                  |
| 792160                  | NO. 1 ENGINE - LOWER RIGHT OIL COOLER |           |          |          |                           |           |           | Component ATA:79 |
| PN:PN                   | MOS/MSC                               | 11-Nov-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN              | HRS                                   | 20        |          | TSN 0    |                           |           |           |                  |
| WC#: 79.090             | ENC                                   | 12        |          | TSN 0    |                           |           |           |                  |
| PROC. REF: LMM 79-20-09 |                                       |           |          |          |                           |           |           |                  |
| 792160                  | NO. 2 ENGINE - LOWER RIGHT OIL COOLER |           |          |          |                           |           |           | Component ATA:79 |
| PN:159910-3             | MOS/MSC                               | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN              | HRS                                   | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 79.090             | ENC                                   | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: LMM 79-20-09 |                                       |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                 | Unit                                     | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|-------------------------|------------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 79 - OIL            |                                          |           |          |          |                           |           |           |                  |
| 792170                  | NO. 1 ENGINE - OIL TEMPERATURE REGULATOR |           |          |          |                           |           |           | Component ATA:79 |
| PN:PN                   | MOS/MSC                                  | 11-Nov-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN              | HRS                                      | 20        |          | TSN 0    |                           |           |           |                  |
| WC#: 79.100             | ENC                                      | 12        |          | TSN 0    |                           |           |           |                  |
| PROC. REF: LMM 79-20-07 |                                          |           |          |          |                           |           |           |                  |
| 792170                  | NO. 2 ENGINE - OIL TEMPERATURE REGULATOR |           |          |          |                           |           |           | Component ATA:79 |
| PN:158610-8             | MOS/MSC                                  | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN              | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 79.100             | ENC                                      | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: LMM 79-20-07 |                                          |           |          |          |                           |           |           |                  |
| 793001                  | NO. 1 ENGINE OIL PRESSURE TRANSMITTER    |           |          |          |                           |           |           | Component ATA:79 |
| PN:695-4-22             | MOS/MSC                                  | 11-Nov-96 | O/C      |          |                           |           |           |                  |
| SN:BY6986               | HRS                                      | 20        |          | TSN 23   |                           |           |           |                  |
| WC#: 79.040             | AFL                                      |           |          |          |                           |           |           |                  |
| PROC. REF: AMM 79-32-11 |                                          |           |          |          |                           |           |           |                  |
| 793002                  | NO. 2 ENGINE OIL PRESSURE TRANSMITTER    |           |          |          |                           |           |           | Component ATA:79 |
| PN:695-4-22             | MOS/MSC                                  | 21-Feb-96 | O/C      |          |                           |           |           |                  |
| SN:BY6743               | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 79.040             | AFL                                      | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 79-32-11 |                                          |           |          |          |                           |           |           |                  |
| 793037                  | NO. 1 ENGINE OIL PRESSURE INDICATOR      |           |          |          |                           |           |           | Component ATA:79 |
| PN:2121-01-0014         | MOS/MSC                                  | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:BG75809              | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 79.045             | AFL                                      | 0         |          |          |                           |           |           |                  |
| 793038                  | NO. 2 ENGINE OIL PRESSURE INDICATOR      |           |          |          |                           |           |           | Component ATA:79 |
| PN:2121-01-0014         | MOS/MSC                                  | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:BG75817              | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 79.045             | AFL                                      | 0         |          |          |                           |           |           |                  |
| 793049                  | NO. 1 ENGINE OIL TEMPERATURE INDICATOR   |           |          |          |                           |           |           | Component ATA:79 |
| PN:2121-01-0013         | MOS/MSC                                  | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:BG75869              | HRS                                      | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 79.050             | AFL                                      | 0         |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 800XP Serial: 258300 RegNo: N950PC HRS: 6528.3 AFL: 3929 As Of: 29-Jan-2023

31-Jan-2023 04:44 PM

| PN & SN                   | Unit                                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---------------------------|-----------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| ATA 79 - OIL              |                                         |           |          |          |                           |           |           |                  |
| 793050                    | NO. 2 ENGINE OIL TEMPERATURE INDICATOR  |           |          |          |                           |           |           | Component ATA:79 |
| PN:2121-01-0013           | MOS/MSC                                 | 30-May-96 | O/C      |          |                           |           |           |                  |
| SN:BG75872                | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 79.050               | AFL                                     | 0         |          |          |                           |           |           |                  |
| 793110                    | NO. 1 ENGINE - OIL PRESSURE TRANSMITTER |           |          |          |                           |           |           | Component ATA:79 |
| PN:PN                     | MOS/MSC                                 | 11-Nov-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                     | 20        |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                     | 12        |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                         |           |          |          |                           |           |           |                  |
| 793110                    | NO. 2 ENGINE - OIL PRESSURE TRANSMITTER |           |          |          |                           |           |           | Component ATA:79 |
| PN:PN                     | MOS/MSC                                 | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: GENERIC NO REF |                                         |           |          |          |                           |           |           |                  |
| 793320                    | NO. 1 ENGINE - FUEL/OIL COOLER          |           |          |          |                           |           |           | Component ATA:79 |
| PN:PN                     | MOS/MSC                                 | 11-Nov-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                     | 20        |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                     | 12        |          | TSN 0    |                           |           |           |                  |
| PROC. REF: LMM 79-10-01   |                                         |           |          |          |                           |           |           |                  |
| 793320                    | NO. 2 ENGINE - FUEL/OIL COOLER          |           |          |          |                           |           |           | Component ATA:79 |
| PN:PN                     | MOS/MSC                                 | 30-May-96 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN                | HRS                                     | 0         |          | TSN 0    |                           |           |           |                  |
|                           | ENC                                     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: LMM 79-10-01   |                                         |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task