

N390AA

2012 Beech Premier IA

Airworthiness Directives

MSN: RB-293



Prepared by the worldwide aviation specialists at RidgeAire, Inc.



Status Report

PREMIER IA

S/N RB-293 N390AA

OWNER: AIR BC, LLC
ADDRESS: PO BOX 249
HEWITT TX 76643

OPERATOR: AIR BC, LLC
ADDRESS: PO BOX 249
HEWITT TX 76643

OFFICE:
FAX:

OFFICE:
FAX:

ANALYST: WADE HOAGBOON
EMAIL: WHOAGBOON@CAMPSYSTEMS.COM

1-316-462-2455 (DIRECT)
+1-631-588-3200 (MAIN)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (EFAX-CARDS)

PLEASE REACH OUT TO YOUR ANALYST TO
RECORD CHANGES TO ADDRESS, LAST ACTUALS
(IF ANY).

AIRCRAFT SERIAL/REGNO: RB-293/N390AA MODEL: PREMIER IA MANUFACTURER: TEXTRON AVIATION INC.

CERTIFICATION DATE: 27-JUN-2012

LAST ACTUALS:
2066.8 A/C HRS as of 03-JAN-2025
1714 AFL as of 03-JAN-2025
1637.2 ACH as of 17-JUN-2024

ENGINE NO. 1 SERIAL/PART: 105499/FJ44-2A MODEL: FJ44-2A MANUFACTURER: WILLIAMS INTERNATIONAL

INSTALLED ON: 27-JUN-2012

0 ENG. HRS 0 A/C HRS
0 ENC

LAST ACTUALS:
2066.8 ENG. HRS as of 03-JAN-2025
1714 ENC as of 03-JAN-2025

ENGINE NO. 2 SERIAL/PART: 105498/FJ44-2A MODEL: FJ44-2A MANUFACTURER: WILLIAMS INTERNATIONAL

INSTALLED ON: 27-JUN-2012

0 ENG. HRS 0 A/C HRS
0 ENC

LAST ACTUALS:
2066.8 ENG. HRS as of 03-JAN-2025
1714 ENC as of 03-JAN-2025



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 00 - INFORMATION

SC 246	LANDING PERFORMANCE AWARENESS, SAFETY COMMUNIQUE							Bulletin	ATA:00
	MOS/MSC		-					INFORMATIONAL	
	HRS	0							
	AFL	0							

SC 258	WET AND CONTAMINATED RUNWAY PERFORMANCE AWARENESS, SAFETY COMMUNIQUE							Bulletin	ATA:00
	MOS/MSC		-					INFORMATIONAL	
	HRS	0							
	AFL	0							

ATA 05 - TIME LIMITS/MAINTENANCE CHECKS

PSID WIPSID-05-1000 R04	NO. 1 ENGINE - UNSERVICEABLE PARTS - NOTIFICATION, PRODUCT SUPPORT INFORMATIONAL DOCUMENT							Bulletin	ATA:05
	MOS/MSC		-					INFORMATIONAL	
	HRS								
	ENC								

PSID WIPSID-05-1000 R04	NO. 2 ENGINE - UNSERVICEABLE PARTS - NOTIFICATION, PRODUCT SUPPORT INFORMATIONAL DOCUMENT							Bulletin	ATA:05
	MOS/MSC		-					INFORMATIONAL	
	HRS								
	ENC								

PSID WIPSID-05-1000 R05	NO. 1 ENGINE - UNSERVICEABLE PARTS - NOTIFICATION, PRODUCT SUPPORT INFORMATIONAL DOCUMENT							Bulletin	ATA:05
	MOS/MSC		-					INFORMATIONAL	
	HRS								
	ENC								

PSID WIPSID-05-1000 R05	NO. 2 ENGINE - UNSERVICEABLE PARTS - NOTIFICATION, PRODUCT SUPPORT INFORMATIONAL DOCUMENT							Bulletin	ATA:05
	MOS/MSC		-					INFORMATIONAL	
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 05 - TIME LIMITS/MAINTENANCE CHECKS

PSID WIPSID-05-1000 R06	NO. 1 ENGINE - UNSERVICEABLE PARTS - NOTIFICATION, PRODUCT SUPPORT INFORMATIONAL DOCUMENT							Bulletin	ATA:05
----------------------------	---	--	--	--	--	--	--	----------	--------

MOS/MSC	-							INFORMATIONAL	
HRS									
ENC									

PSID WIPSID-05-1000 R06	NO. 2 ENGINE - UNSERVICEABLE PARTS - NOTIFICATION, PRODUCT SUPPORT INFORMATIONAL DOCUMENT							Bulletin	ATA:05
----------------------------	---	--	--	--	--	--	--	----------	--------

MOS/MSC	-							INFORMATIONAL	
HRS									
ENC									

PSID WIPSID-05-1003	NO. 1 ENGINE - TIME LIMITS/MAINTENANCE CHECKS - FORMS, PRODUCT SUPPORT INFORMATIONAL DOCUMENT							Bulletin	ATA:05
---------------------	---	--	--	--	--	--	--	----------	--------

MOS/MSC	-								
HRS									
ENC									

PSID WIPSID-05-1003	NO. 2 ENGINE - TIME LIMITS/MAINTENANCE CHECKS - FORMS, PRODUCT SUPPORT INFORMATIONAL DOCUMENT							Bulletin	ATA:05
---------------------	---	--	--	--	--	--	--	----------	--------

MOS/MSC	-								
HRS									
ENC									

PSID WIPSID-05-1003 R01	NO. 1 ENGINE - TIME LIMITS/MAINTENANCE CHECKS - FORMS, PRODUCT SUPPORT INFORMATIONAL DOCUMENT							Bulletin	ATA:05
----------------------------	---	--	--	--	--	--	--	----------	--------

MOS/MSC	-								
HRS									
ENC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
PSID WIPSID-05-1003 R01	NO. 2 ENGINE - TIME LIMITS/MAINTENANCE CHECKS - FORMS, PRODUCT SUPPORT INFORMATIONAL DOCUMENT								Bulletin	ATA:05
	MOS/MSC		-							
	HRS									
	ENC									
SB FJ44-05-002 R01	NO. 1 ENGINE - UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R02), SERVICE BULLETIN								Bulletin	ATA:05
	MOS/MSC		-					INFORMATIONAL		
	HRS									
	ENC									
SB FJ44-05-002 R01	NO. 2 ENGINE - UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R02), SERVICE BULLETIN								Bulletin	ATA:05
	MOS/MSC		-					INFORMATIONAL		
	HRS									
	ENC									
SB FJ44-05-002 R04	NO. 1 ENGINE - UNSERVICEABLE PARTS - NOTIFICATION, SERVICE BULLETIN								Bulletin	ATA:05
	MOS/MSC		-					INFORMATIONAL		
	HRS									
	ENC									
SB FJ44-05-002 R04	NO. 2 ENGINE - UNSERVICEABLE PARTS - NOTIFICATION, SERVICE BULLETIN								Bulletin	ATA:05
	MOS/MSC		-					INFORMATIONAL		
	HRS									
	ENC									
SB FJ44-05-002 R05	NO. 1 ENGINE - UNSERVICEABLE PARTS - NOTIFICATION, SERVICE BULLETIN								Bulletin	ATA:05
	MOS/MSC		-					INFORMATIONAL		
	HRS									
	ENC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS										
SB FJ44-05-002 R05	NO. 2 ENGINE - UNSERVICEABLE PARTS - NOTIFICATION, SERVICE BULLETIN								Bulletin	ATA:05
	MOS/MSC		-					INFORMATIONAL		
	HRS									
	ENC									
SB FJ44-05-002 R05-CN	NO. 1 ENGINE - SUPERSEDED - UNSERVICEABLE PARTS - NOTIFICATION (THIS SERVICE DOCUMENT HAS BEEN SUPERSEDED BY WIPSID -05-1000), SERVICE BULLETIN								Bulletin	ATA:05
	MOS/MSC		-					CANCELLED		
	HRS									
	ENC									
SB FJ44-05-002 R05-CN	NO. 2 ENGINE - SUPERSEDED - UNSERVICEABLE PARTS - NOTIFICATION (THIS SERVICE DOCUMENT HAS BEEN SUPERSEDED BY WIPSID -05-1000), SERVICE BULLETIN								Bulletin	ATA:05
	MOS/MSC		-					CANCELLED		
	HRS									
	ENC									
ATA 22 - AUTO FLIGHT										
SC 259	ROCKWELL COLLINS DIGITAL AUTOPILOT VERTICAL MODE SELECTION ANOMALY, SAFETY COMMUNIQUE								Bulletin	ATA:22
	MOS/MSC		-					INFORMATIONAL		
	HRS	0								
	AFL	0								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 23 - COMMUNICATIONS

FAA 2013-18-09 ^S	APPLIANCE AD - EMERGENCY LOCATOR TRANSMITTER - BATTERY WIRING DISCREPANCIES - HONEYWELL ASCA INC (SUPERSEDED BY FAA AD 2014-17-02)							AD	ATA:23
	DAYS/MSC	29-May-14	-					MANDATORY	
	HRS	195.2							
	AFL	193							

Category: APPLIANCE

MOC: NOT APPLICABLE - NA. THIS AD DOES NOT AFFECTS THE COMPONENTS INSTALLED IN THIS AIRCRAFT WITH P/N 453-500-366. THIS AD ONLY APPLIES TO THE COMPONENT WITH P/N 1152682-1, -2 AND -3 INSTALLED.

SB 23-4087	COMMUNICATIONS - INSTALLATION OF HF COMM SYSTEM, SERVICE BULLETIN							Bulletin	ATA:23
	MOS/MSC		-					OPTIONAL	
	HRS	0							
	AFL	0							

ATA 24 - ELECTRICAL POWER

SB 24-3721	ELECTRICAL POWER - MAIN BATTERY SPARES REPLACEMENT, SERVICE BULLETIN							Bulletin	ATA:24
	MOS/MSC		-					OPTIONAL	
	HRS	0							
	AFL	0							

ATA 25 - EQUIPMENT/FURNISHINGS

FAA 2017-16-01 ^S	APPLIANCE AD - EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS							AD	ATA:25
	MOS/MSC	24-Oct-17	-					MANDATORY	
	HRS	852.5							
	AFL	866							

Category: APPLIANCE

MOC: NOT APPLICABLE - BECAUSE THE AIRCRAFT DOES NOT HAVE INSTALLED THE EMERGENCY LOCATOR TRANSMITTER MODEL AFFECTED, THE AIRCRAFT HAVE INSTALLED AND ELT OF ARTEX AIRCRAFT SUPPLIES.

FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS							AD	ATA:25
	MOS/MSC	24-Oct-17	-						
	HRS	852.5							
	AFL	866							

Category: APPLIANCE

MOC: NOT APPLICABLE - BECAUSE THE AIRCRAFT DOES NOT HAVE INSTALLED THE EMERGENCY LOCATOR TRANSMITTER MODEL AFFECTED, THE AIRCRAFT HAVE INSTALLED AND ELT OF ARTEX AIRCRAFT SUPPLIES.

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 25 - EQUIPMENT/FURNISHINGS

FAA 2017-16-01 PARA (S)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT							AD	ATA:25
	MOS/MSC	24-Oct-17	-					MANDATORY	
	HRS	852.5							
	AFL	866							

Category: APPLIANCE

MOC: NOT APPLICABLE - BECAUSE THE AIRCRAFT DOES NOT HAVE INSTALLED THE EMERGENCY LOCATOR TRANSMITTER MODEL AFFECTED, THE AIRCRAFT HAVE INSTALLED AND ELT OF ARTEX AIRCRAFT SUPPLIES.

FAA 2021-07-13	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT							AD	ATA:25
	MOS/MSC	21-Mar-24	-					MANDATORY	
	HRS	2032							
	AFL	1683							

Category: APPLIANCE

MOC: NOT APPLICABLE - FOUND AD IS NOT APPLICABLE TO THIS AIRCRAFT BY EQUIPMENT MANUFACTURER. (HAS AM SAFE)

FAA 2021-07-13 PARA (E) (1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE							AD	ATA:25
	MOS/MSC	21-Mar-24	-					MANDATORY	
	HRS	2032							
	AFL	1683							

Category: APPLIANCE

MOC: NOT APPLICABLE - FOUND AD IS NOT APPLICABLE TO THIS AIRCRAFT BY EQUIPMENT MANUFACTURER. (HAS AM SAFE)

FAA 2021-07-13 PARA (E) (2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE							AD	ATA:25
	MOS/MSC	21-Mar-24	-					MANDATORY	
	HRS	2032							
	AFL	1683							

Category: APPLIANCE

MOC: NOT APPLICABLE - FOUND AD IS NOT APPLICABLE TO THIS AIRCRAFT BY EQUIPMENT MANUFACTURER. (HAS AM SAFE)



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 25 - EQUIPMENT/FURNISHINGS

FAA 2021-07-13 PARA (E) (3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER							AD	ATA:25
	MOS/MSC	21-Mar-24	-					MANDATORY	
	HRS	2032							
	AFL	1683							

Category: APPLIANCE

MOC: NOT APPLICABLE - FOUND AD IS NOT APPLICABLE TO THIS AIRCRAFT BY EQUIPMENT MANUFACTURER. (HAS AM SAFE)

SB SB 25-4155 ^{U S}	SB 25-4155 EQUIPMENT AND FURNISHINGS - INSPECTION/REPLACEMENT OF CABIN SEAT BELT BUCKLES							Bulletin	ATA:25
------------------------------	--	--	--	--	--	--	--	----------	--------

	MOS/MSC	29-May-15	-						
	HRS	394							
	AFL	394							

MOC: NOT APPLICABLE - NA. C/W REV 1

SB SB 25-4155 R1 ^{U S}	SB 25-4155 REV 1 EQUIPMENT AND FURNISHINGS - INSPECTION/REPLACEMENT OF CABIN SEAT BELT BUCKLES							Bulletin	ATA:25
---------------------------------	--	--	--	--	--	--	--	----------	--------

	MOS/MSC	29-May-15	-						
	HRS	394							
	AFL	394							

MOC: NOT APPLICABLE - NA. NOT AFFECTED THIS AIRCRAFT PER MODEL AS A REFERENCE AFFECTIVITY PARAGRAPH A-1.

ATA 28 - FUEL

SC 208	LOW FUEL QUANTITY ANNUNCIATION, SAFETY COMMUNIQUE							Bulletin	ATA:28
--------	---	--	--	--	--	--	--	----------	--------

	MOS/MSC		-					INFORMATIONAL	
	HRS	0							
	AFL	0							

SL SL390-28-01	FUEL - MICROBIOLOGICAL CONTAMINATION IN AIRCRAFT FUEL TANKS AND FUEL SYSTEMS, SERVICE LETTER							Bulletin	ATA:28
----------------	--	--	--	--	--	--	--	----------	--------

	MOS/MSC		-					INFORMATIONAL	
	HRS								
	AFL								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 29 - HYDRAULIC POWER										
COM 51	PREMIER I/IA COMMUNIQUE - HYDRAULIC POWER - ENGINE DRIVEN HYDRAULIC PUMP, COMMUNIQUE								Bulletin	ATA:29
	MOS/MSC		-							
	HRS									
	AFL									
FAA 2017-18-11	HYDRAULIC POWER - INSPECT THE AIRPLANE TO DETERMINE IF ANY AFFECTED SN EDP, (P/N) 66179-01 (BEECHCRAFT/TEXTRON P/N 390-389022-0003), IS INSTALLED ON THE AIRPLANE / REPLACE ANY AFFECTED SN EDP, P/N 66179-01 (BEECHCRAFT/TEXTRON P/N 390-389022-0003), WITH A SERVICEABLE SN EDP, P/N 66179-01 (P/N 390-389022-0003) THAT IS EITHER NOT LISTED IN TABLE 1 OF PARKER SB 66179-29-486, OR HAS BEEN REWORKED FOLLOWING PARKER SB 66179-29-486 (IF ANY AFFECTED SN EDP WAS FOUND DURING THE INSPECTION)								AD	ATA:29
	MOS/MSC	23-Oct-17	-					MANDATORY		
	HRS	852.5								
	AFL	866								
MOC: NOT APPLICABLE - A/C DOESN'T HAVE INSTALLED SN AFFECTED IN ACCORDANCE OF PARKER SERVICE BULLETIN 66179-29-486 TABLE 1 SECTION A										
SB 29-4161	HYDRAULIC POWER - PARKER ENGINE DRIVEN HYDRAULIC PUMP, SERVICE BULLETIN								Bulletin	ATA:29
	MOS/MSC	14-Feb-17	-					MANDATORY		
	HRS	758.25								
	AFL	773								
MOC: NOT APPLICABLE - BECAUSE THE AIRCRAFT DON'T HAVE INSTALL THE S/N (S/N ON: K0632) AFFECTED IN ACCORDANCE OF PARKER SERVICE BULLETIN 66179-29-486, TABLE 1										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 31 - INDICATING/RECORDING SYSTEMS

COM ALL-004	INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION, COMMUNIQUE							Bulletin	ATA:31
	MOS/MSC		-					INFORMATIONAL	
	HRS								
	AFL								

FAA 2021-23-12	APPLIANCE AD - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS							AD	ATA:31
	MOS/MSC	05-Jan-22	-					MANDATORY	
	HRS	1636.1							
	AFL	1439							

Category: APPLIANCE

MOC: COMPLIED WITH

FAA 2023-10-02	APPLIANCE AD - INDICATING/RECORDING SYSTEM/NAVIGATION - RADIO ALTIMETER - AFM REVISION							AD	ATA:31
	MOS/MSC	10-Jul-23	-					MANDATORY	
	HRS	1970.3							
	AFL	1639							

Category: APPLIANCE

MOC: COMPLIED WITH - COMPLIED WITH FAA 2023-10-02 APPLIANCE AD - INDICATING/RECORDING SYSTEM/NAVIGATION - RADIO ALTIMETER - AFM REVISION, AD REQUIRED INFORMATION ADDED TO AFM LIMITATIONS SECTION.

FAA 2023-10-02 PARA (F ⁵)	REVISE THE LIMITATIONS SECTION OF THE EXISTING AFM (UNTIL 30--JUNE- 2023 - SATISFIED BY FAA 2021-23-12)							AD	ATA:31
	MOS/MSC	10-Jul-23	-					MANDATORY	
	HRS	1970.3							
	AFL	1639							

MOC: COMPLIED WITH

FAA 2023-10-02 PARA (I)	REVISE THE LIMITATIONS SECTION AND REMOVE THE AFM REVISION REQUIRED BY PARA (H) (AFTER 30 JUN 2023)							AD	ATA:31
	MOS/MSC	10-Jul-23	-					MANDATORY	
	HRS	1970.3							
	AFL	1639							

Category: APPLIANCE

MOC: COMPLIED WITH

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 32 - LANDING GEAR

FAA 2012-17-01 ^S	AD 2012-17-01 [EFFECTIVE DATE: 13 SEP 2012] GOODYEAR AVIATION TIRE FAILURE								AD ATA:32
	MOS/MSC	24-Jul-14	-					MANDATORY	
	HRS	210.2							
	AFL	209							

MOC: NOT APPLICABLE - NA. THIS AD DOES NOT APPLY DUE TO THE AIRCRAFT HAS THE FOLLOWING TIRE SPECIFICATIONS. TIRE SIZE: H22X8.25-10, PLY RATING: 12, SPEED RATING: 190H

SB 32-4072 LANDING GEAR - BRAKE ACCUMULATOR SERVICE RELOCATION, SERVICE BULLETIN

SB 32-4072	LANDING GEAR - BRAKE ACCUMULATOR SERVICE RELOCATION, SERVICE BULLETIN								Bulletin ATA:32
	MOS/MSC		-					OPTIONAL	
	HRS	0							
	AFL	0							

ATA 34 - NAVIGATION

FAA 2012-26-15 ^{U S}	AD 2012-26-15 [EFFECTIVE DATE: 24 JAN 2013] HONEYWELL AIR DATA PRESSURE TRANSDUCERS (RESCINDED BY AD 2012-26-15R1)								AD ATA:34
	MOS/MSC	29-May-14	-						
	HRS	195.2							
	AFL	193							

MOC: NOT APPLICABLE - NA. THIS AD DOES NOT AFFECTS THE COMPONENTS INSTALLED IN THIS AIRCRAFT WITH P/N 822-1109-016(ROCKWELL COLLINS).

FAA 2012-26-15 R01 ^S AIR DATA PRESSURE TRANSDUCERS, AS INSTALLED IN AIR DATA COMPUTERS (ADC), AIR DATA MODULES (ADM), AIR DATA ATTITUDE HEADING REFERENCE SYSTEMS (ADAHRS), AND DIGITAL AIR DATA COMPUTERS (DADC)

FAA 2012-26-15 R01 ^S	AIR DATA PRESSURE TRANSDUCERS, AS INSTALLED IN AIR DATA COMPUTERS (ADC), AIR DATA MODULES (ADM), AIR DATA ATTITUDE HEADING REFERENCE SYSTEMS (ADAHRS), AND DIGITAL AIR DATA COMPUTERS (DADC)								AD ATA:34
	MOS/MSC	16-Feb-15	-					MANDATORY	
	HRS	327.7							
	AFL	327							

MOC: NOT APPLICABLE - NA. AD DOES NOT AFFECTS THE COMPONENTS INSTALLED IN THIS AIRCRAFT WITH P/N 822-1109-016 (ROCKWELL COLLINS). THIS AD ONLY APPLIES TO HONEYWELL COMPONENTS INSTALLED.

FAA 2014-05-27 APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. TPR-720 AND TPR-900 MODE S TRANSPONDERS - TEST AND CALIBRATION

FAA 2014-05-27	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. TPR-720 AND TPR-900 MODE S TRANSPONDERS - TEST AND CALIBRATION								AD ATA:34
	MOS/MSC	15-Jul-14	-					MANDATORY	
	HRS	208.9							
	AFL	207							

Category: APPLIANCE

MOC: NOT APPLICABLE - NA. THIS AD DOES NOT AFFECTS THE COMPONENT INSTALLED IN THIS AIRCRAFT WITH COMPONENT MODEL TDR94D P/N 622-9210-008 S/N 491XD/491WY.

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 34 - NAVIGATION

FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION							AD	ATA:34
	MOS/MSC	08-Oct-16	-					MANDATORY	
	HRS	659.3							
	AFL	677							

Category: APPLIANCE

MOC: COMPLIED WITH - FOUND THE AIRCRAFT CONFIGURATION STRAPPING TYPE 0, NO FURTHER ACTION REQUIRE

FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS							AD	ATA:34
	MOS/MSC	21-Mar-24	-					MANDATORY	
	HRS	2032							
	AFL	1683							

Category: APPLIANCE

MOC: NOT APPLICABLE - FOUND NOT APPLICABLE PER EQUIPMENT NOT INSTALLED. NO ACTION REQD.

FAA 2015-10-51-E	APPLIANCE/EMERGENCY AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.							AD	ATA:34
	MOS/MSC	21-Mar-24	-					MANDATORY	
	HRS	2032							
	AFL	1683							

Category: APPLIANCE, EMERGENCY

MOC: NOT APPLICABLE - FOUND NOT APPLICABLE PER EQUIPMENT NOT INSTALLED. NO ACTION REQD.

FAA 2020-10-05	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS PRO LINE 4 AND PRO LINE 21 FLIGHT MANAGEMENT SYSTEMS							AD	ATA:34
	MOS/MSC	29-Jun-21	-					MANDATORY	
	HRS	1533.1							
	AFL	1373							

Category: APPLIANCE

MOC: COMPLIED WITH - COMPLIED WITH AD 2020-10-05 EFFECTIVE JUNE/24/2020. REMOVED #1 CSU-3100 P/N 822-1363-002 S/N 4B1LT AND #2 CSU-3100 P/N 822-1363-002 S/N 4B1LR. PLACED WORD 10 SWITCH 4 IS SET TO 0 PER ROCKWELL COLLINS SERVICES INFORMATION LETTER CSU-XX00-18-1 DATED JUNE/27/2018 ON BOTH CSU'S. CONFIRMED TEMPERATURE COMPENSATION IS NOT VISIBLE ON BOTH FMS CDU. INSTALLED #1 CSU-3100 P/N822-1363-002 S/N 4B1LT AND #2 CSU-3100 P/N 822-1363-002 S/N 4B1LR. OPERATIONAL CHECK SATISFACTORY IAW ROCKWELL COLLINS PREMIER IA AVIONICS SYSTEM WITH IFIS MAINTENANCE MANUAL NO.523-0807233.

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 34 - NAVIGATION

FAA 2021-05-17	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS FDSA-6500 FLIGHT DISPLAY SYSTEM - OPERATING LIMITIATIONS / SOFTWARE UPGRADE							AD	ATA:34
	MOS/MSC	21-Mar-24	-					MANDATORY	
	HRS	2032							
	AFL	1683							

Category: APPLIANCE

MOC: NOT APPLICABLE - FOUND NOT APPLICABLE TO PROLINE 21 AIRCRAFT.

FAA 2021-05-17 PARA (G) (1) & (G)(2)	REVISE THE AIRCRAFT FLIGHT MANUAL (AFM) OR AFM SUPPLEMENT (AFMS), FABRICATE A PLACARD FOR EACH PRIMARY FLIGHT DISPLAY AND INSTALL THE PLACARD ON THE BOTTOM OF EACH PRIMARY FLIGHT DISPLAY BEZEL (RESTATEMENT OF FAA AD 2019-12-09)							AD	ATA:34
	MOS/MSC	21-Mar-24	-					MANDATORY	
	HRS	2032							
	AFL	1683							

Category: APPLIANCE

MOC: NOT APPLICABLE - FOUND NOT APPLICABLE TO PROLINE 21 AIRCRAFT.

FAA 2021-05-17 PARA (G) (3)	UPGRADE THE FDSA-6500 FIELD LOADABLE SOFTWARE							AD	ATA:34
	MOS/MSC	21-Mar-24	-					MANDATORY	
	HRS	2032							
	AFL	1683							

Category: APPLIANCE

MOC: NOT APPLICABLE - FOUND NOT APPLICABLE TO PROLINE 21 AIRCRAFT.

FAA 2021-05-17 PARA (G) (5)	AS OF THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL A ROCKWELL COLLINS FLIGHT DISPLAY SYSTEM APPLICATION FDSA-6500 P/N 810-0234-1H0001, 810-0234-1H0002, 810-0234-1H0003, 810-0234-2H0001, 810-0234-2C0001, 810-0234-2C0002, OR 810-0234-4B0001 ON ANY AIRPLANE							AD	ATA:34
	MOS/MSC	21-Mar-24	-					MANDATORY	
	HRS	2032							
	AFL	1683							

Category: APPLIANCE

MOC: NOT APPLICABLE - FOUND NOT APPLICABLE TO PROLINE 21 AIRCRAFT.



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 34 - NAVIGATION										
FAA 2021-08-07	APPLIANCE AD - ROCKWELL COLLINS - GLOBAL POSITIONING SYSTEM GPS-4000S - UPGRADE								AD	ATA:34
	MOS/MSC	21-Mar-24	-					MANDATORY		
	HRS	2032								
	AFL	1683								
Category: APPLIANCE										
MOC: NOT APPLICABLE - FOUND NOT APPLICABLE PER GPS UNIT P/N INSTALLED. (HAS A -004)										
FAA 2021-08-07 PARA (G) (1)	REPLACE EACH GPS-4000S GPS P/N 822-2189-100 WITH A GPS THAT DOES NOT HAVE P/N 822-2189-100								AD	ATA:34
	MOS/MSC	21-Mar-24	-					MANDATORY		
	HRS	2032								
	AFL	1683								
Category: APPLIANCE										
MOC: NOT APPLICABLE - FOUND NOT APPLICABLE PER GPS UNIT P/N INSTALLED. (HAS A -004)										
FAA 2021-08-07 PARA (G) (2)	DO NOT INSTALL GPS-4000S GPS P/N 822-2189-100 ON ANY AIRPLANE								AD	ATA:34
	MOS/MSC	21-Mar-24	-					MANDATORY		
	HRS	2032								
	AFL	1683								
Category: APPLIANCE										
MOC: NOT APPLICABLE - FOUND NOT APPLICABLE PER GPS UNIT P/N INSTALLED. (HAS A -004)										
FAA 2021-08-15	APPLIANCE AD - NAVIGATION - GARMIN INTERNATIONAL GMN-00962 GTS PROCESSOR UNITS, PART NUMBER 011-02571-0() - SOFTWARE UPATE								AD	ATA:34
	MOS/MSC	21-Mar-24	-					MANDATORY		
	HRS	2032								
	AFL	1683								
Category: APPLIANCE										
MOC: NOT APPLICABLE - FOUND NOT APPLICABLE PER EQUIP NOT INSTALLED.										
SB 34-3730	NAVIGATION - AVIONIC MODIFICATION FOR ENHANCED FLIGHT IDENTIFICATION, SERVICE BULLETIN								Bulletin	ATA:34
	MOS/MSC		-					OPTIONAL		
	HRS	0								
	AFL	0								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 34 - NAVIGATION										
SB 34-4088	NAVIGATION - INSTALLATION OF SECOND FLIGHT MANAGEMENT SYSTEM, SERVICE BULLETIN								Bulletin	ATA:34
	MOS/MSC		-					OPTIONAL		
	HRS	0								
	AFL	0								
<hr/>										
SB 34-4151	NAVIGATION - INTRODUCTION OF AUTOMATIC DEPENDENT SURVEILLANCE - BROADCAST OUT (ADS-B OUT) INSTALLATION KIT, SERVICE BULLETIN								Bulletin	ATA:34
	MOS/MSC		-					OPTIONAL		
	HRS									
	AFL									
<hr/>										
SB 34-4151 R01	NAVIGATION - INTRODUCTION OF AUTOMATIC DEPENDENT SURVEILLANCE - BROADCAST OUT (ADS-B OUT) INSTALLATION KIT, SERVICE BULLETIN								Bulletin	ATA:34
	MOS/MSC		-					OPTIONAL		
	HRS									
	AFL									
<hr/>										
SB 390-34-01	NAVIGATION - GPS TRANSPONDER WIRING MODIFICATION, SERVICE BULLETIN								Bulletin	ATA:34
	MOS/MSC		-					RECOMMENDED		
	HRS									
	AFL									
<hr/>										
SL SL390-34-01	NAVIGATION - IMPLEMENT AIRPLANE FLIGHT MANUAL CHANGES AFTER DISABLING LNAV/VNAV, SERVICE LETTER								Bulletin	ATA:34
	MOS/MSC	04-Apr-24	-					MANDATORY		
	HRS	2032								
	AFL	1683								
<hr/>										
MOC: COMPLIED WITH - ACCOMPLISHED MANDATORY SL 390-34-01, VERIFIED AD 2020-10-05 PREVIOUSLY ACCOMPLISHED ON 6/29/2021 (TEMPERATURE COMPENSATION TURNED OFF IAW COLLINS SERVICE LETTER CSU-XX00-18-1 ON BOTH CSU'S, AND INSTALLED SUPPLEMENT 390-590001-0103 AND TEMP CHANGE 390-590001-0003CTC13 IN FLIGHT MANUAL. THIS ACTION SATISFIES SL390-34-01.										
<hr/>										
SL SL390-34-02	NAVIGATION - TRANSMITTAL OF COLLINS AEROSPACE SERVICE BULLETIN ALT-4000-34-14, NAVIGATION - ALT 4000 POWER SUPPLY ROBUSTNESS IMPROVEMENT, SERVICE LETTER								Bulletin	ATA:34
	MOS/MSC		-					OPTIONAL		
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 34 - NAVIGATION

ATA 35 - OXYGEN

FAA 2011-14-08	APPLIANCE AD - INSPECT FOR FRACTURED AND SEPARATING IN-LINE FLOW INDICATORS OF THE OXYGEN MASK ASSEMBLY							AD	ATA:35
	MOS/MSC	21-Mar-24	-					MANDATORY	
	HRS	2032							
	AFL	1683							

Category: APPLIANCE

MOC: NOT APPLICABLE - FOUND NOT APPLICABLE PER MFG OF PASSENGER MASKS INSTALLED. (8/2019 AND 11/2019)

FAA 2012-11-09 R01	OXYGEN - INSTALLING A SUPPLEMENTAL OXYGEN SYSTEM IN AFFECTED LAVATORIES							AD	ATA:35
	MOS/MSC	17-Aug-18	-					MANDATORY	
	HRS	1001.27							
	AFL	994							

MOC: NOT APPLICABLE - AD DOES NOT APPLY BY NOT HAVING ANY OXYGEN GENERATOR INSTALLED IN THE BAN

FAA 2015-08-07	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESES							AD	ATA:35
	MOS/MSC	31-May-17	-					MANDATORY	
	HRS	818.42							
	AFL	839							

Category: APPLIANCE

MOC: NOT APPLICABLE - FOR THIS AIRCRAFT SN RB-293 DUE TO CREW OXYGEN MASK REGULATOR INSTALLED IS NOT AFFECTED

FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011							AD	ATA:35
	MOS/MSC	31-May-17	-					MANDATORY	
	HRS	818.42							
	AFL	839							

Category: APPLIANCE

MOC: NOT APPLICABLE - FOR THIS AIRCRAFT SN RB-293 DUE TO CREW OXYGEN MASK REGULATOR INSTALLED IS NOT AFFECTED



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 35 - OXYGEN

FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PAPERGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESES							AD	ATA:35
	MOS/MSC	31-May-17	-					MANDATORY	
	HRS	818.42							
	AFL	839							

Category: APPLIANCE

MOC: NOT APPLICABLE - FOR THIS AIRCRAFT SN RB-293 DUE TO CREW OXYGEN MASK REGULATOR INSTALLED IS NOT AFFECTED

FAA 2015-23-09	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS							AD	ATA:35
	MOS/MSC	07-Jan-16	-					MANDATORY	
	HRS	567.2							
	AFL	578							

Category: APPLIANCE

MOC: NOT APPLICABLE - THIS AD DOES NOT APPLY BECAUSE THE AIRCRAFT DOES NOT HAVE THE INSTALLED OXYGEN MASK REGULATOR PART NUMBER AFFECTED. MFG REF NUMBER: , DOC: AD 2015-23-09, REV: , ISSUED: 28 DEC 2015, SECTION: G

FAA 2015-23-09 PARA (G)	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER							AD	ATA:35
	MOS/MSC	07-Jan-16	-					MANDATORY	
	HRS	567.2							
	AFL	578							

Category: APPLIANCE

MOC: NOT APPLICABLE - THIS AD DOES NOT APPLY BECAUSE THE AIRCRAFT DOES NOT HAVE THE INSTALLED OXYGEN MASK REGULATOR PART NUMBER AFFECTED. MFG REF NUMBER: , DOC: AD 2015-23-09, REV: , ISSUED: 28 DEC 2015, SECTION: G

FAA 2015-23-09 PARA (H.1)	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).							AD	ATA:35
	MOS/MSC	07-Jan-16	-					MANDATORY	
	HRS	567.2							
	AFL	578							

Category: APPLIANCE

MOC: NOT APPLICABLE - THIS AD DOES NOT APPLY BECAUSE THE AIRCRAFT DOES NOT HAVE THE INSTALLED OXYGEN MASK REGULATOR PART NUMBER AFFECTED. MFG REF NUMBER: , DOC: AD 2015-23-09, REV: , ISSUED: 28 DEC 2015, SECTION: G



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 35 - OXYGEN

FAA 2015-23-09 PARA (H.2.I)	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1							AD	ATA:35
	MOS/MSC	07-Jan-16	-					MANDATORY	
	HRS	567.2							
	AFL	578							

Category: APPLIANCE

MOC: NOT APPLICABLE - THIS AD DOES NOT APPLY BECAUSE THE AIRCRAFT DOES NOT HAVE THE INSTALLED OXYGEN MASK REGULATOR PART NUMBER AFFECTED. MFG REF NUMBER: , DOC: AD 2015-23-09, REV: , ISSUED: 28 DEC 2015, SECTION: G

FAA 2015-23-09 PARA (H.2.II)	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."							AD	ATA:35
	MOS/MSC	07-Jan-16	-					MANDATORY	
	HRS	567.2							
	AFL	578							

Category: APPLIANCE

MOC: NOT APPLICABLE - THIS AD DOES NOT APPLY BECAUSE THE AIRCRAFT DOES NOT HAVE THE INSTALLED OXYGEN MASK REGULATOR PART NUMBER AFFECTED. MFG REF NUMBER: , DOC: AD 2015-23-09, REV: , ISSUED: 28 DEC 2015, SECTION: G

FAA 2015-23-09 PARA (I)	REGULATOR REPLACEMENT							AD	ATA:35
	MOS/MSC	07-Jan-16	-					MANDATORY	
	HRS	567.2							
	AFL	578							

Category: APPLIANCE

MOC: NOT APPLICABLE - THIS AD DOES NOT APPLY BECAUSE THE AIRCRAFT DOES NOT HAVE THE INSTALLED OXYGEN MASK REGULATOR PART NUMBER AFFECTED. MFG REF NUMBER: , DOC: AD 2015-23-09, REV: , ISSUED: 28 DEC 2015, SECTION: G

FAA 2016-11-20 ^S	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12							AD	ATA:35
	MOS/MSC	04-Oct-17	-					MANDATORY	
	HRS	852.5							
	AFL	866							

Category: APPLIANCE

MOC: NOT APPLICABLE - BY SUBJECT EQUIPMENT NOT INSTALLED ON AIRCRAFT



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 35 - OXYGEN

FAA 2016-11-20 PARA (S)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A..1 SUPERSEDED BY FAA AD 2017-18-12							AD	ATA:35
MOS/MSC	04-Oct-17	-						MANDATORY	
HRS	852.5								
AFL	866								

Category: APPLIANCE

MOC: NOT APPLICABLE - BY SUBJECT EQUIPMENT NOT INSTALLED ON AIRCRAFT

FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12							AD	ATA:35
MOS/MSC	04-Oct-17	-						MANDATORY	
HRS	852.5								
AFL	866								

Category: APPLIANCE

MOC: NOT APPLICABLE - BY SUBJECT EQUIPMENT NOT INSTALLED ON AIRCRAFT

FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12							AD	ATA:35
MOS/MSC	04-Oct-17	-						MANDATORY	
HRS	852.5								
AFL	866								

Category: APPLIANCE

MOC: NOT APPLICABLE - BY SUBJECT EQUIPMENT NOT INSTALLED ON AIRCRAFT

FAA 2017-18-12 (S)	OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES							AD	ATA:35
MOS/MSC	23-Oct-17	-						MANDATORY	
HRS	852.5								
AFL	866								

MOC: NOT APPLICABLE - N/A BECAUSE THE A/C DOESN'T HAVE INSTALLED THE PROTECTIVE BREATHING EQUIPMENT

FAA 2017-18-12 PARA (S)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED							AD	ATA:35
MOS/MSC	23-Oct-17	-						MANDATORY	
HRS	852.5								
AFL	866								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 35 - OXYGEN

MOC: NOT APPLICABLE - N/A BECAUSE THE A/C DOESN'T HAVE INSTALLED THE PROTECTIVE BREATHING EQUIPMENT

FAA 2017-18-12 PARA (I ^S)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED							AD	ATA:35
MOS/MSC	23-Oct-17	-						MANDATORY	
HRS	852.5								
AFL	866								

MOC: NOT APPLICABLE - N/A BECAUSE THE A/C DOESN'T HAVE INSTALLED THE PROTECTIVE BREATHING EQUIPMENT

FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.							AD	ATA:35
MOS/MSC	23-Oct-17	-						MANDATORY	
HRS	852.5								
AFL	866								

MOC: NOT APPLICABLE - N/A BECAUSE THE A/C DOESN'T HAVE INSTALLED THE PROTECTIVE BREATHING EQUIPMENT

FAA 2018-21-14	APPLIANCE AD - OXYGEN - OXYGEN MASK REGULATOR HARNESS INFLATION HOSES - INSPECTION / REPLACEMENT							AD	ATA:35
MOS/MSC	21-Mar-24	-						MANDATORY	
HRS	2032								
AFL	1683								

Category: APPLIANCE

MOC: NOT APPLICABLE - FOUND NOT APPLICABLE PER EQUIPMENT NOT INSTALLED. (HAS B/E AEROSPACE)

FAA 2018-21-14 PARA (G)	REQUIRED ACTIONS							AD	ATA:35
MOS/MSC	21-Mar-24	-						MANDATORY	
HRS	2032								
AFL	1683								

Category: APPLIANCE

MOC: NOT APPLICABLE - FOUND NOT APPLICABLE PER EQUIPMENT NOT INSTALLED. (HAS B/E AEROSPACE)



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 35 - OXYGEN

FAA 2018-21-14 PARA (H)	DO NOT INSTALL ON ANY AIRPLANE A FLIGHT CREW OXYGEN MASK REGULATOR WITH A P/N LISTED IN PLANNING INFORMATION, PARAGRAPH 1.A.(1), OF ZODIAC SB MC10-35-274 R02, DATED JUNE 25, 2014, UNLESS IT MEETS THE DEFINITION OF A PART ELIGIBLE FOR INSTALLATION IN PARA (I) OF THIS AD							AD	ATA:35
MOS/MSC	21-Mar-24	-						MANDATORY	
HRS	2032								
AFL	1683								

Category: APPLIANCE

MOC: NOT APPLICABLE - FOUND NOT APPLICABLE PER EQUIPMENT NOT INSTALLED. (HAS B/E AEROSPACE)

ATA 44 - CABIN SYSTEMS

FAA 2017-04-06	APPLIANCE AD - CABIN SYSTEMS - REPLACEMENT OF UNITED INSTRUMENTS INC. 5934 SERIES ALTIMETERS MANUFACTURED BETWEEN JANUARY 2015 AND FEBRUARY 2016							AD	ATA:44
MOS/MSC	23-Oct-17	-						MANDATORY	
HRS	852.5								
AFL	866								

Category: APPLIANCE

MOC: NOT APPLICABLE - A/C DOESN'T HAVE INSTALLED THE ALTIMETER PART NUMBER EFFECTED , ALSO THE INSTALLED ALTIMETER IS FROM AEROSONIC



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 52 - DOORS									
SB 256 ^U	SC 256, LH/RH AFT BAGGAGE AND MAINTENANCE BAY DOORS INSPECTION							Bulletin	ATA:52
	MOS/MSC		-						
	HRS	0							
	AFL	0							
<hr/>									
SB 52-3956	DOORS - INSTALLATION OF AIRFLOW DIVERTER KIT, SERVICE BULLETIN							Bulletin	ATA:52
	MOS/MSC		-					OPTIONAL	
	HRS	0							
	AFL	0							
<hr/>									
SB 52-4110	INTRODUCTION OF CABIN DOOR CABLE BOLT KIT (KIT 390-4014), SERVICE BULLETIN							Bulletin	ATA:52
	MOS/MSC	EFF	-					RECOMMENDED	
	HRS	EFF							
	AFL	EFF							
<hr/>									
SC 227	FORWARD AND AFT BAGGAGE, AVIONICS AND MAINTENANCE BAY DOORS, SAFETY COMMUNIQUE							Bulletin	ATA:52
	MOS/MSC		-					RECOMMENDED	
	HRS	0							
	AFL	0							
<hr/>									
ATA 56 - WINDOWS									
COM MC PR-053	PREMIER I/IA COMMUNIQUE - WINDOWS, COMMUNIQUE							Bulletin	ATA:56
	MOS/MSC		-						
	HRS								
	AFL								
<hr/>									
ATA 72 - ENGINE									
FAA 2022-13-15	NO. 1 ENGINE - TURBINE SECTION - HIGH-PRESSURE TURBINE (HPT) DISK - REPLACE							AD	ATA:72
	MOS/MSC	15-Jul-22	-					MANDATORY	
	HRS	1784.3							
	ENC	1528							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 72 - ENGINE

MOC: COMPLIED WITH - PREVIOUSLY COMPLIED WITH SERVICE BULLETIN WISB-72-1032 ON ENGINE NO.1 P/N 56000 S/N 105499 BY WILLIAMS INTERNATIONAL ON 24/JUN/2021 AT 1533.1 HOURS AND 1373 CYCLES. THIS SATISFIES THE REQUIREMENTS OF AD 2022-13-15.

FAA 2022-13-15	NO. 2 ENGINE - TURBINE SECTION - HIGH-PRESSURE TURBINE (HPT) DISK - REPLACE							AD	ATA:72
MOS/MSC	15-Jul-22	-						MANDATORY	
HRS	1784.3								
ENC	1528								

MOC: COMPLIED WITH - PREVIOUSLY COMPLIED WITH SERVICE BULLETIN WISB-72-1032 ON ENGINE NO.2 P/N 56000 S/N 105498 BY WILLIAMS INTERNATIONAL ON 24/JUN/2021 AT 1533.1 HOURS AND 1373 CYCLES. THIS SATISFIES THE REQUIREMENTS OF AD 2022-13-15.

PSID WIPSID-05-1000 R02	NO. 1 ENGINE - UNSERVICEABLE PARTS - NOTIFICATION, PRODUCT SUPPORT INFORMATIONAL DOCUMENT							Bulletin	ATA:72
MOS/MSC		-						INFORMATIONAL	
HRS									
ENC									

PSID WIPSID-05-1000 R02	NO. 2 ENGINE - UNSERVICEABLE PARTS - NOTIFICATION, PRODUCT SUPPORT INFORMATIONAL DOCUMENT							Bulletin	ATA:72
MOS/MSC		-						INFORMATIONAL	
HRS									
ENC									

PSID WIPSID-05-1000 R03	NO. 1 ENGINE - UNSERVICEABLE PARTS - NOTIFICATION, PRODUCT SUPPORT INFORMATIONAL DOCUMENT							Bulletin	ATA:72
MOS/MSC		-						INFORMATIONAL	
HRS									
ENC									

PSID WIPSID-05-1000 R03	NO. 2 ENGINE - UNSERVICEABLE PARTS - NOTIFICATION, PRODUCT SUPPORT INFORMATIONAL DOCUMENT							Bulletin	ATA:72
MOS/MSC		-						INFORMATIONAL	
HRS									
ENC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
PSID WIPSID-72-1016	NO. 1 ENGINE - REVISION TO ILLUSTRATED PARTS CATALOG (THIS SERVICE DOCUMENT IS NO LONGER AVAILABLE), PRODUCT SUPPORT INFORMATIONAL DOCUMENT							Bulletin	ATA:72
	MOS/MSC		-					INFORMATIONAL	
	HRS								
	ENC								
PSID WIPSID-72-1016	NO. 2 ENGINE - REVISION TO ILLUSTRATED PARTS CATALOG (THIS SERVICE DOCUMENT IS NO LONGER AVAILABLE), PRODUCT SUPPORT INFORMATIONAL DOCUMENT							Bulletin	ATA:72
	MOS/MSC		-					INFORMATIONAL	
	HRS								
	ENC								
PSID WIPSID-72-1022 R01	NO. 1 ENGINE - OPERATING IN AREAS OF SMOKE, PRODUCT SUPPORT INFORMATIONAL DOCUMENT							Bulletin	ATA:72
	MOS/MSC		-						
	HRS								
	ENC								
PSID WIPSID-72-1022 R01	NO. 2 ENGINE - OPERATING IN AREAS OF SMOKE, PRODUCT SUPPORT INFORMATIONAL DOCUMENT							Bulletin	ATA:72
	MOS/MSC		-						
	HRS								
	ENC								
PSID WIPSID-72-1026	NO. 1 ENGINE - FAN CASE - RUB INDICATIONS, PRODUCT SUPPORT INFORMATIONAL DOCUMENT							Bulletin	ATA:72
	MOS/MSC		-						
	HRS								
	ENC								
PSID WIPSID-72-1026	NO. 2 ENGINE - FAN CASE - RUB INDICATIONS, PRODUCT SUPPORT INFORMATIONAL DOCUMENT							Bulletin	ATA:72
	MOS/MSC		-						
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
SB FJ44-05-002 R02	NO. 1 ENGINE - UNSERVICEABLE PARTS - NOTIFICATION, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					INFORMATIONAL		
	HRS									
	ENC									
SB FJ44-05-002 R02	NO. 2 ENGINE - UNSERVICEABLE PARTS - NOTIFICATION, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					INFORMATIONAL		
	HRS									
	ENC									
SB FJ44-05-002 R03	NO. 1 ENGINE - UNSERVICEABLE PARTS - NOTIFICATION, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					INFORMATIONAL		
	HRS									
	ENC									
SB FJ44-05-002 R03	NO. 2 ENGINE - UNSERVICEABLE PARTS - NOTIFICATION, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					INFORMATIONAL		
	HRS									
	ENC									
SB FJ44-72-022 R02	NO. 1 ENGINE - FRONT BYPASS DUCT - REPAIR RIGHT-HAND SERVICE ADAPTER INSERT, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-022 R02	NO. 2 ENGINE - FRONT BYPASS DUCT - REPAIR RIGHT-HAND SERVICE ADAPTER INSERT, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
SB FJ44-72-051 R04	NO. 1 ENGINE - REWORK NAMEPLATE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-051 R04	NO. 2 ENGINE - REWORK NAMEPLATE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-051 R05	NO. 1 ENGINE - NAMEPLATE - REWORK, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-051 R05	NO. 2 ENGINE - NAMEPLATE - REWORK, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-054 R07	NO. 1 ENGINE - GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-054 R07	NO. 2 ENGINE - GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
SB FJ44-72-056	NO. 1 ENGINE - ENGINE - CONVERSION	FJ44-2A (P/N 56000) TO FJ44-2A (P/N 56000-104), SERVICE BULLETIN						Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED	
	HRS	0							
	ENC	0							
SB FJ44-72-056									
SB FJ44-72-056	NO. 2 ENGINE - ENGINE - CONVERSION	FJ44-2A (P/N 56000) TO FJ44-2A (P/N 56000-104), SERVICE BULLETIN						Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED	
	HRS	0							
	ENC	0							
SB FJ44-72-080 R01									
SB FJ44-72-080 R01	NO. 1 ENGINE - ENGINE - 2ND REDUCTION BEVEL GEAR BALL BEARING (GEARBOX ASSEMBLY) - REPLACE, SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED	
	HRS								
	ENC	0							
SB FJ44-72-080 R01									
SB FJ44-72-080 R01	NO. 2 ENGINE - ENGINE - 2ND REDUCTION BEVEL GEAR BALL BEARING (GEARBOX ASSEMBLY) - REPLACE, SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED	
	HRS								
	ENC	0							
SB FJ44-72-080 R02									
SB FJ44-72-080 R02	NO. 1 ENGINE - 2ND REDUCTION BEVEL GEAR BALL BEARING (GEARBOX ASSEMBLY) - REPLACE, SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED	
	HRS								
	ENC								
SB FJ44-72-080 R02									
SB FJ44-72-080 R02	NO. 2 ENGINE - 2ND REDUCTION BEVEL GEAR BALL BEARING (GEARBOX ASSEMBLY) - REPLACE, SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED	
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
SB FJ44-72-085 R07	NO. 1 ENGINE - IP BLEED VALVE - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-085 R07	NO. 2 ENGINE - IP BLEED VALVE - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-085 R08	NO. 1 ENGINE - IP BLEED VALVE - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-085 R08	NO. 2 ENGINE - IP BLEED VALVE - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-085 R09	NO. 1 ENGINE - IP BLEED VALVE - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-085 R09	NO. 2 ENGINE - IP BLEED VALVE - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
SB FJ44-72-098	NO. 1 ENGINE - ENGINE - 1ST REDUCTION BEVEL GEAR BEARING SUPPORT - REWORK OR REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC	0								
SB FJ44-72-098	NO. 2 ENGINE - ENGINE - 1ST REDUCTION BEVEL GEAR BEARING SUPPORT - REWORK OR REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC	0								
SB FJ44-72-098 R01	NO. 1 ENGINE - 1ST REDUCTION BEVEL GEAR BEARING SUPPORT - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC	EFF		T:MPI						
	HRS									
	ENC									
SB FJ44-72-098 R01	NO. 2 ENGINE - 1ST REDUCTION BEVEL GEAR BEARING SUPPORT - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC	EFF		T:MPI						
	HRS									
	ENC									
SB FJ44-72-108	NO. 1 ENGINE - ACCESSORY DRIVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-108 R01), SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC	0								
SB FJ44-72-108	NO. 2 ENGINE - ACCESSORY DRIVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-108 R01), SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC	0								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
SB FJ44-72-108 R01-CN	NO. 1 ENGINE - SUPERSEDED - ACCESSORY DRIVE SHAFT - REPLACE (THIS SERVICE DOCUMENT IS NO LONGER AVAILABLE), SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC		-					CANCELLED	
	HRS								
	ENC								
SB FJ44-72-108 R01-CN	NO. 2 ENGINE - SUPERSEDED - ACCESSORY DRIVE SHAFT - REPLACE (THIS SERVICE DOCUMENT IS NO LONGER AVAILABLE), SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC		-					CANCELLED	
	HRS								
	ENC								
SB FJ44-72-109	NO. 1 ENGINE - ENGINE - 1ST REDUCTION BEVEL GEAR BALL BEARING - REPLACE, SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC		T:DUE					RECOMMENDED	
	HRS								
	ENC	0							
SB FJ44-72-109	NO. 2 ENGINE - ENGINE - 1ST REDUCTION BEVEL GEAR BALL BEARING - REPLACE, SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC		T:DUE					RECOMMENDED	
	HRS								
	ENC	0							
SB FJ44-72-111 R02	NO. 1 ENGINE - ENGINE - 1ST LP TURBINE NOZZLE - INSPECTION, SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC		T:DUE					RECOMMENDED	
	HRS								
	ENC	0							
SB FJ44-72-111 R02	NO. 2 ENGINE - ENGINE - 1ST LP TURBINE NOZZLE - INSPECTION, SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC		T:DUE					RECOMMENDED	
	HRS								
	ENC	0							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
SB FJ44-72-115	NO. 1 ENGINE - ENGINE - DAMPENER BRACKET ASSEMBLY - INSTALL, SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC		T:DUE					MANDATORY	
	HRS								
	ENC								
SB FJ44-72-115	NO. 2 ENGINE - ENGINE - DAMPENER BRACKET ASSEMBLY - INSTALL, SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC		T:DUE					MANDATORY	
	HRS								
	ENC								
SB FJ44-72-120 R05	NO. 1 ENGINE - OIL BREATHER TUBE ASSEMBLY, FRONT BYPASS DUCT ASSEMBLY, AND BREATHER TUBE ASSEMBLY - INSTALL, SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC		-					OPTIONAL	
	HRS								
	ENC								
SB FJ44-72-120 R05	NO. 2 ENGINE - OIL BREATHER TUBE ASSEMBLY, FRONT BYPASS DUCT ASSEMBLY, AND BREATHER TUBE ASSEMBLY - INSTALL, SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC		-					OPTIONAL	
	HRS								
	ENC								
SB FJ44-72-129 R01	NO. 1 ENGINE - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE, SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC		-					MANDATORY	
	HRS								
	ENC								
SB FJ44-72-129 R01	NO. 2 ENGINE - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE, SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC		-						
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
SB FJ44-72-129 R01-CN	NO. 1 ENGINE - CANCELED - ENGINE - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					CANCELLED		
	HRS									
	ENC									
SB FJ44-72-129 R01-CN	NO. 2 ENGINE - CANCELED - ENGINE - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					CANCELLED		
	HRS									
	ENC									
SB FJ44-72-130 R01	NO. 1 ENGINE - HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R02), SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-130 R01	NO. 2 ENGINE - HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R02), SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-130 R02	NO. 1 ENGINE - HP COMPRESSOR ROTOR - INSPECTION, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-130 R02	NO. 2 ENGINE - HP COMPRESSOR ROTOR - INSPECTION, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
SB FJ44-72-133 R02	NO. 1 ENGINE - REPLACE 1ST LP TURBINE NOZZLE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		T:CSI					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-133 R02	NO. 2 ENGINE - REPLACE 1ST LP TURBINE NOZZLE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		T:CSI					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-142 R01	NO. 1 ENGINE - NO. 1 CARBON SEAL ASSEMBLY & SEAL RUNNER - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-142 R01	NO. 2 ENGINE - NO. 1 CARBON SEAL ASSEMBLY & SEAL RUNNER - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-143 R01	NO. 1 ENGINE - BLEED VALVE SHAFT - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-143 R01	NO. 2 ENGINE - BLEED VALVE SHAFT - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
SB FJ44-72-143 R02	NO. 1 ENGINE - BLEED VALVE SHAFT - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-143 R02	NO. 2 ENGINE - BLEED VALVE SHAFT - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-143 R03	NO. 1 ENGINE - BLEED VALVE SHAFT - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-143 R03	NO. 2 ENGINE - BLEED VALVE SHAFT - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-145 R01	NO. 1 ENGINE - GEARBOX ASSEMBLY - INSTALL WASHER & SPRING CARTRIDGE ASSEMBLY, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-145 R01	NO. 2 ENGINE - GEARBOX ASSEMBLY - INSTALL WASHER & SPRING CARTRIDGE ASSEMBLY, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
SB FJ44-72-145 R03	NO. 1 ENGINE - GEARBOX ASSEMBLY - INSTALL WASHER & SPRING CARTRIDGE ASSEMBLY, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-							
	HRS									
	ENC									
SB FJ44-72-145 R03	NO. 2 ENGINE - GEARBOX ASSEMBLY - INSTALL WASHER & SPRING CARTRIDGE ASSEMBLY, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-							
	HRS									
	ENC									
SB FJ44-72-146	NO. 1 ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-146	NO. 2 ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-147	NO. 1 ENGINE - DIFFUSER CASE ASSEMBLY - INSPECTION, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-147	NO. 2 ENGINE - DIFFUSER CASE ASSEMBLY - INSPECTION, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
SB FJ44-72-147 R01	NO. 1 ENGINE - DIFFUSER CASE ASSEMBLY - INSPECTION, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-147 R01	NO. 2 ENGINE - DIFFUSER CASE ASSEMBLY - INSPECTION, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-147 R02	NO. 1 ENGINE - DIFFUSER CASE ASSEMBLY - INSPECTION, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC	EFF	-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-147 R02	NO. 2 ENGINE - DIFFUSER CASE ASSEMBLY - INSPECTION, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC	EFF	-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-149	NO. 1 ENGINE - SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-149	NO. 2 ENGINE - SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
SB FJ44-72-149 R01	NO. 1 ENGINE - SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-149 R01	NO. 2 ENGINE - SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-149 R02	NO. 1 ENGINE - SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-149 R02	NO. 2 ENGINE - SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-149 R03	NO. 1 ENGINE - SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-149 R03	NO. 2 ENGINE - SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
SB FJ44-72-150	NO. 1 ENGINE - LP REAR BEARING SEAL RETAINER - REPLACE (SUPERSEDED BY FJ44-72-150 R01), SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-150	NO. 2 ENGINE - LP REAR BEARING SEAL RETAINER - REPLACE (SUPERSEDED BY FJ44-72-150 R01), SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-150 R01	NO. 1 ENGINE - LP REAR BEARING SEAL RETAINER - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-150 R01	NO. 2 ENGINE - LP REAR BEARING SEAL RETAINER - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-150 R02	NO. 1 ENGINE - LP REAR BEARING SEAL RETAINER - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-							
	HRS									
	ENC									
SB FJ44-72-150 R02	NO. 2 ENGINE - LP REAR BEARING SEAL RETAINER - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-							
	HRS									
	ENC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
SB FJ44-72-150 R03	NO. 1 ENGINE - LP REAR BEARING SEAL RETAINER - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-150 R03	NO. 2 ENGINE - LP REAR BEARING SEAL RETAINER - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-72-56-CN	NO. 1 ENGINE - CANCELED - ENGINE - CONVERSION - FJ44-2A (P/N 56000) TO FJ44-2A (56000-104), SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					CANCELLED		
	HRS									
	ENC									
SB FJ44-72-56-CN	NO. 2 ENGINE - CANCELED - ENGINE - CONVERSION - FJ44-2A (P/N 56000) TO FJ44-2A (56000-104), SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					CANCELLED		
	HRS									
	ENC									
SB WISB-72-1008	NO. 1 ENGINE - HIGH PRESSURE TURBINE ROTOR - REPLACE (SUPERSEDED BY WISB-72-1008 R01), SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					MANDATORY		
	HRS									
	ENC									
SB WISB-72-1008	NO. 2 ENGINE - HIGH PRESSURE TURBINE ROTOR - REPLACE (SUPERSEDED BY WISB-72-1008 R01), SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					MANDATORY		
	HRS									
	ENC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
SB WISB-72-1008 R01	NO. 1 ENGINE - HIGH PRESSURE TURBINE BLADES - REPLACE (SUPERSEDED BY SB WISB-72-1040), SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					MANDATORY		
	HRS									
	ENC									
SB WISB-72-1008 R01	NO. 2 ENGINE - HIGH PRESSURE TURBINE BLADES - REPLACE (SUPERSEDED BY SB WISB-72-1040), SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					MANDATORY		
	HRS									
	ENC									
SB WISB-72-1008 R01-CN	NO. 1 ENGINE - CANCELED - ENGINE - HIGH PRESSURE TURBINE ROTOR - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					CANCELLED		
	HRS									
	ENC									
SB WISB-72-1008 R01-CN	NO. 2 ENGINE - CANCELED - ENGINE - HIGH PRESSURE TURBINE ROTOR - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					CANCELLED		
	HRS									
	ENC									
SB WISB-72-1009 R02	NO. 1 ENGINE - TURBINE BLADES - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC	17-Jun-24	-					RECOMMENDED		
	HRS	2032								
	ENC	1683								
MOC: NOT APPLICABLE - FOUND FJ44-71-002 REV 2 NOT APPLICABLE PER ENGINE SERIAL NUMBER. NO ACTION REQUIRED.										
SB WISB-72-1009 R02	NO. 2 ENGINE - TURBINE BLADES - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC	17-Jun-24	-					RECOMMENDED		
	HRS	2032								
	ENC	1683								
MOC: NOT APPLICABLE - FOUND WISB-72-1009 REV2 NOT APPLICABLE PER ENGINE SERIAL NUMBER. NO ACTION REQUIRED.										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 72 - ENGINE

SB WISB-72-1032 R02	NO. 1 ENGINE - HIGH PRESSURE TURBINE DISK - REPLACE, SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC	29-Jun-21	-					MANDATORY	
	HRS	1533.1							
	ENC	1373							

MOC: COMPLIED WITH - COMPLIED WITH WISB-72-1032 ON LH REPAIRED FJ44-2A ENGINE P/N 56000 S/N 105499 TSN 1533.1 CSN 1373. NEW HPT DISK P/N 223704 S/N HW63028 TSN 0.0 CSN 0.0 WAS INSTALLED BY WILLIAMS INTERNATIONAL CRS# W15R335J UNDER WO# 1124930 DATE 24/JUN/2021. PERFORMED PERFORMANCE/STABILITY/ACCELERATION CHECKS IAW WILLIAMS INTERNATIONAL FJ44-2A LMM CHAPTER 71-00-00-760. NO DISCREPANCIES WERE NOTED.

SB WISB-72-1032 R02	NO. 2 ENGINE - HIGH PRESSURE TURBINE DISK - REPLACE, SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC	29-Jun-21	-					MANDATORY	
	HRS	1533.1							
	ENC	1373							

MOC: COMPLIED WITH - COMPLIED WITH WISB-72-1032 ON RH REPAIRED FJ44-2A ENGINE P/N 56000 S/N 105498 TSN 1533.1 CSN 1373. NEW HPT DISK P/N 223704 S/N HW63022 TSN 0.0 CSN 0.0 WAS INSTALLED BY WILLIAMS INTERNATIONAL CRS# W15R335J UNDER WO# 1124931 DATE 24/JUN/2021. PERFORMED PERFORMANCE/STABILITY/ACCELERATION CHECKS IAW WILLIAMS INTERNATIONAL FJ44-2A LMM CHAPTER 71-00-00-760. NO DISCREPANCIES WERE NOTED.

SB WISB-72-1037 R01	NO. 1 ENGINE - ACCESSORY DRIVE TOWERSHAFT - REPLACE, SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED	
	HRS								
	ENC								

SB WISB-72-1037 R01	NO. 2 ENGINE - ACCESSORY DRIVE TOWERSHAFT - REPLACE, SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED	
	HRS								
	ENC								

SB WISB-72-1037 R02	NO. 1 ENGINE - ACCESSORY DRIVE TOWERSHAFT - REPLACE, SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED	
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 72 - ENGINE									
SB WISB-72-1037 R02	NO. 2 ENGINE - ACCESSORY DRIVE TOWERSHAFT - REPLACE, SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED	
	HRS								
	ENC								
SB WISB-72-1037 R03	NO. 1 ENGINE - ACCESSORY DRIVE TOWERSHAFT - REPLACE, SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED	
	HRS								
	ENC								
SB WISB-72-1037 R03	NO. 2 ENGINE - ACCESSORY DRIVE TOWERSHAFT - REPLACE, SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED	
	HRS								
	ENC								
SB WISB-72-1037 R04	NO. 1 ENGINE - ACCESSORY DRIVE TOWERSHAFT - REPLACE, SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED	
	HRS								
	ENC								
SB WISB-72-1037 R04	NO. 2 ENGINE - ACCESSORY DRIVE TOWERSHAFT - REPLACE, SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED	
	HRS								
	ENC								
SB WISB-72-1037 R05	NO. 1 ENGINE - ACCESSORY DRIVE TOWERSHAFT - REPLACE, SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC		T:CSI					RECOMMENDED	
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
SB WISB-72-1037 R05	NO. 2 ENGINE - ACCESSORY DRIVE TOWERSHAFT - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		T:CSI					RECOMMENDED		
	HRS									
	ENC									
SB WISB-72-1040	NO. 1 ENGINE - HIGH PRESSURE TURBINE BLADES - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB WISB-72-1040	NO. 2 ENGINE - HIGH PRESSURE TURBINE BLADES - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB WISB-72-1040 R01	NO. 1 ENGINE - HIGH PRESSURE TURBINE BLADES - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB WISB-72-1040 R01	NO. 2 ENGINE - HIGH PRESSURE TURBINE BLADES - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB WISB-72-1040 R02	NO. 1 ENGINE - HIGH PRESSURE TURBINE BLADES - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC	EFF	T:MPI					RECOMMENDED		
	HRS									
	ENC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 72 - ENGINE

SB WISB-72-1040 R02	NO. 2 ENGINE - HIGH PRESSURE TURBINE BLADES - REPLACE, SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC	EFF	T:MPI					RECOMMENDED	
	HRS								
	ENC								

SB WISB-72-1041	NO. 1 ENGINE - HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE, SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC	29-Jun-21	-					RECOMMENDED	
	HRS	1533.1							
	ENC	1373							

MOC: COMPLIED WITH - WISB-72-1041 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACEMENT WAS COMPLIED WITH ON LH FJ44-2A ENGINE P/N 56000 S/N 105499 TSN 1533.1 CSN 1373 BY WILLIAMS INTERNATIONAL CRS# WI5R335J UNDER WO# 1124930 DATE 24/JUN/2021.

SB WISB-72-1041	NO. 2 ENGINE - HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE, SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC	29-Jun-21	-					RECOMMENDED	
	HRS	1533.1							
	ENC	1373							

MOC: COMPLIED WITH - WISB-72-1041 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACEMENT WAS COMPLIED WITH ON RH FJ44-2A ENGINE P/N 56000 S/N 105498 TSN 1533.1 CSN 1373 BY WILLIAMS INTERNATIONAL CRS# WI5R335J UNDER WO# 1124931 DATE 24/JUN/2021.

SB WISB-72-1041 R01	NO. 1 ENGINE - HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE, SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC	29-Jun-21	-					RECOMMENDED	
	HRS	1533.1							
	ENC	1373							

MOC: COMPLIED WITH - WISB-72-1041 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACEMENT WAS COMPLIED WITH ON LH FJ44-2A ENGINE P/N 56000 S/N 105499 TSN 1533.1 CSN 1373 BY WILLIAMS INTERNATIONAL CRS# WI5R335J UNDER WO# 1124930 DATE 24/JUN/2021.

SB WISB-72-1041 R01	NO. 2 ENGINE - HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE, SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC	29-Jun-21	-					RECOMMENDED	
	HRS	1533.1							
	ENC	1373							

MOC: COMPLIED WITH - WISB-72-1041 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACEMENT WAS COMPLIED WITH ON RH FJ44-2A ENGINE P/N 56000 S/N 105498 TSN 1533.1 CSN 1373 BY WILLIAMS INTERNATIONAL CRS# WI5R335J UNDER WO# 1124931 DATE 24/JUN/2021.

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
---------	------	-----	----------	----------	------------------------	-----------	-----------	-------------	----------

ATA 72 - ENGINE

SB WISB-72-1041 R02	NO. 1 ENGINE - HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE, SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC	29-Jun-21	-					RECOMMENDED	
	HRS	1533.1							
	ENC	1373							

MOC: COMPLIED WITH - WISB-72-1041 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACEMENT WAS COMPLIED WITH ON LH FJ44-2A ENGINE P/N 56000 S/N 105499 TSN 1533.1 CSN 1373 BY WILLIAMS INTERNATIONAL CRS# WI5R335J UNDER WO# 1124930 DATE 24/JUN/2021.

SB WISB-72-1041 R02	NO. 2 ENGINE - HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE, SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC	29-Jun-21	-					RECOMMENDED	
	HRS	1533.1							
	ENC	1373							

MOC: COMPLIED WITH - WISB-72-1041 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACEMENT WAS COMPLIED WITH ON RH FJ44-2A ENGINE P/N 56000 S/N 105498 TSN 1533.1 CSN 1373 BY WILLIAMS INTERNATIONAL CRS# WI5R335J UNDER WO# 1124931 DATE 24/JUN/2021.

SB WISB-72-1041 R03	NO. 1 ENGINE - HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE, SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC	29-Jun-21	-					RECOMMENDED	
	HRS	1533.1							
	ENC	1373							

MOC: COMPLIED WITH - WISB-72-1041 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACEMENT WAS COMPLIED WITH ON LH FJ44-2A ENGINE P/N 56000 S/N 105499 TSN 1533.1 CSN 1373 BY WILLIAMS INTERNATIONAL CRS# WI5R335J UNDER WO# 1124930 DATE 24/JUN/2021.

SB WISB-72-1041 R03	NO. 2 ENGINE - HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE, SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC	29-Jun-21	-					RECOMMENDED	
	HRS	1533.1							
	ENC	1373							

MOC: COMPLIED WITH - WISB-72-1041 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACEMENT WAS COMPLIED WITH ON RH FJ44-2A ENGINE P/N 56000 S/N 105498 TSN 1533.1 CSN 1373 BY WILLIAMS INTERNATIONAL CRS# WI5R335J UNDER WO# 1124931 DATE 24/JUN/2021.

SB WISB-72-1041 R04	NO. 1 ENGINE - HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE, SERVICE BULLETIN							Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED	
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
SB WISB-72-1041 R04	NO. 2 ENGINE - HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB WISB-72-1044	NO. 1 ENGINE - ENGINE - BALANCE PISTON - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC	EFF	-					RECOMMENDED		
	HRS									
	ENC									
SB WISB-72-1044	NO. 2 ENGINE - ENGINE - BALANCE PISTON - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC	EFF	-					RECOMMENDED		
	HRS									
	ENC									
SB WISB-72-1044 R01	NO. 1 ENGINE - BALANCE PISTON - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB WISB-72-1044 R01	NO. 2 ENGINE - BALANCE PISTON - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB WISB-72-1044 R02	NO. 1 ENGINE - BALANCE PISTON - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
SB WISB-72-1044 R02	NO. 2 ENGINE - BALANCE PISTON - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB WISB-72-1044 R03	NO. 1 ENGINE - BALANCE PISTON - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB WISB-72-1044 R03	NO. 2 ENGINE - BALANCE PISTON - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB WISB-72-1050	NO. 1 ENGINE - HPT ASSEMBLY - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					MANDATORY		
	HRS									
	ENC									
SB WISB-72-1050	NO. 2 ENGINE - HPT ASSEMBLY - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					MANDATORY		
	HRS									
	ENC									
SB WISB-72-1050 R01	NO. 1 ENGINE - HPT ASSEMBLY - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					MANDATORY		
	HRS									
	ENC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
SB WISB-72-1050 R01	NO. 2 ENGINE - HPT ASSEMBLY - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					MANDATORY		
	HRS									
	ENC									
SB WISB-72-1067	NO. 1 ENGINE - FAN STATOR VANE ASSEMBLY - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB WISB-72-1067	NO. 2 ENGINE - FAN STATOR VANE ASSEMBLY - REPLACE, SERVICE BULLETIN								Bulletin	ATA:72
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SL SL44-72-300 R07	NO. 1 ENGINE - ENGINE - HP COMPRESSOR COVER - REAM HOLES, SERVICE LETTER								Bulletin	ATA:72
	MOS/MSC		-							
	HRS									
	ENC									
SL SL44-72-300 R07	NO. 2 ENGINE - ENGINE - HP COMPRESSOR COVER - REAM HOLES, SERVICE LETTER								Bulletin	ATA:72
	MOS/MSC		-							
	HRS									
	ENC									
SL SL44-72-325 R05	NO. 1 ENGINE - 1ST LP TURBINE DISK - INSPECTION, SERVICE LETTER								Bulletin	ATA:72
	MOS/MSC		-							
	HRS									
	ENC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 72 - ENGINE										
SL SL44-72-325 R05	NO. 2 ENGINE - 1ST LP TURBINE DISK - INSPECTION, SERVICE LETTER								Bulletin	ATA:72
	MOS/MSC		-							
	HRS									
	ENC									
SL SL44-72-325 R06	NO. 1 ENGINE - ENGINE - 1ST LP TURBINE DISK - INSPECTION, SERVICE LETTER								Bulletin	ATA:72
	MOS/MSC		-							
	HRS									
	ENC									
SL SL44-72-325 R06	NO. 2 ENGINE - ENGINE - 1ST LP TURBINE DISK - INSPECTION, SERVICE LETTER								Bulletin	ATA:72
	MOS/MSC		-							
	HRS									
	ENC									
SL SL44-72-325 R07	NO. 1 ENGINE - 1ST LP TURBINE DISK - INSPECTION, SERVICE LETTER								Bulletin	ATA:72
	MOS/MSC		-							
	HRS									
	ENC									
SL SL44-72-325 R07	NO. 2 ENGINE - 1ST LP TURBINE DISK - INSPECTION, SERVICE LETTER								Bulletin	ATA:72
	MOS/MSC		-							
	HRS									
	ENC									
ATA 73 - ENGINE FUEL AND CONTROL										
SB FJ44-73-041 R04	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ECU - INSTALL CP317.03 SOFTWARE (SUPERSEDED BY FJ44-73-041 R05), SERVICE BULLETIN								Bulletin	ATA:73
	MOS/MSC		-					OPTIONAL		
	HRS									
	ENC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 73 - ENGINE FUEL AND CONTROL									
SB FJ44-73-041 R04	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ECU - INSTALL CP317.03 SOFTWARE (SUPERSEDED BY FJ44-73-041 R05), SERVICE BULLETIN							Bulletin	ATA:73
	MOS/MSC		-					OPTIONAL	
	HRS								
	ENC								
SB FJ44-73-041 R05	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ECU - INSTALL CP317.03 SOFTWARE (SUPERSEDED BY FJ44-73-041 R06), SERVICE BULLETIN							Bulletin	ATA:73
	MOS/MSC		-					OPTIONAL	
	HRS								
	ENC								
SB FJ44-73-041 R05	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ECU - INSTALL CP317.03 SOFTWARE (SUPERSEDED BY FJ44-73-041 R06), SERVICE BULLETIN							Bulletin	ATA:73
	MOS/MSC		-					OPTIONAL	
	HRS								
	ENC								
SB FJ44-73-041 R06	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ECU - INSTALL CP317.03 SOFTWARE, SERVICE BULLETIN							Bulletin	ATA:73
	MOS/MSC		-					OPTIONAL	
	HRS								
	ENC								
SB FJ44-73-041 R06	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ECU - INSTALL CP317.03 SOFTWARE, SERVICE BULLETIN							Bulletin	ATA:73
	MOS/MSC		-					OPTIONAL	
	HRS								
	ENC								
SB FJ44-73-041 R07	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ECU - INSTALL CP317.03 SOFTWARE, SERVICE BULLETIN							Bulletin	ATA:73
	MOS/MSC		-					OPTIONAL	
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 73 - ENGINE FUEL AND CONTROL										
SB FJ44-73-041 R07	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ECU - INSTALL CP317.03 SOFTWARE, SERVICE BULLETIN								Bulletin	ATA:73
	MOS/MSC		-					OPTIONAL		
	HRS									
	ENC									
<hr/>										
SB FJ44-73-041 R08	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ECU - INSTALL CP317.03 SOFTWARE, SERVICE BULLETIN								Bulletin	ATA:73
	MOS/MSC		-					OPTIONAL		
	HRS									
	ENC									
<hr/>										
SB FJ44-73-041 R08	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ECU - INSTALL CP317.03 SOFTWARE, SERVICE BULLETIN								Bulletin	ATA:73
	MOS/MSC		-					OPTIONAL		
	HRS									
	ENC									
<hr/>										
SB FJ44-73-062	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL FLOW TO OIL COOLER TUBE ASSEMBLY - REPLACE, SERVICE BULLETIN								Bulletin	ATA:73
	MOS/MSC	01-Feb-17	-					RECOMMENDED		
	HRS	753.33								
	ENC	767								
<hr/>										
MOC: DECLINED - THIS SB IS DECLINED FOR CUSTOMER CONVENIENCE										
<hr/>										
SB FJ44-73-062	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL FLOW TO OIL COOLER TUBE ASSEMBLY - REPLACE, SERVICE BULLETIN								Bulletin	ATA:73
	MOS/MSC	01-Feb-17	-					RECOMMENDED		
	HRS	753.33								
	ENC	767								
<hr/>										
MOC: DECLINED - THIS SB IS DECLINED FOR CUSTOMER CONVENIENCE										
<hr/>										
SB FJ44-73-062 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL FLOW TO OIL COOLER TUBE ASSEMBLY - REPLACE, SERVICE BULLETIN								Bulletin	ATA:73
	MOS/MSC		-							
	HRS									
	ENC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 73 - ENGINE FUEL AND CONTROL										
SB FJ44-73-062 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL FLOW TO OIL COOLER TUBE ASSEMBLY - REPLACE, SERVICE BULLETIN								Bulletin	ATA:73
	MOS/MSC		-							
	HRS									
	ENC									
<hr/>										
SB WISB-73-1000	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE, SERVICE BULLETIN								Bulletin	ATA:73
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
<hr/>										
SB WISB-73-1000	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE, SERVICE BULLETIN								Bulletin	ATA:73
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
<hr/>										
SB WISB-73-1000 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE, SERVICE BULLETIN								Bulletin	ATA:73
	MOS/MSC	EFF	T:DUE					RECOMMENDED		
	HRS									
	ENC									
<hr/>										
SB WISB-73-1000 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE, SERVICE BULLETIN								Bulletin	ATA:73
	MOS/MSC	EFF	T:DUE					RECOMMENDED		
	HRS									
	ENC									
<hr/>										
ATA 74 - IGNITION										
SB WISB-74-1002	NO. 1 ENGINE - IGNITION - IGNITER LEAD INSPECTION AND CLAMPING ARRANGEMENT (SUPERSEDED BY WISB-74-1002 R01), SERVICE BULLETIN								Bulletin	ATA:74
	MOS/MSC	04-Oct-17	-					MANDATORY		
	HRS	852.5								
	ENC	866								
<hr/>										
MOC: COMPLIED WITH										

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty
ATA 74 - IGNITION									
SB WISB-74-1002	NO. 2 ENGINE - IGNITION - IGNITER LEAD INSPECTION AND CLAMPING ARRANGEMENT (SUPERSEDED BY WISB-74-1002 R01), SERVICE BULLETIN							Bulletin	ATA:74
	MOS/MSC	04-Oct-17	-					MANDATORY	
	HRS	852.5							
	ENC	866							
MOC: COMPLIED WITH									
SB WISB-74-1002 R01	NO. 1 ENGINE - IGNITION - IGNITER LEAD INSPECTION AND CLAMPING ARRANGEMENT (SUPERSEDED BY WISB-74-1002 R02), SERVICE BULLETIN							Bulletin	ATA:74
	MOS/MSC		-					MANDATORY	
	HRS								
	ENC								
SB WISB-74-1002 R01	NO. 2 ENGINE - IGNITION - IGNITER LEAD INSPECTION AND CLAMPING ARRANGEMENT (SUPERSEDED BY WISB-74-1002 R02), SERVICE BULLETIN							Bulletin	ATA:74
	MOS/MSC		-					MANDATORY	
	HRS								
	ENC								
SB WISB-74-1002 R02	NO. 1 ENGINE - IGNITION - IGNITER LEAD INSPECTION AND CLAMPING ARRANGEMENT, SERVICE BULLETIN							Bulletin	ATA:74
	MOS/MSC		-					MANDATORY	
	HRS								
	ENC								
SB WISB-74-1002 R02	NO. 2 ENGINE - IGNITION - IGNITER LEAD INSPECTION AND CLAMPING ARRANGEMENT, SERVICE BULLETIN							Bulletin	ATA:74
	MOS/MSC		-					MANDATORY	
	HRS								
	ENC								
SB WISB-74-1004 R02	NO. 1 ENGINE - IGNITION - IGNITER LEAD - REPLACE, SERVICE BULLETIN							Bulletin	ATA:74
	MOS/MSC		-					RECOMMENDED	
	HRS								
	ENC								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 74 - IGNITION										
SB WISB-74-1004 R02	NO. 2 ENGINE - IGNITION - IGNITER LEAD - REPLACE, SERVICE BULLETIN								Bulletin	ATA:74
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
ATA 75 - AIR										
SB FJ44-75-002 R03	NO. 1 ENGINE - COMPRESSOR BLEED VALVE RETURN SPRING - REPLACE, SERVICE BULLETIN								Bulletin	ATA:75
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-75-002 R03	NO. 2 ENGINE - COMPRESSOR BLEED VALVE RETURN SPRING - REPLACE, SERVICE BULLETIN								Bulletin	ATA:75
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB WISB-75-1001	NO. 1 ENGINE - AIR - I.P. BLEED VALVE LEVER PIN - REPLACE, SERVICE BULLETIN								Bulletin	ATA:75
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB WISB-75-1001	NO. 2 ENGINE - AIR - I.P. BLEED VALVE LEVER PIN - REPLACE, SERVICE BULLETIN								Bulletin	ATA:75
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB WISB-75-1001 R01	NO. 1 ENGINE - AIR - I.P. BLEED VALVE LEVER PIN - REPLACE, SERVICE BULLETIN								Bulletin	ATA:75
	MOS/MSC		-							
	HRS									
	ENC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 75 - AIR										
SB WISB-75-1001 R01	NO. 2 ENGINE - AIR - I.P. BLEED VALVE LEVER PIN - REPLACE, SERVICE BULLETIN								Bulletin	ATA:75
	MOS/MSC		-							
	HRS									
	ENC									
SB WISB-75-1001 R02	NO. 1 ENGINE - AIR - I.P. BLEED VALVE LEVER PIN - REPLACE, SERVICE BULLETIN								Bulletin	ATA:75
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB WISB-75-1001 R02	NO. 2 ENGINE - AIR - I.P. BLEED VALVE LEVER PIN - REPLACE, SERVICE BULLETIN								Bulletin	ATA:75
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
ATA 77 - ENGINE INDICATING										
SB FJ44-77-006 R02	NO. 1 ENGINE - ENGINE INDICATING - ENGINE EFCU HARNESS ASSEMBLY - REWORK CONNECTOR/BACKSHELL, SERVICE BULLETIN								Bulletin	ATA:77
	MOS/MSC		-							
	HRS									
	ENC									
SB FJ44-77-006 R02	NO. 2 ENGINE - ENGINE INDICATING - ENGINE EFCU HARNESS ASSEMBLY - REWORK CONNECTOR/BACKSHELL, SERVICE BULLETIN								Bulletin	ATA:77
	MOS/MSC		-							
	HRS									
	ENC									
ATA 79 - OIL										
SB 390-79-01	OIL - OIL LEVEL SENSOR OBSOLESCENCE, SERVICE BULLETIN								Bulletin	ATA:79
	MOS/MSC		-					OPTIONAL		
	HRS									
	AFL									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 79 - OIL										
SB FJ44-79-011 R03	NO. 1 ENGINE - OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R04), SERVICE BULLETIN								Bulletin	ATA:79
	MOS/MSC		T:DUE					MANDATORY		
	HRS									
	ENC	0								
SB FJ44-79-011 R03	NO. 2 ENGINE - OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R04), SERVICE BULLETIN								Bulletin	ATA:79
	MOS/MSC		T:DUE					MANDATORY		
	HRS									
	ENC	0								
SB FJ44-79-011 R05	NO. 1 ENGINE - OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE, SERVICE BULLETIN								Bulletin	ATA:79
	MOS/MSC		-					MANDATORY		
	HRS									
	ENC									
SB FJ44-79-011 R05	NO. 2 ENGINE - OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE, SERVICE BULLETIN								Bulletin	ATA:79
	MOS/MSC		-					MANDATORY		
	HRS									
	ENC									
SB FJ44-79-011 R06	NO. 1 ENGINE - OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE, SERVICE BULLETIN								Bulletin	ATA:79
	MOS/MSC		-					MANDATORY		
	HRS									
	ENC									
SB FJ44-79-011 R06	NO. 2 ENGINE - OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE, SERVICE BULLETIN								Bulletin	ATA:79
	MOS/MSC		-					MANDATORY		
	HRS									
	ENC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PREMIER IA Serial: RB-293 RegNo: N390AA HRS: 2066.8 AFL: 1714 As Of: 03-Jan-2025

01-Apr-2025 05:04 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	Warranty	
ATA 79 - OIL										
SB FJ44-79-012 R01	NO. 1 ENGINE - OIL - LUBE OIL COOLER - REWORK OR REPLACE, SERVICE BULLETIN								Bulletin	ATA:79
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SB FJ44-79-012 R01	NO. 2 ENGINE - OIL - LUBE OIL COOLER - REWORK OR REPLACE, SERVICE BULLETIN								Bulletin	ATA:79
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SL SL44-79-013 R02	NO. 1 ENGINE - OIL FILLER CAP AND DIPSTICK ASSEMBLY - ADDITIONAL OIL LEVEL MARKS, SERVICE LETTER								Bulletin	ATA:79
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									
SL SL44-79-013 R02	NO. 2 ENGINE - OIL FILLER CAP AND DIPSTICK ASSEMBLY - ADDITIONAL OIL LEVEL MARKS, SERVICE LETTER								Bulletin	ATA:79
	MOS/MSC		-					RECOMMENDED		
	HRS									
	ENC									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task