


N670RA

1993 King Air 300-LW

Status List



MSN: FA-226

Prepared by the worldwide aviation specialists at RidgeAir, Inc.

Compliance Listing - N670RA

ATA Code	Type	Name	Part Number	Start/Install	Hrs Rmng	Cycl Rmng	Lngs Rmng	Bat Rmng	Days Rmng	Due Date	Status	Open W/O
	Airframe	1200 Hr. Lubrication		2024-03-04	954.50							
12-20-00	Airframe	200 Hr Lubrication		2026-03-27	200							
5-20-00	Inspection	3 Yr/3000 Cyl LH/RH flap inspection		2026-03-27		3,000			1,080	2029-03-31		
	Airframe	400 Hr. Lubrication		2024-03-04	154.50							
	Airframe	600 Hr. Lubrication		2024-03-04	354.50							
	Airframe	800 Hr. Lubrication		2024-03-04	554.50							
5-20-00	Inspection	AFT fuselage area and AFT pressure bulkhead priority area inspection		1993-02-10		5,169						
5-20-00	Inspection	Airstair door and escape hatches priority area inspection		1993-02-10		169					Impending	
	Inspection	Altimeter & Pitot Static 91.411		2026-04-01					745	2028-04-30		
	Inspection	ATC Transponder Test/Inspection 91.413		2026-04-01					745	2028-04-30		
4-00-00, Chart 1, Item 2	Airframe	Cabin airstair door forward and aft side latch bolts - Ch. 4	101-4084	1993-02-10		169					Impending	
4-00-00, Chart 1, Item 3	Airframe	Cabin airstair door upper hook replacement - Ch. 4	101-4085	1993-02-10		5,169						
5-20-00	Inspection	Cabin altitude warning system inspection		2026-03-27					349	2027-03-31		
5-20-00	Inspection	Cabin door and fuselage frame priority area inspection		1993-02-10	3,669.80							
5-20-00	Inspection	Cabin fire extinguisher hydrostatic inspection		2024-03-04					3,637	2036-03-31		
57-18-01, Table 201, Item 6	Inspection	Center section and outboard wing panel aft spar lower fitting - Eddy Current - Ch. 4		1993-02-10	20,669.80							
57-18-01, Table 201, Item 4	Inspection	Center section belly skin - Eddy Current - Ch. 4		1993-02-10	16,169.80							
57-18-01, Table 201, Item 5	Inspection	Center section lower aft spar - Eddy Current - Ch. 4		1993-02-10	20,669.80							
57-18-01, Table 201, Item 3	Inspection	Center section lower forward spar cap - Eddy Current - Ch. 4		1993-02-10	11,669.80							
5-20-00	Inspection	Cockpit and cabin interior removed inspection		2020-11-27		1,892			228	2026-11-30		
5-20-00	Inspection	Cockpit edge light panels inspections		2026-03-27	2,000				1,445	2030-03-31		
5-20-00	Inspection	Cockpit fire extinguisher hydrostatic inspection		2024-03-04					3,637	2036-03-31		

Compliance Listing - N670RA

ATA Code	Type	Name	Part Number	Start/Install	Hrs Rmng	Cycl Rmng	Lngs Rmng	Bat Rmng	Days Rmng	Due Date	Status	Open W/O
5-20-00	Inspection	Elevator bob weight link assembly inspection		1993-02-10	-	1,330.20					Overdue	
5-11-00	Airframe	ELT Battery Expiration		2024-03-04						2029-02-28		
5-11-00	Airframe	Emergency exit light battery replacement	C cell batteries	2026-03-27					349	2027-03-31		
5-20-00	Inspection	Exterior skin priority area inspection		1993-02-10		5,169						
5-20-00	Inspection	Flight controls priority area inspection		1993-02-10		5,169						
5-20-00	Inspection	Forward pressure bulkhead priority area inspection		2024-03-04		2,314						
5-20-00	Inspection	Frame web FS 179 through FS 271 priority inspection		1993-02-10		169					Impending	
5-20-00	Inspection	Fuel quantity level sensor functional inspection		2026-03-27		2,500						
5-20-00	Inspection	Fuselage aft pressure bulkhead priority inspection of fuselage stringers		2024-03-04		314						
5-20-00	Inspection	Fuselage frame FS 143 through FS 382 priority inspection		1993-02-10		5,169						
4-00-00, Chart 2, Item 1	Inspection	Horizontal & Vertical Stabilizer Inspection		2026-03-27					349	2027-03-31		
	Airframe	Instrument Air Filter Replacement		2024-03-04	354.50							
5-20-00	Inspection	Landing gear hydraulic reservoir fill screen inspection		2024-03-04	954.50							
	Inspection	Left Propeller overhaul		2018-10-09	4,000				-898	2023-10-31	Overdue	
5-20-00	Inspection	LH and RH flap flexible drive shaft inspection		1993-02-10		169					Impending	
5-11-00	Airframe	LH emergency exit self illuminating sign replacement		2024-03-04						2030-10-31		
72-00-00	Engine	LH engine 400 Hr Borescope		2024-03-04	154.50							
	Engine	LH engine AGB internal scavenge pump inlet screen inspection		2024-03-04	754.50							
72-00-00	Engine	LH engine chip detector bridge inspection		2026-03-27	600				349	2027-03-31		
	Engine	LH engine FCU overhaul		2007-10-03	972.50							
5-20-00, 49 CFR Ch. 1, Sec. 173-34	Inspection	LH engine fire bottle hydrostatic inspection		2026-03-27					1,810	2031-03-31		
5-20-00	Airframe	LH engine fire bottle squib replacement		2024-03-04					715	2028-03-31		

Compliance Listing - N670RA

ATA Code	Type	Name	Part Number	Start/Install	Hrs Rmng	Cycl Rmng	Lngs Rmng	Bat Rmng	Days Rmng	Due Date	Status	Open W/O
72-00-00	Inspection	LH engine fuel nozzle inspection and cleaning		2024-03-04	154.50							
72-00-00	Engine	LH engine fuel pump overhaul		2007-10-03	972.50							
	Inspection	LH engine ignition system inspection		2024-03-04	154.50							
	Engine	LH engine inlet screen inspection		2024-03-04	354.50							
5-20-00	Inspection	LH engine isolators replacement		2007-01-26	1,128							
	Inspection	LH engine minor inspection		2026-03-27	200				349	2027-03-31		
5-11-00	Engine	LH engine oil filter replacement		2024-03-04	754.50							
	Engine	LH engine overspeed governor overhaul		2007-10-03	3,872.50							
5-11-00	Engine	LH engine P3 filter replacement -		2024-03-04	754.50							
	Engine	LH engine propeller governor overhaul		2007-10-03	1,872.50							
SB 13303 R21	Engine	LH engine TBO	PT6A-60A (PCE-95710)	2007-10-03	972.50							
5-20-00	Inspection	LH main gear actuator clevis inspection		2024-03-04		814						
5-20-00	Inspection	LH main landing gear drag brace inspection		2024-03-04		7,814			1,418	2030-03-04		
5-11-00	Airframe	LH main landing gear exposed brake hose replacement		2024-03-04					1,080	2029-03-31		
5-20-05, 3 thru 5	Inspection	LH main landing gear tear down inspection		2024-03-04		7,814			1,445	2030-03-31		
5-10-00	Inspection	LH MLG inboard wheel assembly penetrant inspection		2022-12-29					-471	2024-12-31	Overdue	
5-11-00	Inspection	LH MLG outboard wheel assembly penetrant inspection		2022-12-29					-471	2024-12-31	Overdue	
5-11-00	Engine	LH starter/generator overhaul	23085-001	2024-03-04	754.50							
57-18-01, Table 201, Item 7	Inspection	Lower forward main spar clevis fittings - Visual - Ch. 4		2024-03-04					1,080	2029-03-31		
57-18-01, Table 201, Item 1	Inspection	Lower spar lugs - Eddy Current - Ch. 4		1993-02-10	8,669.80							
	Inspection	Nacelle Splice Plate Inspection		2026-03-27					349	2027-03-31		
5-10-00	Inspection	NLG wheel assembly penetrant inspection										
5-20-00	Inspection	Nose gear actuator clevis inspection		2024-03-04		814						
5-20-00	Inspection	Nose landing gear drag brace inspection		2024-03-04		7,814			1,418	2030-03-04		
5-20-00	Inspection	Nose landing gear tear down inspection		2024-03-04		7,814			1,445	2030-03-31		

JetPros

231 Terminal Circle , Longview, TX 75603
 903-309-4687, mx@jetpros.com

Compliance Listing - N670RA

ATA Code	Type	Name	Part Number	Start/Install	Hrs Rmng	Cycl Rmng	Lngs Rmng	Bat Rmng	Days Rmng	Due Date	Status	Open W/O
4-00-00, Chart 4	Inspection	O2 Bottle life limit		2012-04-30					379	2027-04-30		
57-18-01, Table 201, Item 8	Inspection	Outboard wing panel upper and lower main spar cap inspection - Visual - Ch. 4		2026-03-27					349	2027-03-31		
57-18-01, Table 201, Item 2	Inspection	Outboard wing panel, lower forward spar cap - Eddy current - Ch. 4		2024-03-04	14,754.50							
5-20-00	Inspection	Oxygen system barometric pressure switch check		2026-03-27					349	2027-03-31		
5-11-00	Airframe	Passenger oxygen shutoff valve o-ring replacement		2026-03-27					1,445	2030-03-31		
5-21-02	Inspection	Phase Complete		2026-03-30					715	2028-03-31		
5-20-00	Inspection	Pilot and co-pilot edge light panel and under storm window inspection		2026-03-27					349	2027-03-31		
5-20-00	Inspection	Power lever stop pin inspection		2024-03-03	954.50							
4-00-00, Chart 1, Item 1	Airframe	Replace all windshield screws - Ch. 4 Item	101-3259	1993-02-10		5,169						
5-11-00	Airframe	RH emergency exit self illuminating sign replacement		2024-03-04						2030-10-31		
72-00-00	Inspection	RH engine 400 HR borescope		2024-03-04	154.50							
	Engine	RH engine AGB internal scavenge pump inlet screen inspection		2024-03-04	754.50							
72-00-00	Engine	RH engine chip detector bridge inspection		2026-03-27	6,000				349	2027-03-31		
72-00-00	Engine	RH engine FCU overhaul		2007-06-29	915.50							
5-20-00	Inspection	RH engine fire bottle hydrostatic inspection		2026-03-27						2031-03-31		
5-20-00	Airframe	RH engine fire bottle squib replacement		2024-03-04					715	2028-03-31		
72-00-00	Engine	RH engine fuel nozzle inspection and cleaning		2024-03-04	154.50							
72-00-00	Engine	RH engine fuel pump overhaul		2007-06-29	915.50							
	Inspection	RH engine ignition system inspection		2024-03-04	154.50							
	Engine	RH engine inlet screen inspection		2024-03-04	354.50							
5-20-00	Inspection	RH engine isolators inspection		2007-06-29	1,263.90							
	Inspection	RH engine minor inspection		2026-03-27	200				349	2027-03-31		
5-11-00	Engine	RH engine oil filter replacement		2024-03-04	754.50							
	Engine	RH engine overspeed governor overhaul		2007-06-29	3,815.50							

Compliance Listing - N670RA

ATA Code	Type	Name	Part Number	Start/Install	Hrs Rmng	Cycl Rmng	Lngs Rmng	Bat Rmng	Days Rmng	Due Date	Status	Open W/O
5-11-00	Engine	RH engine P3 filter replacement		2007-06-14	49.65						Impending	
	Engine	RH engine propeller governor overhaul		2008-09-02	2,229.70							
5-11-00	Engine	RH engine starter/generator overhaul	23085-001	2024-03-04	754.50							
SB 13303 R21	Engine	RH engine TBO	PT6A-60A (PCE-95711)	2007-06-29	915.50							
5-20-00	Inspection	RH main gear actuator clevis inspection		2024-03-04		814						
5-20-00	Inspection	RH main landing gear drag brace inspection		2024-03-04		7,814			1,418	2030-03-04		
5-11-00	Airframe	RH main landing gear exposed brake hose replacement		2024-03-04					1,080	2029-03-31		
5-20-05, 13 thru 15	Inspection	RH main landing gear tear down inspection		2024-03-04		7,814			1,445	2030-03-31		
5-10-00	Inspection	RH MLG inboard wheel assembly penetrant inspection		2022-12-29					-471	2024-12-31	Overdue	
5-10-00	Inspection	RH MLG outboard wheel assembly penetrant inspection		2024-12-29					259	2026-12-31		
	Inspection	Right Propeller Overhaul		2018-10-18	4,000				-898	2023-10-31	Overdue	
	Inspection	Stringers from FS 88 through FS 125 and instrument panel support brackets priority area inspection		1993-02-10		5,169						
5-20-00	Inspection	Upper and lower windshield corner priority are inspection		1993-02-10		5,169						
5-11-00	Airframe	Window defog filter replacement/inspection							0		NotApplicable	
57-18-01, Table 201, Item 11	Inspection	Wing Bolt Fitting Inspection - Eddy Current - Ch. 4		2024-03-04					1,080	2029-03-31		
57-18-01, Table 201, Item 11	Inspection	Wing Bolt Fitting Inspection - Visual - Ch. 4		2024-03-04					1,080	2029-03-31		
57-18-01, Table 201, Item 12	Inspection	Wing Bolt Inspection - Dye Pen - Ch. 4		2024-03-04					1,080	2029-03-31		
57-18-01, Table 201, Item 12	Inspection	Wing Bolt Inspection - Visual - Ch. 4		2024-03-04					1,080	2029-03-31		
4-00-00, Chart 3, Item 1	Airframe	Wing Center and Outboard Section Life Limit - Ch. 4	101-4050; 101-1200	1993-02-10	1,969.80						Upcoming	
57-18-01, Table 201, Item 13	Inspection	Wing Forward Spar Angle - Eddy Current - Ch. 4		1993-02-10	11,669.80							
4-00-00, Chart 3, Item 7	Airframe	Wing to fuselage attach angles - Ch. 4	101-120032-3, and -4	1993-02-10	23,669.80							

JetPros

231 Terminal Circle , Longview, TX 75603
903-309-4687, mx@jetpros.com

Compliance Listing - N670RA

ATA Code	Type	Name	Part Number	Start/Install	Hrs Rmng	Cycl Rmng	Lngs Rmng	Bat Rmng	Days Rmng	Due Date	Status	Open W/O
5-20-00	Inspection	Wing upper surface bonded panel inspection		2026-03-27					532	2027-09-30		