N5769X

1962 Cessna 320

LH Prop Logbook SPOH 2012 - 2023

Aircraft S/N: 320-0069



Prepared by the worldwide aviation specialists at RidgeAire, Inc.



RAFT PROPELLER LLC

CRS N5PR141Y

PROPELLER LOGBOOK



Owner Name Address Propeller Model 3 **Blade Model** Hub Serial No. Blade Serial No. 1. A 79466 2. A79352

DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS, SERVICE LETTERS, & MINOR ADJUSTMENTS

| DATE | TACH TIME | DESCRIPTION OF WORK | SIGNATURE |
|--|--|--|--|
| Jan 1991 | Hobbs 276. | p laborification | lapoly do |
| | Time Si | nce new 0.0 Installed | ode Design 4 X Y as 2 XV |
| Same and the same | this aro | peller on the 4H position | 1819ms |
| | of Cessr | a 320 sn#320-0069 | b Ser. No. of ser. / Live |
| | N5769X | Ground run-up for leak | as Set Mass |
| | # operation | nal check good - END- | SRM 17 P585-5684 |
| and the second program of the second program | and advantage of the control of the self-black of a first | The state of the s | No. 7 - 2 - 1 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 |
| Feb 199 | 2 7 | Annual inspection and airworthy condition as | In Accordance |
| SN 104.0 | ar | Annual inspection and | determined to be |
| 7380.0 | on | airworthy condition as | this time-END |
| | H RANGE |)T19 | AP585-588 |
| | wod | High | 41 |
| | A Sevense A | Land State of Pentings | Bevokati L. L. Bevokati |
| the comment of the second | had a grant of the state of the | lebo / nomerco | SAME OF THE SAME O |

MAINTENANCE & SERVICE HISTORY

| Date 20/2 | Total Propeller Time | Time Since Overhaul | Description of Work | Authorized Signatures Repairman and Station Certificate Numbers |
|-----------------------|--|---|---|---|
| 7-20 | | 0.0 | | |
| | | | | |
| TI N: IN Si | HIS PROPELLER N SPR141Y AND WAS ISPECTED IAW WIT ERVICE. GROUND I | S REINSTALLED. SEE NMAP | HAULED BY NEW MEXICO AIRC WO# 4015. I CERTIFY THAT THIS AND HAS BEEN DETERMINED AIRW | PROPELLER HAS BEEN |
| | | | | |
| and the second second | 1 | | | |
| Oc | tober 19, 2013 hobb | os: 1566.9 TSMOH: 97.4 Total | 1300.8 | Bode Aviation INC |
| Oc. | tober 19, 2013 hobb 769X L/H Propeller | os: 1566.9 TSMOH: 97.4 Total Hartzell HC-A2MVF-2 s/n Y29 | 1300.8 12 | Bode Aviation INC CRS J7BR555Y |
| 10 ch | 769X L/H Propeller 0 hour/Annual inspec | Hartzell HC-A2MVF-2 s/n Y29 | 1300.8 12 e with far 43 appendix d, using Ces propeller has been inspected IAW wit | CRS J7BR555Y |

MAINTENANCE & SERVICE HISTORY

| Date | Total Propeller Time | Time Since Overhaul | Description of W | Authorized Signatures Repairman and Station Certificate Numbers |
|------|--|--|--|--|
| | | s: 1629.7 TSMOH: 160.2 ller Hartzell HC-A2MVF-2 | | Bode Aviation INC CRS J7BR555Y |
| | checklist as a guide has been determine | Dressed blades. I certife to be in an airworthy co | y that this propeller has been insp | d, using Cessna model 320 inspection ected IAW with an Annual Inspection and egard to the above work performed. R555Y WO 7212 |
| | | 1701.2 TSMOH: 231.7 To Hartzell HC-A2MVF-2 s/ | | Bode Aviation INC CRS J7BR555Y |
| 0 | iculial as a dulue. D | ressed biades. I certify th | ordance with far 43 appendix d, nat this propeller has been inspecte tion and return to service with respe | using Cessna model 320 inspection and lAW with an Annual Inspection and lect to the above work performed. |
| | tuart Miles A&P 5853 | | Holdlite . | WO 7558 |

Note: Enter compliance with all applicable FAA Airworthiness Director on pages 11 & 12

February 02, 2017 Hobbs: 1765.4 TSMOH: 297.9 Total: 1501.3 **Bode Aviation INC** N5769X L/H Propeller Hartzell HC-A2MVF-2 S/N Y2912 100 hour/Annual inspection completed in accordance with far 43 appendix d, using Cessna model 320 inspection checklist as a guide. Dressed blades. I certify that this propeller has been inspected IAW with an Annual Inspection and has been determined to be in an airworthy condition and return to service with respect to the above work performed. gnatures nd Station Gilbert B. Aragon A&P 1835643 IA WO 7807 lumbers October 04, 2019 hobbs: 1811.3 TSMOH: 341.8 Total 1545.2 **Bode Aviation INC** N5769X L/H Propeller Hartzell HC-A2MVF-2 s/n Y2912 CRS J7BR555Y Annual inspection completed in accordance with far 43 appendix d, using Cessna model 320 inspection checklist as a guide. Dressed blades. I certify that this propeller has been inspected IAW with an Annual Inspection and has been determined to be in an airworthy condition and return to service with regard to the above work performed. Stuart Miles A&P 585393595 IA WO 8286 November 22, 2021 Hobbs: 1811.3 TSMOH: 341.8 Total 1545.2 **Bode Aviation INC** N5769X L/H Propeller Hartzell HC-A2MVF-2 s/n Y2912 KAEG Annual inspection completed in accordance with far 43 appendix D inspection checklist as a guide. Dressed blades. This propeller has been inspected IAW with an Annual Inspection and has been determined to be in an airworthy condition and is approved for return to service with respect to the above work performed. WO 9325 Stuart Miles A&P 585393595 IA <

Note: Enter compliance with all applicable FAA Airworthiness Director on pages 11 & 12

MAINTENANCE & SERVICE HISTORY

| Date | N5769X L/H Pro Annual inspection This propeller has | s been inspected IAW w | /F-2 s/n Y2912 ce with far 43 appendix D inspecti | Bode Aviation INC KAEG on checklist as a guide. Dressed blade been determined to be in an airwortik performed. | Station nbers |
|------|---|------------------------|--|---|------------------|
| | Stuart Miles A&P | 585393595 IA | Junt Mobile | WO 9806 | |
| | | | | | |
| | | | | | 3,457 |

Note: Enter compliance with all applicable FAA Airworthiness Director on pages 11 & 12

F.A.A. AIRWORTHINESS DIRECTIVE

| Date 2012 | Total Propeller Time | Since Overhaul | A.D./Bulletin/Letter Number | Authorized Signatures Bepairman and Station |
|-----------|--|---------------------|---|--|
| 7-20 | | 0,0 | CIWAD 97-18-02 mv mod | LING NSPRINY |
| | | 9-1 | | DIG NSPRIANY |
| | de constitución de constitució | | | |
| | And the second s | | | |
| | | | | |
| | | | | |
| | > Ener con | change with all are | sk of the PAA American Princess December of | 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 |

STAPLE M

MAINTENANCE RELEASE

The aircraft and/or component identified within was repaired and inspected in accordance with current Federal Air Regulations and was found airworthy for return to service with respect to work performed.

weller w.o. # 4016 MODHC-AZMUF-2 S/N Y29/2

NEW MEXICO AIRCRAFT PROPELLER, LLC 5 Airport Road Belen, NM 87002 (505) 864-4500 Repair Station N5PR141Y

Date 2-20-2012

New Mexico Aircraft Propeller 5 Airport Road Alexander Airport Belen, NM 87002

> phone: 505-864-4500 toll free: 888-477-5067 fax: 505-864-4555