

## Aircraft Details

**Use the query results with caution**

Over time registration numbers are assigned to different aircraft and diverse data stores with inconsistent data are being joined

[Back to Query Entry](#)

### N Number: 414CR

<b>Last Action Date</b>	2022-07-28		
<b>Airworthiness Date</b>	1975-02-27	<b>Expiration Date</b>	2024-09-30
<b>Manufacturer_Name</b>	CESSNA	<b>Model Name</b>	414
<b>Registrant Name</b>	SERMI INC	<b>Street</b>	1211 SAN DARIO AVE STE 1124
<b>Registrant City</b>	LAREDO	<b>Registrant State</b>	TX
<b>Registrant Zip Code</b>	780404505	<b>Country</b>	UNITED STATES
<b>Region</b>	Southwestern	<b>Registrant Type</b>	Non Citizen Corporation
<b>Fract Owner</b>		<b>Certificate Issue Date</b>	2021-09-02
<b>Status</b>	Foreign companies which have not returned their flight hour reports		
<b>Serial Number</b>	414-0629	<b>Aircraft Type</b>	Fixed wing multi engine
<b>Mode S Code</b>	51161476	<b>Year Mfr</b>	1975
<b>Aircraft Category</b>	Land	<b>Builder Certification</b>	Type Certificated
<b>Number Engines</b>	2	<b>Number Seats</b>	7
<b>Aircraft Weight</b>	CLASS 1	<b>Aircraft Cruising Speed</b>	198
<b>Airworthiness Classification</b>	Standard	<b>Approved Operation Codes</b>	Normal
<b>Engine Manufacturer</b>	CONT MOTOR		
<b>Engine Model Name</b>	TSIO-520 SER	<b>Engine Type</b>	Reciprocating
<b>Engine Horsepower/Thrust</b>	0	<b>Fuel Consumed</b>	0.00

#### ----- History 1 -----

<b>Last Action Date</b>	2021-09-02		
<b>Registrant Name</b>	SERMI INC	<b>Street</b>	1211 SAN DARIO AVE STE 1124
<b>Registrant City</b>	LAREDO	<b>Registrant State</b>	TX
<b>Registrant Zip Code</b>	780404505	<b>Country</b>	UNITED STATES

<b>Region</b>	Southwestern	<b>Registrant Type</b>	Non Citizen Corporation
<b>Fract Owner</b>		<b>Certificate Issue Date</b>	2021-09-02
<b>Status</b>	N-Number Assigned and Registered		

----- History 2 -----

<b>Last Action Date</b>	2021-08-10		
<b>Registrant Name</b>	SERMI INC	<b>Street</b>	1211 SAN DARIO AVE STE 1124
<b>Registrant City</b>	LAREDO	<b>Registrant State</b>	TX
<b>Registrant Zip Code</b>	780404505	<b>Country</b>	UNITED STATES
<b>Region</b>	Southwestern	<b>Registrant Type</b>	Non Citizen Corporation
<b>Fract Owner</b>		<b>Certificate Issue Date</b>	2020-10-09
<b>Status</b>	Foreign companies which have not returned their flight hour reports		

----- History 3 -----

<b>Last Action Date</b>	2020-10-09		
<b>Registrant Name</b>	SERMI INC	<b>Street</b>	1211 SAN DARIO AVE STE 1124
<b>Registrant City</b>	LAREDO	<b>Registrant State</b>	TX
<b>Registrant Zip Code</b>	780404505	<b>Country</b>	UNITED STATES
<b>Region</b>	Southwestern	<b>Registrant Type</b>	Non Citizen Corporation
<b>Fract Owner</b>		<b>Certificate Issue Date</b>	2020-10-09
<b>Status</b>	N-Number Assigned and Registered		

----- History 4 -----

<b>Last Action Date</b>	2020-08-18		
<b>Registrant Name</b>	REGISTRATION PENDING	<b>Street</b>	1211 SAN DARIO AVE STE 1124
<b>Registrant City</b>	LAREDO	<b>Registrant State</b>	TX
<b>Registrant Zip Code</b>	780404505	<b>Country</b>	UNITED STATES
<b>Region</b>	Southwestern	<b>Registrant Type</b>	Individual
<b>Fract Owner</b>		<b>Certificate Issue Date</b>	
<b>Status</b>	Registration pending		

----- History 5 -----

<b>Last Action Date</b>	2020-01-28		
<b>Registrant Name</b>	AVIATION SOUTH INC	<b>Street</b>	1759 DEMERE RD
<b>Registrant City</b>	ST SIMONS ISLAND	<b>Registrant State</b>	GA

<b>Registrant Zip Code</b>	315222815	<b>Country</b>	UNITED STATES
<b>Region</b>	Southern	<b>Registrant Type</b>	Corporation
<b>Fract Owner</b>		<b>Certificate Issue Date</b>	2020-01-28
<b>Status</b>	N-Number Assigned and Registered		

----- History 6 -----

<b>Last Action Date</b>	2016-12-27		
<b>Registrant Name</b>	FIRST CITY AVIATION INC	<b>Street</b>	1914 MARSH OAK LANE
<b>Registrant City</b>	SEABROOK ISLAND	<b>Registrant State</b>	SC
<b>Registrant Zip Code</b>	29455	<b>Country</b>	UNITED STATES
<b>Region</b>	Southern	<b>Registrant Type</b>	Corporation
<b>Fract Owner</b>		<b>Certificate Issue Date</b>	2011-05-17
<b>Status</b>	First Notice for Registration Renewal		

----- History 7 -----

<b>Last Action Date</b>	2014-02-27		
<b>Registrant Name</b>	FIRST CITY AVIATION INC	<b>Street</b>	1914 MARSH OAK LANE
<b>Registrant City</b>	SEABROOK ISLAND	<b>Registrant State</b>	SC
<b>Registrant Zip Code</b>	29455	<b>Country</b>	UNITED STATES
<b>Region</b>	Southern	<b>Registrant Type</b>	Corporation
<b>Fract Owner</b>		<b>Certificate Issue Date</b>	2011-05-17
<b>Status</b>	First Notice for Registration Renewal		

----- History 8 -----

<b>Last Action Date</b>	2011-05-17		
<b>Registrant Name</b>	FIRST CITY AVIATION INC	<b>Street</b>	1914 MARSH OAK LANE
<b>Registrant City</b>	SEABROOK ISLAND	<b>Registrant State</b>	SC
<b>Registrant Zip Code</b>	29455	<b>Country</b>	UNITED STATES
<b>Region</b>	Southern	<b>Registrant Type</b>	Corporation
<b>Fract Owner</b>		<b>Certificate Issue Date</b>	2011-05-17
<b>Status</b>	First Notice for Registration Renewal		

----- History 9 -----

<b>Last Action Date</b>	2010-03-03		
<b>Registrant Name</b>	BERGEN & BERGEN PC	<b>Street</b>	1914 MARSH OAK LN

<b>Registrant City</b>	SEABROOK ISLAND	<b>Registrant State</b>	SC
<b>Registrant Zip Code</b>	29455-6305	<b>Country</b>	UNITED STATES
<b>Region</b>	Southern	<b>Registrant Type</b>	Corporation
<b>Fract Owner</b>		<b>Certificate Issue Date</b>	2010-03-03
<b>Status</b>	Third Notice for Re- Registration/Renewal		

----- History 10 -----

<b>Last Action Date</b>	2009-08-31		
<b>Registrant Name</b>	JM AIRCRAFT INC	<b>Street</b>	3103 9TH AVENUE DR NW
<b>Registrant City</b>	HICKORY	<b>Registrant State</b>	NC
<b>Registrant Zip Code</b>	28601-8508	<b>Country</b>	UNITED STATES
<b>Region</b>	Eastern	<b>Registrant Type</b>	Corporation
<b>Fract Owner</b>		<b>Certificate Issue Date</b>	
<b>Status</b>	N-Number Assigned and Registered		

----- History 11 -----

<b>Last Action Date</b>	2003-02-24		
<b>Registrant Name</b>	CODE ENGINEERING CO INC	<b>Street</b>	3069 CASCADE CT #13A
<b>Registrant City</b>	PRESCOTT	<b>Registrant State</b>	AZ
<b>Registrant Zip Code</b>	86301	<b>Country</b>	UNITED STATES
<b>Region</b>	Western-Pacific	<b>Registrant Type</b>	Corporation
<b>Fract Owner</b>		<b>Certificate Issue Date</b>	2000-02-15
<b>Status</b>	A second attempt has been made at mailing a Triennial Aircraft Registration form with no response		

----- History 12 -----

<b>Last Action Date</b>	2000-02-15		
<b>Registrant Name</b>	CODE ENGINEERING CO INC	<b>Street</b>	3069 CASCADE CT #13A
<b>Registrant City</b>	PRESCOTT	<b>Registrant State</b>	AZ
<b>Registrant Zip Code</b>	86301	<b>Country</b>	UNITED STATES
<b>Region</b>	Western-Pacific	<b>Registrant Type</b>	Corporation
<b>Fract Owner</b>		<b>Certificate Issue Date</b>	2000-02-15
<b>Status</b>	N-Number assigned		

\*\*\*\*\* No Deregistered Data Found \*\*\*\*\*

\*\*\*\*\* No Reserved Data Found \*\*\*\*\*

----- FAA Accident/Incident 1 -----

<b>Occurrence Date</b>	1993-01-29	<b>Aircraft Make</b>	CESSNA
<b>Aircraft Model</b>	414	<b>Damage</b>	
<b>Document Last Modified</b>	2012-08-08		
<b>Narrative</b>	ENGINE QUIT ON TAKEOFF ROLL. AIRCRAFT VEERED LEFT OFF RUNWAY. CAMSHAFT WAS FOUND BROKEN NEAR GEAR ATTACHMENT.		

\*\*\*\*\* No NTBS Accidents Found \*\*\*\*\*

\*\*\*\*\* No NTBS Pre 1982 Accidents Found \*\*\*\*\*

----- SDR 1 -----

<b>Date Of Report</b>	1986-10-21	<b>Operator Control Number</b>	EA038686939
<b>Date Of Occurrence</b>	1986-08-13	<b>Aircraft Registration</b>	414CR
<b>Aircraft Manufacturer</b>	CESSNA	<b>Aircraft Group Code</b>	414
<b>Aircraft Manufacturer Model</b>	414	<b>Aircraft Make Model Sequence</b>	2075908
<b>Air Carrier Name</b>	Unknown	<b>Air Carrier Operation Code</b>	
<b>Operation Type</b>	G	<b>Stage Of Operation</b>	TAXI/GRND HDL
<b>Severity Factor</b>	COMMON	<b>Air Transport Association Code</b>	Magneto/Distributor
<b>Precautionary Procedures</b>	NONE	<b>Nature Of Condition</b>	OTHER
<b>Segment</b>	ENGINE	<b>Descriptive Name Of Part</b>	RETARD BREAKER
<b>Defective Location On Aircraft</b>	LT MAG	<b>Failed Part Condition</b>	BRKN CAM STRIKER
<b>Part Total Time</b>	0	<b>Part Total Time Since Overhaul</b>	350
<b>Component Manufacturer</b>	BENDIX	<b>Component Manufacturer Model</b>	S6RN1231
<b>Component Manufacturer Number</b>		<b>Manufacturer Part Number</b>	10382554
<b>Ata Code</b>			
<b>Remarks</b>	LEFT ENG WOULD NOT START. FOUND CAM STRIKER ON RETARD BREAKER BROKEN OFF.		