

**E. L. Fincher Aviation**

**Engine Logbook**

04/27/2020

**Services Inc.**

N824DH

Bombardier CL-601

S/N: 3047

AFTT: 7143.0

AFTC: 5375

Engine: R/H S/N: 350130 Hours: 13251.4 Cycles: 7955 CF34-3B


Accomplished Long Term Preservation of Engine. 90 to 730 Days on April 27, 2020. GE SEI 580 Shop Manual, 72-00-00. Engine – Storage and Transportation. 4. Engine Preservation. B.(1) Long Term Preservation. Examine and record the humidity of the air inside the shipping container every 60 days. Desiccant must be changed if they become ineffective.

I certify this aircraft has been inspected and/ or repaired in accordance with FAR 91.409 (f) (3) and current manufacturer's maintenance manuals. It has been found to be airworthy and is approved for return to service with respect to the work performed. For further details and information reference the work order on file at E. L. Fincher Aviation Services.

**Inspected By:**

**Eddie Fincher**

**A&P: 3370338**



---