N2162L 2005 Cessna 182T

Engine Logbook SNEW 2005 - 2024

MSN: 18281662



Prepared by the worldwide aviation specialists at RidgeAire, Inc.









ENGINE MAINTENANCE RECORD

AIRCRAFT SERIAL AND REGISTRATION 1838/662

ENGINE MODEL AND SERIAL ZO-540-ABIAS L-30589-48E

D5518-3-13

INSTRUCTIONS

This record should be completed and maintained in accordance with FAA Federal Aviation Regulations 43.9, 43.11 and 91.173 and/or other prevailing government regulations.

NOTE: Record Service Bulletins and Airworthiness Directives in the back of this record as well as the Airframe Maintenance Record.

Copyright © 1993




DATE	TOTAL IN SER		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE
2005	HOURS	10THS		& NUMBER
,				1828166Z
07/18			NEW RECIPROCATING ENGINE CERTIFICATE	
			This is to certify that the engine as described hereinafter has been manurun-in and tested as prescribed by LYCOMING specifications and Aviation Regulations. No further run-in is required. All applicable Aviation Airworthiness Directives and Lycoming Service Bulletins has complied with at time of Manufacture.	Federal Federal
- 17			MODEL 10-540-AB1A5 SERIAL NO. L-30589-48E DATE 6/14/05 (AUTHORIZED REPRESEN	TATIVE)
-	-			G ENGINES Oliver Street 7701 U.S.A.
			Form No. 777-B (Rev. 3/03)	

			MAINTENANCE RECORD	
DA		TOTAL TIME N SERVICE	DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
200	5 HOU	IRS 10TH	is	u Hombert
09/2	2	3 9	Engine model IO-540-AB1A5, S/N <u>L-30589-486</u> has been installed on aircraft # <u>I8281662</u> . This engine serviced with Phillips Aviation oil type M 20W50 weight.	Show ODARF10/129CE
2005	38	8	CHAGED OIL AND FILTER, SERVICED SUMP WITH PHILLIPS 200-60 TYPE MEND-	1861549441
2006	55	S	CHANGED OIL AND FILTER . CLEANED SCREEN - SEQUED SUMPWITH AFROSHELL ASWIDD - ISMO -	2827152
00 p 18CH	106	3	CLANGED OIL AND FILTER, SERVICED SUMP WI AEROSHED 100. LEAR V OR , - END - 1A61549441	

			MAINTENANCE RECORD	
DATE	TOTAL T		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	HOURS	10THS		a NOMBER
MAY II	158	0	CHANGED OIL AND FICTER, CHECKED SCREEN, SERVICED SUMP WI AFROSHELL 100, EVNUP+ LEAK VOK, -END-	1A61549441
July 260	207	2	CHANGED OIL AND FILTER SERVICED - SUMP W/ AEROSHELLIOCH AEROSHELLIOO WASH AND LEAK CHECK GOOP END	
SEPT 28 7006	256	S	CHANGED OIL AND FILTER, SERVICED SUMP WI AEROSHE 100, CHECKED TIMING AND COMPRESSIONS #175/got 2 78/got 3 79/got 4 76/got 5 76/got 678/got REPLACED ALL	
IE IZ	311		CONFR SCREWS AND CYL DRAIN CLAMPS, C/M AP ZOOZ-ZG-OI, NEXT DUE @ 356.5, CHECKED ADS FOR COMPLIANCE THEN ISSUE ZOOG-IQ, WASHED ENGINE, RUNUP AND LEAK VOK, "I CERTIFY THIS ENGINE HAS	1 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3
60	MARKET TO SERVICE TO S	72.12.	BEEN INSPECTED IAM ANNUAL/100 HOUR INSPECTION PROCEDURES, AND IS APPROVED FOR RETURN TO SERVICE!	-ENDENDENDENDENDENDEND

			MARY 200 MC2	AUTHORIZED SIGNATURE,
DATE		AL TIME ERVICE	DESCRIPTION OF THE WORK PERFORMED	CERTIFICATE TYPE & NUMBER
	HOURS	10THS		1
11-17	310	0	Changed engine oil and filter. Checked and cleaned screen. Serviced w/ 99ts Phillips 20w50x/C. Leak check normal End-	AP+8+8753
Jan 11 2007	357	2	Changed engine oil and filter. Checked and cleaned suction severn. Serviced sump w/ 9 ats Phillips 20050 X/C, Lead Check normal. (CW AD 2003-26-01 by visual inspects on	
<u>5007</u>			of Ivel injection lines and clamps. Cleaned, gapped and rotated spark plugs. Run-up and leak check normal.	APACAZ753
3-22	404	1	CHANGED OIL AND FILTER, SERVICED SUMP WITH 90TS OF PHILLIPS X/C 20W50 OIL. RUN UP MUS LEAK CHECK NURMAL.	1441549441
			C D C I L L L L L L L L L L L L L L L L L L	




DATE	TOTAL T	/ICE	DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	HOURS	10THS		
24 May	Tach4	156,6	Droined o'cl, Soop sample toben, reglaced oil filter, let open old filter, no material, found at this time, added 7 Gts Philleis	
2007	Hobbs.	540,5	200150xc oil, Installed oil quick around plug. Hours right	,
-			due at tack 556.6 or annual. Hall finder by	14/2816593IA
2007	506	9	CHANCES OIL + FILTER, SERVICED SUMP WI PHULIPS YCZOW-SO, REPACED ALL SPAKE DWGS, CHECKES COMPRES # 174/80#276/80#376/80#4760#579/80#67480, REMOVED + REINSTALLES L+R MAGNETOS AFTER 500 HOJE MAG INCIPET	
200	. 1		COMPLIANCE THEY ISSUE ZOOT-ID! "I CERTIFY THIS ENGINE COMPLIANCE THEY ISSUE ZOOT-ID!" I CERTIFY THIS ENGINE COMPLIANCE THEY ISSUE ZOOT-ID!" I CERTIFY THIS ENGINE	
69.5	9942 9742 1657		PROCEDURES, AND IS APPROVED FOR RETURN TO SERVICE! - END -	TAU1549441

DATE	TOTAL IN SER		AIR	AUTHORIZED SIGNATURE, CERTIFICATE TYPE
	HOURS	10THS	ORLANDO	& NUMBER
			Date: 1-10-2008 Make: Cessna Model: 182T S/N: 18281662 Tach: 560.8 Changed oil and filter. Cut oil filter and inspected, no metal	
			found at this time. Removed, inspected, cleaned and reinstalled oil suction screen. Installed new CH48110-1 oil filter. Serviced sump with 9qts. Phillips 20w50X/C oil. Run-up and leak check normal.—END—	
			The aircraft listed above has been inspected and repaired IAW manufacturer's maintenance manuals and current FAA regulations and is approved for return to service. Jeff Hyddleston AP2828753	
		-	Jeli Hyddiestoli Arzozoros	

			MAINTENANCE RECORD	
DATE	TOTAL IN SERV		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE
	HOURS	10THS	Supposed to the first of the second of the s	& NUMBER
7.2.08	602	フ	CHANGED OIL YFILTER. INSTALLED NEW KELLY AGED ES 48110 OIL FILTER. SERVICED SUMP WITH 9 RTS. PHILLIPS 204-50 X/C OIL. RON-UP + LEAK CHECK OK	AR 2359740
9/14/08	624	0	CIW 5.B. 3-08 A REPLACED CARBON BRUS WITH PINAM3215 AND CAM PIN AM3611 BOTA MAGNETOS, 5.B.3-08 A NO LONGER APPLIES TO	
	1		PIN 6351, SIN 05051093 & SIN 05051092 MAG COMPLETED SOOHR INSPECTION BOTH MAGS ADJUSTED CONTACTS & TIMING	WO#0843/
9/16/	624	0	C/W ANNUAL TUSPECTION THIS DETE. COMP VAT 96 HS 78 #678 Changes oil; F. Her, Selvices with 8 Gts Prospection shows No Contamination. UW 583-08 on Slice teacher, Reinstalled & Timed to Engine ops of Good teacher, Reinstalled & Timed to Engine ops of Good	MIPS 20 WSD - F. HAL MIPS , REPLACED CARBONS C/W AB 2007-26-01
DG .			All SPARK Plugs W/ New ORE M-38. Cheaves, IN-perces, Frank Oil Berry Sender Replace with New P/N P/A	Reinstalles A.R. Filter 5-5281. Engal
REPLACED GAS LESS	N) RCC 10/5/ 5LR7	Ken 1,000 59061	Approven (& Return to service. Mblowson	

DATE		AL TIME ERVICE	DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE
	HOURS	10THS		& NUMBER
11.20	648	0=	OIL PHILLIPS GG X/C SAE 20N-50 8 ORTS OIL FILTER KELLY MERO ES 48110 REPLACED. OLD OIL FILTER CUTTINSPECTED OR CHECKED POR OIL LEAKS. CK	AN 2358740
4.7	693	00	REPLACED DIL + FILTER: PHILLIPS CC X/C SAE 20W-50 8 ORTS. TEMPESS RA 48/10. "CANGUALP" ADDED TO OR ENGANG RUN-UP NO LEMES. DIC TRITER CUT X NO MEDIA RESIDUE FOUND	5-1- man
1/09	733	00	100 Hour was Dove in Accordance with FAR'S 43 appendix D. Compression Check# 1780#2 380#3 790#4 880#5: 2. Change Engine oil and Filter	Check List
			3. CLEANED AND GAPOD SPARK PLUGS 4. Checked Fuelsys Tem 5. Tighten ALL INTAKE PIPES + 80 APTORS	10 m. 11 m. 1 m. 1 m.
			6 inspect mags and check Timmings 7. WASH ENGINE 8. LUBED ENGINE CONTEDLS	



DATE 10/	TOTAL T IN SERV		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE
19/1/09	HOURS	10THS	Limber On in Jaking	& NUMBER
CONT	133	00	9. Checked Bil Engine Accessories 10. Checked Exhaust Pipes AND Shrouds	
			11 chedees AD'S ONLY ONE NEW ADOR-02-03-) AD 63-14-02	Exempt
1200	bar .	,	12. ADS 03-1403 N/ALAD 08-19-05 ANBY MODEL	15 145 180 ab a
0	-50		773	13 4000 NOIN-1
3.79	. = 1	~ I	Total Time 7.33 Time S/M/O	Signal Land
06	773	0	Inspection And Was Determined To Be Determined To Be Address Constitution.	2100000
2	Print 1		Edwin W. Stewart 004341188	State of the state

			MARTERATOR	THE STATE STATE OF THE STATE OF
DATE		AL TIME ERVICE	DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	HOURS	10THS		and the same
11.29	773	10	OIL REPLACED PHILIPS GG X/C SAE 20N-50 BRUNKTS, OIL FILTER REFLACED KELLY AERO ES 48110 OIL FILTER CUT + INSPECTED FOUND OK . EVGINE & RUNUP. CHECK FOR OIL LEAKS OF	A 235 9740
3,19	8/2	40	8 QUARTS, DIE FILTER REPLACED KELLY ARD 25 48110, DIE FILTER CUT TINSPECTED OF A	2359740
19/			Topporting was Dave in accorpance with FAR.	43 Appendix D
2010	869.	0	Check List Check #17% #278/80#378 #	478045780#6780
		ó	CHANGED ENG OIL TELTER.	
		4	New Sparre PLUMS I Check magis Theck pus No IVEW ares	
		6	. WASh DOWN ELYGINE	
		1	24 PEdurn W Stewart 004 3411,88	

DATE	TOTAL 1		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	HOURS	10THS	The second control of the control of	& NUMBER
			Dato 10/22/2010 fach Time 869	
			I Sertify That This ENGINE Has Been Inspected In Accordance With A COFFOUR ANNUAL	
			Inspection And Was Determined To Be In Airworthy Condition. A&P/I.A. Edwin W. Stewart 004341188	A SULLEY PARTY
2/9	914	-	OIL REPLACED ATILLY S GGYC SAE 20W-50 8 QUARTS FILTER NOT REPLACED THIS TIME 12 02 CAMGUARD ADDED	AR 235 9740
6/8	941		OIL CHANGED: PHILIPS 66 X/C SAIJ 20W-50 BRUARIS, CAM GUARD 160Z FILTER CHANGED TOMPEST AA 48110, SUETTON BEIRDEN CHANGED	0 7 R 235 9740

DATE	TOTAL IN SE	TIME	DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE
	HOURS	10THS		& NUMBER
11-62-204	980.	0	Checker For Oil Lepts ComPraction	041.6.381.71
	25.5		checker For oil heats ComPraction	z - warner
			Date 1/-02-2011 Fach Time 4/68.2 980.0 Total Time 4/68.2 Howard Hospital That This ENGINE Has Been Has pacted In Accordance With A 100 Hour Annual	
		-	Inspection And Was Determined To Bo In Airworthy Condition. A&P/I.A. Edwin W. Stewart 004341188	
		4		



MAINTENANCE RECORD

DATE	TOTAL T IN SERV	ICE	DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	HOURS	10THS		a NUMBER
3/22	1021	00	ENGINE OIL CHANGED PHUPS XLE 20W/50. OVERAL INSPECTION OIL	20R 2359740
7/27 2012	1052	00	ENGINE DIL + FILTER CHANGED PHILIPS ZOW/50 AA 48110 TEMPEST DIL FIG EUT (NSPECTED OR	x/c nel
(1-29-12	1079	00	New PLugs, New oic AND FILTER New VARIAN Pum PSIN	CO2WOGANOFILTERS
		,	Total Time 1079.00 Time S/M/0 1079.00 1 Contify That This FNGINE Has Been 1 Contify That This FNGINE HAS Been	
	7 ()		Inspection And Was Determined To Be In Alrworthy Condition. ALP/I.A. Clean W. Sena	Sales Sales

Edwin W. Stewart 004341188

TOTAL TIME IN SERVICE

DESCRIPTION OF THE WORK PERFORMED

AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER



Boxell Aerospace Company 2700 Fort Trenholm Rd. Johns Island, SC 29455 843-860-4486

Eng Page: 1 of 1

AC: Cessna 182

ACTT: UNK

Cycles: N/A

#1 Eng Type: 10-540 -AB1A5 #1 ENG S/N: L-30589-48E

AC S/N: 18281662 WO: 12-137 #1 ENG TT: UNK

Hobbs: 1240.4 Date: 8/9/2012 #1 ENG TACH: UNK

Complied with the following inspections / Tasks:

-C/W 500 hr inspection on left magneto only.

The article identified above was repaired and inspected in accordance with current FAA regulations and was found to be airworthy and is approved for return to service.

Thuller Thomas E. Randall AP36141341A

Maintenance Items:

-Removed left magneto and performed a 500 hr inspection. Replaced out of tolerance parts. Installed same magneto, same position and set mag to engine timing.

-Removed right magneto, model 6351, SN 05051093 and installed factory new magneto model 6351, SN 12050731. Ground run leak and ops checked good.

-All pertinent details filed under this work order.

DATE	TOTAL T		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE
	HOURS	10THS		& NUMBER
4//23	////	-	ENGINE OIL REPLACED: PHILUPS X/C 20W-50 CAM GUARD 1602 ADDED	235 9740
5/8	1141		ENGINE OIL CHANGED PHILLIPS X/e ZOW-50 CAM QUARD 1600 ADDED OIL FILTER CHANGED TEMPESTED AA 48110	2 235 9740
13/08/	1171		100 Hour was DONE INACCORDANCE With FAR'S 43 APPENDIX D.C. LYCOMING MEA 1. New SPANCE PLUGS, COMPRESSION Check #1/28 #4 78/80 #5 78/80 #6 79/90 Mag Timming of LAND GRANINSP	
No.			LUBERII Thinht Controls, Checkinds Bate 11-08-2013 Fach Total Time 1171 Time	S/M/O
in the	IDIN:	1. 19	Inspected in Accordance With A	Be In Alrworthy Condition.

			MAINTENANCE RECORD	
DATE	TOTAL IN SEF		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE
	HOURS	10THS		& NUMBER
4/p	1128		OIL TILTEL CHANGED CHILLES TE 20W- TENTEST AT TOTTO -2 CAM GUARD OIL FILTER OFENED & GRANGED OK Date Hall 14 Bolt Time 1264.0	235 9740
14/11	, , , , , , , , , , , , , , , , , , ,		Total Time / 26 / Time S/M/O I Certify That This ENGINE Has Been Has	Sexture wo
			ASP/I.A. Column 1 Condition	
	33 3		Edwin W. Stewart 004341188 DIG T FILE CHANGED PILL PS XIE ZWIN DIG ALTER OPENED OR	SU 235 975

MAINTENANCE	DECORD
MAINTENANCE	RECORD

			MAINTENANCE RECORD	
DATE	TOTAL T IN SERV		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE
	HOURS	10THS		& NUMBER
2.09.15	1361	.2	1. CLEAN All FUCL INJECTION - REPLACED 2. AV 25 24 864-2 2. Replaced all Spanic Plugs 3. Changed Engine of and Filters 4. Compressin check #1 79/80#2 79/80#3 8% #4 78 #5	19/8 #6 8%
		7	5. Ain intake FILTER · CLEAN + INSpected 6. Check MAD Timing Date 12-09-15 sections 1361.2	market the proof
68.3	10.26		Total Time 1361.2 Time S/M/0 I Certify That This ENGINE Has Been	479 45 8go
Ju Je	3 86		Inspected In Accordance With A 100 Hour ANNUAL Inspection And Was Determined To Be In Airworthy Condition. ASP/IA EQUIA IN AIRWORTH CONDITION ASP/IA	6
3/4/	1380	6,3	SHAND STEWARD CHARDS OK AND 28.	9740

	T ====		MAINTENANCE RECORD	
DATE	IN SER	TIME RVICE 10THS	DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
1/16	1396		THE CON ORSY CHECKED THE	AR 274
16 1	430.		Compression Check #1 79/80 # 2 79/80 # 35	8 447% #5 8%
		R.CA	hansed oil + Filten	Trains
		4. C.) 5. C.)	eck ADS + Service Bulttens Date 12-16-16 Bech Time.	/430.0
			Touristy That This ENGINE Tournated In Accordance With A PINI	Has Been WURL /100 Hour
			ASP/I.A. Solvin W. Stewart 004341	
		9	Super a reference of the contract of the contr	9
	(0)			

DATE	TO"	DAVTONA	AUTHOR ED SIGNATURE
	HOUF	N2162L (Engine) Cessna 182T S/N - 18281662 AIRCRAFT SERVICES	4/05/2017 JUMBER
		Cessna 182T S/N: 18281662 A/RCKAF1 SERVICES Engine M/N: 10-540-AB1A5 S/N: L-30589-48E	Tach: 1435.5
		Performed the following maintenance: 1. Drained the engine oil. Removed, cut open, and inspected the oil filter, no new oil filter (P/N: CH48110-1) and serviced the engine with 12 quarts of	
		Leak checks found to be satisfactory. All work was performed with current regulations of the FAA and is approved for re on file at this Repair Station under WO #13180.	turn to service. Details are
		Daytona Aircraft Services, Inc. 561 Pearl Harbor Drive Authorized Signature Daytona Beach, Florida 32114 FND.	FAA CRS DYTR262K
	- "	EN D	
	- 1		

	Engine	
N2162L Tach: 1466.2 Hobbs:1730.6	New Garden Aviation, LLC New Garden Flying Field PO Box 481 / 1235 Newark Rd Toughkenamon, PA 19374 610-268-2048/Fax 610-268-0342	10/03/2017
0.400T - 20NH49224		N: L-30589-48E hispect, No Contamination AB & Pow Pont A&P 3341870 IA
	MAINTENANCE RECORD	
A/C Reg #: N2162L A/C TI: 14 A/C Ser #: 18281662 A/C Tach: 1 W/O #= 11746 Date: 1/18/2	1467.30 Eng Model : IO-540-AB1A5 Eng Ser # : L-30589-48E	167.30
A/C Reg #: N2162L A/C TT: 14 A/C Ser #: 18281662 A/C Tach: 1 A/C Tac	67.30 Eng Make: Lycoming Eng TT: 1-1467.30 Eng Model: 10-540-AB1A5 Eng Ser #: L-30589-48E 2018 the with 14 CFR Part 91.409 (a)(1), Part 43.15 and Part 43, Applied new filter P/N CH48110-1. Cleaned and gapped spark plu 78/75/74 over 80. Performed engine run, leak check and opsic spection with no defects noted. Recurring AD inspection next any clamp (or clamps) on a fuel injector line (or lines) has been 17-16-11 and reviewed aircraft maintenance records. Determine 1467.30 Eng Make: Lycoming TT: 1-16-11 and reviewed aircraft maintenance records.	pendix D gs. Cleaned screens. Serviced engine with heck good. due in 110 hrs (1577.3 ACTT) or after any n disconnected, moved, or loosened. AD list
A/C Reg #: N2162L A/C TT: 14 A/C Ser #: 18281662 A/C Tach: 1 A/C Make / Model: Cessna / 182T WO #: 11746 Date: 1/18/2 1 Complied with an Annual Inspection in accordance and servicing items. Drained engine oil and install Phillips 20W50 XC oil. Comp. results: 74/76/73/7 2 Complied with AD15-19-07 Fuel Injector Line Immaintenance has been done on the engine where a updated.	67.30 Eng Make: Lycoming Eng TT: 1- 1467.30 Eng Model: 10-540-AB1A5 Eng Scr #: L-30589-48E 2018 the with 14 CFR Part 91.409 (a)(1), Part 43.15 and Part 43, Ap- led new filter P/N CH48110-1. Cleaned and gapped spark plu- 78/75/74 over 80. Performed engine run, leak check and opsic spection with no defects noted. Recurring AD inspection next any clamp (or clamps) on a fuel injector line (or lines) has been specified and reviewed aircraft maintenance records. Determine AD list up dated.	pendix D gs. Cleaned screens. Serviced engine with heck good. due in 110 hrs (1577.3 ACTT) or after any n disconnected, moved, or loosened. AD list ined AD does not apply due to no affected

d

ENGINE MODEL: 10-540-A1B1A5 REG NO N2162L WORK ORDER: 1218 Engine Entries Complied with engine 100 hour inspection Items. Cleaned and gapped spark plugs and checked magneto timing. Compression test: #1 72/80 #2 72/80 #3 78/80 #4 78/80 #5 78/80 #6 72/80 Serviced with Philips 20W-50. Removed, cleaned, and reinstalled fuel injector nozzles. Replaced gasket for oil pressure relief valve. Cleaned engine Completed with A D. 15-19-07 injector line inspection, no discrepancies noted. Next due at tach time 1665 9. Completed ground run, no discrepancies noted. Lectify that this engine has been inspected in accordance with an Annual Inspection and has been determined to be in Airworthy condition. DATE 1/10/2019 SIGNED: Work Order: 18218 Printed by EBis 3 (datcomedia com) ENGINE ENTRY FIGURE 1/10/2019 FIGURE 1/10				WAII	WIENANCE RECORD			
ENCINES NI L-30:893-498. REG NO NO REGET 18218 Engine Entries Complied with engine 100 hour inspection Items. Cleaned and gapped spark plugs and checked magneto timing. Complete with engine 100 hour inspection Items. Cleaned and gapped spark plugs and checked magneto timing. Compression test. #1 70:80 #2 72/80 #3 78/80 #4 78/80 #5 78/80 #6 72/80 Changed oil and filter. Cut old filter open and inspected for contamination. No discrepancies noted. Serviced with Philips 20/W-50. Removed, cleaned, and reinstalled fuel injector nozzles. Replaced gasket for oil pressure relief valve. Cleaned engine. Complied with A D 15-19-07 injector line inspection, no discrepancies noted. Next due at tach time 1665-9. Completed ground run, no discrepancies noted. Leetify that this engine has been inspected in accordance with an Annual Inspection and has been determined to be in Airworthy condition. DATE 1/10/2019 SIGNED Work of 18218 Dollas Gluck, IA 3571893 Printed by EBs 3 (datcomedia com) ENGINEERINTY Work Order: 18218 Description 1. COMPLED with PRELIMINARY INSPECTION IN ACCORDANCE WITH 14 CFR 145 211(c)(6) ENGINEERING SERVICED ENGINE WITH 9 or 50 of a REGISHEL 100 MINERAL OIL GROUND RAN OPERATIONAL AND LEAK CHECK GOOD. WORK PERFORMED INVESTOR IN PARED BY A NOVEL CONTROL OF A NOVEL CONTROL RANGE OF A NOVEL RANGE OF A N	-	- 10-5	540-A1B1A5		*		A/C TSN: 1555.9	IZED SIGNATURE, IFICATE TYPE I NUMBER
- Complete with engine 100 hour inspection Items. Cleaned and gapped spark plugs and checked magneto timing. - Compression test: #1 72/80 #2 72/80 #3 78/80 #4 78/80 #5 78/80 #6 72/80 - Changed oil and filter. Cut old filter open and inspected for contamination. No discrepancies noted. Serviced with Philips 20W-50. - Removed, cleaned, and reinstalled fuel injector nozzles Replaced gasket for oil pressure relief valve Cleaned engine Completed ground run, no discrepancies noted. - Completed ground run, no discrepancies noted. - I certify that this engine has been inspected in accordance with an Annual Inspection and has been determined to be in Airworthy condition. - DATE 1/10/2019 - SIGNED - Work Order: 18218 - Date Tot Work Order: 18218 - Printed by EBis 3 (datcomedia com) - Date Tot Work Order: 18218 - Date Tot W		WO	G. NO: N2162L RKORDER: 18218		Box 7 Smoketown, PA 17576		TSMOH:	
DATE 1/10/2019 SIGNED. J.		- Comag - Co - Ch Serv - Rep - Cle - Cor 1665	implied with engine 1 ineto timing. Impression test: #1 7 anged oil and filter. Cliced with Philips 20V moved, cleaned, and blaced gasket for oil paned engine. Implied with A.D. 15-1.9.	72/80 #2 72/80 a Cut old filter open 7-50. reinstalled fuel in pressure relief val 9-07 injector line	#3 78/80 #4 78/80 # and inspected for contr rijector nozzles. lve. inspection, no discrepa	5 78/80 #6 72/80 amination. No disc) repancies noted.	
DATE TOT/ INSI HOURS 1. COMPLIED WITH PRELIMINARY INSPECTION IN ACCORDANCE WITH 14 CFR 145 211(c)(ii). 2. #6 CYLINDER HAS COMPRESSION AT LIMITS - INSPECTED BY BE CYLINDER AND INSTALLED REPAIRED P/N LW13870 SERVICED ENGINE WITH 9 QTS OF AEROSHELL 100 MINERAL OIL. GROUND RAN, OPERATIONAL AND LEAK CHECK GOOD WORK PERFORMED IMM LYCOMING SERVICE TABLE OF LIMITS SSP-1776 AND IO-340-381AS OVERHAULI MANUAL, APPLICABLE SECTION OF SECTION 6 NEW 3. #1. #2. #4. TYLINDER HOSE STRANGOLO WORK PERFORMED IMM LYCOMING SERVICE TABLE OF LIMITS SSP-1776 AND IO-340-381AS OVERHAULI MANUAL, APPLICABLE SECTION OF SECTION 6 NEW COMPRESSION THORN MOLICITOR TUBE HOSES FRAYED - REMOVED AND REPLACED #1, #2. # 4 INDUCTION TUBE HOSES WITH NEW PROPELLER SECTION FOR PERFORMED IMM LYCOMING IO-340-AB1AS SERVICE TABLE OF LIMITS SSP-1776. THE AIRCRAFT, AIRFRAME, AIRCRAFT ENGINE, PROPELLER OR APPLIANCE IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANGE WITH CURRENT FEDERAL AVAITION REGULATIONS AND IS APPROVED FOR RETURN TO SERVICE PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY UNDER WORK ORDER NO STITS. SIGNED BY: BAGLE AVAITION, INC., 2801 AVAITION WAY WEST COMMINIS SOUTH CARDI INA 29170					d in accordance with ar	Annual Inspection	n and has been	
TOT/ INSI HOURS 1. COMPLIED WITH PRELIMINARY INSPECTION IN ACCORDANCE WITH 14 CFR 145 211(c)(ii). 2. #6 CYLINDER HAS COMPRESSION AT LIMITS – INSPECTED #6 CYLINDER AND FOUND COMPRESSION AT LIMITS AND LEAKING PAST EXHAUST VALVE REMOVED CYLINDER AND INSTALLED REPAIRED P/N LW13870. SERVICED ENGINE WITH 9 QTS OF AEROSHELL 100 MINERAL OIL. GROUND RAN, OPERATIONAL AND LEAK CHECK GOOD. WORK PERFORMED IAW LYCOMING SERVICE TABLE OF LIMITS SSP-1776 AND IO-540-AB1AS OVERHAUL MANUAL, APPLICABLE SECTION OF SECTION 6. NEW COMPRESSION READING IS 74/80. MINERAL OIL CHANGE DUE IN 25 HOURS OR 1598 3 TACH. 3. #1, #2. & #4- CYLINDER INDUCTION TUBE HOSES FRAYED – REMOVED AND REPLACED #1, #2 & #4 INDUCTION TUBE HOSES WITH NEW P/N 69603. GROUND RAN, NO LEAKS NOTED. WORK PERFORMED IAW LYCOMING IO-540-AB1AS SERVICE TABLE OF LIMITS SSP-1776. THE AIRCRAFT, AIRFRAME, AIRCRAFT ENGINE, PROPELLER OR APPLIANCE IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AVIATION REGULATIONS AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY UNDER WORK ORDER NO. 95779. SIGNED BY: EAGLE AVIATION, INC., 2861 AVIATION WAY, WEST COLUMBIA SOUTH CAROLINA 29170.		DATE		4NV E	1A 3571893	Printed by		_
DATE TOT/ IN SI HOURS 1. COMPLIED WITH PRELIMINARY INSPECTION IN ACCORDANCE WITH 14 CFR 145 211(c)(ii). 2. #6 CYLINDER HAS COMPRESSION AT LIMITS – INSPECTED #6 CYLINDER AND FOUND COMPRESSION AT LIMITS AND LEAKING PAST EXHAUST VALVE REMOVED CYLINDER AND INSTALLED REPAIRED P/N LW13870 SERVICED ENGINE WITH 9 OTS OF AEROSHELL 100 MINERAL OIL. GROUND RAN, OPERATIONAL AND LEAK CHECK GOOD. WORK PERFORMED IAW LYCOMING SERVICE TABLE OF LIMITS SSP-1776 AND IO-540-AB1AS OVERHAUL MANUAL, APPLICABLE SECTION OF SECTION 6. NEW COMPRESSION READING IS 74/80. MINERAL OIL CHANGE DUE IN 25 HOURS OR 1598 3 TACH. 3. #1, #2- & #4- CYLINDER INDUCTION TUBE HOSES FRAYED – REMOVED AND REPLACED #1, #2 & #4 INDUCTION TUBE HOSES WITH NEW P/N 69603. GROUND RAN, NO LEAKS NOTED. WORK PERFORMED IAW LYCOMING IO-540-AB1AS SERVICE TABLE OF LIMITS SSP-1776. THE AIRCRAFT, AIRFRAME, AIRCRAFT ENGINE, PROPELLER OR APPLIANCE IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AVIATION REGULATIONS AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY UNDER WORK ORDER NO. 95779. SIGNED BY: EAGLE AVIATION, INC., 2861 AVIATION WAY, WEST COLUMBIA SOUTH CAROLINA 29170								
DATE TOT/ IN SI HOURS 1. COMPLIED WITH PRELIMINARY INSPECTION IN ACCORDANCE WITH 14 CFR 145 211(c)(ii). 2. #6 CYLINDER HAS COMPRESSION AT LIMITS – INSPECTED #6 CYLINDER AND FOUND COMPRESSION AT LIMITS AND LEAKING PAST EXHAUST VALVE REMOVED CYLINDER AND INSTALLED REPAIRED P/N LW13870. SERVICED ENGINE WITH 9 OTS OF AEROSHELL 100 MINERAL OIL. GROUND RAN, OPERATIONAL AND LEAK CHECK GOOD. WORK PERFORMED IAW LYCOMING SERVICE TABLE OF LIMITS SSP-1776 AND IO-540-AB1AS OVERHAUL MANUAL, APPLICABLE SECTION OF SECTION 6. NEW COMPRESSION READING IS 74/80. MINERAL OIL CHANGE DUE IN 25 HOURS OR 1598.3 TACH. 3. #1, #2- & #4- CYLINDER INDUCTION TUBE HOSES FRAYED – REMOVED AND REPLACED #1, #2 & #4 INDUCTION TUBE HOSES WITH NEW P/N 69603. GROUND RAN, NO LEAKS NOTED. WORK PERFORMED IAW LYCOMING IO-540-AB1AS SERVICE TABLE OF LIMITS SSP-1776. THE AIRCRAFT, AIRFRAME, AIRCRAFT ENGINE, PROPELLER OR APPLIANCE IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AVIATION REGULATIONS AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY UNDER WORK ORDER NO. 95779. SIGNED BY: SIGNED BY: SIGNED BY: EAGLE AVATION, INC., 2861 AVIATION WAY WEST COLUMBIA SOUTH CAROLINA 29170.						ENGIN	E ENTRY	
HOURS 1. COMPLIED WITH PRELIMINARY INSPECTION IN ACCORDANCE WITH 14 CFR 145 211(c)(ii). 2. #6 CYLINDER HAS COMPRESSION AT LIMITS – INSPECTED #6 CYLINDER AND FOUND COMPRESSION AT LIMITS AND LEAKING PAST EXHAUST VALUE REMOVED CYLINDER AND INSTALLED REPAIRED P/N LW13870. SERVICED ENGINE WITH 9 QTS OF AEROSHELL 100 MINERAL OIL. GROUND RAN, OPERATIONAL AND LEAK CHECK GOOD. WORK PERFORMED IAW LYCOMING SERVICE TABLE OF LIMITS SSP-1776 AND IO-540-AB1AS OVERHAUL MANUAL, APPLICABLE SECTION OF SECTION 6. NEW COMPRESSION READING IS 74/80. MINERAL OIL CHANGE DUE IN 25 HOURS OR 1598 3 TACH. 3. #1, #2-8 #4- CYLINDER INDUCTION TUBE HOSES FRAYED – REMOVED AND REPLACED #1, #2 & #4 INDUCTION TUBE HOSES WITH NEW P/N 69603. GROUND RAN, NO LEAKS NOTED. WORK PERFORMED IAW LYCOMING IO-540-AB1A5 SERVICE TABLE OF LIMITS SSP-1776. THE AIRCRAFT, AIRFRAME, AIRCRAFT ENGINE, PROPELLER OR APPLIANCE IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AVIATION REGULATIONS AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY UNDER WORK ORDER NO. 95779. SIGNED BY: SIGNED BY: EAGLE AVIATION, INC., 2861 AVIATION WAY, WEST COLUMBIA SOUTH CAROLINA 29170.	DATE) SIGNATURE,
EAGLE AVIATION, INC., 2861 AVIATION WAY, WEST COLUMBIA SOUTH CAROLINA 29170		HOURS	2. #6 CYLINDER FAT LIMITS AND LW13870. SER OPERATIONAL LIMITS SSP-17' COMPRESSION 3. #1, #2- & #4-0' INDUCTION TO IAW LYCOMING THE AIRCRAFT, AIRI REPAIRED AND INSP APPROVED FOR RETO	HAS COMPRESSION LEAKING PAST EXH VICED ENGINE WI' AND LEAK CHECK 76 AND IO-540-AB1A: I READING IS 74/80. I CYLINDER INDUCTIO BE HOSES WITH NEV G IO-540-AB1A5 SERV FRAME, AIRCRAFT ECTED IN ACCORD/ JRN TO SERVICE. PE	PECTION IN ACCORDANCE AT LIMITS - INSPECTED #6 AUST VALVE. REMOVED CY TH 9 QTS OF AEROSHEI GOOD. WORK PERFORME S OVERHAUL MANUAL, APP MINERAL OIL CHANGE DUE N TUBE HOSES FRAYED - W P/N 69603. GROUND RAN, //CE TABLE OF LIMTS SSP-1 **MAINTENANCE RELEASE ENGINE, PROPELLER OR ANCE WITH CURRENT FED ERTINENT DETAILS OF THE	CYLINDER AND FOUN /LINDER AND INSTALL LL 100 MINERAL OIL D IAW LYCOMING SE *LICABLE SECTION OF IN 25 HOURS OR 1598 REMOVED AND REPL NO LEAKS NOTED. W 776.	ID COMPRESSION ED REPAIRED P/N GROUND RAN, GROUND RAN, SECTION 6. NEW 3 TACH. ACED #1, #2 & #4 ORK PERFORMED	
TAA AFFROVED REPAIR STATION NO. FEHROSOD	1		EAGLE AVIATION, EAG	GLE AVIATION, INC.,	2861 AVIATION WAY, WEST	COLUMBIA SOUTH CA	DR ROLINA 29170	
		1		FAA	AFFROVED REPAIR STATIO	JN_NO. FEHR859D		

			MAINTENANCE RECORD	
DATE	TOTAL IN SER	RVICE	DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE
	HOURS	10THS		& NUMBER
8/8/19	1875	.2	Replaced Vacuum pump partit AA3215CC Ran engine tested ok. LWagenaar AEP 3611579 IA	
			,	



DATE	TOTAL IN SER			AUTHORIZED SIGNATURE CERTIFICATE TYPE
	HOURS	10THS	Summit Aero Excellence in Aircraft Maintenance	& NUMBER
			A/C: N2162L Eng Mod :Lyc- IO-540-AB1A5 S/N: 18281662_ Eng Sr. :L-30589-48E A/C TSN: <u>/5 86.3</u> ENG TT. : <u>/5 86.3</u> TSMOH:	
			Performed annual inspection on engine I.A.W. FAR43 Appx D. 1. Cleaned and gapped sparkplugs 2. Serviced engine with 9 qts Aero Shell 100, replaced oil filter CH48110-1 3. Replaced EGT temp sensor on Cyl #1 (part number PN86343) 4. Compression test: 1-72, 2-68, 3-72, 4-78, 5-76, 6-78/80 5. Test ran engine no leaks found	
590	\$ 250 170		I certify that this engine has been inspected I.A.W. an annual inspection and was found to be in airworthy condition. DATE:4/4/2020 Lucas Wagenaar A&P 3611579 IA	FD 17

ATE TOTA		AUTHORIZED SIGNATURE CERTIFICATE TYPE & NUMBER
HOURS	A/C: N2162L Eng Mod :Lyc- IO-540-AB1A5	
	S/N: 18281662 Eng Sr. :L-30589-48E	
	TSMOH:_1595.3_ ENG TT. :_1595.3	
	Performed annual inspection on engine I.A.W. FAR43 Appx D.	
	Cleaned and gapped sparkplugs	
+	2. Serviced engine with 9 qts Aero Shell 100, replaced oil filter CH48110-1 — 3. Compression test: 1-71, 2-72, 3-78, 4-78, 5-78, 6-78/80	
	4. Sprayed down engine with PSC1000	
	5. Test ran engine no leaks found	
	I certify that this engine has been inspected I.A.W. an annual inspection and	
	was found to be in airworthy condition.	
-	——————————————————————————————————————	
	DATE:5/5/2021	
	Lucas Wagenaar A&P 3611579 IA	
4)

DATE	TOTAL TY	Summit Aero Excellence in Aircraft Maintenance	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER	
	noono	A/C: N2162L Eng Mod :Lyc- IO-540-AB1A5 S/N: 18281662 Eng Sr. :L-30589-48E TSMOH:_1596.5_ ENG TT. :_1596.5 1. Performed annual inspection on engine I.A.W. FAR43 Appx D. 2. Cleaned and gapped sparkplugs 3. Compression test: 1-70, 2-74, 3-74, 4-78, 5-76, 6-78/80 4. Test ran engine no leaks found		
17.5		I certify that this engine has been inspected I.A.W. an annual inspection and was found to be in airworthy condition. DATE: 8/16/2022 Lucas Wagenaar A&P 3611579 IA	tushin- manusi in- manusi in-	

				MAINTENANO	E RECORD	Engine · page 1	of 1
DATE	H w	o: WO_9	985	,	\Line	Engine · page ·	SIGNATURE, ATE TYPE MBER
,			First Line	Aero, LLC - 458 CR 1618		316-8331	
20	N:	2162L ACH: 16		MING, IO-540-AB1A5,	S/N: L-30589-48E	March 20, 20	23
	rein Rep Tem	stalled solaced of	spark plugs with nev oil filter. Serviced oil il Filter, P/N AOA O	vwashers. Drained oil, 1 with Phillips XC20W50 il Sample Kit. Installed	look oil sample, inspec 0, P/N AN900-16 - Cru (8 qt) P/N XC20W50 ng MM as required. Le	74/80 , cleaned, tested ted oil screen and filter meash Gasket, P/N AA4811 - Oil, (12) P/N M674 - Seak check performed after for return to service.	0-2 - park
			A&P/IA 3554698	Morras	Thuts		
		: WO 9	85			Airframe - pag	e 1 of 1
	_	. VVO_9		————— A E	Line		
			First Line	e Aero, LLC · 458 CR 161	8 - Rusk, TX 75785 - 903	3-316-8331	
,	N2 TA	2 162L CH: 16	01.8	CESSNA, 182T, S/N	I: 18281662	March 20,	2023
	C/W Ops	12 MC check) Garmin standby b normal after test. V	attery capacity check, Vith respect to the work	and main aircraft batte k performed, this aircra	ery capacity check. aft is returned to service.	
	T.J.	Hunter	A&P/IA 3554698	/ howas	Thuts		540
	100				7		
				MAINTENAN	ICE RECORD		
DATE		TOTAL TIME IN SERVICE DESCRIPTION OF THE WORK PERFORMED AUTHORS C				AUTHORIZED SIGNATURE, CERTIFICATE TYPE	
	HOURS					& NUMBER	
18/23	1610	2	V	Servo RSA- el leak. 7			
				ngine no pro			
			Lucas Was	penaat ARP	-IA 361157	9 the	



Excellence in Aircraft Mainter	nance		
A/C: N2162L Eng Mod :Lyc- IO-540-AB1 S/N: 18281662_ Eng Sr. :L-30589-48E TSMOH:_1610.8_ ENG TT. :_1610.8	`		
 Performed annual inspection on engine I.A.W. F Cleaned and gapped sparkplugs Compression test: 1-72, 2-66, 3-70, 4-80, 5-78, 6 Test ran engine no leaks found 	FAR43 Appx D.		,
I certify that this engine has been inspected I.A.W. a was found to be in airworthy condition at the date of DATE: 8/15/2023 Lucas Wagenaar A&P 3611579 IA		4	
	SHI	OI SAUC	ОН
AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER		TOTAL TIME	714(1

