


N2130L

1976 Beech 58TC Baron

Aircraft Database Query

Aircraft S/N: TK-25



Prepared by the worldwide aviation specialists at RidgeAire, Inc.

Aircraft Details

Use the query results with caution

Over time registration numbers are assigned to different aircraft and diverse data stores with inconsistent data are being joined

[Back to Query Entry](#)

N Number: 2130L

Last Action Date	2020-09-04		
Airworthiness Date	1976-08-09	Expiration Date	2023-09-30
Manufacturer_Name	BEECH	Model Name	58TC
Registrant Name	CHAB DEVELOPMENT LLC	Street	10018 S RACETRACK RD
Registrant City	MINERAL POINT	Registrant State	MO
Registrant Zip Code	636609310	Country	UNITED STATES
Region	Central	Registrant Type	LLC
Fract Owner		Certificate Issue Date	2020-09-04
Status	N-Number Assigned and Registered		
Serial Number	TK-25	Aircraft Type	Fixed wing multi engine
Mode S Code	50343412	Year Mfr	1976
Aircraft Category	Land	Builder Certification	Type Certificated
Number Engines	2	Number Seats	6
Aircraft Weight	CLASS 1	Aircraft Cruising Speed	123
Airworthiness Classification	Standard	Approved Operation Codes	Normal
Engine Manufacturer			
Engine Model Name		Engine Type	Reciprocating
Engine Horsepower/Thrust		Fuel Consumed	

----- History 1 -----

Last Action Date	2017-05-18		
Registrant Name	CHAB DEVELOPMENT LLC	Street	PO BOX 492
Registrant City	LAKE OZARK	Registrant State	MO

Registrant Zip Code	650490492	Country	UNITED STATES
Region	Central	Registrant Type	LLC
Fract Owner		Certificate Issue Date	2017-05-18
Status	Third Notice for Registration Renewal		

----- **History 2** -----

Last Action Date	2017-01-04		
Registrant Name	PARRIS AVIATION LLC	Street	4719 BALLGROUND HWY
Registrant City	BALLGROUND	Registrant State	GA
Registrant Zip Code	30107	Country	UNITED STATES
Region	Southern	Registrant Type	Corporation
Fract Owner		Certificate Issue Date	2017-01-04
Status	N-Number Assigned and Registered		

----- **History 3** -----

Last Action Date	2014-07-29		
Registrant Name	HOWARD JAMES L	Street	50 NORTHCREST WAY
Registrant City	POWDER SPRINGS	Registrant State	GA
Registrant Zip Code	301275106	Country	UNITED STATES
Region	Southern	Registrant Type	Individual
Fract Owner		Certificate Issue Date	2014-07-29
Status	N-Number Assigned and Registered		

----- **History 4** -----

Last Action Date	2012-08-14		
Registrant Name	A36 LEASING CORP	Street	3511 SILVERSIDE RD STE 105
Registrant City	WILMINGTON	Registrant State	DE
Registrant Zip Code	198104902	Country	UNITED STATES
Region	Eastern	Registrant Type	Corporation
Fract Owner		Certificate Issue Date	1999-10-13
Status	N-Number Assigned and Registered		

----- **History 5** -----

Last Action Date	2012-04-05		
Registrant Name	A36 LEASING CORP	Street	3511 SILVERSIDE RD STE 105
Registrant City	WILMINGTON	Registrant State	DE

Registrant Zip Code	198104902	Country	UNITED STATES
Region	Eastern	Registrant Type	Corporation
Fract Owner		Certificate Issue Date	1999-10-13
Status	First Notice for Re- Registration/Renewal		

----- History 6 -----

Last Action Date	2009-02-25		
Registrant Name	A36 LEASING CORP	Street	3511 SILVERSIDE RD STE 105
Registrant City	WILMINGTON	Registrant State	DE
Registrant Zip Code	198104902	Country	UNITED STATES
Region	Eastern	Registrant Type	Corporation
Fract Owner		Certificate Issue Date	1999-10-13
Status	A second attempt has been made at mailing a Triennial Aircraft Registration form with no response		

----- History 7 -----

Last Action Date	2008-11-14		
Registrant Name	A36 LEASING CORP	Street	3511 SILVERSIDE RD STE 105
Registrant City	WILMINGTON	Registrant State	DE
Registrant Zip Code	19810-4902	Country	UNKNOWN
Region	Eastern	Registrant Type	Corporation
Fract Owner		Certificate Issue Date	1999-10-13
Status	Second Triennial Aircraft Registration Form has been mailed and has not been returned		

----- History 8 -----

Last Action Date	2008-10-21		
Registrant Name	A36 LEASING CORP	Street	3511 SILVERSIDE RD STE 105
Registrant City	WILMINGTON	Registrant State	DE
Registrant Zip Code	19810-4902	Country	UNITED STATES
Region	Eastern	Registrant Type	Corporation
Fract Owner		Certificate Issue Date	1999-10-13
Status	The Triennial Aircraft Registration form was mailed and has not been returned by the Post Office		

----- History 9 -----

Last Action Date	2005-10-18		
Registrant Name	A36 LEASING CORP	Street	3511 SILVERSIDE RD STE 105
Registrant City	WILMINGTON	Registrant State	DE

Registrant Zip Code	19810-4902	Country	UNITED STATES
Region	Eastern	Registrant Type	Corporation
Fract Owner		Certificate Issue Date	1999-10-13
Status	The Triennial Aircraft Registration form was mailed and has not been returned by the Post Office		

----- History 10 -----

Last Action Date	2002-10-15		
Registrant Name	A36 LEASING CORP	Street	3511 SILVERSIDE RD STE 105
Registrant City	WILMINGTON	Registrant State	DE
Registrant Zip Code	19810-4902	Country	UNITED STATES
Region	Eastern	Registrant Type	Corporation
Fract Owner		Certificate Issue Date	1999-10-13
Status	The Triennial Aircraft Registration form was mailed and has not been returned by the Post Office		

----- History 11 -----

Last Action Date	1999-10-13		
Registrant Name	A36 LEASING CORP	Street	3511 SILVERSIDE RD STE 105
Registrant City	WILMINGTON	Registrant State	DE
Registrant Zip Code	19810-4902	Country	UNITED STATES
Region	Eastern	Registrant Type	Corporation
Fract Owner		Certificate Issue Date	1999-10-13
Status	N-Number assigned		

***** No Deregistered Data Found *****

***** No Reserved Data Found *****

----- FAA Accident/Incident 1 -----

Occurrence Date	1989-01-28	Aircraft Make	BEECH
Aircraft Model	58TC	Damage	MINOR
Document Last Modified	2012-08-08		
Narrative	AFTER LANDING PILOT ACCIDENTLY ACTIVATED GEAR SWITCH INSTEAD OF FLAPS. GEAR PARTIALLY RETRACTED.		

***** No NTBS Accidents Found *****

***** No NTBS Pre 1982 Accidents Found *****

----- SDR 1 -----

Date Of Report	1980-01-29	Operator Control Number	Z198002900084
Date Of Occurrence		Aircraft Registration	2130L
Aircraft Manufacturer	BEECH	Aircraft Group Code	58
Aircraft Manufacturer Model	58TC	Aircraft Make Model Sequence	1152746
Air Carrier Name	Unknown	Air Carrier Operation Code	
Operation Type	G	Stage Of Operation	INSP/MAINT
Severity Factor	FREQUENT	Air Transport Association Code	Master Cylinder/Brake Valve
Precautionary Procedures	NONE	Nature Of Condition	OTHER
Segment	AIRFRAME	Descriptive Name Of Part	SNAP RING
Defective Location On Aircraft		Failed Part Condition	OUT OF GROOVE
Part Total Time	1,014	Part Total Time Since Overhaul	1,014
Component Manufacturer	GERDES	Component Manufacturer Model	963800341
Component Manufacturer Number	3999	Manufacturer Part Number	X513321
Ata Code			
Remarks	SNAP RING ON BOTTOM OF SHAFT SLIPPED OUT OF GROOVE AND COMPRESSED SPRING AGAINST THE PISTON ALLOWING NO FLUID TO PA S		

----- SDR 2 -----

Date Of Report	1978-03-31	Operator Control Number	Z197809000106
Date Of Occurrence		Aircraft Registration	2130L
Aircraft Manufacturer	BEECH	Aircraft Group Code	58
Aircraft Manufacturer Model	58TC	Aircraft Make Model Sequence	1152746
Air Carrier Name	Unknown	Air Carrier Operation Code	
Operation Type		Stage Of Operation	INSP/MAINT
Severity Factor	OVER 24 MO	Air Transport Association Code	Engine Exhaust System
Precautionary Procedures	NONE	Nature Of Condition	OTHER
Segment	AIRFRAME	Descriptive Name Of Part	CLAMP
Defective Location On Aircraft	SPOT WELDS	Failed Part Condition	BROKEN
Part Total Time	552	Part Total Time Since Overhaul	552
Component Manufacturer		Component Manufacturer Model	
Component Manufacturer Number		Manufacturer Part Number	4404450M
Ata Code			
Remarks	SPOT WELDS BROKE ON INNER SEGMENTS OF EXH CLAMPS		

----- SDR 3 -----

Date Of Report	1978-01-30	Operator Control Number	Z197803000040
Date Of Occurrence		Aircraft Registration	2130L
Aircraft Manufacturer	BEECH	Aircraft Group Code	58
Aircraft Manufacturer Model	58TC	Aircraft Make Model Sequence	1152746
Air Carrier Name	Unknown	Air Carrier Operation Code	
Operation Type		Stage Of Operation	INSP/MAINT
Severity Factor	OVER 24 MO	Air Transport Association Code	Emergency Locator Beacon
Precautionary Procedures	NONE	Nature Of Condition	NO TEST, OTHER
Segment	COMPONENT	Descriptive Name Of Part	BATTERY
Defective Location On Aircraft		Failed Part Condition	CORRODED/INOP
Part Total Time	495	Part Total Time Since Overhaul	495
Component Manufacturer	COMMUNCOMP	Component Manufacturer Model	CIR10
Component Manufacturer Number	14214	Manufacturer Part Number	BP60
Ata Code			