


N13839

1970 Piper Turbo Aztec D

Aircraft Database Query

MSN: 27-4480



Prepared by the worldwide aviation specialists at RidgeAire, Inc.

Aircraft Details

Use the query results with caution

Over time registration numbers are assigned to different aircraft and diverse data stores with inconsistent data are being joined

[Back to Query Entry](#)

N Number: 13839

Last Action Date	2023-09-22		
Airworthiness Date	1970-02-26	Expiration Date	2029-12-31
Manufacturer_Name	PIPER	Model Name	PA-23-250
Registrant Name	MACE AIR LLC	Street	120 N ANNIE GLIDDEN RD
Registrant City	DEKALB	Registrant State	IL
Registrant Zip Code	601152702	Country	UNITED STATES
Region	Great Lakes	Registrant Type	LLC
Fract Owner		Certificate Issue Date	2022-12-31
Status	N-Number Assigned and Registered		
Serial Number	27-4480	Aircraft Type	Fixed wing multi engine
Mode S Code	50115714	Year Mfr	1970
Aircraft Category	Land	Builder Certification	Type Certificated
Number Engines	2	Number Seats	6
Aircraft Weight	CLASS 1	Aircraft Cruising Speed	150
Airworthiness Classification	Standard	Approved Operation Codes	Normal
Engine Manufacturer	LYCOMING		
Engine Model Name	TIO-540 SER	Engine Type	Reciprocating
Engine Horsepower/Thrust	0	Fuel Consumed	0.00

----- History 1 -----

Last Action Date	2022-12-31		
Registrant Name	MACE AIR LLC	Street	120 N ANNIE GLIDDEN RD
Registrant City	DEKALB	Registrant State	IL
Registrant Zip Code	601152702	Country	UNITED STATES
Region	Great Lakes	Registrant Type	LLC
Fract Owner		Certificate Issue Date	2022-12-31
Status	N-Number Assigned and Registered		

----- History 2 -----

Last Action Date 2021-06-23
Registrant Name MONROE AVIATION LLC **Street** 5763 CAMBER VW
Registrant City COLORADO SPRINGS **Registrant State** CO
Registrant Zip Code 809162785 **Country** UNITED STATES
Region Northwest Mountain **Registrant Type** LLC
Fract Owner **Certificate Issue Date**
Status N-Number Assigned and Registered

----- **History 3** -----

Last Action Date 2020-05-12
Registrant Name WOODS MICHAEL J **Street** 3 FULLERTON LN
Registrant City PETALUMA **Registrant State** CA
Registrant Zip Code 949524760 **Country** UNITED STATES
Region Western-Pacific **Registrant Type** Individual
Fract Owner **Certificate Issue Date** 2020-05-12
Status N-Number Assigned and Registered

----- **History 4** -----

Last Action Date 2017-06-15
Registrant Name DEATON JOHN G **Street** 15 WEDGEWOOD CT
Registrant City PETALUMA **Registrant State** CA
Registrant Zip Code 949545888 **Country** UNITED STATES
Region Western-Pacific **Registrant Type** Individual
Fract Owner **Certificate Issue Date** 1992-07-15
Status N-Number Assigned and Registered

----- **History 5** -----

Last Action Date 2017-06-13
Registrant Name DEATON JOHN G **Street** 15 WEDGEWOOD CT
Registrant City PETALUMA **Registrant State** CA
Registrant Zip Code 949545888 **Country** UNITED STATES
Region Western-Pacific **Registrant Type** Individual
Fract Owner **Certificate Issue Date** 1992-07-15
Status First Notice for Registration Renewal

----- **History 6** -----

Last Action Date 2014-06-18

Registrant Name	DEATON JOHN G	Street	PO BOX 7007
Registrant City	PETALUMA	Registrant State	CA
Registrant Zip Code	949557007	Country	UNITED STATES
Region	Southern	Registrant Type	Individual
Fract Owner		Certificate Issue Date	1992-07-15
Status	First Notice for Registration Renewal		

----- **History 7** -----

Last Action Date	2011-11-09		
Registrant Name	DEATON JOHN G	Street	PO BOX 7007
Registrant City	PETALUMA	Registrant State	CA
Registrant Zip Code	949557007	Country	UNITED STATES
Region	Southern	Registrant Type	Individual
Fract Owner		Certificate Issue Date	1992-07-15
Status	First Notice for Registration Renewal		

----- **History 8** -----

Last Action Date	2007-09-18		
Registrant Name	DEATON JOHN G	Street	PO BOX 7007
Registrant City	PETALUMA	Registrant State	CA
Registrant Zip Code	94955-7007	Country	UNITED STATES
Region	Southern	Registrant Type	Individual
Fract Owner		Certificate Issue Date	1992-07-15
Status	First Notice for Re- Registration/Renewal		

----- **History 9** -----

Last Action Date	2004-09-21		
Registrant Name	DEATON JOHN G	Street	PO BOX 7007
Registrant City	PETALUMA	Registrant State	CA
Registrant Zip Code	94955-7007	Country	UNITED STATES
Region	Southern	Registrant Type	Individual
Fract Owner		Certificate Issue Date	1992-07-15
Status	The Triennial Aircraft Registration form was mailed and has not been returned by the Post Office		

----- **History 10** -----

Last Action Date	2001-09-10		
Registrant Name	DEATON JOHN G	Street	PO BOX 7007
Registrant City	PETALUMA	Registrant State	CA
Registrant Zip Code	94955-7007	Country	UNITED STATES

Region	Southern	Registrant Type	Individual
Fract Owner		Certificate Issue Date	1992-07-15
Status	N-Number assigned		

----- History 11 -----

Last Action Date	2001-06-19		
Registrant Name	DEATON JOHN G	Street	PO BOX 163
Registrant City	VINEBURG	Registrant State	CA
Registrant Zip Code	95487-0163	Country	UNITED STATES
Region	Western-Pacific	Registrant Type	Individual
Fract Owner		Certificate Issue Date	1992-07-15
Status	The Triennial Aircraft Registration form was mailed and has not been returned by the Post Office		

----- History 12 -----

Last Action Date	1998-06-17		
Registrant Name	DEATON JOHN G	Street	PO BOX 163
Registrant City	VINEBURG	Registrant State	CA
Registrant Zip Code	95487-0163	Country	UNITED STATES
Region	Western-Pacific	Registrant Type	Individual
Fract Owner		Certificate Issue Date	1992-07-15
Status	The Triennial Aircraft Registration form was mailed and has not been returned by the Post Office		

***** No Deregistered Data Found *****

***** No Reserved Data Found *****

***** No FAA Accidents/Incidents Found *****

***** No NTBS Accidents Found *****

***** No NTBS Pre 1982 Accidents Found *****

----- SDR 1 -----

Date Of Report	1987-05-21	Operator Control Number	GL088776652
Date Of Occurrence	1987-03-18	Aircraft Registration	13839
Aircraft Manufacturer	PIPER	Aircraft Group Code	PA23
Aircraft Manufacturer Model	PA23250	Aircraft Make Model Sequence	7102308
Air Carrier Name	Unknown	Air Carrier Operation Code	
Operation Type	G	Stage Of Operation	CRUISE
Severity Factor	OCCASIONAL	Air Transport Association Code	Engine Collector/Tailpipe/Nozzle

Precautionary Procedures	OTHER	Nature Of Condition	ELECT. POWER LOSS-50 PC, UNKNOWN
Segment	AIRFRAME	Descriptive Name Of Part	CLAMP
Defective Location On Aircraft	CROSSOVER PIPE	Failed Part Condition	BROKEN
Part Total Time	1,821	Part Total Time Since Overhaul	1,821
Component Manufacturer		Component Manufacturer Model	
Component Manufacturer Number		Manufacturer Part Number	
Ata Code	2430		
Remarks	<p>19 HOURS AFTER ANNUAL INSPECTION OF AIRCRAFT, WHILE IN FLIGHT, LOST RIGHT ALTERNATOR. ON FINAL APPROACH, PILOT TRIED TO RESET PROP. CONTROL WAS FROZEN. UPON INSPECTION, SUBMITTER FOUND CLAMP ON CROSSOVER PIPE BROKEN LETTING THE PIPE SEPARATE ONE INCH. THIS CAUSED EXENSIVE DAMAGE TO ALTERNATOR, PROP CONTROL CABLE, INTAKE HOSES AND COWLING. SUBMITTER RECOMMENDS THAT AN INSPECTION WITH A MANIFYING GLASS BE DONE AT ANNUALS OR 100 HOUR INSPECTIONS.</p>		