

N505RA

2016 Cessna Turbo 206H

Propeller Logbooks (2016-2025)



MSN: T20609213

Prepared by the worldwide aviation specialists at RidgeAire, Inc.



PROPELLER MAINTENANCE RECORD

AIRCRAFT SERIAL AND REGISTRATION T20609213 N505RA (3-10-17)
~~N932CF~~
PROPELLER MODEL AND SERIAL B3D36C432/80 VSA-1
HUB SERIAL 150773 BLADE SERIALS AJJ26071, AJJ26072, AJI26117

D5519-2-13

2002-00-012-9005

MAINTENANCE RECORD

DATE	TOTAL TIME IN SERVICE		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	HOURS	10THS		

A/C Serial #	A/C Unit #	A/C Registration #	Date	City ID	Total A/C Hours	Total A/C Landings	Total Engine HRS	Total Prop Hrs
T20609213	9213	N932CT	Dec. 08, 2016	IDP	10.6	10	10.6	10.6
Propeller hub S/N 150773 Blade S/N #1 AJJ26071 Blade S/N #2 AJJ26072 Blade S/N #3 AJJ26117 has been installed on engine S/N L-14220-61E on aircraft S/N T20609213 with TTAF 10.6 TTSN was 10.6								

Work Performed by CESSNA AIRCRAFT COMPANY Certificate No. PC-4 Date Dec. 08, 2016

I certify that the above stated maintenance and inspection was performed in accordance with the current regulations of the Federal Aviation Administration.

Joseph R. Carrier
 Work inspected by Joseph R. Carrier Certificate No. PC-4 Date Dec. 08, 2016
 at our facility under the above Work/Service Order Number as applicable.

Date: 12/10/2017 Hours: 136.7(HOBBS)

Tail#: N505RA


Make: McCauley Model: B3D26C432/80VSA-1 S/N:

I certify that this propeller has been inspected and serviced in accordance with a 100/hr inspection and was determined to be in airworthy condition at this time.

W. B. W. 3172474 A+P

MAINTENANCE RECORD

DATE	TOTAL TIME IN SERVICE		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	HOURS	10THS		
10/18/2018	N505RA	McCauley B3D36C432/80VSA-1	Propeller Logbook	
Hobbs Hours: 188.6 :: Propeller TT: 188.6 Completed 100 Hour inspection in accordance with manufacturers inspection procedures manual. I certify that this Propeller has been inspected in accordance with a 100 hour inspection and was determined to be in an airworthy condition.				
Signed <u>William Butler</u> William Butler A&P3172474				



BROADIE'S AIRCRAFT
 Meacham International Airport
 4701 N. Main St., Loc 44N, Fort Worth, Texas 76106
 817-626-1532 www.BroadiesAircraft.com

SUPPLEMENTAL LOG BOOK ENTRY




Aircraft Registration #	N505RA	S/N:	T20609213	TACH	171.3
Description of work performed:	Propeller			HOBBS	190.1

1 Blended out nicks and contoured sharp edges of all qty.3 propeller blade leading edges. Ref. McCauley MM MPC260W.

All work was done IAW the manufacturers service instructions and the aircraft is approved for return to service in regards to the work performed.

Signature: [Signature]

Repair Station # WF1R582K
 Date: 10/29/2018

Repair Order # 18-002864

DATE	TOTAL TIME IN SERVICE		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE
	HOURS	10THS		
	N505RA	PROPELLER LOGBOOK ENTRY		

MAINTENANCE RECORD

DATE

TOTAL TIME
IN SERVICE

DESCRIPTION OF THE WORK PERFORMED

AUTHORIZED SIGNATURE,
CERTIFICATE TYPE
& NUMBER

N505RA PROPELLER LOGBOOK ENTRY

3-4-2019

TSNEW: 267.7

TSMOH: N/A

Balance propeller in accordance with Dyna-Vibe instructions. Initial reading 0.46 IPS @108°.
Corrected to 0.00 IPS @ 360°

Kyle G. Fosso

A&P 3790199




Make: McCauley
Model: B3D36C432
S/N: 80VSA-1

TacAero 45 Airport Way
Dallesport, WA 98617
Phone: (844) FLY - CUBS ext: 706

Date: 11/1/2019
TACH: 394.4
HOBBS: 456.0
TTSN: 394.4

Propeller

Performed an Annual Inspection I.A.W Cessna T206H Maintenance Manual and Cessna 206 100 HR. Check List. Propeller removed to facilitate Engine Crankcase Oil Seal replacement. Replaced Propeller Hub O-Ring @ this time. Installed Lycoming P/N A-1633-11 O-Ring. Reinstalled Propeller, Blended and Detailed all (3) Blades per McCauley Propellers Service Instructions. There are currently no AD's applicable to this Propeller @ this time. Complete list of all Airworthiness Directives included with Aircraft Permanent Records. Operational & leak check good

I certify that this Propeller has been inspected I.A.W an annual inspection & determined to be in airworthy condition.



Jeffrey E. Kroo AP36840651A

100-012-9005

By specified
entry of the

227

No:

12

Block

4

12

MAINTENANCE RECORD

DATE

N505RA

SPANAFLIGHT AVIATION, LLC

16705 103rd Ave. Ct. E.
Puyallup, WA 98374
(253)848-2020



AUTHORIZED SIGNATURE, DATE

Prop Make/Model

McCauley

Prop Serial

DATE: 22 October 2020 TACH: 510.9 AFTT: 510.9 Prop TT: 510.9

Dressed propeller blade nicks. I certify this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition this date.

Signature

Michael Schur

A&P3436919IA

MAINTENANCE RECORD

DATE

Log Book Entry TURE,
PE



289 E Perimeter Rd.
Renton, Washington 98057
United States

Telephone: 425-204-0845

www.aceaviationinc.com

Manufacturer: Mccauley Industrial Corp
Part/Model number: B3D36C432
Work Order No: 3534

Hour Meter: 556.1

TSN/TSO: 556.10 / N/A

CSN/CSO: N/A / N/A

Serial Number: 80VSA-1

Date: 2/12/2021

Squawk

3.1 Performed propeller pre-purchase inspection, see report dated February 11, 2021 for findings.

Pertinent details are on file at the repair station under Work Order Number 3534.

Jake Johnson (JAKE)

AP#3796010

*** End of Document ***

Wingmaster Aircraft LLC Lubbock Executive Airpark

MAKE	McCauley	MODEL	B3D36C432	SERIAL #	80VSA-1	SIGNATURE, TYPE
AIRCRAFT	N505RA	PROP TOT TIME	643.4	TACH TIME	756.1	
DATE	11/22/21	ACFT TOT TIME	756.1	TSMOH	643.4	

I certify that this PROPELLER has been inspected IAW A 100 Hour inspection and found to be in an AIRWORTHY condition. Inspected IAW the scope and detail of Part 43 Appendix D using a Service Manual for reference. Engine ground ran and test flown, no defects noted. See AD summary for compliances.

Nick Odom

A&P/IA #3560008



VAN BORTEL AIRCRAFT INC™

4912 S. Collins St., Arlington, TX 76018

FAA CRS VNFR171L

N505RA TACH & TOTAL 690.8 H.M. 809.6 DATE 1/10/2023 W.O. SV10560

PROPELLER S/N: 150773

PERFORMED A 100 HOUR INSPECTION IN ACCORDANCE WITH FAR 43 WITH REFERENCE TO CESSNA MAINTENANCE MANUAL 182SMM21. AD'S CHECKED THROUGH 2023-02.

I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HOUR/ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. PERTINENT DETAILS OF THE REPAIRS ARE ON FILE AT THIS REPAIR STATION UNDER THIS WORK ORDER.

Paul Park

PAUL PARK, CHIEF INSPECTOR

[illegible]

20-012-9005

specified
ity of the

MAINTENANCE RECORD

DESCRIPTION OF THE WORK PERFORMED

AUTHORIZED SIGNATURE,
CERTIFICATE TYPE
• NUMBER

DATE

TOTAL TIME
IN SERVICE

HC



MCCREERY AVIATION CO., INC.
P.O. BOX 1659
McALLEN, TX 78505

PROPELLER
03/01/2025
REG. NO.: N505RA
MODEL: B3D36C432-C
S/N: 150773

TACH: 0967.1
P.T.T.: 0967.1
W.O.#: M-25-16312

- COMPLIED WITH AN ANNUAL INSPECTION IN ACCORDANCE WITH FAR APPENDIX D TO PART 43 USING THE CESSNA T206H MAINTENANCE MANUAL INSPECTION CHECKLIST AS A GUIDE.
- COMPLIED WITH ALL APPLICABLE AD'S AND BI-WEEKLY THRU 2025-04.

I CERTIFY THAT THIS PROPELLER IDENTIFIED ABOVE HAS BEEN INSPECTED IN ACCORDANCE WITH ANNUAL INSPECTION AND CURRENT FEDERAL AVIATION REGULATIONS AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF REPAIRS ARE ON FILE AT THIS REPAIR STATION UNDER WORK ORDER NO.: M-25-16312.

DATE: 03/01/2025

SIGNED:

ANTHONY PRATS

MCCREERY AVIATION CO., INC.
FAA REPAIR STATION NO. CRSHLFR716E
McALLEN, TX 78503